



# 101676591 2021 OH Checklist

## Asset Details

Date Inspected	Jun 13, 2021 at 09:01 AM
GPS Location of when form initiated	37.07745361328125,-122.07873211895763
Main Work Center	STCRUZ
Voltage	21 kV
SAP Equipment ID	101676591
Inspection Order Number	000085024925
GIS Latitude	37.07742196403703
GIS Longitude	-122.07866414578571
Structure Type	-
Person completing form	
Maintenance Plan ID	D76T3CC CAMP EVERS 2105 M1208
Maintenance Plat Name	M1208

## Access & Confirmations

In what role are you performing this work?	GO165 Compliance Inspector
Is this Asset approved for an Inspection?	Yes
Approved assets are as follows: (1) Distribution Pole (wood, composite, steel, or fiberglass) (2) Transmission Pole with Distribution under-build (steel or wood) (3) Idle Pole (4) Streetlight on Distribution Pole (5) Tree Connect	
Did you gain access to the Structure?	Yes
Did you perform a visual 360-degree Inspection of this Structure?	Yes
Did you perform a visual Inspection of conductor(s) to mid-span/weather-head in all directions?	Yes

## Structure

Select type of structure	Distribution Pole
Structure (Distribution Pole)	• No Structure damage or compelling abnormal conditions to report

## Conductor

Does this structure have PG&E owned conductor?	Yes
Conductor Issues	<ul style="list-style-type: none"> <li>• No Conductor damage or compelling abnormal conditions to report</li> </ul>

## Equipment

Does this structure have equipment?	Yes
Common Equipment Issues	<ul style="list-style-type: none"> <li>• No Equipment damage or compelling abnormal conditions to report (Common Equipment Issues)</li> </ul>
Other Equipment Issues	<ul style="list-style-type: none"> <li>• No Equipment damage or compelling abnormal conditions to report (Other Equipment Issues)</li> </ul>

## Anchor & Guys

Does or should this location have a Guy?	Yes
Anchor & Guys Issues	<ul style="list-style-type: none"> <li>• No Anchor/Guy damage or compelling abnormal conditions to report</li> </ul>

## Hardware Framing

Is Hardware Framing present on this structure?	Yes
Hardware Framing Issues	<ul style="list-style-type: none"> <li>• No Hardware Framing damage or compelling abnormal conditions to report</li> </ul>

## Vegetation

Does this structure have vegetation present?	Yes
Vegetation - EC Specific Tags	<ul style="list-style-type: none"> <li>• No vegetation issues or compelling abnormal conditions to report for the EC in accordance with GO165</li> </ul>
Vegetation - Vegetation Specific Tags	<ul style="list-style-type: none"> <li>• No vegetation issues or compelling abnormal conditions to report for the EC in accordance with GO95, PRC 4292, PRC 4293</li> </ul>

## Non-Time-Dependent Issues

Non-Time-Dependent Issues	<ul style="list-style-type: none"> <li>• No non-time dependent or compelling abnormal conditions to report</li> </ul>
---------------------------	---

## Other Required Data

Other Required Data Items	<ul style="list-style-type: none"> <li>• Open Wire Service (to weatherhead) or Open Wire Secondary at this location</li> </ul>
---------------------------	--

## Attach Photo of Open Wire Service or Open Wire Secondary



Comments

Open secondaries on crossarms



## Attach Photos

### Attach 2 Photos of the entire pole from 2 locations



### Attach Photo of the top 1/3 of the pole





**Attach Photo of the middle 1/3 of the pole**



**Attach Photo of the bottom 1/3 of the pole**



Declarations

Declaration Items	• No declarations items to report
Pending EC	117777611

Versions

Inspect Version	5.18.2.1
Checklist Version	v 2.0