



**GEOLOGIC HAZARDS**



Qlss	-Surficial slump
Qls	-Landslide
Qlsrf	-Rockfall
Qlsrs	-Rockslide
Qlsdf	-Debris flow
eu	-Erosional undermining



**DeSabra-Centerville Project**  
**FERC 803**  
 ©2005, PACIFIC GAS AND ELECTRIC CO.

**E6.1.2.4-4a**  
**Lower Centerville Canal**  
**Geologic Hazards and Risks**  
 Map 1 of 6








**GEOLOGIC HAZARDS**

Qlss	-Surficial slump
Qls	-Landslide
Qlsrf	-Rockfall
Qlssr	-Rockslide
Qlsdf	-Debris flow
eu	-Erosional undermining


**DeSabra-Centerville Project  
FERC 803**  
©2005, PACIFIC GAS AND ELECTRIC CO.

**E6.1.2.4-4b  
Lower Centerville Canal  
Geologic Hazards and Risks  
Map 2 of 6**






- ### GEOLOGIC HAZARDS
- Qlss - Surficial slump
  - Qls - Landslide
  - Qlsrf - Rockfall
  - Qlsrs - Rockslide
  - Qlsdf - Debris flow
  - eu - Erosional undermining






**DeSabra-Centerville Project  
FERC 803**  
©2005, PACIFIC GAS AND ELECTRIC CO.

**E6.1.2.4-4c  
Lower Centerville Canal  
Geologic Hazards and Risks**

**Map 3 of 6**






**GEOLOGIC HAZARDS**



Qlss	-Surficial slump
Qls	-Landslide
Qlsrf	-Rockfall
Qlsrs	-Rockslide
Qlsdf	-Debris flow
eu	-Erosional undermining



**DeSabra-Centerville Project**  
**FERC 803**  
 ©2005, PACIFIC GAS AND ELECTRIC CO.


**E6.1.2.4-4d**  
**Lower Centerville Canal**  
**Geologic Hazards and Risks**  
**Map 4 of 6**





**GEOLOGIC HAZARDS**

Qlss	-Surficial slump
Qls	-Landslide
Qlsrf	-Rockfall
Qlsrs	-Rockslide
Qlsdf	-Debris flow
eu	-Erosional undermining






**DeSabra-Centerville Project  
FERC 803**

©2005, PACIFIC GAS AND ELECTRIC CO.

**E6.1.2.4-4e  
Lower Centerville Canal  
Geologic Hazards and Risks**


**Map 5 of 6**





**GEOLOGIC HAZARDS**

Qlss	-Surficial slump
Qls	-Landslide
Qlsrf	-Rockfall
Qlsrs	-Rockslide
Qlsdf	-Debris flow
eu	-Erosional undermining



**DeSabra-Centerville Project**  
**FERC 803**  
 ©2005, PACIFIC GAS AND ELECTRIC CO.

**E6.1.2.4-4f**  
**Lower Centerville Canal**  
**Geologic Hazards and Risks**  
 Map 6 of 6

