PUBLIC UTILITIES COMMISSION
505 Van Ness Avenue
San Francisco CA 94102-3298

Pacific Gas & Electric Company
ELC (Corp ID 39)
Status of Advice Letter 6890E
As of September 5, 2023

Subject: Information-Only Voltage Complaints Reports for the Period February 22, 2022 to February 21, 2023 Pursuant to Resolution E-4898 Ordering Paragraph 7

Division Assigned: Energy

Date Filed: 03-22-2023

Date to Calendar: 03-29-2023

Authorizing Documents: E-4898

Disposition:	**Accepted**
Effective Date:	**03-22-2023**

Resolution Required: No

Resolution Number: None

Commission Meeting Date: None

CPUC Contact Information:

edtariffunit@cpuc.ca.gov

AL Certificate Contact Information:

Annie Ho
(415) 973-8794
PGETariffs@pge.com

STATE OF CALIFORNIA **GAVIN NEWSOM,** *Governor*

PUBLIC UTILITIES COMMISSION
505 Van Ness Avenue
San Francisco CA 94102-3298

To: Energy Company Filing Advice Letter

From: Energy Division PAL Coordinator

Subject: Your Advice Letter Filing

The Energy Division of the California Public Utilities Commission has processed your recent Advice Letter (AL) filing and is returning an AL status certificate for your records.

The AL status certificate indicates:

Advice Letter Number
Name of Filer
CPUC Corporate ID number of Filer
Subject of Filing
Date Filed
Disposition of Filing (Accepted, Rejected, Withdrawn, etc.)
Effective Date of Filing
Other Miscellaneous Information (e.g., Resolution, if applicable, etc.)

The Energy Division has made no changes to your copy of the Advice Letter Filing; please review your Advice Letter Filing with the information contained in the AL status certificate, and update your Advice Letter and tariff records accordingly.

All inquiries to the California Public Utilities Commission on the status of your Advice Letter Filing will be answered by Energy Division staff based on the information contained in the Energy Division's PAL database from which the AL status certificate is generated. If you have any questions on this matter please contact the:

Energy Division's Tariff Unit by e-mail to
edtariffunit@cpuc.ca.gov

Sidney Bob Dietz II
Director
Regulatory Relations

Pacific Gas and Electric Company
77 Beale St., Mail Code B13U
P.O. Box 770000
San Francisco, CA 94177

Fax: 415-973-3585

March 22, 2023

Advice 6890-E
(Pacific Gas and Electric Company ID U 39 E)

Public Utilities Commission of the State of California

Subject: **Information-Only Voltage Complaints Reports for the Period February 22, 2022 to February 21, 2023 Pursuant to Resolution E-4898 Ordering Paragraph 7**

Purpose

The purpose of this information-only advice letter is for Pacific Gas and Electric Company (PG&E) to submit its report on the amount of voltage excursions pursuant to Resolution E-4898[1] Ordering Paragraph (OP) 7.

Background

The California Public Utilities Commission (CPUC or Commission) initiated Rulemaking (R.) 11-09-011 on September 22, 2011 to review and, if necessary, revise the rules and regulations governing the interconnection of generation and storage facilities to the electric distribution systems of the investor-owned utilities (IOUs) [2]. The IOUs' rules and regulations pertaining to the interconnection of generating facilities are set forth in the Electric Rule 21 Tariff.

In early 2013, the Smart Inverter Working Group (SIWG) was formed by parties of R.11-09-011 to develop proposals to take advantage of the new, rapidly advancing technical capabilities of inverters. In March 2016, the SIWG completed its first set of recommendations for the Phase 3 advanced functions.[3,4]

---

[1] Resolution E-4898. *Approval, with Modifications, of Request for Modifications to Electric Rule 21 Tariff to Incorporate Smart Inverter Phase 3 Advanced Functions in Compliance with Decision 16-06-052* dated April 26, 2018, which can be found at: http://docs.cpuc.ca.gov/PublishedDocs/Published/G000/M213/K658/213658887.PDF

[2] IOUs or the investor-owned utilities, i.e., Pacific Gas and Electric Company (PG&E), Southern California Edison Company (SCE), and San Diego Gas & Electric (SDG&E).

[3] SIWG Phase 3 DER Functions: Recommendations to the CPUC for Rule 21, Phase 3 Function Key Requirements, and Additional Discussion Issues, Issued March 31, 2017.

[4] The SIWG's Phase 1 and Phase 2 recommendations were incorporated into Rule 21 in April 2015 and April 2017.

Among the key Phase 3 advanced functions of relevance to this advice letter was Function 6, Volt Watt Mode. In E-4898[5] it is described as:

> "As a general rule, the production of active power raises voltage. This relationship can be problematic when solar photovoltaic (PV) systems interconnect in large numbers on distribution circuits where utilities have not planned for voltage rise and where existing distribution equipment cannot lower voltage. **Volt Watt Mode modifies active power from DERs based on predetermined voltage ranges to prevent the local voltage on the distribution circuit from rising/dropping outside of allowable levels.** Voltage regulators are a common mitigation measure used on circuits with and without PV to ensure that voltage stays within acceptable levels all the way to the end of the circuit. As PV injects power to the grid at various points along a circuit, the complex interaction of ever-changing load and generation conditions can cause imbalances in voltage levels. **These voltage excursions can be mitigated by the smart inverter's Volt Watt Mode raising or lowering voltage but that change in voltage reduces the amount of real power that is exported.**" (Emphasis added)

On June 23, 2016, the Commission adopted Decision (D.) 16-06-052[6], which directed the IOUs to submit advice letters proposing revisions to Rule 21 setting forth any agreed-upon technical requirements, testing and certification processes, and effective dates for Phase 3 functions. On November 17, 2016, the Energy Division hosted a public workshop with the purpose of providing guidance to the IOUs on the Advice Letter submittals.

On December 20, 2016, the IOUs jointly submitted a Tier 1 Advice Letter (AL) 4983-E[7] that provided a work plan and an outline of next steps for tariff development including a status update on the activities outlined in the work plan by March 30, 2017.

On March 31, 2017, the SIWG submitted final revisions to the Phase 3 recommendations. In addition, the IOUs submitted the required status update on March 30, 2017. In accordance with the work plan, the IOUs each anticipated submitting a Tier 3 Advice Letter in June 2017.

---

[5] E-4898, page 4.

[6] D. 16-06-052 – *Alternate Decision Instituting Cost Certainty, Granting Joint Motions To Approve Proposed Revisions To Electric Tariff Rule 21, And Providing Smart Inverter Development A Pathway Forward For Pacific Gas And Electric Company, Southern California Edison Company, And San Diego Gas & Electric Company* http://docs.cpuc.ca.gov/PublishedDocs/Published/G000/M164/K376/164376491.pdf

[7] Information-Only Advice Letter Joint Investor-Owned Utilities Status Report and Supporting Action Plan for the Development of Advanced Inverter Functions for Smart Inverters (Phase 3), submitted December 20, 2016, approved January 26, 2017, and made effective January 19, 2017. https://www.pge.com/tariffs/tm2/pdf/ELEC_4983-E.pdf

On June 27, 2017, the IOUs were granted a requested to extend the submittal date of the Tier 3 Advice Letters to August 18, 2017. On August 18, 2017, PG&E submitted Advice Letter 5129-E[8] to comply with D.16-06-052 proposing Rule 21 tariff revisions.

Following the submission of AL 5129-E, the Energy Division held a public workshop to discuss and, if possible, resolve issues raised in protests to the advice letters.

On April 27, 2018 the CPUC issued Resolution E-4898 - Approval, with Modifications, of Request for Modifications to Electric Rule 21 Tariff to Incorporate Smart Inverter Phase 3 Advanced Functions in Compliance with Decision 16-06-052. Among other things, OP 1 stated that PG&E AL 5129-E is approved as modified herein.

With regards to this advice letter, E-4898 OP 7 requires:

> Pacific Gas and Electric, Southern California Edison, and San Diego Gas & Electric shall each submit quarterly reports via Tier 1 information-only Advice Letter for one year starting three months after the mandatory activation of Function 6 **on the voltage complaint process**, and following the completion of the quarterly reports, shall submit annual reports on the voltage complaint process via Tier 1 information-only Advice Letter. No sooner than five years after the activation of Function 6, the IOUs may submit proposals via Tier 2 Advice Letter on whether to continue or modify the reporting requirement. [Emphasis added]

In its Discussion[9] about the voltage complaint process, the E-4898 noted:[10]

> In the event that customers, with or without DERs, experience voltage issues, these customers can and should report these issues to the utility. The Volt Watt Mode will assist in discovering these voltage issues and ensuring that they are not exacerbated. Reporting on the voltage complaint process, as is discussed later in this Discussion section, will assist with enforcing utility compliance with Rule 2 and ensuring voltage issues are resolved in a timely and appropriate manner.
>
> In the case that utility engineering analysis uncovers that the voltage issue is caused by the customer, it is the customer's responsibility under Rule 2 to resolve the issue. In this situation, the IOU works with the customer to help the customer adjust their settings if feasible or coordinate on the appropriate infrastructure upgrades. Volt Watt Mode helps these customers to stay in compliance with Rule 2. The alternative could be worse for the customer. If their voltage rises above 110% of nominal voltage, then

---

[8] AL 5129-E - *Modifications to PG&E's Electric Rule 21 Tariff and Interconnection Agreements and Forms to Incorporate Smart Inverter Phase 3 Modifications* – Submitted August 18, 2018, and approved May 8, 2018 effective April 25, 2018, per E-4898.
https://www.pge.com/tariffs/assets/pdf/adviceletter/ELEC_5129-E.pdf

[9] Sub-issue: Impact of Activation of Function 6 starting on Page 30 of E-4898

[10] Ibid, Page 32.

their system automatically trips off, which would have more of an impact on their power production than the small amount of curtailment from the use of Volt Watt Mode.[11]

Additionally, E-4898 notes:

> If we find that the IOUs are not resolving voltage issues within a timely period that are on the utility side of the meter, and thus, the responsibility of the IOU, we may determine to deactivate the Volt Watt Mode at a later time. In order to do so, we order the IOUs to report on their voltage complaint resolution process. Specifically, we order the IOUs to report on **how many voltage complaints were received with categories for both DER and non-DER customers, whether the complaint was from the customer or a third-party on behalf of the customer, the duration it took to resolve each complaint, whether the voltage issue was on the utility side or the customer side of the meter, the method for resolving the voltage issue, and the cost of the method for resolving the voltage issue**.[12] [emphasis added]
>
> … the IOUs shall file quarterly reports via Tier 1 Advice Letter on the voltage complaint process for one full calendar year, i.e. four reports, starting three months after the mandatory activation of Function 6. Following this year, the IOUs shall submit annual reports on the voltage complaint process via Tier 1 Advice Letter with a submittal date based on the anniversary of the activation of Function 6. No sooner than five years after the activation of Function 6, the IOUs may submit proposals via Tier 2 Advice Letter on whether to continue or modify the reporting requirement.
>
> By the time of the first quarterly Tier 1 Advice Letter the utilities shall update their websites with clearly identified and easy to find information explaining their respective voltage complaint processes, including steps of the customer and utility and how a customer can contact the utility regarding a voltage issue. This section of utility website should explain how the utility determines if the cause of a voltage issue is attributable to the utility or the customer.[13]

Prior Reports Submitted

- AL 5572-E - 1st Voltage Complaints Report Information-Only Voltage Complaints Reports for the Period March 22, 2019 to May 22, 2019 Pursuant to Resolution E-4898 Ordering Paragraph 7 Voltage complaints (1st quarterly report)
- AL 5642-E - 2nd Voltage Complaints Report - Information-Only Voltage Complaints Reports for the Period May 23, 2019 through August 22, 2019 Pursuant to Resolution E-4898 Ordering Paragraph 7 (2nd quarterly report)

[11] Resolution, p 30, 31
[12] Resolution, p. 33
[13] E-4898, page 33

- AL 5721-E - 3rd Voltage Complaints Report Information-Only Voltage Complaints Reports for the Period August 23, 2019 through November 22, 2019 Pursuant to Resolution E-4898 Ordering Paragraph 7 (3rd quarterly report)
- AL 5788-E - 4th Voltage Complaints Report - Information-Only Voltage Complaints Reports for the Period November 23, 2019 through February 22, 2020 Pursuant to Resolution E-4898 Ordering Paragraph 7 Voltage and Frequency Reporting - AL due 150 days from E-5016. i.e., 5/17/2020
- AL 6126-E - 5th Annual Voltage Complaints Reports for the Period February 22, 2020, through February 21, 2021, Pursuant to Resolution E-4898 Ordering Paragraph 7
- AL 6534-E - Information-Only Voltage Complaints Reports for the Period February 22, 2021 to February 21, 2022 Pursuant to Resolution E-4898 Ordering Paragraph 7

This advice letter is submitted to present the standardized reporting of the voltage complaints received by PG&E for the period from February 22, 2022 to February 21, 2023, pursuant to E-4898 OP 7. Having completed the first year of quarterly reports, this is the third annual report.

Voltage Complaint Report

PG&E voltage complaint process website can be found at:

https://www.pge.com/en_US/residential/outages/current-outages/report-view-an-electric-outage/additional-resources/report-voltage-problem.page

Also, for quick access, a web browser search for “PG&E voltage complaint” will bring up this page.

The Report is included as **Attachment A.**

For simplification, the report breaks down the resolution for the complaints into 16 generic categories.

Please note the costs in this report are a general cost estimate. For future reporting, PG&E is working on more detailed cost estimation.

Protests

This is an information-only advice letter submittal. Pursuant to General Order 96-B Section 6.2, PG&E is not seeking relief through this advice letter and is not subject to protest.

Effective Date

Pursuant to Resolution E-4898 Ordering Paragraph 7, PG&E requests that this Tier 1 information-only advice letter become effective upon date of submittal, which is March 22, 2023.

Notice

In accordance with General Order 96-B, Section IV, a copy of this advice letter is being sent electronically to parties shown on the attached list and the parties on the service lists for R.11-09-011 and R.17-07-007. Address changes to the General Order 96-B service list should be directed to PG&E at email address PGETariffs@pge.com. For changes to any other service list, please contact the Commission's Process Office at (415) 703-2021 or at Process_Office@cpuc.ca.gov. Send all electronic approvals to PGETariffs@pge.com. Advice letter submittals can also be accessed electronically at: http://www.pge.com/tariffs/.

/S/
Sidney Bob Dietz II
Director, Regulatory Relations

cc: Service Lists R.11-09-011 and R.17-07-007

California Public Utilities Commission

ADVICE LETTER SUMMARY

ENERGY UTILITY

MUST BE COMPLETED BY UTILITY (Attach additional pages as needed)

Company name/CPUC Utility No.: Pacific Gas and Electric Company (ID U39 E)

Utility type:
☑ ELC ☐ GAS ☐ WATER
☐ PLC ☐ HEAT

Contact Person: Annie Ho
Phone #: (415) 973-8794
E-mail: PGETariffs@pge.com
E-mail Disposition Notice to: AMHP@pge.com

EXPLANATION OF UTILITY TYPE
ELC = Electric GAS = Gas WATER = Water
PLC = Pipeline HEAT = Heat

(Date Submitted / Received Stamp by CPUC)

Advice Letter (AL) #: 6890-E

Tier Designation: 1

Subject of AL: Information-Only Voltage Complaints Reports for the Period February 22, 2022 to February 21, 2023 Pursuant to Resolution E-4898 Ordering Paragraph 7

Keywords (choose from CPUC listing): Compliance

AL Type: ☐ Monthly ☐ Quarterly ☐ Annual ☑ One-Time ☐ Other:

If AL submitted in compliance with a Commission order, indicate relevant Decision/Resolution #: E-4898

Does AL replace a withdrawn or rejected AL? If so, identify the prior AL:

Summarize differences between the AL and the prior withdrawn or rejected AL:

Confidential treatment requested? ☐ Yes ☑ No

If yes, specification of confidential information:
Confidential information will be made available to appropriate parties who execute a nondisclosure agreement. Name and contact information to request nondisclosure agreement/ access to confidential information:

Resolution required? ☐ Yes ☑ No

Requested effective date: 3/22/23

No. of tariff sheets: N/A

Estimated system annual revenue effect (%): N/A

Estimated system average rate effect (%): N/A

When rates are affected by AL, include attachment in AL showing average rate effects on customer classes (residential, small commercial, large C/I, agricultural, lighting).

Tariff schedules affected: N/A

Service affected and changes proposed[1]: N/A

Pending advice letters that revise the same tariff sheets: N/A

[1]Discuss in AL if more space is needed.

Clear Form

Protests and correspondence regarding this AL are to be sent via email and are due no later than 20 days after the date of this submittal, unless otherwise authorized by the Commission, and shall be sent to:

California Public Utilities Commission
Energy Division Tariff Unit Email:
EDTariffUnit@cpuc.ca.gov

Contact Name: Sidney Bob Dietz II, c/o Megan Lawson
Title: Director, Regulatory Relations
Utility/Entity Name: Pacific Gas and Electric Company

Telephone (xxx) xxx-xxxx: (415)973-2093
Facsimile (xxx) xxx-xxxx: (415)973-3582
Email: PGETariffs@pge.com

Contact Name:
Title:
Utility/Entity Name:

Telephone (xxx) xxx-xxxx:
Facsimile (xxx) xxx-xxxx:
Email:

CPUC
Energy Division Tariff Unit
505 Van Ness Avenue
San Francisco, CA 94102

Clear Form

Advice 6890-E
March 22, 2023

Attachment A

Report

REPORTING PERIOD
February 22, 2022 - February 21, 2023

	DER	REPORTED BY THIRD PARTY	VOLTACE ISSUE ON UTILITY SIDE
YES	810	12	19939
NO	46766	47564	27637
TOTAL	47576	47576	47576

Row Labels	Count of METHOD
CUSTOMER ISSUE	27637
DIST - CHANGE SETTINGS	197
DIST - CIRCUIT RETURN TO NORMAL CONFIG	12
DIST - REPAIR EQUIPMENT	54
DIST - REPLACE EQUIPMENT	46
DIST - REPLACE FUSE	1494
DIST - TREE TRIMMING	1572
SEC/SVC - REPAIR	6387
SEC/SVC - REPLACE	9499
SUB/TRANS - CHANGE SETTINGS	23
SUB/TRANS - REPAIR	16
SUB/TRANS - REPLACE	5
TX - INSTALL	4
TX - REPLACE	556
TX/SEC/SVC- REPLACE	74
Grand Total	**47576**

DMS/FAS/PQ/VRT	VC CASE	DER	REPORTED BY THIRD PARTY	VOLTAGE ISSUE ON UTILITY SIDE	INVESTIGATION DURATION (DAYS)	METHOD	COST
FAS_00008	00001	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00009	00002	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00011	00003	N	N	Y	1	TX - REPLACE	2500
FAS_00013	00004	N	N	N	1	CUSTOMER ISSUE	-
FAS_00019	00005	N	N	N	1	CUSTOMER ISSUE	-
FAS_00020	00006	N	N	N	1	CUSTOMER ISSUE	-
FAS_00021	00007	N	N	N	1	CUSTOMER ISSUE	-
FAS_00023	00008	N	N	N	1	CUSTOMER ISSUE	-
FAS_00026	00009	N	N	N	1	CUSTOMER ISSUE	-
FAS_00030	00010	N	N	N	1	CUSTOMER ISSUE	-
FAS_00031	00011	N	N	N	1	CUSTOMER ISSUE	-
FAS_00033	00012	N	N	N	1	CUSTOMER ISSUE	-
FAS_00034	00013	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00039	00014	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00050	00015	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00061	00016	N	N	N	1	CUSTOMER ISSUE	-
FAS_00063	00017	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00064	00018	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00065	00019	N	N	N	1	CUSTOMER ISSUE	-
FAS_00066	00020	N	N	N	1	CUSTOMER ISSUE	-
FAS_00070	00021	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00071	00022	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00072	00023	N	N	N	1	CUSTOMER ISSUE	-
FAS_00073	00024	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00074	00025	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00075	00026	N	N	N	1	CUSTOMER ISSUE	-
FAS_00076	00027	Y	N	N	1	CUSTOMER ISSUE	-
FAS_00077	00028	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00078	00029	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00079	00030	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00080	00031	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00081	00032	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00082	00033	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00083	00034	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00084	00035	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00085	00036	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00086	00037	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00087	00038	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00088	00039	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00089	00040	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00090	00041	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00091	00042	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00092	00043	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00094	00044	N	N	N	1	CUSTOMER ISSUE	-
FAS_00095	00045	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00096	00046	N	N	N	1	CUSTOMER ISSUE	-
FAS_00098	00047	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00099	00048	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00100	00049	N	N	N	1	CUSTOMER ISSUE	-
FAS_00101	00050	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00104	00051	N	N	N	1	CUSTOMER ISSUE	-
FAS_00105	00052	N	N	N	3	CUSTOMER ISSUE	-
FAS_00106	00053	N	N	Y	1	SUB/TRANS - REPLACE	10000
FAS_00107	00054	Y	N	Y	1	SUB/TRANS - REPLACE	10000
FAS_00108	00055	N	N	Y	1	SUB/TRANS - REPLACE	10000
FAS_00110	00056	N	N	N	1	CUSTOMER ISSUE	-

FAS_00113	00057	N	N	N	1	CUSTOMER ISSUE	-
FAS_00115	00058	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00116	00059	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00117	00060	N	N	Y	1	TX - REPLACE	2500
FAS_00119	00061	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00120	00062	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00122	00063	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
FAS_00126	00064	N	N	N	1	CUSTOMER ISSUE	-
FAS_00128	00065	Y	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00129	00066	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00130	00067	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00131	00068	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00132	00069	N	N	Y	3	DIST - REPLACE FUSE	708.75
FAS_00133	00070	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00140	00071	N	N	N	1	CUSTOMER ISSUE	-
FAS_00142	00072	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00144	00073	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00145	00074	N	N	Y	2	TX - REPLACE	2500
FAS_00146	00075	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00147	00076	N	N	N	1	CUSTOMER ISSUE	-
FAS_00148	00077	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00150	00078	N	N	N	1	CUSTOMER ISSUE	-
FAS_00151	00079	N	N	N	1	CUSTOMER ISSUE	-
FAS_00152	00080	N	N	N	1	CUSTOMER ISSUE	-
FAS_00153	00081	N	N	Y	1	TX - REPLACE	2500
FAS_00154	00082	N	N	Y	1	TX - REPLACE	2500
FAS_00156	00083	N	N	N	1	CUSTOMER ISSUE	-
FAS_00162	00084	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00165	00085	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00166	00086	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00167	00087	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00169	00088	N	N	N	1	CUSTOMER ISSUE	-
FAS_00172	00089	N	N	Y	1	TX - REPLACE	2500
FAS_00173	00090	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00175	00091	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_00179	00092	N	N	N	1	CUSTOMER ISSUE	-
FAS_00186	00093	N	N	N	1	CUSTOMER ISSUE	-
FAS_00187	00094	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00188	00095	N	N	Y	1	TX - REPLACE	2500
FAS_00189	00096	N	N	N	1	CUSTOMER ISSUE	-
FAS_00190	00097	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00191	00098	Y	N	N	1	CUSTOMER ISSUE	-
FAS_00197	00099	N	N	N	1	CUSTOMER ISSUE	-
FAS_00199	00100	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00204	00101	N	N	Y	1	TX - REPLACE	2500
FAS_00208	00102	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00209	00103	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00212	00104	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00213	00105	N	N	N	1	CUSTOMER ISSUE	-
FAS_00216	00106	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
FAS_00217	00107	N	N	N	1	CUSTOMER ISSUE	-
FAS_00219	00108	N	N	N	1	CUSTOMER ISSUE	-
FAS_00220	00109	N	N	Y	5	SEC/SVC - REPAIR	472.5
FAS_00224	00110	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00225	00111	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00228	00112	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00229	00113	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00231	00114	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00233	00115	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_00235	00116	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00239	00117	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_00241	00118	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00242	00119	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00243	00120	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_00244	00121	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00245	00122	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00247	00123	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00248	00124	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00251	00125	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00254	00126	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00255	00127	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00256	00128	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00257	00129	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00259	00130	N	N	N	1	CUSTOMER ISSUE	-
FAS_00263	00131	Y	N	N	1	CUSTOMER ISSUE	-
FAS_00266	00132	N	N	N	3	CUSTOMER ISSUE	-
FAS_00269	00133	N	N	Y	3	DIST - REPLACE FUSE	708.75
FAS_00271	00134	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00275	00135	N	N	N	1	CUSTOMER ISSUE	-
FAS_00276	00136	N	N	Y	1	SEC/SVC - REPAIR	472.5

FAS_00284	00137	N	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
FAS_00298	00138	N	N	N	1	CUSTOMER ISSUE	-
FAS_00299	00139	N	N	N	1	CUSTOMER ISSUE	-
FAS_00301	00140	N	N	N	1	CUSTOMER ISSUE	-
FAS_00302	00141	N	N	N	1	CUSTOMER ISSUE	-
FAS_00303	00142	Y	N	N	1	CUSTOMER ISSUE	-
FAS_00304	00143	Y	N	N	1	CUSTOMER ISSUE	-
FAS_00306	00144	Y	N	N	1	CUSTOMER ISSUE	-
FAS_00308	00145	N	N	N	1	CUSTOMER ISSUE	-
FAS_00309	00146	N	N	N	1	CUSTOMER ISSUE	-
FAS_00310	00147	Y	N	N	1	CUSTOMER ISSUE	-
FAS_00311	00148	Y	N	N	2	CUSTOMER ISSUE	-
FAS_00312	00149	N	N	N	1	CUSTOMER ISSUE	-
FAS_00313	00150	N	N	N	1	CUSTOMER ISSUE	-
FAS_00314	00151	N	N	N	1	CUSTOMER ISSUE	-
FAS_00315	00152	N	N	N	1	CUSTOMER ISSUE	-
FAS_00316	00153	N	N	N	1	CUSTOMER ISSUE	-
FAS_00317	00154	N	N	N	1	CUSTOMER ISSUE	-
FAS_00318	00155	N	N	N	1	CUSTOMER ISSUE	-
FAS_00319	00156	N	N	N	1	CUSTOMER ISSUE	-
FAS_00320	00157	N	N	N	1	CUSTOMER ISSUE	-
FAS_00321	00158	N	N	N	1	CUSTOMER ISSUE	-
FAS_00323	00159	N	N	N	1	CUSTOMER ISSUE	-
FAS_00324	00160	N	N	N	2	CUSTOMER ISSUE	-
FAS_00325	00161	N	N	N	1	CUSTOMER ISSUE	-
FAS_00326	00162	N	N	N	1	CUSTOMER ISSUE	-
FAS_00329	00163	N	N	N	1	CUSTOMER ISSUE	-
FAS_00330	00164	N	N	N	1	CUSTOMER ISSUE	-
FAS_00331	00165	N	N	N	1	CUSTOMER ISSUE	-
FAS_00332	00166	N	N	N	3	CUSTOMER ISSUE	-
FAS_00333	00167	N	N	N	1	CUSTOMER ISSUE	-
FAS_00334	00168	N	N	N	1	CUSTOMER ISSUE	-
FAS_00336	00169	N	N	N	1	CUSTOMER ISSUE	-
FAS_00337	00170	N	N	N	1	CUSTOMER ISSUE	-
FAS_00338	00171	N	N	N	1	CUSTOMER ISSUE	-
FAS_00339	00172	N	N	N	1	CUSTOMER ISSUE	-
FAS_00340	00173	N	N	N	1	CUSTOMER ISSUE	-
FAS_00342	00174	N	N	N	1	CUSTOMER ISSUE	-
FAS_00343	00175	N	N	N	1	CUSTOMER ISSUE	-
FAS_00344	00176	N	N	N	1	CUSTOMER ISSUE	-
FAS_00345	00177	N	N	N	1	CUSTOMER ISSUE	-
FAS_00346	00178	N	N	N	1	CUSTOMER ISSUE	-
FAS_00347	00179	N	N	N	1	CUSTOMER ISSUE	-
FAS_00348	00180	N	N	N	1	CUSTOMER ISSUE	-
FAS_00349	00181	N	N	N	2	CUSTOMER ISSUE	-
FAS_00350	00182	N	N	N	1	CUSTOMER ISSUE	-
FAS_00351	00183	N	N	N	1	CUSTOMER ISSUE	-
FAS_00352	00184	N	N	N	1	CUSTOMER ISSUE	-
FAS_00353	00185	N	N	N	5	CUSTOMER ISSUE	-
FAS_00354	00186	N	N	N	1	CUSTOMER ISSUE	-
FAS_00355	00187	N	N	N	1	CUSTOMER ISSUE	-
FAS_00357	00188	N	N	N	1	CUSTOMER ISSUE	-
FAS_00358	00189	N	N	N	1	CUSTOMER ISSUE	-
FAS_00359	00190	N	N	N	2	CUSTOMER ISSUE	-
FAS_00361	00191	N	N	N	1	CUSTOMER ISSUE	-
FAS_00362	00192	N	N	N	1	CUSTOMER ISSUE	-
FAS_00363	00193	N	N	N	1	CUSTOMER ISSUE	-
FAS_00364	00194	Y	N	N	1	CUSTOMER ISSUE	-
FAS_00365	00195	N	N	N	1	CUSTOMER ISSUE	-
FAS_00366	00196	N	N	N	1	CUSTOMER ISSUE	-
FAS_00367	00197	N	N	N	1	CUSTOMER ISSUE	-
FAS_00369	00198	N	N	N	1	CUSTOMER ISSUE	-
FAS_00370	00199	N	N	N	1	CUSTOMER ISSUE	-
FAS_00372	00200	N	N	N	3	CUSTOMER ISSUE	-
FAS_00373	00201	N	N	N	1	CUSTOMER ISSUE	-
FAS_00374	00202	Y	N	N	1	CUSTOMER ISSUE	-
FAS_00375	00203	N	N	N	1	CUSTOMER ISSUE	-
FAS_00376	00204	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_00377	00205	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_00381	00206	N	N	N	1	CUSTOMER ISSUE	-
FAS_00382	00207	N	N	N	1	CUSTOMER ISSUE	-
FAS_00390	00208	N	N	N	1	CUSTOMER ISSUE	-
FAS_00391	00209	N	N	N	1	CUSTOMER ISSUE	-
FAS_00397	00210	N	N	N	1	CUSTOMER ISSUE	-
FAS_00411	00211	N	N	N	1	CUSTOMER ISSUE	-
FAS_00463	00212	N	N	N	1	CUSTOMER ISSUE	-
FAS_00464	00213	N	N	N	1	CUSTOMER ISSUE	-
FAS_00465	00214	N	N	N	1	CUSTOMER ISSUE	-
FAS_00466	00215	N	N	N	5	CUSTOMER ISSUE	-
FAS_00467	00216	N	N	Y	1	SEC/SVC - REPLACE	708.75

FAS_00470	00217	Y	N	N	1	CUSTOMER ISSUE	-
FAS_00471	00218	N	N	N	1	CUSTOMER ISSUE	-
FAS_00472	00219	N	N	N	1	CUSTOMER ISSUE	-
FAS_00473	00220	N	N	N	1	CUSTOMER ISSUE	-
FAS_00475	00221	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00477	00222	N	N	N	1	CUSTOMER ISSUE	-
FAS_00478	00223	N	N	N	1	CUSTOMER ISSUE	-
FAS_00479	00224	N	N	N	1	CUSTOMER ISSUE	-
FAS_00480	00225	N	N	N	1	CUSTOMER ISSUE	-
FAS_00481	00226	N	N	N	1	CUSTOMER ISSUE	-
FAS_00484	00227	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00486	00228	N	N	N	1	CUSTOMER ISSUE	-
FAS_00487	00229	N	N	N	1	CUSTOMER ISSUE	-
FAS_00488	00230	N	N	N	1	CUSTOMER ISSUE	-
FAS_00491	00231	N	N	N	1	CUSTOMER ISSUE	-
FAS_00495	00232	N	N	N	1	CUSTOMER ISSUE	-
FAS_00496	00233	N	N	N	2	CUSTOMER ISSUE	-
FAS_00501	00234	Y	N	N	1	CUSTOMER ISSUE	-
FAS_00504	00235	N	N	N	1	CUSTOMER ISSUE	-
FAS_00512	00236	N	N	N	1	CUSTOMER ISSUE	-
FAS_00536	00237	N	N	N	1	CUSTOMER ISSUE	-
FAS_00537	00238	N	N	N	1	CUSTOMER ISSUE	-
FAS_00541	00239	N	N	N	1	CUSTOMER ISSUE	-
FAS_00572	00240	N	N	N	1	CUSTOMER ISSUE	-
FAS_00581	00241	N	N	N	1	CUSTOMER ISSUE	-
FAS_00582	00242	N	N	N	1	CUSTOMER ISSUE	-
FAS_00592	00243	N	N	N	1	CUSTOMER ISSUE	-
FAS_00597	00244	N	N	N	1	CUSTOMER ISSUE	-
FAS_00604	00245	N	N	N	1	CUSTOMER ISSUE	-
FAS_00611	00246	N	N	N	1	CUSTOMER ISSUE	-
FAS_00613	00247	Y	N	N	1	CUSTOMER ISSUE	-
FAS_00614	00248	N	N	N	1	CUSTOMER ISSUE	-
FAS_00619	00249	N	N	N	1	CUSTOMER ISSUE	-
FAS_00624	00250	N	N	N	1	CUSTOMER ISSUE	-
FAS_00627	00251	N	N	N	1	CUSTOMER ISSUE	-
FAS_00638	00252	N	N	N	1	CUSTOMER ISSUE	-
FAS_00639	00253	N	N	N	1	CUSTOMER ISSUE	-
FAS_00640	00254	Y	N	N	1	CUSTOMER ISSUE	-
FAS_00641	00255	N	N	N	1	CUSTOMER ISSUE	-
FAS_00642	00256	N	N	N	1	CUSTOMER ISSUE	-
FAS_00644	00257	N	N	N	1	CUSTOMER ISSUE	-
FAS_00655	00258	N	N	N	1	CUSTOMER ISSUE	-
FAS_00659	00259	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
FAS_00660	00260	N	N	N	1	CUSTOMER ISSUE	-
FAS_00661	00261	N	N	N	1	CUSTOMER ISSUE	-
FAS_00662	00262	N	N	N	1	CUSTOMER ISSUE	-
FAS_00664	00263	N	N	N	1	CUSTOMER ISSUE	-
FAS_00666	00264	Y	N	N	1	CUSTOMER ISSUE	-
FAS_00667	00265	N	N	N	1	CUSTOMER ISSUE	-
FAS_00670	00266	N	N	N	1	CUSTOMER ISSUE	-
FAS_00671	00267	N	N	N	1	CUSTOMER ISSUE	-
FAS_00673	00268	N	N	N	1	CUSTOMER ISSUE	-
FAS_00675	00269	N	N	N	1	CUSTOMER ISSUE	-
FAS_00676	00270	N	N	N	1	CUSTOMER ISSUE	-
FAS_00677	00271	N	N	N	1	CUSTOMER ISSUE	-
FAS_00678	00272	N	N	N	1	CUSTOMER ISSUE	-
FAS_00679	00273	N	N	N	1	CUSTOMER ISSUE	-
FAS_00682	00274	N	N	N	1	CUSTOMER ISSUE	-
FAS_00684	00275	N	N	N	1	CUSTOMER ISSUE	-
FAS_00685	00276	N	N	N	1	CUSTOMER ISSUE	-
FAS_00687	00277	N	N	N	1	CUSTOMER ISSUE	-
FAS_00688	00278	N	N	N	1	CUSTOMER ISSUE	-
FAS_00689	00279	N	N	N	1	CUSTOMER ISSUE	-
FAS_00690	00280	N	N	N	1	CUSTOMER ISSUE	-
FAS_00691	00281	Y	N	N	1	CUSTOMER ISSUE	-
FAS_00695	00282	N	N	N	1	CUSTOMER ISSUE	-
FAS_00696	00283	N	N	N	1	CUSTOMER ISSUE	-
FAS_00697	00284	Y	N	N	1	CUSTOMER ISSUE	-
FAS_00698	00285	N	N	N	1	CUSTOMER ISSUE	-
FAS_00699	00286	N	N	N	1	CUSTOMER ISSUE	-
FAS_00700	00287	N	N	N	1	CUSTOMER ISSUE	-
FAS_00701	00288	N	N	N	1	CUSTOMER ISSUE	-
FAS_00702	00289	N	N	N	1	CUSTOMER ISSUE	-
FAS_00703	00290	N	N	N	1	CUSTOMER ISSUE	-
FAS_00704	00291	N	N	N	1	CUSTOMER ISSUE	-
FAS_00705	00292	N	N	N	1	CUSTOMER ISSUE	-
FAS_00706	00293	N	N	N	1	CUSTOMER ISSUE	-
FAS_00707	00294	N	N	N	1	CUSTOMER ISSUE	-
FAS_00708	00295	N	N	N	1	CUSTOMER ISSUE	-
FAS_00709	00296	N	N	N	1	CUSTOMER ISSUE	-

FAS_00710	00297	N	N	N	1	CUSTOMER ISSUE	-
FAS_00711	00298	N	N	N	1	CUSTOMER ISSUE	-
FAS_00715	00299	N	N	N	1	CUSTOMER ISSUE	-
FAS_00716	00300	Y	N	N	1	CUSTOMER ISSUE	-
FAS_00720	00301	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00721	00302	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00725	00303	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00726	00304	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00728	00305	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00729	00306	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00730	00307	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00731	00308	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00732	00309	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00733	00310	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00734	00311	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00735	00312	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00736	00313	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00737	00314	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00738	00315	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00739	00316	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00740	00317	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00741	00318	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00742	00319	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00743	00320	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00744	00321	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00745	00322	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00746	00323	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00747	00324	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00748	00325	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00751	00326	N	N	N	1	CUSTOMER ISSUE	-
FAS_00752	00327	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_00764	00328	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00767	00329	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00781	00330	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00786	00331	N	N	Y	3	SUB/TRANS - REPLACE	10000
FAS_00790	00332	N	N	Y	2	TX - REPLACE	2500
FAS_00797	00333	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00800	00334	N	N	N	1	CUSTOMER ISSUE	-
FAS_00801	00335	N	N	N	1	CUSTOMER ISSUE	-
FAS_00802	00336	N	N	N	1	CUSTOMER ISSUE	-
FAS_00803	00337	N	N	N	1	CUSTOMER ISSUE	-
FAS_00804	00338	N	N	N	1	CUSTOMER ISSUE	-
FAS_00805	00339	N	N	N	2	CUSTOMER ISSUE	-
FAS_00807	00340	N	N	N	1	CUSTOMER ISSUE	-
FAS_00808	00341	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00809	00342	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_00810	00343	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00811	00344	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00812	00345	N	N	N	1	CUSTOMER ISSUE	-
FAS_00813	00346	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00814	00347	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00815	00348	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00816	00349	Y	N	N	1	CUSTOMER ISSUE	-
FAS_00817	00350	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00818	00351	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00819	00352	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00820	00353	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00821	00354	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00822	00355	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00823	00356	N	N	Y	4	SEC/SVC - REPLACE	708.75
FAS_00824	00357	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00825	00358	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00826	00359	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00827	00360	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00828	00361	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00829	00362	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00830	00363	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00831	00364	N	N	N	1	CUSTOMER ISSUE	-
FAS_00832	00365	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00833	00366	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00834	00367	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00835	00368	N	N	Y	30	SEC/SVC - REPLACE	708.75
FAS_00836	00369	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00837	00370	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00838	00371	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00839	00372	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00840	00373	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00842	00374	Y	N	N	1	CUSTOMER ISSUE	-
FAS_00843	00375	N	N	N	1	CUSTOMER ISSUE	-
FAS_00844	00376	N	N	Y	1	SEC/SVC - REPLACE	708.75

FAS_00845	00377	N	N	N	1	CUSTOMER ISSUE	-
FAS_00846	00378	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00847	00379	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00848	00380	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00849	00381	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00850	00382	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00851	00383	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00854	00384	N	N	N	1	CUSTOMER ISSUE	-
FAS_00855	00385	N	N	N	1	CUSTOMER ISSUE	-
FAS_00856	00386	N	N	N	1	CUSTOMER ISSUE	-
FAS_00857	00387	N	N	N	1	CUSTOMER ISSUE	-
FAS_00859	00388	N	N	N	1	CUSTOMER ISSUE	-
FAS_00861	00389	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00862	00390	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00863	00391	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00864	00392	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00865	00393	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00866	00394	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00867	00395	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00868	00396	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00869	00397	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00870	00398	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00871	00399	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_00872	00400	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00873	00401	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00874	00402	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00875	00403	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00876	00404	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00877	00405	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_00878	00406	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00879	00407	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00880	00408	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00881	00409	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00882	00410	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00883	00411	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00884	00412	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00885	00413	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00886	00414	N	N	Y	1	TX - REPLACE	2500
FAS_00887	00415	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00888	00416	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00889	00417	N	N	N	1	CUSTOMER ISSUE	-
FAS_00890	00418	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00891	00419	N	N	Y	1	TX - REPLACE	2500
FAS_00892	00420	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00893	00421	N	N	Y	1	TX - REPLACE	2500
FAS_00894	00422	Y	N	Y	1	TX - REPLACE	2500
FAS_00895	00423	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00896	00424	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00897	00425	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00898	00426	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00899	00427	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00900	00428	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00901	00429	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00902	00430	N	N	N	1	CUSTOMER ISSUE	-
FAS_00903	00431	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
FAS_00904	00432	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00905	00433	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00906	00434	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00914	00435	N	N	N	1	CUSTOMER ISSUE	-
FAS_00915	00436	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00916	00437	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00917	00438	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00918	00439	N	N	N	1	CUSTOMER ISSUE	-
FAS_00919	00440	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00921	00441	N	N	N	1	CUSTOMER ISSUE	-
FAS_00922	00442	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00924	00443	N	N	N	1	CUSTOMER ISSUE	-
FAS_00925	00444	N	N	N	1	CUSTOMER ISSUE	-
FAS_00927	00445	N	N	N	1	CUSTOMER ISSUE	-
FAS_00930	00446	N	N	N	1	CUSTOMER ISSUE	-
FAS_00932	00447	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_00933	00448	N	N	N	1	CUSTOMER ISSUE	-
FAS_00940	00449	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00941	00450	N	N	Y	2	DIST - REPLACE FUSE	708.75
FAS_00942	00451	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00943	00452	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00945	00453	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00946	00454	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00947	00455	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00952	00456	N	N	N	56	CUSTOMER ISSUE	-

FAS_00953	00457	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00954	00458	N	N	N	1	CUSTOMER ISSUE	-
FAS_00955	00459	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00957	00460	N	N	N	1	CUSTOMER ISSUE	-
FAS_00958	00461	N	N	Y	2	DIST - REPLACE FUSE	708.75
FAS_00959	00462	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00960	00463	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00962	00464	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00963	00465	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00964	00466	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00965	00467	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00966	00468	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00967	00469	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00968	00470	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_00969	00471	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_00970	00472	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_00971	00473	N	N	Y	1	TX - REPLACE	2500
FAS_00978	00474	N	N	N	1	CUSTOMER ISSUE	-
FAS_00989	00475	N	N	N	1	CUSTOMER ISSUE	-
FAS_00990	00476	N	N	N	1	CUSTOMER ISSUE	-
FAS_00993	00477	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_00997	00478	N	N	N	1	CUSTOMER ISSUE	-
FAS_01003	00479	N	N	N	1	CUSTOMER ISSUE	-
FAS_01005	00480	N	N	N	1	CUSTOMER ISSUE	-
FAS_01010	00481	N	N	N	1	CUSTOMER ISSUE	-
FAS_01012	00482	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01013	00483	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_01016	00484	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_01018	00485	N	N	N	1	CUSTOMER ISSUE	-
FAS_01023	00486	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_01025	00487	N	N	N	1	CUSTOMER ISSUE	-
FAS_01027	00488	N	N	N	1	CUSTOMER ISSUE	-
FAS_01028	00489	N	N	N	1	CUSTOMER ISSUE	-
FAS_01029	00490	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01030	00491	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01031	00492	N	N	N	1	CUSTOMER ISSUE	-
FAS_01032	00493	N	N	N	1	CUSTOMER ISSUE	-
FAS_01033	00494	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01034	00495	N	N	N	1	CUSTOMER ISSUE	-
FAS_01035	00496	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01036	00497	N	N	N	1	CUSTOMER ISSUE	-
FAS_01037	00498	N	N	N	1	CUSTOMER ISSUE	-
FAS_01038	00499	N	N	N	1	CUSTOMER ISSUE	-
FAS_01039	00500	N	N	N	1	CUSTOMER ISSUE	-
FAS_01040	00501	N	N	N	1	CUSTOMER ISSUE	-
FAS_01044	00502	N	N	N	1	CUSTOMER ISSUE	-
FAS_01045	00503	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01046	00504	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01047	00505	N	N	N	1	CUSTOMER ISSUE	-
FAS_01048	00506	N	N	N	1	CUSTOMER ISSUE	-
FAS_01049	00507	N	N	N	1	CUSTOMER ISSUE	-
FAS_01050	00508	N	N	N	1	CUSTOMER ISSUE	-
FAS_01051	00509	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01053	00510	N	N	N	1	CUSTOMER ISSUE	-
FAS_01054	00511	N	N	N	1	CUSTOMER ISSUE	-
FAS_01055	00512	N	N	N	1	CUSTOMER ISSUE	-
FAS_01056	00513	N	N	N	1	CUSTOMER ISSUE	-
FAS_01057	00514	N	N	N	1	CUSTOMER ISSUE	-
FAS_01058	00515	N	N	N	1	CUSTOMER ISSUE	-
FAS_01059	00516	N	N	N	1	CUSTOMER ISSUE	-
FAS_01060	00517	N	N	N	1	CUSTOMER ISSUE	-
FAS_01062	00518	N	N	N	1	CUSTOMER ISSUE	-
FAS_01064	00519	N	N	N	1	CUSTOMER ISSUE	-
FAS_01066	00520	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01067	00521	N	N	N	1	CUSTOMER ISSUE	-
FAS_01068	00522	N	N	N	1	CUSTOMER ISSUE	-
FAS_01069	00523	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01070	00524	N	N	N	1	CUSTOMER ISSUE	-
FAS_01071	00525	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01072	00526	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01073	00527	N	N	N	1	CUSTOMER ISSUE	-
FAS_01075	00528	N	N	N	1	CUSTOMER ISSUE	-
FAS_01076	00529	N	N	N	1	CUSTOMER ISSUE	-
FAS_01078	00530	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01082	00531	N	N	N	1	CUSTOMER ISSUE	-
FAS_01084	00532	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01085	00533	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01087	00534	N	N	N	1	CUSTOMER ISSUE	-
FAS_01088	00535	N	N	N	1	CUSTOMER ISSUE	-
FAS_01090	00536	N	N	Y	1	SEC/SVC - REPLACE	708.75

FAS_01091	00537	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01092	00538	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_01093	00539	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01102	00540	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01112	00541	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01119	00542	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01121	00543	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01127	00544	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01128	00545	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01133	00546	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_01134	00547	N	N	N	1	CUSTOMER ISSUE	-
FAS_01138	00548	N	N	N	1	CUSTOMER ISSUE	-
FAS_01139	00549	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
FAS_01140	00550	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
FAS_01141	00551	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
FAS_01144	00552	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_01145	00553	N	N	N	1	CUSTOMER ISSUE	-
FAS_01146	00554	N	N	N	1	CUSTOMER ISSUE	-
FAS_01149	00555	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01154	00556	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01155	00557	N	N	N	1	CUSTOMER ISSUE	-
FAS_01160	00558	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_01161	00559	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_01164	00560	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01165	00561	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01166	00562	N	N	N	1	CUSTOMER ISSUE	-
FAS_01167	00563	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01168	00564	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01169	00565	N	N	N	1	CUSTOMER ISSUE	-
FAS_01170	00566	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01171	00567	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01173	00568	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01174	00569	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01177	00570	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01178	00571	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01180	00572	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01181	00573	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01183	00574	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01184	00575	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01206	00576	N	N	N	1	CUSTOMER ISSUE	-
FAS_01211	00577	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01212	00578	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01213	00579	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01214	00580	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01215	00581	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01216	00582	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01217	00583	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01218	00584	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01219	00585	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01220	00586	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_01221	00587	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01222	00588	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01223	00589	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01224	00590	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01225	00591	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01226	00592	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01227	00593	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01228	00594	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01229	00595	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01230	00596	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01231	00597	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01232	00598	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01233	00599	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01234	00600	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01235	00601	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01236	00602	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01237	00603	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01238	00604	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01239	00605	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01240	00606	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01241	00607	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01242	00608	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01243	00609	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_01244	00610	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01245	00611	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01246	00612	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01247	00613	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01248	00614	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01249	00615	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01250	00616	N	N	Y	1	SEC/SVC - REPAIR	472.5

FAS_01251	00617	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01252	00618	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01253	00619	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01254	00620	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01255	00621	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01256	00622	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01257	00623	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01258	00624	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01259	00625	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01260	00626	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01261	00627	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01262	00628	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01263	00629	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01264	00630	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01265	00631	N	N	Y	5	SEC/SVC - REPLACE	708.75
FAS_01266	00632	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01267	00633	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_01268	00634	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01269	00635	N	N	Y	3	SEC/SVC - REPLACE	708.75
FAS_01270	00636	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01271	00637	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01272	00638	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01273	00639	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01274	00640	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01275	00641	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01276	00642	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01277	00643	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01278	00644	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01279	00645	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01280	00646	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01281	00647	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01282	00648	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01283	00649	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01284	00650	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01285	00651	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01286	00652	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01287	00653	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01288	00654	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01289	00655	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01290	00656	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01291	00657	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01292	00658	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01293	00659	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01294	00660	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01295	00661	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01298	00662	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01299	00663	N	N	N	1	CUSTOMER ISSUE	-
FAS_01300	00664	N	N	N	1	CUSTOMER ISSUE	-
FAS_01302	00665	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01303	00666	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01304	00667	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01305	00668	N	N	N	1	CUSTOMER ISSUE	-
FAS_01306	00669	N	N	N	1	CUSTOMER ISSUE	-
FAS_01308	00670	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01309	00671	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01310	00672	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01322	00673	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01323	00674	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01327	00675	N	N	Y	5	SEC/SVC - REPLACE	708.75
FAS_01337	00676	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01338	00677	N	N	Y	1	TX - REPLACE	2500
FAS_01339	00678	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
FAS_01341	00679	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01345	00680	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01346	00681	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01347	00682	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01348	00683	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_01350	00684	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01353	00685	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
FAS_01355	00686	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01356	00687	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01357	00688	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01358	00689	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01359	00690	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01370	00691	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01371	00692	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01372	00693	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01375	00694	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01377	00695	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01383	00696	N	N	Y	1	SEC/SVC - REPAIR	472.5

FAS_01384	00697	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01385	00698	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_01386	00699	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_01388	00700	Y	N	Y	1	TX - REPLACE	2500
FAS_01392	00701	N	N	N	1	CUSTOMER ISSUE	-
FAS_01393	00702	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01394	00703	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01395	00704	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_01400	00705	N	N	N	1	CUSTOMER ISSUE	-
FAS_01407	00706	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01408	00707	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_01409	00708	N	N	N	1	CUSTOMER ISSUE	-
FAS_01410	00709	N	N	N	1	CUSTOMER ISSUE	-
FAS_01411	00710	N	N	N	1	CUSTOMER ISSUE	-
FAS_01412	00711	N	N	N	1	CUSTOMER ISSUE	-
FAS_01413	00712	N	N	N	1	CUSTOMER ISSUE	-
FAS_01416	00713	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01417	00714	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01418	00715	N	N	N	1	CUSTOMER ISSUE	-
FAS_01419	00716	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01420	00717	N	N	N	1	CUSTOMER ISSUE	-
FAS_01421	00718	N	N	N	1	CUSTOMER ISSUE	-
FAS_01422	00719	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01423	00720	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01424	00721	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01426	00722	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01427	00723	Y	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_01428	00724	N	N	N	1	CUSTOMER ISSUE	-
FAS_01430	00725	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01432	00726	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01433	00727	N	N	N	1	CUSTOMER ISSUE	-
FAS_01434	00728	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01436	00729	N	N	N	1	CUSTOMER ISSUE	-
FAS_01437	00730	N	N	N	1	CUSTOMER ISSUE	-
FAS_01438	00731	N	N	N	1	CUSTOMER ISSUE	-
FAS_01439	00732	N	N	N	1	CUSTOMER ISSUE	-
FAS_01440	00733	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01441	00734	N	N	N	1	CUSTOMER ISSUE	-
FAS_01442	00735	N	N	N	1	CUSTOMER ISSUE	-
FAS_01443	00736	N	N	N	1	CUSTOMER ISSUE	-
FAS_01444	00737	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01445	00738	N	N	N	1	CUSTOMER ISSUE	-
FAS_01446	00739	N	N	N	1	CUSTOMER ISSUE	-
FAS_01447	00740	N	N	N	1	CUSTOMER ISSUE	-
FAS_01449	00741	N	N	N	1	CUSTOMER ISSUE	-
FAS_01450	00742	N	N	N	1	CUSTOMER ISSUE	-
FAS_01451	00743	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_01452	00744	N	N	Y	2	DIST - REPLACE FUSE	708.75
FAS_01453	00745	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_01454	00746	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_01455	00747	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01458	00748	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01459	00749	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01463	00750	N	N	N	1	CUSTOMER ISSUE	-
FAS_01465	00751	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01486	00752	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01489	00753	N	N	N	1	CUSTOMER ISSUE	-
FAS_01491	00754	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01493	00755	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_01494	00756	N	N	Y	1	TX - REPLACE	2500
FAS_01499	00757	N	N	N	1	CUSTOMER ISSUE	-
FAS_01501	00758	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01514	00759	N	N	N	1	CUSTOMER ISSUE	-
FAS_01515	00760	N	N	N	1	CUSTOMER ISSUE	-
FAS_01519	00761	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_01520	00762	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_01521	00763	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01522	00764	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01523	00765	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01525	00766	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01528	00767	N	N	N	1	CUSTOMER ISSUE	-
FAS_01535	00768	N	N	N	2	CUSTOMER ISSUE	-
FAS_01536	00769	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_01539	00770	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_01540	00771	N	N	N	1	CUSTOMER ISSUE	-
FAS_01544	00772	N	N	N	1	CUSTOMER ISSUE	-
FAS_01545	00773	N	N	N	1	CUSTOMER ISSUE	-
FAS_01546	00774	N	N	N	1	CUSTOMER ISSUE	-
FAS_01547	00775	N	N	N	1	CUSTOMER ISSUE	-
FAS_01548	00776	N	N	N	1	CUSTOMER ISSUE	-

FAS_01550	00777	N	N	N	1	CUSTOMER ISSUE	-
FAS_01551	00778	N	N	N	1	CUSTOMER ISSUE	-
FAS_01552	00779	N	N	N	1	CUSTOMER ISSUE	-
FAS_01553	00780	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01554	00781	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01555	00782	N	N	N	1	CUSTOMER ISSUE	-
FAS_01557	00783	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01558	00784	N	N	N	1	CUSTOMER ISSUE	-
FAS_01559	00785	N	N	N	1	CUSTOMER ISSUE	-
FAS_01560	00786	N	N	N	1	CUSTOMER ISSUE	-
FAS_01562	00787	N	N	N	1	CUSTOMER ISSUE	-
FAS_01563	00788	N	N	N	33	CUSTOMER ISSUE	-
FAS_01565	00789	N	N	N	1	CUSTOMER ISSUE	-
FAS_01566	00790	N	N	N	1	CUSTOMER ISSUE	-
FAS_01569	00791	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01570	00792	N	N	N	1	CUSTOMER ISSUE	-
FAS_01571	00793	N	N	N	1	CUSTOMER ISSUE	-
FAS_01572	00794	N	N	N	1	CUSTOMER ISSUE	-
FAS_01574	00795	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_01578	00796	N	N	N	1	CUSTOMER ISSUE	-
FAS_01579	00797	N	N	N	1	CUSTOMER ISSUE	-
FAS_01580	00798	N	N	N	1	CUSTOMER ISSUE	-
FAS_01581	00799	N	N	N	1	CUSTOMER ISSUE	-
FAS_01582	00800	N	N	N	1	CUSTOMER ISSUE	-
FAS_01583	00801	N	N	N	1	CUSTOMER ISSUE	-
FAS_01584	00802	N	N	N	1	CUSTOMER ISSUE	-
FAS_01585	00803	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01586	00804	N	N	N	7	CUSTOMER ISSUE	-
FAS_01587	00805	N	N	N	1	CUSTOMER ISSUE	-
FAS_01588	00806	N	N	N	1	CUSTOMER ISSUE	-
FAS_01589	00807	N	N	N	1	CUSTOMER ISSUE	-
FAS_01590	00808	N	N	N	1	CUSTOMER ISSUE	-
FAS_01595	00809	N	N	N	1	CUSTOMER ISSUE	-
FAS_01596	00810	N	N	N	1	CUSTOMER ISSUE	-
FAS_01597	00811	N	N	N	1	CUSTOMER ISSUE	-
FAS_01598	00812	N	N	N	1	CUSTOMER ISSUE	-
FAS_01599	00813	N	N	Y	1	TX - REPLACE	2500
FAS_01601	00814	N	N	N	1	CUSTOMER ISSUE	-
FAS_01605	00815	N	N	N	1	CUSTOMER ISSUE	-
FAS_01606	00816	N	N	N	1	CUSTOMER ISSUE	-
FAS_01607	00817	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01609	00818	N	N	N	1	CUSTOMER ISSUE	-
FAS_01610	00819	N	N	N	1	CUSTOMER ISSUE	-
FAS_01612	00820	N	N	N	16	CUSTOMER ISSUE	-
FAS_01613	00821	N	N	N	1	CUSTOMER ISSUE	-
FAS_01617	00822	N	N	N	1	CUSTOMER ISSUE	-
FAS_01618	00823	N	N	N	2	CUSTOMER ISSUE	-
FAS_01619	00824	N	N	N	1	CUSTOMER ISSUE	-
FAS_01621	00825	N	N	N	1	CUSTOMER ISSUE	-
FAS_01622	00826	N	N	N	3	CUSTOMER ISSUE	-
FAS_01623	00827	N	N	N	1	CUSTOMER ISSUE	-
FAS_01625	00828	N	N	Y	1	TX - REPLACE	2500
FAS_01626	00829	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01628	00830	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01631	00831	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01647	00832	N	N	Y	1	TX - REPLACE	2500
FAS_01651	00833	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01652	00834	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01653	00835	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01654	00836	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01655	00837	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01657	00838	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01659	00839	N	N	Y	1	TX - REPLACE	2500
FAS_01660	00840	N	N	Y	2	TX - REPLACE	2500
FAS_01662	00841	N	N	N	1	CUSTOMER ISSUE	-
FAS_01663	00842	N	N	N	1	CUSTOMER ISSUE	-
FAS_01666	00843	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01667	00844	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_01669	00845	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_01671	00846	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01673	00847	N	N	Y	1	TX - REPLACE	2500
FAS_01676	00848	N	N	N	1	CUSTOMER ISSUE	-
FAS_01686	00849	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01687	00850	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_01688	00851	Y	N	Y	2	DIST - TREE TRIMMING	945
FAS_01693	00852	N	N	N	1	CUSTOMER ISSUE	-
FAS_01694	00853	N	N	N	1	CUSTOMER ISSUE	-
FAS_01695	00854	N	N	N	1	CUSTOMER ISSUE	-
FAS_01701	00855	N	N	N	1	CUSTOMER ISSUE	-
FAS_01702	00856	N	N	N	1	CUSTOMER ISSUE	-

FAS_01707	00857	N	N	N	1	CUSTOMER ISSUE	-
FAS_01708	00858	N	N	N	1	CUSTOMER ISSUE	-
FAS_01709	00859	N	N	N	1	CUSTOMER ISSUE	-
FAS_01710	00860	N	N	N	1	CUSTOMER ISSUE	-
FAS_01711	00861	N	N	N	1	CUSTOMER ISSUE	-
FAS_01712	00862	N	N	N	1	CUSTOMER ISSUE	-
FAS_01714	00863	N	N	N	1	CUSTOMER ISSUE	-
FAS_01715	00864	N	N	N	1	CUSTOMER ISSUE	-
FAS_01718	00865	N	N	N	1	CUSTOMER ISSUE	-
FAS_01724	00866	N	N	N	1	CUSTOMER ISSUE	-
FAS_01726	00867	N	N	N	1	CUSTOMER ISSUE	-
FAS_01729	00868	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01732	00869	N	N	N	1	CUSTOMER ISSUE	-
FAS_01734	00870	N	N	N	1	CUSTOMER ISSUE	-
FAS_01735	00871	N	N	N	1	CUSTOMER ISSUE	-
FAS_01736	00872	N	N	N	1	CUSTOMER ISSUE	-
FAS_01738	00873	N	N	N	1	CUSTOMER ISSUE	-
FAS_01742	00874	N	N	N	1	CUSTOMER ISSUE	-
FAS_01744	00875	N	N	N	1	CUSTOMER ISSUE	-
FAS_01745	00876	N	N	N	1	CUSTOMER ISSUE	-
FAS_01746	00877	N	N	N	1	CUSTOMER ISSUE	-
FAS_01747	00878	N	N	N	1	CUSTOMER ISSUE	-
FAS_01749	00879	N	N	N	1	CUSTOMER ISSUE	-
FAS_01751	00880	N	N	N	1	CUSTOMER ISSUE	-
FAS_01752	00881	N	N	N	1	CUSTOMER ISSUE	-
FAS_01753	00882	N	N	N	1	CUSTOMER ISSUE	-
FAS_01754	00883	N	N	N	1	CUSTOMER ISSUE	-
FAS_01755	00884	N	N	N	1	CUSTOMER ISSUE	-
FAS_01756	00885	N	N	N	1	CUSTOMER ISSUE	-
FAS_01757	00886	N	N	N	1	CUSTOMER ISSUE	-
FAS_01760	00887	N	N	N	1	CUSTOMER ISSUE	-
FAS_01764	00888	N	N	Y	1	TX - REPLACE	2500
FAS_01771	00889	N	N	N	1	CUSTOMER ISSUE	-
FAS_01776	00890	N	N	N	30	CUSTOMER ISSUE	-
FAS_01787	00891	N	N	N	14	CUSTOMER ISSUE	-
FAS_01790	00892	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01791	00893	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01792	00894	N	N	N	1	CUSTOMER ISSUE	-
FAS_01793	00895	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01794	00896	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01795	00897	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01796	00898	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01799	00899	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01800	00900	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01801	00901	Y	N	N	2	CUSTOMER ISSUE	-
FAS_01802	00902	N	N	N	1	CUSTOMER ISSUE	-
FAS_01803	00903	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01804	00904	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01806	00905	N	N	N	1	CUSTOMER ISSUE	-
FAS_01807	00906	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01808	00907	N	N	N	1	CUSTOMER ISSUE	-
FAS_01809	00908	N	N	N	1	CUSTOMER ISSUE	-
FAS_01810	00909	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01811	00910	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01812	00911	N	N	N	1	CUSTOMER ISSUE	-
FAS_01813	00912	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01814	00913	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01816	00914	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01817	00915	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01818	00916	N	N	N	1	CUSTOMER ISSUE	-
FAS_01821	00917	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_01822	00918	N	N	Y	6	SEC/SVC - REPLACE	708.75
FAS_01823	00919	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01824	00920	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01825	00921	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01826	00922	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01827	00923	N	N	N	1	CUSTOMER ISSUE	-
FAS_01828	00924	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01829	00925	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01831	00926	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01832	00927	N	N	N	1	CUSTOMER ISSUE	-
FAS_01833	00928	N	N	N	1	CUSTOMER ISSUE	-
FAS_01837	00929	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01839	00930	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01840	00931	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01845	00932	N	N	N	1	CUSTOMER ISSUE	-
FAS_01846	00933	N	N	N	29	CUSTOMER ISSUE	-
FAS_01850	00934	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_01853	00935	N	N	N	1	CUSTOMER ISSUE	-
FAS_01855	00936	N	N	N	1	CUSTOMER ISSUE	-

FAS_01858	00937	N	N	N	1	CUSTOMER ISSUE	-
FAS_01860	00938	N	N	N	1	CUSTOMER ISSUE	-
FAS_01861	00939	N	N	N	1	CUSTOMER ISSUE	-
FAS_01862	00940	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01863	00941	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01864	00942	N	N	N	2	CUSTOMER ISSUE	-
FAS_01865	00943	N	N	N	1	CUSTOMER ISSUE	-
FAS_01867	00944	N	N	N	1	CUSTOMER ISSUE	-
FAS_01871	00945	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_01872	00946	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_01873	00947	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01874	00948	N	N	N	1	CUSTOMER ISSUE	-
FAS_01875	00949	N	N	N	15	CUSTOMER ISSUE	-
FAS_01876	00950	N	N	N	1	CUSTOMER ISSUE	-
FAS_01877	00951	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01881	00952	N	N	N	1	CUSTOMER ISSUE	-
FAS_01882	00953	N	N	N	1	CUSTOMER ISSUE	-
FAS_01885	00954	N	N	N	1	CUSTOMER ISSUE	-
FAS_01886	00955	N	N	N	1	CUSTOMER ISSUE	-
FAS_01887	00956	N	N	N	1	CUSTOMER ISSUE	-
FAS_01888	00957	N	N	N	1	CUSTOMER ISSUE	-
FAS_01889	00958	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01890	00959	N	N	N	1	CUSTOMER ISSUE	-
FAS_01891	00960	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01892	00961	N	N	N	6	CUSTOMER ISSUE	-
FAS_01893	00962	N	N	N	1	CUSTOMER ISSUE	-
FAS_01894	00963	N	N	N	1	CUSTOMER ISSUE	-
FAS_01896	00964	N	N	Y	2	TX - REPLACE	2500
FAS_01897	00965	N	N	N	1	CUSTOMER ISSUE	-
FAS_01900	00966	N	N	N	1	CUSTOMER ISSUE	-
FAS_01901	00967	N	N	N	2	CUSTOMER ISSUE	-
FAS_01903	00968	N	N	N	1	CUSTOMER ISSUE	-
FAS_01904	00969	N	N	N	1	CUSTOMER ISSUE	-
FAS_01905	00970	N	N	N	1	CUSTOMER ISSUE	-
FAS_01906	00971	N	N	N	1	CUSTOMER ISSUE	-
FAS_01907	00972	N	N	N	1	CUSTOMER ISSUE	-
FAS_01908	00973	N	N	N	1	CUSTOMER ISSUE	-
FAS_01909	00974	N	N	N	1	CUSTOMER ISSUE	-
FAS_01910	00975	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01912	00976	N	N	N	1	CUSTOMER ISSUE	-
FAS_01913	00977	N	N	N	1	CUSTOMER ISSUE	-
FAS_01918	00978	N	N	N	1	CUSTOMER ISSUE	-
FAS_01919	00979	N	N	N	1	CUSTOMER ISSUE	-
FAS_01920	00980	N	N	N	1	CUSTOMER ISSUE	-
FAS_01922	00981	N	N	N	1	CUSTOMER ISSUE	-
FAS_01923	00982	N	N	N	1	CUSTOMER ISSUE	-
FAS_01924	00983	N	N	N	1	CUSTOMER ISSUE	-
FAS_01925	00984	N	N	N	1	CUSTOMER ISSUE	-
FAS_01926	00985	N	N	N	1	CUSTOMER ISSUE	-
FAS_01927	00986	N	N	N	1	CUSTOMER ISSUE	-
FAS_01928	00987	N	N	N	1	CUSTOMER ISSUE	-
FAS_01932	00988	N	N	N	1	CUSTOMER ISSUE	-
FAS_01933	00989	N	N	N	1	CUSTOMER ISSUE	-
FAS_01934	00990	N	N	N	13	CUSTOMER ISSUE	-
FAS_01935	00991	N	N	N	1	CUSTOMER ISSUE	-
FAS_01936	00992	N	N	N	1	CUSTOMER ISSUE	-
FAS_01939	00993	N	N	N	1	CUSTOMER ISSUE	-
FAS_01942	00994	N	N	N	1	CUSTOMER ISSUE	-
FAS_01943	00995	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01944	00996	N	N	N	1	CUSTOMER ISSUE	-
FAS_01948	00997	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_01952	00998	N	N	N	1	CUSTOMER ISSUE	-
FAS_01953	00999	N	N	N	1	CUSTOMER ISSUE	-
FAS_01954	01000	N	N	N	1	CUSTOMER ISSUE	-
FAS_01955	01001	N	N	N	1	CUSTOMER ISSUE	-
FAS_01957	01002	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01958	01003	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01959	01004	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_01960	01005	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_01961	01006	N	N	N	1	CUSTOMER ISSUE	-
FAS_01962	01007	N	N	N	3	CUSTOMER ISSUE	-
FAS_01963	01008	N	N	N	1	CUSTOMER ISSUE	-
FAS_01965	01009	N	N	N	1	CUSTOMER ISSUE	-
FAS_01966	01010	N	N	N	1	CUSTOMER ISSUE	-
FAS_01967	01011	N	N	N	1	CUSTOMER ISSUE	-
FAS_01972	01012	N	N	N	1	CUSTOMER ISSUE	-
FAS_01974	01013	N	N	N	1	CUSTOMER ISSUE	-
FAS_01977	01014	N	N	N	1	CUSTOMER ISSUE	-
FAS_01978	01015	N	N	N	1	CUSTOMER ISSUE	-
FAS_01979	01016	Y	N	Y	1	SEC/SVC - REPLACE	708.75

FAS_01980	01017	Y	N	N	1	CUSTOMER ISSUE	-
FAS_01988	01018	N	N	N	1	CUSTOMER ISSUE	-
FAS_01989	01019	Y	N	N	2	CUSTOMER ISSUE	-
FAS_01992	01020	N	N	N	1	CUSTOMER ISSUE	-
FAS_01993	01021	N	N	N	1	CUSTOMER ISSUE	-
FAS_01994	01022	N	N	N	2	CUSTOMER ISSUE	-
FAS_01995	01023	N	N	N	1	CUSTOMER ISSUE	-
FAS_01997	01024	N	N	N	1	CUSTOMER ISSUE	-
FAS_01998	01025	N	N	N	1	CUSTOMER ISSUE	-
FAS_02000	01026	N	N	N	1	CUSTOMER ISSUE	-
FAS_02001	01027	N	N	N	1	CUSTOMER ISSUE	-
FAS_02002	01028	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02003	01029	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02004	01030	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02005	01031	N	N	N	1	CUSTOMER ISSUE	-
FAS_02006	01032	N	N	N	1	CUSTOMER ISSUE	-
FAS_02008	01033	N	N	N	1	CUSTOMER ISSUE	-
FAS_02009	01034	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_02010	01035	N	N	N	1	CUSTOMER ISSUE	-
FAS_02011	01036	N	N	N	1	CUSTOMER ISSUE	-
FAS_02014	01037	N	N	N	1	CUSTOMER ISSUE	-
FAS_02021	01038	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02022	01039	N	N	N	1	CUSTOMER ISSUE	-
FAS_02025	01040	N	N	N	1	CUSTOMER ISSUE	-
FAS_02026	01041	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02030	01042	N	N	N	1	CUSTOMER ISSUE	-
FAS_02031	01043	N	N	N	10	CUSTOMER ISSUE	-
FAS_02032	01044	N	N	N	1	CUSTOMER ISSUE	-
FAS_02035	01045	N	N	N	1	CUSTOMER ISSUE	-
FAS_02036	01046	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02039	01047	N	N	N	1	CUSTOMER ISSUE	-
FAS_02040	01048	N	N	N	1	CUSTOMER ISSUE	-
FAS_02041	01049	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02043	01050	N	N	N	1	CUSTOMER ISSUE	-
FAS_02045	01051	N	N	N	1	CUSTOMER ISSUE	-
FAS_02046	01052	N	N	N	1	CUSTOMER ISSUE	-
FAS_02048	01053	N	N	N	1	CUSTOMER ISSUE	-
FAS_02049	01054	N	N	N	5	CUSTOMER ISSUE	-
FAS_02050	01055	N	N	N	1	CUSTOMER ISSUE	-
FAS_02051	01056	N	N	N	1	CUSTOMER ISSUE	-
FAS_02052	01057	N	N	N	1	CUSTOMER ISSUE	-
FAS_02055	01058	N	N	N	1	CUSTOMER ISSUE	-
FAS_02059	01059	N	N	N	1	CUSTOMER ISSUE	-
FAS_02060	01060	N	N	N	1	CUSTOMER ISSUE	-
FAS_02062	01061	N	N	N	1	CUSTOMER ISSUE	-
FAS_02063	01062	N	N	N	1	CUSTOMER ISSUE	-
FAS_02064	01063	N	N	N	1	CUSTOMER ISSUE	-
FAS_02066	01064	N	N	N	4	CUSTOMER ISSUE	-
FAS_02067	01065	N	N	N	1	CUSTOMER ISSUE	-
FAS_02068	01066	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02069	01067	N	N	N	1	CUSTOMER ISSUE	-
FAS_02070	01068	N	N	N	1	CUSTOMER ISSUE	-
FAS_02071	01069	N	N	N	1	CUSTOMER ISSUE	-
FAS_02073	01070	N	N	N	1	CUSTOMER ISSUE	-
FAS_02074	01071	N	N	N	1	CUSTOMER ISSUE	-
FAS_02075	01072	N	N	N	1	CUSTOMER ISSUE	-
FAS_02078	01073	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02079	01074	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02080	01075	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02081	01076	N	N	N	1	CUSTOMER ISSUE	-
FAS_02086	01077	N	N	N	1	CUSTOMER ISSUE	-
FAS_02088	01078	N	N	N	1	CUSTOMER ISSUE	-
FAS_02093	01079	N	N	N	1	CUSTOMER ISSUE	-
FAS_02096	01080	N	N	N	1	CUSTOMER ISSUE	-
FAS_02097	01081	Y	N	N	2	CUSTOMER ISSUE	-
FAS_02098	01082	N	N	N	1	CUSTOMER ISSUE	-
FAS_02100	01083	N	N	N	1	CUSTOMER ISSUE	-
FAS_02101	01084	N	N	N	1	CUSTOMER ISSUE	-
FAS_02103	01085	N	N	N	1	CUSTOMER ISSUE	-
FAS_02104	01086	N	N	N	1	CUSTOMER ISSUE	-
FAS_02105	01087	N	N	N	1	CUSTOMER ISSUE	-
FAS_02106	01088	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02108	01089	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02109	01090	N	N	N	1	CUSTOMER ISSUE	-
FAS_02110	01091	Y	N	Y	1	TX - REPLACE	2500
FAS_02114	01092	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02118	01093	N	N	N	1	CUSTOMER ISSUE	-
FAS_02120	01094	N	N	N	1	CUSTOMER ISSUE	-
FAS_02124	01095	N	N	N	1	CUSTOMER ISSUE	-
FAS_02128	01096	N	N	Y	1	SEC/SVC - REPAIR	472.5

FAS_02133	01097	N	N	N	1	CUSTOMER ISSUE	-
FAS_02134	01098	N	N	N	1	CUSTOMER ISSUE	-
FAS_02135	01099	N	N	N	1	CUSTOMER ISSUE	-
FAS_02141	01100	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02150	01101	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_02153	01102	N	N	N	2	CUSTOMER ISSUE	-
FAS_02157	01103	N	N	N	1	CUSTOMER ISSUE	-
FAS_02160	01104	N	N	N	1	CUSTOMER ISSUE	-
FAS_02162	01105	N	N	Y	2	DIST - CHANGE SETTINGS	708.75
FAS_02165	01106	N	N	N	1	CUSTOMER ISSUE	-
FAS_02167	01107	N	N	N	1	CUSTOMER ISSUE	-
FAS_02168	01108	N	N	N	1	CUSTOMER ISSUE	-
FAS_02169	01109	N	N	N	1	CUSTOMER ISSUE	-
FAS_02170	01110	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02173	01111	N	N	N	1	CUSTOMER ISSUE	-
FAS_02174	01112	N	N	N	1	CUSTOMER ISSUE	-
FAS_02176	01113	N	N	N	1	CUSTOMER ISSUE	-
FAS_02177	01114	N	N	N	1	CUSTOMER ISSUE	-
FAS_02179	01115	N	N	N	1	CUSTOMER ISSUE	-
FAS_02180	01116	N	N	N	1	CUSTOMER ISSUE	-
FAS_02181	01117	N	N	N	1	CUSTOMER ISSUE	-
FAS_02182	01118	N	N	N	1	CUSTOMER ISSUE	-
FAS_02183	01119	N	N	N	1	CUSTOMER ISSUE	-
FAS_02184	01120	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02185	01121	N	N	N	1	CUSTOMER ISSUE	-
FAS_02186	01122	N	N	N	1	CUSTOMER ISSUE	-
FAS_02188	01123	N	N	N	1	CUSTOMER ISSUE	-
FAS_02190	01124	N	N	N	1	CUSTOMER ISSUE	-
FAS_02192	01125	N	N	N	1	CUSTOMER ISSUE	-
FAS_02193	01126	N	N	N	1	CUSTOMER ISSUE	-
FAS_02194	01127	N	N	N	1	CUSTOMER ISSUE	-
FAS_02196	01128	N	N	N	32	CUSTOMER ISSUE	-
FAS_02197	01129	N	N	N	1	CUSTOMER ISSUE	-
FAS_02198	01130	N	N	N	1	CUSTOMER ISSUE	-
FAS_02199	01131	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02200	01132	N	N	N	1	CUSTOMER ISSUE	-
FAS_02201	01133	N	N	N	1	CUSTOMER ISSUE	-
FAS_02203	01134	N	N	N	1	CUSTOMER ISSUE	-
FAS_02204	01135	N	N	N	1	CUSTOMER ISSUE	-
FAS_02205	01136	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02206	01137	N	N	N	1	CUSTOMER ISSUE	-
FAS_02207	01138	N	N	N	1	CUSTOMER ISSUE	-
FAS_02208	01139	N	N	N	1	CUSTOMER ISSUE	-
FAS_02209	01140	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02210	01141	N	N	N	1	CUSTOMER ISSUE	-
FAS_02211	01142	N	N	N	1	CUSTOMER ISSUE	-
FAS_02212	01143	N	N	N	1	CUSTOMER ISSUE	-
FAS_02214	01144	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02215	01145	N	N	N	1	CUSTOMER ISSUE	-
FAS_02216	01146	N	N	N	1	CUSTOMER ISSUE	-
FAS_02217	01147	N	N	N	1	CUSTOMER ISSUE	-
FAS_02218	01148	N	N	N	1	CUSTOMER ISSUE	-
FAS_02219	01149	N	N	N	1	CUSTOMER ISSUE	-
FAS_02220	01150	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02221	01151	N	N	N	1	CUSTOMER ISSUE	-
FAS_02222	01152	N	N	N	1	CUSTOMER ISSUE	-
FAS_02224	01153	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02225	01154	N	N	N	1	CUSTOMER ISSUE	-
FAS_02226	01155	N	N	N	1	CUSTOMER ISSUE	-
FAS_02227	01156	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02228	01157	N	N	N	1	CUSTOMER ISSUE	-
FAS_02229	01158	N	N	N	1	CUSTOMER ISSUE	-
FAS_02230	01159	N	N	N	1	CUSTOMER ISSUE	-
FAS_02231	01160	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02232	01161	N	N	N	1	CUSTOMER ISSUE	-
FAS_02233	01162	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02247	01163	N	N	N	12	CUSTOMER ISSUE	-
FAS_02249	01164	N	N	N	1	CUSTOMER ISSUE	-
FAS_02257	01165	N	N	N	1	CUSTOMER ISSUE	-
FAS_02264	01166	N	N	Y	1	TX - REPLACE	2500
FAS_02265	01167	N	N	N	1	CUSTOMER ISSUE	-
FAS_02267	01168	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02273	01169	Y	N	Y	1	TX - REPLACE	2500
FAS_02274	01170	N	N	N	1	CUSTOMER ISSUE	-
FAS_02279	01171	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02280	01172	N	N	N	1	CUSTOMER ISSUE	-
FAS_02282	01173	N	N	N	1	CUSTOMER ISSUE	-
FAS_02285	01174	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02286	01175	N	N	N	1	CUSTOMER ISSUE	-
FAS_02287	01176	N	N	N	1	CUSTOMER ISSUE	-

FAS_02290	01177	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02291	01178	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02293	01179	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02294	01180	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02295	01181	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02296	01182	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_02297	01183	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02298	01184	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02299	01185	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02300	01186	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02301	01187	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02302	01188	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02304	01189	N	N	N	1	CUSTOMER ISSUE	-
FAS_02305	01190	N	N	N	1	CUSTOMER ISSUE	-
FAS_02311	01191	N	N	N	1	CUSTOMER ISSUE	-
FAS_02312	01192	N	N	N	1	CUSTOMER ISSUE	-
FAS_02314	01193	N	N	N	1	CUSTOMER ISSUE	-
FAS_02315	01194	N	N	N	1	CUSTOMER ISSUE	-
FAS_02324	01195	N	N	N	1	CUSTOMER ISSUE	-
FAS_02326	01196	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_02328	01197	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02335	01198	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02336	01199	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02337	01200	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02338	01201	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02339	01202	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02340	01203	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02341	01204	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02342	01205	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02343	01206	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02345	01207	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02346	01208	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02347	01209	N	N	N	1	CUSTOMER ISSUE	-
FAS_02352	01210	N	N	N	1	CUSTOMER ISSUE	-
FAS_02354	01211	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02355	01212	N	N	N	7	CUSTOMER ISSUE	-
FAS_02358	01213	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02359	01214	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02360	01215	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02362	01216	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02363	01217	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02364	01218	N	N	N	1	CUSTOMER ISSUE	-
FAS_02366	01219	N	N	N	1	CUSTOMER ISSUE	-
FAS_02369	01220	N	N	N	1	CUSTOMER ISSUE	-
FAS_02370	01221	N	N	N	1	CUSTOMER ISSUE	-
FAS_02371	01222	N	N	N	1	CUSTOMER ISSUE	-
FAS_02372	01223	N	N	N	1	CUSTOMER ISSUE	-
FAS_02373	01224	N	N	N	1	CUSTOMER ISSUE	-
FAS_02374	01225	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02376	01226	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02377	01227	N	N	N	1	CUSTOMER ISSUE	-
FAS_02378	01228	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02380	01229	N	N	N	1	CUSTOMER ISSUE	-
FAS_02381	01230	N	N	N	1	CUSTOMER ISSUE	-
FAS_02383	01231	N	N	N	1	CUSTOMER ISSUE	-
FAS_02385	01232	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02387	01233	N	N	N	1	CUSTOMER ISSUE	-
FAS_02391	01234	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
FAS_02392	01235	N	N	N	1	CUSTOMER ISSUE	-
FAS_02395	01236	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_02396	01237	Y	N	Y	6	SEC/SVC - REPLACE	708.75
FAS_02397	01238	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02398	01239	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02399	01240	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02400	01241	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02401	01242	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02402	01243	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02403	01244	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02404	01245	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02405	01246	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_02406	01247	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02407	01248	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02408	01249	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02409	01250	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02410	01251	Y	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_02411	01252	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02412	01253	N	N	N	1	CUSTOMER ISSUE	-
FAS_02413	01254	N	N	Y	9	SEC/SVC - REPLACE	708.75
FAS_02415	01255	N	N	N	1	CUSTOMER ISSUE	-
FAS_02416	01256	N	N	N	1	CUSTOMER ISSUE	-

FAS_02417	01257	N	N	N	1	CUSTOMER ISSUE	-
FAS_02419	01258	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02420	01259	N	N	N	3	CUSTOMER ISSUE	-
FAS_02421	01260	N	N	N	1	CUSTOMER ISSUE	-
FAS_02423	01261	N	N	N	1	CUSTOMER ISSUE	-
FAS_02440	01262	N	N	N	1	CUSTOMER ISSUE	-
FAS_02441	01263	N	N	N	1	CUSTOMER ISSUE	-
FAS_02445	01264	N	N	N	1	CUSTOMER ISSUE	-
FAS_02446	01265	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02449	01266	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02450	01267	N	N	N	1	CUSTOMER ISSUE	-
FAS_02454	01268	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02456	01269	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02457	01270	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02458	01271	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02461	01272	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02465	01273	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02474	01274	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_02477	01275	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02478	01276	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02480	01277	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_02484	01278	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02485	01279	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02486	01280	Y	N	Y	1	TX - REPLACE	2500
FAS_02494	01281	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02498	01282	N	N	Y	1	TX - REPLACE	2500
FAS_02501	01283	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02502	01284	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02504	01285	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02506	01286	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02508	01287	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02516	01288	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02517	01289	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_02521	01290	Y	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_02523	01291	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02527	01292	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02528	01293	N	N	N	1	CUSTOMER ISSUE	-
FAS_02531	01294	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02543	01295	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02544	01296	N	N	N	1	CUSTOMER ISSUE	-
FAS_02548	01297	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02555	01298	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02557	01299	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02558	01300	N	N	Y	3	SEC/SVC - REPLACE	708.75
FAS_02559	01301	N	N	Y	1	TX - REPLACE	2500
FAS_02561	01302	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02562	01303	N	N	Y	1	TX - REPLACE	2500
FAS_02565	01304	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02567	01305	N	N	Y	1	TX - REPLACE	2500
FAS_02575	01306	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_02576	01307	N	N	Y	12	SEC/SVC - REPLACE	708.75
FAS_02578	01308	N	N	Y	32	DIST - REPLACE EQUIPMENT	5500
FAS_02579	01309	N	N	Y	32	DIST - REPLACE EQUIPMENT	5500
FAS_02580	01310	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02581	01311	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02582	01312	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02586	01313	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02587	01314	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_02588	01315	Y	N	Y	1	TX - INSTALL	3000
FAS_02589	01316	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02590	01317	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02592	01318	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02593	01319	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02594	01320	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02595	01321	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02596	01322	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02598	01323	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02599	01324	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02600	01325	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02601	01326	Y	N	Y	20	SEC/SVC - REPAIR	472.5
FAS_02605	01327	N	N	Y	3	SEC/SVC - REPLACE	708.75
FAS_02607	01328	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02608	01329	N	N	Y	1	TX - REPLACE	2500
FAS_02610	01330	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02611	01331	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02612	01332	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02613	01333	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02614	01334	Y	N	Y	2	DIST - TREE TRIMMING	945
FAS_02616	01335	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_02617	01336	Y	N	Y	1	DIST - TREE TRIMMING	945

FAS_02619	01337	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02621	01338	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02624	01339	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02626	01340	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02629	01341	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02630	01342	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02632	01343	N	N	Y	1	TX - REPLACE	2500
FAS_02634	01344	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02635	01345	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02637	01346	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02638	01347	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02640	01348	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02641	01349	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02642	01350	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02643	01351	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02644	01352	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02645	01353	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_02647	01354	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02649	01355	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02650	01356	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02651	01357	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02652	01358	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02653	01359	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02654	01360	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02655	01361	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02656	01362	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02662	01363	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02663	01364	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02664	01365	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02665	01366	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02668	01367	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02670	01368	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_02671	01369	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02672	01370	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02673	01371	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02675	01372	N	N	N	1	CUSTOMER ISSUE	-
FAS_02683	01373	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02684	01374	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02686	01375	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02687	01376	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
FAS_02688	01377	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02689	01378	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02690	01379	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02691	01380	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02692	01381	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02693	01382	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02694	01383	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02695	01384	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02696	01385	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02697	01386	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02698	01387	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02700	01388	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02701	01389	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02702	01390	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02703	01391	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02704	01392	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02706	01393	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02711	01394	N	N	Y	1	TX - REPLACE	2500
FAS_02712	01395	N	N	Y	1	TX - REPLACE	2500
FAS_02716	01396	N	N	N	1	CUSTOMER ISSUE	-
FAS_02717	01397	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_02718	01398	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_02719	01399	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_02720	01400	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_02722	01401	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02723	01402	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02731	01403	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_02734	01404	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02735	01405	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02736	01406	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02737	01407	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02738	01408	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02739	01409	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02740	01410	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02741	01411	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02742	01412	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02743	01413	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02745	01414	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02746	01415	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02752	01416	N	N	Y	1	TX/SEC/SVC- REPLACE	3800

FAS_02759	01417	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02760	01418	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02761	01419	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_02762	01420	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02763	01421	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02764	01422	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02765	01423	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02766	01424	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02767	01425	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02768	01426	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02769	01427	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02770	01428	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_02772	01429	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02773	01430	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02774	01431	N	N	Y	1	TX - REPLACE	2500
FAS_02776	01432	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02778	01433	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_02780	01434	N	N	Y	1	TX - REPLACE	2500
FAS_02781	01435	N	N	Y	1	TX - REPLACE	2500
FAS_02783	01436	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02784	01437	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02785	01438	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02786	01439	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02787	01440	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02789	01441	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02791	01442	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02792	01443	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02794	01444	N	N	Y	1	TX - REPLACE	2500
FAS_02795	01445	N	N	Y	1	TX - REPLACE	2500
FAS_02797	01446	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02798	01447	N	N	Y	1	TX - REPLACE	2500
FAS_02800	01448	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02802	01449	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02803	01450	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02804	01451	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02805	01452	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02806	01453	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02807	01454	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02808	01455	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02809	01456	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02810	01457	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02812	01458	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02813	01459	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02814	01460	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02815	01461	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02816	01462	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02817	01463	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02818	01464	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02819	01465	N	N	Y	1	TX - REPLACE	2500
FAS_02820	01466	N	N	Y	1	TX - REPLACE	2500
FAS_02821	01467	N	N	Y	1	TX - REPLACE	2500
FAS_02822	01468	N	N	Y	1	TX - REPLACE	2500
FAS_02823	01469	N	N	Y	1	TX - REPLACE	2500
FAS_02824	01470	N	N	Y	1	TX - REPLACE	2500
FAS_02825	01471	N	N	Y	1	TX - REPLACE	2500
FAS_02829	01472	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02830	01473	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02831	01474	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02832	01475	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_02833	01476	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02834	01477	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02835	01478	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02836	01479	N	N	Y	1	TX - REPLACE	2500
FAS_02837	01480	N	N	Y	1	TX - REPLACE	2500
FAS_02838	01481	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02841	01482	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_02842	01483	N	N	N	1	CUSTOMER ISSUE	-
FAS_02843	01484	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02844	01485	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02845	01486	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02846	01487	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02847	01488	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02848	01489	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02849	01490	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02850	01491	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02851	01492	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02852	01493	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02853	01494	N	N	Y	1	TX - REPLACE	2500
FAS_02854	01495	N	N	Y	1	TX - REPLACE	2500
FAS_02855	01496	N	N	Y	4	TX - REPLACE	2500

FAS_02856	01497	N	N	Y	1	TX - REPLACE	2500
FAS_02858	01498	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02860	01499	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02864	01500	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02865	01501	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02870	01502	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02874	01503	N	N	Y	1	TX - REPLACE	2500
FAS_02875	01504	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02876	01505	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02877	01506	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02878	01507	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02879	01508	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02880	01509	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02881	01510	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02882	01511	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02883	01512	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02884	01513	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02885	01514	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02886	01515	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02887	01516	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02888	01517	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02889	01518	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02890	01519	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02891	01520	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02892	01521	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02893	01522	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02894	01523	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02895	01524	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02896	01525	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02897	01526	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02898	01527	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02899	01528	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02900	01529	N	N	Y	3	SEC/SVC - REPLACE	708.75
FAS_02901	01530	Y	N	Y	15	SEC/SVC - REPLACE	708.75
FAS_02902	01531	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02903	01532	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02904	01533	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02905	01534	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02906	01535	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02907	01536	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02908	01537	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02909	01538	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02910	01539	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02911	01540	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02912	01541	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02913	01542	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02914	01543	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02915	01544	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02917	01545	N	N	Y	1	TX - REPLACE	2500
FAS_02919	01546	N	N	Y	1	TX - REPLACE	2500
FAS_02920	01547	Y	N	Y	1	TX - REPLACE	2500
FAS_02921	01548	N	N	Y	1	TX - REPLACE	2500
FAS_02922	01549	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02925	01550	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02928	01551	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02929	01552	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02930	01553	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02931	01554	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02938	01555	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02939	01556	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02941	01557	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02946	01558	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02947	01559	N	N	Y	1	TX - REPLACE	2500
FAS_02949	01560	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_02950	01561	N	N	N	1	CUSTOMER ISSUE	-
FAS_02954	01562	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02955	01563	N	N	N	1	CUSTOMER ISSUE	-
FAS_02956	01564	N	N	N	1	CUSTOMER ISSUE	-
FAS_02958	01565	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02960	01566	N	N	N	2	CUSTOMER ISSUE	-
FAS_02961	01567	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02962	01568	N	N	Y	6	SEC/SVC - REPLACE	708.75
FAS_02963	01569	N	N	N	1	CUSTOMER ISSUE	-
FAS_02965	01570	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_02966	01571	N	N	N	1	CUSTOMER ISSUE	-
FAS_02967	01572	N	N	N	1	CUSTOMER ISSUE	-
FAS_02968	01573	N	N	N	2	CUSTOMER ISSUE	-
FAS_02969	01574	N	N	N	1	CUSTOMER ISSUE	-
FAS_02970	01575	N	N	N	1	CUSTOMER ISSUE	-
FAS_02971	01576	Y	N	N	1	CUSTOMER ISSUE	-

FAS_02972	01577	N	N	N	1	CUSTOMER ISSUE	-
FAS_02975	01578	N	N	N	1	CUSTOMER ISSUE	-
FAS_02976	01579	N	N	N	1	CUSTOMER ISSUE	-
FAS_02977	01580	N	N	N	1	CUSTOMER ISSUE	-
FAS_02978	01581	N	N	N	3	CUSTOMER ISSUE	-
FAS_02979	01582	N	N	N	1	CUSTOMER ISSUE	-
FAS_02980	01583	N	N	N	1	CUSTOMER ISSUE	-
FAS_02981	01584	N	N	N	1	CUSTOMER ISSUE	-
FAS_02982	01585	N	N	N	1	CUSTOMER ISSUE	-
FAS_02983	01586	N	N	N	1	CUSTOMER ISSUE	-
FAS_02984	01587	N	N	N	1	CUSTOMER ISSUE	-
FAS_02985	01588	N	N	N	1	CUSTOMER ISSUE	-
FAS_02986	01589	N	N	N	1	CUSTOMER ISSUE	-
FAS_02987	01590	N	N	N	1	CUSTOMER ISSUE	-
FAS_02988	01591	N	N	N	1	CUSTOMER ISSUE	-
FAS_02989	01592	N	N	N	1	CUSTOMER ISSUE	-
FAS_02990	01593	N	N	N	1	CUSTOMER ISSUE	-
FAS_02991	01594	N	N	N	1	CUSTOMER ISSUE	-
FAS_02992	01595	N	N	N	1	CUSTOMER ISSUE	-
FAS_02993	01596	N	N	N	1	CUSTOMER ISSUE	-
FAS_02994	01597	N	N	N	1	CUSTOMER ISSUE	-
FAS_02995	01598	Y	N	N	1	CUSTOMER ISSUE	-
FAS_02996	01599	N	N	N	1	CUSTOMER ISSUE	-
FAS_02998	01600	N	N	N	1	CUSTOMER ISSUE	-
FAS_02999	01601	N	N	N	1	CUSTOMER ISSUE	-
FAS_03002	01602	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03003	01603	N	N	N	1	CUSTOMER ISSUE	-
FAS_03004	01604	N	N	N	1	CUSTOMER ISSUE	-
FAS_03005	01605	N	N	N	1	CUSTOMER ISSUE	-
FAS_03006	01606	N	N	N	1	CUSTOMER ISSUE	-
FAS_03007	01607	N	N	N	1	CUSTOMER ISSUE	-
FAS_03008	01608	N	N	N	1	CUSTOMER ISSUE	-
FAS_03009	01609	N	N	N	1	CUSTOMER ISSUE	-
FAS_03010	01610	N	N	N	1	CUSTOMER ISSUE	-
FAS_03011	01611	N	N	N	1	CUSTOMER ISSUE	-
FAS_03012	01612	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03013	01613	N	N	N	1	CUSTOMER ISSUE	-
FAS_03014	01614	N	N	N	1	CUSTOMER ISSUE	-
FAS_03015	01615	N	N	N	1	CUSTOMER ISSUE	-
FAS_03016	01616	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03017	01617	N	N	N	1	CUSTOMER ISSUE	-
FAS_03018	01618	N	N	N	1	CUSTOMER ISSUE	-
FAS_03019	01619	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03020	01620	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03021	01621	N	N	N	1	CUSTOMER ISSUE	-
FAS_03026	01622	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03027	01623	Y	N	Y	7	SEC/SVC - REPLACE	708.75
FAS_03028	01624	N	N	N	1	CUSTOMER ISSUE	-
FAS_03031	01625	N	N	N	4	CUSTOMER ISSUE	-
FAS_03033	01626	N	N	N	1	CUSTOMER ISSUE	-
FAS_03035	01627	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03036	01628	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03037	01629	N	N	N	1	CUSTOMER ISSUE	-
FAS_03044	01630	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03051	01631	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03057	01632	N	N	N	1	CUSTOMER ISSUE	-
FAS_03058	01633	N	N	N	1	CUSTOMER ISSUE	-
FAS_03059	01634	N	N	N	1	CUSTOMER ISSUE	-
FAS_03060	01635	N	N	N	1	CUSTOMER ISSUE	-
FAS_03061	01636	N	N	N	1	CUSTOMER ISSUE	-
FAS_03062	01637	N	N	N	1	CUSTOMER ISSUE	-
FAS_03063	01638	N	N	N	1	CUSTOMER ISSUE	-
FAS_03066	01639	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03068	01640	N	N	N	1	CUSTOMER ISSUE	-
FAS_03070	01641	N	N	N	1	CUSTOMER ISSUE	-
FAS_03071	01642	N	N	N	1	CUSTOMER ISSUE	-
FAS_03072	01643	N	N	N	1	CUSTOMER ISSUE	-
FAS_03073	01644	N	N	N	1	CUSTOMER ISSUE	-
FAS_03074	01645	N	N	N	1	CUSTOMER ISSUE	-
FAS_03075	01646	N	N	N	1	CUSTOMER ISSUE	-
FAS_03078	01647	N	N	N	1	CUSTOMER ISSUE	-
FAS_03079	01648	N	N	N	1	CUSTOMER ISSUE	-
FAS_03080	01649	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03082	01650	N	N	N	1	CUSTOMER ISSUE	-
FAS_03083	01651	N	N	N	1	CUSTOMER ISSUE	-
FAS_03085	01652	N	N	N	1	CUSTOMER ISSUE	-
FAS_03086	01653	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03087	01654	N	N	N	1	CUSTOMER ISSUE	-
FAS_03088	01655	N	N	N	1	CUSTOMER ISSUE	-
FAS_03091	01656	Y	N	N	1	CUSTOMER ISSUE	-

FAS_03092	01657	N	N	N	1	CUSTOMER ISSUE	-
FAS_03093	01658	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03094	01659	N	N	N	1	CUSTOMER ISSUE	-
FAS_03098	01660	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03099	01661	N	N	Y	5	SEC/SVC - REPLACE	708.75
FAS_03100	01662	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03101	01663	N	N	N	1	CUSTOMER ISSUE	-
FAS_03102	01664	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03103	01665	N	N	N	1	CUSTOMER ISSUE	-
FAS_03105	01666	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03106	01667	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03107	01668	N	N	N	1	CUSTOMER ISSUE	-
FAS_03108	01669	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03109	01670	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03110	01671	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03111	01672	N	N	N	1	CUSTOMER ISSUE	-
FAS_03113	01673	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03114	01674	N	N	N	1	CUSTOMER ISSUE	-
FAS_03116	01675	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03117	01676	N	N	N	1	CUSTOMER ISSUE	-
FAS_03118	01677	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03119	01678	N	N	N	1	CUSTOMER ISSUE	-
FAS_03120	01679	N	N	N	1	CUSTOMER ISSUE	-
FAS_03121	01680	N	N	N	1	CUSTOMER ISSUE	-
FAS_03123	01681	N	N	N	1	CUSTOMER ISSUE	-
FAS_03124	01682	N	N	N	1	CUSTOMER ISSUE	-
FAS_03125	01683	N	N	N	1	CUSTOMER ISSUE	-
FAS_03126	01684	N	N	N	1	CUSTOMER ISSUE	-
FAS_03127	01685	N	N	N	1	CUSTOMER ISSUE	-
FAS_03128	01686	N	N	N	1	CUSTOMER ISSUE	-
FAS_03129	01687	N	N	N	1	CUSTOMER ISSUE	-
FAS_03130	01688	N	N	N	1	CUSTOMER ISSUE	-
FAS_03131	01689	N	N	N	4	CUSTOMER ISSUE	-
FAS_03133	01690	N	N	N	1	CUSTOMER ISSUE	-
FAS_03134	01691	N	N	N	1	CUSTOMER ISSUE	-
FAS_03135	01692	N	N	N	1	CUSTOMER ISSUE	-
FAS_03136	01693	N	N	N	1	CUSTOMER ISSUE	-
FAS_03137	01694	N	N	N	1	CUSTOMER ISSUE	-
FAS_03138	01695	N	N	N	1	CUSTOMER ISSUE	-
FAS_03139	01696	N	N	N	1	CUSTOMER ISSUE	-
FAS_03140	01697	N	N	N	1	CUSTOMER ISSUE	-
FAS_03141	01698	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03142	01699	N	N	N	1	CUSTOMER ISSUE	-
FAS_03143	01700	N	N	N	1	CUSTOMER ISSUE	-
FAS_03145	01701	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03146	01702	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03147	01703	N	N	N	1	CUSTOMER ISSUE	-
FAS_03149	01704	N	N	N	1	CUSTOMER ISSUE	-
FAS_03150	01705	N	N	N	1	CUSTOMER ISSUE	-
FAS_03152	01706	N	N	N	1	CUSTOMER ISSUE	-
FAS_03153	01707	N	N	N	1	CUSTOMER ISSUE	-
FAS_03154	01708	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03155	01709	N	N	N	1	CUSTOMER ISSUE	-
FAS_03156	01710	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03157	01711	N	N	N	1	CUSTOMER ISSUE	-
FAS_03158	01712	N	N	N	1	CUSTOMER ISSUE	-
FAS_03160	01713	N	N	N	1	CUSTOMER ISSUE	-
FAS_03161	01714	N	N	N	1	CUSTOMER ISSUE	-
FAS_03162	01715	N	N	N	1	CUSTOMER ISSUE	-
FAS_03163	01716	N	N	N	1	CUSTOMER ISSUE	-
FAS_03164	01717	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03165	01718	N	N	N	1	CUSTOMER ISSUE	-
FAS_03166	01719	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03167	01720	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03168	01721	N	N	N	1	CUSTOMER ISSUE	-
FAS_03169	01722	N	N	N	1	CUSTOMER ISSUE	-
FAS_03170	01723	N	N	N	1	CUSTOMER ISSUE	-
FAS_03171	01724	N	N	N	1	CUSTOMER ISSUE	-
FAS_03173	01725	N	N	N	1	CUSTOMER ISSUE	-
FAS_03174	01726	N	N	N	1	CUSTOMER ISSUE	-
FAS_03175	01727	N	N	N	3	CUSTOMER ISSUE	-
FAS_03177	01728	N	N	N	1	CUSTOMER ISSUE	-
FAS_03178	01729	N	N	N	1	CUSTOMER ISSUE	-
FAS_03179	01730	N	N	N	1	CUSTOMER ISSUE	-
FAS_03184	01731	N	N	N	1	CUSTOMER ISSUE	-
FAS_03185	01732	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03188	01733	N	N	N	1	CUSTOMER ISSUE	-
FAS_03189	01734	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03190	01735	N	N	N	1	CUSTOMER ISSUE	-
FAS_03191	01736	N	N	N	1	CUSTOMER ISSUE	-

FAS_03192	01737	N	N	N	1	CUSTOMER ISSUE	-
FAS_03193	01738	N	N	N	1	CUSTOMER ISSUE	-
FAS_03194	01739	N	N	N	1	CUSTOMER ISSUE	-
FAS_03196	01740	N	N	N	1	CUSTOMER ISSUE	-
FAS_03197	01741	N	N	N	1	CUSTOMER ISSUE	-
FAS_03198	01742	N	N	N	1	CUSTOMER ISSUE	-
FAS_03199	01743	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03200	01744	N	N	N	1	CUSTOMER ISSUE	-
FAS_03201	01745	N	N	N	1	CUSTOMER ISSUE	-
FAS_03202	01746	N	N	N	1	CUSTOMER ISSUE	-
FAS_03203	01747	N	N	N	1	CUSTOMER ISSUE	-
FAS_03204	01748	N	N	N	1	CUSTOMER ISSUE	-
FAS_03205	01749	N	N	N	1	CUSTOMER ISSUE	-
FAS_03206	01750	N	N	N	1	CUSTOMER ISSUE	-
FAS_03207	01751	N	N	N	1	CUSTOMER ISSUE	-
FAS_03208	01752	N	N	N	3	CUSTOMER ISSUE	-
FAS_03209	01753	N	N	N	1	CUSTOMER ISSUE	-
FAS_03210	01754	N	N	N	1	CUSTOMER ISSUE	-
FAS_03211	01755	N	N	N	1	CUSTOMER ISSUE	-
FAS_03212	01756	N	N	N	1	CUSTOMER ISSUE	-
FAS_03213	01757	N	N	N	1	CUSTOMER ISSUE	-
FAS_03214	01758	N	N	N	1	CUSTOMER ISSUE	-
FAS_03215	01759	N	N	N	1	CUSTOMER ISSUE	-
FAS_03216	01760	N	N	N	1	CUSTOMER ISSUE	-
FAS_03217	01761	N	N	N	1	CUSTOMER ISSUE	-
FAS_03218	01762	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03219	01763	N	N	N	1	CUSTOMER ISSUE	-
FAS_03220	01764	N	N	N	1	CUSTOMER ISSUE	-
FAS_03221	01765	N	N	N	1	CUSTOMER ISSUE	-
FAS_03222	01766	N	N	N	1	CUSTOMER ISSUE	-
FAS_03223	01767	N	N	N	1	CUSTOMER ISSUE	-
FAS_03224	01768	N	N	N	1	CUSTOMER ISSUE	-
FAS_03225	01769	N	N	N	1	CUSTOMER ISSUE	-
FAS_03227	01770	N	N	N	1	CUSTOMER ISSUE	-
FAS_03228	01771	N	N	N	1	CUSTOMER ISSUE	-
FAS_03229	01772	N	N	N	2	CUSTOMER ISSUE	-
FAS_03230	01773	N	N	N	1	CUSTOMER ISSUE	-
FAS_03231	01774	Y	N	N	2	CUSTOMER ISSUE	-
FAS_03232	01775	N	N	N	2	CUSTOMER ISSUE	-
FAS_03233	01776	N	N	N	1	CUSTOMER ISSUE	-
FAS_03234	01777	N	N	N	1	CUSTOMER ISSUE	-
FAS_03235	01778	N	N	N	1	CUSTOMER ISSUE	-
FAS_03236	01779	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03237	01780	N	N	N	1	CUSTOMER ISSUE	-
FAS_03238	01781	N	N	N	23	CUSTOMER ISSUE	-
FAS_03239	01782	N	N	N	1	CUSTOMER ISSUE	-
FAS_03240	01783	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03241	01784	N	N	N	1	CUSTOMER ISSUE	-
FAS_03242	01785	N	N	N	1	CUSTOMER ISSUE	-
FAS_03243	01786	N	N	N	1	CUSTOMER ISSUE	-
FAS_03244	01787	N	N	N	1	CUSTOMER ISSUE	-
FAS_03245	01788	N	N	N	1	CUSTOMER ISSUE	-
FAS_03246	01789	N	N	N	1	CUSTOMER ISSUE	-
FAS_03247	01790	N	N	N	1	CUSTOMER ISSUE	-
FAS_03248	01791	N	N	N	1	CUSTOMER ISSUE	-
FAS_03251	01792	N	N	N	1	CUSTOMER ISSUE	-
FAS_03252	01793	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03253	01794	N	N	N	1	CUSTOMER ISSUE	-
FAS_03254	01795	N	N	N	1	CUSTOMER ISSUE	-
FAS_03255	01796	N	N	N	1	CUSTOMER ISSUE	-
FAS_03256	01797	N	N	N	1	CUSTOMER ISSUE	-
FAS_03257	01798	N	N	N	1	CUSTOMER ISSUE	-
FAS_03258	01799	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03259	01800	N	N	N	1	CUSTOMER ISSUE	-
FAS_03260	01801	N	N	N	1	CUSTOMER ISSUE	-
FAS_03261	01802	N	N	N	1	CUSTOMER ISSUE	-
FAS_03264	01803	N	N	N	1	CUSTOMER ISSUE	-
FAS_03265	01804	N	N	N	1	CUSTOMER ISSUE	-
FAS_03267	01805	N	N	N	1	CUSTOMER ISSUE	-
FAS_03269	01806	N	N	N	1	CUSTOMER ISSUE	-
FAS_03271	01807	N	N	N	1	CUSTOMER ISSUE	-
FAS_03272	01808	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03273	01809	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03275	01810	N	N	N	1	CUSTOMER ISSUE	-
FAS_03277	01811	N	N	N	1	CUSTOMER ISSUE	-
FAS_03278	01812	N	N	N	1	CUSTOMER ISSUE	-
FAS_03279	01813	N	N	N	1	CUSTOMER ISSUE	-
FAS_03280	01814	N	N	N	1	CUSTOMER ISSUE	-
FAS_03281	01815	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03282	01816	N	N	N	1	CUSTOMER ISSUE	-

FAS_03283	01817	N	N	N	1	CUSTOMER ISSUE	-
FAS_03284	01818	N	N	N	1	CUSTOMER ISSUE	-
FAS_03285	01819	N	N	N	1	CUSTOMER ISSUE	-
FAS_03286	01820	N	N	N	1	CUSTOMER ISSUE	-
FAS_03287	01821	N	N	N	1	CUSTOMER ISSUE	-
FAS_03288	01822	N	N	N	1	CUSTOMER ISSUE	-
FAS_03289	01823	N	N	N	1	CUSTOMER ISSUE	-
FAS_03290	01824	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03291	01825	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03292	01826	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03293	01827	N	N	N	1	CUSTOMER ISSUE	-
FAS_03294	01828	N	N	N	1	CUSTOMER ISSUE	-
FAS_03298	01829	N	N	N	2	CUSTOMER ISSUE	-
FAS_03301	01830	N	N	N	1	CUSTOMER ISSUE	-
FAS_03302	01831	N	N	N	1	CUSTOMER ISSUE	-
FAS_03303	01832	N	N	N	1	CUSTOMER ISSUE	-
FAS_03305	01833	N	N	N	1	CUSTOMER ISSUE	-
FAS_03306	01834	N	N	N	1	CUSTOMER ISSUE	-
FAS_03307	01835	N	N	N	1	CUSTOMER ISSUE	-
FAS_03308	01836	N	N	N	1	CUSTOMER ISSUE	-
FAS_03309	01837	N	N	N	1	CUSTOMER ISSUE	-
FAS_03310	01838	N	N	N	1	CUSTOMER ISSUE	-
FAS_03311	01839	N	N	N	1	CUSTOMER ISSUE	-
FAS_03313	01840	N	N	N	1	CUSTOMER ISSUE	-
FAS_03314	01841	N	N	N	1	CUSTOMER ISSUE	-
FAS_03315	01842	N	N	N	1	CUSTOMER ISSUE	-
FAS_03318	01843	N	N	N	1	CUSTOMER ISSUE	-
FAS_03319	01844	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03320	01845	N	N	N	1	CUSTOMER ISSUE	-
FAS_03321	01846	N	N	N	1	CUSTOMER ISSUE	-
FAS_03322	01847	N	N	N	1	CUSTOMER ISSUE	-
FAS_03323	01848	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03324	01849	N	N	N	1	CUSTOMER ISSUE	-
FAS_03325	01850	N	N	N	1	CUSTOMER ISSUE	-
FAS_03326	01851	N	N	N	1	CUSTOMER ISSUE	-
FAS_03327	01852	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03330	01853	N	N	N	1	CUSTOMER ISSUE	-
FAS_03331	01854	N	N	N	1	CUSTOMER ISSUE	-
FAS_03332	01855	N	N	N	1	CUSTOMER ISSUE	-
FAS_03333	01856	N	N	N	1	CUSTOMER ISSUE	-
FAS_03334	01857	N	N	N	1	CUSTOMER ISSUE	-
FAS_03335	01858	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03336	01859	N	N	N	1	CUSTOMER ISSUE	-
FAS_03338	01860	N	N	N	1	CUSTOMER ISSUE	-
FAS_03339	01861	N	N	N	1	CUSTOMER ISSUE	-
FAS_03342	01862	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03343	01863	N	N	N	1	CUSTOMER ISSUE	-
FAS_03344	01864	N	N	N	1	CUSTOMER ISSUE	-
FAS_03345	01865	N	N	N	1	CUSTOMER ISSUE	-
FAS_03346	01866	N	N	N	1	CUSTOMER ISSUE	-
FAS_03347	01867	N	N	N	1	CUSTOMER ISSUE	-
FAS_03348	01868	N	N	N	1	CUSTOMER ISSUE	-
FAS_03349	01869	N	N	N	1	CUSTOMER ISSUE	-
FAS_03351	01870	N	N	N	1	CUSTOMER ISSUE	-
FAS_03352	01871	N	N	N	1	CUSTOMER ISSUE	-
FAS_03353	01872	N	N	N	1	CUSTOMER ISSUE	-
FAS_03354	01873	N	N	N	1	CUSTOMER ISSUE	-
FAS_03355	01874	N	N	N	1	CUSTOMER ISSUE	-
FAS_03356	01875	N	N	N	1	CUSTOMER ISSUE	-
FAS_03357	01876	N	N	N	1	CUSTOMER ISSUE	-
FAS_03358	01877	N	N	N	1	CUSTOMER ISSUE	-
FAS_03359	01878	N	N	N	1	CUSTOMER ISSUE	-
FAS_03360	01879	N	N	N	1	CUSTOMER ISSUE	-
FAS_03362	01880	N	N	N	1	CUSTOMER ISSUE	-
FAS_03363	01881	N	N	N	1	CUSTOMER ISSUE	-
FAS_03364	01882	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03365	01883	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03366	01884	N	N	N	1	CUSTOMER ISSUE	-
FAS_03369	01885	N	N	N	3	CUSTOMER ISSUE	-
FAS_03371	01886	N	N	N	1	CUSTOMER ISSUE	-
FAS_03372	01887	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03376	01888	N	N	N	1	CUSTOMER ISSUE	-
FAS_03377	01889	N	N	N	1	CUSTOMER ISSUE	-
FAS_03378	01890	N	N	N	1	CUSTOMER ISSUE	-
FAS_03379	01891	N	N	N	1	CUSTOMER ISSUE	-
FAS_03380	01892	N	N	N	1	CUSTOMER ISSUE	-
FAS_03383	01893	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03384	01894	N	N	N	1	CUSTOMER ISSUE	-
FAS_03386	01895	N	N	N	2	CUSTOMER ISSUE	-
FAS_03390	01896	N	N	N	1	CUSTOMER ISSUE	-

FAS_03392	01897	N	N	N	8	CUSTOMER ISSUE	-
FAS_03393	01898	N	N	N	1	CUSTOMER ISSUE	-
FAS_03394	01899	N	N	N	5	CUSTOMER ISSUE	-
FAS_03395	01900	N	N	N	1	CUSTOMER ISSUE	-
FAS_03396	01901	N	N	N	1	CUSTOMER ISSUE	-
FAS_03399	01902	N	N	N	1	CUSTOMER ISSUE	-
FAS_03400	01903	N	N	N	1	CUSTOMER ISSUE	-
FAS_03402	01904	N	N	N	1	CUSTOMER ISSUE	-
FAS_03405	01905	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_03406	01906	N	N	N	1	CUSTOMER ISSUE	-
FAS_03407	01907	N	N	N	1	CUSTOMER ISSUE	-
FAS_03408	01908	N	N	N	1	CUSTOMER ISSUE	-
FAS_03409	01909	N	N	N	1	CUSTOMER ISSUE	-
FAS_03410	01910	N	N	N	1	CUSTOMER ISSUE	-
FAS_03411	01911	N	N	N	1	CUSTOMER ISSUE	-
FAS_03412	01912	N	N	N	1	CUSTOMER ISSUE	-
FAS_03413	01913	N	N	N	1	CUSTOMER ISSUE	-
FAS_03415	01914	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03417	01915	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03419	01916	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03422	01917	N	N	N	1	CUSTOMER ISSUE	-
FAS_03423	01918	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03424	01919	N	N	N	1	CUSTOMER ISSUE	-
FAS_03425	01920	N	N	N	1	CUSTOMER ISSUE	-
FAS_03426	01921	N	N	N	1	CUSTOMER ISSUE	-
FAS_03427	01922	N	N	N	1	CUSTOMER ISSUE	-
FAS_03428	01923	N	N	N	1	CUSTOMER ISSUE	-
FAS_03430	01924	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03431	01925	N	N	N	4	CUSTOMER ISSUE	-
FAS_03432	01926	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03433	01927	N	N	N	1	CUSTOMER ISSUE	-
FAS_03434	01928	N	N	N	1	CUSTOMER ISSUE	-
FAS_03439	01929	N	N	N	1	CUSTOMER ISSUE	-
FAS_03441	01930	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03443	01931	N	N	N	1	CUSTOMER ISSUE	-
FAS_03444	01932	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03445	01933	N	N	N	1	CUSTOMER ISSUE	-
FAS_03446	01934	N	N	N	1	CUSTOMER ISSUE	-
FAS_03447	01935	N	N	N	1	CUSTOMER ISSUE	-
FAS_03448	01936	N	N	N	1	CUSTOMER ISSUE	-
FAS_03449	01937	N	N	N	1	CUSTOMER ISSUE	-
FAS_03450	01938	N	N	N	1	CUSTOMER ISSUE	-
FAS_03451	01939	N	N	N	1	CUSTOMER ISSUE	-
FAS_03452	01940	N	N	N	1	CUSTOMER ISSUE	-
FAS_03453	01941	N	N	N	1	CUSTOMER ISSUE	-
FAS_03454	01942	N	N	N	1	CUSTOMER ISSUE	-
FAS_03455	01943	N	N	N	2	CUSTOMER ISSUE	-
FAS_03458	01944	N	N	N	1	CUSTOMER ISSUE	-
FAS_03465	01945	N	N	N	1	CUSTOMER ISSUE	-
FAS_03467	01946	N	N	N	1	CUSTOMER ISSUE	-
FAS_03468	01947	N	N	N	1	CUSTOMER ISSUE	-
FAS_03469	01948	N	N	N	1	CUSTOMER ISSUE	-
FAS_03470	01949	N	N	N	1	CUSTOMER ISSUE	-
FAS_03471	01950	N	N	N	1	CUSTOMER ISSUE	-
FAS_03472	01951	N	N	N	1	CUSTOMER ISSUE	-
FAS_03473	01952	N	N	N	1	CUSTOMER ISSUE	-
FAS_03474	01953	N	N	N	1	CUSTOMER ISSUE	-
FAS_03475	01954	N	N	N	1	CUSTOMER ISSUE	-
FAS_03476	01955	N	N	N	1	CUSTOMER ISSUE	-
FAS_03477	01956	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03478	01957	N	N	N	1	CUSTOMER ISSUE	-
FAS_03479	01958	N	N	N	1	CUSTOMER ISSUE	-
FAS_03480	01959	N	N	N	1	CUSTOMER ISSUE	-
FAS_03481	01960	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03482	01961	N	N	N	1	CUSTOMER ISSUE	-
FAS_03483	01962	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03484	01963	N	N	N	1	CUSTOMER ISSUE	-
FAS_03485	01964	N	N	N	1	CUSTOMER ISSUE	-
FAS_03486	01965	N	N	N	1	CUSTOMER ISSUE	-
FAS_03488	01966	N	N	N	1	CUSTOMER ISSUE	-
FAS_03489	01967	Y	N	N	2	CUSTOMER ISSUE	-
FAS_03493	01968	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03494	01969	N	N	N	1	CUSTOMER ISSUE	-
FAS_03496	01970	N	N	N	2	CUSTOMER ISSUE	-
FAS_03497	01971	N	N	N	1	CUSTOMER ISSUE	-
FAS_03500	01972	N	N	N	1	CUSTOMER ISSUE	-
FAS_03501	01973	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03502	01974	N	N	N	1	CUSTOMER ISSUE	-
FAS_03503	01975	N	N	N	1	CUSTOMER ISSUE	-
FAS_03506	01976	N	N	N	1	CUSTOMER ISSUE	-

FAS_03507	01977	N	N	N	1	CUSTOMER ISSUE	-
FAS_03508	01978	N	N	N	1	CUSTOMER ISSUE	-
FAS_03509	01979	N	N	N	1	CUSTOMER ISSUE	-
FAS_03510	01980	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_03512	01981	N	N	N	22	CUSTOMER ISSUE	-
FAS_03513	01982	N	N	N	1	CUSTOMER ISSUE	-
FAS_03515	01983	N	N	N	1	CUSTOMER ISSUE	-
FAS_03516	01984	N	N	N	1	CUSTOMER ISSUE	-
FAS_03517	01985	N	N	N	1	CUSTOMER ISSUE	-
FAS_03518	01986	N	N	N	1	CUSTOMER ISSUE	-
FAS_03519	01987	N	N	N	1	CUSTOMER ISSUE	-
FAS_03520	01988	N	N	N	11	CUSTOMER ISSUE	-
FAS_03521	01989	N	N	N	1	CUSTOMER ISSUE	-
FAS_03522	01990	N	N	N	1	CUSTOMER ISSUE	-
FAS_03523	01991	N	N	N	1	CUSTOMER ISSUE	-
FAS_03524	01992	N	N	N	1	CUSTOMER ISSUE	-
FAS_03525	01993	N	N	N	1	CUSTOMER ISSUE	-
FAS_03526	01994	N	N	N	1	CUSTOMER ISSUE	-
FAS_03527	01995	N	N	N	1	CUSTOMER ISSUE	-
FAS_03530	01996	N	N	N	1	CUSTOMER ISSUE	-
FAS_03531	01997	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_03532	01998	N	N	N	1	CUSTOMER ISSUE	-
FAS_03534	01999	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03535	02000	N	N	N	1	CUSTOMER ISSUE	-
FAS_03537	02001	N	N	N	1	CUSTOMER ISSUE	-
FAS_03538	02002	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_03543	02003	N	N	N	1	CUSTOMER ISSUE	-
FAS_03544	02004	N	N	N	1	CUSTOMER ISSUE	-
FAS_03545	02005	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03546	02006	N	N	N	1	CUSTOMER ISSUE	-
FAS_03547	02007	N	N	N	1	CUSTOMER ISSUE	-
FAS_03548	02008	N	N	N	1	CUSTOMER ISSUE	-
FAS_03550	02009	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_03551	02010	N	N	N	1	CUSTOMER ISSUE	-
FAS_03552	02011	N	N	N	1	CUSTOMER ISSUE	-
FAS_03554	02012	N	N	N	1	CUSTOMER ISSUE	-
FAS_03555	02013	N	N	N	1	CUSTOMER ISSUE	-
FAS_03556	02014	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03557	02015	N	N	N	1	CUSTOMER ISSUE	-
FAS_03558	02016	N	N	N	1	CUSTOMER ISSUE	-
FAS_03560	02017	N	N	N	1	CUSTOMER ISSUE	-
FAS_03562	02018	N	N	N	1	CUSTOMER ISSUE	-
FAS_03564	02019	N	N	N	1	CUSTOMER ISSUE	-
FAS_03565	02020	N	N	N	1	CUSTOMER ISSUE	-
FAS_03567	02021	N	N	N	1	CUSTOMER ISSUE	-
FAS_03568	02022	N	N	N	1	CUSTOMER ISSUE	-
FAS_03569	02023	N	N	N	1	CUSTOMER ISSUE	-
FAS_03570	02024	N	N	N	1	CUSTOMER ISSUE	-
FAS_03571	02025	N	N	N	1	CUSTOMER ISSUE	-
FAS_03572	02026	N	N	N	1	CUSTOMER ISSUE	-
FAS_03573	02027	N	N	N	1	CUSTOMER ISSUE	-
FAS_03574	02028	N	N	N	1	CUSTOMER ISSUE	-
FAS_03575	02029	N	N	N	1	CUSTOMER ISSUE	-
FAS_03576	02030	N	N	N	1	CUSTOMER ISSUE	-
FAS_03577	02031	N	N	N	1	CUSTOMER ISSUE	-
FAS_03578	02032	N	N	N	1	CUSTOMER ISSUE	-
FAS_03579	02033	N	N	N	1	CUSTOMER ISSUE	-
FAS_03580	02034	N	N	N	1	CUSTOMER ISSUE	-
FAS_03581	02035	N	N	N	1	CUSTOMER ISSUE	-
FAS_03582	02036	N	N	N	1	CUSTOMER ISSUE	-
FAS_03583	02037	N	N	N	1	CUSTOMER ISSUE	-
FAS_03584	02038	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03585	02039	N	N	N	1	CUSTOMER ISSUE	-
FAS_03586	02040	N	N	N	1	CUSTOMER ISSUE	-
FAS_03587	02041	N	N	N	1	CUSTOMER ISSUE	-
FAS_03588	02042	N	N	N	1	CUSTOMER ISSUE	-
FAS_03589	02043	N	N	N	1	CUSTOMER ISSUE	-
FAS_03590	02044	N	N	N	1	CUSTOMER ISSUE	-
FAS_03592	02045	N	N	N	1	CUSTOMER ISSUE	-
FAS_03593	02046	N	N	N	1	CUSTOMER ISSUE	-
FAS_03594	02047	N	N	N	1	CUSTOMER ISSUE	-
FAS_03595	02048	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03597	02049	N	N	Y	1	TX - REPLACE	2500
FAS_03600	02050	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03602	02051	N	N	N	1	CUSTOMER ISSUE	-
FAS_03604	02052	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03607	02053	N	N	N	1	CUSTOMER ISSUE	-
FAS_03610	02054	N	N	N	1	CUSTOMER ISSUE	-
FAS_03611	02055	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03612	02056	N	N	N	1	CUSTOMER ISSUE	-

FAS_03614	02057	N	N	N	1	CUSTOMER ISSUE	-
FAS_03615	02058	N	N	N	1	CUSTOMER ISSUE	-
FAS_03619	02059	N	N	N	1	CUSTOMER ISSUE	-
FAS_03621	02060	N	N	N	1	CUSTOMER ISSUE	-
FAS_03637	02061	N	N	N	1	CUSTOMER ISSUE	-
FAS_03641	02062	N	N	N	1	CUSTOMER ISSUE	-
FAS_03643	02063	N	N	N	1	CUSTOMER ISSUE	-
FAS_03646	02064	N	N	N	1	CUSTOMER ISSUE	-
FAS_03647	02065	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03651	02066	N	N	N	1	CUSTOMER ISSUE	-
FAS_03652	02067	N	N	N	1	CUSTOMER ISSUE	-
FAS_03653	02068	N	N	N	1	CUSTOMER ISSUE	-
FAS_03654	02069	N	N	N	1	CUSTOMER ISSUE	-
FAS_03656	02070	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03657	02071	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03658	02072	N	N	N	1	CUSTOMER ISSUE	-
FAS_03660	02073	N	N	N	1	CUSTOMER ISSUE	-
FAS_03661	02074	N	N	N	1	CUSTOMER ISSUE	-
FAS_03669	02075	N	N	N	1	CUSTOMER ISSUE	-
FAS_03670	02076	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03671	02077	N	N	N	1	CUSTOMER ISSUE	-
FAS_03675	02078	N	N	N	1	CUSTOMER ISSUE	-
FAS_03677	02079	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03678	02080	N	N	N	1	CUSTOMER ISSUE	-
FAS_03679	02081	N	N	N	1	CUSTOMER ISSUE	-
FAS_03680	02082	N	N	N	1	CUSTOMER ISSUE	-
FAS_03681	02083	N	N	N	2	CUSTOMER ISSUE	-
FAS_03682	02084	N	N	N	1	CUSTOMER ISSUE	-
FAS_03683	02085	N	N	N	1	CUSTOMER ISSUE	-
FAS_03684	02086	N	N	N	1	CUSTOMER ISSUE	-
FAS_03685	02087	N	N	N	1	CUSTOMER ISSUE	-
FAS_03686	02088	N	N	N	1	CUSTOMER ISSUE	-
FAS_03687	02089	N	N	N	1	CUSTOMER ISSUE	-
FAS_03688	02090	N	N	N	1	CUSTOMER ISSUE	-
FAS_03689	02091	N	N	N	1	CUSTOMER ISSUE	-
FAS_03690	02092	N	N	N	1	CUSTOMER ISSUE	-
FAS_03691	02093	N	N	N	1	CUSTOMER ISSUE	-
FAS_03692	02094	N	N	N	1	CUSTOMER ISSUE	-
FAS_03693	02095	N	N	N	1	CUSTOMER ISSUE	-
FAS_03695	02096	N	N	N	1	CUSTOMER ISSUE	-
FAS_03696	02097	N	N	N	1	CUSTOMER ISSUE	-
FAS_03698	02098	N	N	N	1	CUSTOMER ISSUE	-
FAS_03699	02099	N	N	N	1	CUSTOMER ISSUE	-
FAS_03700	02100	N	N	N	1	CUSTOMER ISSUE	-
FAS_03701	02101	N	N	N	1	CUSTOMER ISSUE	-
FAS_03702	02102	N	N	N	1	CUSTOMER ISSUE	-
FAS_03704	02103	N	N	N	1	CUSTOMER ISSUE	-
FAS_03705	02104	N	N	N	1	CUSTOMER ISSUE	-
FAS_03706	02105	N	N	N	1	CUSTOMER ISSUE	-
FAS_03707	02106	N	N	N	1	CUSTOMER ISSUE	-
FAS_03708	02107	N	N	N	1	CUSTOMER ISSUE	-
FAS_03709	02108	N	N	N	1	CUSTOMER ISSUE	-
FAS_03710	02109	N	N	N	2	CUSTOMER ISSUE	-
FAS_03711	02110	N	N	N	1	CUSTOMER ISSUE	-
FAS_03712	02111	N	N	N	2	CUSTOMER ISSUE	-
FAS_03713	02112	N	N	N	1	CUSTOMER ISSUE	-
FAS_03714	02113	N	N	N	1	CUSTOMER ISSUE	-
FAS_03715	02114	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03716	02115	N	N	N	1	CUSTOMER ISSUE	-
FAS_03717	02116	Y	N	N	2	CUSTOMER ISSUE	-
FAS_03718	02117	N	N	N	1	CUSTOMER ISSUE	-
FAS_03719	02118	N	N	Y	1	TX - REPLACE	2500
FAS_03720	02119	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03723	02120	N	N	N	1	CUSTOMER ISSUE	-
FAS_03724	02121	N	N	N	1	CUSTOMER ISSUE	-
FAS_03726	02122	N	N	N	1	CUSTOMER ISSUE	-
FAS_03727	02123	N	N	N	1	CUSTOMER ISSUE	-
FAS_03729	02124	N	N	N	1	CUSTOMER ISSUE	-
FAS_03731	02125	N	N	N	1	CUSTOMER ISSUE	-
FAS_03733	02126	N	N	N	1	CUSTOMER ISSUE	-
FAS_03734	02127	N	N	N	1	CUSTOMER ISSUE	-
FAS_03735	02128	N	N	N	1	CUSTOMER ISSUE	-
FAS_03736	02129	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03737	02130	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03739	02131	N	N	N	1	CUSTOMER ISSUE	-
FAS_03740	02132	N	N	N	1	CUSTOMER ISSUE	-
FAS_03741	02133	N	N	N	2	CUSTOMER ISSUE	-
FAS_03742	02134	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03743	02135	N	N	N	1	CUSTOMER ISSUE	-
FAS_03745	02136	N	N	N	1	CUSTOMER ISSUE	-

FAS_03746	02137	N	N	N	1	CUSTOMER ISSUE	-
FAS_03747	02138	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03748	02139	N	N	N	1	CUSTOMER ISSUE	-
FAS_03749	02140	N	N	N	1	CUSTOMER ISSUE	-
FAS_03750	02141	N	N	N	1	CUSTOMER ISSUE	-
FAS_03751	02142	N	N	N	1	CUSTOMER ISSUE	-
FAS_03752	02143	N	N	N	1	CUSTOMER ISSUE	-
FAS_03753	02144	N	N	N	1	CUSTOMER ISSUE	-
FAS_03754	02145	N	N	N	1	CUSTOMER ISSUE	-
FAS_03755	02146	N	N	N	1	CUSTOMER ISSUE	-
FAS_03756	02147	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03759	02148	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03760	02149	N	N	N	1	CUSTOMER ISSUE	-
FAS_03761	02150	N	N	N	1	CUSTOMER ISSUE	-
FAS_03762	02151	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03763	02152	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03764	02153	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03765	02154	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03766	02155	Y	N	N	4	CUSTOMER ISSUE	-
FAS_03767	02156	N	N	N	1	CUSTOMER ISSUE	-
FAS_03768	02157	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03769	02158	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03770	02159	N	N	N	1	CUSTOMER ISSUE	-
FAS_03771	02160	N	N	N	1	CUSTOMER ISSUE	-
FAS_03772	02161	N	N	N	1	CUSTOMER ISSUE	-
FAS_03773	02162	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03775	02163	N	N	N	1	CUSTOMER ISSUE	-
FAS_03776	02164	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03777	02165	N	N	N	1	CUSTOMER ISSUE	-
FAS_03778	02166	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03779	02167	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_03780	02168	N	N	N	1	CUSTOMER ISSUE	-
FAS_03781	02169	N	N	N	1	CUSTOMER ISSUE	-
FAS_03782	02170	N	N	N	1	CUSTOMER ISSUE	-
FAS_03785	02171	N	N	N	1	CUSTOMER ISSUE	-
FAS_03786	02172	N	N	N	1	CUSTOMER ISSUE	-
FAS_03787	02173	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03788	02174	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03789	02175	N	N	N	1	CUSTOMER ISSUE	-
FAS_03790	02176	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03791	02177	N	N	Y	8	SEC/SVC - REPLACE	708.75
FAS_03792	02178	N	N	N	1	CUSTOMER ISSUE	-
FAS_03793	02179	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03794	02180	N	N	N	1	CUSTOMER ISSUE	-
FAS_03795	02181	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03797	02182	N	N	N	1	CUSTOMER ISSUE	-
FAS_03798	02183	N	N	N	1	CUSTOMER ISSUE	-
FAS_03799	02184	N	N	N	1	CUSTOMER ISSUE	-
FAS_03800	02185	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03801	02186	N	N	N	1	CUSTOMER ISSUE	-
FAS_03802	02187	N	N	N	1	CUSTOMER ISSUE	-
FAS_03803	02188	N	N	N	1	CUSTOMER ISSUE	-
FAS_03804	02189	N	N	N	1	CUSTOMER ISSUE	-
FAS_03805	02190	N	N	N	1	CUSTOMER ISSUE	-
FAS_03806	02191	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03809	02192	N	N	N	1	CUSTOMER ISSUE	-
FAS_03810	02193	N	N	N	1	CUSTOMER ISSUE	-
FAS_03811	02194	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03812	02195	N	N	N	1	CUSTOMER ISSUE	-
FAS_03813	02196	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03814	02197	N	N	N	1	CUSTOMER ISSUE	-
FAS_03816	02198	N	N	N	1	CUSTOMER ISSUE	-
FAS_03818	02199	N	N	N	1	CUSTOMER ISSUE	-
FAS_03819	02200	N	N	N	1	CUSTOMER ISSUE	-
FAS_03820	02201	N	N	N	2	CUSTOMER ISSUE	-
FAS_03821	02202	N	N	N	1	CUSTOMER ISSUE	-
FAS_03822	02203	N	N	N	1	CUSTOMER ISSUE	-
FAS_03823	02204	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03824	02205	N	N	N	1	CUSTOMER ISSUE	-
FAS_03825	02206	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03826	02207	N	N	N	1	CUSTOMER ISSUE	-
FAS_03827	02208	N	N	N	1	CUSTOMER ISSUE	-
FAS_03828	02209	N	N	N	1	CUSTOMER ISSUE	-
FAS_03829	02210	N	N	N	1	CUSTOMER ISSUE	-
FAS_03830	02211	N	N	N	1	CUSTOMER ISSUE	-
FAS_03831	02212	N	N	N	1	CUSTOMER ISSUE	-
FAS_03832	02213	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03833	02214	N	N	N	1	CUSTOMER ISSUE	-
FAS_03835	02215	N	N	N	1	CUSTOMER ISSUE	-
FAS_03836	02216	N	N	N	1	CUSTOMER ISSUE	-

FAS_03837	02217	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03838	02218	N	N	N	1	CUSTOMER ISSUE	-
FAS_03839	02219	N	N	N	1	CUSTOMER ISSUE	-
FAS_03840	02220	Y	N	N	2	CUSTOMER ISSUE	-
FAS_03841	02221	N	N	N	1	CUSTOMER ISSUE	-
FAS_03842	02222	N	N	N	1	CUSTOMER ISSUE	-
FAS_03843	02223	N	N	N	1	CUSTOMER ISSUE	-
FAS_03845	02224	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03846	02225	N	N	N	1	CUSTOMER ISSUE	-
FAS_03847	02226	N	N	N	1	CUSTOMER ISSUE	-
FAS_03848	02227	N	N	N	1	CUSTOMER ISSUE	-
FAS_03849	02228	N	N	N	1	CUSTOMER ISSUE	-
FAS_03850	02229	N	N	N	1	CUSTOMER ISSUE	-
FAS_03851	02230	N	N	N	1	CUSTOMER ISSUE	-
FAS_03852	02231	N	N	N	1	CUSTOMER ISSUE	-
FAS_03853	02232	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_03854	02233	N	N	N	1	CUSTOMER ISSUE	-
FAS_03855	02234	N	N	N	1	CUSTOMER ISSUE	-
FAS_03856	02235	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03857	02236	N	N	N	1	CUSTOMER ISSUE	-
FAS_03858	02237	N	N	N	1	CUSTOMER ISSUE	-
FAS_03859	02238	N	N	N	1	CUSTOMER ISSUE	-
FAS_03860	02239	N	N	N	1	CUSTOMER ISSUE	-
FAS_03861	02240	N	N	N	1	CUSTOMER ISSUE	-
FAS_03862	02241	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03863	02242	N	N	N	6	CUSTOMER ISSUE	-
FAS_03864	02243	N	N	N	1	CUSTOMER ISSUE	-
FAS_03865	02244	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03866	02245	N	N	N	1	CUSTOMER ISSUE	-
FAS_03867	02246	N	N	N	1	CUSTOMER ISSUE	-
FAS_03869	02247	N	N	N	1	CUSTOMER ISSUE	-
FAS_03870	02248	N	N	N	1	CUSTOMER ISSUE	-
FAS_03871	02249	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03872	02250	N	N	N	1	CUSTOMER ISSUE	-
FAS_03873	02251	N	N	N	1	CUSTOMER ISSUE	-
FAS_03874	02252	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03875	02253	N	N	N	1	CUSTOMER ISSUE	-
FAS_03876	02254	N	N	N	1	CUSTOMER ISSUE	-
FAS_03877	02255	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03878	02256	N	N	N	1	CUSTOMER ISSUE	-
FAS_03879	02257	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_03880	02258	N	N	N	1	CUSTOMER ISSUE	-
FAS_03881	02259	N	N	N	1	CUSTOMER ISSUE	-
FAS_03883	02260	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03884	02261	N	N	N	1	CUSTOMER ISSUE	-
FAS_03885	02262	N	N	N	1	CUSTOMER ISSUE	-
FAS_03886	02263	N	N	N	1	CUSTOMER ISSUE	-
FAS_03888	02264	N	N	N	1	CUSTOMER ISSUE	-
FAS_03889	02265	N	N	N	1	CUSTOMER ISSUE	-
FAS_03890	02266	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03891	02267	N	N	N	1	CUSTOMER ISSUE	-
FAS_03893	02268	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_03894	02269	N	N	N	1	CUSTOMER ISSUE	-
FAS_03895	02270	N	N	N	1	CUSTOMER ISSUE	-
FAS_03896	02271	N	N	N	1	CUSTOMER ISSUE	-
FAS_03897	02272	N	N	N	3	CUSTOMER ISSUE	-
FAS_03898	02273	N	N	N	1	CUSTOMER ISSUE	-
FAS_03899	02274	N	N	N	1	CUSTOMER ISSUE	-
FAS_03900	02275	N	N	N	1	CUSTOMER ISSUE	-
FAS_03901	02276	N	N	N	1	CUSTOMER ISSUE	-
FAS_03902	02277	N	N	N	1	CUSTOMER ISSUE	-
FAS_03903	02278	N	N	N	1	CUSTOMER ISSUE	-
FAS_03904	02279	N	N	N	1	CUSTOMER ISSUE	-
FAS_03905	02280	N	N	N	1	CUSTOMER ISSUE	-
FAS_03906	02281	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03907	02282	N	N	N	1	CUSTOMER ISSUE	-
FAS_03908	02283	N	N	N	1	CUSTOMER ISSUE	-
FAS_03909	02284	N	N	N	1	CUSTOMER ISSUE	-
FAS_03910	02285	N	N	N	1	CUSTOMER ISSUE	-
FAS_03911	02286	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03912	02287	N	N	N	1	CUSTOMER ISSUE	-
FAS_03913	02288	N	N	N	1	CUSTOMER ISSUE	-
FAS_03914	02289	N	N	N	1	CUSTOMER ISSUE	-
FAS_03915	02290	N	N	N	1	CUSTOMER ISSUE	-
FAS_03916	02291	N	N	N	1	CUSTOMER ISSUE	-
FAS_03918	02292	N	N	N	1	CUSTOMER ISSUE	-
FAS_03920	02293	N	N	N	1	CUSTOMER ISSUE	-
FAS_03921	02294	N	N	N	1	CUSTOMER ISSUE	-
FAS_03922	02295	N	N	N	1	CUSTOMER ISSUE	-
FAS_03923	02296	Y	N	N	1	CUSTOMER ISSUE	-

FAS_03924	02297	N	N	N	1	CUSTOMER ISSUE	-
FAS_03925	02298	N	N	N	1	CUSTOMER ISSUE	-
FAS_03926	02299	N	N	N	1	CUSTOMER ISSUE	-
FAS_03928	02300	N	N	N	1	CUSTOMER ISSUE	-
FAS_03930	02301	N	N	N	1	CUSTOMER ISSUE	-
FAS_03931	02302	N	N	N	1	CUSTOMER ISSUE	-
FAS_03932	02303	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03933	02304	N	N	N	1	CUSTOMER ISSUE	-
FAS_03934	02305	N	N	N	1	CUSTOMER ISSUE	-
FAS_03935	02306	N	N	N	1	CUSTOMER ISSUE	-
FAS_03936	02307	N	N	N	1	CUSTOMER ISSUE	-
FAS_03937	02308	N	N	N	1	CUSTOMER ISSUE	-
FAS_03938	02309	N	N	N	1	CUSTOMER ISSUE	-
FAS_03939	02310	N	N	N	3	CUSTOMER ISSUE	-
FAS_03941	02311	N	N	N	1	CUSTOMER ISSUE	-
FAS_03943	02312	N	N	N	1	CUSTOMER ISSUE	-
FAS_03946	02313	N	N	N	1	CUSTOMER ISSUE	-
FAS_03947	02314	N	N	N	1	CUSTOMER ISSUE	-
FAS_03948	02315	N	N	N	7	CUSTOMER ISSUE	-
FAS_03951	02316	N	N	N	1	CUSTOMER ISSUE	-
FAS_03954	02317	N	N	N	1	CUSTOMER ISSUE	-
FAS_03955	02318	N	N	N	1	CUSTOMER ISSUE	-
FAS_03958	02319	N	N	N	1	CUSTOMER ISSUE	-
FAS_03961	02320	N	N	N	1	CUSTOMER ISSUE	-
FAS_03962	02321	N	N	N	1	CUSTOMER ISSUE	-
FAS_03964	02322	N	N	N	1	CUSTOMER ISSUE	-
FAS_03966	02323	N	N	N	1	CUSTOMER ISSUE	-
FAS_03967	02324	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03968	02325	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03969	02326	N	N	N	1	CUSTOMER ISSUE	-
FAS_03970	02327	N	N	N	1	CUSTOMER ISSUE	-
FAS_03971	02328	Y	N	N	1	CUSTOMER ISSUE	-
FAS_03973	02329	N	N	N	1	CUSTOMER ISSUE	-
FAS_03974	02330	N	N	N	1	CUSTOMER ISSUE	-
FAS_03975	02331	N	N	N	1	CUSTOMER ISSUE	-
FAS_03976	02332	N	N	N	1	CUSTOMER ISSUE	-
FAS_03977	02333	N	N	N	1	CUSTOMER ISSUE	-
FAS_03978	02334	N	N	N	1	CUSTOMER ISSUE	-
FAS_03979	02335	N	N	N	1	CUSTOMER ISSUE	-
FAS_03981	02336	N	N	N	1	CUSTOMER ISSUE	-
FAS_03982	02337	N	N	N	2	CUSTOMER ISSUE	-
FAS_03983	02338	N	N	N	1	CUSTOMER ISSUE	-
FAS_03985	02339	N	N	N	1	CUSTOMER ISSUE	-
FAS_03986	02340	N	N	N	1	CUSTOMER ISSUE	-
FAS_03987	02341	N	N	N	1	CUSTOMER ISSUE	-
FAS_03988	02342	N	N	N	1	CUSTOMER ISSUE	-
FAS_03989	02343	N	N	N	1	CUSTOMER ISSUE	-
FAS_03990	02344	N	N	N	1	CUSTOMER ISSUE	-
FAS_03991	02345	N	N	N	1	CUSTOMER ISSUE	-
FAS_03992	02346	N	N	N	1	CUSTOMER ISSUE	-
FAS_03993	02347	N	N	N	1	CUSTOMER ISSUE	-
FAS_03994	02348	N	N	N	1	CUSTOMER ISSUE	-
FAS_03995	02349	N	N	N	1	CUSTOMER ISSUE	-
FAS_03996	02350	N	N	N	1	CUSTOMER ISSUE	-
FAS_03997	02351	N	N	N	1	CUSTOMER ISSUE	-
FAS_03998	02352	N	N	N	1	CUSTOMER ISSUE	-
FAS_03999	02353	N	N	N	1	CUSTOMER ISSUE	-
FAS_04000	02354	N	N	N	1	CUSTOMER ISSUE	-
FAS_04001	02355	N	N	N	1	CUSTOMER ISSUE	-
FAS_04002	02356	N	N	N	1	CUSTOMER ISSUE	-
FAS_04003	02357	N	N	N	1	CUSTOMER ISSUE	-
FAS_04004	02358	N	N	N	1	CUSTOMER ISSUE	-
FAS_04005	02359	N	N	N	1	CUSTOMER ISSUE	-
FAS_04006	02360	N	N	N	1	CUSTOMER ISSUE	-
FAS_04007	02361	N	N	N	1	CUSTOMER ISSUE	-
FAS_04008	02362	N	N	N	1	CUSTOMER ISSUE	-
FAS_04010	02363	N	N	N	32	CUSTOMER ISSUE	-
FAS_04011	02364	N	N	N	1	CUSTOMER ISSUE	-
FAS_04012	02365	N	N	N	1	CUSTOMER ISSUE	-
FAS_04013	02366	N	N	N	1	CUSTOMER ISSUE	-
FAS_04014	02367	N	N	N	1	CUSTOMER ISSUE	-
FAS_04015	02368	N	N	N	1	CUSTOMER ISSUE	-
FAS_04017	02369	N	N	N	1	CUSTOMER ISSUE	-
FAS_04019	02370	N	N	N	1	CUSTOMER ISSUE	-
FAS_04020	02371	N	N	N	1	CUSTOMER ISSUE	-
FAS_04021	02372	N	N	N	1	CUSTOMER ISSUE	-
FAS_04022	02373	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04023	02374	N	N	N	1	CUSTOMER ISSUE	-
FAS_04024	02375	N	N	N	1	CUSTOMER ISSUE	-
FAS_04025	02376	N	N	N	1	CUSTOMER ISSUE	-

FAS_04026	02377	N	N	N	1	CUSTOMER ISSUE	-
FAS_04027	02378	N	N	N	1	CUSTOMER ISSUE	-
FAS_04028	02379	N	N	N	1	CUSTOMER ISSUE	-
FAS_04029	02380	N	N	N	1	CUSTOMER ISSUE	-
FAS_04030	02381	N	N	N	1	CUSTOMER ISSUE	-
FAS_04031	02382	N	N	N	1	CUSTOMER ISSUE	-
FAS_04032	02383	N	N	N	1	CUSTOMER ISSUE	-
FAS_04033	02384	N	N	N	1	CUSTOMER ISSUE	-
FAS_04034	02385	N	N	N	1	CUSTOMER ISSUE	-
FAS_04035	02386	N	N	N	1	CUSTOMER ISSUE	-
FAS_04036	02387	N	N	N	1	CUSTOMER ISSUE	-
FAS_04037	02388	N	N	N	1	CUSTOMER ISSUE	-
FAS_04038	02389	N	N	N	1	CUSTOMER ISSUE	-
FAS_04039	02390	N	N	N	1	CUSTOMER ISSUE	-
FAS_04040	02391	N	N	N	1	CUSTOMER ISSUE	-
FAS_04041	02392	N	N	N	1	CUSTOMER ISSUE	-
FAS_04042	02393	N	N	N	1	CUSTOMER ISSUE	-
FAS_04043	02394	N	N	N	1	CUSTOMER ISSUE	-
FAS_04044	02395	N	N	N	1	CUSTOMER ISSUE	-
FAS_04045	02396	N	N	N	2	CUSTOMER ISSUE	-
FAS_04046	02397	N	N	N	1	CUSTOMER ISSUE	-
FAS_04047	02398	N	N	N	1	CUSTOMER ISSUE	-
FAS_04048	02399	N	N	N	1	CUSTOMER ISSUE	-
FAS_04049	02400	N	N	N	1	CUSTOMER ISSUE	-
FAS_04050	02401	N	N	N	1	CUSTOMER ISSUE	-
FAS_04051	02402	N	N	N	1	CUSTOMER ISSUE	-
FAS_04053	02403	N	N	N	1	CUSTOMER ISSUE	-
FAS_04054	02404	N	N	N	1	CUSTOMER ISSUE	-
FAS_04055	02405	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_04056	02406	N	N	N	1	CUSTOMER ISSUE	-
FAS_04059	02407	N	N	N	3	CUSTOMER ISSUE	-
FAS_04062	02408	N	N	N	1	CUSTOMER ISSUE	-
FAS_04063	02409	N	N	N	2	CUSTOMER ISSUE	-
FAS_04064	02410	N	N	N	1	CUSTOMER ISSUE	-
FAS_04065	02411	N	N	N	1	CUSTOMER ISSUE	-
FAS_04066	02412	N	N	N	1	CUSTOMER ISSUE	-
FAS_04067	02413	N	N	N	1	CUSTOMER ISSUE	-
FAS_04068	02414	N	N	N	1	CUSTOMER ISSUE	-
FAS_04069	02415	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04070	02416	N	N	N	1	CUSTOMER ISSUE	-
FAS_04071	02417	N	N	N	5	CUSTOMER ISSUE	-
FAS_04072	02418	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04073	02419	N	N	N	1	CUSTOMER ISSUE	-
FAS_04074	02420	N	N	N	1	CUSTOMER ISSUE	-
FAS_04075	02421	N	N	N	1	CUSTOMER ISSUE	-
FAS_04076	02422	N	N	N	1	CUSTOMER ISSUE	-
FAS_04078	02423	N	N	N	1	CUSTOMER ISSUE	-
FAS_04079	02424	N	N	N	1	CUSTOMER ISSUE	-
FAS_04081	02425	N	N	N	1	CUSTOMER ISSUE	-
FAS_04082	02426	N	N	N	1	CUSTOMER ISSUE	-
FAS_04083	02427	N	N	N	1	CUSTOMER ISSUE	-
FAS_04084	02428	N	N	N	1	CUSTOMER ISSUE	-
FAS_04085	02429	N	N	N	2	CUSTOMER ISSUE	-
FAS_04086	02430	N	N	N	1	CUSTOMER ISSUE	-
FAS_04087	02431	N	N	N	1	CUSTOMER ISSUE	-
FAS_04088	02432	N	N	N	1	CUSTOMER ISSUE	-
FAS_04089	02433	N	N	N	1	CUSTOMER ISSUE	-
FAS_04090	02434	N	N	N	1	CUSTOMER ISSUE	-
FAS_04092	02435	N	N	N	1	CUSTOMER ISSUE	-
FAS_04093	02436	N	N	N	1	CUSTOMER ISSUE	-
FAS_04094	02437	N	N	N	1	CUSTOMER ISSUE	-
FAS_04096	02438	N	N	N	1	CUSTOMER ISSUE	-
FAS_04097	02439	N	N	N	1	CUSTOMER ISSUE	-
FAS_04098	02440	N	N	N	1	CUSTOMER ISSUE	-
FAS_04099	02441	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04100	02442	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04101	02443	N	N	N	1	CUSTOMER ISSUE	-
FAS_04102	02444	N	N	N	1	CUSTOMER ISSUE	-
FAS_04103	02445	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04104	02446	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04105	02447	N	N	N	1	CUSTOMER ISSUE	-
FAS_04106	02448	N	N	N	1	CUSTOMER ISSUE	-
FAS_04107	02449	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04108	02450	N	N	N	1	CUSTOMER ISSUE	-
FAS_04109	02451	N	N	N	1	CUSTOMER ISSUE	-
FAS_04110	02452	N	N	N	1	CUSTOMER ISSUE	-
FAS_04111	02453	N	N	N	1	CUSTOMER ISSUE	-
FAS_04112	02454	N	N	N	1	CUSTOMER ISSUE	-
FAS_04114	02455	N	N	N	1	CUSTOMER ISSUE	-
FAS_04115	02456	N	N	N	1	CUSTOMER ISSUE	-

FAS_04116	02457	N	N	N	1	CUSTOMER ISSUE	-
FAS_04119	02458	N	N	N	1	CUSTOMER ISSUE	-
FAS_04120	02459	N	N	N	1	CUSTOMER ISSUE	-
FAS_04121	02460	N	N	N	1	CUSTOMER ISSUE	-
FAS_04126	02461	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04127	02462	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04128	02463	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04129	02464	N	N	N	1	CUSTOMER ISSUE	-
FAS_04130	02465	N	N	N	1	CUSTOMER ISSUE	-
FAS_04132	02466	N	N	N	1	CUSTOMER ISSUE	-
FAS_04133	02467	N	N	N	1	CUSTOMER ISSUE	-
FAS_04134	02468	N	N	N	1	CUSTOMER ISSUE	-
FAS_04135	02469	N	N	N	1	CUSTOMER ISSUE	-
FAS_04136	02470	N	N	N	1	CUSTOMER ISSUE	-
FAS_04137	02471	N	N	N	1	CUSTOMER ISSUE	-
FAS_04138	02472	N	N	N	1	CUSTOMER ISSUE	-
FAS_04139	02473	N	N	N	1	CUSTOMER ISSUE	-
FAS_04140	02474	N	N	N	1	CUSTOMER ISSUE	-
FAS_04141	02475	N	N	N	1	CUSTOMER ISSUE	-
FAS_04143	02476	N	N	N	1	CUSTOMER ISSUE	-
FAS_04145	02477	N	N	N	1	CUSTOMER ISSUE	-
FAS_04146	02478	N	N	N	1	CUSTOMER ISSUE	-
FAS_04147	02479	N	N	N	2	CUSTOMER ISSUE	-
FAS_04148	02480	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04149	02481	N	N	N	8	CUSTOMER ISSUE	-
FAS_04151	02482	N	N	N	1	CUSTOMER ISSUE	-
FAS_04154	02483	N	N	N	4	CUSTOMER ISSUE	-
FAS_04155	02484	N	N	N	1	CUSTOMER ISSUE	-
FAS_04156	02485	N	N	N	1	CUSTOMER ISSUE	-
FAS_04157	02486	N	N	N	1	CUSTOMER ISSUE	-
FAS_04158	02487	N	N	N	1	CUSTOMER ISSUE	-
FAS_04159	02488	N	N	N	1	CUSTOMER ISSUE	-
FAS_04160	02489	N	N	N	1	CUSTOMER ISSUE	-
FAS_04161	02490	N	N	N	1	CUSTOMER ISSUE	-
FAS_04162	02491	N	N	N	1	CUSTOMER ISSUE	-
FAS_04163	02492	N	N	N	1	CUSTOMER ISSUE	-
FAS_04164	02493	N	N	N	5	CUSTOMER ISSUE	-
FAS_04165	02494	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04166	02495	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04167	02496	N	N	N	1	CUSTOMER ISSUE	-
FAS_04168	02497	N	N	N	1	CUSTOMER ISSUE	-
FAS_04169	02498	N	N	N	1	CUSTOMER ISSUE	-
FAS_04170	02499	N	N	N	1	CUSTOMER ISSUE	-
FAS_04171	02500	N	N	N	1	CUSTOMER ISSUE	-
FAS_04172	02501	N	N	N	2	CUSTOMER ISSUE	-
FAS_04173	02502	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04174	02503	N	N	N	1	CUSTOMER ISSUE	-
FAS_04175	02504	N	N	N	1	CUSTOMER ISSUE	-
FAS_04176	02505	N	N	N	1	CUSTOMER ISSUE	-
FAS_04177	02506	N	N	N	1	CUSTOMER ISSUE	-
FAS_04178	02507	N	N	N	2	CUSTOMER ISSUE	-
FAS_04179	02508	N	N	N	1	CUSTOMER ISSUE	-
FAS_04180	02509	N	N	N	1	CUSTOMER ISSUE	-
FAS_04181	02510	N	N	N	1	CUSTOMER ISSUE	-
FAS_04182	02511	N	N	N	1	CUSTOMER ISSUE	-
FAS_04183	02512	N	N	N	1	CUSTOMER ISSUE	-
FAS_04184	02513	N	N	N	1	CUSTOMER ISSUE	-
FAS_04185	02514	N	N	N	1	CUSTOMER ISSUE	-
FAS_04186	02515	N	N	N	1	CUSTOMER ISSUE	-
FAS_04187	02516	N	N	N	1	CUSTOMER ISSUE	-
FAS_04188	02517	N	N	N	1	CUSTOMER ISSUE	-
FAS_04189	02518	N	N	N	1	CUSTOMER ISSUE	-
FAS_04190	02519	N	N	N	1	CUSTOMER ISSUE	-
FAS_04191	02520	N	N	N	1	CUSTOMER ISSUE	-
FAS_04192	02521	N	N	N	2	CUSTOMER ISSUE	-
FAS_04194	02522	N	N	N	1	CUSTOMER ISSUE	-
FAS_04197	02523	N	N	N	1	CUSTOMER ISSUE	-
FAS_04202	02524	N	N	N	1	CUSTOMER ISSUE	-
FAS_04203	02525	N	N	N	1	CUSTOMER ISSUE	-
FAS_04204	02526	N	N	N	1	CUSTOMER ISSUE	-
FAS_04205	02527	N	N	N	1	CUSTOMER ISSUE	-
FAS_04207	02528	N	N	N	2	CUSTOMER ISSUE	-
FAS_04208	02529	N	N	N	1	CUSTOMER ISSUE	-
FAS_04209	02530	N	N	N	1	CUSTOMER ISSUE	-
FAS_04210	02531	N	N	N	1	CUSTOMER ISSUE	-
FAS_04211	02532	N	N	N	1	CUSTOMER ISSUE	-
FAS_04212	02533	N	N	N	1	CUSTOMER ISSUE	-
FAS_04213	02534	N	N	N	1	CUSTOMER ISSUE	-
FAS_04214	02535	N	N	N	1	CUSTOMER ISSUE	-
FAS_04215	02536	N	N	N	1	CUSTOMER ISSUE	-

FAS_04216	02537	N	N	N	1	CUSTOMER ISSUE	-
FAS_04217	02538	N	N	N	1	CUSTOMER ISSUE	-
FAS_04218	02539	N	N	N	1	CUSTOMER ISSUE	-
FAS_04219	02540	N	N	N	1	CUSTOMER ISSUE	-
FAS_04220	02541	N	N	N	1	CUSTOMER ISSUE	-
FAS_04221	02542	N	N	N	1	CUSTOMER ISSUE	-
FAS_04222	02543	N	N	N	1	CUSTOMER ISSUE	-
FAS_04223	02544	N	N	N	1	CUSTOMER ISSUE	-
FAS_04224	02545	N	N	N	1	CUSTOMER ISSUE	-
FAS_04225	02546	N	N	N	1	CUSTOMER ISSUE	-
FAS_04227	02547	N	N	N	1	CUSTOMER ISSUE	-
FAS_04228	02548	N	N	N	1	CUSTOMER ISSUE	-
FAS_04229	02549	N	N	N	1	CUSTOMER ISSUE	-
FAS_04230	02550	N	N	N	1	CUSTOMER ISSUE	-
FAS_04231	02551	N	N	N	1	CUSTOMER ISSUE	-
FAS_04232	02552	N	N	N	1	CUSTOMER ISSUE	-
FAS_04233	02553	N	N	N	1	CUSTOMER ISSUE	-
FAS_04234	02554	N	N	N	1	CUSTOMER ISSUE	-
FAS_04240	02555	N	N	N	1	CUSTOMER ISSUE	-
FAS_04243	02556	N	N	N	1	CUSTOMER ISSUE	-
FAS_04245	02557	N	N	N	1	CUSTOMER ISSUE	-
FAS_04246	02558	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04247	02559	N	N	N	1	CUSTOMER ISSUE	-
FAS_04248	02560	N	N	N	1	CUSTOMER ISSUE	-
FAS_04249	02561	N	N	N	1	CUSTOMER ISSUE	-
FAS_04250	02562	N	N	N	1	CUSTOMER ISSUE	-
FAS_04251	02563	N	N	N	1	CUSTOMER ISSUE	-
FAS_04252	02564	N	N	N	1	CUSTOMER ISSUE	-
FAS_04254	02565	N	N	N	1	CUSTOMER ISSUE	-
FAS_04256	02566	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04257	02567	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04261	02568	N	N	N	1	CUSTOMER ISSUE	-
FAS_04262	02569	N	N	N	1	CUSTOMER ISSUE	-
FAS_04264	02570	N	N	N	1	CUSTOMER ISSUE	-
FAS_04265	02571	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04266	02572	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04267	02573	N	N	N	1	CUSTOMER ISSUE	-
FAS_04268	02574	N	N	N	1	CUSTOMER ISSUE	-
FAS_04270	02575	N	N	N	1	CUSTOMER ISSUE	-
FAS_04274	02576	N	N	N	1	CUSTOMER ISSUE	-
FAS_04275	02577	N	N	N	1	CUSTOMER ISSUE	-
FAS_04276	02578	N	N	N	1	CUSTOMER ISSUE	-
FAS_04277	02579	N	N	N	1	CUSTOMER ISSUE	-
FAS_04278	02580	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04279	02581	N	N	N	1	CUSTOMER ISSUE	-
FAS_04281	02582	N	N	N	1	CUSTOMER ISSUE	-
FAS_04282	02583	N	N	N	2	CUSTOMER ISSUE	-
FAS_04283	02584	N	N	N	1	CUSTOMER ISSUE	-
FAS_04288	02585	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04289	02586	N	N	N	1	CUSTOMER ISSUE	-
FAS_04290	02587	N	N	N	1	CUSTOMER ISSUE	-
FAS_04291	02588	N	N	N	1	CUSTOMER ISSUE	-
FAS_04292	02589	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04293	02590	N	N	N	1	CUSTOMER ISSUE	-
FAS_04294	02591	N	N	N	1	CUSTOMER ISSUE	-
FAS_04295	02592	N	N	N	1	CUSTOMER ISSUE	-
FAS_04296	02593	N	N	N	1	CUSTOMER ISSUE	-
FAS_04297	02594	N	N	N	2	CUSTOMER ISSUE	-
FAS_04298	02595	N	N	N	1	CUSTOMER ISSUE	-
FAS_04300	02596	N	N	N	1	CUSTOMER ISSUE	-
FAS_04302	02597	N	N	N	1	CUSTOMER ISSUE	-
FAS_04304	02598	N	N	N	1	CUSTOMER ISSUE	-
FAS_04305	02599	N	N	N	1	CUSTOMER ISSUE	-
FAS_04307	02600	N	N	N	1	CUSTOMER ISSUE	-
FAS_04308	02601	N	N	N	1	CUSTOMER ISSUE	-
FAS_04309	02602	N	N	N	1	CUSTOMER ISSUE	-
FAS_04310	02603	N	N	N	1	CUSTOMER ISSUE	-
FAS_04311	02604	N	N	N	1	CUSTOMER ISSUE	-
FAS_04312	02605	N	N	N	1	CUSTOMER ISSUE	-
FAS_04313	02606	N	N	N	1	CUSTOMER ISSUE	-
FAS_04316	02607	N	N	N	1	CUSTOMER ISSUE	-
FAS_04317	02608	N	N	N	1	CUSTOMER ISSUE	-
FAS_04318	02609	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04319	02610	N	N	N	1	CUSTOMER ISSUE	-
FAS_04320	02611	N	N	N	1	CUSTOMER ISSUE	-
FAS_04321	02612	N	N	N	1	CUSTOMER ISSUE	-
FAS_04322	02613	N	N	N	1	CUSTOMER ISSUE	-
FAS_04323	02614	N	N	N	1	CUSTOMER ISSUE	-
FAS_04324	02615	N	N	N	1	CUSTOMER ISSUE	-
FAS_04325	02616	N	N	N	1	CUSTOMER ISSUE	-

FAS_04326	02617	N	N	N	1	CUSTOMER ISSUE	-
FAS_04330	02618	N	N	N	2	CUSTOMER ISSUE	-
FAS_04331	02619	N	N	N	1	CUSTOMER ISSUE	-
FAS_04332	02620	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04336	02621	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04337	02622	N	N	N	1	CUSTOMER ISSUE	-
FAS_04338	02623	N	N	N	1	CUSTOMER ISSUE	-
FAS_04341	02624	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_04343	02625	N	N	N	1	CUSTOMER ISSUE	-
FAS_04344	02626	N	N	N	1	CUSTOMER ISSUE	-
FAS_04345	02627	N	N	N	1	CUSTOMER ISSUE	-
FAS_04346	02628	N	N	N	1	CUSTOMER ISSUE	-
FAS_04347	02629	N	N	N	1	CUSTOMER ISSUE	-
FAS_04348	02630	N	N	N	1	CUSTOMER ISSUE	-
FAS_04349	02631	N	N	N	1	CUSTOMER ISSUE	-
FAS_04351	02632	N	N	N	1	CUSTOMER ISSUE	-
FAS_04352	02633	N	N	N	1	CUSTOMER ISSUE	-
FAS_04353	02634	N	N	N	1	CUSTOMER ISSUE	-
FAS_04354	02635	N	N	N	1	CUSTOMER ISSUE	-
FAS_04355	02636	N	N	N	1	CUSTOMER ISSUE	-
FAS_04356	02637	N	N	N	1	CUSTOMER ISSUE	-
FAS_04357	02638	N	N	N	1	CUSTOMER ISSUE	-
FAS_04358	02639	N	N	N	1	CUSTOMER ISSUE	-
FAS_04360	02640	N	N	N	1	CUSTOMER ISSUE	-
FAS_04361	02641	N	N	N	1	CUSTOMER ISSUE	-
FAS_04362	02642	N	N	N	1	CUSTOMER ISSUE	-
FAS_04363	02643	N	N	N	1	CUSTOMER ISSUE	-
FAS_04368	02644	N	N	N	1	CUSTOMER ISSUE	-
FAS_04372	02645	N	N	N	1	CUSTOMER ISSUE	-
FAS_04373	02646	N	N	N	1	CUSTOMER ISSUE	-
FAS_04374	02647	N	N	N	5	CUSTOMER ISSUE	-
FAS_04375	02648	N	N	N	2	CUSTOMER ISSUE	-
FAS_04376	02649	N	N	N	1	CUSTOMER ISSUE	-
FAS_04377	02650	N	N	N	1	CUSTOMER ISSUE	-
FAS_04382	02651	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04383	02652	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04384	02653	N	N	N	1	CUSTOMER ISSUE	-
FAS_04385	02654	N	N	N	1	CUSTOMER ISSUE	-
FAS_04386	02655	N	N	N	1	CUSTOMER ISSUE	-
FAS_04387	02656	N	N	N	1	CUSTOMER ISSUE	-
FAS_04388	02657	N	N	N	2	CUSTOMER ISSUE	-
FAS_04389	02658	N	N	N	1	CUSTOMER ISSUE	-
FAS_04390	02659	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04391	02660	N	N	N	1	CUSTOMER ISSUE	-
FAS_04392	02661	N	N	N	22	CUSTOMER ISSUE	-
FAS_04393	02662	N	N	N	1	CUSTOMER ISSUE	-
FAS_04394	02663	N	N	N	1	CUSTOMER ISSUE	-
FAS_04395	02664	N	N	N	1	CUSTOMER ISSUE	-
FAS_04396	02665	N	N	N	1	CUSTOMER ISSUE	-
FAS_04397	02666	N	N	N	1	CUSTOMER ISSUE	-
FAS_04398	02667	N	N	N	1	CUSTOMER ISSUE	-
FAS_04399	02668	N	N	N	1	CUSTOMER ISSUE	-
FAS_04400	02669	N	N	N	1	CUSTOMER ISSUE	-
FAS_04401	02670	N	N	N	1	CUSTOMER ISSUE	-
FAS_04402	02671	N	N	N	1	CUSTOMER ISSUE	-
FAS_04408	02672	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04409	02673	N	N	N	1	CUSTOMER ISSUE	-
FAS_04410	02674	N	N	N	1	CUSTOMER ISSUE	-
FAS_04411	02675	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04412	02676	N	N	N	1	CUSTOMER ISSUE	-
FAS_04413	02677	N	N	N	1	CUSTOMER ISSUE	-
FAS_04414	02678	N	N	N	1	CUSTOMER ISSUE	-
FAS_04417	02679	N	N	N	1	CUSTOMER ISSUE	-
FAS_04418	02680	N	N	N	1	CUSTOMER ISSUE	-
FAS_04419	02681	N	N	N	1	CUSTOMER ISSUE	-
FAS_04420	02682	N	N	N	1	CUSTOMER ISSUE	-
FAS_04421	02683	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04422	02684	N	N	N	1	CUSTOMER ISSUE	-
FAS_04423	02685	N	N	N	1	CUSTOMER ISSUE	-
FAS_04424	02686	N	N	N	1	CUSTOMER ISSUE	-
FAS_04425	02687	N	N	N	1	CUSTOMER ISSUE	-
FAS_04426	02688	N	N	N	1	CUSTOMER ISSUE	-
FAS_04429	02689	N	N	N	1	CUSTOMER ISSUE	-
FAS_04430	02690	N	N	N	1	CUSTOMER ISSUE	-
FAS_04431	02691	N	N	N	1	CUSTOMER ISSUE	-
FAS_04433	02692	N	N	N	1	CUSTOMER ISSUE	-
FAS_04434	02693	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_04436	02694	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04437	02695	N	N	N	1	CUSTOMER ISSUE	-
FAS_04438	02696	N	N	N	1	CUSTOMER ISSUE	-

FAS_04440	02697	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04441	02698	N	N	N	1	CUSTOMER ISSUE	-
FAS_04442	02699	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04443	02700	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04444	02701	N	N	N	1	CUSTOMER ISSUE	-
FAS_04445	02702	N	N	N	2	CUSTOMER ISSUE	-
FAS_04446	02703	N	N	N	1	CUSTOMER ISSUE	-
FAS_04447	02704	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04448	02705	N	N	N	1	CUSTOMER ISSUE	-
FAS_04449	02706	N	N	N	1	CUSTOMER ISSUE	-
FAS_04451	02707	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04452	02708	N	N	N	1	CUSTOMER ISSUE	-
FAS_04453	02709	N	N	N	1	CUSTOMER ISSUE	-
FAS_04454	02710	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04455	02711	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04456	02712	N	N	N	1	CUSTOMER ISSUE	-
FAS_04457	02713	N	N	N	1	CUSTOMER ISSUE	-
FAS_04458	02714	N	N	N	1	CUSTOMER ISSUE	-
FAS_04459	02715	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04460	02716	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04461	02717	N	N	N	1	CUSTOMER ISSUE	-
FAS_04462	02718	N	N	N	1	CUSTOMER ISSUE	-
FAS_04463	02719	N	N	N	1	CUSTOMER ISSUE	-
FAS_04464	02720	N	N	N	1	CUSTOMER ISSUE	-
FAS_04465	02721	N	N	N	1	CUSTOMER ISSUE	-
FAS_04467	02722	N	N	N	1	CUSTOMER ISSUE	-
FAS_04468	02723	N	N	N	1	CUSTOMER ISSUE	-
FAS_04469	02724	N	N	N	1	CUSTOMER ISSUE	-
FAS_04470	02725	N	N	N	1	CUSTOMER ISSUE	-
FAS_04472	02726	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04473	02727	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04474	02728	N	N	N	1	CUSTOMER ISSUE	-
FAS_04475	02729	N	N	N	1	CUSTOMER ISSUE	-
FAS_04476	02730	N	N	N	2	CUSTOMER ISSUE	-
FAS_04477	02731	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04478	02732	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_04480	02733	N	N	N	1	CUSTOMER ISSUE	-
FAS_04481	02734	N	N	N	1	CUSTOMER ISSUE	-
FAS_04483	02735	N	N	N	2	CUSTOMER ISSUE	-
FAS_04485	02736	N	N	N	1	CUSTOMER ISSUE	-
FAS_04486	02737	N	N	N	1	CUSTOMER ISSUE	-
FAS_04487	02738	N	N	N	1	CUSTOMER ISSUE	-
FAS_04488	02739	N	N	N	1	CUSTOMER ISSUE	-
FAS_04490	02740	N	N	Y	9	DIST - TREE TRIMMING	945
FAS_04492	02741	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_04493	02742	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_04494	02743	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_04495	02744	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_04498	02745	N	N	N	1	CUSTOMER ISSUE	-
FAS_04499	02746	N	N	N	1	CUSTOMER ISSUE	-
FAS_04501	02747	N	N	N	1	CUSTOMER ISSUE	-
FAS_04502	02748	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04503	02749	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_04504	02750	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_04509	02751	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04510	02752	N	N	N	1	CUSTOMER ISSUE	-
FAS_04511	02753	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04512	02754	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_04513	02755	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_04514	02756	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_04515	02757	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_04516	02758	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_04517	02759	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04519	02760	N	N	N	1	CUSTOMER ISSUE	-
FAS_04520	02761	N	N	N	1	CUSTOMER ISSUE	-
FAS_04521	02762	N	N	N	1	CUSTOMER ISSUE	-
FAS_04526	02763	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_04527	02764	N	N	N	1	CUSTOMER ISSUE	-
FAS_04528	02765	N	N	Y	1	TX - REPLACE	2500
FAS_04530	02766	N	N	N	1	CUSTOMER ISSUE	-
FAS_04534	02767	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04535	02768	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04536	02769	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04538	02770	N	N	N	1	CUSTOMER ISSUE	-
FAS_04539	02771	N	N	N	1	CUSTOMER ISSUE	-
FAS_04540	02772	N	N	N	1	CUSTOMER ISSUE	-
FAS_04541	02773	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04542	02774	N	N	N	1	CUSTOMER ISSUE	-
FAS_04543	02775	N	N	N	1	CUSTOMER ISSUE	-
FAS_04544	02776	N	N	N	1	CUSTOMER ISSUE	-

FAS_04546	02777	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04547	02778	N	N	N	1	CUSTOMER ISSUE	-
FAS_04548	02779	N	N	N	1	CUSTOMER ISSUE	-
FAS_04549	02780	N	N	N	1	CUSTOMER ISSUE	-
FAS_04550	02781	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04551	02782	N	N	N	1	CUSTOMER ISSUE	-
FAS_04558	02783	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04559	02784	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04563	02785	N	N	N	1	CUSTOMER ISSUE	-
FAS_04565	02786	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04566	02787	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04567	02788	N	N	N	1	CUSTOMER ISSUE	-
FAS_04568	02789	N	N	N	1	CUSTOMER ISSUE	-
FAS_04569	02790	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04570	02791	N	N	N	1	CUSTOMER ISSUE	-
FAS_04571	02792	N	N	N	1	CUSTOMER ISSUE	-
FAS_04572	02793	N	N	N	1	CUSTOMER ISSUE	-
FAS_04576	02794	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04577	02795	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04578	02796	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_04587	02797	N	N	N	1	CUSTOMER ISSUE	-
FAS_04588	02798	Y	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_04589	02799	N	N	N	1	CUSTOMER ISSUE	-
FAS_04591	02800	N	N	N	1	CUSTOMER ISSUE	-
FAS_04592	02801	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04593	02802	N	N	N	1	CUSTOMER ISSUE	-
FAS_04595	02803	N	N	N	1	CUSTOMER ISSUE	-
FAS_04596	02804	N	N	N	1	CUSTOMER ISSUE	-
FAS_04597	02805	N	N	Y	1	TX - REPLACE	2500
FAS_04602	02806	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04604	02807	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04611	02808	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04613	02809	N	N	N	1	CUSTOMER ISSUE	-
FAS_04616	02810	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04618	02811	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04619	02812	N	N	N	1	CUSTOMER ISSUE	-
FAS_04620	02813	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04621	02814	N	N	N	1	CUSTOMER ISSUE	-
FAS_04622	02815	N	N	N	1	CUSTOMER ISSUE	-
FAS_04623	02816	N	N	N	1	CUSTOMER ISSUE	-
FAS_04624	02817	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04628	02818	N	N	N	2	CUSTOMER ISSUE	-
FAS_04629	02819	N	N	N	1	CUSTOMER ISSUE	-
FAS_04630	02820	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_04634	02821	N	N	N	1	CUSTOMER ISSUE	-
FAS_04635	02822	N	N	N	1	CUSTOMER ISSUE	-
FAS_04636	02823	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04638	02824	N	N	N	6	CUSTOMER ISSUE	-
FAS_04643	02825	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04644	02826	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04645	02827	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04646	02828	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04647	02829	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04649	02830	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04650	02831	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_04658	02832	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_04663	02833	N	N	N	1	CUSTOMER ISSUE	-
FAS_04665	02834	N	N	N	1	CUSTOMER ISSUE	-
FAS_04670	02835	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04675	02836	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04677	02837	N	N	N	1	CUSTOMER ISSUE	-
FAS_04690	02838	N	N	N	1	CUSTOMER ISSUE	-
FAS_04692	02839	N	N	N	1	CUSTOMER ISSUE	-
FAS_04694	02840	N	N	N	11	CUSTOMER ISSUE	-
FAS_04695	02841	N	N	N	1	CUSTOMER ISSUE	-
FAS_04697	02842	N	N	N	1	CUSTOMER ISSUE	-
FAS_04701	02843	N	N	N	13	CUSTOMER ISSUE	-
FAS_04706	02844	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_04708	02845	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04714	02846	N	N	N	1	CUSTOMER ISSUE	-
FAS_04715	02847	N	N	N	1	CUSTOMER ISSUE	-
FAS_04716	02848	N	N	N	1	CUSTOMER ISSUE	-
FAS_04719	02849	N	N	N	1	CUSTOMER ISSUE	-
FAS_04720	02850	N	N	N	1	CUSTOMER ISSUE	-
FAS_04721	02851	N	N	N	1	CUSTOMER ISSUE	-
FAS_04722	02852	N	N	N	6	CUSTOMER ISSUE	-
FAS_04724	02853	N	N	N	1	CUSTOMER ISSUE	-
FAS_04725	02854	N	N	Y	15	SEC/SVC - REPLACE	708.75
FAS_04726	02855	N	N	Y	15	SEC/SVC - REPLACE	708.75
FAS_04727	02856	Y	N	N	1	CUSTOMER ISSUE	-

FAS_04728	02857	N	N	N	1	CUSTOMER ISSUE	-
FAS_04730	02858	N	N	N	1	CUSTOMER ISSUE	-
FAS_04731	02859	N	N	N	16	CUSTOMER ISSUE	-
FAS_04733	02860	N	N	N	1	CUSTOMER ISSUE	-
FAS_04734	02861	N	N	N	1	CUSTOMER ISSUE	-
FAS_04736	02862	N	N	N	2	CUSTOMER ISSUE	-
FAS_04738	02863	N	N	N	1	CUSTOMER ISSUE	-
FAS_04739	02864	N	N	N	1	CUSTOMER ISSUE	-
FAS_04741	02865	N	N	N	1	CUSTOMER ISSUE	-
FAS_04742	02866	N	N	N	1	CUSTOMER ISSUE	-
FAS_04743	02867	N	N	N	1	CUSTOMER ISSUE	-
FAS_04744	02868	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04745	02869	N	N	N	1	CUSTOMER ISSUE	-
FAS_04746	02870	N	N	N	1	CUSTOMER ISSUE	-
FAS_04747	02871	N	N	N	1	CUSTOMER ISSUE	-
FAS_04751	02872	Y	N	N	2	CUSTOMER ISSUE	-
FAS_04753	02873	N	N	N	1	CUSTOMER ISSUE	-
FAS_04754	02874	N	N	N	1	CUSTOMER ISSUE	-
FAS_04755	02875	N	N	N	1	CUSTOMER ISSUE	-
FAS_04756	02876	N	N	N	1	CUSTOMER ISSUE	-
FAS_04757	02877	N	N	N	1	CUSTOMER ISSUE	-
FAS_04758	02878	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04759	02879	N	N	N	1	CUSTOMER ISSUE	-
FAS_04764	02880	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04765	02881	N	N	N	1	CUSTOMER ISSUE	-
FAS_04767	02882	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04769	02883	N	N	N	1	CUSTOMER ISSUE	-
FAS_04772	02884	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04773	02885	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04775	02886	N	N	Y	1	TX - REPLACE	2500
FAS_04778	02887	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
FAS_04782	02888	N	N	N	4	CUSTOMER ISSUE	-
FAS_04783	02889	N	N	N	1	CUSTOMER ISSUE	-
FAS_04788	02890	N	N	N	1	CUSTOMER ISSUE	-
FAS_04796	02891	N	N	N	1	CUSTOMER ISSUE	-
FAS_04800	02892	N	N	N	1	CUSTOMER ISSUE	-
FAS_04806	02893	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04809	02894	N	N	N	1	CUSTOMER ISSUE	-
FAS_04815	02895	N	N	Y	32	DIST - REPLACE FUSE	708.75
FAS_04816	02896	N	N	Y	32	DIST - REPLACE FUSE	708.75
FAS_04817	02897	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_04818	02898	N	N	Y	32	DIST - REPLACE FUSE	708.75
FAS_04819	02899	N	N	N	1	CUSTOMER ISSUE	-
FAS_04820	02900	N	N	N	2	CUSTOMER ISSUE	-
FAS_04821	02901	N	N	N	1	CUSTOMER ISSUE	-
FAS_04825	02902	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04829	02903	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04830	02904	N	N	N	1	CUSTOMER ISSUE	-
FAS_04831	02905	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_04832	02906	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04833	02907	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04834	02908	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04836	02909	N	N	N	1	CUSTOMER ISSUE	-
FAS_04841	02910	N	N	Y	4	DIST - REPLACE FUSE	708.75
FAS_04842	02911	N	N	N	3	CUSTOMER ISSUE	-
FAS_04843	02912	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04844	02913	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_04847	02914	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04848	02915	N	N	N	1	CUSTOMER ISSUE	-
FAS_04850	02916	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_04851	02917	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04852	02918	Y	N	Y	1	TX - REPLACE	2500
FAS_04853	02919	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04854	02920	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_04855	02921	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04856	02922	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04857	02923	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04867	02924	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04887	02925	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04888	02926	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04889	02927	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04890	02928	N	N	Y	1	TX - REPLACE	2500
FAS_04893	02929	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_04894	02930	N	N	Y	1	TX - REPLACE	2500
FAS_04896	02931	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04897	02932	N	N	Y	1	TX - REPLACE	2500
FAS_04898	02933	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04899	02934	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_04911	02935	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04912	02936	N	N	Y	1	TX - REPLACE	2500

FAS_04915	02937	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04916	02938	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04918	02939	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04919	02940	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04920	02941	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04921	02942	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04922	02943	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04923	02944	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04924	02945	N	N	Y	1	TX - REPLACE	2500
FAS_04925	02946	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_04927	02947	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04929	02948	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04930	02949	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04931	02950	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04932	02951	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04933	02952	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04934	02953	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04936	02954	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04939	02955	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04942	02956	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04955	02957	N	N	Y	1	TX - REPLACE	2500
FAS_04960	02958	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04961	02959	N	N	Y	1	TX - REPLACE	2500
FAS_04964	02960	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04965	02961	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04966	02962	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04967	02963	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04968	02964	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04970	02965	N	N	Y	1	TX - REPLACE	2500
FAS_04973	02966	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04974	02967	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04975	02968	N	N	Y	1	TX - REPLACE	2500
FAS_04980	02969	N	N	Y	1	TX - REPLACE	2500
FAS_04981	02970	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04982	02971	N	N	N	1	CUSTOMER ISSUE	-
FAS_04983	02972	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_04985	02973	N	N	N	1	CUSTOMER ISSUE	-
FAS_04986	02974	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_04987	02975	N	N	N	1	CUSTOMER ISSUE	-
FAS_04989	02976	N	N	N	1	CUSTOMER ISSUE	-
FAS_04990	02977	N	N	N	1	CUSTOMER ISSUE	-
FAS_04992	02978	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04993	02979	N	N	N	1	CUSTOMER ISSUE	-
FAS_04995	02980	N	N	N	1	CUSTOMER ISSUE	-
FAS_04996	02981	N	N	N	1	CUSTOMER ISSUE	-
FAS_04997	02982	Y	N	N	1	CUSTOMER ISSUE	-
FAS_04998	02983	N	N	N	13	CUSTOMER ISSUE	-
FAS_04999	02984	N	N	N	1	CUSTOMER ISSUE	-
FAS_05000	02985	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05001	02986	N	N	N	1	CUSTOMER ISSUE	-
FAS_05002	02987	N	N	N	1	CUSTOMER ISSUE	-
FAS_05003	02988	N	N	N	1	CUSTOMER ISSUE	-
FAS_05004	02989	N	N	N	1	CUSTOMER ISSUE	-
FAS_05005	02990	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05007	02991	N	N	N	1	CUSTOMER ISSUE	-
FAS_05009	02992	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05010	02993	N	N	N	12	CUSTOMER ISSUE	-
FAS_05011	02994	N	N	N	1	CUSTOMER ISSUE	-
FAS_05012	02995	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05013	02996	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05014	02997	N	N	N	1	CUSTOMER ISSUE	-
FAS_05016	02998	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05017	02999	N	N	N	1	CUSTOMER ISSUE	-
FAS_05018	03000	N	N	N	1	CUSTOMER ISSUE	-
FAS_05021	03001	N	N	N	1	CUSTOMER ISSUE	-
FAS_05024	03002	N	N	N	1	CUSTOMER ISSUE	-
FAS_05026	03003	N	N	N	1	CUSTOMER ISSUE	-
FAS_05027	03004	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_05029	03005	N	N	Y	32	DIST - REPLACE FUSE	708.75
FAS_05030	03006	Y	N	N	4	CUSTOMER ISSUE	-
FAS_05033	03007	N	N	N	1	CUSTOMER ISSUE	-
FAS_05035	03008	N	N	Y	19	SEC/SVC - REPAIR	472.5
FAS_05045	03009	N	N	N	1	CUSTOMER ISSUE	-
FAS_05047	03010	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_05048	03011	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05060	03012	N	N	N	1	CUSTOMER ISSUE	-
FAS_05063	03013	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05069	03014	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05070	03015	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05071	03016	Y	N	Y	1	SEC/SVC - REPAIR	472.5

FAS_05072	03017	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05073	03018	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05074	03019	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05075	03020	N	N	N	1	CUSTOMER ISSUE	-
FAS_05076	03021	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05077	03022	N	N	N	1	CUSTOMER ISSUE	-
FAS_05078	03023	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05079	03024	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05092	03025	N	N	N	1	CUSTOMER ISSUE	-
FAS_05100	03026	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05101	03027	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05102	03028	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05103	03029	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05104	03030	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05105	03031	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_05106	03032	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05107	03033	N	N	Y	6	TX - REPLACE	2500
FAS_05108	03034	N	N	N	1	CUSTOMER ISSUE	-
FAS_05113	03035	N	N	N	1	CUSTOMER ISSUE	-
FAS_05114	03036	N	N	N	1	CUSTOMER ISSUE	-
FAS_05115	03037	N	N	N	1	CUSTOMER ISSUE	-
FAS_05116	03038	N	N	N	1	CUSTOMER ISSUE	-
FAS_05120	03039	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05121	03040	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05122	03041	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05124	03042	N	N	N	2	CUSTOMER ISSUE	-
FAS_05126	03043	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05133	03044	N	N	Y	2	TX/SEC/SVC- REPLACE	3800
FAS_05134	03045	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05137	03046	N	N	N	1	CUSTOMER ISSUE	-
FAS_05139	03047	N	N	N	1	CUSTOMER ISSUE	-
FAS_05147	03048	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05158	03049	N	N	N	1	CUSTOMER ISSUE	-
FAS_05159	03050	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_05167	03051	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05172	03052	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05173	03053	N	N	N	1	CUSTOMER ISSUE	-
FAS_05179	03054	N	N	N	1	CUSTOMER ISSUE	-
FAS_05180	03055	N	N	N	1	CUSTOMER ISSUE	-
FAS_05181	03056	N	N	N	6	CUSTOMER ISSUE	-
FAS_05185	03057	N	N	N	1	CUSTOMER ISSUE	-
FAS_05187	03058	N	N	N	1	CUSTOMER ISSUE	-
FAS_05192	03059	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05194	03060	N	N	N	1	CUSTOMER ISSUE	-
FAS_05200	03061	N	N	N	1	CUSTOMER ISSUE	-
FAS_05201	03062	N	N	N	1	CUSTOMER ISSUE	-
FAS_05202	03063	N	N	N	1	CUSTOMER ISSUE	-
FAS_05203	03064	N	N	N	1	CUSTOMER ISSUE	-
FAS_05206	03065	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05207	03066	N	N	Y	1	TX - REPLACE	2500
FAS_05208	03067	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05211	03068	N	N	N	1	CUSTOMER ISSUE	-
FAS_05213	03069	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05214	03070	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05215	03071	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05216	03072	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05217	03073	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05218	03074	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05219	03075	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05220	03076	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05221	03077	N	N	N	1	CUSTOMER ISSUE	-
FAS_05223	03078	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05224	03079	N	N	Y	1	TX - REPLACE	2500
FAS_05225	03080	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05226	03081	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05227	03082	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05228	03083	N	N	Y	4	TX - REPLACE	2500
FAS_05229	03084	N	N	N	2	CUSTOMER ISSUE	-
FAS_05230	03085	N	N	Y	1	TX - REPLACE	2500
FAS_05231	03086	N	N	N	1	CUSTOMER ISSUE	-
FAS_05232	03087	N	N	N	1	CUSTOMER ISSUE	-
FAS_05234	03088	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05235	03089	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05236	03090	N	N	N	1	CUSTOMER ISSUE	-
FAS_05239	03091	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05240	03092	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05241	03093	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05243	03094	N	N	N	1	CUSTOMER ISSUE	-
FAS_05244	03095	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05245	03096	N	N	N	1	CUSTOMER ISSUE	-

FAS_05246	03097	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05247	03098	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05267	03099	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05272	03100	N	N	Y	8	SEC/SVC - REPAIR	472.5
FAS_05273	03101	N	N	Y	1	TX - REPLACE	2500
FAS_05278	03102	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05279	03103	N	N	N	1	CUSTOMER ISSUE	-
FAS_05281	03104	N	N	Y	1	TX - REPLACE	2500
FAS_05284	03105	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05285	03106	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05286	03107	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_05291	03108	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05292	03109	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05293	03110	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05294	03111	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05296	03112	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05297	03113	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05298	03114	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05299	03115	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05300	03116	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05301	03117	N	N	N	1	CUSTOMER ISSUE	-
FAS_05302	03118	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05303	03119	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05304	03120	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05305	03121	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05306	03122	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_05307	03123	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05309	03124	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05310	03125	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05311	03126	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05314	03127	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05322	03128	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_05327	03129	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05328	03130	N	N	N	1	CUSTOMER ISSUE	-
FAS_05329	03131	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05330	03132	N	N	N	1	CUSTOMER ISSUE	-
FAS_05331	03133	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05332	03134	N	N	N	1	CUSTOMER ISSUE	-
FAS_05333	03135	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05336	03136	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_05337	03137	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05338	03138	N	N	N	1	CUSTOMER ISSUE	-
FAS_05343	03139	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05344	03140	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05345	03141	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05346	03142	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05348	03143	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_05351	03144	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05352	03145	N	N	N	1	CUSTOMER ISSUE	-
FAS_05354	03146	N	N	N	1	CUSTOMER ISSUE	-
FAS_05355	03147	N	N	N	1	CUSTOMER ISSUE	-
FAS_05356	03148	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05357	03149	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05358	03150	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05359	03151	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05360	03152	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05361	03153	N	N	Y	7	SEC/SVC - REPLACE	708.75
FAS_05366	03154	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05369	03155	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05370	03156	N	N	Y	1	TX - REPLACE	2500
FAS_05372	03157	N	N	N	1	CUSTOMER ISSUE	-
FAS_05377	03158	N	N	N	1	CUSTOMER ISSUE	-
FAS_05382	03159	N	N	Y	1	TX - REPLACE	2500
FAS_05385	03160	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05386	03161	N	N	N	1	CUSTOMER ISSUE	-
FAS_05388	03162	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_05390	03163	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_05391	03164	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_05392	03165	N	N	N	1	CUSTOMER ISSUE	-
FAS_05395	03166	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05396	03167	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05402	03168	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05403	03169	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05404	03170	N	N	N	1	CUSTOMER ISSUE	-
FAS_05405	03171	N	N	N	1	CUSTOMER ISSUE	-
FAS_05406	03172	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05407	03173	N	N	N	1	CUSTOMER ISSUE	-
FAS_05408	03174	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05409	03175	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05410	03176	N	N	Y	1	DIST - REPLACE FUSE	708.75

FAS_05411	03177	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05412	03178	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05413	03179	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05414	03180	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05415	03181	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05416	03182	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05417	03183	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05418	03184	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05419	03185	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05420	03186	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05421	03187	N	N	N	1	CUSTOMER ISSUE	-
FAS_05424	03188	N	N	N	1	CUSTOMER ISSUE	-
FAS_05425	03189	N	N	N	1	CUSTOMER ISSUE	-
FAS_05426	03190	N	N	N	1	CUSTOMER ISSUE	-
FAS_05428	03191	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05429	03192	N	N	Y	7	DIST - REPLACE FUSE	708.75
FAS_05430	03193	N	N	N	1	CUSTOMER ISSUE	-
FAS_05432	03194	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_05433	03195	N	N	Y	2	DIST - REPLACE FUSE	708.75
FAS_05434	03196	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05435	03197	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05437	03198	N	N	N	1	CUSTOMER ISSUE	-
FAS_05438	03199	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05439	03200	N	N	Y	1	TX - REPLACE	2500
FAS_05440	03201	N	N	Y	2	TX/SEC/SVC- REPLACE	3800
FAS_05441	03202	N	N	N	1	CUSTOMER ISSUE	-
FAS_05442	03203	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05443	03204	N	N	Y	1	TX - REPLACE	2500
FAS_05445	03205	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_05446	03206	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05451	03207	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05452	03208	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05453	03209	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05454	03210	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05455	03211	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05459	03212	N	N	Y	2	DIST - REPLACE FUSE	708.75
FAS_05462	03213	N	N	N	1	CUSTOMER ISSUE	-
FAS_05465	03214	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05466	03215	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05467	03216	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05468	03217	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05469	03218	N	N	N	2	CUSTOMER ISSUE	-
FAS_05471	03219	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05472	03220	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05474	03221	N	N	N	1	CUSTOMER ISSUE	-
FAS_05475	03222	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05476	03223	N	N	N	1	CUSTOMER ISSUE	-
FAS_05477	03224	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05478	03225	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05479	03226	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05480	03227	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05481	03228	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05482	03229	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05483	03230	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05484	03231	N	N	Y	2	DIST - REPLACE FUSE	708.75
FAS_05485	03232	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05486	03233	N	N	N	1	CUSTOMER ISSUE	-
FAS_05487	03234	N	N	N	1	CUSTOMER ISSUE	-
FAS_05488	03235	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05489	03236	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05490	03237	N	N	N	1	CUSTOMER ISSUE	-
FAS_05491	03238	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_05492	03239	N	N	N	1	CUSTOMER ISSUE	-
FAS_05493	03240	N	N	N	1	CUSTOMER ISSUE	-
FAS_05494	03241	N	N	N	1	CUSTOMER ISSUE	-
FAS_05496	03242	N	N	N	1	CUSTOMER ISSUE	-
FAS_05498	03243	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05499	03244	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05500	03245	N	N	N	1	CUSTOMER ISSUE	-
FAS_05501	03246	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05502	03247	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05503	03248	N	N	N	1	CUSTOMER ISSUE	-
FAS_05504	03249	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05505	03250	Y	N	Y	5	SEC/SVC - REPAIR	472.5
FAS_05507	03251	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05508	03252	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05509	03253	N	N	Y	9	SEC/SVC - REPLACE	708.75
FAS_05510	03254	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05511	03255	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05512	03256	N	N	Y	1	SEC/SVC - REPAIR	472.5

FAS_05513	03257	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05514	03258	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05515	03259	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05516	03260	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05517	03261	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05518	03262	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_05520	03263	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_05522	03264	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05523	03265	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05524	03266	N	N	N	1	CUSTOMER ISSUE	-
FAS_05525	03267	N	N	N	2	CUSTOMER ISSUE	-
FAS_05526	03268	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05527	03269	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05528	03270	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05529	03271	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05530	03272	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05532	03273	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05535	03274	N	N	N	1	CUSTOMER ISSUE	-
FAS_05536	03275	N	N	N	1	CUSTOMER ISSUE	-
FAS_05542	03276	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05549	03277	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05550	03278	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05554	03279	N	N	N	2	CUSTOMER ISSUE	-
FAS_05556	03280	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05557	03281	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05558	03282	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05559	03283	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05560	03284	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05563	03285	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05565	03286	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05566	03287	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05567	03288	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05568	03289	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05569	03290	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05570	03291	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05571	03292	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05572	03293	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05573	03294	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05574	03295	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05575	03296	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05576	03297	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05577	03298	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05578	03299	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05579	03300	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05580	03301	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05582	03302	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05583	03303	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05584	03304	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05585	03305	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05586	03306	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05587	03307	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05588	03308	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05589	03309	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05592	03310	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05593	03311	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05594	03312	N	N	N	1	CUSTOMER ISSUE	-
FAS_05600	03313	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05606	03314	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_05607	03315	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05608	03316	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05610	03317	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05614	03318	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05616	03319	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05617	03320	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05618	03321	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05619	03322	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05620	03323	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05621	03324	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05622	03325	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05623	03326	N	N	N	1	CUSTOMER ISSUE	-
FAS_05624	03327	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05625	03328	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05627	03329	N	N	N	1	CUSTOMER ISSUE	-
FAS_05628	03330	N	N	N	1	CUSTOMER ISSUE	-
FAS_05629	03331	N	N	Y	1	TX - REPLACE	2500
FAS_05630	03332	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05631	03333	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_05634	03334	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05636	03335	N	N	N	1	CUSTOMER ISSUE	-
FAS_05639	03336	N	N	Y	1	SEC/SVC - REPAIR	472.5

FAS_05640	03337	N	N	N	1	CUSTOMER ISSUE	-
FAS_05641	03338	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05642	03339	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05643	03340	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05644	03341	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05645	03342	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05646	03343	N	N	Y	4	SEC/SVC - REPLACE	708.75
FAS_05647	03344	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05648	03345	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05649	03346	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05650	03347	N	N	N	1	CUSTOMER ISSUE	-
FAS_05651	03348	N	N	Y	8	SEC/SVC - REPLACE	708.75
FAS_05652	03349	N	N	N	1	CUSTOMER ISSUE	-
FAS_05653	03350	N	N	N	1	CUSTOMER ISSUE	-
FAS_05654	03351	N	N	N	1	CUSTOMER ISSUE	-
FAS_05655	03352	N	N	N	1	CUSTOMER ISSUE	-
FAS_05656	03353	N	N	N	1	CUSTOMER ISSUE	-
FAS_05657	03354	N	N	N	1	CUSTOMER ISSUE	-
FAS_05658	03355	N	N	N	1	CUSTOMER ISSUE	-
FAS_05659	03356	N	N	N	1	CUSTOMER ISSUE	-
FAS_05660	03357	N	N	N	1	CUSTOMER ISSUE	-
FAS_05661	03358	N	N	N	1	CUSTOMER ISSUE	-
FAS_05662	03359	N	N	N	1	CUSTOMER ISSUE	-
FAS_05664	03360	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05665	03361	N	N	N	1	CUSTOMER ISSUE	-
FAS_05666	03362	N	N	N	1	CUSTOMER ISSUE	-
FAS_05667	03363	N	N	N	1	CUSTOMER ISSUE	-
FAS_05668	03364	N	N	N	1	CUSTOMER ISSUE	-
FAS_05670	03365	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05671	03366	N	N	N	1	CUSTOMER ISSUE	-
FAS_05672	03367	N	N	N	1	CUSTOMER ISSUE	-
FAS_05674	03368	N	N	N	1	CUSTOMER ISSUE	-
FAS_05675	03369	N	N	N	1	CUSTOMER ISSUE	-
FAS_05676	03370	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05678	03371	N	N	N	1	CUSTOMER ISSUE	-
FAS_05680	03372	N	N	N	1	CUSTOMER ISSUE	-
FAS_05685	03373	N	N	Y	21	SEC/SVC - REPAIR	472.5
FAS_05689	03374	N	N	Y	1	TX - REPLACE	2500
FAS_05690	03375	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_05693	03376	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05694	03377	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05697	03378	N	N	N	1	CUSTOMER ISSUE	-
FAS_05698	03379	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05700	03380	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_05701	03381	N	N	N	2	CUSTOMER ISSUE	-
FAS_05705	03382	N	N	N	1	CUSTOMER ISSUE	-
FAS_05706	03383	N	N	N	1	CUSTOMER ISSUE	-
FAS_05707	03384	N	N	N	1	CUSTOMER ISSUE	-
FAS_05708	03385	N	N	N	1	CUSTOMER ISSUE	-
FAS_05709	03386	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05710	03387	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05711	03388	N	N	N	1	CUSTOMER ISSUE	-
FAS_05712	03389	N	N	N	1	CUSTOMER ISSUE	-
FAS_05715	03390	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05716	03391	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05717	03392	Y	N	Y	1	TX - REPLACE	2500
FAS_05719	03393	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05720	03394	N	N	N	1	CUSTOMER ISSUE	-
FAS_05721	03395	N	N	Y	2	DIST - REPLACE FUSE	708.75
FAS_05722	03396	N	N	N	1	CUSTOMER ISSUE	-
FAS_05724	03397	N	N	N	1	CUSTOMER ISSUE	-
FAS_05725	03398	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05727	03399	N	N	N	1	CUSTOMER ISSUE	-
FAS_05728	03400	N	N	N	1	CUSTOMER ISSUE	-
FAS_05730	03401	N	N	N	1	CUSTOMER ISSUE	-
FAS_05731	03402	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05732	03403	N	N	N	1	CUSTOMER ISSUE	-
FAS_05733	03404	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05735	03405	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05736	03406	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05737	03407	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05738	03408	N	N	N	1	CUSTOMER ISSUE	-
FAS_05741	03409	N	N	N	1	CUSTOMER ISSUE	-
FAS_05743	03410	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05748	03411	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_05749	03412	N	N	Y	1	TX - REPLACE	2500
FAS_05750	03413	N	N	Y	1	TX - REPLACE	2500
FAS_05751	03414	N	N	Y	1	TX - REPLACE	2500
FAS_05752	03415	N	N	Y	1	TX - REPLACE	2500
FAS_05753	03416	N	N	Y	1	TX - REPLACE	2500

FAS_05754	03417	N	N	Y	1	TX - REPLACE	2500
FAS_05755	03418	N	N	N	1	CUSTOMER ISSUE	-
FAS_05756	03419	N	N	Y	1	TX - REPLACE	2500
FAS_05757	03420	N	N	Y	1	TX - REPLACE	2500
FAS_05765	03421	N	N	N	1	CUSTOMER ISSUE	-
FAS_05770	03422	N	N	N	1	CUSTOMER ISSUE	-
FAS_05773	03423	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05777	03424	N	N	N	1	CUSTOMER ISSUE	-
FAS_05778	03425	N	N	N	1	CUSTOMER ISSUE	-
FAS_05782	03426	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_05783	03427	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_05784	03428	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05785	03429	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_05786	03430	N	N	N	1	CUSTOMER ISSUE	-
FAS_05789	03431	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05791	03432	N	N	N	1	CUSTOMER ISSUE	-
FAS_05792	03433	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05793	03434	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05794	03435	N	N	N	1	CUSTOMER ISSUE	-
FAS_05795	03436	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_05796	03437	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05798	03438	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05799	03439	N	N	N	1	CUSTOMER ISSUE	-
FAS_05801	03440	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05803	03441	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05804	03442	N	N	N	1	CUSTOMER ISSUE	-
FAS_05805	03443	Y	N	Y	1	TX - REPLACE	2500
FAS_05806	03444	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05807	03445	N	N	N	1	CUSTOMER ISSUE	-
FAS_05808	03446	N	N	N	1	CUSTOMER ISSUE	-
FAS_05809	03447	N	N	N	1	CUSTOMER ISSUE	-
FAS_05811	03448	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05812	03449	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05813	03450	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05814	03451	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05815	03452	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05816	03453	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05817	03454	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05818	03455	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05819	03456	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05820	03457	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05821	03458	N	N	N	1	CUSTOMER ISSUE	-
FAS_05822	03459	N	N	N	1	CUSTOMER ISSUE	-
FAS_05823	03460	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05824	03461	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_05825	03462	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05826	03463	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05827	03464	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05828	03465	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05829	03466	N	N	N	1	CUSTOMER ISSUE	-
FAS_05830	03467	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05831	03468	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05832	03469	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05833	03470	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05834	03471	N	N	N	1	CUSTOMER ISSUE	-
FAS_05835	03472	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05836	03473	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05837	03474	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05838	03475	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05839	03476	N	N	Y	1	TX - REPLACE	2500
FAS_05840	03477	N	N	Y	1	TX - REPLACE	2500
FAS_05841	03478	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05847	03479	N	N	N	1	CUSTOMER ISSUE	-
FAS_05849	03480	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05850	03481	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05856	03482	N	N	N	1	CUSTOMER ISSUE	-
FAS_05861	03483	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05866	03484	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05874	03485	N	N	N	1	CUSTOMER ISSUE	-
FAS_05876	03486	N	N	N	1	CUSTOMER ISSUE	-
FAS_05885	03487	N	N	N	1	CUSTOMER ISSUE	-
FAS_05890	03488	N	N	N	1	CUSTOMER ISSUE	-
FAS_05891	03489	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05892	03490	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05893	03491	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05894	03492	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05895	03493	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05896	03494	Y	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05897	03495	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05898	03496	N	N	N	1	CUSTOMER ISSUE	-

FAS_05899	03497	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05900	03498	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05901	03499	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05902	03500	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05903	03501	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05904	03502	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05905	03503	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05909	03504	N	N	N	1	CUSTOMER ISSUE	-
FAS_05910	03505	N	N	N	1	CUSTOMER ISSUE	-
FAS_05913	03506	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05921	03507	N	N	N	1	CUSTOMER ISSUE	-
FAS_05922	03508	N	N	N	1	CUSTOMER ISSUE	-
FAS_05923	03509	N	N	N	1	CUSTOMER ISSUE	-
FAS_05928	03510	N	N	Y	32	SEC/SVC - REPAIR	472.5
FAS_05929	03511	N	N	N	1	CUSTOMER ISSUE	-
FAS_05933	03512	N	N	N	1	CUSTOMER ISSUE	-
FAS_05935	03513	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05938	03514	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05939	03515	N	N	N	3	CUSTOMER ISSUE	-
FAS_05941	03516	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05942	03517	N	N	N	1	CUSTOMER ISSUE	-
FAS_05943	03518	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05945	03519	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05946	03520	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_05947	03521	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_05952	03522	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05960	03523	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05961	03524	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05962	03525	N	N	N	1	CUSTOMER ISSUE	-
FAS_05965	03526	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05966	03527	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05967	03528	N	N	N	1	CUSTOMER ISSUE	-
FAS_05968	03529	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05972	03530	N	N	Y	1	TX - REPLACE	2500
FAS_05975	03531	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05977	03532	N	N	Y	1	TX - REPLACE	2500
FAS_05978	03533	N	N	Y	1	TX - REPLACE	2500
FAS_05980	03534	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05984	03535	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_05985	03536	N	N	N	1	CUSTOMER ISSUE	-
FAS_05986	03537	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_05988	03538	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_05992	03539	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_05994	03540	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_05995	03541	N	N	N	1	CUSTOMER ISSUE	-
FAS_05996	03542	Y	N	N	1	CUSTOMER ISSUE	-
FAS_05997	03543	N	N	Y	12	DIST - REPLACE FUSE	708.75
FAS_05998	03544	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_05999	03545	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_06000	03546	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_06001	03547	N	N	N	1	CUSTOMER ISSUE	-
FAS_06002	03548	N	N	Y	1	TX - REPLACE	2500
FAS_06003	03549	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
FAS_06006	03550	N	N	Y	2	DIST - REPLACE FUSE	708.75
FAS_06007	03551	N	N	Y	10	DIST - REPLACE FUSE	708.75
FAS_06009	03552	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06010	03553	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_06012	03554	N	N	N	1	CUSTOMER ISSUE	-
FAS_06016	03555	Y	N	N	1	CUSTOMER ISSUE	-
FAS_06019	03556	N	N	N	1	CUSTOMER ISSUE	-
FAS_06020	03557	Y	N	Y	1	TX - REPLACE	2500
FAS_06021	03558	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06022	03559	N	N	N	1	CUSTOMER ISSUE	-
FAS_06024	03560	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06025	03561	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06027	03562	N	N	N	1	CUSTOMER ISSUE	-
FAS_06028	03563	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06029	03564	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06031	03565	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06032	03566	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06033	03567	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06035	03568	N	N	N	1	CUSTOMER ISSUE	-
FAS_06037	03569	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06038	03570	N	N	N	1	CUSTOMER ISSUE	-
FAS_06039	03571	N	N	Y	16	DIST - REPLACE FUSE	708.75
FAS_06041	03572	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_06042	03573	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_06046	03574	N	N	N	1	CUSTOMER ISSUE	-
FAS_06047	03575	N	N	N	1	CUSTOMER ISSUE	-
FAS_06048	03576	N	N	N	1	CUSTOMER ISSUE	-

FAS_06049	03577	N	N	N	1	CUSTOMER ISSUE	-
FAS_06052	03578	N	N	N	1	CUSTOMER ISSUE	-
FAS_06053	03579	N	N	N	1	CUSTOMER ISSUE	-
FAS_06060	03580	N	N	N	1	CUSTOMER ISSUE	-
FAS_06068	03581	N	N	N	5	CUSTOMER ISSUE	-
FAS_06074	03582	N	N	N	1	CUSTOMER ISSUE	-
FAS_06077	03583	N	N	N	1	CUSTOMER ISSUE	-
FAS_06079	03584	N	N	N	1	CUSTOMER ISSUE	-
FAS_06080	03585	N	N	N	1	CUSTOMER ISSUE	-
FAS_06085	03586	N	N	N	1	CUSTOMER ISSUE	-
FAS_06086	03587	N	N	N	1	CUSTOMER ISSUE	-
FAS_06087	03588	N	N	N	1	CUSTOMER ISSUE	-
FAS_06088	03589	N	N	N	1	CUSTOMER ISSUE	-
FAS_06089	03590	N	N	N	1	CUSTOMER ISSUE	-
FAS_06090	03591	Y	N	N	1	CUSTOMER ISSUE	-
FAS_06091	03592	N	N	N	2	CUSTOMER ISSUE	-
FAS_06093	03593	N	N	N	1	CUSTOMER ISSUE	-
FAS_06095	03594	N	N	N	1	CUSTOMER ISSUE	-
FAS_06098	03595	N	N	N	1	CUSTOMER ISSUE	-
FAS_06099	03596	Y	N	N	1	CUSTOMER ISSUE	-
FAS_06101	03597	N	N	N	1	CUSTOMER ISSUE	-
FAS_06102	03598	N	N	N	1	CUSTOMER ISSUE	-
FAS_06103	03599	N	N	N	1	CUSTOMER ISSUE	-
FAS_06104	03600	N	N	N	1	CUSTOMER ISSUE	-
FAS_06105	03601	Y	N	N	1	CUSTOMER ISSUE	-
FAS_06106	03602	N	N	N	1	CUSTOMER ISSUE	-
FAS_06109	03603	Y	N	N	1	CUSTOMER ISSUE	-
FAS_06110	03604	N	N	N	1	CUSTOMER ISSUE	-
FAS_06113	03605	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_06119	03606	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06120	03607	N	N	Y	19	SEC/SVC - REPAIR	472.5
FAS_06121	03608	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06124	03609	N	N	Y	2	DIST - REPAIR EQUIPMENT	2500
FAS_06125	03610	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06126	03611	N	N	N	1	CUSTOMER ISSUE	-
FAS_06130	03612	N	N	N	1	CUSTOMER ISSUE	-
FAS_06132	03613	N	N	N	1	CUSTOMER ISSUE	-
FAS_06135	03614	N	N	N	1	CUSTOMER ISSUE	-
FAS_06137	03615	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06143	03616	N	N	Y	1	TX - REPLACE	2500
FAS_06144	03617	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06146	03618	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06147	03619	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06148	03620	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06151	03621	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06153	03622	N	N	N	1	CUSTOMER ISSUE	-
FAS_06159	03623	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06163	03624	N	N	N	1	CUSTOMER ISSUE	-
FAS_06164	03625	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06168	03626	N	N	N	1	CUSTOMER ISSUE	-
FAS_06171	03627	N	N	N	1	CUSTOMER ISSUE	-
FAS_06172	03628	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_06173	03629	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_06175	03630	N	N	N	1	CUSTOMER ISSUE	-
FAS_06177	03631	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_06178	03632	N	N	N	1	CUSTOMER ISSUE	-
FAS_06179	03633	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06180	03634	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06184	03635	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_06186	03636	N	N	N	1	CUSTOMER ISSUE	-
FAS_06187	03637	N	N	N	1	CUSTOMER ISSUE	-
FAS_06190	03638	N	N	N	1	CUSTOMER ISSUE	-
FAS_06191	03639	N	N	N	1	CUSTOMER ISSUE	-
FAS_06192	03640	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06194	03641	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_06196	03642	N	N	N	1	CUSTOMER ISSUE	-
FAS_06198	03643	N	N	N	1	CUSTOMER ISSUE	-
FAS_06202	03644	N	N	N	1	CUSTOMER ISSUE	-
FAS_06204	03645	N	N	N	1	CUSTOMER ISSUE	-
FAS_06210	03646	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06212	03647	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06214	03648	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_06217	03649	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06218	03650	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06219	03651	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06221	03652	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06222	03653	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06223	03654	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06228	03655	N	N	N	1	CUSTOMER ISSUE	-
FAS_06229	03656	N	N	Y	6	DIST - CHANGE SETTINGS	708.75

FAS_06231	03657	Y	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_06232	03658	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06233	03659	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06235	03660	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06236	03661	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06237	03662	N	N	N	1	CUSTOMER ISSUE	-
FAS_06241	03663	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06245	03664	N	N	N	1	CUSTOMER ISSUE	-
FAS_06248	03665	N	N	N	1	CUSTOMER ISSUE	-
FAS_06249	03666	N	N	N	1	CUSTOMER ISSUE	-
FAS_06250	03667	N	N	N	1	CUSTOMER ISSUE	-
FAS_06254	03668	Y	N	N	1	CUSTOMER ISSUE	-
FAS_06257	03669	N	N	N	1	CUSTOMER ISSUE	-
FAS_06258	03670	N	N	N	14	CUSTOMER ISSUE	-
FAS_06259	03671	N	N	N	1	CUSTOMER ISSUE	-
FAS_06260	03672	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06261	03673	N	N	N	1	CUSTOMER ISSUE	-
FAS_06262	03674	N	N	N	1	CUSTOMER ISSUE	-
FAS_06265	03675	N	N	N	1	CUSTOMER ISSUE	-
FAS_06266	03676	N	N	N	1	CUSTOMER ISSUE	-
FAS_06267	03677	N	N	N	1	CUSTOMER ISSUE	-
FAS_06270	03678	N	N	N	1	CUSTOMER ISSUE	-
FAS_06271	03679	N	N	Y	1	TX - REPLACE	2500
FAS_06272	03680	N	N	N	1	CUSTOMER ISSUE	-
FAS_06273	03681	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06274	03682	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06275	03683	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06276	03684	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06277	03685	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06278	03686	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06279	03687	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06280	03688	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06281	03689	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06282	03690	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06283	03691	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06285	03692	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06288	03693	N	N	N	1	CUSTOMER ISSUE	-
FAS_06289	03694	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06302	03695	N	N	N	1	CUSTOMER ISSUE	-
FAS_06304	03696	N	N	N	1	CUSTOMER ISSUE	-
FAS_06305	03697	N	N	N	1	CUSTOMER ISSUE	-
FAS_06306	03698	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06307	03699	N	N	N	1	CUSTOMER ISSUE	-
FAS_06308	03700	N	N	N	1	CUSTOMER ISSUE	-
FAS_06309	03701	N	N	N	1	CUSTOMER ISSUE	-
FAS_06312	03702	N	N	N	1	CUSTOMER ISSUE	-
FAS_06313	03703	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06314	03704	N	N	N	1	CUSTOMER ISSUE	-
FAS_06317	03705	N	N	N	1	CUSTOMER ISSUE	-
FAS_06318	03706	Y	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_06325	03707	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06327	03708	N	N	Y	1	TX - REPLACE	2500
FAS_06328	03709	N	N	Y	1	TX - REPLACE	2500
FAS_06329	03710	N	N	Y	1	TX - REPLACE	2500
FAS_06336	03711	N	N	N	1	CUSTOMER ISSUE	-
FAS_06339	03712	Y	N	N	1	CUSTOMER ISSUE	-
FAS_06341	03713	N	N	Y	1	TX - REPLACE	2500
FAS_06342	03714	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06343	03715	N	N	N	3	CUSTOMER ISSUE	-
FAS_06344	03716	N	N	N	1	CUSTOMER ISSUE	-
FAS_06345	03717	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_06347	03718	N	N	N	1	CUSTOMER ISSUE	-
FAS_06349	03719	N	N	N	1	CUSTOMER ISSUE	-
FAS_06350	03720	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06353	03721	N	N	N	1	CUSTOMER ISSUE	-
FAS_06355	03722	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06360	03723	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06362	03724	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06364	03725	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06370	03726	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06371	03727	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_06372	03728	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06376	03729	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_06377	03730	N	N	N	1	CUSTOMER ISSUE	-
FAS_06378	03731	N	N	N	1	CUSTOMER ISSUE	-
FAS_06380	03732	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06381	03733	N	N	N	1	CUSTOMER ISSUE	-
FAS_06383	03734	N	N	N	1	CUSTOMER ISSUE	-
FAS_06384	03735	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06385	03736	N	N	Y	1	TX - REPLACE	2500

FAS_06388	03737	Y	N	N	1	CUSTOMER ISSUE	-
FAS_06390	03738	N	N	N	1	CUSTOMER ISSUE	-
FAS_06392	03739	N	N	N	1	CUSTOMER ISSUE	-
FAS_06393	03740	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06394	03741	N	N	N	3	CUSTOMER ISSUE	-
FAS_06400	03742	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06401	03743	N	N	N	1	CUSTOMER ISSUE	-
FAS_06403	03744	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06406	03745	N	N	N	1	CUSTOMER ISSUE	-
FAS_06408	03746	N	N	N	1	CUSTOMER ISSUE	-
FAS_06412	03747	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06414	03748	N	N	N	1	CUSTOMER ISSUE	-
FAS_06416	03749	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_06417	03750	N	N	N	1	CUSTOMER ISSUE	-
FAS_06418	03751	Y	N	N	1	CUSTOMER ISSUE	-
FAS_06419	03752	N	N	N	1	CUSTOMER ISSUE	-
FAS_06420	03753	N	N	N	1	CUSTOMER ISSUE	-
FAS_06421	03754	N	N	N	1	CUSTOMER ISSUE	-
FAS_06422	03755	N	N	N	1	CUSTOMER ISSUE	-
FAS_06423	03756	N	N	N	1	CUSTOMER ISSUE	-
FAS_06424	03757	N	N	N	1	CUSTOMER ISSUE	-
FAS_06425	03758	N	N	N	1	CUSTOMER ISSUE	-
FAS_06426	03759	N	N	N	1	CUSTOMER ISSUE	-
FAS_06427	03760	Y	N	N	1	CUSTOMER ISSUE	-
FAS_06429	03761	N	N	N	1	CUSTOMER ISSUE	-
FAS_06431	03762	N	N	Y	1	TX - REPLACE	2500
FAS_06433	03763	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_06440	03764	N	N	N	1	CUSTOMER ISSUE	-
FAS_06458	03765	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06461	03766	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06471	03767	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06474	03768	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_06475	03769	N	N	N	1	CUSTOMER ISSUE	-
FAS_06476	03770	N	N	N	1	CUSTOMER ISSUE	-
FAS_06484	03771	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06485	03772	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06490	03773	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_06491	03774	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_06492	03775	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06496	03776	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06501	03777	N	N	N	1	CUSTOMER ISSUE	-
FAS_06503	03778	N	N	N	1	CUSTOMER ISSUE	-
FAS_06504	03779	N	N	N	1	CUSTOMER ISSUE	-
FAS_06505	03780	N	N	N	1	CUSTOMER ISSUE	-
FAS_06513	03781	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06521	03782	N	N	N	1	CUSTOMER ISSUE	-
FAS_06527	03783	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_06536	03784	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06550	03785	N	N	N	1	CUSTOMER ISSUE	-
FAS_06551	03786	N	N	N	1	CUSTOMER ISSUE	-
FAS_06554	03787	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06557	03788	N	N	N	2	CUSTOMER ISSUE	-
FAS_06558	03789	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06559	03790	N	N	N	1	CUSTOMER ISSUE	-
FAS_06560	03791	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06564	03792	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06569	03793	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06570	03794	N	N	N	1	CUSTOMER ISSUE	-
FAS_06571	03795	N	N	N	1	CUSTOMER ISSUE	-
FAS_06572	03796	N	N	N	1	CUSTOMER ISSUE	-
FAS_06574	03797	N	N	N	1	CUSTOMER ISSUE	-
FAS_06576	03798	N	N	N	1	CUSTOMER ISSUE	-
FAS_06577	03799	N	N	N	1	CUSTOMER ISSUE	-
FAS_06578	03800	N	N	N	1	CUSTOMER ISSUE	-
FAS_06579	03801	N	N	N	1	CUSTOMER ISSUE	-
FAS_06581	03802	N	N	N	1	CUSTOMER ISSUE	-
FAS_06584	03803	N	N	Y	1	TX - REPLACE	2500
FAS_06585	03804	N	N	N	1	CUSTOMER ISSUE	-
FAS_06586	03805	N	N	N	1	CUSTOMER ISSUE	-
FAS_06589	03806	N	N	N	1	CUSTOMER ISSUE	-
FAS_06590	03807	N	N	N	1	CUSTOMER ISSUE	-
FAS_06600	03808	N	N	N	1	CUSTOMER ISSUE	-
FAS_06602	03809	N	N	N	1	CUSTOMER ISSUE	-
FAS_06604	03810	N	N	N	1	CUSTOMER ISSUE	-
FAS_06605	03811	N	N	N	1	CUSTOMER ISSUE	-
FAS_06612	03812	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06613	03813	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06614	03814	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_06624	03815	N	N	Y	1	TX - REPLACE	2500
FAS_06628	03816	N	N	N	33	CUSTOMER ISSUE	-

FAS_06630	03817	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_06632	03818	N	N	N	1	CUSTOMER ISSUE	-
FAS_06635	03819	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06639	03820	Y	N	N	1	CUSTOMER ISSUE	-
FAS_06640	03821	Y	N	N	1	CUSTOMER ISSUE	-
FAS_06641	03822	N	N	N	1	CUSTOMER ISSUE	-
FAS_06642	03823	N	N	N	1	CUSTOMER ISSUE	-
FAS_06653	03824	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_06655	03825	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_06660	03826	N	N	N	5	CUSTOMER ISSUE	-
FAS_06663	03827	N	N	N	1	CUSTOMER ISSUE	-
FAS_06664	03828	Y	N	Y	1	TX - REPLACE	2500
FAS_06670	03829	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_06675	03830	N	N	N	1	CUSTOMER ISSUE	-
FAS_06681	03831	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_06685	03832	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_06686	03833	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_06690	03834	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_06692	03835	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_06696	03836	N	N	N	1	CUSTOMER ISSUE	-
FAS_06698	03837	N	N	Y	1	TX - REPLACE	2500
FAS_06699	03838	Y	N	Y	1	TX - REPLACE	2500
FAS_06700	03839	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_06701	03840	N	N	Y	1	TX - REPLACE	2500
FAS_06703	03841	N	N	Y	1	TX - REPLACE	2500
FAS_06704	03842	Y	N	Y	1	TX - REPLACE	2500
FAS_06706	03843	N	N	Y	1	TX - REPLACE	2500
FAS_06707	03844	N	N	Y	1	TX - REPLACE	2500
FAS_06709	03845	N	N	Y	1	TX - REPLACE	2500
FAS_06710	03846	Y	N	Y	1	TX - REPLACE	2500
FAS_06711	03847	N	N	Y	1	TX - REPLACE	2500
FAS_06712	03848	N	N	Y	1	TX - REPLACE	2500
FAS_06713	03849	N	N	Y	1	TX - REPLACE	2500
FAS_06714	03850	N	N	Y	1	TX - REPLACE	2500
FAS_06715	03851	N	N	Y	1	TX - REPLACE	2500
FAS_06716	03852	N	N	Y	1	TX - REPLACE	2500
FAS_06717	03853	N	N	Y	1	TX - REPLACE	2500
FAS_06718	03854	N	N	Y	1	TX - REPLACE	2500
FAS_06719	03855	N	N	Y	1	TX - REPLACE	2500
FAS_06720	03856	N	N	Y	1	TX - REPLACE	2500
FAS_06721	03857	N	N	Y	1	TX - REPLACE	2500
FAS_06722	03858	N	N	Y	1	TX - REPLACE	2500
FAS_06723	03859	Y	N	Y	1	TX - REPLACE	2500
FAS_06724	03860	N	N	Y	1	TX - REPLACE	2500
FAS_06725	03861	N	N	Y	1	TX - REPLACE	2500
FAS_06726	03862	N	N	Y	1	TX - REPLACE	2500
FAS_06727	03863	N	N	Y	1	TX - REPLACE	2500
FAS_06728	03864	Y	N	Y	1	TX - REPLACE	2500
FAS_06729	03865	N	N	Y	1	TX - REPLACE	2500
FAS_06730	03866	Y	N	Y	1	TX - REPLACE	2500
FAS_06731	03867	N	N	Y	1	TX - REPLACE	2500
FAS_06732	03868	N	N	Y	1	TX - REPLACE	2500
FAS_06734	03869	N	N	Y	1	TX - REPLACE	2500
FAS_06735	03870	N	N	Y	1	TX - REPLACE	2500
FAS_06736	03871	N	N	Y	1	TX - REPLACE	2500
FAS_06737	03872	N	N	Y	1	TX - REPLACE	2500
FAS_06775	03873	N	N	N	1	CUSTOMER ISSUE	-
FAS_06777	03874	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06778	03875	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06779	03876	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06780	03877	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06782	03878	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06806	03879	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_06808	03880	N	N	N	1	CUSTOMER ISSUE	-
FAS_06809	03881	N	N	N	1	CUSTOMER ISSUE	-
FAS_06815	03882	N	N	N	1	CUSTOMER ISSUE	-
FAS_06820	03883	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_06821	03884	N	N	N	1	CUSTOMER ISSUE	-
FAS_06822	03885	N	N	N	1	CUSTOMER ISSUE	-
FAS_06826	03886	Y	N	Y	1	TX - REPLACE	2500
FAS_06828	03887	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_06829	03888	N	N	N	1	CUSTOMER ISSUE	-
FAS_06831	03889	N	N	N	1	CUSTOMER ISSUE	-
FAS_06832	03890	N	N	N	1	CUSTOMER ISSUE	-
FAS_06833	03891	N	N	N	1	CUSTOMER ISSUE	-
FAS_06837	03892	N	N	N	1	CUSTOMER ISSUE	-
FAS_06838	03893	Y	N	N	1	CUSTOMER ISSUE	-
FAS_06844	03894	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06845	03895	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06847	03896	N	N	N	1	CUSTOMER ISSUE	-

FAS_06848	03897	Y	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_06855	03898	N	N	N	1	CUSTOMER ISSUE	-
FAS_06858	03899	N	N	N	1	CUSTOMER ISSUE	-
FAS_06859	03900	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06860	03901	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06862	03902	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06863	03903	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06864	03904	Y	N	N	1	CUSTOMER ISSUE	-
FAS_06866	03905	N	N	N	1	CUSTOMER ISSUE	-
FAS_06867	03906	Y	N	N	1	CUSTOMER ISSUE	-
FAS_06870	03907	N	N	N	1	CUSTOMER ISSUE	-
FAS_06871	03908	N	N	N	1	CUSTOMER ISSUE	-
FAS_06872	03909	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_06874	03910	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06877	03911	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06878	03912	N	N	N	1	CUSTOMER ISSUE	-
FAS_06882	03913	N	N	N	1	CUSTOMER ISSUE	-
FAS_06883	03914	N	N	N	1	CUSTOMER ISSUE	-
FAS_06884	03915	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06889	03916	N	N	N	1	CUSTOMER ISSUE	-
FAS_06892	03917	N	N	N	1	CUSTOMER ISSUE	-
FAS_06894	03918	N	N	N	1	CUSTOMER ISSUE	-
FAS_06896	03919	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06897	03920	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_06898	03921	N	N	N	1	CUSTOMER ISSUE	-
FAS_06901	03922	Y	N	N	1	CUSTOMER ISSUE	-
FAS_06902	03923	N	N	N	2	CUSTOMER ISSUE	-
FAS_06903	03924	Y	N	N	1	CUSTOMER ISSUE	-
FAS_06904	03925	N	N	N	1	CUSTOMER ISSUE	-
FAS_06906	03926	N	N	N	1	CUSTOMER ISSUE	-
FAS_06908	03927	N	N	N	1	CUSTOMER ISSUE	-
FAS_06909	03928	N	N	N	1	CUSTOMER ISSUE	-
FAS_06910	03929	N	N	N	1	CUSTOMER ISSUE	-
FAS_06911	03930	N	N	N	1	CUSTOMER ISSUE	-
FAS_06912	03931	N	N	N	1	CUSTOMER ISSUE	-
FAS_06913	03932	N	N	N	1	CUSTOMER ISSUE	-
FAS_06914	03933	N	N	N	1	CUSTOMER ISSUE	-
FAS_06915	03934	N	N	N	1	CUSTOMER ISSUE	-
FAS_06922	03935	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06926	03936	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_06931	03937	Y	N	N	1	CUSTOMER ISSUE	-
FAS_06933	03938	N	N	N	1	CUSTOMER ISSUE	-
FAS_06934	03939	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06942	03940	N	N	N	1	CUSTOMER ISSUE	-
FAS_06943	03941	N	N	N	1	CUSTOMER ISSUE	-
FAS_06945	03942	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06948	03943	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06950	03944	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06952	03945	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06953	03946	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06955	03947	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_06958	03948	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_06965	03949	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06970	03950	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06971	03951	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06972	03952	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06973	03953	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06978	03954	N	N	Y	3	SEC/SVC - REPLACE	708.75
FAS_06979	03955	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06980	03956	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06981	03957	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06984	03958	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06985	03959	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06989	03960	N	N	Y	1	TX - REPLACE	2500
FAS_06990	03961	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06994	03962	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06995	03963	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_06998	03964	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_06999	03965	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07000	03966	N	N	Y	1	TX - REPLACE	2500
FAS_07003	03967	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07006	03968	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07012	03969	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07024	03970	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07032	03971	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07035	03972	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07047	03973	N	N	Y	1	TX - REPLACE	2500
FAS_07055	03974	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07056	03975	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07059	03976	N	N	Y	1	DIST - TREE TRIMMING	945

FAS_07063	03977	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07064	03978	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07065	03979	N	N	N	1	CUSTOMER ISSUE	-
FAS_07069	03980	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07074	03981	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07075	03982	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07078	03983	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07080	03984	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_07086	03985	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07087	03986	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07089	03987	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07093	03988	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07094	03989	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07098	03990	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07103	03991	N	N	Y	1	TX - REPLACE	2500
FAS_07105	03992	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07106	03993	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07107	03994	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07110	03995	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07111	03996	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07122	03997	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07123	03998	N	N	Y	6	TX - REPLACE	2500
FAS_07127	03999	N	N	Y	1	TX - REPLACE	2500
FAS_07128	04000	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07131	04001	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07133	04002	N	N	Y	6	SEC/SVC - REPAIR	472.5
FAS_07134	04003	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07136	04004	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07137	04005	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07138	04006	N	N	Y	5	SEC/SVC - REPAIR	472.5
FAS_07139	04007	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07140	04008	N	N	N	1	CUSTOMER ISSUE	-
FAS_07141	04009	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07142	04010	N	N	N	1	CUSTOMER ISSUE	-
FAS_07143	04011	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07144	04012	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07145	04013	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07146	04014	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07147	04015	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07148	04016	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07149	04017	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07150	04018	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07151	04019	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07152	04020	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07153	04021	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07154	04022	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_07155	04023	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_07156	04024	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07157	04025	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07158	04026	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07159	04027	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07160	04028	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07161	04029	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07162	04030	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07163	04031	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07164	04032	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07166	04033	N	N	N	1	CUSTOMER ISSUE	-
FAS_07167	04034	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07168	04035	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07169	04036	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07170	04037	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07171	04038	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07172	04039	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07173	04040	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07174	04041	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07175	04042	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07176	04043	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07177	04044	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07179	04045	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07180	04046	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07182	04047	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07183	04048	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07184	04049	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07185	04050	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07186	04051	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07187	04052	N	N	Y	11	SEC/SVC - REPAIR	472.5
FAS_07188	04053	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07189	04054	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07190	04055	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07191	04056	N	N	Y	1	SEC/SVC - REPAIR	472.5

FAS_07192	04057	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07193	04058	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07194	04059	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07195	04060	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_07196	04061	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07197	04062	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07198	04063	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_07199	04064	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07200	04065	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_07201	04066	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07202	04067	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07203	04068	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_07205	04069	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07206	04070	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07207	04071	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07208	04072	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07209	04073	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07210	04074	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07211	04075	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07212	04076	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07213	04077	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07214	04078	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07215	04079	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07216	04080	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07217	04081	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07218	04082	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07219	04083	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07220	04084	N	N	N	1	CUSTOMER ISSUE	-
FAS_07221	04085	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07222	04086	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07223	04087	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07224	04088	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07225	04089	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07226	04090	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07227	04091	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07234	04092	N	N	N	1	CUSTOMER ISSUE	-
FAS_07235	04093	N	N	N	1	CUSTOMER ISSUE	-
FAS_07239	04094	Y	N	Y	2	TX - REPLACE	2500
FAS_07240	04095	N	N	N	1	CUSTOMER ISSUE	-
FAS_07241	04096	N	N	N	1	CUSTOMER ISSUE	-
FAS_07242	04097	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07243	04098	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07244	04099	N	N	N	1	CUSTOMER ISSUE	-
FAS_07247	04100	N	N	N	1	CUSTOMER ISSUE	-
FAS_07248	04101	N	N	N	1	CUSTOMER ISSUE	-
FAS_07249	04102	N	N	N	2	CUSTOMER ISSUE	-
FAS_07250	04103	N	N	N	1	CUSTOMER ISSUE	-
FAS_07252	04104	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_07256	04105	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07259	04106	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07261	04107	N	N	N	1	CUSTOMER ISSUE	-
FAS_07262	04108	N	N	N	1	CUSTOMER ISSUE	-
FAS_07263	04109	Y	N	N	1	CUSTOMER ISSUE	-
FAS_07269	04110	N	N	N	1	CUSTOMER ISSUE	-
FAS_07275	04111	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_07277	04112	N	N	Y	1	TX - REPLACE	2500
FAS_07278	04113	N	N	Y	1	TX - REPLACE	2500
FAS_07280	04114	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07281	04115	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07291	04116	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07293	04117	N	N	Y	1	TX - REPLACE	2500
FAS_07296	04118	N	N	N	1	CUSTOMER ISSUE	-
FAS_07297	04119	N	N	N	1	CUSTOMER ISSUE	-
FAS_07298	04120	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07299	04121	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07300	04122	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07301	04123	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07302	04124	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07303	04125	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07304	04126	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07305	04127	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07307	04128	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07308	04129	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07309	04130	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07310	04131	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07312	04132	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07313	04133	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07314	04134	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07315	04135	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07317	04136	N	N	Y	1	SEC/SVC - REPLACE	708.75

FAS_07319	04137	N	N	N	1	CUSTOMER ISSUE	-
FAS_07320	04138	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07322	04139	N	N	Y	2	DIST - TREE TRIMMING	945
FAS_07323	04140	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_07324	04141	N	N	N	1	CUSTOMER ISSUE	-
FAS_07327	04142	N	N	N	1	CUSTOMER ISSUE	-
FAS_07328	04143	N	N	N	1	CUSTOMER ISSUE	-
FAS_07329	04144	N	N	N	1	CUSTOMER ISSUE	-
FAS_07330	04145	Y	N	N	1	CUSTOMER ISSUE	-
FAS_07331	04146	N	N	N	1	CUSTOMER ISSUE	-
FAS_07332	04147	N	N	N	1	CUSTOMER ISSUE	-
FAS_07333	04148	Y	N	N	1	CUSTOMER ISSUE	-
FAS_07334	04149	N	N	N	1	CUSTOMER ISSUE	-
FAS_07335	04150	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07336	04151	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07337	04152	N	N	N	1	CUSTOMER ISSUE	-
FAS_07338	04153	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07340	04154	N	N	Y	1	TX - REPLACE	2500
FAS_07359	04155	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_07360	04156	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07367	04157	N	N	N	1	CUSTOMER ISSUE	-
FAS_07369	04158	N	N	N	1	CUSTOMER ISSUE	-
FAS_07370	04159	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07371	04160	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07372	04161	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07373	04162	N	N	N	1	CUSTOMER ISSUE	-
FAS_07375	04163	Y	N	N	1	CUSTOMER ISSUE	-
FAS_07377	04164	N	N	N	1	CUSTOMER ISSUE	-
FAS_07378	04165	N	N	N	1	CUSTOMER ISSUE	-
FAS_07379	04166	N	N	N	1	CUSTOMER ISSUE	-
FAS_07384	04167	N	N	N	2	CUSTOMER ISSUE	-
FAS_07388	04168	N	N	N	1	CUSTOMER ISSUE	-
FAS_07392	04169	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_07395	04170	N	N	N	1	CUSTOMER ISSUE	-
FAS_07404	04171	N	N	N	1	CUSTOMER ISSUE	-
FAS_07405	04172	N	N	N	1	CUSTOMER ISSUE	-
FAS_07408	04173	N	N	N	1	CUSTOMER ISSUE	-
FAS_07409	04174	N	N	N	1	CUSTOMER ISSUE	-
FAS_07416	04175	N	N	N	1	CUSTOMER ISSUE	-
FAS_07418	04176	N	N	N	4	CUSTOMER ISSUE	-
FAS_07419	04177	N	N	N	1	CUSTOMER ISSUE	-
FAS_07421	04178	N	N	N	1	CUSTOMER ISSUE	-
FAS_07422	04179	N	N	N	1	CUSTOMER ISSUE	-
FAS_07426	04180	N	N	N	1	CUSTOMER ISSUE	-
FAS_07427	04181	N	N	N	1	CUSTOMER ISSUE	-
FAS_07428	04182	N	N	N	1	CUSTOMER ISSUE	-
FAS_07429	04183	N	N	N	1	CUSTOMER ISSUE	-
FAS_07430	04184	Y	N	N	1	CUSTOMER ISSUE	-
FAS_07434	04185	N	N	N	1	CUSTOMER ISSUE	-
FAS_07435	04186	Y	N	N	1	CUSTOMER ISSUE	-
FAS_07438	04187	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_07439	04188	N	N	N	1	CUSTOMER ISSUE	-
FAS_07446	04189	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07447	04190	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_07448	04191	N	N	N	1	CUSTOMER ISSUE	-
FAS_07450	04192	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_07452	04193	N	N	N	1	CUSTOMER ISSUE	-
FAS_07455	04194	N	N	N	21	CUSTOMER ISSUE	-
FAS_07461	04195	N	N	N	2	CUSTOMER ISSUE	-
FAS_07466	04196	N	N	N	1	CUSTOMER ISSUE	-
FAS_07469	04197	N	N	N	1	CUSTOMER ISSUE	-
FAS_07470	04198	N	N	N	1	CUSTOMER ISSUE	-
FAS_07473	04199	N	N	N	1	CUSTOMER ISSUE	-
FAS_07474	04200	N	N	N	1	CUSTOMER ISSUE	-
FAS_07477	04201	N	N	N	2	CUSTOMER ISSUE	-
FAS_07478	04202	N	N	N	1	CUSTOMER ISSUE	-
FAS_07479	04203	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07480	04204	N	N	N	1	CUSTOMER ISSUE	-
FAS_07481	04205	N	N	N	1	CUSTOMER ISSUE	-
FAS_07482	04206	N	N	N	1	CUSTOMER ISSUE	-
FAS_07483	04207	N	N	N	1	CUSTOMER ISSUE	-
FAS_07485	04208	N	N	N	1	CUSTOMER ISSUE	-
FAS_07486	04209	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07487	04210	N	N	N	1	CUSTOMER ISSUE	-
FAS_07514	04211	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07515	04212	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07517	04213	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07518	04214	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_07520	04215	N	N	Y	4	SEC/SVC - REPLACE	708.75
FAS_07521	04216	N	N	Y	1	SEC/SVC - REPAIR	472.5

FAS_07522	04217	N	N	N	1	CUSTOMER ISSUE	-
FAS_07525	04218	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07526	04219	N	N	Y	1	TX - REPLACE	2500
FAS_07528	04220	N	N	N	1	CUSTOMER ISSUE	-
FAS_07529	04221	N	N	N	1	CUSTOMER ISSUE	-
FAS_07530	04222	N	N	N	1	CUSTOMER ISSUE	-
FAS_07531	04223	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07532	04224	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07533	04225	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07534	04226	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07535	04227	N	N	N	1	CUSTOMER ISSUE	-
FAS_07537	04228	N	N	N	1	CUSTOMER ISSUE	-
FAS_07538	04229	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07539	04230	N	N	N	1	CUSTOMER ISSUE	-
FAS_07540	04231	N	N	N	1	CUSTOMER ISSUE	-
FAS_07541	04232	Y	N	N	2	CUSTOMER ISSUE	-
FAS_07542	04233	N	N	N	1	CUSTOMER ISSUE	-
FAS_07543	04234	N	N	N	1	CUSTOMER ISSUE	-
FAS_07544	04235	N	N	N	1	CUSTOMER ISSUE	-
FAS_07545	04236	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07546	04237	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07547	04238	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07548	04239	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07549	04240	N	N	N	1	CUSTOMER ISSUE	-
FAS_07550	04241	N	N	Y	1	TX - REPLACE	2500
FAS_07551	04242	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07552	04243	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07553	04244	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07555	04245	N	N	N	1	CUSTOMER ISSUE	-
FAS_07559	04246	Y	N	N	1	CUSTOMER ISSUE	-
FAS_07563	04247	N	N	Y	8	SEC/SVC - REPLACE	708.75
FAS_07566	04248	N	N	N	1	CUSTOMER ISSUE	-
FAS_07567	04249	N	N	N	1	CUSTOMER ISSUE	-
FAS_07568	04250	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07570	04251	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07572	04252	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07579	04253	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07580	04254	N	N	Y	8	SEC/SVC - REPAIR	472.5
FAS_07582	04255	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_07583	04256	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07584	04257	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07585	04258	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07588	04259	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_07590	04260	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07592	04261	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07593	04262	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07594	04263	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07595	04264	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07596	04265	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07597	04266	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07599	04267	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07600	04268	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07601	04269	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07604	04270	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07609	04271	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07610	04272	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_07611	04273	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07613	04274	N	N	Y	7	SEC/SVC - REPLACE	708.75
FAS_07614	04275	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07615	04276	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07616	04277	N	N	Y	1	TX - REPLACE	2500
FAS_07617	04278	N	N	Y	1	TX - REPLACE	2500
FAS_07618	04279	N	N	Y	1	TX - REPLACE	2500
FAS_07619	04280	N	N	Y	1	TX - REPLACE	2500
FAS_07621	04281	N	N	Y	1	TX - REPLACE	2500
FAS_07622	04282	N	N	Y	1	TX - REPLACE	2500
FAS_07624	04283	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07625	04284	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07626	04285	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07627	04286	N	N	Y	1	TX - REPLACE	2500
FAS_07628	04287	N	N	Y	1	TX - REPLACE	2500
FAS_07635	04288	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07636	04289	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07637	04290	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07638	04291	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07639	04292	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07640	04293	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07643	04294	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07644	04295	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07652	04296	N	N	Y	1	SEC/SVC - REPLACE	708.75

FAS_07653	04297	N	N	N	1	CUSTOMER ISSUE	-
FAS_07654	04298	N	N	Y	1	TX - REPLACE	2500
FAS_07657	04299	N	N	N	1	CUSTOMER ISSUE	-
FAS_07659	04300	N	N	N	1	CUSTOMER ISSUE	-
FAS_07661	04301	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07662	04302	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07664	04303	Y	N	N	1	CUSTOMER ISSUE	-
FAS_07665	04304	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07668	04305	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_07669	04306	N	N	N	1	CUSTOMER ISSUE	-
FAS_07670	04307	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07674	04308	N	N	N	1	CUSTOMER ISSUE	-
FAS_07675	04309	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07677	04310	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07678	04311	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07680	04312	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07681	04313	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07682	04314	N	N	Y	1	TX - REPLACE	2500
FAS_07684	04315	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07685	04316	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07686	04317	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07687	04318	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07691	04319	Y	N	N	1	CUSTOMER ISSUE	-
FAS_07692	04320	N	N	Y	1	TX - REPLACE	2500
FAS_07693	04321	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07697	04322	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07699	04323	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07707	04324	N	N	Y	26	SEC/SVC - REPLACE	708.75
FAS_07708	04325	N	N	Y	26	SEC/SVC - REPLACE	708.75
FAS_07710	04326	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07712	04327	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07715	04328	N	N	N	1	CUSTOMER ISSUE	-
FAS_07718	04329	N	N	N	1	CUSTOMER ISSUE	-
FAS_07719	04330	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07721	04331	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_07722	04332	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07726	04333	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_07733	04334	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07734	04335	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07736	04336	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07737	04337	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07738	04338	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07739	04339	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07740	04340	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07741	04341	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07742	04342	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07743	04343	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07744	04344	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07745	04345	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07746	04346	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07747	04347	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07748	04348	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07749	04349	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07750	04350	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07751	04351	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07752	04352	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07753	04353	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07754	04354	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07756	04355	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07757	04356	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07758	04357	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07759	04358	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07767	04359	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07768	04360	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07769	04361	N	N	N	1	CUSTOMER ISSUE	-
FAS_07772	04362	N	N	N	1	CUSTOMER ISSUE	-
FAS_07773	04363	N	N	N	1	CUSTOMER ISSUE	-
FAS_07774	04364	N	N	N	8	CUSTOMER ISSUE	-
FAS_07775	04365	Y	N	N	1	CUSTOMER ISSUE	-
FAS_07776	04366	N	N	N	1	CUSTOMER ISSUE	-
FAS_07777	04367	Y	N	N	7	CUSTOMER ISSUE	-
FAS_07778	04368	N	N	N	1	CUSTOMER ISSUE	-
FAS_07788	04369	N	N	N	1	CUSTOMER ISSUE	-
FAS_07792	04370	Y	N	Y	1	TX - REPLACE	2500
FAS_07795	04371	N	N	N	1	CUSTOMER ISSUE	-
FAS_07796	04372	N	N	N	1	CUSTOMER ISSUE	-
FAS_07797	04373	N	N	Y	1	TX - REPLACE	2500
FAS_07799	04374	N	N	N	1	CUSTOMER ISSUE	-
FAS_07800	04375	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07803	04376	N	N	Y	1	SEC/SVC - REPAIR	472.5

FAS_07804	04377	Y	N	N	1	CUSTOMER ISSUE	-
FAS_07805	04378	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07809	04379	N	N	N	1	CUSTOMER ISSUE	-
FAS_07810	04380	N	N	N	1	CUSTOMER ISSUE	-
FAS_07811	04381	N	N	N	1	CUSTOMER ISSUE	-
FAS_07812	04382	N	N	N	1	CUSTOMER ISSUE	-
FAS_07813	04383	Y	N	N	2	CUSTOMER ISSUE	-
FAS_07814	04384	N	N	N	1	CUSTOMER ISSUE	-
FAS_07815	04385	N	N	N	1	CUSTOMER ISSUE	-
FAS_07816	04386	N	N	N	1	CUSTOMER ISSUE	-
FAS_07817	04387	N	N	N	1	CUSTOMER ISSUE	-
FAS_07818	04388	N	N	N	1	CUSTOMER ISSUE	-
FAS_07820	04389	Y	N	N	1	CUSTOMER ISSUE	-
FAS_07821	04390	N	N	N	1	CUSTOMER ISSUE	-
FAS_07822	04391	Y	N	N	1	CUSTOMER ISSUE	-
FAS_07824	04392	N	N	N	1	CUSTOMER ISSUE	-
FAS_07826	04393	N	N	Y	4	SEC/SVC - REPLACE	708.75
FAS_07827	04394	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07828	04395	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07829	04396	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07830	04397	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07831	04398	N	N	N	1	CUSTOMER ISSUE	-
FAS_07832	04399	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07833	04400	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_07834	04401	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07835	04402	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07836	04403	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07837	04404	N	N	N	1	CUSTOMER ISSUE	-
FAS_07838	04405	N	N	Y	3	SEC/SVC - REPLACE	708.75
FAS_07839	04406	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07840	04407	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07841	04408	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07842	04409	N	N	N	1	CUSTOMER ISSUE	-
FAS_07843	04410	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_07844	04411	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07845	04412	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07846	04413	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07847	04414	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07848	04415	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07849	04416	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07850	04417	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07851	04418	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07852	04419	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07853	04420	Y	N	N	5	CUSTOMER ISSUE	-
FAS_07854	04421	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07855	04422	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07856	04423	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07857	04424	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07858	04425	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07859	04426	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07860	04427	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07861	04428	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07862	04429	N	N	N	1	CUSTOMER ISSUE	-
FAS_07863	04430	N	N	N	1	CUSTOMER ISSUE	-
FAS_07864	04431	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07865	04432	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07866	04433	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07867	04434	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07868	04435	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07869	04436	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07870	04437	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07871	04438	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07872	04439	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07873	04440	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07874	04441	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07875	04442	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07876	04443	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07880	04444	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07881	04445	N	N	N	1	CUSTOMER ISSUE	-
FAS_07882	04446	N	N	N	1	CUSTOMER ISSUE	-
FAS_07883	04447	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07884	04448	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_07885	04449	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_07886	04450	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_07887	04451	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_07889	04452	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07890	04453	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07891	04454	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07892	04455	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07893	04456	N	N	Y	1	SEC/SVC - REPLACE	708.75

FAS_07894	04457	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07895	04458	N	N	Y	5	SEC/SVC - REPLACE	708.75
FAS_07896	04459	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07897	04460	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07899	04461	N	N	N	1	CUSTOMER ISSUE	-
FAS_07900	04462	N	N	N	2	CUSTOMER ISSUE	-
FAS_07901	04463	N	N	N	1	CUSTOMER ISSUE	-
FAS_07902	04464	N	N	N	1	CUSTOMER ISSUE	-
FAS_07903	04465	N	N	N	1	CUSTOMER ISSUE	-
FAS_07904	04466	N	N	N	1	CUSTOMER ISSUE	-
FAS_07905	04467	Y	N	N	1	CUSTOMER ISSUE	-
FAS_07906	04468	N	N	N	1	CUSTOMER ISSUE	-
FAS_07907	04469	N	N	N	1	CUSTOMER ISSUE	-
FAS_07909	04470	N	N	N	1	CUSTOMER ISSUE	-
FAS_07912	04471	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07913	04472	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07914	04473	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07915	04474	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07916	04475	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07917	04476	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07918	04477	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07919	04478	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07920	04479	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07921	04480	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07922	04481	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07923	04482	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07924	04483	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07925	04484	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07926	04485	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07927	04486	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07928	04487	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07929	04488	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07930	04489	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07931	04490	N	N	Y	10	TX - REPLACE	2500
FAS_07932	04491	N	N	Y	6	SEC/SVC - REPLACE	708.75
FAS_07933	04492	N	N	N	1	CUSTOMER ISSUE	-
FAS_07934	04493	Y	N	N	1	CUSTOMER ISSUE	-
FAS_07936	04494	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07937	04495	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_07938	04496	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07939	04497	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07940	04498	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07941	04499	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07942	04500	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07943	04501	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07944	04502	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07945	04503	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07946	04504	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07947	04505	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_07949	04506	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07950	04507	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07951	04508	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07952	04509	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07953	04510	Y	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_07954	04511	N	N	Y	3	SEC/SVC - REPLACE	708.75
FAS_07955	04512	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07956	04513	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07957	04514	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07958	04515	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07959	04516	N	N	Y	1	TX - REPLACE	2500
FAS_07960	04517	N	N	Y	5	TX - REPLACE	2500
FAS_07961	04518	N	N	Y	1	TX - REPLACE	2500
FAS_07962	04519	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07963	04520	N	N	Y	1	TX - REPLACE	2500
FAS_07964	04521	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07965	04522	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07966	04523	N	N	Y	1	TX - REPLACE	2500
FAS_07967	04524	N	N	Y	1	TX - REPLACE	2500
FAS_07968	04525	N	N	Y	1	TX - REPLACE	2500
FAS_07969	04526	Y	N	Y	1	TX - REPLACE	2500
FAS_07970	04527	N	N	Y	1	TX - REPLACE	2500
FAS_07971	04528	N	N	Y	1	TX - REPLACE	2500
FAS_07972	04529	N	N	Y	1	TX - REPLACE	2500
FAS_07973	04530	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07975	04531	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07976	04532	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_07977	04533	Y	N	N	1	CUSTOMER ISSUE	-
FAS_07984	04534	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_07985	04535	N	N	N	1	CUSTOMER ISSUE	-
FAS_07986	04536	N	N	N	1	CUSTOMER ISSUE	-

FAS_07988	04537	N	N	N	1	CUSTOMER ISSUE	-
FAS_07989	04538	N	N	Y	4	SEC/SVC - REPLACE	708.75
FAS_07995	04539	N	N	N	1	CUSTOMER ISSUE	-
FAS_07996	04540	N	N	N	1	CUSTOMER ISSUE	-
FAS_07998	04541	Y	N	N	1	CUSTOMER ISSUE	-
FAS_07999	04542	N	N	N	6	CUSTOMER ISSUE	-
FAS_08002	04543	N	N	N	4	CUSTOMER ISSUE	-
FAS_08005	04544	N	N	N	1	CUSTOMER ISSUE	-
FAS_08007	04545	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08013	04546	N	N	N	1	CUSTOMER ISSUE	-
FAS_08024	04547	N	N	N	1	CUSTOMER ISSUE	-
FAS_08027	04548	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_08028	04549	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_08029	04550	N	N	N	1	CUSTOMER ISSUE	-
FAS_08031	04551	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_08033	04552	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_08043	04553	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08044	04554	N	N	N	1	CUSTOMER ISSUE	-
FAS_08046	04555	N	N	N	1	CUSTOMER ISSUE	-
FAS_08048	04556	N	N	N	1	CUSTOMER ISSUE	-
FAS_08049	04557	N	N	N	1	CUSTOMER ISSUE	-
FAS_08060	04558	N	N	N	1	CUSTOMER ISSUE	-
FAS_08061	04559	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08063	04560	N	N	N	1	CUSTOMER ISSUE	-
FAS_08068	04561	N	N	N	1	CUSTOMER ISSUE	-
FAS_08070	04562	N	N	N	1	CUSTOMER ISSUE	-
FAS_08077	04563	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_08105	04564	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_08106	04565	N	N	N	1	CUSTOMER ISSUE	-
FAS_08116	04566	N	N	N	1	CUSTOMER ISSUE	-
FAS_08118	04567	N	N	N	1	CUSTOMER ISSUE	-
FAS_08125	04568	N	N	N	1	CUSTOMER ISSUE	-
FAS_08148	04569	N	N	N	1	CUSTOMER ISSUE	-
FAS_08152	04570	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08153	04571	N	N	N	1	CUSTOMER ISSUE	-
FAS_08154	04572	N	N	N	1	CUSTOMER ISSUE	-
FAS_08158	04573	N	N	N	1	CUSTOMER ISSUE	-
FAS_08206	04574	N	N	N	1	CUSTOMER ISSUE	-
FAS_08213	04575	N	N	N	1	CUSTOMER ISSUE	-
FAS_08226	04576	N	N	N	1	CUSTOMER ISSUE	-
FAS_08227	04577	N	N	N	1	CUSTOMER ISSUE	-
FAS_08228	04578	N	N	N	1	CUSTOMER ISSUE	-
FAS_08234	04579	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_08236	04580	N	N	N	1	CUSTOMER ISSUE	-
FAS_08245	04581	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08246	04582	N	N	N	1	CUSTOMER ISSUE	-
FAS_08250	04583	N	N	N	1	CUSTOMER ISSUE	-
FAS_08253	04584	N	N	N	1	CUSTOMER ISSUE	-
FAS_08256	04585	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_08263	04586	N	N	N	1	CUSTOMER ISSUE	-
FAS_08268	04587	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08269	04588	N	N	N	1	CUSTOMER ISSUE	-
FAS_08272	04589	N	N	N	1	CUSTOMER ISSUE	-
FAS_08274	04590	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08277	04591	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08284	04592	N	N	N	1	CUSTOMER ISSUE	-
FAS_08289	04593	N	N	N	1	CUSTOMER ISSUE	-
FAS_08291	04594	N	N	N	1	CUSTOMER ISSUE	-
FAS_08292	04595	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08295	04596	N	N	N	1	CUSTOMER ISSUE	-
FAS_08300	04597	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_08301	04598	N	N	N	1	CUSTOMER ISSUE	-
FAS_08310	04599	N	N	N	1	CUSTOMER ISSUE	-
FAS_08311	04600	N	N	N	1	CUSTOMER ISSUE	-
FAS_08328	04601	N	N	N	1	CUSTOMER ISSUE	-
FAS_08339	04602	N	N	N	1	CUSTOMER ISSUE	-
FAS_08343	04603	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08354	04604	N	N	N	1	CUSTOMER ISSUE	-
FAS_08358	04605	N	N	N	1	CUSTOMER ISSUE	-
FAS_08372	04606	N	N	N	1	CUSTOMER ISSUE	-
FAS_08377	04607	N	N	N	1	CUSTOMER ISSUE	-
FAS_08378	04608	N	N	N	1	CUSTOMER ISSUE	-
FAS_08389	04609	N	N	N	1	CUSTOMER ISSUE	-
FAS_08390	04610	N	N	N	1	CUSTOMER ISSUE	-
FAS_08399	04611	N	N	N	1	CUSTOMER ISSUE	-
FAS_08408	04612	N	N	N	1	CUSTOMER ISSUE	-
FAS_08421	04613	N	N	N	1	CUSTOMER ISSUE	-
FAS_08423	04614	N	N	N	1	CUSTOMER ISSUE	-
FAS_08434	04615	N	N	N	1	CUSTOMER ISSUE	-
FAS_08435	04616	N	N	Y	1	SEC/SVC - REPAIR	472.5

FAS_08440	04617	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08446	04618	N	N	N	1	CUSTOMER ISSUE	-
FAS_08447	04619	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08448	04620	N	N	N	1	CUSTOMER ISSUE	-
FAS_08453	04621	N	N	N	1	CUSTOMER ISSUE	-
FAS_08456	04622	N	N	N	1	CUSTOMER ISSUE	-
FAS_08464	04623	N	N	N	1	CUSTOMER ISSUE	-
FAS_08466	04624	N	N	N	1	CUSTOMER ISSUE	-
FAS_08474	04625	N	N	N	1	CUSTOMER ISSUE	-
FAS_08487	04626	N	N	N	1	CUSTOMER ISSUE	-
FAS_08488	04627	N	N	N	1	CUSTOMER ISSUE	-
FAS_08494	04628	N	N	N	1	CUSTOMER ISSUE	-
FAS_08495	04629	N	N	N	1	CUSTOMER ISSUE	-
FAS_08497	04630	N	N	N	1	CUSTOMER ISSUE	-
FAS_08498	04631	N	N	N	1	CUSTOMER ISSUE	-
FAS_08500	04632	N	N	N	1	CUSTOMER ISSUE	-
FAS_08501	04633	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08502	04634	N	N	N	1	CUSTOMER ISSUE	-
FAS_08503	04635	N	N	N	9	CUSTOMER ISSUE	-
FAS_08507	04636	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08508	04637	N	N	N	1	CUSTOMER ISSUE	-
FAS_08509	04638	N	N	N	1	CUSTOMER ISSUE	-
FAS_08510	04639	N	N	N	1	CUSTOMER ISSUE	-
FAS_08511	04640	N	N	N	1	CUSTOMER ISSUE	-
FAS_08512	04641	N	N	N	1	CUSTOMER ISSUE	-
FAS_08514	04642	N	N	N	1	CUSTOMER ISSUE	-
FAS_08516	04643	N	N	N	1	CUSTOMER ISSUE	-
FAS_08517	04644	N	N	N	1	CUSTOMER ISSUE	-
FAS_08518	04645	N	N	N	1	CUSTOMER ISSUE	-
FAS_08519	04646	N	N	N	1	CUSTOMER ISSUE	-
FAS_08520	04647	N	N	N	1	CUSTOMER ISSUE	-
FAS_08521	04648	N	N	N	1	CUSTOMER ISSUE	-
FAS_08522	04649	N	N	N	1	CUSTOMER ISSUE	-
FAS_08524	04650	N	N	N	1	CUSTOMER ISSUE	-
FAS_08525	04651	N	N	N	1	CUSTOMER ISSUE	-
FAS_08526	04652	N	N	N	1	CUSTOMER ISSUE	-
FAS_08527	04653	N	N	N	1	CUSTOMER ISSUE	-
FAS_08528	04654	N	N	N	1	CUSTOMER ISSUE	-
FAS_08529	04655	N	N	N	1	CUSTOMER ISSUE	-
FAS_08530	04656	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08532	04657	N	N	N	1	CUSTOMER ISSUE	-
FAS_08533	04658	N	N	N	1	CUSTOMER ISSUE	-
FAS_08534	04659	N	N	N	15	CUSTOMER ISSUE	-
FAS_08535	04660	N	N	N	1	CUSTOMER ISSUE	-
FAS_08537	04661	N	N	N	2	CUSTOMER ISSUE	-
FAS_08538	04662	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08539	04663	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08540	04664	N	N	N	1	CUSTOMER ISSUE	-
FAS_08541	04665	N	N	N	1	CUSTOMER ISSUE	-
FAS_08543	04666	N	N	N	1	CUSTOMER ISSUE	-
FAS_08544	04667	N	N	N	1	CUSTOMER ISSUE	-
FAS_08545	04668	N	N	N	1	CUSTOMER ISSUE	-
FAS_08546	04669	N	N	N	1	CUSTOMER ISSUE	-
FAS_08547	04670	N	N	N	1	CUSTOMER ISSUE	-
FAS_08548	04671	N	N	N	1	CUSTOMER ISSUE	-
FAS_08549	04672	N	N	N	1	CUSTOMER ISSUE	-
FAS_08550	04673	N	N	N	1	CUSTOMER ISSUE	-
FAS_08551	04674	N	N	N	1	CUSTOMER ISSUE	-
FAS_08552	04675	N	N	N	1	CUSTOMER ISSUE	-
FAS_08553	04676	N	N	N	1	CUSTOMER ISSUE	-
FAS_08554	04677	N	N	N	1	CUSTOMER ISSUE	-
FAS_08555	04678	N	N	N	1	CUSTOMER ISSUE	-
FAS_08556	04679	N	N	N	22	CUSTOMER ISSUE	-
FAS_08557	04680	N	N	N	1	CUSTOMER ISSUE	-
FAS_08562	04681	N	N	N	1	CUSTOMER ISSUE	-
FAS_08565	04682	N	N	N	1	CUSTOMER ISSUE	-
FAS_08566	04683	N	N	N	2	CUSTOMER ISSUE	-
FAS_08567	04684	Y	N	N	2	CUSTOMER ISSUE	-
FAS_08568	04685	N	N	N	1	CUSTOMER ISSUE	-
FAS_08569	04686	N	N	N	1	CUSTOMER ISSUE	-
FAS_08574	04687	N	N	N	1	CUSTOMER ISSUE	-
FAS_08578	04688	N	N	N	1	CUSTOMER ISSUE	-
FAS_08579	04689	N	N	N	1	CUSTOMER ISSUE	-
FAS_08580	04690	N	N	N	1	CUSTOMER ISSUE	-
FAS_08581	04691	N	N	N	1	CUSTOMER ISSUE	-
FAS_08582	04692	N	N	N	1	CUSTOMER ISSUE	-
FAS_08583	04693	N	N	N	1	CUSTOMER ISSUE	-
FAS_08584	04694	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08585	04695	N	N	N	1	CUSTOMER ISSUE	-
FAS_08588	04696	N	N	N	1	CUSTOMER ISSUE	-

FAS_08589	04697	N	N	N	1	CUSTOMER ISSUE	-
FAS_08592	04698	N	N	N	1	CUSTOMER ISSUE	-
FAS_08597	04699	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08598	04700	N	N	N	1	CUSTOMER ISSUE	-
FAS_08600	04701	N	N	N	1	CUSTOMER ISSUE	-
FAS_08601	04702	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08602	04703	N	N	N	1	CUSTOMER ISSUE	-
FAS_08603	04704	N	N	N	1	CUSTOMER ISSUE	-
FAS_08604	04705	N	N	N	1	CUSTOMER ISSUE	-
FAS_08605	04706	N	N	N	1	CUSTOMER ISSUE	-
FAS_08606	04707	N	N	N	1	CUSTOMER ISSUE	-
FAS_08609	04708	N	N	N	1	CUSTOMER ISSUE	-
FAS_08610	04709	N	N	N	1	CUSTOMER ISSUE	-
FAS_08611	04710	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08614	04711	N	N	N	1	CUSTOMER ISSUE	-
FAS_08616	04712	N	N	N	1	CUSTOMER ISSUE	-
FAS_08617	04713	N	N	N	1	CUSTOMER ISSUE	-
FAS_08618	04714	N	N	N	1	CUSTOMER ISSUE	-
FAS_08619	04715	N	N	N	1	CUSTOMER ISSUE	-
FAS_08620	04716	N	N	N	1	CUSTOMER ISSUE	-
FAS_08621	04717	N	N	N	1	CUSTOMER ISSUE	-
FAS_08622	04718	N	N	N	1	CUSTOMER ISSUE	-
FAS_08623	04719	N	N	N	1	CUSTOMER ISSUE	-
FAS_08624	04720	N	N	N	1	CUSTOMER ISSUE	-
FAS_08625	04721	N	N	N	1	CUSTOMER ISSUE	-
FAS_08626	04722	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08628	04723	N	N	N	1	CUSTOMER ISSUE	-
FAS_08629	04724	N	N	N	1	CUSTOMER ISSUE	-
FAS_08630	04725	N	N	N	1	CUSTOMER ISSUE	-
FAS_08631	04726	N	N	N	1	CUSTOMER ISSUE	-
FAS_08632	04727	N	N	N	1	CUSTOMER ISSUE	-
FAS_08636	04728	N	N	N	1	CUSTOMER ISSUE	-
FAS_08637	04729	N	N	N	1	CUSTOMER ISSUE	-
FAS_08641	04730	N	N	N	1	CUSTOMER ISSUE	-
FAS_08642	04731	N	N	N	1	CUSTOMER ISSUE	-
FAS_08643	04732	N	N	N	1	CUSTOMER ISSUE	-
FAS_08644	04733	N	N	N	1	CUSTOMER ISSUE	-
FAS_08645	04734	N	N	N	1	CUSTOMER ISSUE	-
FAS_08646	04735	N	N	N	1	CUSTOMER ISSUE	-
FAS_08647	04736	N	N	N	1	CUSTOMER ISSUE	-
FAS_08648	04737	N	N	N	1	CUSTOMER ISSUE	-
FAS_08649	04738	N	N	N	1	CUSTOMER ISSUE	-
FAS_08650	04739	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08651	04740	N	N	N	1	CUSTOMER ISSUE	-
FAS_08652	04741	N	N	N	1	CUSTOMER ISSUE	-
FAS_08653	04742	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_08667	04743	N	N	Y	32	DIST - REPLACE FUSE	708.75
FAS_08668	04744	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_08669	04745	N	N	N	1	CUSTOMER ISSUE	-
FAS_08670	04746	N	N	N	1	CUSTOMER ISSUE	-
FAS_08672	04747	N	N	Y	31	SEC/SVC - REPAIR	472.5
FAS_08673	04748	N	N	Y	31	SEC/SVC - REPAIR	472.5
FAS_08674	04749	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_08680	04750	N	N	N	1	CUSTOMER ISSUE	-
FAS_08683	04751	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_08684	04752	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_08685	04753	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08686	04754	N	N	N	2	CUSTOMER ISSUE	-
FAS_08687	04755	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08688	04756	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08689	04757	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08693	04758	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_08698	04759	N	N	N	1	CUSTOMER ISSUE	-
FAS_08705	04760	N	N	Y	8	SEC/SVC - REPAIR	472.5
FAS_08708	04761	N	N	N	1	CUSTOMER ISSUE	-
FAS_08709	04762	N	N	Y	1	TX - REPLACE	2500
FAS_08710	04763	N	N	N	1	CUSTOMER ISSUE	-
FAS_08711	04764	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08714	04765	N	N	Y	1	TX - REPLACE	2500
FAS_08723	04766	N	N	N	1	CUSTOMER ISSUE	-
FAS_08724	04767	N	N	N	1	CUSTOMER ISSUE	-
FAS_08728	04768	N	N	N	1	CUSTOMER ISSUE	-
FAS_08730	04769	N	N	N	1	CUSTOMER ISSUE	-
FAS_08733	04770	N	N	N	1	CUSTOMER ISSUE	-
FAS_08734	04771	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08735	04772	N	N	N	1	CUSTOMER ISSUE	-
FAS_08741	04773	N	N	N	1	CUSTOMER ISSUE	-
FAS_08742	04774	N	N	N	1	CUSTOMER ISSUE	-
FAS_08743	04775	N	N	N	1	CUSTOMER ISSUE	-
FAS_08747	04776	N	N	N	1	CUSTOMER ISSUE	-

FAS_08750	04777	N	N	N	1	CUSTOMER ISSUE	-
FAS_08751	04778	N	N	N	1	CUSTOMER ISSUE	-
FAS_08752	04779	N	N	N	1	CUSTOMER ISSUE	-
FAS_08756	04780	N	N	N	1	CUSTOMER ISSUE	-
FAS_08757	04781	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08764	04782	N	N	N	1	CUSTOMER ISSUE	-
FAS_08770	04783	N	N	N	1	CUSTOMER ISSUE	-
FAS_08773	04784	N	N	N	1	CUSTOMER ISSUE	-
FAS_08782	04785	N	N	N	1	CUSTOMER ISSUE	-
FAS_08787	04786	N	N	N	1	CUSTOMER ISSUE	-
FAS_08790	04787	N	N	N	1	CUSTOMER ISSUE	-
FAS_08791	04788	N	N	N	1	CUSTOMER ISSUE	-
FAS_08796	04789	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08797	04790	N	N	N	1	CUSTOMER ISSUE	-
FAS_08798	04791	N	N	N	1	CUSTOMER ISSUE	-
FAS_08800	04792	N	N	N	1	CUSTOMER ISSUE	-
FAS_08801	04793	N	N	N	1	CUSTOMER ISSUE	-
FAS_08802	04794	N	N	N	1	CUSTOMER ISSUE	-
FAS_08804	04795	N	N	N	1	CUSTOMER ISSUE	-
FAS_08805	04796	N	N	N	1	CUSTOMER ISSUE	-
FAS_08806	04797	N	N	N	1	CUSTOMER ISSUE	-
FAS_08816	04798	N	N	N	1	CUSTOMER ISSUE	-
FAS_08817	04799	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_08818	04800	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_08824	04801	N	N	N	1	CUSTOMER ISSUE	-
FAS_08829	04802	N	N	N	1	CUSTOMER ISSUE	-
FAS_08837	04803	N	N	N	1	CUSTOMER ISSUE	-
FAS_08840	04804	N	N	N	1	CUSTOMER ISSUE	-
FAS_08843	04805	N	N	N	1	CUSTOMER ISSUE	-
FAS_08845	04806	N	N	N	1	CUSTOMER ISSUE	-
FAS_08846	04807	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_08849	04808	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_08851	04809	N	N	N	1	CUSTOMER ISSUE	-
FAS_08853	04810	N	N	N	1	CUSTOMER ISSUE	-
FAS_08855	04811	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_08856	04812	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08858	04813	N	N	N	1	CUSTOMER ISSUE	-
FAS_08860	04814	N	N	N	1	CUSTOMER ISSUE	-
FAS_08861	04815	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_08862	04816	N	N	Y	2	DIST - REPLACE FUSE	708.75
FAS_08863	04817	N	N	N	1	CUSTOMER ISSUE	-
FAS_08864	04818	N	N	N	1	CUSTOMER ISSUE	-
FAS_08865	04819	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08866	04820	N	N	N	1	CUSTOMER ISSUE	-
FAS_08867	04821	N	N	N	1	CUSTOMER ISSUE	-
FAS_08868	04822	N	N	N	1	CUSTOMER ISSUE	-
FAS_08869	04823	N	N	N	1	CUSTOMER ISSUE	-
FAS_08870	04824	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_08873	04825	N	N	N	1	CUSTOMER ISSUE	-
FAS_08874	04826	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08875	04827	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_08876	04828	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08877	04829	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08878	04830	N	N	N	1	CUSTOMER ISSUE	-
FAS_08879	04831	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_08880	04832	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08881	04833	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08882	04834	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08883	04835	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08884	04836	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08885	04837	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08886	04838	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08887	04839	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08888	04840	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08889	04841	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08890	04842	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08892	04843	N	N	N	1	CUSTOMER ISSUE	-
FAS_08893	04844	N	N	Y	2	DIST - REPLACE FUSE	708.75
FAS_08896	04845	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08897	04846	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_08902	04847	N	N	N	1	CUSTOMER ISSUE	-
FAS_08906	04848	N	N	N	1	CUSTOMER ISSUE	-
FAS_08907	04849	N	N	N	1	CUSTOMER ISSUE	-
FAS_08910	04850	N	N	N	1	CUSTOMER ISSUE	-
FAS_08911	04851	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_08913	04852	N	N	N	1	CUSTOMER ISSUE	-
FAS_08914	04853	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_08917	04854	N	N	N	9	CUSTOMER ISSUE	-
FAS_08921	04855	N	N	N	1	CUSTOMER ISSUE	-
FAS_08922	04856	N	N	N	1	CUSTOMER ISSUE	-

FAS_08923	04857	N	N	N	1	CUSTOMER ISSUE	-
FAS_08924	04858	N	N	N	1	CUSTOMER ISSUE	-
FAS_08925	04859	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08930	04860	N	N	N	1	CUSTOMER ISSUE	-
FAS_08931	04861	N	N	N	1	CUSTOMER ISSUE	-
FAS_08932	04862	N	N	N	1	CUSTOMER ISSUE	-
FAS_08933	04863	N	N	Y	1	TX - REPLACE	2500
FAS_08934	04864	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_08935	04865	N	N	N	1	CUSTOMER ISSUE	-
FAS_08936	04866	N	N	N	1	CUSTOMER ISSUE	-
FAS_08937	04867	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_08938	04868	N	N	Y	5	TX - REPLACE	2500
FAS_08941	04869	N	N	N	1	CUSTOMER ISSUE	-
FAS_08945	04870	N	N	N	1	CUSTOMER ISSUE	-
FAS_08947	04871	N	N	N	1	CUSTOMER ISSUE	-
FAS_08948	04872	N	N	N	1	CUSTOMER ISSUE	-
FAS_08951	04873	N	N	N	1	CUSTOMER ISSUE	-
FAS_08952	04874	N	N	N	1	CUSTOMER ISSUE	-
FAS_08953	04875	N	N	N	1	CUSTOMER ISSUE	-
FAS_08954	04876	N	N	N	1	CUSTOMER ISSUE	-
FAS_08955	04877	N	N	N	1	CUSTOMER ISSUE	-
FAS_08957	04878	Y	N	Y	1	TX - REPLACE	2500
FAS_08959	04879	N	N	Y	1	TX - REPLACE	2500
FAS_08975	04880	N	N	N	1	CUSTOMER ISSUE	-
FAS_08976	04881	N	N	N	1	CUSTOMER ISSUE	-
FAS_08978	04882	N	N	N	1	CUSTOMER ISSUE	-
FAS_08979	04883	N	N	N	1	CUSTOMER ISSUE	-
FAS_08980	04884	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08983	04885	N	N	N	1	CUSTOMER ISSUE	-
FAS_08985	04886	N	N	N	1	CUSTOMER ISSUE	-
FAS_08986	04887	Y	N	N	1	CUSTOMER ISSUE	-
FAS_08987	04888	N	N	N	1	CUSTOMER ISSUE	-
FAS_08988	04889	N	N	N	1	CUSTOMER ISSUE	-
FAS_08990	04890	N	N	N	1	CUSTOMER ISSUE	-
FAS_08993	04891	N	N	N	1	CUSTOMER ISSUE	-
FAS_08994	04892	N	N	N	1	CUSTOMER ISSUE	-
FAS_08995	04893	N	N	N	1	CUSTOMER ISSUE	-
FAS_08996	04894	N	N	N	1	CUSTOMER ISSUE	-
FAS_08997	04895	N	N	N	1	CUSTOMER ISSUE	-
FAS_09000	04896	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09001	04897	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09003	04898	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09004	04899	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09006	04900	N	N	N	1	CUSTOMER ISSUE	-
FAS_09013	04901	Y	N	Y	1	TX - REPLACE	2500
FAS_09018	04902	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_09019	04903	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09020	04904	N	N	N	1	CUSTOMER ISSUE	-
FAS_09022	04905	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_09026	04906	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09027	04907	N	N	Y	31	SEC/SVC - REPAIR	472.5
FAS_09028	04908	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_09029	04909	N	N	N	1	CUSTOMER ISSUE	-
FAS_09030	04910	N	N	N	1	CUSTOMER ISSUE	-
FAS_09031	04911	N	N	N	1	CUSTOMER ISSUE	-
FAS_09032	04912	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09033	04913	N	N	N	1	CUSTOMER ISSUE	-
FAS_09034	04914	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_09035	04915	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09036	04916	N	N	N	1	CUSTOMER ISSUE	-
FAS_09037	04917	N	N	N	1	CUSTOMER ISSUE	-
FAS_09038	04918	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09039	04919	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09040	04920	N	N	N	1	CUSTOMER ISSUE	-
FAS_09041	04921	N	N	N	2	CUSTOMER ISSUE	-
FAS_09042	04922	N	N	N	1	CUSTOMER ISSUE	-
FAS_09043	04923	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09044	04924	N	N	N	1	CUSTOMER ISSUE	-
FAS_09045	04925	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09046	04926	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09047	04927	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09049	04928	N	N	N	1	CUSTOMER ISSUE	-
FAS_09050	04929	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09051	04930	N	N	Y	32	SEC/SVC - REPAIR	472.5
FAS_09052	04931	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09053	04932	N	N	N	1	CUSTOMER ISSUE	-
FAS_09054	04933	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09055	04934	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09057	04935	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09058	04936	Y	N	Y	1	SEC/SVC - REPLACE	708.75

FAS_09059	04937	N	N	N	1	CUSTOMER ISSUE	-
FAS_09060	04938	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09061	04939	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09062	04940	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09064	04941	N	N	N	1	CUSTOMER ISSUE	-
FAS_09066	04942	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09089	04943	N	N	N	1	CUSTOMER ISSUE	-
FAS_09090	04944	N	N	N	1	CUSTOMER ISSUE	-
FAS_09091	04945	N	N	N	1	CUSTOMER ISSUE	-
FAS_09095	04946	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09097	04947	N	N	N	1	CUSTOMER ISSUE	-
FAS_09099	04948	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09100	04949	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09103	04950	N	N	N	1	CUSTOMER ISSUE	-
FAS_09104	04951	N	N	N	1	CUSTOMER ISSUE	-
FAS_09107	04952	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_09108	04953	N	N	N	2	CUSTOMER ISSUE	-
FAS_09109	04954	N	N	N	1	CUSTOMER ISSUE	-
FAS_09110	04955	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09111	04956	N	N	N	1	CUSTOMER ISSUE	-
FAS_09112	04957	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09115	04958	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09117	04959	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09119	04960	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09120	04961	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09121	04962	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_09123	04963	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09125	04964	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_09127	04965	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09130	04966	N	N	N	1	CUSTOMER ISSUE	-
FAS_09132	04967	N	N	N	1	CUSTOMER ISSUE	-
FAS_09133	04968	N	N	N	1	CUSTOMER ISSUE	-
FAS_09135	04969	N	N	N	1	CUSTOMER ISSUE	-
FAS_09136	04970	N	N	N	1	CUSTOMER ISSUE	-
FAS_09138	04971	N	N	N	1	CUSTOMER ISSUE	-
FAS_09139	04972	N	N	N	1	CUSTOMER ISSUE	-
FAS_09140	04973	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09141	04974	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09142	04975	N	N	N	1	CUSTOMER ISSUE	-
FAS_09143	04976	N	N	N	1	CUSTOMER ISSUE	-
FAS_09145	04977	N	N	N	1	CUSTOMER ISSUE	-
FAS_09146	04978	N	N	N	1	CUSTOMER ISSUE	-
FAS_09147	04979	N	N	N	1	CUSTOMER ISSUE	-
FAS_09148	04980	N	N	N	1	CUSTOMER ISSUE	-
FAS_09149	04981	N	N	N	1	CUSTOMER ISSUE	-
FAS_09150	04982	N	N	N	1	CUSTOMER ISSUE	-
FAS_09151	04983	N	N	N	2	CUSTOMER ISSUE	-
FAS_09152	04984	N	N	N	2	CUSTOMER ISSUE	-
FAS_09153	04985	N	N	N	1	CUSTOMER ISSUE	-
FAS_09154	04986	N	N	N	1	CUSTOMER ISSUE	-
FAS_09165	04987	N	N	N	1	CUSTOMER ISSUE	-
FAS_09166	04988	N	N	N	1	CUSTOMER ISSUE	-
FAS_09167	04989	N	N	N	1	CUSTOMER ISSUE	-
FAS_09169	04990	N	N	N	1	CUSTOMER ISSUE	-
FAS_09171	04991	N	N	N	1	CUSTOMER ISSUE	-
FAS_09172	04992	N	N	N	1	CUSTOMER ISSUE	-
FAS_09173	04993	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09177	04994	N	N	N	1	CUSTOMER ISSUE	-
FAS_09178	04995	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09179	04996	N	N	N	1	CUSTOMER ISSUE	-
FAS_09182	04997	N	N	N	6	CUSTOMER ISSUE	-
FAS_09183	04998	N	N	N	1	CUSTOMER ISSUE	-
FAS_09184	04999	N	N	N	1	CUSTOMER ISSUE	-
FAS_09186	05000	N	N	N	1	CUSTOMER ISSUE	-
FAS_09187	05001	N	N	N	1	CUSTOMER ISSUE	-
FAS_09191	05002	N	N	N	1	CUSTOMER ISSUE	-
FAS_09192	05003	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_09195	05004	N	N	N	1	CUSTOMER ISSUE	-
FAS_09198	05005	N	N	N	1	CUSTOMER ISSUE	-
FAS_09202	05006	N	N	N	1	CUSTOMER ISSUE	-
FAS_09204	05007	N	N	N	1	CUSTOMER ISSUE	-
FAS_09206	05008	N	N	N	1	CUSTOMER ISSUE	-
FAS_09209	05009	N	N	N	1	CUSTOMER ISSUE	-
FAS_09211	05010	N	N	N	1	CUSTOMER ISSUE	-
FAS_09212	05011	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09215	05012	N	N	N	1	CUSTOMER ISSUE	-
FAS_09218	05013	N	N	N	1	CUSTOMER ISSUE	-
FAS_09219	05014	N	N	N	1	CUSTOMER ISSUE	-
FAS_09223	05015	N	N	N	1	CUSTOMER ISSUE	-
FAS_09224	05016	N	N	N	1	CUSTOMER ISSUE	-

FAS_09227	05017	N	N	N	1	CUSTOMER ISSUE	-
FAS_09229	05018	N	N	N	1	CUSTOMER ISSUE	-
FAS_09230	05019	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09233	05020	N	N	N	1	CUSTOMER ISSUE	-
FAS_09234	05021	N	N	N	1	CUSTOMER ISSUE	-
FAS_09235	05022	N	N	N	1	CUSTOMER ISSUE	-
FAS_09236	05023	N	N	N	1	CUSTOMER ISSUE	-
FAS_09237	05024	N	N	N	1	CUSTOMER ISSUE	-
FAS_09238	05025	N	N	N	1	CUSTOMER ISSUE	-
FAS_09239	05026	N	N	N	1	CUSTOMER ISSUE	-
FAS_09240	05027	N	N	N	1	CUSTOMER ISSUE	-
FAS_09241	05028	N	N	N	1	CUSTOMER ISSUE	-
FAS_09242	05029	N	N	N	2	CUSTOMER ISSUE	-
FAS_09243	05030	N	N	N	1	CUSTOMER ISSUE	-
FAS_09244	05031	N	N	N	1	CUSTOMER ISSUE	-
FAS_09245	05032	N	N	N	1	CUSTOMER ISSUE	-
FAS_09246	05033	N	N	N	1	CUSTOMER ISSUE	-
FAS_09247	05034	N	N	N	1	CUSTOMER ISSUE	-
FAS_09248	05035	N	N	N	1	CUSTOMER ISSUE	-
FAS_09249	05036	N	N	N	1	CUSTOMER ISSUE	-
FAS_09250	05037	N	N	N	1	CUSTOMER ISSUE	-
FAS_09251	05038	N	N	N	1	CUSTOMER ISSUE	-
FAS_09252	05039	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09253	05040	N	N	N	1	CUSTOMER ISSUE	-
FAS_09255	05041	N	N	N	1	CUSTOMER ISSUE	-
FAS_09256	05042	N	N	N	1	CUSTOMER ISSUE	-
FAS_09257	05043	N	N	N	19	CUSTOMER ISSUE	-
FAS_09259	05044	N	N	N	1	CUSTOMER ISSUE	-
FAS_09260	05045	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09261	05046	N	N	N	1	CUSTOMER ISSUE	-
FAS_09263	05047	N	N	N	1	CUSTOMER ISSUE	-
FAS_09264	05048	N	N	N	1	CUSTOMER ISSUE	-
FAS_09266	05049	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09272	05050	N	N	N	1	CUSTOMER ISSUE	-
FAS_09274	05051	N	N	N	1	CUSTOMER ISSUE	-
FAS_09275	05052	N	N	N	1	CUSTOMER ISSUE	-
FAS_09276	05053	N	N	N	1	CUSTOMER ISSUE	-
FAS_09277	05054	N	N	N	1	CUSTOMER ISSUE	-
FAS_09278	05055	N	N	N	1	CUSTOMER ISSUE	-
FAS_09279	05056	N	N	N	1	CUSTOMER ISSUE	-
FAS_09280	05057	N	N	N	1	CUSTOMER ISSUE	-
FAS_09281	05058	N	N	N	1	CUSTOMER ISSUE	-
FAS_09282	05059	N	N	N	1	CUSTOMER ISSUE	-
FAS_09283	05060	N	N	N	1	CUSTOMER ISSUE	-
FAS_09284	05061	N	N	N	1	CUSTOMER ISSUE	-
FAS_09285	05062	N	N	N	1	CUSTOMER ISSUE	-
FAS_09286	05063	N	N	N	1	CUSTOMER ISSUE	-
FAS_09288	05064	N	N	N	1	CUSTOMER ISSUE	-
FAS_09290	05065	N	N	N	1	CUSTOMER ISSUE	-
FAS_09291	05066	N	N	N	1	CUSTOMER ISSUE	-
FAS_09292	05067	N	N	N	1	CUSTOMER ISSUE	-
FAS_09293	05068	N	N	N	1	CUSTOMER ISSUE	-
FAS_09294	05069	N	N	N	1	CUSTOMER ISSUE	-
FAS_09295	05070	N	N	N	1	CUSTOMER ISSUE	-
FAS_09296	05071	N	N	N	1	CUSTOMER ISSUE	-
FAS_09297	05072	N	N	N	1	CUSTOMER ISSUE	-
FAS_09298	05073	N	N	N	1	CUSTOMER ISSUE	-
FAS_09299	05074	N	N	N	1	CUSTOMER ISSUE	-
FAS_09301	05075	N	N	N	1	CUSTOMER ISSUE	-
FAS_09302	05076	N	N	N	1	CUSTOMER ISSUE	-
FAS_09307	05077	N	N	N	1	CUSTOMER ISSUE	-
FAS_09312	05078	N	N	N	1	CUSTOMER ISSUE	-
FAS_09315	05079	N	N	N	1	CUSTOMER ISSUE	-
FAS_09316	05080	N	N	N	1	CUSTOMER ISSUE	-
FAS_09317	05081	N	N	N	1	CUSTOMER ISSUE	-
FAS_09318	05082	N	N	N	1	CUSTOMER ISSUE	-
FAS_09319	05083	N	N	N	1	CUSTOMER ISSUE	-
FAS_09320	05084	N	N	N	1	CUSTOMER ISSUE	-
FAS_09322	05085	N	N	N	1	CUSTOMER ISSUE	-
FAS_09323	05086	N	N	N	1	CUSTOMER ISSUE	-
FAS_09324	05087	N	N	N	1	CUSTOMER ISSUE	-
FAS_09325	05088	N	N	N	1	CUSTOMER ISSUE	-
FAS_09326	05089	N	N	N	1	CUSTOMER ISSUE	-
FAS_09328	05090	N	N	N	1	CUSTOMER ISSUE	-
FAS_09329	05091	N	N	N	1	CUSTOMER ISSUE	-
FAS_09330	05092	N	N	N	1	CUSTOMER ISSUE	-
FAS_09332	05093	N	N	N	1	CUSTOMER ISSUE	-
FAS_09339	05094	N	N	N	1	CUSTOMER ISSUE	-
FAS_09340	05095	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09341	05096	Y	N	N	1	CUSTOMER ISSUE	-

FAS_09342	05097	N	N	N	1	CUSTOMER ISSUE	-
FAS_09343	05098	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09344	05099	N	N	N	1	CUSTOMER ISSUE	-
FAS_09345	05100	N	N	N	1	CUSTOMER ISSUE	-
FAS_09346	05101	N	N	N	9	CUSTOMER ISSUE	-
FAS_09347	05102	N	N	N	1	CUSTOMER ISSUE	-
FAS_09348	05103	N	N	N	1	CUSTOMER ISSUE	-
FAS_09349	05104	N	N	N	1	CUSTOMER ISSUE	-
FAS_09350	05105	N	N	N	1	CUSTOMER ISSUE	-
FAS_09351	05106	N	N	N	1	CUSTOMER ISSUE	-
FAS_09352	05107	N	N	N	1	CUSTOMER ISSUE	-
FAS_09353	05108	N	N	N	26	CUSTOMER ISSUE	-
FAS_09354	05109	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09355	05110	N	N	N	1	CUSTOMER ISSUE	-
FAS_09356	05111	N	N	N	1	CUSTOMER ISSUE	-
FAS_09357	05112	N	N	N	2	CUSTOMER ISSUE	-
FAS_09358	05113	N	N	N	1	CUSTOMER ISSUE	-
FAS_09360	05114	Y	N	N	9	CUSTOMER ISSUE	-
FAS_09362	05115	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09363	05116	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09364	05117	N	N	N	1	CUSTOMER ISSUE	-
FAS_09367	05118	N	N	N	1	CUSTOMER ISSUE	-
FAS_09369	05119	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09370	05120	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09371	05121	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09372	05122	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09373	05123	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09374	05124	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09375	05125	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09376	05126	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09377	05127	N	N	N	3	CUSTOMER ISSUE	-
FAS_09378	05128	N	N	N	1	CUSTOMER ISSUE	-
FAS_09380	05129	N	N	N	1	CUSTOMER ISSUE	-
FAS_09381	05130	N	N	N	1	CUSTOMER ISSUE	-
FAS_09382	05131	N	N	N	1	CUSTOMER ISSUE	-
FAS_09385	05132	N	N	N	1	CUSTOMER ISSUE	-
FAS_09387	05133	N	N	N	1	CUSTOMER ISSUE	-
FAS_09388	05134	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09389	05135	N	N	N	1	CUSTOMER ISSUE	-
FAS_09390	05136	N	N	N	1	CUSTOMER ISSUE	-
FAS_09391	05137	N	N	N	1	CUSTOMER ISSUE	-
FAS_09392	05138	N	N	N	9	CUSTOMER ISSUE	-
FAS_09393	05139	N	N	N	1	CUSTOMER ISSUE	-
FAS_09394	05140	N	N	N	1	CUSTOMER ISSUE	-
FAS_09396	05141	N	N	N	1	CUSTOMER ISSUE	-
FAS_09397	05142	N	N	N	1	CUSTOMER ISSUE	-
FAS_09398	05143	N	N	N	1	CUSTOMER ISSUE	-
FAS_09399	05144	N	N	N	1	CUSTOMER ISSUE	-
FAS_09400	05145	N	N	N	1	CUSTOMER ISSUE	-
FAS_09401	05146	N	N	N	1	CUSTOMER ISSUE	-
FAS_09402	05147	N	N	N	1	CUSTOMER ISSUE	-
FAS_09403	05148	N	N	N	1	CUSTOMER ISSUE	-
FAS_09404	05149	N	N	N	1	CUSTOMER ISSUE	-
FAS_09406	05150	N	N	N	1	CUSTOMER ISSUE	-
FAS_09407	05151	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09408	05152	N	N	N	1	CUSTOMER ISSUE	-
FAS_09409	05153	N	N	N	1	CUSTOMER ISSUE	-
FAS_09410	05154	N	N	N	1	CUSTOMER ISSUE	-
FAS_09413	05155	N	N	N	1	CUSTOMER ISSUE	-
FAS_09417	05156	N	N	N	1	CUSTOMER ISSUE	-
FAS_09418	05157	N	N	N	1	CUSTOMER ISSUE	-
FAS_09420	05158	N	N	N	1	CUSTOMER ISSUE	-
FAS_09424	05159	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09425	05160	N	N	N	1	CUSTOMER ISSUE	-
FAS_09426	05161	N	N	N	1	CUSTOMER ISSUE	-
FAS_09427	05162	N	N	N	1	CUSTOMER ISSUE	-
FAS_09428	05163	N	N	N	1	CUSTOMER ISSUE	-
FAS_09429	05164	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09430	05165	N	N	N	1	CUSTOMER ISSUE	-
FAS_09431	05166	N	N	N	1	CUSTOMER ISSUE	-
FAS_09432	05167	N	N	N	1	CUSTOMER ISSUE	-
FAS_09433	05168	N	N	N	1	CUSTOMER ISSUE	-
FAS_09434	05169	N	N	N	1	CUSTOMER ISSUE	-
FAS_09435	05170	N	N	N	1	CUSTOMER ISSUE	-
FAS_09436	05171	N	N	N	1	CUSTOMER ISSUE	-
FAS_09437	05172	N	N	N	1	CUSTOMER ISSUE	-
FAS_09438	05173	N	N	N	2	CUSTOMER ISSUE	-
FAS_09440	05174	N	N	N	1	CUSTOMER ISSUE	-
FAS_09441	05175	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09442	05176	N	N	N	1	CUSTOMER ISSUE	-

FAS_09443	05177	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09445	05178	N	N	N	1	CUSTOMER ISSUE	-
FAS_09446	05179	N	N	N	1	CUSTOMER ISSUE	-
FAS_09447	05180	N	N	N	1	CUSTOMER ISSUE	-
FAS_09449	05181	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09450	05182	N	N	N	1	CUSTOMER ISSUE	-
FAS_09453	05183	N	N	N	1	CUSTOMER ISSUE	-
FAS_09454	05184	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09455	05185	N	N	N	1	CUSTOMER ISSUE	-
FAS_09456	05186	N	N	N	1	CUSTOMER ISSUE	-
FAS_09461	05187	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09464	05188	N	N	N	1	CUSTOMER ISSUE	-
FAS_09465	05189	N	N	N	1	CUSTOMER ISSUE	-
FAS_09467	05190	N	N	N	1	CUSTOMER ISSUE	-
FAS_09469	05191	N	N	N	1	CUSTOMER ISSUE	-
FAS_09472	05192	N	N	N	1	CUSTOMER ISSUE	-
FAS_09474	05193	N	N	N	1	CUSTOMER ISSUE	-
FAS_09475	05194	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09476	05195	N	N	N	1	CUSTOMER ISSUE	-
FAS_09477	05196	N	N	N	1	CUSTOMER ISSUE	-
FAS_09478	05197	N	N	N	1	CUSTOMER ISSUE	-
FAS_09479	05198	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09480	05199	N	N	N	1	CUSTOMER ISSUE	-
FAS_09486	05200	N	N	N	1	CUSTOMER ISSUE	-
FAS_09487	05201	N	N	N	1	CUSTOMER ISSUE	-
FAS_09488	05202	N	N	N	1	CUSTOMER ISSUE	-
FAS_09489	05203	N	N	N	1	CUSTOMER ISSUE	-
FAS_09491	05204	N	N	N	1	CUSTOMER ISSUE	-
FAS_09492	05205	N	N	N	1	CUSTOMER ISSUE	-
FAS_09493	05206	N	N	N	1	CUSTOMER ISSUE	-
FAS_09494	05207	N	N	N	1	CUSTOMER ISSUE	-
FAS_09495	05208	N	N	N	1	CUSTOMER ISSUE	-
FAS_09498	05209	N	N	N	1	CUSTOMER ISSUE	-
FAS_09499	05210	N	N	N	1	CUSTOMER ISSUE	-
FAS_09501	05211	N	N	N	1	CUSTOMER ISSUE	-
FAS_09502	05212	N	N	N	1	CUSTOMER ISSUE	-
FAS_09503	05213	N	N	N	1	CUSTOMER ISSUE	-
FAS_09507	05214	N	N	N	1	CUSTOMER ISSUE	-
FAS_09509	05215	N	N	N	1	CUSTOMER ISSUE	-
FAS_09510	05216	N	N	N	1	CUSTOMER ISSUE	-
FAS_09511	05217	N	N	N	1	CUSTOMER ISSUE	-
FAS_09514	05218	N	N	N	1	CUSTOMER ISSUE	-
FAS_09516	05219	N	N	N	1	CUSTOMER ISSUE	-
FAS_09517	05220	N	N	N	1	CUSTOMER ISSUE	-
FAS_09534	05221	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09537	05222	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09538	05223	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09540	05224	N	N	N	2	CUSTOMER ISSUE	-
FAS_09542	05225	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09544	05226	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_09546	05227	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_09547	05228	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_09552	05229	N	N	N	1	CUSTOMER ISSUE	-
FAS_09566	05230	N	N	N	1	CUSTOMER ISSUE	-
FAS_09676	05231	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09677	05232	N	N	N	1	CUSTOMER ISSUE	-
FAS_09682	05233	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09686	05234	N	N	N	1	CUSTOMER ISSUE	-
FAS_09688	05235	N	N	N	1	CUSTOMER ISSUE	-
FAS_09690	05236	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09691	05237	N	N	N	1	CUSTOMER ISSUE	-
FAS_09692	05238	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09693	05239	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09694	05240	N	N	N	1	CUSTOMER ISSUE	-
FAS_09695	05241	N	N	N	2	CUSTOMER ISSUE	-
FAS_09696	05242	N	N	N	1	CUSTOMER ISSUE	-
FAS_09697	05243	N	N	N	1	CUSTOMER ISSUE	-
FAS_09698	05244	N	N	N	1	CUSTOMER ISSUE	-
FAS_09699	05245	N	N	N	1	CUSTOMER ISSUE	-
FAS_09700	05246	N	N	N	1	CUSTOMER ISSUE	-
FAS_09701	05247	N	N	N	2	CUSTOMER ISSUE	-
FAS_09702	05248	N	N	N	1	CUSTOMER ISSUE	-
FAS_09703	05249	N	N	N	1	CUSTOMER ISSUE	-
FAS_09704	05250	N	N	N	1	CUSTOMER ISSUE	-
FAS_09706	05251	N	N	N	1	CUSTOMER ISSUE	-
FAS_09708	05252	N	N	N	1	CUSTOMER ISSUE	-
FAS_09709	05253	N	N	Y	1	TX - REPLACE	2500
FAS_09712	05254	N	N	N	1	CUSTOMER ISSUE	-
FAS_09714	05255	N	N	N	1	CUSTOMER ISSUE	-
FAS_09715	05256	N	N	N	1	CUSTOMER ISSUE	-

FAS_09717	05257	N	N	N	1	CUSTOMER ISSUE	-
FAS_09724	05258	N	N	N	1	CUSTOMER ISSUE	-
FAS_09737	05259	Y	N	N	21	CUSTOMER ISSUE	-
FAS_09738	05260	N	N	N	1	CUSTOMER ISSUE	-
FAS_09739	05261	N	N	N	1	CUSTOMER ISSUE	-
FAS_09740	05262	N	N	N	1	CUSTOMER ISSUE	-
FAS_09741	05263	N	N	N	1	CUSTOMER ISSUE	-
FAS_09742	05264	N	N	N	1	CUSTOMER ISSUE	-
FAS_09743	05265	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09745	05266	N	N	N	1	CUSTOMER ISSUE	-
FAS_09749	05267	N	N	N	1	CUSTOMER ISSUE	-
FAS_09750	05268	N	N	N	1	CUSTOMER ISSUE	-
FAS_09752	05269	N	N	N	1	CUSTOMER ISSUE	-
FAS_09753	05270	N	N	N	1	CUSTOMER ISSUE	-
FAS_09754	05271	N	N	N	1	CUSTOMER ISSUE	-
FAS_09755	05272	N	N	N	1	CUSTOMER ISSUE	-
FAS_09756	05273	N	N	N	1	CUSTOMER ISSUE	-
FAS_09757	05274	N	N	N	1	CUSTOMER ISSUE	-
FAS_09758	05275	N	N	N	1	CUSTOMER ISSUE	-
FAS_09760	05276	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09761	05277	N	N	N	1	CUSTOMER ISSUE	-
FAS_09762	05278	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09763	05279	N	N	N	2	CUSTOMER ISSUE	-
FAS_09765	05280	N	N	N	2	CUSTOMER ISSUE	-
FAS_09766	05281	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09767	05282	N	N	N	1	CUSTOMER ISSUE	-
FAS_09770	05283	N	N	N	1	CUSTOMER ISSUE	-
FAS_09772	05284	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09773	05285	N	N	N	2	CUSTOMER ISSUE	-
FAS_09776	05286	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09777	05287	N	N	N	1	CUSTOMER ISSUE	-
FAS_09778	05288	N	N	N	1	CUSTOMER ISSUE	-
FAS_09779	05289	N	N	N	1	CUSTOMER ISSUE	-
FAS_09781	05290	N	N	N	1	CUSTOMER ISSUE	-
FAS_09782	05291	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09783	05292	N	N	N	2	CUSTOMER ISSUE	-
FAS_09784	05293	N	N	N	1	CUSTOMER ISSUE	-
FAS_09790	05294	N	N	N	1	CUSTOMER ISSUE	-
FAS_09791	05295	N	N	N	1	CUSTOMER ISSUE	-
FAS_09792	05296	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09794	05297	N	N	N	1	CUSTOMER ISSUE	-
FAS_09795	05298	N	N	N	2	CUSTOMER ISSUE	-
FAS_09796	05299	N	N	N	1	CUSTOMER ISSUE	-
FAS_09797	05300	N	N	N	1	CUSTOMER ISSUE	-
FAS_09798	05301	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09799	05302	N	N	N	1	CUSTOMER ISSUE	-
FAS_09800	05303	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09804	05304	N	N	N	1	CUSTOMER ISSUE	-
FAS_09806	05305	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09807	05306	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09811	05307	N	N	Y	5	DIST - REPLACE FUSE	708.75
FAS_09813	05308	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09814	05309	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09815	05310	N	N	N	1	CUSTOMER ISSUE	-
FAS_09816	05311	N	N	N	1	CUSTOMER ISSUE	-
FAS_09817	05312	N	N	N	1	CUSTOMER ISSUE	-
FAS_09819	05313	N	N	N	1	CUSTOMER ISSUE	-
FAS_09820	05314	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09821	05315	N	N	N	1	CUSTOMER ISSUE	-
FAS_09823	05316	N	N	N	1	CUSTOMER ISSUE	-
FAS_09824	05317	N	N	N	1	CUSTOMER ISSUE	-
FAS_09826	05318	N	N	N	1	CUSTOMER ISSUE	-
FAS_09827	05319	N	N	Y	2	TX/SEC/SVC- REPLACE	3800
FAS_09829	05320	N	N	Y	1	TX - REPLACE	2500
FAS_09831	05321	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_09832	05322	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09833	05323	N	N	N	1	CUSTOMER ISSUE	-
FAS_09834	05324	N	N	N	1	CUSTOMER ISSUE	-
FAS_09838	05325	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_09849	05326	N	N	N	2	CUSTOMER ISSUE	-
FAS_09850	05327	N	N	N	1	CUSTOMER ISSUE	-
FAS_09851	05328	N	N	N	1	CUSTOMER ISSUE	-
FAS_09852	05329	N	N	N	1	CUSTOMER ISSUE	-
FAS_09853	05330	N	N	N	1	CUSTOMER ISSUE	-
FAS_09854	05331	N	N	N	1	CUSTOMER ISSUE	-
FAS_09855	05332	N	N	N	1	CUSTOMER ISSUE	-
FAS_09857	05333	N	N	N	1	CUSTOMER ISSUE	-
FAS_09858	05334	N	N	N	1	CUSTOMER ISSUE	-
FAS_09859	05335	N	N	N	1	CUSTOMER ISSUE	-
FAS_09860	05336	N	N	N	1	CUSTOMER ISSUE	-

FAS_09861	05337	N	N	N	1	CUSTOMER ISSUE	-
FAS_09863	05338	N	N	N	1	CUSTOMER ISSUE	-
FAS_09864	05339	N	N	N	1	CUSTOMER ISSUE	-
FAS_09865	05340	N	N	N	1	CUSTOMER ISSUE	-
FAS_09866	05341	N	N	N	1	CUSTOMER ISSUE	-
FAS_09867	05342	N	N	N	1	CUSTOMER ISSUE	-
FAS_09868	05343	N	N	N	1	CUSTOMER ISSUE	-
FAS_09875	05344	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
FAS_09877	05345	N	N	N	1	CUSTOMER ISSUE	-
FAS_09878	05346	N	N	N	1	CUSTOMER ISSUE	-
FAS_09879	05347	N	N	N	1	CUSTOMER ISSUE	-
FAS_09880	05348	N	N	N	1	CUSTOMER ISSUE	-
FAS_09884	05349	N	N	N	1	CUSTOMER ISSUE	-
FAS_09886	05350	N	N	N	1	CUSTOMER ISSUE	-
FAS_09887	05351	N	N	N	1	CUSTOMER ISSUE	-
FAS_09888	05352	N	N	N	1	CUSTOMER ISSUE	-
FAS_09889	05353	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09890	05354	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_09891	05355	N	N	N	1	CUSTOMER ISSUE	-
FAS_09892	05356	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09894	05357	N	N	N	1	CUSTOMER ISSUE	-
FAS_09900	05358	N	N	N	1	CUSTOMER ISSUE	-
FAS_09903	05359	N	N	N	1	CUSTOMER ISSUE	-
FAS_09908	05360	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_09929	05361	N	N	N	1	CUSTOMER ISSUE	-
FAS_09933	05362	N	N	N	1	CUSTOMER ISSUE	-
FAS_09939	05363	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_09956	05364	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_09957	05365	N	N	N	1	CUSTOMER ISSUE	-
FAS_09958	05366	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09961	05367	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09962	05368	N	N	N	1	CUSTOMER ISSUE	-
FAS_09963	05369	N	N	N	1	CUSTOMER ISSUE	-
FAS_09964	05370	N	N	N	1	CUSTOMER ISSUE	-
FAS_09965	05371	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
FAS_09973	05372	N	N	N	1	CUSTOMER ISSUE	-
FAS_09977	05373	N	N	N	1	CUSTOMER ISSUE	-
FAS_09978	05374	N	N	N	1	CUSTOMER ISSUE	-
FAS_09979	05375	N	N	N	1	CUSTOMER ISSUE	-
FAS_09981	05376	N	N	N	1	CUSTOMER ISSUE	-
FAS_09982	05377	Y	N	N	2	CUSTOMER ISSUE	-
FAS_09984	05378	N	N	N	1	CUSTOMER ISSUE	-
FAS_09985	05379	N	N	N	1	CUSTOMER ISSUE	-
FAS_09987	05380	N	N	N	1	CUSTOMER ISSUE	-
FAS_09989	05381	N	N	N	1	CUSTOMER ISSUE	-
FAS_09991	05382	N	N	N	1	CUSTOMER ISSUE	-
FAS_09992	05383	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09994	05384	Y	N	N	1	CUSTOMER ISSUE	-
FAS_09995	05385	N	N	N	1	CUSTOMER ISSUE	-
FAS_09996	05386	N	N	N	1	CUSTOMER ISSUE	-
FAS_09997	05387	N	N	N	1	CUSTOMER ISSUE	-
FAS_09999	05388	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10000	05389	N	N	N	1	CUSTOMER ISSUE	-
FAS_10001	05390	Y	N	N	1	CUSTOMER ISSUE	-
FAS_10005	05391	N	N	N	1	CUSTOMER ISSUE	-
FAS_10006	05392	N	N	N	1	CUSTOMER ISSUE	-
FAS_10007	05393	N	N	N	6	CUSTOMER ISSUE	-
FAS_10008	05394	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10009	05395	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10012	05396	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_10013	05397	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_10014	05398	Y	N	Y	1	DIST - REPAIR EQUIPMENT	2500
FAS_10015	05399	N	N	N	1	CUSTOMER ISSUE	-
FAS_10025	05400	N	N	N	1	CUSTOMER ISSUE	-
FAS_10026	05401	Y	N	N	1	CUSTOMER ISSUE	-
FAS_10027	05402	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10030	05403	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10031	05404	N	N	N	1	CUSTOMER ISSUE	-
FAS_10032	05405	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10033	05406	N	N	N	1	CUSTOMER ISSUE	-
FAS_10034	05407	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10035	05408	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10036	05409	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10051	05410	N	N	N	26	CUSTOMER ISSUE	-
FAS_10052	05411	N	N	N	1	CUSTOMER ISSUE	-
FAS_10057	05412	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10059	05413	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10068	05414	N	N	N	1	CUSTOMER ISSUE	-
FAS_10076	05415	Y	N	N	1	CUSTOMER ISSUE	-
FAS_10080	05416	N	N	N	1	CUSTOMER ISSUE	-

FAS_10081	05417	N	N	N	1	CUSTOMER ISSUE	-
FAS_10116	05418	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10117	05419	Y	N	N	1	CUSTOMER ISSUE	-
FAS_10122	05420	N	N	Y	31	SEC/SVC - REPLACE	708.75
FAS_10129	05421	N	N	N	1	CUSTOMER ISSUE	-
FAS_10130	05422	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10132	05423	N	N	N	1	CUSTOMER ISSUE	-
FAS_10135	05424	N	N	N	1	CUSTOMER ISSUE	-
FAS_10156	05425	N	N	N	1	CUSTOMER ISSUE	-
FAS_10163	05426	N	N	N	1	CUSTOMER ISSUE	-
FAS_10166	05427	N	N	N	1	CUSTOMER ISSUE	-
FAS_10168	05428	N	N	N	1	CUSTOMER ISSUE	-
FAS_10169	05429	N	N	Y	32	DIST - REPLACE FUSE	708.75
FAS_10171	05430	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10172	05431	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10173	05432	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10174	05433	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10175	05434	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10177	05435	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10178	05436	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10179	05437	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10180	05438	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10181	05439	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10182	05440	N	N	Y	3	DIST - REPLACE FUSE	708.75
FAS_10183	05441	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10184	05442	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10185	05443	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10186	05444	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10187	05445	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10188	05446	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10190	05447	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10191	05448	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10192	05449	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10210	05450	N	N	N	1	CUSTOMER ISSUE	-
FAS_10221	05451	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10225	05452	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10232	05453	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_10337	05454	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10338	05455	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10339	05456	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10340	05457	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10352	05458	N	N	N	1	CUSTOMER ISSUE	-
FAS_10354	05459	N	N	N	1	CUSTOMER ISSUE	-
FAS_10359	05460	N	N	N	1	CUSTOMER ISSUE	-
FAS_10371	05461	N	N	N	1	CUSTOMER ISSUE	-
FAS_10372	05462	N	N	N	1	CUSTOMER ISSUE	-
FAS_10376	05463	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10383	05464	N	N	N	1	CUSTOMER ISSUE	-
FAS_10385	05465	N	N	N	1	CUSTOMER ISSUE	-
FAS_10386	05466	N	N	N	1	CUSTOMER ISSUE	-
FAS_10405	05467	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10409	05468	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_10410	05469	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10415	05470	N	N	N	1	CUSTOMER ISSUE	-
FAS_10430	05471	N	N	N	1	CUSTOMER ISSUE	-
FAS_10438	05472	N	N	N	1	CUSTOMER ISSUE	-
FAS_10449	05473	N	N	N	1	CUSTOMER ISSUE	-
FAS_10454	05474	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_10483	05475	N	N	N	1	CUSTOMER ISSUE	-
FAS_10495	05476	N	N	N	1	CUSTOMER ISSUE	-
FAS_10499	05477	N	N	N	1	CUSTOMER ISSUE	-
FAS_10512	05478	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10518	05479	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_10520	05480	N	N	N	1	CUSTOMER ISSUE	-
FAS_10521	05481	Y	N	N	1	CUSTOMER ISSUE	-
FAS_10531	05482	N	N	N	1	CUSTOMER ISSUE	-
FAS_10566	05483	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10601	05484	N	N	N	1	CUSTOMER ISSUE	-
FAS_10606	05485	N	N	N	1	CUSTOMER ISSUE	-
FAS_10607	05486	N	N	N	1	CUSTOMER ISSUE	-
FAS_10638	05487	N	N	N	1	CUSTOMER ISSUE	-
FAS_10649	05488	Y	N	N	1	CUSTOMER ISSUE	-
FAS_10656	05489	N	N	N	1	CUSTOMER ISSUE	-
FAS_10659	05490	N	N	N	1	CUSTOMER ISSUE	-
FAS_10660	05491	N	N	N	1	CUSTOMER ISSUE	-
FAS_10662	05492	N	N	N	1	CUSTOMER ISSUE	-
FAS_10767	05493	Y	N	N	1	CUSTOMER ISSUE	-
FAS_10769	05494	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10775	05495	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10776	05496	N	N	Y	1	SEC/SVC - REPLACE	708.75

FAS_10779	05497	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10780	05498	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_10781	05499	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10782	05500	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_10783	05501	N	N	Y	25	SEC/SVC - REPAIR	472.5
FAS_10784	05502	Y	N	Y	14	SEC/SVC - REPAIR	472.5
FAS_10785	05503	Y	N	Y	22	SEC/SVC - REPAIR	472.5
FAS_10786	05504	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10787	05505	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_10788	05506	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10790	05507	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10791	05508	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10792	05509	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10793	05510	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10794	05511	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10795	05512	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10796	05513	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10797	05514	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10798	05515	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10799	05516	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10800	05517	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10801	05518	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10802	05519	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10803	05520	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10804	05521	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10805	05522	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10806	05523	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10807	05524	N	N	N	1	CUSTOMER ISSUE	-
FAS_10808	05525	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10809	05526	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10815	05527	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10816	05528	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10817	05529	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10818	05530	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10819	05531	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10820	05532	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10821	05533	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10822	05534	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10823	05535	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10824	05536	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10825	05537	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10826	05538	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10827	05539	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10828	05540	N	N	N	1	CUSTOMER ISSUE	-
FAS_10830	05541	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10831	05542	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10832	05543	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10834	05544	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10835	05545	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10837	05546	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10838	05547	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10840	05548	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10841	05549	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10842	05550	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_10843	05551	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10844	05552	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10845	05553	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10846	05554	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10847	05555	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10849	05556	Y	N	Y	21	SEC/SVC - REPAIR	472.5
FAS_10852	05557	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10853	05558	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_10854	05559	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_10855	05560	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10856	05561	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_10857	05562	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10860	05563	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10861	05564	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10862	05565	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10863	05566	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10864	05567	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10865	05568	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10866	05569	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10867	05570	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10868	05571	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10869	05572	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10870	05573	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10871	05574	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10872	05575	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10873	05576	N	N	Y	1	SEC/SVC - REPAIR	472.5

FAS_10874	05577	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10875	05578	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10876	05579	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10877	05580	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10878	05581	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10879	05582	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10880	05583	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10881	05584	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10882	05585	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10883	05586	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10884	05587	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_10885	05588	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10887	05589	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10889	05590	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10890	05591	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10891	05592	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10892	05593	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10893	05594	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10894	05595	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10895	05596	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10896	05597	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10897	05598	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10898	05599	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10899	05600	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10900	05601	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10901	05602	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10902	05603	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10903	05604	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10904	05605	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10905	05606	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10906	05607	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10907	05608	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10908	05609	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10909	05610	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10910	05611	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10911	05612	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10912	05613	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10913	05614	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10914	05615	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10915	05616	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10916	05617	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10917	05618	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10918	05619	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10919	05620	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10920	05621	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10921	05622	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10922	05623	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10923	05624	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10924	05625	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10925	05626	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10926	05627	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10927	05628	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10928	05629	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10929	05630	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10930	05631	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10931	05632	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10932	05633	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10933	05634	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10934	05635	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10935	05636	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10936	05637	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10937	05638	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10938	05639	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10939	05640	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10940	05641	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10941	05642	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10942	05643	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10943	05644	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10944	05645	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10945	05646	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10946	05647	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10947	05648	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10948	05649	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_10949	05650	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10950	05651	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10951	05652	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10952	05653	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10953	05654	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10954	05655	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10955	05656	N	N	Y	1	SEC/SVC - REPAIR	472.5

FAS_10956	05657	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10957	05658	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10958	05659	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_10959	05660	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10960	05661	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10961	05662	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10962	05663	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10963	05664	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10964	05665	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_10965	05666	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10966	05667	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10967	05668	N	N	Y	6	SEC/SVC - REPAIR	472.5
FAS_10970	05669	N	N	N	1	CUSTOMER ISSUE	-
FAS_10971	05670	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10972	05671	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10973	05672	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10974	05673	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10975	05674	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10976	05675	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10977	05676	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10978	05677	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10979	05678	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10980	05679	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10981	05680	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10982	05681	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10983	05682	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10984	05683	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_10985	05684	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_10986	05685	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10987	05686	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10988	05687	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10989	05688	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10990	05689	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10991	05690	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10992	05691	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10993	05692	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10994	05693	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10995	05694	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10996	05695	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10997	05696	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10998	05697	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_10999	05698	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11000	05699	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11001	05700	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11002	05701	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11003	05702	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11004	05703	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11005	05704	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11006	05705	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11007	05706	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11008	05707	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_11009	05708	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11010	05709	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11011	05710	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11012	05711	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11014	05712	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11016	05713	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11018	05714	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11019	05715	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11020	05716	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11022	05717	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11023	05718	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11024	05719	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11025	05720	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11027	05721	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11028	05722	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11029	05723	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11030	05724	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11031	05725	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11032	05726	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11033	05727	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11034	05728	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11035	05729	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11036	05730	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11037	05731	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11038	05732	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11039	05733	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11040	05734	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11041	05735	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11042	05736	N	N	Y	1	SEC/SVC - REPAIR	472.5

FAS_11043	05737	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11044	05738	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11045	05739	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11046	05740	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11047	05741	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11048	05742	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11049	05743	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11050	05744	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11051	05745	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11052	05746	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11053	05747	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11054	05748	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11055	05749	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11056	05750	N	N	N	1	CUSTOMER ISSUE	-
FAS_11057	05751	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11058	05752	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11059	05753	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11060	05754	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11061	05755	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11062	05756	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11063	05757	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_11064	05758	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11065	05759	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11066	05760	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11067	05761	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11068	05762	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11069	05763	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11070	05764	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11071	05765	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11072	05766	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11073	05767	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11075	05768	N	N	N	1	CUSTOMER ISSUE	-
FAS_11077	05769	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11078	05770	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11079	05771	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_11080	05772	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11082	05773	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11084	05774	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11085	05775	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11087	05776	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11088	05777	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11089	05778	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11090	05779	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11091	05780	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11092	05781	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11093	05782	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11094	05783	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11095	05784	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11096	05785	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11097	05786	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11098	05787	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11099	05788	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11100	05789	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11101	05790	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11102	05791	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11103	05792	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11104	05793	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11105	05794	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11106	05795	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11107	05796	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11108	05797	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11109	05798	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11110	05799	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11111	05800	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_11112	05801	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11113	05802	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11114	05803	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11115	05804	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11116	05805	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11117	05806	N	N	Y	6	SEC/SVC - REPAIR	472.5
FAS_11118	05807	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11119	05808	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11120	05809	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11121	05810	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11122	05811	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11123	05812	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11124	05813	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11125	05814	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11126	05815	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11127	05816	N	N	Y	1	SEC/SVC - REPAIR	472.5

FAS_11128	05817	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11129	05818	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11130	05819	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11132	05820	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11133	05821	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11134	05822	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11135	05823	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11136	05824	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11137	05825	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11138	05826	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11139	05827	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11140	05828	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11141	05829	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11142	05830	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11143	05831	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11144	05832	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11146	05833	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11147	05834	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11148	05835	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11149	05836	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11150	05837	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11151	05838	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11157	05839	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11158	05840	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11159	05841	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11160	05842	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11161	05843	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11162	05844	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11163	05845	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11164	05846	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11165	05847	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11166	05848	N	N	N	1	CUSTOMER ISSUE	-
FAS_11167	05849	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11168	05850	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11169	05851	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11170	05852	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11171	05853	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11172	05854	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11173	05855	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11174	05856	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11175	05857	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11176	05858	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11177	05859	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11178	05860	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11179	05861	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11180	05862	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11181	05863	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11182	05864	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11183	05865	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11184	05866	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11185	05867	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11186	05868	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11188	05869	N	N	Y	16	SEC/SVC - REPAIR	472.5
FAS_11190	05870	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11191	05871	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11192	05872	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11193	05873	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11194	05874	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11195	05875	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11196	05876	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11197	05877	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11198	05878	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_11199	05879	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11200	05880	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11202	05881	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11205	05882	N	N	N	8	CUSTOMER ISSUE	-
FAS_11207	05883	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11209	05884	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11210	05885	N	N	N	1	CUSTOMER ISSUE	-
FAS_11214	05886	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11215	05887	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11216	05888	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11217	05889	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11218	05890	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11219	05891	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11220	05892	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11223	05893	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11224	05894	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11227	05895	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_11228	05896	N	N	Y	1	SEC/SVC - REPLACE	708.75

FAS_11229	05897	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11230	05898	N	N	Y	1	TX - REPLACE	2500
FAS_11232	05899	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11233	05900	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11234	05901	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11235	05902	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11241	05903	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11242	05904	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11244	05905	N	N	Y	9	SEC/SVC - REPLACE	708.75
FAS_11245	05906	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11247	05907	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11249	05908	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11250	05909	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11251	05910	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11252	05911	N	N	Y	4	SEC/SVC - REPLACE	708.75
FAS_11253	05912	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11254	05913	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11255	05914	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11256	05915	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_11257	05916	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11258	05917	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11261	05918	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11262	05919	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11263	05920	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11264	05921	N	N	Y	8	SEC/SVC - REPLACE	708.75
FAS_11265	05922	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11266	05923	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11268	05924	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11273	05925	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11274	05926	Y	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11276	05927	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11278	05928	Y	N	Y	4	SEC/SVC - REPLACE	708.75
FAS_11280	05929	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11281	05930	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11282	05931	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11284	05932	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11285	05933	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11286	05934	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11289	05935	N	N	Y	3	SEC/SVC - REPLACE	708.75
FAS_11290	05936	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_11291	05937	N	N	N	1	CUSTOMER ISSUE	-
FAS_11292	05938	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11293	05939	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11294	05940	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11295	05941	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11296	05942	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_11297	05943	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11298	05944	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11299	05945	N	N	N	1	CUSTOMER ISSUE	-
FAS_11300	05946	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11301	05947	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11302	05948	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11303	05949	N	N	Y	30	SEC/SVC - REPLACE	708.75
FAS_11304	05950	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11305	05951	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11308	05952	N	N	Y	31	SEC/SVC - REPLACE	708.75
FAS_11309	05953	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11310	05954	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11311	05955	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11312	05956	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11314	05957	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11315	05958	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11316	05959	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11317	05960	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11321	05961	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_11322	05962	Y	N	Y	1	TX - REPLACE	2500
FAS_11331	05963	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11333	05964	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11334	05965	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11335	05966	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11337	05967	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11338	05968	N	N	Y	2	TX - REPLACE	2500
FAS_11339	05969	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11340	05970	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11341	05971	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11342	05972	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11343	05973	N	N	Y	7	SEC/SVC - REPLACE	708.75
FAS_11344	05974	N	N	N	1	CUSTOMER ISSUE	-
FAS_11345	05975	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11346	05976	N	N	Y	2	SEC/SVC - REPLACE	708.75

FAS_11347	05977	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11349	05978	N	N	Y	1	TX - REPLACE	2500
FAS_11351	05979	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11356	05980	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11357	05981	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11359	05982	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11360	05983	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11361	05984	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11362	05985	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11363	05986	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11364	05987	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11365	05988	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11366	05989	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11367	05990	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11368	05991	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11369	05992	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11370	05993	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11371	05994	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11372	05995	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11374	05996	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11379	05997	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11380	05998	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11381	05999	N	N	Y	3	SEC/SVC - REPLACE	708.75
FAS_11384	06000	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11385	06001	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11386	06002	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11389	06003	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11393	06004	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11396	06005	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11408	06006	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11409	06007	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11410	06008	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11411	06009	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11412	06010	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11413	06011	N	N	Y	9	SEC/SVC - REPLACE	708.75
FAS_11415	06012	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11416	06013	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11420	06014	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11421	06015	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11422	06016	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11428	06017	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11430	06018	N	N	Y	29	SEC/SVC - REPLACE	708.75
FAS_11432	06019	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11433	06020	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11434	06021	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11435	06022	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11436	06023	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11437	06024	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11438	06025	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11440	06026	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11441	06027	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_11442	06028	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11444	06029	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11445	06030	Y	N	N	1	CUSTOMER ISSUE	-
FAS_11446	06031	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11450	06032	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11451	06033	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11452	06034	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11453	06035	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11454	06036	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11455	06037	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_11456	06038	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11457	06039	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11458	06040	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11459	06041	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11460	06042	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11461	06043	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11462	06044	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11463	06045	N	N	Y	12	SEC/SVC - REPLACE	708.75
FAS_11464	06046	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11465	06047	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11466	06048	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11467	06049	N	N	N	1	CUSTOMER ISSUE	-
FAS_11468	06050	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11469	06051	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11470	06052	Y	N	N	1	CUSTOMER ISSUE	-
FAS_11471	06053	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11472	06054	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11473	06055	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11475	06056	N	N	Y	1	SEC/SVC - REPLACE	708.75

FAS_11476	06057	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11477	06058	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11478	06059	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11479	06060	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11480	06061	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11481	06062	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11482	06063	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11483	06064	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11484	06065	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_11485	06066	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11486	06067	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11487	06068	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11488	06069	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11489	06070	N	N	Y	4	SEC/SVC - REPLACE	708.75
FAS_11490	06071	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11491	06072	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11492	06073	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11494	06074	Y	N	N	3	CUSTOMER ISSUE	-
FAS_11495	06075	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11496	06076	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11497	06077	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11498	06078	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11499	06079	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11500	06080	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_11501	06081	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11502	06082	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11503	06083	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11504	06084	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11506	06085	N	N	Y	17	DIST - REPLACE FUSE	708.75
FAS_11507	06086	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11508	06087	N	N	Y	33	DIST - REPLACE FUSE	708.75
FAS_11509	06088	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11510	06089	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11540	06090	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11542	06091	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11570	06092	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11571	06093	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11572	06094	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11573	06095	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11574	06096	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11577	06097	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11578	06098	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11622	06099	N	N	Y	3	DIST - REPLACE FUSE	708.75
FAS_11623	06100	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11624	06101	N	N	Y	2	DIST - REPLACE FUSE	708.75
FAS_11629	06102	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11630	06103	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11631	06104	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11632	06105	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11633	06106	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_11634	06107	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11635	06108	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_11638	06109	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11639	06110	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11640	06111	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11641	06112	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11642	06113	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11643	06114	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11644	06115	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11645	06116	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11646	06117	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11647	06118	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11648	06119	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11649	06120	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_11650	06121	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11651	06122	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11652	06123	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11653	06124	N	N	Y	3	SEC/SVC - REPLACE	708.75
FAS_11654	06125	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11655	06126	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11656	06127	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11657	06128	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11658	06129	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11659	06130	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11660	06131	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11661	06132	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11662	06133	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11663	06134	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11664	06135	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11665	06136	N	N	Y	1	SEC/SVC - REPLACE	708.75

FAS_11666	06137	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11667	06138	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11668	06139	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11669	06140	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11670	06141	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11671	06142	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_11672	06143	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11673	06144	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11674	06145	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11675	06146	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_11676	06147	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11677	06148	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11678	06149	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11679	06150	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_11680	06151	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11681	06152	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11682	06153	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11683	06154	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11684	06155	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11685	06156	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11686	06157	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11687	06158	N	N	Y	4	SEC/SVC - REPLACE	708.75
FAS_11688	06159	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11689	06160	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11690	06161	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11691	06162	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11692	06163	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11693	06164	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11695	06165	N	N	N	1	CUSTOMER ISSUE	-
FAS_11696	06166	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11697	06167	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11698	06168	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11699	06169	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11700	06170	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11701	06171	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11702	06172	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11703	06173	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11704	06174	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11705	06175	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11706	06176	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11707	06177	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11708	06178	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11709	06179	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11710	06180	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11711	06181	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11712	06182	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11717	06183	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11718	06184	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11719	06185	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11720	06186	N	N	N	3	CUSTOMER ISSUE	-
FAS_11721	06187	N	N	N	9	CUSTOMER ISSUE	-
FAS_11722	06188	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11735	06189	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11739	06190	N	N	Y	4	DIST - REPLACE FUSE	708.75
FAS_11740	06191	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11741	06192	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11742	06193	N	N	Y	2	DIST - REPLACE FUSE	708.75
FAS_11744	06194	N	N	Y	32	DIST - REPLACE FUSE	708.75
FAS_11745	06195	N	N	Y	32	DIST - REPLACE FUSE	708.75
FAS_11746	06196	Y	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11747	06197	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11749	06198	N	N	Y	32	DIST - REPLACE FUSE	708.75
FAS_11750	06199	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11751	06200	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11752	06201	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11753	06202	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11755	06203	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11756	06204	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11758	06205	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11760	06206	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11761	06207	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11762	06208	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11763	06209	N	N	Y	2	DIST - REPLACE FUSE	708.75
FAS_11764	06210	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11765	06211	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_11767	06212	N	N	Y	5	DIST - REPLACE FUSE	708.75
FAS_11768	06213	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11769	06214	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11770	06215	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11771	06216	N	N	Y	1	SEC/SVC - REPLACE	708.75

FAS_11815	06217	N	N	Y	32	DIST - REPLACE FUSE	708.75
FAS_11822	06218	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11823	06219	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11824	06220	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11826	06221	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11846	06222	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11847	06223	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11848	06224	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11849	06225	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11850	06226	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11851	06227	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11852	06228	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11853	06229	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11854	06230	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11857	06231	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11858	06232	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11859	06233	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11860	06234	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11861	06235	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11862	06236	N	N	N	1	CUSTOMER ISSUE	-
FAS_11863	06237	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11864	06238	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11865	06239	N	N	Y	3	SEC/SVC - REPLACE	708.75
FAS_11866	06240	N	N	Y	34	SEC/SVC - REPLACE	708.75
FAS_11867	06241	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11868	06242	Y	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_11869	06243	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11870	06244	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11871	06245	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11872	06246	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11873	06247	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11874	06248	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11875	06249	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11876	06250	Y	N	Y	5	SEC/SVC - REPLACE	708.75
FAS_11877	06251	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11878	06252	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11879	06253	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11880	06254	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11881	06255	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11882	06256	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11883	06257	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11885	06258	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11886	06259	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11887	06260	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_11888	06261	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11889	06262	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11890	06263	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11891	06264	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11892	06265	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_11893	06266	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11894	06267	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11895	06268	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11896	06269	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11897	06270	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11898	06271	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11899	06272	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11900	06273	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11901	06274	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11902	06275	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11903	06276	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11904	06277	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11905	06278	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11906	06279	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11907	06280	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11908	06281	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11909	06282	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11910	06283	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11911	06284	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11912	06285	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11913	06286	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11914	06287	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11915	06288	N	N	Y	3	SEC/SVC - REPLACE	708.75
FAS_11916	06289	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11917	06290	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11918	06291	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11919	06292	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11920	06293	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11921	06294	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11922	06295	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11923	06296	N	N	Y	1	SEC/SVC - REPLACE	708.75

FAS_11924	06297	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11925	06298	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11926	06299	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11927	06300	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11928	06301	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11929	06302	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11930	06303	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11933	06304	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11934	06305	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11935	06306	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11936	06307	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11937	06308	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11938	06309	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11941	06310	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11942	06311	N	N	N	1	CUSTOMER ISSUE	-
FAS_11943	06312	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11944	06313	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11945	06314	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11946	06315	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11947	06316	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11948	06317	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11949	06318	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11950	06319	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11951	06320	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11952	06321	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11953	06322	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11954	06323	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11955	06324	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11956	06325	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11957	06326	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11958	06327	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11959	06328	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11960	06329	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11961	06330	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11962	06331	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11963	06332	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11965	06333	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11966	06334	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11967	06335	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11968	06336	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11969	06337	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11970	06338	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11971	06339	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11972	06340	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11973	06341	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11974	06342	N	N	N	1	CUSTOMER ISSUE	-
FAS_11975	06343	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11976	06344	N	N	N	1	CUSTOMER ISSUE	-
FAS_11977	06345	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11978	06346	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11981	06347	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11982	06348	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11983	06349	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_11984	06350	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11985	06351	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11986	06352	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11987	06353	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11988	06354	N	N	Y	16	SEC/SVC - REPLACE	708.75
FAS_11989	06355	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11990	06356	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_11991	06357	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11992	06358	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11993	06359	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11994	06360	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_11995	06361	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12000	06362	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12001	06363	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12002	06364	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12003	06365	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12004	06366	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_12005	06367	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12009	06368	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12010	06369	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12011	06370	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12012	06371	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12029	06372	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12030	06373	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12037	06374	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12043	06375	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12044	06376	N	N	Y	1	SEC/SVC - REPLACE	708.75

FAS_12045	06377	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12046	06378	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12047	06379	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12048	06380	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12049	06381	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12050	06382	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12051	06383	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12052	06384	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12053	06385	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12054	06386	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12055	06387	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12056	06388	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12057	06389	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12058	06390	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12059	06391	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12060	06392	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12061	06393	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12062	06394	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12063	06395	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12064	06396	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12065	06397	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12066	06398	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12067	06399	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12068	06400	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12069	06401	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12070	06402	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12086	06403	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12087	06404	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12088	06405	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12089	06406	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12090	06407	N	N	Y	7	SEC/SVC - REPLACE	708.75
FAS_12091	06408	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12093	06409	N	N	N	1	CUSTOMER ISSUE	-
FAS_12094	06410	N	N	N	1	CUSTOMER ISSUE	-
FAS_12096	06411	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_12097	06412	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_12099	06413	Y	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_12101	06414	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_12102	06415	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12108	06416	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12109	06417	N	N	Y	4	SEC/SVC - REPLACE	708.75
FAS_12110	06418	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12111	06419	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12112	06420	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12113	06421	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12114	06422	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12115	06423	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12116	06424	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12117	06425	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12118	06426	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12119	06427	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12120	06428	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12121	06429	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12122	06430	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12123	06431	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12124	06432	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12125	06433	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12126	06434	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12127	06435	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12129	06436	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
FAS_12130	06437	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12134	06438	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12135	06439	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12136	06440	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12137	06441	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12140	06442	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_12145	06443	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12146	06444	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12147	06445	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12148	06446	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12149	06447	N	N	N	1	CUSTOMER ISSUE	-
FAS_12153	06448	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_12154	06449	N	N	Y	1	TX - REPLACE	2500
FAS_12157	06450	N	N	Y	1	TX - REPLACE	2500
FAS_12198	06451	N	N	N	1	CUSTOMER ISSUE	-
FAS_12201	06452	N	N	N	1	CUSTOMER ISSUE	-
FAS_12202	06453	N	N	N	1	CUSTOMER ISSUE	-
FAS_12203	06454	N	N	N	1	CUSTOMER ISSUE	-
FAS_12204	06455	N	N	N	1	CUSTOMER ISSUE	-
FAS_12205	06456	Y	N	N	1	CUSTOMER ISSUE	-

FAS_12207	06457	Y	N	N	1	CUSTOMER ISSUE	-
FAS_12208	06458	N	N	N	1	CUSTOMER ISSUE	-
FAS_12209	06459	N	N	N	1	CUSTOMER ISSUE	-
FAS_12210	06460	N	N	N	1	CUSTOMER ISSUE	-
FAS_12211	06461	N	N	N	1	CUSTOMER ISSUE	-
FAS_12212	06462	N	N	N	1	CUSTOMER ISSUE	-
FAS_12213	06463	N	N	N	1	CUSTOMER ISSUE	-
FAS_12214	06464	N	N	N	1	CUSTOMER ISSUE	-
FAS_12215	06465	N	N	N	1	CUSTOMER ISSUE	-
FAS_12216	06466	N	N	N	1	CUSTOMER ISSUE	-
FAS_12217	06467	Y	N	N	3	CUSTOMER ISSUE	-
FAS_12218	06468	N	N	N	1	CUSTOMER ISSUE	-
FAS_12219	06469	N	N	N	1	CUSTOMER ISSUE	-
FAS_12220	06470	N	N	N	1	CUSTOMER ISSUE	-
FAS_12221	06471	Y	N	N	1	CUSTOMER ISSUE	-
FAS_12223	06472	N	N	N	1	CUSTOMER ISSUE	-
FAS_12224	06473	N	N	N	1	CUSTOMER ISSUE	-
FAS_12225	06474	Y	N	N	1	CUSTOMER ISSUE	-
FAS_12226	06475	N	N	N	1	CUSTOMER ISSUE	-
FAS_12227	06476	N	N	N	1	CUSTOMER ISSUE	-
FAS_12228	06477	Y	N	N	1	CUSTOMER ISSUE	-
FAS_12229	06478	N	N	N	1	CUSTOMER ISSUE	-
FAS_12230	06479	Y	N	N	1	CUSTOMER ISSUE	-
FAS_12231	06480	N	N	N	1	CUSTOMER ISSUE	-
FAS_12232	06481	Y	N	N	1	CUSTOMER ISSUE	-
FAS_12233	06482	Y	N	N	1	CUSTOMER ISSUE	-
FAS_12234	06483	N	N	N	1	CUSTOMER ISSUE	-
FAS_12235	06484	Y	N	N	1	CUSTOMER ISSUE	-
FAS_12236	06485	N	N	N	1	CUSTOMER ISSUE	-
FAS_12237	06486	N	N	N	1	CUSTOMER ISSUE	-
FAS_12238	06487	N	N	N	1	CUSTOMER ISSUE	-
FAS_12239	06488	N	N	N	1	CUSTOMER ISSUE	-
FAS_12241	06489	N	N	N	1	CUSTOMER ISSUE	-
FAS_12242	06490	N	N	N	1	CUSTOMER ISSUE	-
FAS_12243	06491	N	N	N	2	CUSTOMER ISSUE	-
FAS_12244	06492	N	N	N	1	CUSTOMER ISSUE	-
FAS_12246	06493	N	N	N	1	CUSTOMER ISSUE	-
FAS_12247	06494	N	N	N	1	CUSTOMER ISSUE	-
FAS_12248	06495	N	N	N	1	CUSTOMER ISSUE	-
FAS_12251	06496	N	N	N	1	CUSTOMER ISSUE	-
FAS_12255	06497	N	N	N	1	CUSTOMER ISSUE	-
FAS_12256	06498	N	N	N	1	CUSTOMER ISSUE	-
FAS_12257	06499	N	N	N	1	CUSTOMER ISSUE	-
FAS_12259	06500	N	N	N	1	CUSTOMER ISSUE	-
FAS_12261	06501	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12262	06502	N	N	N	1	CUSTOMER ISSUE	-
FAS_12264	06503	N	N	N	1	CUSTOMER ISSUE	-
FAS_12265	06504	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12271	06505	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12275	06506	N	N	N	1	CUSTOMER ISSUE	-
FAS_12277	06507	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12278	06508	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12279	06509	N	N	Y	1	TX - REPLACE	2500
FAS_12280	06510	N	N	Y	1	TX - REPLACE	2500
FAS_12283	06511	N	N	N	1	CUSTOMER ISSUE	-
FAS_12284	06512	N	N	N	1	CUSTOMER ISSUE	-
FAS_12285	06513	N	N	N	1	CUSTOMER ISSUE	-
FAS_12286	06514	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12287	06515	N	N	N	1	CUSTOMER ISSUE	-
FAS_12288	06516	Y	N	N	1	CUSTOMER ISSUE	-
FAS_12289	06517	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12294	06518	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12300	06519	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12301	06520	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12302	06521	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_12303	06522	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12304	06523	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12305	06524	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12306	06525	Y	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12307	06526	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_12308	06527	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12309	06528	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12310	06529	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12311	06530	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12314	06531	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12315	06532	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12316	06533	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12317	06534	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_12318	06535	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_12319	06536	N	N	Y	2	SEC/SVC - REPAIR	472.5

FAS_12320	06537	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_12321	06538	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12322	06539	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12323	06540	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_12324	06541	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12325	06542	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12326	06543	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_12327	06544	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12328	06545	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12329	06546	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12330	06547	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12331	06548	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_12333	06549	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_12334	06550	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12335	06551	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12336	06552	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12337	06553	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12338	06554	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12339	06555	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12340	06556	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_12341	06557	Y	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_12342	06558	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_12344	06559	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_12345	06560	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12346	06561	N	N	Y	6	SEC/SVC - REPAIR	472.5
FAS_12347	06562	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12348	06563	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12349	06564	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_12350	06565	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_12351	06566	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12352	06567	Y	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12353	06568	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_12354	06569	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12355	06570	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_12356	06571	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_12357	06572	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_12358	06573	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12359	06574	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_12360	06575	N	N	Y	5	SEC/SVC - REPAIR	472.5
FAS_12361	06576	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_12362	06577	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_12363	06578	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12364	06579	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12365	06580	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12366	06581	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12367	06582	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12368	06583	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12369	06584	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12370	06585	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12371	06586	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12372	06587	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_12373	06588	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12374	06589	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12375	06590	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12376	06591	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12377	06592	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12378	06593	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12379	06594	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12381	06595	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_12382	06596	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_12383	06597	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12384	06598	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12385	06599	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12386	06600	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12387	06601	N	N	N	2	CUSTOMER ISSUE	-
FAS_12388	06602	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_12389	06603	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12395	06604	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12396	06605	N	N	N	1	CUSTOMER ISSUE	-
FAS_12399	06606	N	N	N	1	CUSTOMER ISSUE	-
FAS_12402	06607	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_12405	06608	N	N	N	1	CUSTOMER ISSUE	-
FAS_12407	06609	N	N	N	1	CUSTOMER ISSUE	-
FAS_12408	06610	N	N	N	1	CUSTOMER ISSUE	-
FAS_12409	06611	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12411	06612	N	N	N	1	CUSTOMER ISSUE	-
FAS_12412	06613	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12413	06614	N	N	Y	1	TX - REPLACE	2500
FAS_12425	06615	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12426	06616	N	N	Y	1	SEC/SVC - REPLACE	708.75

FAS_12427	06617	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12428	06618	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12430	06619	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12431	06620	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12432	06621	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12433	06622	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12436	06623	N	N	Y	1	TX - REPLACE	2500
FAS_12442	06624	N	N	N	1	CUSTOMER ISSUE	-
FAS_12452	06625	N	N	N	1	CUSTOMER ISSUE	-
FAS_12458	06626	N	N	N	1	CUSTOMER ISSUE	-
FAS_12460	06627	N	N	N	1	CUSTOMER ISSUE	-
FAS_12463	06628	N	N	N	3	CUSTOMER ISSUE	-
FAS_12470	06629	Y	N	Y	5	SEC/SVC - REPLACE	708.75
FAS_12471	06630	N	N	N	1	CUSTOMER ISSUE	-
FAS_12476	06631	N	N	N	1	CUSTOMER ISSUE	-
FAS_12490	06632	N	N	N	1	CUSTOMER ISSUE	-
FAS_12499	06633	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12504	06634	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12514	06635	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12515	06636	N	N	N	5	CUSTOMER ISSUE	-
FAS_12517	06637	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12518	06638	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12520	06639	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12521	06640	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12522	06641	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12530	06642	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12532	06643	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_12535	06644	N	N	N	1	CUSTOMER ISSUE	-
FAS_12547	06645	N	N	N	1	CUSTOMER ISSUE	-
FAS_12559	06646	N	N	Y	30	SEC/SVC - REPLACE	708.75
FAS_12560	06647	N	N	Y	1	TX - REPLACE	2500
FAS_12562	06648	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_12564	06649	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12568	06650	N	N	Y	1	TX - REPLACE	2500
FAS_12569	06651	N	N	Y	1	TX - REPLACE	2500
FAS_12572	06652	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
FAS_12577	06653	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_12585	06654	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12587	06655	N	N	Y	1	SUB/TRANS - REPLACE	10000
FAS_12590	06656	N	N	Y	1	TX - REPLACE	2500
FAS_12592	06657	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12594	06658	Y	N	Y	1	TX - REPLACE	2500
FAS_12597	06659	N	N	Y	1	TX - REPLACE	2500
FAS_12602	06660	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12608	06661	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_12609	06662	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12610	06663	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12611	06664	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12612	06665	N	N	N	1	CUSTOMER ISSUE	-
FAS_12616	06666	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12618	06667	N	N	N	1	CUSTOMER ISSUE	-
FAS_12619	06668	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12620	06669	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12621	06670	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12622	06671	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12623	06672	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12624	06673	N	N	N	2	CUSTOMER ISSUE	-
FAS_12626	06674	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12627	06675	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12628	06676	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12629	06677	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12631	06678	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12632	06679	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12633	06680	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12634	06681	Y	N	N	1	CUSTOMER ISSUE	-
FAS_12635	06682	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12636	06683	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_12639	06684	N	N	Y	23	SEC/SVC - REPAIR	472.5
FAS_12640	06685	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12641	06686	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12642	06687	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12643	06688	N	N	N	1	CUSTOMER ISSUE	-
FAS_12644	06689	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12645	06690	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12648	06691	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12651	06692	N	N	N	1	CUSTOMER ISSUE	-
FAS_12654	06693	N	N	N	1	CUSTOMER ISSUE	-
FAS_12655	06694	N	N	N	1	CUSTOMER ISSUE	-
FAS_12659	06695	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12660	06696	N	N	Y	1	SEC/SVC - REPLACE	708.75

FAS_12661	06697	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12662	06698	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12665	06699	N	N	N	1	CUSTOMER ISSUE	-
FAS_12668	06700	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12670	06701	N	N	N	1	CUSTOMER ISSUE	-
FAS_12675	06702	N	N	N	1	CUSTOMER ISSUE	-
FAS_12676	06703	N	N	N	1	CUSTOMER ISSUE	-
FAS_12677	06704	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12681	06705	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12682	06706	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12685	06707	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12686	06708	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12687	06709	N	N	Y	4	SEC/SVC - REPLACE	708.75
FAS_12688	06710	N	N	N	1	CUSTOMER ISSUE	-
FAS_12689	06711	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_12690	06712	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12692	06713	N	N	N	5	CUSTOMER ISSUE	-
FAS_12694	06714	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_12695	06715	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12697	06716	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12698	06717	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12699	06718	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12702	06719	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12703	06720	N	N	Y	2	TX - REPLACE	2500
FAS_12707	06721	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12708	06722	N	N	N	1	CUSTOMER ISSUE	-
FAS_12711	06723	N	N	N	1	CUSTOMER ISSUE	-
FAS_12715	06724	N	N	N	1	CUSTOMER ISSUE	-
FAS_12718	06725	N	N	N	1	CUSTOMER ISSUE	-
FAS_12721	06726	N	N	N	1	CUSTOMER ISSUE	-
FAS_12724	06727	N	N	N	1	CUSTOMER ISSUE	-
FAS_12725	06728	Y	N	N	1	CUSTOMER ISSUE	-
FAS_12728	06729	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_12729	06730	N	N	N	1	CUSTOMER ISSUE	-
FAS_12730	06731	N	N	N	2	CUSTOMER ISSUE	-
FAS_12733	06732	N	N	N	1	CUSTOMER ISSUE	-
FAS_12735	06733	N	N	Y	1	TX - REPLACE	2500
FAS_12742	06734	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_12749	06735	Y	N	N	1	CUSTOMER ISSUE	-
FAS_12762	06736	N	N	N	1	CUSTOMER ISSUE	-
FAS_12763	06737	N	N	N	1	CUSTOMER ISSUE	-
FAS_12765	06738	Y	N	N	1	CUSTOMER ISSUE	-
FAS_12766	06739	Y	N	N	1	CUSTOMER ISSUE	-
FAS_12767	06740	Y	N	N	1	CUSTOMER ISSUE	-
FAS_12770	06741	N	N	N	1	CUSTOMER ISSUE	-
FAS_12772	06742	N	N	N	1	CUSTOMER ISSUE	-
FAS_12775	06743	N	N	N	1	CUSTOMER ISSUE	-
FAS_12783	06744	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12785	06745	N	N	N	1	CUSTOMER ISSUE	-
FAS_12786	06746	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12790	06747	N	N	N	1	CUSTOMER ISSUE	-
FAS_12793	06748	N	N	N	1	CUSTOMER ISSUE	-
FAS_12797	06749	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12805	06750	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12806	06751	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12807	06752	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12808	06753	N	N	Y	16	SEC/SVC - REPLACE	708.75
FAS_12809	06754	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12810	06755	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12811	06756	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12812	06757	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12816	06758	N	N	N	1	CUSTOMER ISSUE	-
FAS_12817	06759	N	N	N	1	CUSTOMER ISSUE	-
FAS_12820	06760	N	N	N	1	CUSTOMER ISSUE	-
FAS_12821	06761	N	N	N	1	CUSTOMER ISSUE	-
FAS_12826	06762	N	N	N	1	CUSTOMER ISSUE	-
FAS_12829	06763	N	N	N	1	CUSTOMER ISSUE	-
FAS_12831	06764	N	N	N	2	CUSTOMER ISSUE	-
FAS_12837	06765	N	N	N	1	CUSTOMER ISSUE	-
FAS_12838	06766	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_12841	06767	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12842	06768	N	N	N	1	CUSTOMER ISSUE	-
FAS_12843	06769	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_12847	06770	N	N	N	1	CUSTOMER ISSUE	-
FAS_12848	06771	N	N	N	1	CUSTOMER ISSUE	-
FAS_12853	06772	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_12854	06773	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12855	06774	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12856	06775	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12857	06776	Y	N	Y	1	SEC/SVC - REPAIR	472.5

FAS_12858	06777	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12859	06778	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12861	06779	N	N	Y	1	TX - REPLACE	2500
FAS_12862	06780	N	N	N	1	CUSTOMER ISSUE	-
FAS_12863	06781	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12864	06782	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12865	06783	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12866	06784	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12867	06785	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12869	06786	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_12872	06787	N	N	N	1	CUSTOMER ISSUE	-
FAS_12875	06788	N	N	N	1	CUSTOMER ISSUE	-
FAS_12880	06789	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_12882	06790	N	N	N	1	CUSTOMER ISSUE	-
FAS_12883	06791	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12884	06792	N	N	Y	1	TX - REPLACE	2500
FAS_12890	06793	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12892	06794	N	N	N	1	CUSTOMER ISSUE	-
FAS_12893	06795	N	N	Y	1	TX - REPLACE	2500
FAS_12894	06796	N	N	N	1	CUSTOMER ISSUE	-
FAS_12896	06797	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_12899	06798	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12900	06799	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12901	06800	N	N	Y	1	TX - REPLACE	2500
FAS_12902	06801	N	N	N	1	CUSTOMER ISSUE	-
FAS_12907	06802	N	N	N	1	CUSTOMER ISSUE	-
FAS_12911	06803	N	N	N	1	CUSTOMER ISSUE	-
FAS_12912	06804	N	N	N	1	CUSTOMER ISSUE	-
FAS_12913	06805	N	N	N	1	CUSTOMER ISSUE	-
FAS_12916	06806	N	N	N	1	CUSTOMER ISSUE	-
FAS_12919	06807	N	N	N	1	CUSTOMER ISSUE	-
FAS_12920	06808	N	N	N	1	CUSTOMER ISSUE	-
FAS_12921	06809	N	N	N	1	CUSTOMER ISSUE	-
FAS_12922	06810	N	N	Y	1	SUB/TRANS - REPAIR	5000
FAS_12923	06811	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12928	06812	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12942	06813	Y	N	Y	1	TX - REPLACE	2500
FAS_12948	06814	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12950	06815	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_12953	06816	N	N	Y	13	SEC/SVC - REPAIR	472.5
FAS_12957	06817	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12958	06818	N	N	Y	10	SEC/SVC - REPLACE	708.75
FAS_12962	06819	N	N	Y	1	TX - REPLACE	2500
FAS_12970	06820	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_12971	06821	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_12977	06822	N	N	N	1	CUSTOMER ISSUE	-
FAS_12980	06823	N	N	N	1	CUSTOMER ISSUE	-
FAS_12982	06824	Y	N	N	3	CUSTOMER ISSUE	-
FAS_12984	06825	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12986	06826	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12987	06827	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12988	06828	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12994	06829	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12996	06830	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12997	06831	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_12998	06832	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_12999	06833	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13000	06834	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13001	06835	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13002	06836	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13003	06837	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
FAS_13004	06838	N	N	N	1	CUSTOMER ISSUE	-
FAS_13006	06839	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_13009	06840	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13014	06841	N	N	N	1	CUSTOMER ISSUE	-
FAS_13015	06842	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
FAS_13022	06843	Y	N	N	1	CUSTOMER ISSUE	-
FAS_13023	06844	N	N	N	1	CUSTOMER ISSUE	-
FAS_13024	06845	N	N	N	6	CUSTOMER ISSUE	-
FAS_13026	06846	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13028	06847	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13029	06848	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13030	06849	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13031	06850	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13033	06851	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13035	06852	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13036	06853	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13037	06854	N	N	N	1	CUSTOMER ISSUE	-
FAS_13038	06855	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13039	06856	Y	N	Y	1	SEC/SVC - REPLACE	708.75

FAS_13040	06857	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13041	06858	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13042	06859	N	N	Y	6	SEC/SVC - REPAIR	472.5
FAS_13043	06860	N	N	N	1	CUSTOMER ISSUE	-
FAS_13050	06861	N	N	N	16	CUSTOMER ISSUE	-
FAS_13054	06862	N	N	N	22	CUSTOMER ISSUE	-
FAS_13055	06863	N	N	N	22	CUSTOMER ISSUE	-
FAS_13056	06864	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13058	06865	N	N	N	39	CUSTOMER ISSUE	-
FAS_13059	06866	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13060	06867	N	N	N	1	CUSTOMER ISSUE	-
FAS_13061	06868	N	N	N	1	CUSTOMER ISSUE	-
FAS_13066	06869	N	N	N	2	CUSTOMER ISSUE	-
FAS_13070	06870	N	N	N	19	CUSTOMER ISSUE	-
FAS_13076	06871	Y	N	N	1	CUSTOMER ISSUE	-
FAS_13077	06872	N	N	N	1	CUSTOMER ISSUE	-
FAS_13078	06873	N	N	N	5	CUSTOMER ISSUE	-
FAS_13080	06874	N	N	Y	1	TX - REPLACE	2500
FAS_13085	06875	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13086	06876	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13089	06877	Y	N	N	36	CUSTOMER ISSUE	-
FAS_13091	06878	N	N	N	23	CUSTOMER ISSUE	-
FAS_13093	06879	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_13094	06880	N	N	N	1	CUSTOMER ISSUE	-
FAS_13095	06881	N	N	Y	1	TX - REPLACE	2500
FAS_13096	06882	N	N	Y	1	TX - REPLACE	2500
FAS_13098	06883	N	N	Y	1	TX - REPLACE	2500
FAS_13100	06884	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13101	06885	N	N	Y	1	TX - REPLACE	2500
FAS_13103	06886	N	N	N	1	CUSTOMER ISSUE	-
FAS_13114	06887	N	N	N	1	CUSTOMER ISSUE	-
FAS_13119	06888	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13120	06889	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13127	06890	N	N	Y	1	TX - REPLACE	2500
FAS_13128	06891	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13129	06892	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13133	06893	N	N	N	1	CUSTOMER ISSUE	-
FAS_13136	06894	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13145	06895	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13146	06896	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13147	06897	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13148	06898	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13149	06899	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13156	06900	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13157	06901	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13158	06902	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_13159	06903	N	N	Y	1	TX - REPLACE	2500
FAS_13160	06904	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13165	06905	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13167	06906	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13170	06907	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_13176	06908	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13177	06909	N	N	Y	4	DIST - TREE TRIMMING	945
FAS_13178	06910	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13182	06911	N	N	N	3	CUSTOMER ISSUE	-
FAS_13185	06912	N	N	Y	17	DIST - TREE TRIMMING	945
FAS_13192	06913	N	N	N	1	CUSTOMER ISSUE	-
FAS_13200	06914	N	N	N	1	CUSTOMER ISSUE	-
FAS_13202	06915	N	N	N	1	CUSTOMER ISSUE	-
FAS_13204	06916	N	N	N	1	CUSTOMER ISSUE	-
FAS_13208	06917	N	N	N	1	CUSTOMER ISSUE	-
FAS_13209	06918	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13212	06919	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13214	06920	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13215	06921	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13216	06922	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13218	06923	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13219	06924	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13220	06925	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13221	06926	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13222	06927	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_13223	06928	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_13224	06929	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_13225	06930	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13226	06931	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13227	06932	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_13228	06933	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13229	06934	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13230	06935	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13231	06936	N	N	Y	3	SEC/SVC - REPAIR	472.5

FAS_13232	06937	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13233	06938	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13234	06939	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13235	06940	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13236	06941	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13237	06942	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13238	06943	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13239	06944	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13240	06945	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_13241	06946	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13242	06947	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13243	06948	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13244	06949	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13245	06950	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13246	06951	N	N	N	1	CUSTOMER ISSUE	-
FAS_13247	06952	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13248	06953	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13249	06954	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13250	06955	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13251	06956	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13252	06957	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13253	06958	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13256	06959	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13257	06960	N	N	Y	5	SEC/SVC - REPAIR	472.5
FAS_13258	06961	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13259	06962	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13260	06963	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13261	06964	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13262	06965	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13263	06966	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13264	06967	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13265	06968	Y	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13266	06969	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13267	06970	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13268	06971	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13269	06972	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13270	06973	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13271	06974	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13272	06975	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_13273	06976	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13274	06977	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13275	06978	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13276	06979	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13277	06980	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_13278	06981	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13279	06982	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13280	06983	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_13281	06984	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13282	06985	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_13283	06986	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_13284	06987	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_13285	06988	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13286	06989	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_13287	06990	N	N	N	1	CUSTOMER ISSUE	-
FAS_13288	06991	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13289	06992	N	N	N	1	CUSTOMER ISSUE	-
FAS_13291	06993	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13292	06994	N	N	N	1	CUSTOMER ISSUE	-
FAS_13293	06995	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13294	06996	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13295	06997	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13296	06998	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13297	06999	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13298	07000	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13300	07001	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13301	07002	N	N	N	1	CUSTOMER ISSUE	-
FAS_13302	07003	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13303	07004	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13304	07005	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13305	07006	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_13306	07007	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13307	07008	N	N	N	1	CUSTOMER ISSUE	-
FAS_13308	07009	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13309	07010	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13310	07011	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13311	07012	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13312	07013	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13313	07014	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13314	07015	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13317	07016	N	N	Y	1	SEC/SVC - REPAIR	472.5

FAS_13318	07017	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_13319	07018	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13321	07019	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13324	07020	Y	N	N	1	CUSTOMER ISSUE	-
FAS_13325	07021	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_13326	07022	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13327	07023	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13328	07024	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13329	07025	N	N	N	1	CUSTOMER ISSUE	-
FAS_13330	07026	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13331	07027	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13332	07028	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13333	07029	N	N	N	1	CUSTOMER ISSUE	-
FAS_13334	07030	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13335	07031	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13336	07032	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13337	07033	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13338	07034	Y	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13339	07035	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13340	07036	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13341	07037	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13342	07038	Y	N	N	1	CUSTOMER ISSUE	-
FAS_13343	07039	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13344	07040	N	N	N	2	CUSTOMER ISSUE	-
FAS_13345	07041	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13346	07042	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13347	07043	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13348	07044	N	N	Y	4	SEC/SVC - REPAIR	472.5
FAS_13349	07045	N	N	N	1	CUSTOMER ISSUE	-
FAS_13356	07046	N	N	N	1	CUSTOMER ISSUE	-
FAS_13357	07047	N	N	N	1	CUSTOMER ISSUE	-
FAS_13358	07048	Y	N	N	1	CUSTOMER ISSUE	-
FAS_13362	07049	N	N	N	1	CUSTOMER ISSUE	-
FAS_13363	07050	N	N	N	1	CUSTOMER ISSUE	-
FAS_13364	07051	N	N	N	1	CUSTOMER ISSUE	-
FAS_13365	07052	N	N	N	1	CUSTOMER ISSUE	-
FAS_13366	07053	N	N	N	1	CUSTOMER ISSUE	-
FAS_13367	07054	N	N	N	1	CUSTOMER ISSUE	-
FAS_13368	07055	N	N	N	1	CUSTOMER ISSUE	-
FAS_13369	07056	N	N	N	1	CUSTOMER ISSUE	-
FAS_13370	07057	N	N	N	1	CUSTOMER ISSUE	-
FAS_13372	07058	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13373	07059	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13374	07060	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13375	07061	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13376	07062	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13379	07063	Y	N	N	1	CUSTOMER ISSUE	-
FAS_13380	07064	N	N	N	2	CUSTOMER ISSUE	-
FAS_13381	07065	N	N	N	1	CUSTOMER ISSUE	-
FAS_13382	07066	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13383	07067	N	N	N	1	CUSTOMER ISSUE	-
FAS_13384	07068	N	N	N	1	CUSTOMER ISSUE	-
FAS_13386	07069	N	N	N	1	CUSTOMER ISSUE	-
FAS_13393	07070	N	N	N	1	CUSTOMER ISSUE	-
FAS_13394	07071	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13395	07072	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13397	07073	N	N	N	1	CUSTOMER ISSUE	-
FAS_13399	07074	Y	N	N	1	CUSTOMER ISSUE	-
FAS_13400	07075	N	N	N	1	CUSTOMER ISSUE	-
FAS_13401	07076	N	N	N	1	CUSTOMER ISSUE	-
FAS_13402	07077	Y	N	N	1	CUSTOMER ISSUE	-
FAS_13403	07078	N	N	N	1	CUSTOMER ISSUE	-
FAS_13404	07079	N	N	N	1	CUSTOMER ISSUE	-
FAS_13406	07080	N	N	N	1	CUSTOMER ISSUE	-
FAS_13407	07081	N	N	N	1	CUSTOMER ISSUE	-
FAS_13408	07082	Y	N	N	1	CUSTOMER ISSUE	-
FAS_13409	07083	N	N	N	2	CUSTOMER ISSUE	-
FAS_13410	07084	N	N	Y	2	TX - REPLACE	2500
FAS_13411	07085	Y	N	N	1	CUSTOMER ISSUE	-
FAS_13412	07086	N	N	N	1	CUSTOMER ISSUE	-
FAS_13413	07087	N	N	N	1	CUSTOMER ISSUE	-
FAS_13414	07088	N	N	Y	2	SUB/TRANS - CHANGE SETTINGS	708.75
FAS_13416	07089	N	N	N	1	CUSTOMER ISSUE	-
FAS_13417	07090	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13420	07091	N	N	N	1	CUSTOMER ISSUE	-
FAS_13421	07092	N	N	N	1	CUSTOMER ISSUE	-
FAS_13424	07093	N	N	N	1	CUSTOMER ISSUE	-
FAS_13426	07094	N	N	N	1	CUSTOMER ISSUE	-
FAS_13427	07095	Y	N	N	1	CUSTOMER ISSUE	-
FAS_13428	07096	N	N	N	1	CUSTOMER ISSUE	-

FAS_13429	07097	N	N	N	1	CUSTOMER ISSUE	-
FAS_13430	07098	N	N	N	1	CUSTOMER ISSUE	-
FAS_13431	07099	N	N	N	1	CUSTOMER ISSUE	-
FAS_13432	07100	N	N	N	1	CUSTOMER ISSUE	-
FAS_13433	07101	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_13434	07102	N	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
FAS_13441	07103	Y	N	N	1	CUSTOMER ISSUE	-
FAS_13444	07104	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13445	07105	N	N	N	1	CUSTOMER ISSUE	-
FAS_13446	07106	N	N	N	1	CUSTOMER ISSUE	-
FAS_13447	07107	N	N	N	1	CUSTOMER ISSUE	-
FAS_13448	07108	N	N	N	1	CUSTOMER ISSUE	-
FAS_13449	07109	N	N	N	1	CUSTOMER ISSUE	-
FAS_13450	07110	N	N	N	1	CUSTOMER ISSUE	-
FAS_13456	07111	Y	N	N	1	CUSTOMER ISSUE	-
FAS_13457	07112	N	N	N	1	CUSTOMER ISSUE	-
FAS_13460	07113	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13461	07114	N	N	N	1	CUSTOMER ISSUE	-
FAS_13465	07115	Y	N	N	1	CUSTOMER ISSUE	-
FAS_13466	07116	Y	N	N	1	CUSTOMER ISSUE	-
FAS_13467	07117	N	N	N	1	CUSTOMER ISSUE	-
FAS_13468	07118	N	N	N	1	CUSTOMER ISSUE	-
FAS_13469	07119	N	N	Y	2	TX - REPLACE	2500
FAS_13473	07120	N	N	N	1	CUSTOMER ISSUE	-
FAS_13479	07121	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13480	07122	N	N	N	1	CUSTOMER ISSUE	-
FAS_13484	07123	N	N	N	1	CUSTOMER ISSUE	-
FAS_13487	07124	N	N	N	1	CUSTOMER ISSUE	-
FAS_13491	07125	N	N	N	1	CUSTOMER ISSUE	-
FAS_13493	07126	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13494	07127	N	N	N	1	CUSTOMER ISSUE	-
FAS_13498	07128	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_13501	07129	N	N	N	1	CUSTOMER ISSUE	-
FAS_13502	07130	N	N	N	1	CUSTOMER ISSUE	-
FAS_13504	07131	N	N	N	1	CUSTOMER ISSUE	-
FAS_13506	07132	N	N	N	1	CUSTOMER ISSUE	-
FAS_13508	07133	N	N	N	1	CUSTOMER ISSUE	-
FAS_13509	07134	N	N	N	1	CUSTOMER ISSUE	-
FAS_13510	07135	N	N	N	1	CUSTOMER ISSUE	-
FAS_13511	07136	N	N	N	1	CUSTOMER ISSUE	-
FAS_13512	07137	N	N	N	1	CUSTOMER ISSUE	-
FAS_13514	07138	N	N	N	1	CUSTOMER ISSUE	-
FAS_13516	07139	N	N	N	1	CUSTOMER ISSUE	-
FAS_13517	07140	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13519	07141	N	N	N	1	CUSTOMER ISSUE	-
FAS_13520	07142	N	N	N	6	CUSTOMER ISSUE	-
FAS_13522	07143	N	N	N	1	CUSTOMER ISSUE	-
FAS_13526	07144	N	N	N	1	CUSTOMER ISSUE	-
FAS_13529	07145	N	N	N	1	CUSTOMER ISSUE	-
FAS_13530	07146	N	N	N	1	CUSTOMER ISSUE	-
FAS_13531	07147	N	N	N	1	CUSTOMER ISSUE	-
FAS_13532	07148	N	N	N	1	CUSTOMER ISSUE	-
FAS_13533	07149	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13536	07150	N	N	N	31	CUSTOMER ISSUE	-
FAS_13538	07151	N	N	N	1	CUSTOMER ISSUE	-
FAS_13542	07152	N	N	N	1	CUSTOMER ISSUE	-
FAS_13597	07153	N	N	N	3	CUSTOMER ISSUE	-
FAS_13604	07154	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13605	07155	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
FAS_13606	07156	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13608	07157	N	N	N	32	CUSTOMER ISSUE	-
FAS_13609	07158	N	N	N	1	CUSTOMER ISSUE	-
FAS_13615	07159	N	N	N	1	CUSTOMER ISSUE	-
FAS_13617	07160	N	N	Y	2	TX - REPLACE	2500
FAS_13618	07161	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_13619	07162	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_13623	07163	N	N	N	1	CUSTOMER ISSUE	-
FAS_13624	07164	N	N	N	1	CUSTOMER ISSUE	-
FAS_13631	07165	N	N	N	1	CUSTOMER ISSUE	-
FAS_13632	07166	Y	N	N	1	CUSTOMER ISSUE	-
FAS_13633	07167	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13634	07168	N	N	N	1	CUSTOMER ISSUE	-
FAS_13645	07169	N	N	N	1	CUSTOMER ISSUE	-
FAS_13649	07170	N	N	Y	1	TX - REPLACE	2500
FAS_13650	07171	Y	N	N	1	CUSTOMER ISSUE	-
FAS_13651	07172	N	N	N	1	CUSTOMER ISSUE	-
FAS_13654	07173	N	N	Y	1	TX - REPLACE	2500
FAS_13657	07174	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_13659	07175	N	N	Y	1	TX - REPLACE	2500
FAS_13662	07176	N	N	Y	1	TX - REPLACE	2500

FAS_13663	07177	N	N	Y	1	TX - REPLACE	2500
FAS_13664	07178	N	N	Y	1	TX - REPLACE	2500
FAS_13666	07179	N	N	Y	1	TX - REPLACE	2500
FAS_13670	07180	N	N	Y	1	TX - REPLACE	2500
FAS_13673	07181	N	N	Y	1	TX - REPLACE	2500
FAS_13678	07182	N	N	Y	1	TX - REPLACE	2500
FAS_13679	07183	N	N	N	1	CUSTOMER ISSUE	-
FAS_13683	07184	N	N	N	1	CUSTOMER ISSUE	-
FAS_13685	07185	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13688	07186	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13690	07187	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13692	07188	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13695	07189	N	N	Y	2	DIST - TREE TRIMMING	945
FAS_13696	07190	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13697	07191	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13698	07192	N	N	N	1	CUSTOMER ISSUE	-
FAS_13699	07193	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13700	07194	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13701	07195	N	N	N	1	CUSTOMER ISSUE	-
FAS_13702	07196	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13704	07197	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13705	07198	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13708	07199	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13709	07200	N	N	N	1	CUSTOMER ISSUE	-
FAS_13713	07201	N	N	N	1	CUSTOMER ISSUE	-
FAS_13715	07202	N	N	N	1	CUSTOMER ISSUE	-
FAS_13716	07203	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13721	07204	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13722	07205	N	N	N	1	CUSTOMER ISSUE	-
FAS_13723	07206	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13726	07207	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13727	07208	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13731	07209	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13732	07210	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13734	07211	Y	N	N	1	CUSTOMER ISSUE	-
FAS_13736	07212	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13739	07213	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13740	07214	N	N	N	1	CUSTOMER ISSUE	-
FAS_13741	07215	N	N	N	1	CUSTOMER ISSUE	-
FAS_13751	07216	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13754	07217	N	N	Y	2	DIST - TREE TRIMMING	945
FAS_13755	07218	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13756	07219	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13757	07220	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_13758	07221	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13761	07222	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13762	07223	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13766	07224	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13767	07225	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13768	07226	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13769	07227	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13770	07228	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13772	07229	N	N	N	1	CUSTOMER ISSUE	-
FAS_13773	07230	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_13775	07231	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13776	07232	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13779	07233	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13780	07234	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13781	07235	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13783	07236	N	N	N	1	CUSTOMER ISSUE	-
FAS_13786	07237	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13787	07238	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13789	07239	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13792	07240	N	N	N	1	CUSTOMER ISSUE	-
FAS_13794	07241	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13795	07242	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13796	07243	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13797	07244	N	N	N	1	CUSTOMER ISSUE	-
FAS_13801	07245	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13802	07246	N	N	Y	2	DIST - TREE TRIMMING	945
FAS_13804	07247	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13806	07248	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13809	07249	N	N	N	1	CUSTOMER ISSUE	-
FAS_13811	07250	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_13812	07251	N	N	N	1	CUSTOMER ISSUE	-
FAS_13818	07252	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13822	07253	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13827	07254	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13837	07255	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13838	07256	N	N	Y	4	DIST - TREE TRIMMING	945

FAS_13839	07257	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13840	07258	N	N	N	1	CUSTOMER ISSUE	-
FAS_13841	07259	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13842	07260	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_13844	07261	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13847	07262	N	N	N	1	CUSTOMER ISSUE	-
FAS_13850	07263	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13851	07264	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13852	07265	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13853	07266	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13854	07267	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13855	07268	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13856	07269	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13857	07270	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13859	07271	N	N	N	1	CUSTOMER ISSUE	-
FAS_13860	07272	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_13862	07273	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13875	07274	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13876	07275	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13878	07276	N	N	N	1	CUSTOMER ISSUE	-
FAS_13880	07277	N	N	N	1	CUSTOMER ISSUE	-
FAS_13882	07278	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13886	07279	N	N	N	1	CUSTOMER ISSUE	-
FAS_13887	07280	N	N	N	5	CUSTOMER ISSUE	-
FAS_13898	07281	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13905	07282	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13907	07283	N	N	N	1	CUSTOMER ISSUE	-
FAS_13914	07284	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13915	07285	Y	N	Y	1	TX - REPLACE	2500
FAS_13916	07286	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13917	07287	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13919	07288	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13924	07289	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13928	07290	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13929	07291	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13930	07292	N	N	Y	25	DIST - TREE TRIMMING	945
FAS_13931	07293	N	N	N	1	CUSTOMER ISSUE	-
FAS_13933	07294	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13934	07295	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13935	07296	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13942	07297	N	N	N	23	CUSTOMER ISSUE	-
FAS_13943	07298	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13945	07299	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13946	07300	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13949	07301	N	N	N	1	CUSTOMER ISSUE	-
FAS_13952	07302	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13957	07303	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13961	07304	N	N	N	1	CUSTOMER ISSUE	-
FAS_13965	07305	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13966	07306	N	N	Y	11	DIST - TREE TRIMMING	945
FAS_13967	07307	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13968	07308	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13969	07309	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13970	07310	N	N	Y	2	DIST - TREE TRIMMING	945
FAS_13971	07311	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13972	07312	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_13973	07313	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_13974	07314	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13975	07315	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13976	07316	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13977	07317	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13978	07318	N	N	Y	2	DIST - TREE TRIMMING	945
FAS_13979	07319	N	N	Y	25	DIST - TREE TRIMMING	945
FAS_13980	07320	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13981	07321	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13982	07322	Y	N	Y	2	DIST - TREE TRIMMING	945
FAS_13983	07323	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13984	07324	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13985	07325	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13986	07326	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13987	07327	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_13989	07328	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13990	07329	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_13991	07330	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13992	07331	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_13993	07332	N	N	Y	2	DIST - TREE TRIMMING	945
FAS_13994	07333	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_13995	07334	N	N	Y	2	SEC/SVC - REPAIR	472.5
FAS_13996	07335	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_13997	07336	N	N	Y	1	DIST - TREE TRIMMING	945

FAS_13998	07337	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_13999	07338	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14000	07339	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14001	07340	Y	N	Y	3	DIST - TREE TRIMMING	945
FAS_14002	07341	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14003	07342	N	N	Y	29	DIST - TREE TRIMMING	945
FAS_14004	07343	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14005	07344	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14006	07345	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14007	07346	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14008	07347	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14009	07348	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14010	07349	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14011	07350	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14012	07351	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14013	07352	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14015	07353	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14016	07354	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14017	07355	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14018	07356	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14019	07357	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14020	07358	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14021	07359	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14022	07360	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14023	07361	N	N	N	1	CUSTOMER ISSUE	-
FAS_14025	07362	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14026	07363	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14027	07364	N	N	N	1	CUSTOMER ISSUE	-
FAS_14028	07365	N	N	N	1	CUSTOMER ISSUE	-
FAS_14029	07366	Y	N	N	1	CUSTOMER ISSUE	-
FAS_14030	07367	N	N	N	1	CUSTOMER ISSUE	-
FAS_14031	07368	N	N	N	1	CUSTOMER ISSUE	-
FAS_14033	07369	N	N	N	1	CUSTOMER ISSUE	-
FAS_14035	07370	Y	N	N	1	CUSTOMER ISSUE	-
FAS_14036	07371	Y	N	N	1	CUSTOMER ISSUE	-
FAS_14038	07372	N	N	N	1	CUSTOMER ISSUE	-
FAS_14039	07373	Y	N	N	1	CUSTOMER ISSUE	-
FAS_14040	07374	N	N	N	1	CUSTOMER ISSUE	-
FAS_14041	07375	N	N	N	2	CUSTOMER ISSUE	-
FAS_14044	07376	N	N	N	1	CUSTOMER ISSUE	-
FAS_14045	07377	N	N	N	1	CUSTOMER ISSUE	-
FAS_14046	07378	N	N	N	1	CUSTOMER ISSUE	-
FAS_14047	07379	N	N	N	1	CUSTOMER ISSUE	-
FAS_14053	07380	N	N	N	1	CUSTOMER ISSUE	-
FAS_14054	07381	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14056	07382	N	N	N	1	CUSTOMER ISSUE	-
FAS_14059	07383	N	N	N	1	CUSTOMER ISSUE	-
FAS_14060	07384	N	N	N	1	CUSTOMER ISSUE	-
FAS_14063	07385	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14064	07386	N	N	N	1	CUSTOMER ISSUE	-
FAS_14065	07387	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14069	07388	Y	N	Y	2	TX - REPLACE	2500
FAS_14075	07389	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14080	07390	N	N	N	1	CUSTOMER ISSUE	-
FAS_14087	07391	N	N	N	1	CUSTOMER ISSUE	-
FAS_14088	07392	N	N	N	1	CUSTOMER ISSUE	-
FAS_14089	07393	N	N	N	1	CUSTOMER ISSUE	-
FAS_14090	07394	N	N	N	1	CUSTOMER ISSUE	-
FAS_14091	07395	Y	N	N	1	CUSTOMER ISSUE	-
FAS_14093	07396	N	N	N	1	CUSTOMER ISSUE	-
FAS_14094	07397	N	N	N	1	CUSTOMER ISSUE	-
FAS_14095	07398	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_14096	07399	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_14097	07400	Y	N	Y	1	TX - REPLACE	2500
FAS_14098	07401	N	N	N	1	CUSTOMER ISSUE	-
FAS_14099	07402	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14100	07403	N	N	N	1	CUSTOMER ISSUE	-
FAS_14101	07404	N	N	Y	1	DIST - TREE TRIMMING	945
FAS_14102	07405	Y	N	Y	1	TX - REPLACE	2500
FAS_14103	07406	Y	N	Y	1	TX - REPLACE	2500
FAS_14104	07407	Y	N	Y	1	TX - REPLACE	2500
FAS_14105	07408	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
FAS_14106	07409	N	N	Y	1	TX - REPLACE	2500
FAS_14107	07410	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_14109	07411	N	N	Y	1	TX - REPLACE	2500
FAS_14112	07412	N	N	Y	1	TX - REPLACE	2500
FAS_14113	07413	N	N	Y	1	TX - REPLACE	2500
FAS_14114	07414	N	N	Y	1	TX - REPLACE	2500
FAS_14115	07415	Y	N	Y	1	TX - REPLACE	2500
FAS_14117	07416	Y	N	Y	1	TX - REPLACE	2500

FAS_14126	07417	N	N	Y	1	TX - REPLACE	2500
FAS_14128	07418	Y	N	Y	1	TX - REPLACE	2500
FAS_14136	07419	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14137	07420	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14138	07421	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14144	07422	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14147	07423	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14148	07424	N	N	Y	2	TX - REPLACE	2500
FAS_14158	07425	N	N	N	1	CUSTOMER ISSUE	-
FAS_14159	07426	Y	N	N	1	CUSTOMER ISSUE	-
FAS_14162	07427	N	N	N	1	CUSTOMER ISSUE	-
FAS_14165	07428	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
FAS_14169	07429	N	N	N	1	CUSTOMER ISSUE	-
FAS_14170	07430	N	N	N	2	CUSTOMER ISSUE	-
FAS_14175	07431	N	N	N	1	CUSTOMER ISSUE	-
FAS_14177	07432	N	N	N	1	CUSTOMER ISSUE	-
FAS_14178	07433	N	N	N	1	CUSTOMER ISSUE	-
FAS_14179	07434	N	N	N	1	CUSTOMER ISSUE	-
FAS_14181	07435	N	N	N	1	CUSTOMER ISSUE	-
FAS_14182	07436	N	N	N	1	CUSTOMER ISSUE	-
FAS_14183	07437	N	N	N	1	CUSTOMER ISSUE	-
FAS_14185	07438	N	N	N	1	CUSTOMER ISSUE	-
FAS_14191	07439	N	N	Y	2	DIST - REPLACE FUSE	708.75
FAS_14193	07440	N	N	N	29	CUSTOMER ISSUE	-
FAS_14196	07441	N	N	N	1	CUSTOMER ISSUE	-
FAS_14198	07442	N	N	N	1	CUSTOMER ISSUE	-
FAS_14199	07443	N	N	N	8	CUSTOMER ISSUE	-
FAS_14200	07444	N	N	N	1	CUSTOMER ISSUE	-
FAS_14201	07445	N	N	N	1	CUSTOMER ISSUE	-
FAS_14203	07446	N	N	N	1	CUSTOMER ISSUE	-
FAS_14204	07447	Y	N	Y	1	DIST - TREE TRIMMING	945
FAS_14205	07448	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14206	07449	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_14207	07450	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_14211	07451	N	N	N	1	CUSTOMER ISSUE	-
FAS_14212	07452	N	N	N	1	CUSTOMER ISSUE	-
FAS_14213	07453	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_14216	07454	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14221	07455	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_14222	07456	N	N	N	1	CUSTOMER ISSUE	-
FAS_14225	07457	N	N	Y	1	TX - REPLACE	2500
FAS_14229	07458	N	N	Y	2	DIST - TREE TRIMMING	945
FAS_14230	07459	N	N	Y	2	SEC/SVC - REPLACE	708.75
FAS_14232	07460	N	N	N	1	CUSTOMER ISSUE	-
FAS_14233	07461	N	N	N	1	CUSTOMER ISSUE	-
FAS_14235	07462	N	N	N	8	CUSTOMER ISSUE	-
FAS_14236	07463	N	N	N	1	CUSTOMER ISSUE	-
FAS_14239	07464	N	N	N	1	CUSTOMER ISSUE	-
FAS_14244	07465	N	N	N	1	CUSTOMER ISSUE	-
FAS_14245	07466	N	N	N	2	CUSTOMER ISSUE	-
FAS_14246	07467	N	N	N	1	CUSTOMER ISSUE	-
FAS_14247	07468	N	N	N	1	CUSTOMER ISSUE	-
FAS_14248	07469	N	N	N	1	CUSTOMER ISSUE	-
FAS_14250	07470	N	N	N	1	CUSTOMER ISSUE	-
FAS_14253	07471	N	N	N	1	CUSTOMER ISSUE	-
FAS_14254	07472	N	N	N	1	CUSTOMER ISSUE	-
FAS_14255	07473	N	N	N	1	CUSTOMER ISSUE	-
FAS_14256	07474	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14258	07475	N	N	N	1	CUSTOMER ISSUE	-
FAS_14259	07476	N	N	N	1	CUSTOMER ISSUE	-
FAS_14261	07477	N	N	N	1	CUSTOMER ISSUE	-
FAS_14262	07478	N	N	Y	1	TX - REPLACE	2500
FAS_14264	07479	N	N	N	1	CUSTOMER ISSUE	-
FAS_14265	07480	N	N	N	1	CUSTOMER ISSUE	-
FAS_14266	07481	N	N	N	1	CUSTOMER ISSUE	-
FAS_14267	07482	N	N	N	1	CUSTOMER ISSUE	-
FAS_14270	07483	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14272	07484	N	N	N	1	CUSTOMER ISSUE	-
FAS_14273	07485	N	N	N	1	CUSTOMER ISSUE	-
FAS_14276	07486	N	N	N	1	CUSTOMER ISSUE	-
FAS_14279	07487	N	N	Y	1	TX - REPLACE	2500
FAS_14280	07488	N	N	Y	3	SEC/SVC - REPAIR	472.5
FAS_14283	07489	Y	N	N	1	CUSTOMER ISSUE	-
FAS_14284	07490	N	N	N	1	CUSTOMER ISSUE	-
FAS_14285	07491	N	N	N	1	CUSTOMER ISSUE	-
FAS_14287	07492	N	N	N	1	CUSTOMER ISSUE	-
FAS_14288	07493	N	N	N	1	CUSTOMER ISSUE	-
FAS_14290	07494	Y	N	N	1	CUSTOMER ISSUE	-
FAS_14293	07495	N	N	N	1	CUSTOMER ISSUE	-
FAS_14294	07496	N	N	N	1	CUSTOMER ISSUE	-

FAS_14296	07497	Y	N	N	1	CUSTOMER ISSUE	-
FAS_14297	07498	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14300	07499	N	N	N	1	CUSTOMER ISSUE	-
FAS_14301	07500	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14302	07501	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14303	07502	Y	N	N	1	CUSTOMER ISSUE	-
FAS_14305	07503	N	N	N	1	CUSTOMER ISSUE	-
FAS_14306	07504	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14307	07505	N	N	N	1	CUSTOMER ISSUE	-
FAS_14309	07506	N	N	N	1	CUSTOMER ISSUE	-
FAS_14312	07507	Y	N	N	1	CUSTOMER ISSUE	-
FAS_14315	07508	N	N	N	1	CUSTOMER ISSUE	-
FAS_14316	07509	N	N	Y	1	TX - REPLACE	2500
FAS_14317	07510	N	N	Y	1	TX - REPLACE	2500
FAS_14320	07511	N	N	N	1	CUSTOMER ISSUE	-
FAS_14321	07512	N	N	N	1	CUSTOMER ISSUE	-
FAS_14322	07513	N	N	N	1	CUSTOMER ISSUE	-
FAS_14323	07514	N	N	N	1	CUSTOMER ISSUE	-
FAS_14324	07515	N	N	N	1	CUSTOMER ISSUE	-
FAS_14326	07516	N	N	N	1	CUSTOMER ISSUE	-
FAS_14327	07517	N	N	N	1	CUSTOMER ISSUE	-
FAS_14328	07518	N	N	N	1	CUSTOMER ISSUE	-
FAS_14329	07519	Y	N	Y	16	SEC/SVC - REPLACE	708.75
FAS_14335	07520	N	N	N	1	CUSTOMER ISSUE	-
FAS_14336	07521	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14347	07522	N	N	Y	1	TX - REPLACE	2500
FAS_14351	07523	N	N	N	1	CUSTOMER ISSUE	-
FAS_14352	07524	N	N	N	1	CUSTOMER ISSUE	-
FAS_14353	07525	N	N	N	2	CUSTOMER ISSUE	-
FAS_14354	07526	N	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
FAS_14355	07527	N	N	N	1	CUSTOMER ISSUE	-
FAS_14356	07528	N	N	N	1	CUSTOMER ISSUE	-
FAS_14358	07529	N	N	N	1	CUSTOMER ISSUE	-
FAS_14359	07530	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_14361	07531	N	N	N	1	CUSTOMER ISSUE	-
FAS_14362	07532	N	N	N	1	CUSTOMER ISSUE	-
FAS_14363	07533	N	N	N	1	CUSTOMER ISSUE	-
FAS_14365	07534	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14367	07535	N	N	N	1	CUSTOMER ISSUE	-
FAS_14370	07536	N	N	N	1	CUSTOMER ISSUE	-
FAS_14373	07537	N	N	N	1	CUSTOMER ISSUE	-
FAS_14374	07538	Y	N	N	1	CUSTOMER ISSUE	-
FAS_14378	07539	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14379	07540	N	N	N	1	CUSTOMER ISSUE	-
FAS_14380	07541	N	N	Y	2	TX - REPLACE	2500
FAS_14381	07542	Y	N	N	1	CUSTOMER ISSUE	-
FAS_14383	07543	N	N	N	1	CUSTOMER ISSUE	-
FAS_14385	07544	Y	N	N	1	CUSTOMER ISSUE	-
FAS_14389	07545	N	N	N	2	CUSTOMER ISSUE	-
FAS_14390	07546	Y	N	N	1	CUSTOMER ISSUE	-
FAS_14393	07547	N	N	N	1	CUSTOMER ISSUE	-
FAS_14398	07548	N	N	N	1	CUSTOMER ISSUE	-
FAS_14402	07549	N	N	N	1	CUSTOMER ISSUE	-
FAS_14403	07550	N	N	N	1	CUSTOMER ISSUE	-
FAS_14405	07551	N	N	N	2	CUSTOMER ISSUE	-
FAS_14406	07552	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14407	07553	N	N	N	1	CUSTOMER ISSUE	-
FAS_14409	07554	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14415	07555	N	N	N	1	CUSTOMER ISSUE	-
FAS_14417	07556	N	N	N	1	CUSTOMER ISSUE	-
FAS_14422	07557	N	N	N	1	CUSTOMER ISSUE	-
FAS_14425	07558	N	N	N	1	CUSTOMER ISSUE	-
FAS_14435	07559	N	N	N	1	CUSTOMER ISSUE	-
FAS_14441	07560	N	N	N	1	CUSTOMER ISSUE	-
FAS_14442	07561	N	N	N	1	CUSTOMER ISSUE	-
FAS_14443	07562	N	N	N	1	CUSTOMER ISSUE	-
FAS_14447	07563	N	N	N	1	CUSTOMER ISSUE	-
FAS_14452	07564	N	N	N	8	CUSTOMER ISSUE	-
FAS_14454	07565	N	N	N	1	CUSTOMER ISSUE	-
FAS_14455	07566	N	N	N	1	CUSTOMER ISSUE	-
FAS_14456	07567	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14458	07568	N	N	N	1	CUSTOMER ISSUE	-
FAS_14459	07569	N	N	N	1	CUSTOMER ISSUE	-
FAS_14460	07570	N	N	N	1	CUSTOMER ISSUE	-
FAS_14461	07571	N	N	N	1	CUSTOMER ISSUE	-
FAS_14462	07572	N	N	N	1	CUSTOMER ISSUE	-
FAS_14463	07573	N	N	N	1	CUSTOMER ISSUE	-
FAS_14464	07574	N	N	Y	1	TX - REPLACE	2500
FAS_14465	07575	N	N	Y	1	TX - REPLACE	2500
FAS_14466	07576	N	N	Y	1	TX - REPLACE	2500

FAS_14467	07577	N	N	Y	1	TX - REPLACE	2500
FAS_14468	07578	N	N	Y	1	TX - REPLACE	2500
FAS_14470	07579	N	N	N	1	CUSTOMER ISSUE	-
FAS_14473	07580	N	N	N	1	CUSTOMER ISSUE	-
FAS_14477	07581	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14478	07582	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14481	07583	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14486	07584	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14488	07585	N	N	N	1	CUSTOMER ISSUE	-
FAS_14499	07586	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14500	07587	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14501	07588	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14504	07589	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14506	07590	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14511	07591	Y	N	N	1	CUSTOMER ISSUE	-
FAS_14513	07592	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14515	07593	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14516	07594	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14521	07595	N	N	N	1	CUSTOMER ISSUE	-
FAS_14527	07596	N	N	N	1	CUSTOMER ISSUE	-
FAS_14528	07597	N	N	N	1	CUSTOMER ISSUE	-
FAS_14531	07598	N	N	N	1	CUSTOMER ISSUE	-
FAS_14533	07599	Y	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14534	07600	N	N	N	1	CUSTOMER ISSUE	-
FAS_14537	07601	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14539	07602	N	N	N	1	CUSTOMER ISSUE	-
FAS_14540	07603	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14541	07604	Y	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14547	07605	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14553	07606	N	N	Y	1	SEC/SVC - REPAIR	472.5
FAS_14554	07607	N	N	N	1	CUSTOMER ISSUE	-
FAS_14557	07608	N	N	N	1	CUSTOMER ISSUE	-
FAS_14559	07609	N	N	N	2	CUSTOMER ISSUE	-
FAS_14563	07610	N	N	N	1	CUSTOMER ISSUE	-
FAS_14564	07611	N	N	N	1	CUSTOMER ISSUE	-
FAS_14572	07612	Y	N	Y	1	TX/SEC/SVC- REPLACE	3800
FAS_14575	07613	N	N	Y	1	TX - REPLACE	2500
FAS_14579	07614	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14583	07615	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14585	07616	N	N	Y	1	DIST - REPLACE FUSE	708.75
FAS_14586	07617	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14587	07618	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14588	07619	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14589	07620	N	N	N	1	CUSTOMER ISSUE	-
FAS_14590	07621	N	N	Y	1	SEC/SVC - REPLACE	708.75
FAS_14612	07622	N	N	N	1	CUSTOMER ISSUE	-
FAS_14613	07623	N	N	N	1	CUSTOMER ISSUE	-
FAS_14619	07624	N	N	N	1	CUSTOMER ISSUE	-
FAS_14620	07625	N	N	N	1	CUSTOMER ISSUE	-
DMS_00001	07626	N	N	N	1	CUSTOMER ISSUE	-
DMS_00004	07627	N	N	N	1	CUSTOMER ISSUE	-
DMS_00015	07628	N	N	N	1	CUSTOMER ISSUE	-
DMS_00016	07629	N	N	N	1	CUSTOMER ISSUE	-
DMS_00017	07630	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00018	07631	N	N	N	1	CUSTOMER ISSUE	-
DMS_00019	07632	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00021	07633	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00023	07634	N	N	N	1	CUSTOMER ISSUE	-
DMS_00024	07635	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00025	07636	N	N	N	1	CUSTOMER ISSUE	-
DMS_00027	07637	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00028	07638	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00029	07639	N	N	N	1	CUSTOMER ISSUE	-
DMS_00030	07640	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00031	07641	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00032	07642	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00033	07643	N	N	N	1	CUSTOMER ISSUE	-
DMS_00034	07644	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00035	07645	N	N	N	1	CUSTOMER ISSUE	-
DMS_00036	07646	N	N	N	1	CUSTOMER ISSUE	-
DMS_00037	07647	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00038	07648	N	N	N	1	CUSTOMER ISSUE	-
DMS_00039	07649	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00040	07650	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00041	07651	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00042	07652	N	N	N	2	CUSTOMER ISSUE	-
DMS_00043	07653	N	N	N	1	CUSTOMER ISSUE	-
DMS_00044	07654	N	N	N	1	CUSTOMER ISSUE	-
DMS_00046	07655	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_00047	07656	N	N	N	1	CUSTOMER ISSUE	-

DMS_00048	07657	N	N	N	1	CUSTOMER ISSUE	-
DMS_00049	07658	N	N	N	1	CUSTOMER ISSUE	-
DMS_00050	07659	N	N	N	1	CUSTOMER ISSUE	-
DMS_00051	07660	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00053	07661	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00054	07662	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00057	07663	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00058	07664	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00059	07665	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00060	07666	N	N	N	1	CUSTOMER ISSUE	-
DMS_00061	07667	N	N	N	1	CUSTOMER ISSUE	-
DMS_00062	07668	N	N	N	1	CUSTOMER ISSUE	-
DMS_00063	07669	N	N	N	1	CUSTOMER ISSUE	-
DMS_00064	07670	N	N	N	1	CUSTOMER ISSUE	-
DMS_00065	07671	N	N	N	1	CUSTOMER ISSUE	-
DMS_00066	07672	N	N	N	1	CUSTOMER ISSUE	-
DMS_00067	07673	N	N	N	1	CUSTOMER ISSUE	-
DMS_00068	07674	N	N	N	1	CUSTOMER ISSUE	-
DMS_00069	07675	N	N	N	1	CUSTOMER ISSUE	-
DMS_00070	07676	N	N	N	1	CUSTOMER ISSUE	-
DMS_00071	07677	N	N	N	1	CUSTOMER ISSUE	-
DMS_00072	07678	N	N	N	1	CUSTOMER ISSUE	-
DMS_00073	07679	N	N	N	1	CUSTOMER ISSUE	-
DMS_00074	07680	N	N	N	1	CUSTOMER ISSUE	-
DMS_00075	07681	N	N	N	1	CUSTOMER ISSUE	-
DMS_00076	07682	N	N	N	1	CUSTOMER ISSUE	-
DMS_00077	07683	N	N	N	1	CUSTOMER ISSUE	-
DMS_00078	07684	N	N	N	1	CUSTOMER ISSUE	-
DMS_00079	07685	N	N	N	1	CUSTOMER ISSUE	-
DMS_00080	07686	N	N	N	1	CUSTOMER ISSUE	-
DMS_00081	07687	N	N	N	1	CUSTOMER ISSUE	-
DMS_00082	07688	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00083	07689	N	N	N	1	CUSTOMER ISSUE	-
DMS_00084	07690	N	N	N	1	CUSTOMER ISSUE	-
DMS_00085	07691	N	N	N	1	CUSTOMER ISSUE	-
DMS_00086	07692	N	N	N	1	CUSTOMER ISSUE	-
DMS_00087	07693	N	N	N	1	CUSTOMER ISSUE	-
DMS_00088	07694	N	N	N	1	CUSTOMER ISSUE	-
DMS_00089	07695	N	N	N	1	CUSTOMER ISSUE	-
DMS_00090	07696	N	N	N	1	CUSTOMER ISSUE	-
DMS_00091	07697	N	N	N	1	CUSTOMER ISSUE	-
DMS_00092	07698	N	N	N	1	CUSTOMER ISSUE	-
DMS_00093	07699	N	N	N	1	CUSTOMER ISSUE	-
DMS_00094	07700	N	N	N	1	CUSTOMER ISSUE	-
DMS_00095	07701	N	N	N	1	CUSTOMER ISSUE	-
DMS_00097	07702	N	N	Y	1	TX - REPLACE	2500
DMS_00098	07703	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00099	07704	N	N	N	1	CUSTOMER ISSUE	-
DMS_00100	07705	N	N	N	1	CUSTOMER ISSUE	-
DMS_00102	07706	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00104	07707	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00106	07708	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00107	07709	N	N	N	1	CUSTOMER ISSUE	-
DMS_00108	07710	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00109	07711	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00110	07712	N	N	N	1	CUSTOMER ISSUE	-
DMS_00111	07713	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00112	07714	N	N	N	1	CUSTOMER ISSUE	-
DMS_00113	07715	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00114	07716	N	N	N	1	CUSTOMER ISSUE	-
DMS_00115	07717	N	N	N	1	CUSTOMER ISSUE	-
DMS_00116	07718	N	N	N	1	CUSTOMER ISSUE	-
DMS_00118	07719	N	N	N	1	CUSTOMER ISSUE	-
DMS_00119	07720	N	N	N	1	CUSTOMER ISSUE	-
DMS_00120	07721	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00121	07722	N	N	N	1	CUSTOMER ISSUE	-
DMS_00122	07723	N	N	N	1	CUSTOMER ISSUE	-
DMS_00123	07724	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00124	07725	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00125	07726	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00127	07727	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00128	07728	N	N	N	1	CUSTOMER ISSUE	-
DMS_00129	07729	N	N	N	1	CUSTOMER ISSUE	-
DMS_00131	07730	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00132	07731	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_00133	07732	N	N	N	1	CUSTOMER ISSUE	-
DMS_00134	07733	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00135	07734	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00136	07735	N	N	N	1	CUSTOMER ISSUE	-
DMS_00137	07736	N	N	N	1	CUSTOMER ISSUE	-

DMS_00138	07737	N	N	N	1	CUSTOMER ISSUE	-
DMS_00140	07738	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00141	07739	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_00142	07740	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00143	07741	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00144	07742	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00145	07743	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00146	07744	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00147	07745	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00148	07746	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00149	07747	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00150	07748	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00151	07749	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00152	07750	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00153	07751	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00154	07752	N	N	N	1	CUSTOMER ISSUE	-
DMS_00155	07753	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00156	07754	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00157	07755	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00159	07756	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00168	07757	N	N	N	1	CUSTOMER ISSUE	-
DMS_00178	07758	N	N	N	1	CUSTOMER ISSUE	-
DMS_00180	07759	N	N	N	1	CUSTOMER ISSUE	-
DMS_00185	07760	N	N	N	1	CUSTOMER ISSUE	-
DMS_00187	07761	N	N	N	1	CUSTOMER ISSUE	-
DMS_00191	07762	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
DMS_00192	07763	N	N	N	1	CUSTOMER ISSUE	-
DMS_00193	07764	N	N	N	1	CUSTOMER ISSUE	-
DMS_00194	07765	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00195	07766	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00196	07767	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00197	07768	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00198	07769	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00199	07770	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00200	07771	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00201	07772	N	N	N	1	CUSTOMER ISSUE	-
DMS_00202	07773	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00204	07774	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00206	07775	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00213	07776	N	N	N	1	CUSTOMER ISSUE	-
DMS_00214	07777	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00215	07778	N	N	N	1	CUSTOMER ISSUE	-
DMS_00216	07779	N	N	N	1	CUSTOMER ISSUE	-
DMS_00217	07780	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00219	07781	N	N	N	1	CUSTOMER ISSUE	-
DMS_00220	07782	N	N	N	1	CUSTOMER ISSUE	-
DMS_00221	07783	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00222	07784	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00223	07785	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00224	07786	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00225	07787	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00226	07788	N	N	N	1	CUSTOMER ISSUE	-
DMS_00227	07789	N	N	N	1	CUSTOMER ISSUE	-
DMS_00228	07790	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00229	07791	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00230	07792	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00231	07793	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00232	07794	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00233	07795	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00234	07796	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00235	07797	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00236	07798	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_00237	07799	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00238	07800	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00240	07801	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00242	07802	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_00244	07803	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00245	07804	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00246	07805	N	N	N	1	CUSTOMER ISSUE	-
DMS_00247	07806	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00248	07807	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00249	07808	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00250	07809	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00251	07810	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00252	07811	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00253	07812	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00254	07813	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00255	07814	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00256	07815	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00257	07816	N	N	Y	1	DIST - REPLACE FUSE	708.75

DMS_00258	07817	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00259	07818	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00260	07819	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00261	07820	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00262	07821	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00263	07822	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00264	07823	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00265	07824	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00266	07825	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00267	07826	N	N	N	1	CUSTOMER ISSUE	-
DMS_00268	07827	N	N	N	1	CUSTOMER ISSUE	-
DMS_00269	07828	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00270	07829	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00271	07830	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00272	07831	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00273	07832	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00274	07833	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00275	07834	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00276	07835	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00277	07836	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00278	07837	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00279	07838	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00280	07839	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00281	07840	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00282	07841	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_00283	07842	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00284	07843	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00285	07844	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00286	07845	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00287	07846	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00288	07847	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00289	07848	N	N	N	1	CUSTOMER ISSUE	-
DMS_00290	07849	N	N	N	1	CUSTOMER ISSUE	-
DMS_00291	07850	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00292	07851	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00293	07852	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00294	07853	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00295	07854	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00296	07855	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00297	07856	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00298	07857	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00299	07858	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00300	07859	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00301	07860	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00302	07861	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00303	07862	N	N	N	1	CUSTOMER ISSUE	-
DMS_00304	07863	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00305	07864	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00306	07865	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00307	07866	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00308	07867	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00309	07868	N	N	N	1	CUSTOMER ISSUE	-
DMS_00310	07869	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00311	07870	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_00313	07871	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00314	07872	N	N	N	1	CUSTOMER ISSUE	-
DMS_00315	07873	N	N	N	1	CUSTOMER ISSUE	-
DMS_00317	07874	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00318	07875	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00319	07876	N	N	N	1	CUSTOMER ISSUE	-
DMS_00322	07877	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00323	07878	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00324	07879	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00325	07880	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00326	07881	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00327	07882	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00328	07883	N	N	N	1	CUSTOMER ISSUE	-
DMS_00329	07884	N	N	N	1	CUSTOMER ISSUE	-
DMS_00330	07885	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00331	07886	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00332	07887	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00333	07888	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00334	07889	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00336	07890	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00337	07891	N	N	N	1	CUSTOMER ISSUE	-
DMS_00338	07892	N	N	N	1	CUSTOMER ISSUE	-
DMS_00339	07893	N	N	N	1	CUSTOMER ISSUE	-
DMS_00340	07894	N	N	N	1	CUSTOMER ISSUE	-
DMS_00341	07895	N	N	N	1	CUSTOMER ISSUE	-
DMS_00342	07896	N	N	Y	1	DIST - REPLACE FUSE	708.75

DMS_00343	07897	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00344	07898	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00346	07899	N	N	N	1	CUSTOMER ISSUE	-
DMS_00347	07900	N	N	N	1	CUSTOMER ISSUE	-
DMS_00348	07901	N	N	Y	1	TX - REPLACE	2500
DMS_00350	07902	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_00351	07903	N	N	N	1	CUSTOMER ISSUE	-
DMS_00352	07904	N	N	N	1	CUSTOMER ISSUE	-
DMS_00353	07905	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00354	07906	N	N	N	1	CUSTOMER ISSUE	-
DMS_00355	07907	N	N	N	1	CUSTOMER ISSUE	-
DMS_00356	07908	N	N	N	1	CUSTOMER ISSUE	-
DMS_00357	07909	N	N	N	1	CUSTOMER ISSUE	-
DMS_00358	07910	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00359	07911	N	N	N	1	CUSTOMER ISSUE	-
DMS_00360	07912	N	N	N	1	CUSTOMER ISSUE	-
DMS_00361	07913	N	N	N	1	CUSTOMER ISSUE	-
DMS_00362	07914	N	N	N	1	CUSTOMER ISSUE	-
DMS_00363	07915	N	N	N	1	CUSTOMER ISSUE	-
DMS_00364	07916	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00365	07917	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00366	07918	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00367	07919	N	N	N	1	CUSTOMER ISSUE	-
DMS_00368	07920	N	N	N	1	CUSTOMER ISSUE	-
DMS_00369	07921	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00372	07922	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00373	07923	N	N	N	1	CUSTOMER ISSUE	-
DMS_00374	07924	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00376	07925	N	N	N	1	CUSTOMER ISSUE	-
DMS_00377	07926	N	N	N	1	CUSTOMER ISSUE	-
DMS_00378	07927	N	N	N	1	CUSTOMER ISSUE	-
DMS_00379	07928	N	N	N	1	CUSTOMER ISSUE	-
DMS_00380	07929	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00381	07930	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00383	07931	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00385	07932	N	N	N	1	CUSTOMER ISSUE	-
DMS_00386	07933	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00387	07934	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00388	07935	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00389	07936	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00390	07937	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00391	07938	N	N	N	1	CUSTOMER ISSUE	-
DMS_00392	07939	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00393	07940	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00394	07941	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00395	07942	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00396	07943	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00397	07944	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_00398	07945	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00399	07946	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00400	07947	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00401	07948	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00402	07949	N	N	N	1	CUSTOMER ISSUE	-
DMS_00403	07950	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00404	07951	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00405	07952	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00406	07953	N	N	N	1	CUSTOMER ISSUE	-
DMS_00407	07954	N	N	N	1	CUSTOMER ISSUE	-
DMS_00408	07955	N	N	N	1	CUSTOMER ISSUE	-
DMS_00409	07956	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00410	07957	N	N	N	1	CUSTOMER ISSUE	-
DMS_00411	07958	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00412	07959	N	N	N	1	CUSTOMER ISSUE	-
DMS_00413	07960	N	N	N	1	CUSTOMER ISSUE	-
DMS_00414	07961	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00415	07962	N	N	N	1	CUSTOMER ISSUE	-
DMS_00416	07963	N	N	N	1	CUSTOMER ISSUE	-
DMS_00417	07964	N	N	N	1	CUSTOMER ISSUE	-
DMS_00418	07965	N	N	N	1	CUSTOMER ISSUE	-
DMS_00419	07966	N	N	N	1	CUSTOMER ISSUE	-
DMS_00420	07967	N	N	N	1	CUSTOMER ISSUE	-
DMS_00421	07968	N	N	N	1	CUSTOMER ISSUE	-
DMS_00422	07969	N	N	N	1	CUSTOMER ISSUE	-
DMS_00425	07970	N	N	N	1	CUSTOMER ISSUE	-
DMS_00426	07971	N	N	N	1	CUSTOMER ISSUE	-
DMS_00427	07972	N	N	N	1	CUSTOMER ISSUE	-
DMS_00428	07973	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00429	07974	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00430	07975	N	N	N	1	CUSTOMER ISSUE	-
DMS_00431	07976	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_00432	07977	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00434	07978	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00435	07979	N	N	Y	3	SEC/SVC - REPAIR	472.5
DMS_00439	07980	N	N	N	1	CUSTOMER ISSUE	-
DMS_00440	07981	N	N	N	1	CUSTOMER ISSUE	-
DMS_00441	07982	N	N	N	1	CUSTOMER ISSUE	-
DMS_00442	07983	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00443	07984	N	N	N	1	CUSTOMER ISSUE	-
DMS_00444	07985	N	N	N	1	CUSTOMER ISSUE	-
DMS_00445	07986	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00446	07987	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00447	07988	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00448	07989	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00449	07990	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00450	07991	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00451	07992	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00452	07993	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00453	07994	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00454	07995	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00455	07996	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00456	07997	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00457	07998	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00458	07999	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00459	08000	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00460	08001	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00461	08002	N	N	N	1	CUSTOMER ISSUE	-
DMS_00462	08003	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00464	08004	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00465	08005	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00466	08006	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00467	08007	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00468	08008	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00469	08009	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00472	08010	N	N	N	1	CUSTOMER ISSUE	-
DMS_00474	08011	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_00478	08012	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00479	08013	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00480	08014	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00481	08015	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00482	08016	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00483	08017	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_00484	08018	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00485	08019	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00486	08020	N	N	N	1	CUSTOMER ISSUE	-
DMS_00488	08021	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00489	08022	N	N	N	1	CUSTOMER ISSUE	-
DMS_00490	08023	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00491	08024	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00492	08025	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00494	08026	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00495	08027	N	N	N	1	CUSTOMER ISSUE	-
DMS_00496	08028	N	N	N	1	CUSTOMER ISSUE	-
DMS_00497	08029	N	N	N	1	CUSTOMER ISSUE	-
DMS_00498	08030	N	N	N	1	CUSTOMER ISSUE	-
DMS_00499	08031	N	N	N	1	CUSTOMER ISSUE	-
DMS_00500	08032	N	N	N	1	CUSTOMER ISSUE	-
DMS_00501	08033	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00502	08034	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00503	08035	N	N	N	1	CUSTOMER ISSUE	-
DMS_00505	08036	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00506	08037	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00507	08038	N	N	N	1	CUSTOMER ISSUE	-
DMS_00508	08039	N	N	N	1	CUSTOMER ISSUE	-
DMS_00509	08040	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00511	08041	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_00513	08042	N	N	N	1	CUSTOMER ISSUE	-
DMS_00515	08043	N	N	N	1	CUSTOMER ISSUE	-
DMS_00518	08044	N	N	N	1	CUSTOMER ISSUE	-
DMS_00519	08045	N	N	N	1	CUSTOMER ISSUE	-
DMS_00520	08046	N	N	N	1	CUSTOMER ISSUE	-
DMS_00522	08047	N	N	N	1	CUSTOMER ISSUE	-
DMS_00524	08048	N	N	N	1	CUSTOMER ISSUE	-
DMS_00526	08049	N	N	N	1	CUSTOMER ISSUE	-
DMS_00527	08050	N	N	N	1	CUSTOMER ISSUE	-
DMS_00528	08051	N	N	N	1	CUSTOMER ISSUE	-
DMS_00530	08052	N	N	N	1	CUSTOMER ISSUE	-
DMS_00531	08053	N	N	N	1	CUSTOMER ISSUE	-
DMS_00532	08054	N	N	N	1	CUSTOMER ISSUE	-
DMS_00534	08055	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00535	08056	N	N	N	1	CUSTOMER ISSUE	-

DMS_00536	08057	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00537	08058	N	N	N	1	CUSTOMER ISSUE	-
DMS_00539	08059	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00540	08060	N	N	N	1	CUSTOMER ISSUE	-
DMS_00541	08061	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00542	08062	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00555	08063	N	N	N	1	CUSTOMER ISSUE	-
DMS_00556	08064	N	N	N	1	CUSTOMER ISSUE	-
DMS_00557	08065	N	N	N	1	CUSTOMER ISSUE	-
DMS_00558	08066	N	N	N	1	CUSTOMER ISSUE	-
DMS_00559	08067	N	N	N	1	CUSTOMER ISSUE	-
DMS_00560	08068	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00561	08069	N	N	N	1	CUSTOMER ISSUE	-
DMS_00562	08070	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00564	08071	N	N	N	1	CUSTOMER ISSUE	-
DMS_00565	08072	N	N	N	1	CUSTOMER ISSUE	-
DMS_00566	08073	N	N	N	1	CUSTOMER ISSUE	-
DMS_00567	08074	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00568	08075	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00569	08076	N	N	N	1	CUSTOMER ISSUE	-
DMS_00570	08077	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00571	08078	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00575	08079	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00576	08080	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00579	08081	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00581	08082	N	N	N	1	CUSTOMER ISSUE	-
DMS_00582	08083	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00583	08084	N	N	N	1	CUSTOMER ISSUE	-
DMS_00584	08085	N	N	N	1	CUSTOMER ISSUE	-
DMS_00585	08086	N	N	N	1	CUSTOMER ISSUE	-
DMS_00586	08087	N	N	N	1	CUSTOMER ISSUE	-
DMS_00587	08088	N	N	Y	3	SEC/SVC - REPLACE	708.75
DMS_00588	08089	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00589	08090	N	N	N	1	CUSTOMER ISSUE	-
DMS_00590	08091	N	N	N	1	CUSTOMER ISSUE	-
DMS_00593	08092	N	N	Y	1	TX - REPLACE	2500
DMS_00594	08093	N	N	N	1	CUSTOMER ISSUE	-
DMS_00596	08094	N	N	N	1	CUSTOMER ISSUE	-
DMS_00597	08095	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00598	08096	N	N	N	1	CUSTOMER ISSUE	-
DMS_00600	08097	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00602	08098	N	N	N	1	CUSTOMER ISSUE	-
DMS_00605	08099	N	N	N	1	CUSTOMER ISSUE	-
DMS_00606	08100	N	N	N	1	CUSTOMER ISSUE	-
DMS_00607	08101	N	N	N	1	CUSTOMER ISSUE	-
DMS_00609	08102	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00610	08103	N	N	N	1	CUSTOMER ISSUE	-
DMS_00611	08104	N	N	N	1	CUSTOMER ISSUE	-
DMS_00612	08105	N	N	N	1	CUSTOMER ISSUE	-
DMS_00613	08106	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_00614	08107	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00615	08108	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00616	08109	N	N	Y	4	SEC/SVC - REPLACE	708.75
DMS_00619	08110	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00620	08111	N	N	N	1	CUSTOMER ISSUE	-
DMS_00622	08112	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_00623	08113	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00624	08114	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00625	08115	N	N	N	1	CUSTOMER ISSUE	-
DMS_00626	08116	N	N	N	1	CUSTOMER ISSUE	-
DMS_00627	08117	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00628	08118	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00629	08119	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00630	08120	N	N	N	1	CUSTOMER ISSUE	-
DMS_00631	08121	N	N	N	1	CUSTOMER ISSUE	-
DMS_00632	08122	N	N	N	1	CUSTOMER ISSUE	-
DMS_00633	08123	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00634	08124	N	N	N	1	CUSTOMER ISSUE	-
DMS_00635	08125	N	N	N	1	CUSTOMER ISSUE	-
DMS_00636	08126	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00637	08127	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00638	08128	N	N	N	1	CUSTOMER ISSUE	-
DMS_00639	08129	N	N	N	1	CUSTOMER ISSUE	-
DMS_00640	08130	N	N	N	1	CUSTOMER ISSUE	-
DMS_00641	08131	N	N	N	1	CUSTOMER ISSUE	-
DMS_00642	08132	N	N	N	1	CUSTOMER ISSUE	-
DMS_00643	08133	N	N	N	1	CUSTOMER ISSUE	-
DMS_00644	08134	N	N	N	1	CUSTOMER ISSUE	-
DMS_00645	08135	N	N	N	1	CUSTOMER ISSUE	-
DMS_00646	08136	N	N	N	1	CUSTOMER ISSUE	-

DMS_00650	08137	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00651	08138	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00652	08139	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00654	08140	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00655	08141	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00656	08142	N	N	N	1	CUSTOMER ISSUE	-
DMS_00657	08143	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00659	08144	N	N	N	1	CUSTOMER ISSUE	-
DMS_00660	08145	N	N	Y	1	TX - REPLACE	2500
DMS_00661	08146	N	N	N	1	CUSTOMER ISSUE	-
DMS_00662	08147	N	N	N	1	CUSTOMER ISSUE	-
DMS_00663	08148	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00664	08149	N	N	Y	1	TX - REPLACE	2500
DMS_00665	08150	N	N	N	1	CUSTOMER ISSUE	-
DMS_00666	08151	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_00667	08152	N	N	Y	3	SEC/SVC - REPLACE	708.75
DMS_00668	08153	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00670	08154	N	N	N	1	CUSTOMER ISSUE	-
DMS_00671	08155	N	N	Y	6	SEC/SVC - REPLACE	708.75
DMS_00672	08156	N	N	N	1	CUSTOMER ISSUE	-
DMS_00673	08157	N	N	N	1	CUSTOMER ISSUE	-
DMS_00675	08158	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00677	08159	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00678	08160	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00679	08161	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00680	08162	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00681	08163	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00682	08164	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00683	08165	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00684	08166	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00685	08167	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00686	08168	N	N	N	1	CUSTOMER ISSUE	-
DMS_00687	08169	N	N	N	1	CUSTOMER ISSUE	-
DMS_00688	08170	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00689	08171	N	N	N	1	CUSTOMER ISSUE	-
DMS_00690	08172	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00691	08173	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00692	08174	N	N	N	1	CUSTOMER ISSUE	-
DMS_00693	08175	N	N	N	1	CUSTOMER ISSUE	-
DMS_00694	08176	N	N	N	1	CUSTOMER ISSUE	-
DMS_00695	08177	N	N	N	1	CUSTOMER ISSUE	-
DMS_00696	08178	N	N	N	1	CUSTOMER ISSUE	-
DMS_00697	08179	N	N	N	1	CUSTOMER ISSUE	-
DMS_00698	08180	N	N	N	1	CUSTOMER ISSUE	-
DMS_00701	08181	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00702	08182	N	N	N	1	CUSTOMER ISSUE	-
DMS_00703	08183	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00707	08184	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00708	08185	N	N	N	1	CUSTOMER ISSUE	-
DMS_00709	08186	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00710	08187	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00711	08188	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00712	08189	N	N	N	1	CUSTOMER ISSUE	-
DMS_00713	08190	N	N	N	1	CUSTOMER ISSUE	-
DMS_00715	08191	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00716	08192	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00717	08193	N	N	N	1	CUSTOMER ISSUE	-
DMS_00718	08194	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00719	08195	N	N	N	1	CUSTOMER ISSUE	-
DMS_00720	08196	N	N	N	1	CUSTOMER ISSUE	-
DMS_00721	08197	N	N	N	1	CUSTOMER ISSUE	-
DMS_00722	08198	N	N	N	1	CUSTOMER ISSUE	-
DMS_00723	08199	N	N	N	1	CUSTOMER ISSUE	-
DMS_00724	08200	N	N	N	1	CUSTOMER ISSUE	-
DMS_00725	08201	N	N	N	1	CUSTOMER ISSUE	-
DMS_00726	08202	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_00727	08203	N	N	N	1	CUSTOMER ISSUE	-
DMS_00728	08204	N	N	N	1	CUSTOMER ISSUE	-
DMS_00730	08205	N	N	N	1	CUSTOMER ISSUE	-
DMS_00732	08206	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00734	08207	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
DMS_00735	08208	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00736	08209	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_00738	08210	N	N	N	1	CUSTOMER ISSUE	-
DMS_00739	08211	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00740	08212	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00741	08213	N	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
DMS_00742	08214	N	N	N	1	CUSTOMER ISSUE	-
DMS_00743	08215	N	N	N	1	CUSTOMER ISSUE	-
DMS_00744	08216	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_00745	08217	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00747	08218	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00748	08219	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00749	08220	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00752	08221	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00753	08222	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00756	08223	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00757	08224	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00758	08225	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00759	08226	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00762	08227	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00765	08228	N	N	N	1	CUSTOMER ISSUE	-
DMS_00766	08229	N	N	N	1	CUSTOMER ISSUE	-
DMS_00767	08230	N	N	N	1	CUSTOMER ISSUE	-
DMS_00769	08231	N	N	N	1	CUSTOMER ISSUE	-
DMS_00770	08232	N	N	N	1	CUSTOMER ISSUE	-
DMS_00771	08233	N	N	N	1	CUSTOMER ISSUE	-
DMS_00772	08234	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00773	08235	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00774	08236	N	N	N	1	CUSTOMER ISSUE	-
DMS_00775	08237	N	N	N	1	CUSTOMER ISSUE	-
DMS_00776	08238	N	N	N	1	CUSTOMER ISSUE	-
DMS_00777	08239	N	N	N	1	CUSTOMER ISSUE	-
DMS_00778	08240	N	N	N	1	CUSTOMER ISSUE	-
DMS_00780	08241	N	N	N	1	CUSTOMER ISSUE	-
DMS_00781	08242	N	N	N	1	CUSTOMER ISSUE	-
DMS_00782	08243	N	N	N	1	CUSTOMER ISSUE	-
DMS_00783	08244	N	N	N	1	CUSTOMER ISSUE	-
DMS_00784	08245	N	N	N	1	CUSTOMER ISSUE	-
DMS_00785	08246	N	N	N	1	CUSTOMER ISSUE	-
DMS_00786	08247	N	N	N	1	CUSTOMER ISSUE	-
DMS_00788	08248	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00789	08249	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00790	08250	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00791	08251	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00793	08252	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00794	08253	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00795	08254	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00796	08255	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_00797	08256	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_00798	08257	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00799	08258	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00800	08259	N	N	N	1	CUSTOMER ISSUE	-
DMS_00801	08260	N	N	N	1	CUSTOMER ISSUE	-
DMS_00803	08261	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_00806	08262	N	N	N	1	CUSTOMER ISSUE	-
DMS_00809	08263	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00810	08264	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00811	08265	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00812	08266	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00813	08267	N	N	Y	1	TX - REPLACE	2500
DMS_00814	08268	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00815	08269	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00817	08270	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_00819	08271	N	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
DMS_00825	08272	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_00826	08273	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_00827	08274	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_00828	08275	N	N	N	1	CUSTOMER ISSUE	-
DMS_00831	08276	N	N	N	1	CUSTOMER ISSUE	-
DMS_00832	08277	N	N	N	1	CUSTOMER ISSUE	-
DMS_00833	08278	N	N	N	1	CUSTOMER ISSUE	-
DMS_00834	08279	N	N	N	1	CUSTOMER ISSUE	-
DMS_00835	08280	N	N	N	1	CUSTOMER ISSUE	-
DMS_00837	08281	N	N	N	1	CUSTOMER ISSUE	-
DMS_00838	08282	N	N	N	1	CUSTOMER ISSUE	-
DMS_00839	08283	N	N	N	1	CUSTOMER ISSUE	-
DMS_00840	08284	N	N	N	1	CUSTOMER ISSUE	-
DMS_00841	08285	N	N	N	1	CUSTOMER ISSUE	-
DMS_00843	08286	N	N	N	1	CUSTOMER ISSUE	-
DMS_00844	08287	N	N	N	1	CUSTOMER ISSUE	-
DMS_00845	08288	N	N	N	1	CUSTOMER ISSUE	-
DMS_00846	08289	N	N	N	1	CUSTOMER ISSUE	-
DMS_00847	08290	N	N	N	1	CUSTOMER ISSUE	-
DMS_00848	08291	N	N	N	1	CUSTOMER ISSUE	-
DMS_00850	08292	N	N	N	1	CUSTOMER ISSUE	-
DMS_00851	08293	N	N	N	1	CUSTOMER ISSUE	-
DMS_00852	08294	N	N	N	1	CUSTOMER ISSUE	-
DMS_00853	08295	N	N	N	1	CUSTOMER ISSUE	-
DMS_00854	08296	N	N	N	1	CUSTOMER ISSUE	-

DMS_00855	08297	N	N	N	1	CUSTOMER ISSUE	-
DMS_00856	08298	N	N	N	1	CUSTOMER ISSUE	-
DMS_00857	08299	N	N	N	1	CUSTOMER ISSUE	-
DMS_00858	08300	N	N	N	1	CUSTOMER ISSUE	-
DMS_00859	08301	N	N	N	1	CUSTOMER ISSUE	-
DMS_00860	08302	N	N	N	1	CUSTOMER ISSUE	-
DMS_00861	08303	N	N	N	1	CUSTOMER ISSUE	-
DMS_00862	08304	N	N	N	1	CUSTOMER ISSUE	-
DMS_00863	08305	N	N	N	1	CUSTOMER ISSUE	-
DMS_00864	08306	N	N	N	1	CUSTOMER ISSUE	-
DMS_00865	08307	N	N	N	1	CUSTOMER ISSUE	-
DMS_00866	08308	N	N	N	1	CUSTOMER ISSUE	-
DMS_00867	08309	N	N	N	1	CUSTOMER ISSUE	-
DMS_00872	08310	N	N	N	1	CUSTOMER ISSUE	-
DMS_00874	08311	N	N	N	1	CUSTOMER ISSUE	-
DMS_00876	08312	N	N	N	1	CUSTOMER ISSUE	-
DMS_00877	08313	N	N	N	1	CUSTOMER ISSUE	-
DMS_00878	08314	N	N	N	1	CUSTOMER ISSUE	-
DMS_00879	08315	N	N	N	1	CUSTOMER ISSUE	-
DMS_00880	08316	N	N	N	1	CUSTOMER ISSUE	-
DMS_00882	08317	N	N	N	1	CUSTOMER ISSUE	-
DMS_00886	08318	N	N	N	1	CUSTOMER ISSUE	-
DMS_00887	08319	N	N	N	1	CUSTOMER ISSUE	-
DMS_00888	08320	N	N	N	1	CUSTOMER ISSUE	-
DMS_00891	08321	N	N	N	1	CUSTOMER ISSUE	-
DMS_00892	08322	N	N	N	1	CUSTOMER ISSUE	-
DMS_00893	08323	N	N	N	1	CUSTOMER ISSUE	-
DMS_00894	08324	N	N	N	1	CUSTOMER ISSUE	-
DMS_00895	08325	N	N	N	1	CUSTOMER ISSUE	-
DMS_00896	08326	N	N	N	1	CUSTOMER ISSUE	-
DMS_00898	08327	N	N	N	1	CUSTOMER ISSUE	-
DMS_00899	08328	N	N	N	1	CUSTOMER ISSUE	-
DMS_00900	08329	N	N	N	1	CUSTOMER ISSUE	-
DMS_00902	08330	N	N	N	1	CUSTOMER ISSUE	-
DMS_00903	08331	N	N	N	1	CUSTOMER ISSUE	-
DMS_00904	08332	N	N	N	1	CUSTOMER ISSUE	-
DMS_00905	08333	N	N	N	1	CUSTOMER ISSUE	-
DMS_00906	08334	N	N	N	1	CUSTOMER ISSUE	-
DMS_00907	08335	N	N	N	1	CUSTOMER ISSUE	-
DMS_00908	08336	N	N	N	1	CUSTOMER ISSUE	-
DMS_00909	08337	N	N	N	1	CUSTOMER ISSUE	-
DMS_00910	08338	N	N	N	1	CUSTOMER ISSUE	-
DMS_00911	08339	N	N	N	1	CUSTOMER ISSUE	-
DMS_00912	08340	N	N	N	1	CUSTOMER ISSUE	-
DMS_00913	08341	N	N	N	1	CUSTOMER ISSUE	-
DMS_00914	08342	N	N	N	1	CUSTOMER ISSUE	-
DMS_00915	08343	N	N	N	1	CUSTOMER ISSUE	-
DMS_00916	08344	N	N	N	1	CUSTOMER ISSUE	-
DMS_00917	08345	N	N	N	1	CUSTOMER ISSUE	-
DMS_00918	08346	N	N	N	1	CUSTOMER ISSUE	-
DMS_00919	08347	N	N	N	1	CUSTOMER ISSUE	-
DMS_00920	08348	N	N	N	1	CUSTOMER ISSUE	-
DMS_00921	08349	N	N	N	1	CUSTOMER ISSUE	-
DMS_00923	08350	N	N	N	1	CUSTOMER ISSUE	-
DMS_00924	08351	N	N	N	1	CUSTOMER ISSUE	-
DMS_00925	08352	N	N	N	1	CUSTOMER ISSUE	-
DMS_00926	08353	N	N	N	1	CUSTOMER ISSUE	-
DMS_00927	08354	N	N	N	1	CUSTOMER ISSUE	-
DMS_00928	08355	N	N	N	1	CUSTOMER ISSUE	-
DMS_00929	08356	N	N	N	1	CUSTOMER ISSUE	-
DMS_00930	08357	N	N	N	1	CUSTOMER ISSUE	-
DMS_00931	08358	N	N	N	1	CUSTOMER ISSUE	-
DMS_00932	08359	N	N	N	1	CUSTOMER ISSUE	-
DMS_00933	08360	N	N	N	1	CUSTOMER ISSUE	-
DMS_00934	08361	N	N	N	1	CUSTOMER ISSUE	-
DMS_00935	08362	N	N	N	1	CUSTOMER ISSUE	-
DMS_00936	08363	N	N	N	1	CUSTOMER ISSUE	-
DMS_00938	08364	N	N	N	1	CUSTOMER ISSUE	-
DMS_00939	08365	N	N	N	1	CUSTOMER ISSUE	-
DMS_00940	08366	N	N	N	1	CUSTOMER ISSUE	-
DMS_00941	08367	N	N	N	1	CUSTOMER ISSUE	-
DMS_00942	08368	N	N	N	1	CUSTOMER ISSUE	-
DMS_00943	08369	N	N	N	1	CUSTOMER ISSUE	-
DMS_00944	08370	N	N	N	1	CUSTOMER ISSUE	-
DMS_00945	08371	N	N	N	1	CUSTOMER ISSUE	-
DMS_00947	08372	N	N	N	1	CUSTOMER ISSUE	-
DMS_00949	08373	N	N	N	1	CUSTOMER ISSUE	-
DMS_00950	08374	N	N	N	1	CUSTOMER ISSUE	-
DMS_00951	08375	N	N	N	1	CUSTOMER ISSUE	-
DMS_00952	08376	N	N	N	1	CUSTOMER ISSUE	-

DMS_00953	08377	N	N	N	1	CUSTOMER ISSUE	-
DMS_00954	08378	N	N	N	1	CUSTOMER ISSUE	-
DMS_00955	08379	N	N	N	1	CUSTOMER ISSUE	-
DMS_00956	08380	N	N	N	1	CUSTOMER ISSUE	-
DMS_00957	08381	N	N	N	1	CUSTOMER ISSUE	-
DMS_00958	08382	N	N	N	1	CUSTOMER ISSUE	-
DMS_00960	08383	N	N	N	1	CUSTOMER ISSUE	-
DMS_00962	08384	N	N	N	1	CUSTOMER ISSUE	-
DMS_00963	08385	N	N	N	1	CUSTOMER ISSUE	-
DMS_00965	08386	N	N	N	1	CUSTOMER ISSUE	-
DMS_00966	08387	N	N	N	1	CUSTOMER ISSUE	-
DMS_00967	08388	N	N	N	1	CUSTOMER ISSUE	-
DMS_00968	08389	N	N	N	1	CUSTOMER ISSUE	-
DMS_00969	08390	N	N	N	1	CUSTOMER ISSUE	-
DMS_00970	08391	N	N	N	1	CUSTOMER ISSUE	-
DMS_00973	08392	N	N	N	1	CUSTOMER ISSUE	-
DMS_00974	08393	N	N	N	1	CUSTOMER ISSUE	-
DMS_00975	08394	N	N	N	1	CUSTOMER ISSUE	-
DMS_00976	08395	N	N	N	1	CUSTOMER ISSUE	-
DMS_00977	08396	N	N	N	1	CUSTOMER ISSUE	-
DMS_00978	08397	N	N	N	1	CUSTOMER ISSUE	-
DMS_00979	08398	N	N	N	1	CUSTOMER ISSUE	-
DMS_00980	08399	N	N	N	1	CUSTOMER ISSUE	-
DMS_00981	08400	N	N	N	1	CUSTOMER ISSUE	-
DMS_00983	08401	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00984	08402	N	N	N	1	CUSTOMER ISSUE	-
DMS_00986	08403	N	N	N	1	CUSTOMER ISSUE	-
DMS_00987	08404	N	N	N	1	CUSTOMER ISSUE	-
DMS_00988	08405	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_00989	08406	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00990	08407	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00991	08408	N	N	N	1	CUSTOMER ISSUE	-
DMS_00992	08409	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00993	08410	N	N	N	1	CUSTOMER ISSUE	-
DMS_00994	08411	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_00996	08412	N	N	N	1	CUSTOMER ISSUE	-
DMS_00997	08413	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_00998	08414	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_01000	08415	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_01001	08416	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01004	08417	N	N	N	1	CUSTOMER ISSUE	-
DMS_01005	08418	N	N	N	1	CUSTOMER ISSUE	-
DMS_01007	08419	N	N	N	1	CUSTOMER ISSUE	-
DMS_01008	08420	N	N	N	1	CUSTOMER ISSUE	-
DMS_01009	08421	N	N	N	1	CUSTOMER ISSUE	-
DMS_01010	08422	N	N	N	1	CUSTOMER ISSUE	-
DMS_01011	08423	N	N	N	1	CUSTOMER ISSUE	-
DMS_01012	08424	N	N	N	1	CUSTOMER ISSUE	-
DMS_01013	08425	N	N	N	1	CUSTOMER ISSUE	-
DMS_01014	08426	N	N	N	1	CUSTOMER ISSUE	-
DMS_01015	08427	N	N	N	1	CUSTOMER ISSUE	-
DMS_01016	08428	N	N	N	1	CUSTOMER ISSUE	-
DMS_01017	08429	N	N	N	1	CUSTOMER ISSUE	-
DMS_01018	08430	N	N	N	1	CUSTOMER ISSUE	-
DMS_01019	08431	N	N	N	1	CUSTOMER ISSUE	-
DMS_01020	08432	N	N	N	1	CUSTOMER ISSUE	-
DMS_01028	08433	N	N	N	1	CUSTOMER ISSUE	-
DMS_01029	08434	N	N	N	1	CUSTOMER ISSUE	-
DMS_01030	08435	N	N	N	1	CUSTOMER ISSUE	-
DMS_01031	08436	N	N	N	1	CUSTOMER ISSUE	-
DMS_01032	08437	N	N	N	1	CUSTOMER ISSUE	-
DMS_01033	08438	N	N	N	1	CUSTOMER ISSUE	-
DMS_01034	08439	N	N	N	2	CUSTOMER ISSUE	-
DMS_01035	08440	N	N	N	1	CUSTOMER ISSUE	-
DMS_01036	08441	N	N	N	1	CUSTOMER ISSUE	-
DMS_01037	08442	N	N	N	1	CUSTOMER ISSUE	-
DMS_01038	08443	N	N	N	1	CUSTOMER ISSUE	-
DMS_01039	08444	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01040	08445	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_01041	08446	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01042	08447	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01044	08448	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01045	08449	N	N	N	1	CUSTOMER ISSUE	-
DMS_01046	08450	N	N	N	1	CUSTOMER ISSUE	-
DMS_01047	08451	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01048	08452	N	N	N	1	CUSTOMER ISSUE	-
DMS_01049	08453	N	N	N	1	CUSTOMER ISSUE	-
DMS_01050	08454	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01051	08455	N	N	N	1	CUSTOMER ISSUE	-
DMS_01053	08456	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_01054	08457	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01055	08458	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01057	08459	N	N	N	1	CUSTOMER ISSUE	-
DMS_01064	08460	N	N	N	1	CUSTOMER ISSUE	-
DMS_01065	08461	N	N	N	1	CUSTOMER ISSUE	-
DMS_01066	08462	N	N	N	1	CUSTOMER ISSUE	-
DMS_01067	08463	N	N	N	1	CUSTOMER ISSUE	-
DMS_01068	08464	N	N	N	1	CUSTOMER ISSUE	-
DMS_01069	08465	N	N	N	1	CUSTOMER ISSUE	-
DMS_01070	08466	N	N	N	1	CUSTOMER ISSUE	-
DMS_01071	08467	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01072	08468	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01073	08469	N	N	N	1	CUSTOMER ISSUE	-
DMS_01074	08470	N	N	N	1	CUSTOMER ISSUE	-
DMS_01075	08471	N	N	N	1	CUSTOMER ISSUE	-
DMS_01076	08472	N	N	N	2	CUSTOMER ISSUE	-
DMS_01079	08473	N	N	N	1	CUSTOMER ISSUE	-
DMS_01080	08474	N	N	N	1	CUSTOMER ISSUE	-
DMS_01081	08475	N	N	N	1	CUSTOMER ISSUE	-
DMS_01083	08476	N	N	N	1	CUSTOMER ISSUE	-
DMS_01084	08477	N	N	N	1	CUSTOMER ISSUE	-
DMS_01085	08478	N	N	N	1	CUSTOMER ISSUE	-
DMS_01086	08479	N	N	N	1	CUSTOMER ISSUE	-
DMS_01087	08480	N	N	N	1	CUSTOMER ISSUE	-
DMS_01088	08481	N	N	N	1	CUSTOMER ISSUE	-
DMS_01089	08482	N	N	N	1	CUSTOMER ISSUE	-
DMS_01090	08483	N	N	N	1	CUSTOMER ISSUE	-
DMS_01091	08484	N	N	N	1	CUSTOMER ISSUE	-
DMS_01092	08485	N	N	N	1	CUSTOMER ISSUE	-
DMS_01093	08486	N	N	N	1	CUSTOMER ISSUE	-
DMS_01094	08487	N	N	N	1	CUSTOMER ISSUE	-
DMS_01095	08488	N	N	N	1	CUSTOMER ISSUE	-
DMS_01096	08489	N	N	N	1	CUSTOMER ISSUE	-
DMS_01097	08490	N	N	N	1	CUSTOMER ISSUE	-
DMS_01099	08491	N	N	N	1	CUSTOMER ISSUE	-
DMS_01100	08492	N	N	N	1	CUSTOMER ISSUE	-
DMS_01101	08493	N	N	Y	4	SEC/SVC - REPAIR	472.5
DMS_01102	08494	N	N	N	1	CUSTOMER ISSUE	-
DMS_01103	08495	N	N	N	1	CUSTOMER ISSUE	-
DMS_01104	08496	N	N	N	1	CUSTOMER ISSUE	-
DMS_01105	08497	N	N	N	1	CUSTOMER ISSUE	-
DMS_01106	08498	N	N	N	1	CUSTOMER ISSUE	-
DMS_01109	08499	N	N	N	1	CUSTOMER ISSUE	-
DMS_01110	08500	N	N	N	1	CUSTOMER ISSUE	-
DMS_01111	08501	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01112	08502	N	N	N	1	CUSTOMER ISSUE	-
DMS_01114	08503	N	N	N	1	CUSTOMER ISSUE	-
DMS_01115	08504	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01116	08505	N	N	N	1	CUSTOMER ISSUE	-
DMS_01117	08506	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01118	08507	N	N	N	1	CUSTOMER ISSUE	-
DMS_01119	08508	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01120	08509	N	N	N	1	CUSTOMER ISSUE	-
DMS_01122	08510	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_01123	08511	N	N	N	1	CUSTOMER ISSUE	-
DMS_01124	08512	N	N	N	1	CUSTOMER ISSUE	-
DMS_01126	08513	N	N	N	1	CUSTOMER ISSUE	-
DMS_01127	08514	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01128	08515	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01130	08516	N	N	N	1	CUSTOMER ISSUE	-
DMS_01131	08517	N	N	N	1	CUSTOMER ISSUE	-
DMS_01132	08518	N	N	N	1	CUSTOMER ISSUE	-
DMS_01133	08519	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01135	08520	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01136	08521	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01137	08522	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01139	08523	N	N	N	1	CUSTOMER ISSUE	-
DMS_01142	08524	N	N	N	1	CUSTOMER ISSUE	-
DMS_01143	08525	N	N	N	1	CUSTOMER ISSUE	-
DMS_01144	08526	N	N	N	1	CUSTOMER ISSUE	-
DMS_01145	08527	N	N	N	1	CUSTOMER ISSUE	-
DMS_01146	08528	N	N	N	1	CUSTOMER ISSUE	-
DMS_01147	08529	N	N	N	1	CUSTOMER ISSUE	-
DMS_01148	08530	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01149	08531	N	N	N	1	CUSTOMER ISSUE	-
DMS_01151	08532	N	N	N	1	CUSTOMER ISSUE	-
DMS_01152	08533	N	N	N	1	CUSTOMER ISSUE	-
DMS_01153	08534	N	N	N	1	CUSTOMER ISSUE	-
DMS_01154	08535	N	N	N	1	CUSTOMER ISSUE	-
DMS_01157	08536	N	N	N	1	CUSTOMER ISSUE	-

DMS_01158	08537	N	N	N	2	CUSTOMER ISSUE	-
DMS_01159	08538	N	N	N	1	CUSTOMER ISSUE	-
DMS_01160	08539	N	N	N	1	CUSTOMER ISSUE	-
DMS_01161	08540	N	N	N	1	CUSTOMER ISSUE	-
DMS_01162	08541	N	N	N	1	CUSTOMER ISSUE	-
DMS_01163	08542	N	N	N	1	CUSTOMER ISSUE	-
DMS_01164	08543	N	N	N	1	CUSTOMER ISSUE	-
DMS_01165	08544	N	N	N	1	CUSTOMER ISSUE	-
DMS_01166	08545	N	N	N	1	CUSTOMER ISSUE	-
DMS_01167	08546	N	N	N	1	CUSTOMER ISSUE	-
DMS_01168	08547	N	N	N	1	CUSTOMER ISSUE	-
DMS_01169	08548	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01170	08549	N	N	N	1	CUSTOMER ISSUE	-
DMS_01171	08550	N	N	N	1	CUSTOMER ISSUE	-
DMS_01172	08551	N	N	N	1	CUSTOMER ISSUE	-
DMS_01173	08552	N	N	N	1	CUSTOMER ISSUE	-
DMS_01174	08553	N	N	N	1	CUSTOMER ISSUE	-
DMS_01175	08554	N	N	N	1	CUSTOMER ISSUE	-
DMS_01176	08555	N	N	N	1	CUSTOMER ISSUE	-
DMS_01177	08556	N	N	N	1	CUSTOMER ISSUE	-
DMS_01178	08557	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
DMS_01179	08558	N	N	N	1	CUSTOMER ISSUE	-
DMS_01180	08559	N	N	N	1	CUSTOMER ISSUE	-
DMS_01181	08560	N	N	N	1	CUSTOMER ISSUE	-
DMS_01182	08561	N	N	N	1	CUSTOMER ISSUE	-
DMS_01183	08562	N	N	N	1	CUSTOMER ISSUE	-
DMS_01184	08563	N	N	N	1	CUSTOMER ISSUE	-
DMS_01185	08564	N	N	N	1	CUSTOMER ISSUE	-
DMS_01186	08565	N	N	N	1	CUSTOMER ISSUE	-
DMS_01187	08566	N	N	N	1	CUSTOMER ISSUE	-
DMS_01188	08567	N	N	N	1	CUSTOMER ISSUE	-
DMS_01189	08568	N	N	N	1	CUSTOMER ISSUE	-
DMS_01190	08569	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01191	08570	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01192	08571	N	N	N	1	CUSTOMER ISSUE	-
DMS_01193	08572	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_01194	08573	N	N	N	1	CUSTOMER ISSUE	-
DMS_01195	08574	N	N	N	1	CUSTOMER ISSUE	-
DMS_01196	08575	N	N	N	1	CUSTOMER ISSUE	-
DMS_01197	08576	N	N	N	1	CUSTOMER ISSUE	-
DMS_01198	08577	N	N	N	1	CUSTOMER ISSUE	-
DMS_01199	08578	N	N	N	1	CUSTOMER ISSUE	-
DMS_01200	08579	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01201	08580	N	N	N	1	CUSTOMER ISSUE	-
DMS_01202	08581	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01203	08582	N	N	N	1	CUSTOMER ISSUE	-
DMS_01204	08583	N	N	N	1	CUSTOMER ISSUE	-
DMS_01205	08584	N	N	N	1	CUSTOMER ISSUE	-
DMS_01206	08585	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_01207	08586	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_01208	08587	N	N	N	1	CUSTOMER ISSUE	-
DMS_01209	08588	N	N	N	1	CUSTOMER ISSUE	-
DMS_01210	08589	N	N	N	1	CUSTOMER ISSUE	-
DMS_01211	08590	N	N	N	1	CUSTOMER ISSUE	-
DMS_01212	08591	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_01213	08592	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_01214	08593	N	N	N	1	CUSTOMER ISSUE	-
DMS_01215	08594	N	N	N	1	CUSTOMER ISSUE	-
DMS_01216	08595	N	N	N	1	CUSTOMER ISSUE	-
DMS_01217	08596	N	N	N	1	CUSTOMER ISSUE	-
DMS_01218	08597	N	N	N	1	CUSTOMER ISSUE	-
DMS_01219	08598	N	N	N	1	CUSTOMER ISSUE	-
DMS_01220	08599	N	N	N	1	CUSTOMER ISSUE	-
DMS_01221	08600	N	N	N	1	CUSTOMER ISSUE	-
DMS_01222	08601	N	N	N	1	CUSTOMER ISSUE	-
DMS_01223	08602	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01224	08603	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_01225	08604	N	N	N	1	CUSTOMER ISSUE	-
DMS_01226	08605	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01227	08606	N	N	N	1	CUSTOMER ISSUE	-
DMS_01228	08607	N	N	N	1	CUSTOMER ISSUE	-
DMS_01229	08608	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01230	08609	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01231	08610	N	N	N	1	CUSTOMER ISSUE	-
DMS_01232	08611	N	N	N	1	CUSTOMER ISSUE	-
DMS_01233	08612	N	N	N	1	CUSTOMER ISSUE	-
DMS_01234	08613	N	N	N	1	CUSTOMER ISSUE	-
DMS_01235	08614	N	N	N	1	CUSTOMER ISSUE	-
DMS_01236	08615	N	N	N	1	CUSTOMER ISSUE	-
DMS_01237	08616	N	N	N	1	CUSTOMER ISSUE	-

DMS_01238	08617	N	N	N	1	CUSTOMER ISSUE	-
DMS_01239	08618	N	N	N	1	CUSTOMER ISSUE	-
DMS_01240	08619	N	N	N	1	CUSTOMER ISSUE	-
DMS_01241	08620	N	N	N	1	CUSTOMER ISSUE	-
DMS_01242	08621	N	N	N	1	CUSTOMER ISSUE	-
DMS_01243	08622	N	N	N	1	CUSTOMER ISSUE	-
DMS_01244	08623	N	N	N	1	CUSTOMER ISSUE	-
DMS_01245	08624	N	N	N	1	CUSTOMER ISSUE	-
DMS_01246	08625	N	N	N	1	CUSTOMER ISSUE	-
DMS_01248	08626	N	N	N	1	CUSTOMER ISSUE	-
DMS_01249	08627	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01250	08628	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01252	08629	N	N	N	1	CUSTOMER ISSUE	-
DMS_01253	08630	N	N	N	1	CUSTOMER ISSUE	-
DMS_01258	08631	N	N	N	2	CUSTOMER ISSUE	-
DMS_01263	08632	N	N	N	1	CUSTOMER ISSUE	-
DMS_01264	08633	N	N	N	1	CUSTOMER ISSUE	-
DMS_01265	08634	N	N	N	1	CUSTOMER ISSUE	-
DMS_01266	08635	N	N	N	1	CUSTOMER ISSUE	-
DMS_01267	08636	N	N	N	1	CUSTOMER ISSUE	-
DMS_01268	08637	N	N	N	1	CUSTOMER ISSUE	-
DMS_01269	08638	N	N	N	1	CUSTOMER ISSUE	-
DMS_01270	08639	N	N	N	1	CUSTOMER ISSUE	-
DMS_01271	08640	N	N	N	1	CUSTOMER ISSUE	-
DMS_01272	08641	N	N	N	1	CUSTOMER ISSUE	-
DMS_01273	08642	N	N	N	1	CUSTOMER ISSUE	-
DMS_01274	08643	N	N	N	1	CUSTOMER ISSUE	-
DMS_01275	08644	N	N	N	1	CUSTOMER ISSUE	-
DMS_01276	08645	N	N	N	1	CUSTOMER ISSUE	-
DMS_01277	08646	N	N	N	1	CUSTOMER ISSUE	-
DMS_01278	08647	N	N	N	1	CUSTOMER ISSUE	-
DMS_01279	08648	N	N	N	1	CUSTOMER ISSUE	-
DMS_01280	08649	N	N	N	1	CUSTOMER ISSUE	-
DMS_01282	08650	N	N	N	1	CUSTOMER ISSUE	-
DMS_01283	08651	N	N	N	1	CUSTOMER ISSUE	-
DMS_01284	08652	N	N	N	1	CUSTOMER ISSUE	-
DMS_01285	08653	N	N	N	1	CUSTOMER ISSUE	-
DMS_01286	08654	N	N	N	1	CUSTOMER ISSUE	-
DMS_01287	08655	N	N	N	1	CUSTOMER ISSUE	-
DMS_01288	08656	N	N	N	1	CUSTOMER ISSUE	-
DMS_01291	08657	N	N	N	1	CUSTOMER ISSUE	-
DMS_01292	08658	N	N	N	1	CUSTOMER ISSUE	-
DMS_01294	08659	N	N	N	1	CUSTOMER ISSUE	-
DMS_01295	08660	N	N	N	1	CUSTOMER ISSUE	-
DMS_01296	08661	N	N	N	1	CUSTOMER ISSUE	-
DMS_01298	08662	N	N	N	1	CUSTOMER ISSUE	-
DMS_01301	08663	N	N	N	1	CUSTOMER ISSUE	-
DMS_01303	08664	N	N	N	1	CUSTOMER ISSUE	-
DMS_01306	08665	N	N	N	1	CUSTOMER ISSUE	-
DMS_01309	08666	N	N	N	1	CUSTOMER ISSUE	-
DMS_01310	08667	N	N	N	1	CUSTOMER ISSUE	-
DMS_01311	08668	N	N	N	1	CUSTOMER ISSUE	-
DMS_01312	08669	N	N	N	1	CUSTOMER ISSUE	-
DMS_01313	08670	N	N	N	1	CUSTOMER ISSUE	-
DMS_01315	08671	N	N	N	1	CUSTOMER ISSUE	-
DMS_01317	08672	N	N	N	1	CUSTOMER ISSUE	-
DMS_01321	08673	N	N	N	1	CUSTOMER ISSUE	-
DMS_01324	08674	N	N	N	1	CUSTOMER ISSUE	-
DMS_01325	08675	N	N	N	1	CUSTOMER ISSUE	-
DMS_01327	08676	N	N	N	1	CUSTOMER ISSUE	-
DMS_01328	08677	N	N	N	1	CUSTOMER ISSUE	-
DMS_01330	08678	N	N	N	1	CUSTOMER ISSUE	-
DMS_01333	08679	N	N	N	1	CUSTOMER ISSUE	-
DMS_01334	08680	N	N	N	1	CUSTOMER ISSUE	-
DMS_01335	08681	N	N	N	1	CUSTOMER ISSUE	-
DMS_01336	08682	N	N	N	1	CUSTOMER ISSUE	-
DMS_01337	08683	N	N	N	1	CUSTOMER ISSUE	-
DMS_01338	08684	N	N	N	1	CUSTOMER ISSUE	-
DMS_01339	08685	N	N	N	1	CUSTOMER ISSUE	-
DMS_01340	08686	N	N	N	1	CUSTOMER ISSUE	-
DMS_01341	08687	N	N	N	1	CUSTOMER ISSUE	-
DMS_01342	08688	N	N	N	1	CUSTOMER ISSUE	-
DMS_01343	08689	N	N	N	1	CUSTOMER ISSUE	-
DMS_01344	08690	N	N	N	1	CUSTOMER ISSUE	-
DMS_01345	08691	N	N	N	1	CUSTOMER ISSUE	-
DMS_01346	08692	N	N	N	1	CUSTOMER ISSUE	-
DMS_01347	08693	N	N	N	1	CUSTOMER ISSUE	-
DMS_01348	08694	N	N	N	1	CUSTOMER ISSUE	-
DMS_01349	08695	N	N	N	1	CUSTOMER ISSUE	-
DMS_01350	08696	N	N	N	1	CUSTOMER ISSUE	-

DMS_01351	08697	N	N	N	1	CUSTOMER ISSUE	-
DMS_01352	08698	N	N	N	1	CUSTOMER ISSUE	-
DMS_01353	08699	N	N	N	1	CUSTOMER ISSUE	-
DMS_01354	08700	N	N	N	1	CUSTOMER ISSUE	-
DMS_01355	08701	N	N	N	1	CUSTOMER ISSUE	-
DMS_01356	08702	N	N	N	1	CUSTOMER ISSUE	-
DMS_01357	08703	N	N	N	1	CUSTOMER ISSUE	-
DMS_01358	08704	N	N	N	1	CUSTOMER ISSUE	-
DMS_01359	08705	N	N	N	1	CUSTOMER ISSUE	-
DMS_01360	08706	N	N	N	1	CUSTOMER ISSUE	-
DMS_01361	08707	N	N	N	1	CUSTOMER ISSUE	-
DMS_01362	08708	N	N	N	1	CUSTOMER ISSUE	-
DMS_01363	08709	N	N	N	1	CUSTOMER ISSUE	-
DMS_01364	08710	N	N	N	1	CUSTOMER ISSUE	-
DMS_01365	08711	N	N	N	1	CUSTOMER ISSUE	-
DMS_01366	08712	N	N	N	1	CUSTOMER ISSUE	-
DMS_01367	08713	N	N	N	1	CUSTOMER ISSUE	-
DMS_01368	08714	N	N	N	1	CUSTOMER ISSUE	-
DMS_01369	08715	N	N	N	1	CUSTOMER ISSUE	-
DMS_01370	08716	N	N	N	1	CUSTOMER ISSUE	-
DMS_01371	08717	N	N	N	1	CUSTOMER ISSUE	-
DMS_01372	08718	N	N	N	1	CUSTOMER ISSUE	-
DMS_01373	08719	N	N	N	1	CUSTOMER ISSUE	-
DMS_01374	08720	N	N	N	1	CUSTOMER ISSUE	-
DMS_01375	08721	N	N	N	1	CUSTOMER ISSUE	-
DMS_01376	08722	N	N	N	1	CUSTOMER ISSUE	-
DMS_01377	08723	N	N	N	1	CUSTOMER ISSUE	-
DMS_01378	08724	N	N	N	1	CUSTOMER ISSUE	-
DMS_01379	08725	N	N	N	1	CUSTOMER ISSUE	-
DMS_01380	08726	N	N	N	1	CUSTOMER ISSUE	-
DMS_01381	08727	N	N	N	1	CUSTOMER ISSUE	-
DMS_01382	08728	N	N	N	1	CUSTOMER ISSUE	-
DMS_01383	08729	N	N	N	1	CUSTOMER ISSUE	-
DMS_01384	08730	N	N	N	1	CUSTOMER ISSUE	-
DMS_01386	08731	N	N	N	1	CUSTOMER ISSUE	-
DMS_01387	08732	N	N	N	1	CUSTOMER ISSUE	-
DMS_01388	08733	N	N	N	1	CUSTOMER ISSUE	-
DMS_01389	08734	N	N	N	1	CUSTOMER ISSUE	-
DMS_01391	08735	N	N	N	1	CUSTOMER ISSUE	-
DMS_01392	08736	N	N	N	1	CUSTOMER ISSUE	-
DMS_01393	08737	N	N	N	1	CUSTOMER ISSUE	-
DMS_01394	08738	N	N	N	1	CUSTOMER ISSUE	-
DMS_01395	08739	N	N	N	1	CUSTOMER ISSUE	-
DMS_01396	08740	N	N	N	1	CUSTOMER ISSUE	-
DMS_01397	08741	N	N	N	1	CUSTOMER ISSUE	-
DMS_01398	08742	N	N	N	1	CUSTOMER ISSUE	-
DMS_01399	08743	N	N	N	1	CUSTOMER ISSUE	-
DMS_01400	08744	N	N	N	1	CUSTOMER ISSUE	-
DMS_01401	08745	N	N	N	1	CUSTOMER ISSUE	-
DMS_01402	08746	N	N	N	1	CUSTOMER ISSUE	-
DMS_01403	08747	N	N	N	1	CUSTOMER ISSUE	-
DMS_01404	08748	N	N	N	1	CUSTOMER ISSUE	-
DMS_01405	08749	N	N	N	1	CUSTOMER ISSUE	-
DMS_01406	08750	N	N	N	1	CUSTOMER ISSUE	-
DMS_01407	08751	N	N	N	1	CUSTOMER ISSUE	-
DMS_01408	08752	N	N	N	1	CUSTOMER ISSUE	-
DMS_01409	08753	N	N	N	1	CUSTOMER ISSUE	-
DMS_01410	08754	N	N	N	1	CUSTOMER ISSUE	-
DMS_01411	08755	N	N	N	1	CUSTOMER ISSUE	-
DMS_01412	08756	N	N	N	1	CUSTOMER ISSUE	-
DMS_01413	08757	N	N	N	1	CUSTOMER ISSUE	-
DMS_01414	08758	N	N	N	1	CUSTOMER ISSUE	-
DMS_01415	08759	N	N	N	1	CUSTOMER ISSUE	-
DMS_01416	08760	N	N	N	1	CUSTOMER ISSUE	-
DMS_01417	08761	N	N	N	1	CUSTOMER ISSUE	-
DMS_01418	08762	N	N	N	1	CUSTOMER ISSUE	-
DMS_01422	08763	N	N	N	1	CUSTOMER ISSUE	-
DMS_01425	08764	N	N	N	1	CUSTOMER ISSUE	-
DMS_01428	08765	N	N	N	1	CUSTOMER ISSUE	-
DMS_01429	08766	N	N	N	1	CUSTOMER ISSUE	-
DMS_01435	08767	N	N	N	1	CUSTOMER ISSUE	-
DMS_01436	08768	N	N	N	1	CUSTOMER ISSUE	-
DMS_01437	08769	N	N	N	1	CUSTOMER ISSUE	-
DMS_01438	08770	N	N	N	1	CUSTOMER ISSUE	-
DMS_01439	08771	N	N	N	1	CUSTOMER ISSUE	-
DMS_01440	08772	N	N	N	1	CUSTOMER ISSUE	-
DMS_01441	08773	N	N	N	1	CUSTOMER ISSUE	-
DMS_01442	08774	N	N	N	1	CUSTOMER ISSUE	-
DMS_01443	08775	N	N	N	1	CUSTOMER ISSUE	-
DMS_01444	08776	N	N	N	1	CUSTOMER ISSUE	-

DMS_01445	08777	N	N	N	1	CUSTOMER ISSUE	-
DMS_01446	08778	N	N	N	1	CUSTOMER ISSUE	-
DMS_01447	08779	N	N	N	1	CUSTOMER ISSUE	-
DMS_01448	08780	N	N	N	1	CUSTOMER ISSUE	-
DMS_01465	08781	N	N	N	1	CUSTOMER ISSUE	-
DMS_01471	08782	N	N	N	1	CUSTOMER ISSUE	-
DMS_01478	08783	N	N	N	1	CUSTOMER ISSUE	-
DMS_01479	08784	N	N	N	1	CUSTOMER ISSUE	-
DMS_01498	08785	N	N	N	1	CUSTOMER ISSUE	-
DMS_01499	08786	N	N	N	1	CUSTOMER ISSUE	-
DMS_01500	08787	N	N	N	1	CUSTOMER ISSUE	-
DMS_01501	08788	N	N	N	1	CUSTOMER ISSUE	-
DMS_01502	08789	N	N	N	1	CUSTOMER ISSUE	-
DMS_01503	08790	N	N	N	1	CUSTOMER ISSUE	-
DMS_01504	08791	N	N	N	1	CUSTOMER ISSUE	-
DMS_01507	08792	N	N	N	1	CUSTOMER ISSUE	-
DMS_01508	08793	N	N	N	1	CUSTOMER ISSUE	-
DMS_01509	08794	N	N	N	1	CUSTOMER ISSUE	-
DMS_01510	08795	N	N	N	1	CUSTOMER ISSUE	-
DMS_01511	08796	N	N	N	1	CUSTOMER ISSUE	-
DMS_01512	08797	N	N	N	1	CUSTOMER ISSUE	-
DMS_01513	08798	N	N	N	1	CUSTOMER ISSUE	-
DMS_01514	08799	N	N	N	1	CUSTOMER ISSUE	-
DMS_01515	08800	N	N	N	1	CUSTOMER ISSUE	-
DMS_01516	08801	N	N	N	1	CUSTOMER ISSUE	-
DMS_01517	08802	N	N	N	1	CUSTOMER ISSUE	-
DMS_01518	08803	N	N	N	1	CUSTOMER ISSUE	-
DMS_01519	08804	N	N	N	1	CUSTOMER ISSUE	-
DMS_01520	08805	N	N	N	1	CUSTOMER ISSUE	-
DMS_01521	08806	N	N	N	1	CUSTOMER ISSUE	-
DMS_01522	08807	N	N	N	1	CUSTOMER ISSUE	-
DMS_01523	08808	N	N	N	1	CUSTOMER ISSUE	-
DMS_01524	08809	N	N	N	1	CUSTOMER ISSUE	-
DMS_01525	08810	N	N	N	1	CUSTOMER ISSUE	-
DMS_01526	08811	N	N	N	1	CUSTOMER ISSUE	-
DMS_01527	08812	N	N	N	1	CUSTOMER ISSUE	-
DMS_01528	08813	N	N	N	1	CUSTOMER ISSUE	-
DMS_01529	08814	N	N	N	1	CUSTOMER ISSUE	-
DMS_01530	08815	N	N	N	1	CUSTOMER ISSUE	-
DMS_01531	08816	N	N	N	1	CUSTOMER ISSUE	-
DMS_01532	08817	N	N	N	1	CUSTOMER ISSUE	-
DMS_01533	08818	N	N	N	1	CUSTOMER ISSUE	-
DMS_01534	08819	N	N	N	1	CUSTOMER ISSUE	-
DMS_01535	08820	N	N	N	1	CUSTOMER ISSUE	-
DMS_01536	08821	N	N	N	1	CUSTOMER ISSUE	-
DMS_01537	08822	N	N	N	1	CUSTOMER ISSUE	-
DMS_01538	08823	N	N	N	1	CUSTOMER ISSUE	-
DMS_01539	08824	N	N	N	1	CUSTOMER ISSUE	-
DMS_01540	08825	N	N	N	1	CUSTOMER ISSUE	-
DMS_01541	08826	N	N	N	1	CUSTOMER ISSUE	-
DMS_01542	08827	N	N	N	1	CUSTOMER ISSUE	-
DMS_01543	08828	N	N	N	1	CUSTOMER ISSUE	-
DMS_01544	08829	N	N	N	1	CUSTOMER ISSUE	-
DMS_01545	08830	N	N	N	1	CUSTOMER ISSUE	-
DMS_01546	08831	N	N	N	1	CUSTOMER ISSUE	-
DMS_01547	08832	N	N	N	1	CUSTOMER ISSUE	-
DMS_01548	08833	N	N	N	1	CUSTOMER ISSUE	-
DMS_01549	08834	N	N	N	1	CUSTOMER ISSUE	-
DMS_01550	08835	N	N	N	1	CUSTOMER ISSUE	-
DMS_01551	08836	N	N	N	1	CUSTOMER ISSUE	-
DMS_01552	08837	N	N	N	1	CUSTOMER ISSUE	-
DMS_01553	08838	N	N	N	1	CUSTOMER ISSUE	-
DMS_01554	08839	N	N	N	1	CUSTOMER ISSUE	-
DMS_01555	08840	N	N	N	1	CUSTOMER ISSUE	-
DMS_01565	08841	N	N	N	1	CUSTOMER ISSUE	-
DMS_01566	08842	N	N	N	1	CUSTOMER ISSUE	-
DMS_01570	08843	N	N	N	1	CUSTOMER ISSUE	-
DMS_01571	08844	N	N	N	1	CUSTOMER ISSUE	-
DMS_01572	08845	N	N	N	1	CUSTOMER ISSUE	-
DMS_01573	08846	N	N	N	1	CUSTOMER ISSUE	-
DMS_01574	08847	N	N	N	1	CUSTOMER ISSUE	-
DMS_01575	08848	N	N	N	1	CUSTOMER ISSUE	-
DMS_01576	08849	N	N	N	1	CUSTOMER ISSUE	-
DMS_01577	08850	N	N	N	1	CUSTOMER ISSUE	-
DMS_01578	08851	N	N	N	1	CUSTOMER ISSUE	-
DMS_01579	08852	N	N	N	1	CUSTOMER ISSUE	-
DMS_01586	08853	N	N	N	1	CUSTOMER ISSUE	-
DMS_01587	08854	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_01588	08855	N	N	N	1	CUSTOMER ISSUE	-
DMS_01589	08856	N	N	N	1	CUSTOMER ISSUE	-

DMS_01590	08857	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_01591	08858	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01592	08859	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01594	08860	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01595	08861	N	N	N	1	CUSTOMER ISSUE	-
DMS_01596	08862	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01597	08863	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_01598	08864	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01599	08865	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01600	08866	N	N	N	1	CUSTOMER ISSUE	-
DMS_01601	08867	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01602	08868	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01603	08869	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01604	08870	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01605	08871	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01607	08872	N	N	N	1	CUSTOMER ISSUE	-
DMS_01608	08873	N	N	N	1	CUSTOMER ISSUE	-
DMS_01610	08874	N	N	N	1	CUSTOMER ISSUE	-
DMS_01611	08875	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01612	08876	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01613	08877	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01614	08878	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01615	08879	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01616	08880	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01617	08881	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01618	08882	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01637	08883	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01641	08884	N	N	N	1	CUSTOMER ISSUE	-
DMS_01652	08885	N	N	N	1	CUSTOMER ISSUE	-
DMS_01653	08886	N	N	Y	4	SEC/SVC - REPLACE	708.75
DMS_01655	08887	N	N	N	2	CUSTOMER ISSUE	-
DMS_01656	08888	N	N	N	1	CUSTOMER ISSUE	-
DMS_01657	08889	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01658	08890	N	N	N	1	CUSTOMER ISSUE	-
DMS_01660	08891	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01663	08892	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01664	08893	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01669	08894	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01674	08895	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01677	08896	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01678	08897	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01679	08898	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01680	08899	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01681	08900	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01682	08901	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01683	08902	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01684	08903	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01685	08904	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01686	08905	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01687	08906	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01688	08907	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01689	08908	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01690	08909	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01691	08910	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01692	08911	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01693	08912	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01694	08913	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01695	08914	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01696	08915	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01697	08916	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01698	08917	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01699	08918	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01700	08919	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01701	08920	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01702	08921	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01703	08922	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01704	08923	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01705	08924	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01706	08925	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01707	08926	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01708	08927	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01709	08928	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01710	08929	N	N	Y	1	TX - REPLACE	2500
DMS_01711	08930	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01712	08931	N	N	Y	1	TX - REPLACE	2500
DMS_01713	08932	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01714	08933	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01715	08934	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01716	08935	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01717	08936	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_01718	08937	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01719	08938	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01720	08939	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01722	08940	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01723	08941	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01724	08942	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01725	08943	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01726	08944	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01727	08945	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_01728	08946	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01729	08947	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_01731	08948	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_01732	08949	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01734	08950	N	N	N	1	CUSTOMER ISSUE	-
DMS_01741	08951	N	N	N	1	CUSTOMER ISSUE	-
DMS_01743	08952	N	N	N	1	CUSTOMER ISSUE	-
DMS_01744	08953	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_01746	08954	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_01747	08955	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01748	08956	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01749	08957	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01751	08958	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01752	08959	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_01753	08960	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01754	08961	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01757	08962	N	N	N	1	CUSTOMER ISSUE	-
DMS_01759	08963	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01762	08964	N	N	N	1	CUSTOMER ISSUE	-
DMS_01767	08965	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01768	08966	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01769	08967	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01771	08968	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01772	08969	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01775	08970	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01776	08971	N	N	N	1	CUSTOMER ISSUE	-
DMS_01777	08972	N	N	N	1	CUSTOMER ISSUE	-
DMS_01778	08973	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01779	08974	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01780	08975	N	N	N	1	CUSTOMER ISSUE	-
DMS_01781	08976	N	N	N	1	CUSTOMER ISSUE	-
DMS_01782	08977	N	N	N	1	CUSTOMER ISSUE	-
DMS_01783	08978	N	N	N	1	CUSTOMER ISSUE	-
DMS_01784	08979	N	N	N	1	CUSTOMER ISSUE	-
DMS_01785	08980	N	N	N	1	CUSTOMER ISSUE	-
DMS_01786	08981	N	N	N	1	CUSTOMER ISSUE	-
DMS_01787	08982	N	N	N	1	CUSTOMER ISSUE	-
DMS_01788	08983	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01789	08984	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01790	08985	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01791	08986	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01792	08987	N	N	Y	1	TX - REPLACE	2500
DMS_01793	08988	N	N	Y	1	TX - REPLACE	2500
DMS_01794	08989	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_01795	08990	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01797	08991	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01798	08992	N	N	N	1	CUSTOMER ISSUE	-
DMS_01799	08993	N	N	N	1	CUSTOMER ISSUE	-
DMS_01800	08994	N	N	N	1	CUSTOMER ISSUE	-
DMS_01801	08995	N	N	N	1	CUSTOMER ISSUE	-
DMS_01802	08996	N	N	N	1	CUSTOMER ISSUE	-
DMS_01803	08997	N	N	N	1	CUSTOMER ISSUE	-
DMS_01804	08998	N	N	N	1	CUSTOMER ISSUE	-
DMS_01806	08999	N	N	N	1	CUSTOMER ISSUE	-
DMS_01807	09000	N	N	N	1	CUSTOMER ISSUE	-
DMS_01808	09001	N	N	N	1	CUSTOMER ISSUE	-
DMS_01809	09002	N	N	N	1	CUSTOMER ISSUE	-
DMS_01810	09003	N	N	N	1	CUSTOMER ISSUE	-
DMS_01811	09004	N	N	N	1	CUSTOMER ISSUE	-
DMS_01812	09005	N	N	N	1	CUSTOMER ISSUE	-
DMS_01813	09006	N	N	N	1	CUSTOMER ISSUE	-
DMS_01814	09007	N	N	N	1	CUSTOMER ISSUE	-
DMS_01815	09008	N	N	N	1	CUSTOMER ISSUE	-
DMS_01816	09009	N	N	N	1	CUSTOMER ISSUE	-
DMS_01817	09010	N	N	N	1	CUSTOMER ISSUE	-
DMS_01818	09011	N	N	N	1	CUSTOMER ISSUE	-
DMS_01819	09012	N	N	N	1	CUSTOMER ISSUE	-
DMS_01820	09013	N	N	N	1	CUSTOMER ISSUE	-
DMS_01821	09014	N	N	N	1	CUSTOMER ISSUE	-
DMS_01822	09015	N	N	N	1	CUSTOMER ISSUE	-
DMS_01823	09016	N	N	N	1	CUSTOMER ISSUE	-

DMS_01824	09017	N	N	N	1	CUSTOMER ISSUE	-
DMS_01825	09018	N	N	N	1	CUSTOMER ISSUE	-
DMS_01826	09019	N	N	N	1	CUSTOMER ISSUE	-
DMS_01827	09020	N	N	N	1	CUSTOMER ISSUE	-
DMS_01828	09021	N	N	N	1	CUSTOMER ISSUE	-
DMS_01829	09022	N	N	N	1	CUSTOMER ISSUE	-
DMS_01830	09023	N	N	N	1	CUSTOMER ISSUE	-
DMS_01831	09024	N	N	N	1	CUSTOMER ISSUE	-
DMS_01832	09025	N	N	N	1	CUSTOMER ISSUE	-
DMS_01833	09026	N	N	N	1	CUSTOMER ISSUE	-
DMS_01834	09027	N	N	N	1	CUSTOMER ISSUE	-
DMS_01835	09028	N	N	N	1	CUSTOMER ISSUE	-
DMS_01836	09029	N	N	N	1	CUSTOMER ISSUE	-
DMS_01837	09030	N	N	N	1	CUSTOMER ISSUE	-
DMS_01838	09031	N	N	N	1	CUSTOMER ISSUE	-
DMS_01839	09032	N	N	N	1	CUSTOMER ISSUE	-
DMS_01840	09033	N	N	N	1	CUSTOMER ISSUE	-
DMS_01841	09034	N	N	N	1	CUSTOMER ISSUE	-
DMS_01843	09035	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01844	09036	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01845	09037	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01846	09038	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01847	09039	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01848	09040	N	N	N	1	CUSTOMER ISSUE	-
DMS_01849	09041	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01850	09042	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01851	09043	N	N	N	1	CUSTOMER ISSUE	-
DMS_01852	09044	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01853	09045	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01854	09046	N	N	N	1	CUSTOMER ISSUE	-
DMS_01855	09047	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01856	09048	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01857	09049	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01858	09050	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01859	09051	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01860	09052	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01861	09053	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01862	09054	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01863	09055	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01864	09056	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01865	09057	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01866	09058	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_01867	09059	N	N	N	1	CUSTOMER ISSUE	-
DMS_01868	09060	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01869	09061	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01870	09062	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01871	09063	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01872	09064	N	N	N	1	CUSTOMER ISSUE	-
DMS_01873	09065	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01874	09066	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01875	09067	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01876	09068	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01877	09069	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01878	09070	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01879	09071	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01880	09072	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01881	09073	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01882	09074	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01883	09075	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01884	09076	N	N	Y	1	SUB/TRANS - REPAIR	5000
DMS_01885	09077	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01886	09078	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01887	09079	N	N	Y	1	SUB/TRANS - REPAIR	5000
DMS_01888	09080	N	N	Y	1	SUB/TRANS - REPAIR	5000
DMS_01889	09081	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01890	09082	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01891	09083	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01892	09084	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01893	09085	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01894	09086	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01895	09087	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01896	09088	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01897	09089	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01898	09090	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01899	09091	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01900	09092	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01901	09093	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01902	09094	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01903	09095	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01904	09096	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_01905	09097	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01906	09098	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01907	09099	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01908	09100	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01909	09101	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01910	09102	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01911	09103	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01912	09104	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01913	09105	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01914	09106	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01915	09107	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01916	09108	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01917	09109	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01918	09110	N	N	N	1	CUSTOMER ISSUE	-
DMS_01919	09111	N	N	N	1	CUSTOMER ISSUE	-
DMS_01920	09112	N	N	N	1	CUSTOMER ISSUE	-
DMS_01921	09113	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01922	09114	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01923	09115	N	N	N	1	CUSTOMER ISSUE	-
DMS_01924	09116	N	N	N	1	CUSTOMER ISSUE	-
DMS_01925	09117	N	N	N	1	CUSTOMER ISSUE	-
DMS_01926	09118	N	N	N	1	CUSTOMER ISSUE	-
DMS_01927	09119	N	N	N	1	CUSTOMER ISSUE	-
DMS_01928	09120	N	N	N	1	CUSTOMER ISSUE	-
DMS_01929	09121	N	N	N	1	CUSTOMER ISSUE	-
DMS_01930	09122	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01931	09123	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01932	09124	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01933	09125	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01934	09126	N	N	N	1	CUSTOMER ISSUE	-
DMS_01935	09127	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01936	09128	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01937	09129	N	N	N	1	CUSTOMER ISSUE	-
DMS_01938	09130	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01939	09131	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01940	09132	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01941	09133	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01942	09134	N	N	N	1	CUSTOMER ISSUE	-
DMS_01943	09135	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01944	09136	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01945	09137	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01946	09138	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01947	09139	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01948	09140	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01949	09141	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01950	09142	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01951	09143	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01952	09144	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01953	09145	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01954	09146	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01955	09147	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01956	09148	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01957	09149	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01958	09150	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01959	09151	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01960	09152	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01961	09153	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_01962	09154	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01963	09155	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01964	09156	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01965	09157	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01966	09158	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01967	09159	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01968	09160	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01969	09161	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01970	09162	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01971	09163	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01972	09164	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01973	09165	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01974	09166	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01975	09167	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01976	09168	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01977	09169	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01978	09170	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01979	09171	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01980	09172	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01981	09173	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01982	09174	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01983	09175	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01984	09176	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_01985	09177	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01986	09178	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01987	09179	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01988	09180	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01989	09181	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01990	09182	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01992	09183	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01993	09184	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01994	09185	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01995	09186	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01996	09187	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01997	09188	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01998	09189	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_01999	09190	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02000	09191	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02001	09192	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02002	09193	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02003	09194	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02004	09195	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02005	09196	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02006	09197	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02007	09198	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02008	09199	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02009	09200	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02010	09201	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02011	09202	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02012	09203	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02013	09204	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02014	09205	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02015	09206	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02016	09207	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02017	09208	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02018	09209	N	N	N	1	CUSTOMER ISSUE	-
DMS_02019	09210	N	N	N	1	CUSTOMER ISSUE	-
DMS_02020	09211	N	N	N	1	CUSTOMER ISSUE	-
DMS_02021	09212	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02022	09213	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02023	09214	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02024	09215	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02025	09216	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02026	09217	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02027	09218	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02028	09219	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02029	09220	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02030	09221	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02031	09222	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02032	09223	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02033	09224	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02034	09225	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02035	09226	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02036	09227	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02037	09228	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02038	09229	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02039	09230	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02040	09231	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02041	09232	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02042	09233	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02043	09234	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02044	09235	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02045	09236	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02046	09237	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02047	09238	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02048	09239	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02049	09240	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02050	09241	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02051	09242	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02052	09243	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02053	09244	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02054	09245	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02055	09246	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02056	09247	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02057	09248	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02058	09249	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02059	09250	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02060	09251	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02061	09252	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02062	09253	N	N	N	1	CUSTOMER ISSUE	-
DMS_02063	09254	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02064	09255	N	N	N	1	CUSTOMER ISSUE	-
DMS_02065	09256	N	N	N	1	CUSTOMER ISSUE	-

DMS_02066	09257	N	N	N	1	CUSTOMER ISSUE	-
DMS_02067	09258	N	N	N	1	CUSTOMER ISSUE	-
DMS_02068	09259	N	N	N	1	CUSTOMER ISSUE	-
DMS_02069	09260	N	N	N	1	CUSTOMER ISSUE	-
DMS_02070	09261	N	N	N	1	CUSTOMER ISSUE	-
DMS_02071	09262	N	N	N	1	CUSTOMER ISSUE	-
DMS_02072	09263	N	N	N	1	CUSTOMER ISSUE	-
DMS_02073	09264	N	N	N	1	CUSTOMER ISSUE	-
DMS_02074	09265	N	N	N	1	CUSTOMER ISSUE	-
DMS_02075	09266	N	N	N	1	CUSTOMER ISSUE	-
DMS_02076	09267	N	N	N	1	CUSTOMER ISSUE	-
DMS_02077	09268	N	N	N	1	CUSTOMER ISSUE	-
DMS_02078	09269	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02079	09270	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02080	09271	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02081	09272	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02082	09273	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02083	09274	N	N	N	1	CUSTOMER ISSUE	-
DMS_02084	09275	N	N	N	1	CUSTOMER ISSUE	-
DMS_02085	09276	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02086	09277	N	N	N	1	CUSTOMER ISSUE	-
DMS_02087	09278	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02088	09279	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02089	09280	N	N	N	1	CUSTOMER ISSUE	-
DMS_02090	09281	N	N	N	1	CUSTOMER ISSUE	-
DMS_02091	09282	N	N	N	1	CUSTOMER ISSUE	-
DMS_02092	09283	N	N	N	1	CUSTOMER ISSUE	-
DMS_02093	09284	N	N	N	1	CUSTOMER ISSUE	-
DMS_02094	09285	N	N	N	1	CUSTOMER ISSUE	-
DMS_02095	09286	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02096	09287	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02097	09288	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02098	09289	N	N	N	1	CUSTOMER ISSUE	-
DMS_02099	09290	N	N	N	1	CUSTOMER ISSUE	-
DMS_02100	09291	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_02101	09292	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02102	09293	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02103	09294	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02104	09295	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02105	09296	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02106	09297	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02107	09298	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02108	09299	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02109	09300	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02110	09301	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02111	09302	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02112	09303	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02113	09304	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02114	09305	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02115	09306	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02116	09307	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02117	09308	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02118	09309	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02119	09310	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02120	09311	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02121	09312	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02122	09313	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02123	09314	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02124	09315	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02125	09316	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02126	09317	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02127	09318	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02128	09319	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02129	09320	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02130	09321	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02131	09322	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02132	09323	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02133	09324	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02134	09325	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02135	09326	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02136	09327	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02137	09328	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02138	09329	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02139	09330	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02140	09331	N	N	N	1	CUSTOMER ISSUE	-
DMS_02141	09332	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02142	09333	N	N	N	1	CUSTOMER ISSUE	-
DMS_02143	09334	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02144	09335	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02145	09336	N	N	N	1	CUSTOMER ISSUE	-

DMS_02146	09337	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02147	09338	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02148	09339	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02149	09340	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02150	09341	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02151	09342	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02152	09343	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02153	09344	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02154	09345	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02155	09346	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02156	09347	N	N	N	1	CUSTOMER ISSUE	-
DMS_02157	09348	N	N	N	1	CUSTOMER ISSUE	-
DMS_02158	09349	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02159	09350	N	N	N	1	CUSTOMER ISSUE	-
DMS_02160	09351	N	N	N	1	CUSTOMER ISSUE	-
DMS_02161	09352	N	N	N	1	CUSTOMER ISSUE	-
DMS_02162	09353	N	N	N	1	CUSTOMER ISSUE	-
DMS_02163	09354	N	N	N	1	CUSTOMER ISSUE	-
DMS_02164	09355	N	N	N	1	CUSTOMER ISSUE	-
DMS_02165	09356	N	N	N	1	CUSTOMER ISSUE	-
DMS_02166	09357	N	N	N	1	CUSTOMER ISSUE	-
DMS_02167	09358	N	N	N	2	CUSTOMER ISSUE	-
DMS_02168	09359	N	N	N	1	CUSTOMER ISSUE	-
DMS_02169	09360	N	N	N	1	CUSTOMER ISSUE	-
DMS_02170	09361	N	N	N	1	CUSTOMER ISSUE	-
DMS_02171	09362	N	N	N	1	CUSTOMER ISSUE	-
DMS_02172	09363	N	N	N	1	CUSTOMER ISSUE	-
DMS_02173	09364	N	N	N	1	CUSTOMER ISSUE	-
DMS_02174	09365	N	N	N	1	CUSTOMER ISSUE	-
DMS_02176	09366	N	N	N	1	CUSTOMER ISSUE	-
DMS_02177	09367	N	N	N	1	CUSTOMER ISSUE	-
DMS_02178	09368	N	N	N	1	CUSTOMER ISSUE	-
DMS_02179	09369	N	N	N	1	CUSTOMER ISSUE	-
DMS_02180	09370	N	N	N	1	CUSTOMER ISSUE	-
DMS_02181	09371	N	N	N	1	CUSTOMER ISSUE	-
DMS_02182	09372	N	N	N	1	CUSTOMER ISSUE	-
DMS_02183	09373	N	N	N	1	CUSTOMER ISSUE	-
DMS_02184	09374	N	N	N	1	CUSTOMER ISSUE	-
DMS_02185	09375	N	N	N	1	CUSTOMER ISSUE	-
DMS_02186	09376	N	N	N	1	CUSTOMER ISSUE	-
DMS_02187	09377	N	N	N	1	CUSTOMER ISSUE	-
DMS_02188	09378	N	N	N	1	CUSTOMER ISSUE	-
DMS_02189	09379	N	N	N	1	CUSTOMER ISSUE	-
DMS_02190	09380	N	N	N	1	CUSTOMER ISSUE	-
DMS_02191	09381	N	N	N	1	CUSTOMER ISSUE	-
DMS_02192	09382	N	N	N	1	CUSTOMER ISSUE	-
DMS_02193	09383	N	N	N	1	CUSTOMER ISSUE	-
DMS_02194	09384	N	N	N	1	CUSTOMER ISSUE	-
DMS_02195	09385	N	N	N	1	CUSTOMER ISSUE	-
DMS_02196	09386	N	N	N	1	CUSTOMER ISSUE	-
DMS_02197	09387	N	N	N	1	CUSTOMER ISSUE	-
DMS_02198	09388	N	N	N	1	CUSTOMER ISSUE	-
DMS_02199	09389	N	N	N	1	CUSTOMER ISSUE	-
DMS_02200	09390	N	N	N	1	CUSTOMER ISSUE	-
DMS_02201	09391	N	N	N	1	CUSTOMER ISSUE	-
DMS_02202	09392	N	N	N	1	CUSTOMER ISSUE	-
DMS_02203	09393	N	N	N	1	CUSTOMER ISSUE	-
DMS_02204	09394	N	N	N	1	CUSTOMER ISSUE	-
DMS_02205	09395	N	N	N	1	CUSTOMER ISSUE	-
DMS_02206	09396	N	N	N	1	CUSTOMER ISSUE	-
DMS_02207	09397	N	N	N	1	CUSTOMER ISSUE	-
DMS_02208	09398	N	N	N	1	CUSTOMER ISSUE	-
DMS_02209	09399	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02210	09400	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02211	09401	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02212	09402	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02213	09403	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02214	09404	N	N	N	1	CUSTOMER ISSUE	-
DMS_02215	09405	N	N	N	1	CUSTOMER ISSUE	-
DMS_02216	09406	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02217	09407	N	N	N	1	CUSTOMER ISSUE	-
DMS_02218	09408	N	N	N	1	CUSTOMER ISSUE	-
DMS_02219	09409	N	N	N	1	CUSTOMER ISSUE	-
DMS_02220	09410	N	N	N	1	CUSTOMER ISSUE	-
DMS_02221	09411	N	N	N	1	CUSTOMER ISSUE	-
DMS_02222	09412	N	N	N	1	CUSTOMER ISSUE	-
DMS_02223	09413	N	N	N	1	CUSTOMER ISSUE	-
DMS_02224	09414	N	N	N	1	CUSTOMER ISSUE	-
DMS_02225	09415	N	N	N	1	CUSTOMER ISSUE	-
DMS_02226	09416	N	N	N	1	CUSTOMER ISSUE	-

DMS_02227	09417	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02228	09418	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02229	09419	N	N	N	1	CUSTOMER ISSUE	-
DMS_02230	09420	N	N	N	1	CUSTOMER ISSUE	-
DMS_02231	09421	N	N	N	1	CUSTOMER ISSUE	-
DMS_02232	09422	N	N	N	1	CUSTOMER ISSUE	-
DMS_02233	09423	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02234	09424	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02235	09425	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02236	09426	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02237	09427	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02238	09428	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02239	09429	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02240	09430	N	N	N	1	CUSTOMER ISSUE	-
DMS_02241	09431	N	N	N	1	CUSTOMER ISSUE	-
DMS_02242	09432	N	N	N	1	CUSTOMER ISSUE	-
DMS_02243	09433	N	N	N	1	CUSTOMER ISSUE	-
DMS_02244	09434	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02245	09435	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02246	09436	N	N	N	1	CUSTOMER ISSUE	-
DMS_02247	09437	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02248	09438	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02249	09439	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02250	09440	N	N	N	1	CUSTOMER ISSUE	-
DMS_02251	09441	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02252	09442	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02253	09443	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02254	09444	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02255	09445	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02256	09446	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02257	09447	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02258	09448	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02259	09449	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02260	09450	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02261	09451	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02262	09452	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02263	09453	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02264	09454	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02265	09455	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02266	09456	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02267	09457	N	N	N	1	CUSTOMER ISSUE	-
DMS_02268	09458	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02269	09459	N	N	N	1	CUSTOMER ISSUE	-
DMS_02270	09460	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02271	09461	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02272	09462	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02273	09463	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02274	09464	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02275	09465	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02276	09466	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02277	09467	N	N	N	1	CUSTOMER ISSUE	-
DMS_02278	09468	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02279	09469	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02280	09470	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02281	09471	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02282	09472	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02283	09473	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02284	09474	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02285	09475	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02286	09476	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02287	09477	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02288	09478	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02289	09479	N	N	N	1	CUSTOMER ISSUE	-
DMS_02290	09480	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02291	09481	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02292	09482	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02293	09483	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02294	09484	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02295	09485	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02296	09486	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02297	09487	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02298	09488	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02299	09489	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02300	09490	N	N	N	1	CUSTOMER ISSUE	-
DMS_02301	09491	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02302	09492	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02303	09493	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02304	09494	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02305	09495	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02306	09496	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_02307	09497	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02308	09498	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02309	09499	N	N	N	1	CUSTOMER ISSUE	-
DMS_02310	09500	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02311	09501	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02312	09502	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02313	09503	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02314	09504	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02315	09505	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02316	09506	N	N	Y	1	TX - REPLACE	2500
DMS_02317	09507	N	N	Y	1	TX - REPLACE	2500
DMS_02318	09508	N	N	Y	1	TX - REPLACE	2500
DMS_02319	09509	N	N	Y	1	TX - REPLACE	2500
DMS_02320	09510	N	N	Y	1	TX - REPLACE	2500
DMS_02321	09511	N	N	Y	1	TX - REPLACE	2500
DMS_02322	09512	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02323	09513	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02324	09514	N	N	N	1	CUSTOMER ISSUE	-
DMS_02325	09515	N	N	N	1	CUSTOMER ISSUE	-
DMS_02326	09516	N	N	N	1	CUSTOMER ISSUE	-
DMS_02327	09517	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02328	09518	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02329	09519	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02330	09520	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02331	09521	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02332	09522	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02333	09523	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02334	09524	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02335	09525	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02336	09526	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_02337	09527	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02338	09528	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
DMS_02339	09529	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02340	09530	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02341	09531	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02342	09532	N	N	Y	3	SEC/SVC - REPLACE	708.75
DMS_02343	09533	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02344	09534	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02345	09535	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02346	09536	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02347	09537	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02348	09538	N	N	Y	1	TX - REPLACE	2500
DMS_02349	09539	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02350	09540	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02351	09541	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02352	09542	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02353	09543	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02354	09544	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02355	09545	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02356	09546	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02357	09547	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02358	09548	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02359	09549	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02360	09550	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02361	09551	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02362	09552	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02363	09553	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02364	09554	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02365	09555	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02366	09556	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02367	09557	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02368	09558	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02369	09559	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02370	09560	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02371	09561	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02372	09562	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02373	09563	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02374	09564	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02375	09565	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02376	09566	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02377	09567	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02378	09568	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02379	09569	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02380	09570	N	N	Y	1	TX - REPLACE	2500
DMS_02381	09571	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02382	09572	N	N	N	1	CUSTOMER ISSUE	-
DMS_02383	09573	N	N	Y	1	TX - REPLACE	2500
DMS_02384	09574	N	N	Y	1	TX - REPLACE	2500
DMS_02385	09575	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02386	09576	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_02387	09577	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02388	09578	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02389	09579	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02390	09580	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02391	09581	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02392	09582	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02393	09583	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02394	09584	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02395	09585	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02396	09586	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02397	09587	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02398	09588	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02399	09589	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02400	09590	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02401	09591	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02402	09592	N	N	N	1	CUSTOMER ISSUE	-
DMS_02403	09593	N	N	N	1	CUSTOMER ISSUE	-
DMS_02404	09594	N	N	N	1	CUSTOMER ISSUE	-
DMS_02405	09595	N	N	N	1	CUSTOMER ISSUE	-
DMS_02406	09596	N	N	N	1	CUSTOMER ISSUE	-
DMS_02407	09597	N	N	Y	1	TX - REPLACE	2500
DMS_02408	09598	N	N	N	1	CUSTOMER ISSUE	-
DMS_02409	09599	N	N	Y	1	TX - REPLACE	2500
DMS_02410	09600	N	N	Y	1	TX - REPLACE	2500
DMS_02411	09601	N	N	Y	1	TX - REPLACE	2500
DMS_02412	09602	N	N	Y	1	TX - REPLACE	2500
DMS_02413	09603	N	N	Y	1	TX - REPLACE	2500
DMS_02414	09604	N	N	Y	1	TX - REPLACE	2500
DMS_02415	09605	N	N	Y	1	TX - REPLACE	2500
DMS_02416	09606	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02417	09607	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02418	09608	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02419	09609	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02420	09610	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02421	09611	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02422	09612	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02423	09613	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02424	09614	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02425	09615	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02426	09616	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02427	09617	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02428	09618	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02429	09619	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02430	09620	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02431	09621	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02432	09622	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02433	09623	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02434	09624	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02435	09625	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02436	09626	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02437	09627	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02438	09628	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02439	09629	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02440	09630	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02441	09631	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02442	09632	N	N	Y	1	TX - REPLACE	2500
DMS_02443	09633	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02445	09634	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02446	09635	N	N	N	1	CUSTOMER ISSUE	-
DMS_02447	09636	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02448	09637	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02449	09638	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02450	09639	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02451	09640	N	N	N	1	CUSTOMER ISSUE	-
DMS_02452	09641	N	N	N	1	CUSTOMER ISSUE	-
DMS_02453	09642	N	N	N	1	CUSTOMER ISSUE	-
DMS_02454	09643	N	N	N	1	CUSTOMER ISSUE	-
DMS_02455	09644	N	N	N	1	CUSTOMER ISSUE	-
DMS_02456	09645	N	N	N	1	CUSTOMER ISSUE	-
DMS_02457	09646	N	N	N	1	CUSTOMER ISSUE	-
DMS_02458	09647	N	N	N	1	CUSTOMER ISSUE	-
DMS_02459	09648	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02460	09649	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02461	09650	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02462	09651	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02467	09652	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02475	09653	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_02488	09654	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02512	09655	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_02513	09656	N	N	N	1	CUSTOMER ISSUE	-

DMS_02514	09657	N	N	Y	1	TX - REPLACE	2500
DMS_02515	09658	N	N	N	1	CUSTOMER ISSUE	-
DMS_02516	09659	N	N	N	1	CUSTOMER ISSUE	-
DMS_02517	09660	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02518	09661	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02523	09662	N	N	N	1	CUSTOMER ISSUE	-
DMS_02524	09663	N	N	N	1	CUSTOMER ISSUE	-
DMS_02525	09664	N	N	N	1	CUSTOMER ISSUE	-
DMS_02526	09665	N	N	N	1	CUSTOMER ISSUE	-
DMS_02527	09666	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02529	09667	N	N	N	1	CUSTOMER ISSUE	-
DMS_02530	09668	N	N	N	1	CUSTOMER ISSUE	-
DMS_02531	09669	N	N	N	1	CUSTOMER ISSUE	-
DMS_02532	09670	N	N	N	1	CUSTOMER ISSUE	-
DMS_02533	09671	N	N	N	1	CUSTOMER ISSUE	-
DMS_02534	09672	N	N	N	1	CUSTOMER ISSUE	-
DMS_02535	09673	N	N	N	1	CUSTOMER ISSUE	-
DMS_02538	09674	N	N	N	1	CUSTOMER ISSUE	-
DMS_02540	09675	N	N	N	1	CUSTOMER ISSUE	-
DMS_02541	09676	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02542	09677	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02543	09678	N	N	N	1	CUSTOMER ISSUE	-
DMS_02544	09679	N	N	N	1	CUSTOMER ISSUE	-
DMS_02545	09680	N	N	N	1	CUSTOMER ISSUE	-
DMS_02546	09681	N	N	N	1	CUSTOMER ISSUE	-
DMS_02547	09682	N	N	N	1	CUSTOMER ISSUE	-
DMS_02548	09683	N	N	N	1	CUSTOMER ISSUE	-
DMS_02549	09684	N	N	N	1	CUSTOMER ISSUE	-
DMS_02550	09685	N	N	N	1	CUSTOMER ISSUE	-
DMS_02551	09686	N	N	N	1	CUSTOMER ISSUE	-
DMS_02552	09687	N	N	N	1	CUSTOMER ISSUE	-
DMS_02553	09688	N	N	N	1	CUSTOMER ISSUE	-
DMS_02554	09689	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02555	09690	N	N	N	1	CUSTOMER ISSUE	-
DMS_02556	09691	N	N	N	1	CUSTOMER ISSUE	-
DMS_02557	09692	N	N	N	1	CUSTOMER ISSUE	-
DMS_02558	09693	N	N	N	1	CUSTOMER ISSUE	-
DMS_02559	09694	N	N	N	1	CUSTOMER ISSUE	-
DMS_02561	09695	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_02562	09696	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02564	09697	N	N	N	1	CUSTOMER ISSUE	-
DMS_02568	09698	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02569	09699	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_02570	09700	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02572	09701	N	N	N	1	CUSTOMER ISSUE	-
DMS_02583	09702	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02584	09703	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02587	09704	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02589	09705	N	N	Y	1	TX - REPLACE	2500
DMS_02590	09706	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02591	09707	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02592	09708	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02594	09709	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
DMS_02595	09710	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02598	09711	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02600	09712	N	N	N	1	CUSTOMER ISSUE	-
DMS_02601	09713	N	N	N	1	CUSTOMER ISSUE	-
DMS_02604	09714	N	N	Y	1	TX - REPLACE	2500
DMS_02605	09715	N	N	N	1	CUSTOMER ISSUE	-
DMS_02606	09716	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02607	09717	N	N	N	1	CUSTOMER ISSUE	-
DMS_02608	09718	N	N	N	8	CUSTOMER ISSUE	-
DMS_02609	09719	N	N	N	1	CUSTOMER ISSUE	-
DMS_02610	09720	N	N	N	1	CUSTOMER ISSUE	-
DMS_02611	09721	N	N	N	1	CUSTOMER ISSUE	-
DMS_02612	09722	N	N	N	1	CUSTOMER ISSUE	-
DMS_02613	09723	N	N	N	1	CUSTOMER ISSUE	-
DMS_02614	09724	N	N	N	1	CUSTOMER ISSUE	-
DMS_02615	09725	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02616	09726	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02617	09727	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02618	09728	N	N	N	1	CUSTOMER ISSUE	-
DMS_02619	09729	N	N	N	1	CUSTOMER ISSUE	-
DMS_02620	09730	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02621	09731	N	N	N	1	CUSTOMER ISSUE	-
DMS_02622	09732	N	N	N	1	CUSTOMER ISSUE	-
DMS_02623	09733	N	N	N	1	CUSTOMER ISSUE	-
DMS_02624	09734	N	N	N	1	CUSTOMER ISSUE	-
DMS_02625	09735	N	N	N	1	CUSTOMER ISSUE	-
DMS_02627	09736	N	N	Y	1	TX - REPLACE	2500

DMS_02628	09737	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02629	09738	N	N	N	1	CUSTOMER ISSUE	-
DMS_02630	09739	N	N	N	1	CUSTOMER ISSUE	-
DMS_02631	09740	N	N	N	1	CUSTOMER ISSUE	-
DMS_02632	09741	N	N	N	1	CUSTOMER ISSUE	-
DMS_02633	09742	N	N	N	1	CUSTOMER ISSUE	-
DMS_02634	09743	N	N	N	1	CUSTOMER ISSUE	-
DMS_02635	09744	N	N	N	1	CUSTOMER ISSUE	-
DMS_02636	09745	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02637	09746	N	N	N	1	CUSTOMER ISSUE	-
DMS_02638	09747	N	N	N	1	CUSTOMER ISSUE	-
DMS_02639	09748	N	N	N	1	CUSTOMER ISSUE	-
DMS_02640	09749	N	N	N	1	CUSTOMER ISSUE	-
DMS_02641	09750	N	N	N	1	CUSTOMER ISSUE	-
DMS_02642	09751	N	N	N	1	CUSTOMER ISSUE	-
DMS_02643	09752	N	N	N	1	CUSTOMER ISSUE	-
DMS_02644	09753	N	N	N	1	CUSTOMER ISSUE	-
DMS_02645	09754	N	N	N	1	CUSTOMER ISSUE	-
DMS_02646	09755	N	N	N	1	CUSTOMER ISSUE	-
DMS_02647	09756	N	N	N	1	CUSTOMER ISSUE	-
DMS_02648	09757	N	N	N	1	CUSTOMER ISSUE	-
DMS_02650	09758	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02651	09759	N	N	N	1	CUSTOMER ISSUE	-
DMS_02652	09760	N	N	N	1	CUSTOMER ISSUE	-
DMS_02653	09761	N	N	N	1	CUSTOMER ISSUE	-
DMS_02654	09762	N	N	N	1	CUSTOMER ISSUE	-
DMS_02655	09763	N	N	N	1	CUSTOMER ISSUE	-
DMS_02656	09764	N	N	N	1	CUSTOMER ISSUE	-
DMS_02657	09765	N	N	N	1	CUSTOMER ISSUE	-
DMS_02658	09766	N	N	N	1	CUSTOMER ISSUE	-
DMS_02659	09767	N	N	N	1	CUSTOMER ISSUE	-
DMS_02660	09768	N	N	N	1	CUSTOMER ISSUE	-
DMS_02661	09769	N	N	N	1	CUSTOMER ISSUE	-
DMS_02662	09770	N	N	N	1	CUSTOMER ISSUE	-
DMS_02663	09771	N	N	N	1	CUSTOMER ISSUE	-
DMS_02664	09772	N	N	N	1	CUSTOMER ISSUE	-
DMS_02665	09773	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02667	09774	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02668	09775	N	N	N	1	CUSTOMER ISSUE	-
DMS_02669	09776	N	N	N	1	CUSTOMER ISSUE	-
DMS_02670	09777	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02671	09778	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02672	09779	N	N	N	1	CUSTOMER ISSUE	-
DMS_02673	09780	N	N	N	1	CUSTOMER ISSUE	-
DMS_02674	09781	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02675	09782	N	N	N	1	CUSTOMER ISSUE	-
DMS_02676	09783	N	N	N	1	CUSTOMER ISSUE	-
DMS_02677	09784	N	N	N	1	CUSTOMER ISSUE	-
DMS_02678	09785	N	N	N	1	CUSTOMER ISSUE	-
DMS_02679	09786	N	N	N	1	CUSTOMER ISSUE	-
DMS_02680	09787	N	N	N	1	CUSTOMER ISSUE	-
DMS_02681	09788	N	N	N	1	CUSTOMER ISSUE	-
DMS_02682	09789	N	N	N	1	CUSTOMER ISSUE	-
DMS_02683	09790	N	N	N	1	CUSTOMER ISSUE	-
DMS_02684	09791	N	N	N	1	CUSTOMER ISSUE	-
DMS_02685	09792	N	N	N	1	CUSTOMER ISSUE	-
DMS_02686	09793	N	N	N	1	CUSTOMER ISSUE	-
DMS_02687	09794	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02688	09795	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02689	09796	N	N	N	1	CUSTOMER ISSUE	-
DMS_02690	09797	N	N	N	1	CUSTOMER ISSUE	-
DMS_02691	09798	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02692	09799	N	N	N	1	CUSTOMER ISSUE	-
DMS_02693	09800	N	N	N	1	CUSTOMER ISSUE	-
DMS_02694	09801	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02695	09802	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02696	09803	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02697	09804	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02698	09805	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02699	09806	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02700	09807	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02701	09808	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02702	09809	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02703	09810	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02704	09811	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_02705	09812	N	N	N	1	CUSTOMER ISSUE	-
DMS_02706	09813	N	N	N	1	CUSTOMER ISSUE	-
DMS_02707	09814	N	N	N	1	CUSTOMER ISSUE	-
DMS_02708	09815	N	N	N	1	CUSTOMER ISSUE	-
DMS_02709	09816	N	N	N	1	CUSTOMER ISSUE	-

DMS_02710	09817	N	N	N	1	CUSTOMER ISSUE	-
DMS_02711	09818	N	N	N	1	CUSTOMER ISSUE	-
DMS_02712	09819	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02713	09820	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02714	09821	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02715	09822	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02716	09823	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02717	09824	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02718	09825	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02719	09826	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02720	09827	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02721	09828	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02722	09829	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02723	09830	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02724	09831	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02725	09832	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02726	09833	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02727	09834	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02728	09835	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02729	09836	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02730	09837	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02732	09838	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02733	09839	N	N	N	1	CUSTOMER ISSUE	-
DMS_02734	09840	N	N	N	1	CUSTOMER ISSUE	-
DMS_02735	09841	N	N	N	1	CUSTOMER ISSUE	-
DMS_02736	09842	N	N	N	1	CUSTOMER ISSUE	-
DMS_02737	09843	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02738	09844	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02739	09845	N	N	N	1	CUSTOMER ISSUE	-
DMS_02740	09846	N	N	N	1	CUSTOMER ISSUE	-
DMS_02741	09847	N	N	N	1	CUSTOMER ISSUE	-
DMS_02742	09848	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02743	09849	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02744	09850	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02745	09851	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02746	09852	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02747	09853	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02748	09854	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02749	09855	N	N	N	1	CUSTOMER ISSUE	-
DMS_02750	09856	N	N	N	1	CUSTOMER ISSUE	-
DMS_02752	09857	N	N	N	1	CUSTOMER ISSUE	-
DMS_02753	09858	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02754	09859	N	N	N	1	CUSTOMER ISSUE	-
DMS_02755	09860	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02756	09861	N	N	N	1	CUSTOMER ISSUE	-
DMS_02757	09862	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02758	09863	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02759	09864	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02760	09865	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02761	09866	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02762	09867	N	N	N	1	CUSTOMER ISSUE	-
DMS_02764	09868	N	N	N	1	CUSTOMER ISSUE	-
DMS_02765	09869	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02766	09870	N	N	N	1	CUSTOMER ISSUE	-
DMS_02767	09871	N	N	N	1	CUSTOMER ISSUE	-
DMS_02768	09872	N	N	N	1	CUSTOMER ISSUE	-
DMS_02769	09873	N	N	N	1	CUSTOMER ISSUE	-
DMS_02770	09874	N	N	N	1	CUSTOMER ISSUE	-
DMS_02771	09875	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02774	09876	N	N	N	1	CUSTOMER ISSUE	-
DMS_02775	09877	N	N	N	1	CUSTOMER ISSUE	-
DMS_02776	09878	N	N	N	1	CUSTOMER ISSUE	-
DMS_02777	09879	N	N	N	1	CUSTOMER ISSUE	-
DMS_02783	09880	N	N	N	1	CUSTOMER ISSUE	-
DMS_02784	09881	N	N	N	1	CUSTOMER ISSUE	-
DMS_02785	09882	N	N	N	1	CUSTOMER ISSUE	-
DMS_02786	09883	N	N	N	1	CUSTOMER ISSUE	-
DMS_02787	09884	N	N	N	1	CUSTOMER ISSUE	-
DMS_02789	09885	N	N	N	1	CUSTOMER ISSUE	-
DMS_02790	09886	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02792	09887	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02793	09888	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02795	09889	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02796	09890	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02797	09891	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02798	09892	N	N	N	1	CUSTOMER ISSUE	-
DMS_02800	09893	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_02802	09894	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02803	09895	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02804	09896	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_02806	09897	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02807	09898	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_02811	09899	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02814	09900	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_02815	09901	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_02816	09902	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_02817	09903	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02823	09904	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_02825	09905	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02830	09906	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02831	09907	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_02836	09908	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_02860	09909	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_02862	09910	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_02865	09911	N	N	N	1	CUSTOMER ISSUE	-
DMS_02866	09912	N	N	N	1	CUSTOMER ISSUE	-
DMS_02867	09913	N	N	N	1	CUSTOMER ISSUE	-
DMS_02868	09914	N	N	N	1	CUSTOMER ISSUE	-
DMS_02869	09915	N	N	N	1	CUSTOMER ISSUE	-
DMS_02870	09916	N	N	N	1	CUSTOMER ISSUE	-
DMS_02871	09917	N	N	N	1	CUSTOMER ISSUE	-
DMS_02872	09918	N	N	N	1	CUSTOMER ISSUE	-
DMS_02873	09919	N	N	N	1	CUSTOMER ISSUE	-
DMS_02874	09920	N	N	N	1	CUSTOMER ISSUE	-
DMS_02875	09921	N	N	N	1	CUSTOMER ISSUE	-
DMS_02876	09922	N	N	N	1	CUSTOMER ISSUE	-
DMS_02877	09923	N	N	N	1	CUSTOMER ISSUE	-
DMS_02878	09924	N	N	N	1	CUSTOMER ISSUE	-
DMS_02879	09925	N	N	N	1	CUSTOMER ISSUE	-
DMS_02880	09926	N	N	N	1	CUSTOMER ISSUE	-
DMS_02881	09927	N	N	N	1	CUSTOMER ISSUE	-
DMS_02882	09928	N	N	N	1	CUSTOMER ISSUE	-
DMS_02883	09929	N	N	N	1	CUSTOMER ISSUE	-
DMS_02884	09930	N	N	N	1	CUSTOMER ISSUE	-
DMS_02885	09931	N	N	N	1	CUSTOMER ISSUE	-
DMS_02886	09932	N	N	N	1	CUSTOMER ISSUE	-
DMS_02887	09933	N	N	N	1	CUSTOMER ISSUE	-
DMS_02888	09934	N	N	N	1	CUSTOMER ISSUE	-
DMS_02889	09935	N	N	N	1	CUSTOMER ISSUE	-
DMS_02890	09936	N	N	N	1	CUSTOMER ISSUE	-
DMS_02891	09937	N	N	N	1	CUSTOMER ISSUE	-
DMS_02892	09938	N	N	N	1	CUSTOMER ISSUE	-
DMS_02893	09939	N	N	N	1	CUSTOMER ISSUE	-
DMS_02894	09940	N	N	N	1	CUSTOMER ISSUE	-
DMS_02895	09941	N	N	N	1	CUSTOMER ISSUE	-
DMS_02896	09942	N	N	N	1	CUSTOMER ISSUE	-
DMS_02897	09943	N	N	N	1	CUSTOMER ISSUE	-
DMS_02898	09944	N	N	N	1	CUSTOMER ISSUE	-
DMS_02899	09945	N	N	N	1	CUSTOMER ISSUE	-
DMS_02900	09946	N	N	N	1	CUSTOMER ISSUE	-
DMS_02901	09947	N	N	N	1	CUSTOMER ISSUE	-
DMS_02902	09948	N	N	N	1	CUSTOMER ISSUE	-
DMS_02903	09949	N	N	N	2	CUSTOMER ISSUE	-
DMS_02904	09950	N	N	N	1	CUSTOMER ISSUE	-
DMS_02905	09951	N	N	N	1	CUSTOMER ISSUE	-
DMS_02906	09952	N	N	N	1	CUSTOMER ISSUE	-
DMS_02907	09953	N	N	N	1	CUSTOMER ISSUE	-
DMS_02908	09954	N	N	N	1	CUSTOMER ISSUE	-
DMS_02909	09955	N	N	N	1	CUSTOMER ISSUE	-
DMS_02910	09956	N	N	N	1	CUSTOMER ISSUE	-
DMS_02911	09957	N	N	N	1	CUSTOMER ISSUE	-
DMS_02913	09958	N	N	N	1	CUSTOMER ISSUE	-
DMS_02914	09959	N	N	N	1	CUSTOMER ISSUE	-
DMS_02915	09960	N	N	N	1	CUSTOMER ISSUE	-
DMS_02916	09961	N	N	N	1	CUSTOMER ISSUE	-
DMS_02917	09962	N	N	N	1	CUSTOMER ISSUE	-
DMS_02918	09963	N	N	N	1	CUSTOMER ISSUE	-
DMS_02919	09964	N	N	N	1	CUSTOMER ISSUE	-
DMS_02920	09965	N	N	N	1	CUSTOMER ISSUE	-
DMS_02921	09966	N	N	N	1	CUSTOMER ISSUE	-
DMS_02922	09967	N	N	N	1	CUSTOMER ISSUE	-
DMS_02923	09968	N	N	N	1	CUSTOMER ISSUE	-
DMS_02924	09969	N	N	N	1	CUSTOMER ISSUE	-
DMS_02925	09970	N	N	N	1	CUSTOMER ISSUE	-
DMS_02926	09971	N	N	N	1	CUSTOMER ISSUE	-
DMS_02927	09972	N	N	N	1	CUSTOMER ISSUE	-
DMS_02928	09973	N	N	N	1	CUSTOMER ISSUE	-
DMS_02929	09974	N	N	N	1	CUSTOMER ISSUE	-
DMS_02930	09975	N	N	N	1	CUSTOMER ISSUE	-
DMS_02931	09976	N	N	N	1	CUSTOMER ISSUE	-

DMS_02932	09977	N	N	N	1	CUSTOMER ISSUE	-
DMS_02933	09978	N	N	N	1	CUSTOMER ISSUE	-
DMS_02934	09979	N	N	N	1	CUSTOMER ISSUE	-
DMS_02935	09980	N	N	N	1	CUSTOMER ISSUE	-
DMS_02936	09981	N	N	N	1	CUSTOMER ISSUE	-
DMS_02937	09982	N	N	N	1	CUSTOMER ISSUE	-
DMS_02938	09983	N	N	N	1	CUSTOMER ISSUE	-
DMS_02939	09984	N	N	N	1	CUSTOMER ISSUE	-
DMS_02940	09985	N	N	N	1	CUSTOMER ISSUE	-
DMS_02941	09986	N	N	N	1	CUSTOMER ISSUE	-
DMS_02942	09987	N	N	N	1	CUSTOMER ISSUE	-
DMS_02943	09988	N	N	N	1	CUSTOMER ISSUE	-
DMS_02944	09989	N	N	N	1	CUSTOMER ISSUE	-
DMS_02945	09990	N	N	N	1	CUSTOMER ISSUE	-
DMS_02946	09991	N	N	N	1	CUSTOMER ISSUE	-
DMS_02947	09992	N	N	N	1	CUSTOMER ISSUE	-
DMS_02948	09993	N	N	N	1	CUSTOMER ISSUE	-
DMS_02949	09994	N	N	N	1	CUSTOMER ISSUE	-
DMS_02950	09995	N	N	N	1	CUSTOMER ISSUE	-
DMS_02951	09996	N	N	N	1	CUSTOMER ISSUE	-
DMS_02952	09997	N	N	N	1	CUSTOMER ISSUE	-
DMS_02953	09998	N	N	N	1	CUSTOMER ISSUE	-
DMS_02954	09999	N	N	N	1	CUSTOMER ISSUE	-
DMS_02955	10000	N	N	N	1	CUSTOMER ISSUE	-
DMS_02956	10001	N	N	N	1	CUSTOMER ISSUE	-
DMS_02957	10002	N	N	N	1	CUSTOMER ISSUE	-
DMS_02958	10003	N	N	N	1	CUSTOMER ISSUE	-
DMS_02959	10004	N	N	N	1	CUSTOMER ISSUE	-
DMS_02960	10005	N	N	N	1	CUSTOMER ISSUE	-
DMS_02961	10006	N	N	N	1	CUSTOMER ISSUE	-
DMS_02962	10007	N	N	N	1	CUSTOMER ISSUE	-
DMS_02963	10008	N	N	N	1	CUSTOMER ISSUE	-
DMS_02964	10009	N	N	N	1	CUSTOMER ISSUE	-
DMS_02965	10010	N	N	N	1	CUSTOMER ISSUE	-
DMS_02966	10011	N	N	N	1	CUSTOMER ISSUE	-
DMS_02967	10012	N	N	N	1	CUSTOMER ISSUE	-
DMS_02968	10013	N	N	N	1	CUSTOMER ISSUE	-
DMS_02969	10014	N	N	N	1	CUSTOMER ISSUE	-
DMS_02970	10015	N	N	N	1	CUSTOMER ISSUE	-
DMS_02971	10016	N	N	N	1	CUSTOMER ISSUE	-
DMS_02972	10017	N	N	N	1	CUSTOMER ISSUE	-
DMS_02973	10018	N	N	N	1	CUSTOMER ISSUE	-
DMS_02974	10019	N	N	N	1	CUSTOMER ISSUE	-
DMS_02975	10020	N	N	N	1	CUSTOMER ISSUE	-
DMS_02976	10021	N	N	N	1	CUSTOMER ISSUE	-
DMS_02977	10022	N	N	N	1	CUSTOMER ISSUE	-
DMS_02978	10023	N	N	N	1	CUSTOMER ISSUE	-
DMS_02979	10024	N	N	N	1	CUSTOMER ISSUE	-
DMS_02980	10025	N	N	N	1	CUSTOMER ISSUE	-
DMS_02981	10026	N	N	N	1	CUSTOMER ISSUE	-
DMS_02982	10027	N	N	N	1	CUSTOMER ISSUE	-
DMS_02983	10028	N	N	N	1	CUSTOMER ISSUE	-
DMS_02984	10029	N	N	N	1	CUSTOMER ISSUE	-
DMS_02985	10030	N	N	N	1	CUSTOMER ISSUE	-
DMS_02986	10031	N	N	N	1	CUSTOMER ISSUE	-
DMS_02987	10032	N	N	N	1	CUSTOMER ISSUE	-
DMS_02988	10033	N	N	N	1	CUSTOMER ISSUE	-
DMS_02989	10034	N	N	N	1	CUSTOMER ISSUE	-
DMS_02990	10035	N	N	N	1	CUSTOMER ISSUE	-
DMS_02991	10036	N	N	N	1	CUSTOMER ISSUE	-
DMS_02992	10037	N	N	N	1	CUSTOMER ISSUE	-
DMS_02993	10038	N	N	N	1	CUSTOMER ISSUE	-
DMS_02994	10039	N	N	N	1	CUSTOMER ISSUE	-
DMS_02995	10040	N	N	N	1	CUSTOMER ISSUE	-
DMS_02996	10041	N	N	N	1	CUSTOMER ISSUE	-
DMS_02997	10042	N	N	N	1	CUSTOMER ISSUE	-
DMS_02998	10043	N	N	N	1	CUSTOMER ISSUE	-
DMS_02999	10044	N	N	N	1	CUSTOMER ISSUE	-
DMS_03000	10045	N	N	N	1	CUSTOMER ISSUE	-
DMS_03001	10046	N	N	N	1	CUSTOMER ISSUE	-
DMS_03002	10047	N	N	N	1	CUSTOMER ISSUE	-
DMS_03003	10048	N	N	N	1	CUSTOMER ISSUE	-
DMS_03004	10049	N	N	N	1	CUSTOMER ISSUE	-
DMS_03005	10050	N	N	N	1	CUSTOMER ISSUE	-
DMS_03006	10051	N	N	N	1	CUSTOMER ISSUE	-
DMS_03007	10052	N	N	N	1	CUSTOMER ISSUE	-
DMS_03008	10053	N	N	N	1	CUSTOMER ISSUE	-
DMS_03009	10054	N	N	N	1	CUSTOMER ISSUE	-
DMS_03010	10055	N	N	N	1	CUSTOMER ISSUE	-
DMS_03011	10056	N	N	N	1	CUSTOMER ISSUE	-

DMS_03012	10057	N	N	N	1	CUSTOMER ISSUE	-
DMS_03013	10058	N	N	N	1	CUSTOMER ISSUE	-
DMS_03015	10059	N	N	N	1	CUSTOMER ISSUE	-
DMS_03016	10060	N	N	N	1	CUSTOMER ISSUE	-
DMS_03017	10061	N	N	N	1	CUSTOMER ISSUE	-
DMS_03018	10062	N	N	N	1	CUSTOMER ISSUE	-
DMS_03019	10063	N	N	N	1	CUSTOMER ISSUE	-
DMS_03020	10064	N	N	N	1	CUSTOMER ISSUE	-
DMS_03021	10065	N	N	N	1	CUSTOMER ISSUE	-
DMS_03022	10066	N	N	N	1	CUSTOMER ISSUE	-
DMS_03023	10067	N	N	N	1	CUSTOMER ISSUE	-
DMS_03024	10068	N	N	N	1	CUSTOMER ISSUE	-
DMS_03025	10069	N	N	N	1	CUSTOMER ISSUE	-
DMS_03026	10070	N	N	N	1	CUSTOMER ISSUE	-
DMS_03027	10071	N	N	N	1	CUSTOMER ISSUE	-
DMS_03028	10072	N	N	N	1	CUSTOMER ISSUE	-
DMS_03029	10073	N	N	N	1	CUSTOMER ISSUE	-
DMS_03030	10074	N	N	N	1	CUSTOMER ISSUE	-
DMS_03031	10075	N	N	N	1	CUSTOMER ISSUE	-
DMS_03032	10076	N	N	N	1	CUSTOMER ISSUE	-
DMS_03033	10077	N	N	N	1	CUSTOMER ISSUE	-
DMS_03034	10078	N	N	N	1	CUSTOMER ISSUE	-
DMS_03035	10079	N	N	N	1	CUSTOMER ISSUE	-
DMS_03036	10080	N	N	N	1	CUSTOMER ISSUE	-
DMS_03037	10081	N	N	N	1	CUSTOMER ISSUE	-
DMS_03038	10082	N	N	N	1	CUSTOMER ISSUE	-
DMS_03039	10083	N	N	N	1	CUSTOMER ISSUE	-
DMS_03040	10084	N	N	N	1	CUSTOMER ISSUE	-
DMS_03041	10085	N	N	N	1	CUSTOMER ISSUE	-
DMS_03042	10086	N	N	N	1	CUSTOMER ISSUE	-
DMS_03043	10087	N	N	N	1	CUSTOMER ISSUE	-
DMS_03044	10088	N	N	N	1	CUSTOMER ISSUE	-
DMS_03045	10089	N	N	N	1	CUSTOMER ISSUE	-
DMS_03046	10090	N	N	N	1	CUSTOMER ISSUE	-
DMS_03047	10091	N	N	N	1	CUSTOMER ISSUE	-
DMS_03048	10092	N	N	N	1	CUSTOMER ISSUE	-
DMS_03049	10093	N	N	N	1	CUSTOMER ISSUE	-
DMS_03050	10094	N	N	N	1	CUSTOMER ISSUE	-
DMS_03051	10095	N	N	N	1	CUSTOMER ISSUE	-
DMS_03052	10096	N	N	N	1	CUSTOMER ISSUE	-
DMS_03053	10097	N	N	N	1	CUSTOMER ISSUE	-
DMS_03054	10098	N	N	N	1	CUSTOMER ISSUE	-
DMS_03055	10099	N	N	N	1	CUSTOMER ISSUE	-
DMS_03056	10100	N	N	N	1	CUSTOMER ISSUE	-
DMS_03057	10101	N	N	N	1	CUSTOMER ISSUE	-
DMS_03058	10102	N	N	N	1	CUSTOMER ISSUE	-
DMS_03059	10103	N	N	N	1	CUSTOMER ISSUE	-
DMS_03060	10104	N	N	N	1	CUSTOMER ISSUE	-
DMS_03061	10105	N	N	N	1	CUSTOMER ISSUE	-
DMS_03062	10106	N	N	N	1	CUSTOMER ISSUE	-
DMS_03063	10107	N	N	N	1	CUSTOMER ISSUE	-
DMS_03064	10108	N	N	N	1	CUSTOMER ISSUE	-
DMS_03065	10109	N	N	N	1	CUSTOMER ISSUE	-
DMS_03066	10110	N	N	N	1	CUSTOMER ISSUE	-
DMS_03067	10111	N	N	N	1	CUSTOMER ISSUE	-
DMS_03068	10112	N	N	N	1	CUSTOMER ISSUE	-
DMS_03069	10113	N	N	N	1	CUSTOMER ISSUE	-
DMS_03070	10114	N	N	N	1	CUSTOMER ISSUE	-
DMS_03071	10115	N	N	N	1	CUSTOMER ISSUE	-
DMS_03072	10116	N	N	N	1	CUSTOMER ISSUE	-
DMS_03073	10117	N	N	N	1	CUSTOMER ISSUE	-
DMS_03074	10118	N	N	N	1	CUSTOMER ISSUE	-
DMS_03075	10119	N	N	N	1	CUSTOMER ISSUE	-
DMS_03076	10120	N	N	N	1	CUSTOMER ISSUE	-
DMS_03077	10121	N	N	N	1	CUSTOMER ISSUE	-
DMS_03078	10122	N	N	N	1	CUSTOMER ISSUE	-
DMS_03079	10123	N	N	N	1	CUSTOMER ISSUE	-
DMS_03080	10124	N	N	N	1	CUSTOMER ISSUE	-
DMS_03081	10125	N	N	N	1	CUSTOMER ISSUE	-
DMS_03082	10126	N	N	N	1	CUSTOMER ISSUE	-
DMS_03083	10127	N	N	N	1	CUSTOMER ISSUE	-
DMS_03084	10128	N	N	N	1	CUSTOMER ISSUE	-
DMS_03085	10129	N	N	N	1	CUSTOMER ISSUE	-
DMS_03086	10130	N	N	N	1	CUSTOMER ISSUE	-
DMS_03087	10131	N	N	N	1	CUSTOMER ISSUE	-
DMS_03088	10132	N	N	N	1	CUSTOMER ISSUE	-
DMS_03089	10133	N	N	N	1	CUSTOMER ISSUE	-
DMS_03090	10134	N	N	N	1	CUSTOMER ISSUE	-
DMS_03091	10135	N	N	N	1	CUSTOMER ISSUE	-
DMS_03092	10136	N	N	N	1	CUSTOMER ISSUE	-

DMS_03093	10137	N	N	N	1	CUSTOMER ISSUE	-
DMS_03094	10138	N	N	N	1	CUSTOMER ISSUE	-
DMS_03095	10139	N	N	N	1	CUSTOMER ISSUE	-
DMS_03096	10140	N	N	N	1	CUSTOMER ISSUE	-
DMS_03098	10141	N	N	N	1	CUSTOMER ISSUE	-
DMS_03099	10142	N	N	N	1	CUSTOMER ISSUE	-
DMS_03100	10143	N	N	N	1	CUSTOMER ISSUE	-
DMS_03101	10144	N	N	N	1	CUSTOMER ISSUE	-
DMS_03102	10145	N	N	N	1	CUSTOMER ISSUE	-
DMS_03103	10146	N	N	N	1	CUSTOMER ISSUE	-
DMS_03104	10147	N	N	N	1	CUSTOMER ISSUE	-
DMS_03105	10148	N	N	N	1	CUSTOMER ISSUE	-
DMS_03106	10149	N	N	N	1	CUSTOMER ISSUE	-
DMS_03107	10150	N	N	N	1	CUSTOMER ISSUE	-
DMS_03108	10151	N	N	N	1	CUSTOMER ISSUE	-
DMS_03109	10152	N	N	N	1	CUSTOMER ISSUE	-
DMS_03110	10153	N	N	N	1	CUSTOMER ISSUE	-
DMS_03111	10154	N	N	N	1	CUSTOMER ISSUE	-
DMS_03112	10155	N	N	N	1	CUSTOMER ISSUE	-
DMS_03113	10156	N	N	N	1	CUSTOMER ISSUE	-
DMS_03114	10157	N	N	N	1	CUSTOMER ISSUE	-
DMS_03115	10158	N	N	N	1	CUSTOMER ISSUE	-
DMS_03116	10159	N	N	N	1	CUSTOMER ISSUE	-
DMS_03117	10160	N	N	N	1	CUSTOMER ISSUE	-
DMS_03118	10161	N	N	N	1	CUSTOMER ISSUE	-
DMS_03119	10162	N	N	N	1	CUSTOMER ISSUE	-
DMS_03120	10163	N	N	N	1	CUSTOMER ISSUE	-
DMS_03121	10164	N	N	N	1	CUSTOMER ISSUE	-
DMS_03122	10165	N	N	N	1	CUSTOMER ISSUE	-
DMS_03124	10166	N	N	N	1	CUSTOMER ISSUE	-
DMS_03125	10167	N	N	N	1	CUSTOMER ISSUE	-
DMS_03126	10168	N	N	N	1	CUSTOMER ISSUE	-
DMS_03127	10169	N	N	N	1	CUSTOMER ISSUE	-
DMS_03128	10170	N	N	N	1	CUSTOMER ISSUE	-
DMS_03129	10171	N	N	N	1	CUSTOMER ISSUE	-
DMS_03130	10172	N	N	N	1	CUSTOMER ISSUE	-
DMS_03131	10173	N	N	N	1	CUSTOMER ISSUE	-
DMS_03132	10174	N	N	N	1	CUSTOMER ISSUE	-
DMS_03133	10175	N	N	N	1	CUSTOMER ISSUE	-
DMS_03134	10176	N	N	N	1	CUSTOMER ISSUE	-
DMS_03135	10177	N	N	N	1	CUSTOMER ISSUE	-
DMS_03136	10178	N	N	N	1	CUSTOMER ISSUE	-
DMS_03137	10179	N	N	N	1	CUSTOMER ISSUE	-
DMS_03138	10180	N	N	N	1	CUSTOMER ISSUE	-
DMS_03139	10181	N	N	N	1	CUSTOMER ISSUE	-
DMS_03140	10182	N	N	N	1	CUSTOMER ISSUE	-
DMS_03141	10183	N	N	N	1	CUSTOMER ISSUE	-
DMS_03142	10184	N	N	N	1	CUSTOMER ISSUE	-
DMS_03143	10185	N	N	N	1	CUSTOMER ISSUE	-
DMS_03144	10186	N	N	N	1	CUSTOMER ISSUE	-
DMS_03145	10187	N	N	N	1	CUSTOMER ISSUE	-
DMS_03146	10188	N	N	N	1	CUSTOMER ISSUE	-
DMS_03147	10189	N	N	N	1	CUSTOMER ISSUE	-
DMS_03148	10190	N	N	N	1	CUSTOMER ISSUE	-
DMS_03149	10191	N	N	N	1	CUSTOMER ISSUE	-
DMS_03150	10192	N	N	N	1	CUSTOMER ISSUE	-
DMS_03151	10193	N	N	N	1	CUSTOMER ISSUE	-
DMS_03152	10194	N	N	N	1	CUSTOMER ISSUE	-
DMS_03153	10195	N	N	N	1	CUSTOMER ISSUE	-
DMS_03154	10196	N	N	N	1	CUSTOMER ISSUE	-
DMS_03155	10197	N	N	N	1	CUSTOMER ISSUE	-
DMS_03156	10198	N	N	N	1	CUSTOMER ISSUE	-
DMS_03157	10199	N	N	N	1	CUSTOMER ISSUE	-
DMS_03158	10200	N	N	N	1	CUSTOMER ISSUE	-
DMS_03159	10201	N	N	N	1	CUSTOMER ISSUE	-
DMS_03160	10202	N	N	N	1	CUSTOMER ISSUE	-
DMS_03162	10203	N	N	N	1	CUSTOMER ISSUE	-
DMS_03163	10204	N	N	N	1	CUSTOMER ISSUE	-
DMS_03164	10205	N	N	N	1	CUSTOMER ISSUE	-
DMS_03165	10206	N	N	N	1	CUSTOMER ISSUE	-
DMS_03166	10207	N	N	N	1	CUSTOMER ISSUE	-
DMS_03167	10208	N	N	N	1	CUSTOMER ISSUE	-
DMS_03168	10209	N	N	N	1	CUSTOMER ISSUE	-
DMS_03169	10210	N	N	N	1	CUSTOMER ISSUE	-
DMS_03170	10211	N	N	N	1	CUSTOMER ISSUE	-
DMS_03171	10212	N	N	N	1	CUSTOMER ISSUE	-
DMS_03172	10213	N	N	N	1	CUSTOMER ISSUE	-
DMS_03173	10214	N	N	N	1	CUSTOMER ISSUE	-
DMS_03174	10215	N	N	N	1	CUSTOMER ISSUE	-
DMS_03175	10216	N	N	N	1	CUSTOMER ISSUE	-

DMS_03176	10217	N	N	N	1	CUSTOMER ISSUE	-
DMS_03177	10218	N	N	N	1	CUSTOMER ISSUE	-
DMS_03178	10219	N	N	N	1	CUSTOMER ISSUE	-
DMS_03179	10220	N	N	N	1	CUSTOMER ISSUE	-
DMS_03180	10221	N	N	N	1	CUSTOMER ISSUE	-
DMS_03181	10222	N	N	N	1	CUSTOMER ISSUE	-
DMS_03182	10223	N	N	N	1	CUSTOMER ISSUE	-
DMS_03183	10224	N	N	N	1	CUSTOMER ISSUE	-
DMS_03184	10225	N	N	N	1	CUSTOMER ISSUE	-
DMS_03185	10226	N	N	N	1	CUSTOMER ISSUE	-
DMS_03186	10227	N	N	N	1	CUSTOMER ISSUE	-
DMS_03187	10228	N	N	N	1	CUSTOMER ISSUE	-
DMS_03188	10229	N	N	N	1	CUSTOMER ISSUE	-
DMS_03189	10230	N	N	N	1	CUSTOMER ISSUE	-
DMS_03190	10231	N	N	N	1	CUSTOMER ISSUE	-
DMS_03191	10232	N	N	N	1	CUSTOMER ISSUE	-
DMS_03192	10233	N	N	N	1	CUSTOMER ISSUE	-
DMS_03193	10234	N	N	N	1	CUSTOMER ISSUE	-
DMS_03194	10235	N	N	N	1	CUSTOMER ISSUE	-
DMS_03195	10236	N	N	N	1	CUSTOMER ISSUE	-
DMS_03196	10237	N	N	N	1	CUSTOMER ISSUE	-
DMS_03197	10238	N	N	N	1	CUSTOMER ISSUE	-
DMS_03198	10239	N	N	N	1	CUSTOMER ISSUE	-
DMS_03199	10240	N	N	N	1	CUSTOMER ISSUE	-
DMS_03200	10241	N	N	N	1	CUSTOMER ISSUE	-
DMS_03201	10242	N	N	N	1	CUSTOMER ISSUE	-
DMS_03202	10243	N	N	N	1	CUSTOMER ISSUE	-
DMS_03203	10244	N	N	N	1	CUSTOMER ISSUE	-
DMS_03204	10245	N	N	N	1	CUSTOMER ISSUE	-
DMS_03205	10246	N	N	N	1	CUSTOMER ISSUE	-
DMS_03206	10247	N	N	N	1	CUSTOMER ISSUE	-
DMS_03207	10248	N	N	N	1	CUSTOMER ISSUE	-
DMS_03208	10249	N	N	N	1	CUSTOMER ISSUE	-
DMS_03209	10250	N	N	N	1	CUSTOMER ISSUE	-
DMS_03210	10251	N	N	N	1	CUSTOMER ISSUE	-
DMS_03211	10252	N	N	N	1	CUSTOMER ISSUE	-
DMS_03212	10253	N	N	N	1	CUSTOMER ISSUE	-
DMS_03213	10254	N	N	N	1	CUSTOMER ISSUE	-
DMS_03214	10255	N	N	N	1	CUSTOMER ISSUE	-
DMS_03215	10256	N	N	N	1	CUSTOMER ISSUE	-
DMS_03216	10257	N	N	N	1	CUSTOMER ISSUE	-
DMS_03217	10258	N	N	N	1	CUSTOMER ISSUE	-
DMS_03218	10259	N	N	N	1	CUSTOMER ISSUE	-
DMS_03219	10260	N	N	N	1	CUSTOMER ISSUE	-
DMS_03220	10261	N	N	N	1	CUSTOMER ISSUE	-
DMS_03221	10262	N	N	N	1	CUSTOMER ISSUE	-
DMS_03222	10263	N	N	N	1	CUSTOMER ISSUE	-
DMS_03223	10264	N	N	N	1	CUSTOMER ISSUE	-
DMS_03224	10265	N	N	N	1	CUSTOMER ISSUE	-
DMS_03225	10266	N	N	N	1	CUSTOMER ISSUE	-
DMS_03226	10267	N	N	N	1	CUSTOMER ISSUE	-
DMS_03227	10268	N	N	N	1	CUSTOMER ISSUE	-
DMS_03228	10269	N	N	N	1	CUSTOMER ISSUE	-
DMS_03229	10270	N	N	N	1	CUSTOMER ISSUE	-
DMS_03230	10271	N	N	N	1	CUSTOMER ISSUE	-
DMS_03231	10272	N	N	N	1	CUSTOMER ISSUE	-
DMS_03232	10273	N	N	N	1	CUSTOMER ISSUE	-
DMS_03233	10274	N	N	N	1	CUSTOMER ISSUE	-
DMS_03234	10275	N	N	N	1	CUSTOMER ISSUE	-
DMS_03236	10276	N	N	N	1	CUSTOMER ISSUE	-
DMS_03237	10277	N	N	N	1	CUSTOMER ISSUE	-
DMS_03238	10278	N	N	N	1	CUSTOMER ISSUE	-
DMS_03239	10279	N	N	N	1	CUSTOMER ISSUE	-
DMS_03240	10280	N	N	N	1	CUSTOMER ISSUE	-
DMS_03241	10281	N	N	N	1	CUSTOMER ISSUE	-
DMS_03242	10282	N	N	N	1	CUSTOMER ISSUE	-
DMS_03243	10283	N	N	N	1	CUSTOMER ISSUE	-
DMS_03244	10284	N	N	N	1	CUSTOMER ISSUE	-
DMS_03245	10285	N	N	N	1	CUSTOMER ISSUE	-
DMS_03246	10286	N	N	N	1	CUSTOMER ISSUE	-
DMS_03247	10287	N	N	N	1	CUSTOMER ISSUE	-
DMS_03248	10288	N	N	N	1	CUSTOMER ISSUE	-
DMS_03249	10289	N	N	N	1	CUSTOMER ISSUE	-
DMS_03250	10290	N	N	N	1	CUSTOMER ISSUE	-
DMS_03251	10291	N	N	N	1	CUSTOMER ISSUE	-
DMS_03252	10292	N	N	N	1	CUSTOMER ISSUE	-
DMS_03253	10293	N	N	N	1	CUSTOMER ISSUE	-
DMS_03254	10294	N	N	N	1	CUSTOMER ISSUE	-
DMS_03255	10295	N	N	N	1	CUSTOMER ISSUE	-
DMS_03256	10296	N	N	N	1	CUSTOMER ISSUE	-

DMS_03257	10297	N	N	N	1	CUSTOMER ISSUE	-
DMS_03258	10298	N	N	N	1	CUSTOMER ISSUE	-
DMS_03259	10299	N	N	N	1	CUSTOMER ISSUE	-
DMS_03260	10300	N	N	N	1	CUSTOMER ISSUE	-
DMS_03261	10301	N	N	N	1	CUSTOMER ISSUE	-
DMS_03262	10302	N	N	N	1	CUSTOMER ISSUE	-
DMS_03264	10303	N	N	N	1	CUSTOMER ISSUE	-
DMS_03265	10304	N	N	N	1	CUSTOMER ISSUE	-
DMS_03266	10305	N	N	N	1	CUSTOMER ISSUE	-
DMS_03267	10306	N	N	N	1	CUSTOMER ISSUE	-
DMS_03268	10307	N	N	N	1	CUSTOMER ISSUE	-
DMS_03269	10308	N	N	N	1	CUSTOMER ISSUE	-
DMS_03270	10309	N	N	N	1	CUSTOMER ISSUE	-
DMS_03271	10310	N	N	N	1	CUSTOMER ISSUE	-
DMS_03272	10311	N	N	N	1	CUSTOMER ISSUE	-
DMS_03273	10312	N	N	N	1	CUSTOMER ISSUE	-
DMS_03274	10313	N	N	N	1	CUSTOMER ISSUE	-
DMS_03275	10314	N	N	N	1	CUSTOMER ISSUE	-
DMS_03276	10315	N	N	N	1	CUSTOMER ISSUE	-
DMS_03277	10316	N	N	N	1	CUSTOMER ISSUE	-
DMS_03278	10317	N	N	N	1	CUSTOMER ISSUE	-
DMS_03279	10318	N	N	N	1	CUSTOMER ISSUE	-
DMS_03280	10319	N	N	N	1	CUSTOMER ISSUE	-
DMS_03281	10320	N	N	N	1	CUSTOMER ISSUE	-
DMS_03282	10321	N	N	N	1	CUSTOMER ISSUE	-
DMS_03283	10322	N	N	N	1	CUSTOMER ISSUE	-
DMS_03284	10323	N	N	N	1	CUSTOMER ISSUE	-
DMS_03285	10324	N	N	N	1	CUSTOMER ISSUE	-
DMS_03286	10325	N	N	N	1	CUSTOMER ISSUE	-
DMS_03287	10326	N	N	N	1	CUSTOMER ISSUE	-
DMS_03288	10327	N	N	N	1	CUSTOMER ISSUE	-
DMS_03289	10328	N	N	N	1	CUSTOMER ISSUE	-
DMS_03290	10329	N	N	N	1	CUSTOMER ISSUE	-
DMS_03291	10330	N	N	N	1	CUSTOMER ISSUE	-
DMS_03292	10331	N	N	N	1	CUSTOMER ISSUE	-
DMS_03293	10332	N	N	N	1	CUSTOMER ISSUE	-
DMS_03294	10333	N	N	N	1	CUSTOMER ISSUE	-
DMS_03295	10334	N	N	N	1	CUSTOMER ISSUE	-
DMS_03296	10335	N	N	N	1	CUSTOMER ISSUE	-
DMS_03297	10336	N	N	N	1	CUSTOMER ISSUE	-
DMS_03298	10337	N	N	N	1	CUSTOMER ISSUE	-
DMS_03299	10338	N	N	N	1	CUSTOMER ISSUE	-
DMS_03300	10339	N	N	N	1	CUSTOMER ISSUE	-
DMS_03301	10340	N	N	N	1	CUSTOMER ISSUE	-
DMS_03302	10341	N	N	N	1	CUSTOMER ISSUE	-
DMS_03303	10342	N	N	N	1	CUSTOMER ISSUE	-
DMS_03304	10343	N	N	N	1	CUSTOMER ISSUE	-
DMS_03305	10344	N	N	N	1	CUSTOMER ISSUE	-
DMS_03306	10345	N	N	N	1	CUSTOMER ISSUE	-
DMS_03307	10346	N	N	N	1	CUSTOMER ISSUE	-
DMS_03308	10347	N	N	N	1	CUSTOMER ISSUE	-
DMS_03309	10348	N	N	N	1	CUSTOMER ISSUE	-
DMS_03310	10349	N	N	N	1	CUSTOMER ISSUE	-
DMS_03311	10350	N	N	N	1	CUSTOMER ISSUE	-
DMS_03312	10351	N	N	N	1	CUSTOMER ISSUE	-
DMS_03313	10352	N	N	N	1	CUSTOMER ISSUE	-
DMS_03314	10353	N	N	N	1	CUSTOMER ISSUE	-
DMS_03315	10354	N	N	N	1	CUSTOMER ISSUE	-
DMS_03316	10355	N	N	N	1	CUSTOMER ISSUE	-
DMS_03317	10356	N	N	N	1	CUSTOMER ISSUE	-
DMS_03318	10357	N	N	N	1	CUSTOMER ISSUE	-
DMS_03319	10358	N	N	N	1	CUSTOMER ISSUE	-
DMS_03320	10359	N	N	N	1	CUSTOMER ISSUE	-
DMS_03321	10360	N	N	N	1	CUSTOMER ISSUE	-
DMS_03322	10361	N	N	N	1	CUSTOMER ISSUE	-
DMS_03323	10362	N	N	N	1	CUSTOMER ISSUE	-
DMS_03324	10363	N	N	N	1	CUSTOMER ISSUE	-
DMS_03325	10364	N	N	N	1	CUSTOMER ISSUE	-
DMS_03326	10365	N	N	N	1	CUSTOMER ISSUE	-
DMS_03327	10366	N	N	N	1	CUSTOMER ISSUE	-
DMS_03328	10367	N	N	N	1	CUSTOMER ISSUE	-
DMS_03329	10368	N	N	N	1	CUSTOMER ISSUE	-
DMS_03330	10369	N	N	N	1	CUSTOMER ISSUE	-
DMS_03331	10370	N	N	N	1	CUSTOMER ISSUE	-
DMS_03332	10371	N	N	N	1	CUSTOMER ISSUE	-
DMS_03333	10372	N	N	N	1	CUSTOMER ISSUE	-
DMS_03334	10373	N	N	N	1	CUSTOMER ISSUE	-
DMS_03335	10374	N	N	N	1	CUSTOMER ISSUE	-
DMS_03336	10375	N	N	N	1	CUSTOMER ISSUE	-
DMS_03337	10376	N	N	N	1	CUSTOMER ISSUE	-

DMS_03338	10377	N	N	N	1	CUSTOMER ISSUE	-
DMS_03339	10378	N	N	N	1	CUSTOMER ISSUE	-
DMS_03340	10379	N	N	N	1	CUSTOMER ISSUE	-
DMS_03341	10380	N	N	N	1	CUSTOMER ISSUE	-
DMS_03342	10381	N	N	N	1	CUSTOMER ISSUE	-
DMS_03343	10382	N	N	N	1	CUSTOMER ISSUE	-
DMS_03344	10383	N	N	N	1	CUSTOMER ISSUE	-
DMS_03345	10384	N	N	N	1	CUSTOMER ISSUE	-
DMS_03346	10385	N	N	N	1	CUSTOMER ISSUE	-
DMS_03347	10386	N	N	N	1	CUSTOMER ISSUE	-
DMS_03348	10387	N	N	N	1	CUSTOMER ISSUE	-
DMS_03349	10388	N	N	N	1	CUSTOMER ISSUE	-
DMS_03350	10389	N	N	N	1	CUSTOMER ISSUE	-
DMS_03351	10390	N	N	N	1	CUSTOMER ISSUE	-
DMS_03352	10391	N	N	N	1	CUSTOMER ISSUE	-
DMS_03353	10392	N	N	N	1	CUSTOMER ISSUE	-
DMS_03354	10393	N	N	N	1	CUSTOMER ISSUE	-
DMS_03355	10394	N	N	N	1	CUSTOMER ISSUE	-
DMS_03356	10395	N	N	N	1	CUSTOMER ISSUE	-
DMS_03357	10396	N	N	N	1	CUSTOMER ISSUE	-
DMS_03358	10397	N	N	N	1	CUSTOMER ISSUE	-
DMS_03359	10398	N	N	N	1	CUSTOMER ISSUE	-
DMS_03360	10399	N	N	N	1	CUSTOMER ISSUE	-
DMS_03361	10400	N	N	N	1	CUSTOMER ISSUE	-
DMS_03362	10401	N	N	N	1	CUSTOMER ISSUE	-
DMS_03363	10402	N	N	N	1	CUSTOMER ISSUE	-
DMS_03364	10403	N	N	N	1	CUSTOMER ISSUE	-
DMS_03365	10404	N	N	N	1	CUSTOMER ISSUE	-
DMS_03366	10405	N	N	N	1	CUSTOMER ISSUE	-
DMS_03367	10406	N	N	N	1	CUSTOMER ISSUE	-
DMS_03368	10407	N	N	N	1	CUSTOMER ISSUE	-
DMS_03369	10408	N	N	N	1	CUSTOMER ISSUE	-
DMS_03370	10409	N	N	N	1	CUSTOMER ISSUE	-
DMS_03371	10410	N	N	N	1	CUSTOMER ISSUE	-
DMS_03372	10411	N	N	N	1	CUSTOMER ISSUE	-
DMS_03373	10412	N	N	N	1	CUSTOMER ISSUE	-
DMS_03374	10413	N	N	N	1	CUSTOMER ISSUE	-
DMS_03375	10414	N	N	N	1	CUSTOMER ISSUE	-
DMS_03376	10415	N	N	N	1	CUSTOMER ISSUE	-
DMS_03377	10416	N	N	N	1	CUSTOMER ISSUE	-
DMS_03378	10417	N	N	N	1	CUSTOMER ISSUE	-
DMS_03379	10418	N	N	N	1	CUSTOMER ISSUE	-
DMS_03380	10419	N	N	N	1	CUSTOMER ISSUE	-
DMS_03381	10420	N	N	N	1	CUSTOMER ISSUE	-
DMS_03382	10421	N	N	N	1	CUSTOMER ISSUE	-
DMS_03383	10422	N	N	N	1	CUSTOMER ISSUE	-
DMS_03384	10423	N	N	N	1	CUSTOMER ISSUE	-
DMS_03385	10424	N	N	N	1	CUSTOMER ISSUE	-
DMS_03386	10425	N	N	N	1	CUSTOMER ISSUE	-
DMS_03388	10426	N	N	N	1	CUSTOMER ISSUE	-
DMS_03389	10427	N	N	N	1	CUSTOMER ISSUE	-
DMS_03390	10428	N	N	N	1	CUSTOMER ISSUE	-
DMS_03391	10429	N	N	N	1	CUSTOMER ISSUE	-
DMS_03392	10430	N	N	N	1	CUSTOMER ISSUE	-
DMS_03393	10431	N	N	N	1	CUSTOMER ISSUE	-
DMS_03394	10432	N	N	N	1	CUSTOMER ISSUE	-
DMS_03395	10433	N	N	N	1	CUSTOMER ISSUE	-
DMS_03396	10434	N	N	N	1	CUSTOMER ISSUE	-
DMS_03397	10435	N	N	N	1	CUSTOMER ISSUE	-
DMS_03398	10436	N	N	N	1	CUSTOMER ISSUE	-
DMS_03399	10437	N	N	N	1	CUSTOMER ISSUE	-
DMS_03400	10438	N	N	N	1	CUSTOMER ISSUE	-
DMS_03401	10439	N	N	N	1	CUSTOMER ISSUE	-
DMS_03402	10440	N	N	N	1	CUSTOMER ISSUE	-
DMS_03403	10441	N	N	N	1	CUSTOMER ISSUE	-
DMS_03404	10442	N	N	N	1	CUSTOMER ISSUE	-
DMS_03405	10443	N	N	N	1	CUSTOMER ISSUE	-
DMS_03406	10444	N	N	N	1	CUSTOMER ISSUE	-
DMS_03407	10445	N	N	N	1	CUSTOMER ISSUE	-
DMS_03408	10446	N	N	N	1	CUSTOMER ISSUE	-
DMS_03409	10447	N	N	N	1	CUSTOMER ISSUE	-
DMS_03410	10448	N	N	N	1	CUSTOMER ISSUE	-
DMS_03411	10449	N	N	N	1	CUSTOMER ISSUE	-
DMS_03412	10450	N	N	N	1	CUSTOMER ISSUE	-
DMS_03413	10451	N	N	N	1	CUSTOMER ISSUE	-
DMS_03414	10452	N	N	N	1	CUSTOMER ISSUE	-
DMS_03415	10453	N	N	N	1	CUSTOMER ISSUE	-
DMS_03416	10454	N	N	N	1	CUSTOMER ISSUE	-
DMS_03417	10455	N	N	N	1	CUSTOMER ISSUE	-
DMS_03418	10456	N	N	N	1	CUSTOMER ISSUE	-

DMS_03419	10457	N	N	N	1	CUSTOMER ISSUE	-
DMS_03420	10458	N	N	N	1	CUSTOMER ISSUE	-
DMS_03421	10459	N	N	N	1	CUSTOMER ISSUE	-
DMS_03422	10460	N	N	N	1	CUSTOMER ISSUE	-
DMS_03423	10461	N	N	N	1	CUSTOMER ISSUE	-
DMS_03424	10462	N	N	N	1	CUSTOMER ISSUE	-
DMS_03425	10463	N	N	N	1	CUSTOMER ISSUE	-
DMS_03426	10464	N	N	N	1	CUSTOMER ISSUE	-
DMS_03427	10465	N	N	N	1	CUSTOMER ISSUE	-
DMS_03428	10466	N	N	N	1	CUSTOMER ISSUE	-
DMS_03429	10467	N	N	N	1	CUSTOMER ISSUE	-
DMS_03430	10468	N	N	N	1	CUSTOMER ISSUE	-
DMS_03431	10469	N	N	N	1	CUSTOMER ISSUE	-
DMS_03432	10470	N	N	N	1	CUSTOMER ISSUE	-
DMS_03433	10471	N	N	N	1	CUSTOMER ISSUE	-
DMS_03434	10472	N	N	N	1	CUSTOMER ISSUE	-
DMS_03435	10473	N	N	N	1	CUSTOMER ISSUE	-
DMS_03436	10474	N	N	N	1	CUSTOMER ISSUE	-
DMS_03437	10475	N	N	N	1	CUSTOMER ISSUE	-
DMS_03438	10476	N	N	N	1	CUSTOMER ISSUE	-
DMS_03439	10477	N	N	N	1	CUSTOMER ISSUE	-
DMS_03440	10478	N	N	N	1	CUSTOMER ISSUE	-
DMS_03441	10479	N	N	N	1	CUSTOMER ISSUE	-
DMS_03442	10480	N	N	N	1	CUSTOMER ISSUE	-
DMS_03443	10481	N	N	N	1	CUSTOMER ISSUE	-
DMS_03444	10482	N	N	N	1	CUSTOMER ISSUE	-
DMS_03445	10483	N	N	N	1	CUSTOMER ISSUE	-
DMS_03446	10484	N	N	N	1	CUSTOMER ISSUE	-
DMS_03447	10485	N	N	N	1	CUSTOMER ISSUE	-
DMS_03448	10486	N	N	N	1	CUSTOMER ISSUE	-
DMS_03449	10487	N	N	N	1	CUSTOMER ISSUE	-
DMS_03450	10488	N	N	N	1	CUSTOMER ISSUE	-
DMS_03451	10489	N	N	N	1	CUSTOMER ISSUE	-
DMS_03452	10490	N	N	N	1	CUSTOMER ISSUE	-
DMS_03453	10491	N	N	N	1	CUSTOMER ISSUE	-
DMS_03454	10492	N	N	N	1	CUSTOMER ISSUE	-
DMS_03455	10493	N	N	N	1	CUSTOMER ISSUE	-
DMS_03456	10494	N	N	N	1	CUSTOMER ISSUE	-
DMS_03457	10495	N	N	N	1	CUSTOMER ISSUE	-
DMS_03458	10496	N	N	N	1	CUSTOMER ISSUE	-
DMS_03459	10497	N	N	N	1	CUSTOMER ISSUE	-
DMS_03460	10498	N	N	N	1	CUSTOMER ISSUE	-
DMS_03461	10499	N	N	N	1	CUSTOMER ISSUE	-
DMS_03462	10500	N	N	N	1	CUSTOMER ISSUE	-
DMS_03464	10501	N	N	N	1	CUSTOMER ISSUE	-
DMS_03465	10502	N	N	N	1	CUSTOMER ISSUE	-
DMS_03466	10503	N	N	N	1	CUSTOMER ISSUE	-
DMS_03467	10504	N	N	N	1	CUSTOMER ISSUE	-
DMS_03468	10505	N	N	N	1	CUSTOMER ISSUE	-
DMS_03469	10506	N	N	N	1	CUSTOMER ISSUE	-
DMS_03470	10507	N	N	N	1	CUSTOMER ISSUE	-
DMS_03471	10508	N	N	N	1	CUSTOMER ISSUE	-
DMS_03472	10509	N	N	N	1	CUSTOMER ISSUE	-
DMS_03473	10510	N	N	N	1	CUSTOMER ISSUE	-
DMS_03474	10511	N	N	N	1	CUSTOMER ISSUE	-
DMS_03475	10512	N	N	N	1	CUSTOMER ISSUE	-
DMS_03476	10513	N	N	N	1	CUSTOMER ISSUE	-
DMS_03477	10514	N	N	N	1	CUSTOMER ISSUE	-
DMS_03478	10515	N	N	N	1	CUSTOMER ISSUE	-
DMS_03479	10516	N	N	N	1	CUSTOMER ISSUE	-
DMS_03480	10517	N	N	N	1	CUSTOMER ISSUE	-
DMS_03481	10518	N	N	N	1	CUSTOMER ISSUE	-
DMS_03482	10519	N	N	N	1	CUSTOMER ISSUE	-
DMS_03483	10520	N	N	N	1	CUSTOMER ISSUE	-
DMS_03484	10521	N	N	N	1	CUSTOMER ISSUE	-
DMS_03485	10522	N	N	N	1	CUSTOMER ISSUE	-
DMS_03486	10523	N	N	N	1	CUSTOMER ISSUE	-
DMS_03487	10524	N	N	N	1	CUSTOMER ISSUE	-
DMS_03488	10525	N	N	N	1	CUSTOMER ISSUE	-
DMS_03489	10526	N	N	N	1	CUSTOMER ISSUE	-
DMS_03490	10527	N	N	N	1	CUSTOMER ISSUE	-
DMS_03491	10528	N	N	N	1	CUSTOMER ISSUE	-
DMS_03492	10529	N	N	N	1	CUSTOMER ISSUE	-
DMS_03493	10530	N	N	N	1	CUSTOMER ISSUE	-
DMS_03494	10531	N	N	N	1	CUSTOMER ISSUE	-
DMS_03495	10532	N	N	N	1	CUSTOMER ISSUE	-
DMS_03496	10533	N	N	N	1	CUSTOMER ISSUE	-
DMS_03497	10534	N	N	N	1	CUSTOMER ISSUE	-
DMS_03498	10535	N	N	N	1	CUSTOMER ISSUE	-
DMS_03499	10536	N	N	N	1	CUSTOMER ISSUE	-

DMS_03500	10537	N	N	N	1	CUSTOMER ISSUE	-
DMS_03501	10538	N	N	N	1	CUSTOMER ISSUE	-
DMS_03502	10539	N	N	N	1	CUSTOMER ISSUE	-
DMS_03503	10540	N	N	N	1	CUSTOMER ISSUE	-
DMS_03504	10541	N	N	N	1	CUSTOMER ISSUE	-
DMS_03505	10542	N	N	N	1	CUSTOMER ISSUE	-
DMS_03506	10543	N	N	N	1	CUSTOMER ISSUE	-
DMS_03507	10544	N	N	N	1	CUSTOMER ISSUE	-
DMS_03508	10545	N	N	N	1	CUSTOMER ISSUE	-
DMS_03509	10546	N	N	N	1	CUSTOMER ISSUE	-
DMS_03510	10547	N	N	N	1	CUSTOMER ISSUE	-
DMS_03512	10548	N	N	N	1	CUSTOMER ISSUE	-
DMS_03513	10549	N	N	N	1	CUSTOMER ISSUE	-
DMS_03514	10550	N	N	N	1	CUSTOMER ISSUE	-
DMS_03515	10551	N	N	N	1	CUSTOMER ISSUE	-
DMS_03516	10552	N	N	N	1	CUSTOMER ISSUE	-
DMS_03517	10553	N	N	N	1	CUSTOMER ISSUE	-
DMS_03518	10554	N	N	N	1	CUSTOMER ISSUE	-
DMS_03519	10555	N	N	N	1	CUSTOMER ISSUE	-
DMS_03520	10556	N	N	N	1	CUSTOMER ISSUE	-
DMS_03521	10557	N	N	N	1	CUSTOMER ISSUE	-
DMS_03522	10558	N	N	N	1	CUSTOMER ISSUE	-
DMS_03523	10559	N	N	N	1	CUSTOMER ISSUE	-
DMS_03524	10560	N	N	N	1	CUSTOMER ISSUE	-
DMS_03525	10561	N	N	N	1	CUSTOMER ISSUE	-
DMS_03526	10562	N	N	N	1	CUSTOMER ISSUE	-
DMS_03527	10563	N	N	N	1	CUSTOMER ISSUE	-
DMS_03528	10564	N	N	N	1	CUSTOMER ISSUE	-
DMS_03529	10565	N	N	N	1	CUSTOMER ISSUE	-
DMS_03530	10566	N	N	N	1	CUSTOMER ISSUE	-
DMS_03531	10567	N	N	N	1	CUSTOMER ISSUE	-
DMS_03532	10568	N	N	N	1	CUSTOMER ISSUE	-
DMS_03533	10569	N	N	N	1	CUSTOMER ISSUE	-
DMS_03535	10570	N	N	N	1	CUSTOMER ISSUE	-
DMS_03536	10571	N	N	N	1	CUSTOMER ISSUE	-
DMS_03537	10572	N	N	N	1	CUSTOMER ISSUE	-
DMS_03538	10573	N	N	N	1	CUSTOMER ISSUE	-
DMS_03539	10574	N	N	N	1	CUSTOMER ISSUE	-
DMS_03540	10575	N	N	N	1	CUSTOMER ISSUE	-
DMS_03541	10576	N	N	N	1	CUSTOMER ISSUE	-
DMS_03542	10577	N	N	N	1	CUSTOMER ISSUE	-
DMS_03543	10578	N	N	N	1	CUSTOMER ISSUE	-
DMS_03544	10579	N	N	N	1	CUSTOMER ISSUE	-
DMS_03545	10580	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_03547	10581	N	N	N	1	CUSTOMER ISSUE	-
DMS_03548	10582	N	N	N	1	CUSTOMER ISSUE	-
DMS_03549	10583	N	N	N	1	CUSTOMER ISSUE	-
DMS_03550	10584	N	N	N	1	CUSTOMER ISSUE	-
DMS_03551	10585	N	N	N	1	CUSTOMER ISSUE	-
DMS_03552	10586	N	N	N	1	CUSTOMER ISSUE	-
DMS_03553	10587	N	N	N	1	CUSTOMER ISSUE	-
DMS_03554	10588	N	N	N	1	CUSTOMER ISSUE	-
DMS_03555	10589	N	N	N	1	CUSTOMER ISSUE	-
DMS_03556	10590	N	N	N	1	CUSTOMER ISSUE	-
DMS_03557	10591	N	N	N	2	CUSTOMER ISSUE	-
DMS_03558	10592	N	N	N	1	CUSTOMER ISSUE	-
DMS_03559	10593	N	N	N	1	CUSTOMER ISSUE	-
DMS_03560	10594	N	N	N	1	CUSTOMER ISSUE	-
DMS_03561	10595	N	N	N	1	CUSTOMER ISSUE	-
DMS_03562	10596	N	N	N	1	CUSTOMER ISSUE	-
DMS_03563	10597	N	N	Y	1	TX - REPLACE	2500
DMS_03564	10598	N	N	N	1	CUSTOMER ISSUE	-
DMS_03565	10599	N	N	N	1	CUSTOMER ISSUE	-
DMS_03566	10600	N	N	N	1	CUSTOMER ISSUE	-
DMS_03567	10601	N	N	N	1	CUSTOMER ISSUE	-
DMS_03568	10602	N	N	N	1	CUSTOMER ISSUE	-
DMS_03569	10603	N	N	N	1	CUSTOMER ISSUE	-
DMS_03571	10604	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03572	10605	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03573	10606	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03575	10607	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03576	10608	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03577	10609	N	N	N	1	CUSTOMER ISSUE	-
DMS_03578	10610	N	N	N	1	CUSTOMER ISSUE	-
DMS_03579	10611	N	N	N	1	CUSTOMER ISSUE	-
DMS_03580	10612	N	N	N	1	CUSTOMER ISSUE	-
DMS_03581	10613	N	N	N	1	CUSTOMER ISSUE	-
DMS_03582	10614	N	N	N	1	CUSTOMER ISSUE	-
DMS_03583	10615	N	N	N	1	CUSTOMER ISSUE	-
DMS_03584	10616	N	N	N	1	CUSTOMER ISSUE	-

DMS_03585	10617	N	N	N	1	CUSTOMER ISSUE	-
DMS_03586	10618	N	N	N	1	CUSTOMER ISSUE	-
DMS_03587	10619	N	N	N	1	CUSTOMER ISSUE	-
DMS_03588	10620	N	N	N	1	CUSTOMER ISSUE	-
DMS_03589	10621	N	N	N	1	CUSTOMER ISSUE	-
DMS_03590	10622	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03591	10623	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03592	10624	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03593	10625	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03594	10626	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03598	10627	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_03599	10628	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03600	10629	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03601	10630	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03602	10631	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03603	10632	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03604	10633	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03605	10634	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03606	10635	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03607	10636	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03608	10637	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03609	10638	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03612	10639	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03617	10640	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03618	10641	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03619	10642	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03620	10643	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03621	10644	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03622	10645	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03623	10646	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03624	10647	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03625	10648	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03626	10649	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03627	10650	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03628	10651	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03629	10652	N	N	N	1	CUSTOMER ISSUE	-
DMS_03630	10653	N	N	N	1	CUSTOMER ISSUE	-
DMS_03631	10654	N	N	N	1	CUSTOMER ISSUE	-
DMS_03632	10655	N	N	N	1	CUSTOMER ISSUE	-
DMS_03633	10656	N	N	N	2	CUSTOMER ISSUE	-
DMS_03634	10657	N	N	N	2	CUSTOMER ISSUE	-
DMS_03635	10658	N	N	N	1	CUSTOMER ISSUE	-
DMS_03636	10659	N	N	N	1	CUSTOMER ISSUE	-
DMS_03637	10660	N	N	N	1	CUSTOMER ISSUE	-
DMS_03638	10661	N	N	N	1	CUSTOMER ISSUE	-
DMS_03639	10662	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_03640	10663	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_03641	10664	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_03642	10665	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03644	10666	N	N	N	1	CUSTOMER ISSUE	-
DMS_03645	10667	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_03646	10668	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_03647	10669	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_03648	10670	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_03649	10671	N	N	N	1	CUSTOMER ISSUE	-
DMS_03651	10672	N	N	N	1	CUSTOMER ISSUE	-
DMS_03652	10673	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03653	10674	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_03654	10675	N	N	N	1	CUSTOMER ISSUE	-
DMS_03655	10676	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03656	10677	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03657	10678	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03658	10679	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03659	10680	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03660	10681	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03661	10682	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03662	10683	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03663	10684	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03664	10685	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03665	10686	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_03666	10687	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03667	10688	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03668	10689	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03669	10690	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03670	10691	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03671	10692	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03672	10693	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03674	10694	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03675	10695	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03676	10696	N	N	Y	1	DIST - REPLACE FUSE	708.75

DMS_03677	10697	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03678	10698	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03679	10699	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03680	10700	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03681	10701	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03682	10702	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03683	10703	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03684	10704	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03685	10705	N	N	Y	3	SEC/SVC - REPLACE	708.75
DMS_03686	10706	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03687	10707	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03688	10708	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03689	10709	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03690	10710	N	N	N	1	CUSTOMER ISSUE	-
DMS_03691	10711	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03692	10712	N	N	N	1	CUSTOMER ISSUE	-
DMS_03695	10713	N	N	N	1	CUSTOMER ISSUE	-
DMS_03696	10714	N	N	N	1	CUSTOMER ISSUE	-
DMS_03698	10715	N	N	N	1	CUSTOMER ISSUE	-
DMS_03699	10716	N	N	N	1	CUSTOMER ISSUE	-
DMS_03700	10717	N	N	N	1	CUSTOMER ISSUE	-
DMS_03701	10718	N	N	N	1	CUSTOMER ISSUE	-
DMS_03702	10719	N	N	N	1	CUSTOMER ISSUE	-
DMS_03703	10720	N	N	N	1	CUSTOMER ISSUE	-
DMS_03704	10721	N	N	N	1	CUSTOMER ISSUE	-
DMS_03705	10722	N	N	N	1	CUSTOMER ISSUE	-
DMS_03708	10723	N	N	N	1	CUSTOMER ISSUE	-
DMS_03710	10724	N	N	N	1	CUSTOMER ISSUE	-
DMS_03712	10725	N	N	N	1	CUSTOMER ISSUE	-
DMS_03717	10726	N	N	N	1	CUSTOMER ISSUE	-
DMS_03718	10727	N	N	N	2	CUSTOMER ISSUE	-
DMS_03719	10728	N	N	N	1	CUSTOMER ISSUE	-
DMS_03720	10729	N	N	N	1	CUSTOMER ISSUE	-
DMS_03721	10730	N	N	N	1	CUSTOMER ISSUE	-
DMS_03723	10731	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03724	10732	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03725	10733	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03726	10734	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_03727	10735	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03728	10736	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03729	10737	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03730	10738	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03731	10739	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03732	10740	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03733	10741	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03734	10742	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03735	10743	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03736	10744	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03737	10745	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03738	10746	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03739	10747	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03740	10748	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03741	10749	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03742	10750	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03743	10751	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03744	10752	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03745	10753	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03746	10754	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03747	10755	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03748	10756	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03749	10757	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03750	10758	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03751	10759	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03752	10760	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03753	10761	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03754	10762	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03755	10763	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03756	10764	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03757	10765	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03758	10766	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03759	10767	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03760	10768	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03761	10769	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03762	10770	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03763	10771	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03764	10772	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03765	10773	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03766	10774	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03767	10775	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03768	10776	N	N	N	1	CUSTOMER ISSUE	-

DMS_03769	10777	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03770	10778	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03771	10779	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03772	10780	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03773	10781	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_03774	10782	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03775	10783	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03776	10784	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03777	10785	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03778	10786	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03779	10787	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03780	10788	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03781	10789	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03782	10790	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03783	10791	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03784	10792	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03785	10793	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03786	10794	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03787	10795	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03788	10796	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03789	10797	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03790	10798	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03791	10799	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03792	10800	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_03793	10801	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03794	10802	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03795	10803	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03796	10804	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03797	10805	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03798	10806	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03799	10807	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03800	10808	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03801	10809	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03802	10810	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03803	10811	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_03804	10812	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03805	10813	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03806	10814	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03807	10815	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03808	10816	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03809	10817	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03810	10818	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03811	10819	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03812	10820	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03813	10821	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03814	10822	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03815	10823	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03816	10824	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03817	10825	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03818	10826	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03819	10827	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03820	10828	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03821	10829	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03822	10830	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03823	10831	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03824	10832	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03825	10833	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03826	10834	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03827	10835	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03828	10836	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03829	10837	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03830	10838	N	N	N	1	CUSTOMER ISSUE	-
DMS_03831	10839	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03832	10840	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03833	10841	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03834	10842	N	N	N	1	CUSTOMER ISSUE	-
DMS_03835	10843	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03836	10844	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03837	10845	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03838	10846	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03839	10847	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03840	10848	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03841	10849	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03842	10850	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03843	10851	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03844	10852	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03845	10853	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03846	10854	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03847	10855	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03848	10856	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_03849	10857	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03850	10858	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03851	10859	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03852	10860	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03853	10861	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03854	10862	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03855	10863	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03856	10864	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03857	10865	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03858	10866	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03859	10867	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03860	10868	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03861	10869	N	N	N	1	CUSTOMER ISSUE	-
DMS_03862	10870	N	N	N	1	CUSTOMER ISSUE	-
DMS_03863	10871	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03864	10872	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03865	10873	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03866	10874	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03867	10875	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03868	10876	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03869	10877	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03870	10878	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03871	10879	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03872	10880	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03873	10881	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03874	10882	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03875	10883	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03876	10884	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03877	10885	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03878	10886	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03879	10887	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03880	10888	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03881	10889	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03882	10890	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03883	10891	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03884	10892	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03885	10893	N	N	N	1	CUSTOMER ISSUE	-
DMS_03886	10894	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03887	10895	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03888	10896	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03889	10897	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03890	10898	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03891	10899	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03892	10900	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03893	10901	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03894	10902	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03895	10903	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03896	10904	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03897	10905	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03898	10906	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03899	10907	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03900	10908	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_03901	10909	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03902	10910	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03903	10911	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03904	10912	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03905	10913	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03906	10914	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03907	10915	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03908	10916	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_03909	10917	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03910	10918	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03911	10919	N	N	N	1	CUSTOMER ISSUE	-
DMS_03912	10920	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03913	10921	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03914	10922	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03915	10923	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03916	10924	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03917	10925	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03918	10926	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03919	10927	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03920	10928	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03921	10929	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03922	10930	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03923	10931	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03924	10932	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03925	10933	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03926	10934	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03927	10935	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03928	10936	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_03929	10937	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03930	10938	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03931	10939	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03932	10940	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03933	10941	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03934	10942	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03935	10943	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03936	10944	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03937	10945	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03938	10946	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03939	10947	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03940	10948	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03941	10949	N	N	N	1	CUSTOMER ISSUE	-
DMS_03942	10950	N	N	N	1	CUSTOMER ISSUE	-
DMS_03943	10951	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03944	10952	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03945	10953	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03946	10954	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03947	10955	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03948	10956	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03949	10957	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03950	10958	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03951	10959	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03952	10960	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03953	10961	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03954	10962	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03955	10963	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03956	10964	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03957	10965	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03958	10966	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03959	10967	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03960	10968	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03961	10969	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03962	10970	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03963	10971	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03964	10972	N	N	N	1	CUSTOMER ISSUE	-
DMS_03965	10973	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03966	10974	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03967	10975	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03968	10976	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03969	10977	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03970	10978	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03971	10979	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03972	10980	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03973	10981	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03974	10982	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_03975	10983	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03976	10984	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03980	10985	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03981	10986	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03987	10987	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03989	10988	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_03991	10989	N	N	N	1	CUSTOMER ISSUE	-
DMS_03992	10990	N	N	N	1	CUSTOMER ISSUE	-
DMS_03993	10991	N	N	N	1	CUSTOMER ISSUE	-
DMS_03995	10992	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04000	10993	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04001	10994	N	N	N	1	CUSTOMER ISSUE	-
DMS_04002	10995	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04003	10996	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04004	10997	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04005	10998	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04008	10999	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04009	11000	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04010	11001	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04011	11002	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04012	11003	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04013	11004	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04015	11005	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04016	11006	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04017	11007	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04018	11008	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04019	11009	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04020	11010	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04021	11011	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04022	11012	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04023	11013	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04024	11014	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04025	11015	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04026	11016	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_04027	11017	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04028	11018	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04029	11019	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04030	11020	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04031	11021	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_04032	11022	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04035	11023	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04036	11024	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04037	11025	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04038	11026	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04039	11027	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04040	11028	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04041	11029	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04044	11030	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04046	11031	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04048	11032	N	N	N	1	CUSTOMER ISSUE	-
DMS_04050	11033	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04051	11034	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04053	11035	N	N	N	2	CUSTOMER ISSUE	-
DMS_04054	11036	N	N	N	1	CUSTOMER ISSUE	-
DMS_04055	11037	N	N	N	1	CUSTOMER ISSUE	-
DMS_04056	11038	N	N	N	1	CUSTOMER ISSUE	-
DMS_04057	11039	N	N	N	1	CUSTOMER ISSUE	-
DMS_04058	11040	N	N	N	1	CUSTOMER ISSUE	-
DMS_04059	11041	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04060	11042	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04061	11043	N	N	Y	1	TX - REPLACE	2500
DMS_04062	11044	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04063	11045	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04064	11046	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04065	11047	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04066	11048	N	N	N	1	CUSTOMER ISSUE	-
DMS_04067	11049	N	N	N	1	CUSTOMER ISSUE	-
DMS_04068	11050	N	N	N	1	CUSTOMER ISSUE	-
DMS_04069	11051	N	N	N	1	CUSTOMER ISSUE	-
DMS_04070	11052	N	N	N	1	CUSTOMER ISSUE	-
DMS_04071	11053	N	N	N	1	CUSTOMER ISSUE	-
DMS_04072	11054	N	N	N	1	CUSTOMER ISSUE	-
DMS_04073	11055	N	N	N	1	CUSTOMER ISSUE	-
DMS_04074	11056	N	N	N	1	CUSTOMER ISSUE	-
DMS_04075	11057	N	N	N	1	CUSTOMER ISSUE	-
DMS_04076	11058	N	N	N	1	CUSTOMER ISSUE	-
DMS_04078	11059	N	N	N	1	CUSTOMER ISSUE	-
DMS_04079	11060	N	N	N	1	CUSTOMER ISSUE	-
DMS_04080	11061	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04081	11062	N	N	N	1	CUSTOMER ISSUE	-
DMS_04082	11063	N	N	N	1	CUSTOMER ISSUE	-
DMS_04083	11064	N	N	N	1	CUSTOMER ISSUE	-
DMS_04084	11065	N	N	N	1	CUSTOMER ISSUE	-
DMS_04085	11066	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04086	11067	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04087	11068	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04088	11069	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04089	11070	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04090	11071	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04091	11072	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04092	11073	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04093	11074	N	N	N	1	CUSTOMER ISSUE	-
DMS_04094	11075	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04095	11076	N	N	N	1	CUSTOMER ISSUE	-
DMS_04096	11077	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04097	11078	N	N	N	1	CUSTOMER ISSUE	-
DMS_04098	11079	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04099	11080	N	N	N	1	CUSTOMER ISSUE	-
DMS_04100	11081	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04101	11082	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04102	11083	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04103	11084	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04104	11085	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04105	11086	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04106	11087	N	N	N	1	CUSTOMER ISSUE	-
DMS_04107	11088	N	N	N	1	CUSTOMER ISSUE	-
DMS_04108	11089	N	N	N	1	CUSTOMER ISSUE	-
DMS_04109	11090	N	N	N	1	CUSTOMER ISSUE	-
DMS_04110	11091	N	N	N	1	CUSTOMER ISSUE	-
DMS_04111	11092	N	N	N	1	CUSTOMER ISSUE	-
DMS_04112	11093	N	N	N	1	CUSTOMER ISSUE	-
DMS_04113	11094	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04114	11095	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04115	11096	N	N	N	1	CUSTOMER ISSUE	-

DMS_04116	11097	N	N	N	1	CUSTOMER ISSUE	-
DMS_04117	11098	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04118	11099	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04119	11100	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04120	11101	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04121	11102	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04122	11103	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04123	11104	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04124	11105	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04125	11106	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04126	11107	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04127	11108	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04128	11109	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04129	11110	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04130	11111	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04131	11112	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04132	11113	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04133	11114	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04134	11115	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04135	11116	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04136	11117	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04137	11118	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04138	11119	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04139	11120	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04140	11121	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04141	11122	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04142	11123	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04143	11124	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04144	11125	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04145	11126	N	N	Y	6	SEC/SVC - REPLACE	708.75
DMS_04146	11127	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04147	11128	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04148	11129	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04149	11130	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04150	11131	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04151	11132	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04152	11133	N	N	N	1	CUSTOMER ISSUE	-
DMS_04153	11134	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04154	11135	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04155	11136	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04156	11137	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04157	11138	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04158	11139	N	N	N	1	CUSTOMER ISSUE	-
DMS_04159	11140	N	N	N	1	CUSTOMER ISSUE	-
DMS_04160	11141	N	N	N	1	CUSTOMER ISSUE	-
DMS_04161	11142	N	N	N	1	CUSTOMER ISSUE	-
DMS_04162	11143	N	N	N	1	CUSTOMER ISSUE	-
DMS_04163	11144	N	N	N	1	CUSTOMER ISSUE	-
DMS_04164	11145	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04165	11146	N	N	N	1	CUSTOMER ISSUE	-
DMS_04166	11147	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04167	11148	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04168	11149	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04169	11150	N	N	N	1	CUSTOMER ISSUE	-
DMS_04170	11151	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04171	11152	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04172	11153	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04173	11154	N	N	N	1	CUSTOMER ISSUE	-
DMS_04174	11155	N	N	N	1	CUSTOMER ISSUE	-
DMS_04175	11156	N	N	N	1	CUSTOMER ISSUE	-
DMS_04176	11157	N	N	N	1	CUSTOMER ISSUE	-
DMS_04177	11158	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04178	11159	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04179	11160	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04180	11161	N	N	N	1	CUSTOMER ISSUE	-
DMS_04181	11162	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04182	11163	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04183	11164	N	N	N	1	CUSTOMER ISSUE	-
DMS_04184	11165	N	N	N	1	CUSTOMER ISSUE	-
DMS_04185	11166	N	N	N	1	CUSTOMER ISSUE	-
DMS_04186	11167	N	N	N	1	CUSTOMER ISSUE	-
DMS_04187	11168	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04188	11169	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04189	11170	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04190	11171	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04191	11172	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04192	11173	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04193	11174	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04194	11175	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04195	11176	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_04196	11177	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04197	11178	N	N	N	1	CUSTOMER ISSUE	-
DMS_04198	11179	N	N	N	1	CUSTOMER ISSUE	-
DMS_04199	11180	N	N	N	1	CUSTOMER ISSUE	-
DMS_04200	11181	N	N	N	1	CUSTOMER ISSUE	-
DMS_04201	11182	N	N	N	1	CUSTOMER ISSUE	-
DMS_04202	11183	N	N	N	1	CUSTOMER ISSUE	-
DMS_04203	11184	N	N	N	1	CUSTOMER ISSUE	-
DMS_04204	11185	N	N	N	1	CUSTOMER ISSUE	-
DMS_04205	11186	N	N	N	1	CUSTOMER ISSUE	-
DMS_04206	11187	N	N	N	1	CUSTOMER ISSUE	-
DMS_04207	11188	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04208	11189	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04209	11190	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04210	11191	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04211	11192	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04212	11193	N	N	N	1	CUSTOMER ISSUE	-
DMS_04213	11194	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04214	11195	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04215	11196	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04216	11197	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04217	11198	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04220	11199	N	N	N	1	CUSTOMER ISSUE	-
DMS_04221	11200	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04222	11201	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04223	11202	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04224	11203	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04225	11204	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04226	11205	N	N	N	1	CUSTOMER ISSUE	-
DMS_04227	11206	N	N	N	1	CUSTOMER ISSUE	-
DMS_04228	11207	N	N	N	1	CUSTOMER ISSUE	-
DMS_04229	11208	N	N	N	1	CUSTOMER ISSUE	-
DMS_04230	11209	N	N	N	1	CUSTOMER ISSUE	-
DMS_04231	11210	N	N	N	1	CUSTOMER ISSUE	-
DMS_04232	11211	N	N	N	1	CUSTOMER ISSUE	-
DMS_04233	11212	N	N	N	1	CUSTOMER ISSUE	-
DMS_04234	11213	N	N	N	1	CUSTOMER ISSUE	-
DMS_04235	11214	N	N	N	1	CUSTOMER ISSUE	-
DMS_04236	11215	N	N	N	1	CUSTOMER ISSUE	-
DMS_04237	11216	N	N	N	1	CUSTOMER ISSUE	-
DMS_04238	11217	N	N	N	1	CUSTOMER ISSUE	-
DMS_04239	11218	N	N	N	1	CUSTOMER ISSUE	-
DMS_04240	11219	N	N	N	1	CUSTOMER ISSUE	-
DMS_04241	11220	N	N	N	1	CUSTOMER ISSUE	-
DMS_04242	11221	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04243	11222	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04244	11223	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04245	11224	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04246	11225	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04247	11226	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04248	11227	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04249	11228	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04250	11229	N	N	N	1	CUSTOMER ISSUE	-
DMS_04251	11230	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04252	11231	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04253	11232	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04254	11233	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04255	11234	N	N	N	1	CUSTOMER ISSUE	-
DMS_04257	11235	N	N	N	1	CUSTOMER ISSUE	-
DMS_04258	11236	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04259	11237	N	N	N	1	CUSTOMER ISSUE	-
DMS_04260	11238	N	N	N	1	CUSTOMER ISSUE	-
DMS_04261	11239	N	N	N	1	CUSTOMER ISSUE	-
DMS_04262	11240	N	N	N	1	CUSTOMER ISSUE	-
DMS_04263	11241	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04264	11242	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04265	11243	N	N	N	1	CUSTOMER ISSUE	-
DMS_04266	11244	N	N	N	1	CUSTOMER ISSUE	-
DMS_04267	11245	N	N	N	1	CUSTOMER ISSUE	-
DMS_04268	11246	N	N	N	1	CUSTOMER ISSUE	-
DMS_04269	11247	N	N	N	1	CUSTOMER ISSUE	-
DMS_04270	11248	N	N	N	1	CUSTOMER ISSUE	-
DMS_04271	11249	N	N	N	1	CUSTOMER ISSUE	-
DMS_04272	11250	N	N	N	1	CUSTOMER ISSUE	-
DMS_04273	11251	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04274	11252	N	N	N	1	CUSTOMER ISSUE	-
DMS_04275	11253	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04276	11254	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04277	11255	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04278	11256	N	N	N	1	CUSTOMER ISSUE	-

DMS_04279	11257	N	N	N	1	CUSTOMER ISSUE	-
DMS_04280	11258	N	N	N	1	CUSTOMER ISSUE	-
DMS_04281	11259	N	N	N	1	CUSTOMER ISSUE	-
DMS_04282	11260	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04283	11261	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04284	11262	N	N	N	1	CUSTOMER ISSUE	-
DMS_04286	11263	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04287	11264	N	N	N	1	CUSTOMER ISSUE	-
DMS_04288	11265	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04289	11266	N	N	N	1	CUSTOMER ISSUE	-
DMS_04290	11267	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04291	11268	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04293	11269	N	N	N	1	CUSTOMER ISSUE	-
DMS_04294	11270	N	N	N	1	CUSTOMER ISSUE	-
DMS_04295	11271	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04296	11272	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04298	11273	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04299	11274	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04301	11275	N	N	N	1	CUSTOMER ISSUE	-
DMS_04302	11276	N	N	N	1	CUSTOMER ISSUE	-
DMS_04303	11277	N	N	N	1	CUSTOMER ISSUE	-
DMS_04304	11278	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04305	11279	N	N	N	1	CUSTOMER ISSUE	-
DMS_04306	11280	N	N	N	1	CUSTOMER ISSUE	-
DMS_04307	11281	N	N	N	1	CUSTOMER ISSUE	-
DMS_04308	11282	N	N	N	1	CUSTOMER ISSUE	-
DMS_04309	11283	N	N	N	1	CUSTOMER ISSUE	-
DMS_04311	11284	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_04312	11285	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04313	11286	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04314	11287	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04317	11288	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_04318	11289	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04319	11290	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04320	11291	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04321	11292	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04322	11293	N	N	N	1	CUSTOMER ISSUE	-
DMS_04323	11294	N	N	N	1	CUSTOMER ISSUE	-
DMS_04324	11295	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04325	11296	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04326	11297	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04327	11298	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04328	11299	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04330	11300	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04331	11301	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04332	11302	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04333	11303	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_04334	11304	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04335	11305	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04336	11306	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04337	11307	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04338	11308	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04340	11309	N	N	N	1	CUSTOMER ISSUE	-
DMS_04341	11310	N	N	N	1	CUSTOMER ISSUE	-
DMS_04342	11311	N	N	N	1	CUSTOMER ISSUE	-
DMS_04343	11312	N	N	N	1	CUSTOMER ISSUE	-
DMS_04344	11313	N	N	N	1	CUSTOMER ISSUE	-
DMS_04345	11314	N	N	N	1	CUSTOMER ISSUE	-
DMS_04346	11315	N	N	N	1	CUSTOMER ISSUE	-
DMS_04347	11316	N	N	N	1	CUSTOMER ISSUE	-
DMS_04348	11317	N	N	N	1	CUSTOMER ISSUE	-
DMS_04349	11318	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04350	11319	N	N	N	1	CUSTOMER ISSUE	-
DMS_04351	11320	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04354	11321	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04355	11322	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04356	11323	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04357	11324	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04358	11325	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04359	11326	N	N	N	1	CUSTOMER ISSUE	-
DMS_04360	11327	N	N	N	1	CUSTOMER ISSUE	-
DMS_04361	11328	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04362	11329	N	N	N	1	CUSTOMER ISSUE	-
DMS_04363	11330	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04366	11331	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04374	11332	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04375	11333	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04376	11334	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04377	11335	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04378	11336	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_04379	11337	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04380	11338	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04381	11339	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04382	11340	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04383	11341	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04384	11342	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04385	11343	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04386	11344	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04388	11345	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04389	11346	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04390	11347	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04391	11348	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04392	11349	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04393	11350	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04394	11351	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04395	11352	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04396	11353	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04397	11354	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04398	11355	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04399	11356	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04400	11357	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04401	11358	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04402	11359	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04403	11360	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04404	11361	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04405	11362	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04406	11363	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04407	11364	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04408	11365	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04409	11366	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04410	11367	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04411	11368	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04412	11369	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04413	11370	N	N	N	1	CUSTOMER ISSUE	-
DMS_04414	11371	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04415	11372	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04417	11373	N	N	Y	1	TX - REPLACE	2500
DMS_04420	11374	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04421	11375	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04434	11376	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04451	11377	N	N	N	1	CUSTOMER ISSUE	-
DMS_04452	11378	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04453	11379	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04455	11380	N	N	N	1	CUSTOMER ISSUE	-
DMS_04456	11381	N	N	N	1	CUSTOMER ISSUE	-
DMS_04457	11382	N	N	N	1	CUSTOMER ISSUE	-
DMS_04458	11383	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04459	11384	N	N	N	1	CUSTOMER ISSUE	-
DMS_04460	11385	N	N	N	1	CUSTOMER ISSUE	-
DMS_04461	11386	N	N	N	1	CUSTOMER ISSUE	-
DMS_04462	11387	N	N	N	1	CUSTOMER ISSUE	-
DMS_04463	11388	N	N	N	1	CUSTOMER ISSUE	-
DMS_04464	11389	N	N	N	1	CUSTOMER ISSUE	-
DMS_04466	11390	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04467	11391	N	N	N	1	CUSTOMER ISSUE	-
DMS_04468	11392	N	N	N	1	CUSTOMER ISSUE	-
DMS_04469	11393	N	N	N	1	CUSTOMER ISSUE	-
DMS_04471	11394	N	N	N	1	CUSTOMER ISSUE	-
DMS_04472	11395	N	N	N	1	CUSTOMER ISSUE	-
DMS_04473	11396	N	N	N	1	CUSTOMER ISSUE	-
DMS_04474	11397	N	N	N	1	CUSTOMER ISSUE	-
DMS_04476	11398	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04477	11399	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_04478	11400	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04479	11401	N	N	N	1	CUSTOMER ISSUE	-
DMS_04480	11402	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04482	11403	N	N	N	1	CUSTOMER ISSUE	-
DMS_04483	11404	N	N	N	1	CUSTOMER ISSUE	-
DMS_04485	11405	N	N	N	1	CUSTOMER ISSUE	-
DMS_04486	11406	N	N	N	1	CUSTOMER ISSUE	-
DMS_04487	11407	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04488	11408	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04489	11409	N	N	N	1	CUSTOMER ISSUE	-
DMS_04490	11410	N	N	N	1	CUSTOMER ISSUE	-
DMS_04491	11411	N	N	N	1	CUSTOMER ISSUE	-
DMS_04492	11412	N	N	N	1	CUSTOMER ISSUE	-
DMS_04493	11413	N	N	N	1	CUSTOMER ISSUE	-
DMS_04494	11414	N	N	N	1	CUSTOMER ISSUE	-
DMS_04495	11415	N	N	N	1	CUSTOMER ISSUE	-
DMS_04497	11416	N	N	N	1	CUSTOMER ISSUE	-

DMS_04498	11417	N	N	N	1	CUSTOMER ISSUE	-
DMS_04499	11418	N	N	N	1	CUSTOMER ISSUE	-
DMS_04500	11419	N	N	N	1	CUSTOMER ISSUE	-
DMS_04505	11420	N	N	N	1	CUSTOMER ISSUE	-
DMS_04506	11421	N	N	N	1	CUSTOMER ISSUE	-
DMS_04507	11422	N	N	N	1	CUSTOMER ISSUE	-
DMS_04508	11423	N	N	N	1	CUSTOMER ISSUE	-
DMS_04509	11424	N	N	N	1	CUSTOMER ISSUE	-
DMS_04510	11425	N	N	N	1	CUSTOMER ISSUE	-
DMS_04511	11426	N	N	N	1	CUSTOMER ISSUE	-
DMS_04512	11427	N	N	N	1	CUSTOMER ISSUE	-
DMS_04513	11428	N	N	N	1	CUSTOMER ISSUE	-
DMS_04514	11429	N	N	N	1	CUSTOMER ISSUE	-
DMS_04515	11430	N	N	N	1	CUSTOMER ISSUE	-
DMS_04516	11431	N	N	N	1	CUSTOMER ISSUE	-
DMS_04517	11432	N	N	N	1	CUSTOMER ISSUE	-
DMS_04518	11433	N	N	N	1	CUSTOMER ISSUE	-
DMS_04519	11434	N	N	N	1	CUSTOMER ISSUE	-
DMS_04520	11435	N	N	N	1	CUSTOMER ISSUE	-
DMS_04521	11436	N	N	N	1	CUSTOMER ISSUE	-
DMS_04522	11437	N	N	N	1	CUSTOMER ISSUE	-
DMS_04523	11438	N	N	N	1	CUSTOMER ISSUE	-
DMS_04524	11439	N	N	N	1	CUSTOMER ISSUE	-
DMS_04527	11440	N	N	N	1	CUSTOMER ISSUE	-
DMS_04528	11441	N	N	N	1	CUSTOMER ISSUE	-
DMS_04529	11442	N	N	N	1	CUSTOMER ISSUE	-
DMS_04531	11443	N	N	N	1	CUSTOMER ISSUE	-
DMS_04532	11444	N	N	N	1	CUSTOMER ISSUE	-
DMS_04533	11445	N	N	N	1	CUSTOMER ISSUE	-
DMS_04535	11446	N	N	N	1	CUSTOMER ISSUE	-
DMS_04536	11447	N	N	N	1	CUSTOMER ISSUE	-
DMS_04537	11448	N	N	N	1	CUSTOMER ISSUE	-
DMS_04538	11449	N	N	N	1	CUSTOMER ISSUE	-
DMS_04539	11450	N	N	N	1	CUSTOMER ISSUE	-
DMS_04540	11451	N	N	N	1	CUSTOMER ISSUE	-
DMS_04541	11452	N	N	N	1	CUSTOMER ISSUE	-
DMS_04542	11453	N	N	N	1	CUSTOMER ISSUE	-
DMS_04543	11454	N	N	N	1	CUSTOMER ISSUE	-
DMS_04544	11455	N	N	N	1	CUSTOMER ISSUE	-
DMS_04545	11456	N	N	N	1	CUSTOMER ISSUE	-
DMS_04546	11457	N	N	N	1	CUSTOMER ISSUE	-
DMS_04547	11458	N	N	N	1	CUSTOMER ISSUE	-
DMS_04548	11459	N	N	N	1	CUSTOMER ISSUE	-
DMS_04549	11460	N	N	N	1	CUSTOMER ISSUE	-
DMS_04550	11461	N	N	N	1	CUSTOMER ISSUE	-
DMS_04551	11462	N	N	N	1	CUSTOMER ISSUE	-
DMS_04552	11463	N	N	N	1	CUSTOMER ISSUE	-
DMS_04553	11464	N	N	N	1	CUSTOMER ISSUE	-
DMS_04554	11465	N	N	N	1	CUSTOMER ISSUE	-
DMS_04555	11466	N	N	N	1	CUSTOMER ISSUE	-
DMS_04556	11467	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04557	11468	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04558	11469	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04559	11470	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04561	11471	N	N	N	1	CUSTOMER ISSUE	-
DMS_04562	11472	N	N	N	1	CUSTOMER ISSUE	-
DMS_04563	11473	N	N	N	1	CUSTOMER ISSUE	-
DMS_04564	11474	N	N	N	1	CUSTOMER ISSUE	-
DMS_04565	11475	N	N	N	1	CUSTOMER ISSUE	-
DMS_04566	11476	N	N	N	1	CUSTOMER ISSUE	-
DMS_04567	11477	N	N	N	1	CUSTOMER ISSUE	-
DMS_04568	11478	N	N	N	1	CUSTOMER ISSUE	-
DMS_04569	11479	N	N	N	1	CUSTOMER ISSUE	-
DMS_04570	11480	N	N	N	1	CUSTOMER ISSUE	-
DMS_04571	11481	N	N	N	1	CUSTOMER ISSUE	-
DMS_04572	11482	N	N	N	1	CUSTOMER ISSUE	-
DMS_04573	11483	N	N	N	1	CUSTOMER ISSUE	-
DMS_04574	11484	N	N	N	1	CUSTOMER ISSUE	-
DMS_04575	11485	N	N	N	1	CUSTOMER ISSUE	-
DMS_04577	11486	N	N	N	1	CUSTOMER ISSUE	-
DMS_04578	11487	N	N	N	1	CUSTOMER ISSUE	-
DMS_04579	11488	N	N	N	1	CUSTOMER ISSUE	-
DMS_04580	11489	N	N	N	1	CUSTOMER ISSUE	-
DMS_04581	11490	N	N	N	1	CUSTOMER ISSUE	-
DMS_04582	11491	N	N	N	1	CUSTOMER ISSUE	-
DMS_04583	11492	N	N	N	1	CUSTOMER ISSUE	-
DMS_04584	11493	N	N	N	1	CUSTOMER ISSUE	-
DMS_04585	11494	N	N	N	1	CUSTOMER ISSUE	-
DMS_04586	11495	N	N	N	1	CUSTOMER ISSUE	-
DMS_04587	11496	N	N	N	1	CUSTOMER ISSUE	-

DMS_04588	11497	N	N	N	1	CUSTOMER ISSUE	-
DMS_04589	11498	N	N	N	1	CUSTOMER ISSUE	-
DMS_04590	11499	N	N	N	1	CUSTOMER ISSUE	-
DMS_04591	11500	N	N	N	1	CUSTOMER ISSUE	-
DMS_04592	11501	N	N	N	1	CUSTOMER ISSUE	-
DMS_04593	11502	N	N	N	1	CUSTOMER ISSUE	-
DMS_04594	11503	N	N	N	1	CUSTOMER ISSUE	-
DMS_04595	11504	N	N	N	1	CUSTOMER ISSUE	-
DMS_04596	11505	N	N	N	1	CUSTOMER ISSUE	-
DMS_04597	11506	N	N	N	1	CUSTOMER ISSUE	-
DMS_04598	11507	N	N	N	1	CUSTOMER ISSUE	-
DMS_04599	11508	N	N	N	1	CUSTOMER ISSUE	-
DMS_04600	11509	N	N	N	1	CUSTOMER ISSUE	-
DMS_04601	11510	N	N	N	1	CUSTOMER ISSUE	-
DMS_04602	11511	N	N	N	1	CUSTOMER ISSUE	-
DMS_04603	11512	N	N	N	1	CUSTOMER ISSUE	-
DMS_04606	11513	N	N	N	1	CUSTOMER ISSUE	-
DMS_04607	11514	N	N	N	1	CUSTOMER ISSUE	-
DMS_04608	11515	N	N	N	1	CUSTOMER ISSUE	-
DMS_04609	11516	N	N	N	1	CUSTOMER ISSUE	-
DMS_04610	11517	N	N	N	1	CUSTOMER ISSUE	-
DMS_04611	11518	N	N	N	1	CUSTOMER ISSUE	-
DMS_04612	11519	N	N	N	1	CUSTOMER ISSUE	-
DMS_04613	11520	N	N	N	1	CUSTOMER ISSUE	-
DMS_04614	11521	N	N	N	1	CUSTOMER ISSUE	-
DMS_04615	11522	N	N	N	1	CUSTOMER ISSUE	-
DMS_04616	11523	N	N	N	1	CUSTOMER ISSUE	-
DMS_04618	11524	N	N	N	1	CUSTOMER ISSUE	-
DMS_04619	11525	N	N	N	1	CUSTOMER ISSUE	-
DMS_04620	11526	N	N	N	1	CUSTOMER ISSUE	-
DMS_04621	11527	N	N	N	1	CUSTOMER ISSUE	-
DMS_04622	11528	N	N	N	1	CUSTOMER ISSUE	-
DMS_04623	11529	N	N	N	1	CUSTOMER ISSUE	-
DMS_04625	11530	N	N	N	1	CUSTOMER ISSUE	-
DMS_04626	11531	N	N	N	1	CUSTOMER ISSUE	-
DMS_04627	11532	N	N	N	2	CUSTOMER ISSUE	-
DMS_04628	11533	N	N	N	1	CUSTOMER ISSUE	-
DMS_04629	11534	N	N	N	1	CUSTOMER ISSUE	-
DMS_04630	11535	N	N	N	1	CUSTOMER ISSUE	-
DMS_04631	11536	N	N	N	1	CUSTOMER ISSUE	-
DMS_04634	11537	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
DMS_04635	11538	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04638	11539	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04639	11540	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04640	11541	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04642	11542	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04643	11543	N	N	N	1	CUSTOMER ISSUE	-
DMS_04644	11544	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04645	11545	N	N	N	1	CUSTOMER ISSUE	-
DMS_04646	11546	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04650	11547	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04651	11548	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04652	11549	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04653	11550	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04654	11551	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04655	11552	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04656	11553	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04657	11554	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04658	11555	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04659	11556	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04660	11557	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04661	11558	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04662	11559	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04663	11560	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04664	11561	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04665	11562	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04666	11563	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04667	11564	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04668	11565	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04672	11566	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04673	11567	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04674	11568	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04675	11569	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04676	11570	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04677	11571	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04678	11572	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04679	11573	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04680	11574	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04681	11575	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04682	11576	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_04683	11577	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04684	11578	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04685	11579	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04686	11580	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04687	11581	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04688	11582	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04689	11583	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04690	11584	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04691	11585	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04692	11586	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04693	11587	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
DMS_04695	11588	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_04696	11589	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04697	11590	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04698	11591	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04699	11592	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04700	11593	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04701	11594	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04702	11595	N	N	Y	1	TX - REPLACE	2500
DMS_04703	11596	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_04704	11597	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_04705	11598	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04706	11599	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04708	11600	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04709	11601	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04710	11602	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04711	11603	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04712	11604	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04713	11605	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04714	11606	N	N	N	1	CUSTOMER ISSUE	-
DMS_04715	11607	N	N	Y	1	TX - REPLACE	2500
DMS_04716	11608	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04717	11609	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04720	11610	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04728	11611	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04729	11612	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04730	11613	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04731	11614	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04732	11615	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04733	11616	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04734	11617	N	N	N	1	CUSTOMER ISSUE	-
DMS_04735	11618	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04736	11619	N	N	N	1	CUSTOMER ISSUE	-
DMS_04737	11620	N	N	N	1	CUSTOMER ISSUE	-
DMS_04738	11621	N	N	N	1	CUSTOMER ISSUE	-
DMS_04739	11622	N	N	N	1	CUSTOMER ISSUE	-
DMS_04740	11623	N	N	N	1	CUSTOMER ISSUE	-
DMS_04741	11624	N	N	N	1	CUSTOMER ISSUE	-
DMS_04743	11625	N	N	Y	1	TX - REPLACE	2500
DMS_04744	11626	N	N	N	1	CUSTOMER ISSUE	-
DMS_04745	11627	N	N	N	1	CUSTOMER ISSUE	-
DMS_04746	11628	N	N	N	1	CUSTOMER ISSUE	-
DMS_04748	11629	N	N	N	1	CUSTOMER ISSUE	-
DMS_04749	11630	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04753	11631	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04754	11632	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04755	11633	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04756	11634	N	N	N	1	CUSTOMER ISSUE	-
DMS_04757	11635	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_04759	11636	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04761	11637	N	N	N	1	CUSTOMER ISSUE	-
DMS_04763	11638	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_04764	11639	N	N	N	1	CUSTOMER ISSUE	-
DMS_04766	11640	N	N	N	1	CUSTOMER ISSUE	-
DMS_04767	11641	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04768	11642	N	N	N	1	CUSTOMER ISSUE	-
DMS_04769	11643	N	N	N	1	CUSTOMER ISSUE	-
DMS_04770	11644	N	N	N	1	CUSTOMER ISSUE	-
DMS_04771	11645	N	N	N	1	CUSTOMER ISSUE	-
DMS_04774	11646	N	N	N	1	CUSTOMER ISSUE	-
DMS_04776	11647	N	N	N	1	CUSTOMER ISSUE	-
DMS_04777	11648	N	N	N	1	CUSTOMER ISSUE	-
DMS_04779	11649	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04780	11650	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_04781	11651	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04783	11652	N	N	N	1	CUSTOMER ISSUE	-
DMS_04784	11653	N	N	N	1	CUSTOMER ISSUE	-
DMS_04785	11654	N	N	N	1	CUSTOMER ISSUE	-
DMS_04788	11655	N	N	N	1	CUSTOMER ISSUE	-
DMS_04790	11656	N	N	N	1	CUSTOMER ISSUE	-

DMS_04791	11657	N	N	N	1	CUSTOMER ISSUE	-
DMS_04794	11658	N	N	N	1	CUSTOMER ISSUE	-
DMS_04795	11659	N	N	N	1	CUSTOMER ISSUE	-
DMS_04796	11660	N	N	N	1	CUSTOMER ISSUE	-
DMS_04797	11661	N	N	N	1	CUSTOMER ISSUE	-
DMS_04804	11662	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04805	11663	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04806	11664	N	N	N	1	CUSTOMER ISSUE	-
DMS_04807	11665	N	N	N	1	CUSTOMER ISSUE	-
DMS_04808	11666	N	N	N	1	CUSTOMER ISSUE	-
DMS_04815	11667	N	N	N	1	CUSTOMER ISSUE	-
DMS_04816	11668	N	N	N	1	CUSTOMER ISSUE	-
DMS_04817	11669	N	N	N	1	CUSTOMER ISSUE	-
DMS_04818	11670	N	N	N	1	CUSTOMER ISSUE	-
DMS_04819	11671	N	N	N	1	CUSTOMER ISSUE	-
DMS_04820	11672	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04822	11673	N	N	N	1	CUSTOMER ISSUE	-
DMS_04824	11674	N	N	N	1	CUSTOMER ISSUE	-
DMS_04825	11675	N	N	N	1	CUSTOMER ISSUE	-
DMS_04826	11676	N	N	N	1	CUSTOMER ISSUE	-
DMS_04827	11677	N	N	N	1	CUSTOMER ISSUE	-
DMS_04828	11678	N	N	N	1	CUSTOMER ISSUE	-
DMS_04829	11679	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04831	11680	N	N	N	1	CUSTOMER ISSUE	-
DMS_04832	11681	N	N	N	1	CUSTOMER ISSUE	-
DMS_04833	11682	N	N	N	1	CUSTOMER ISSUE	-
DMS_04834	11683	N	N	N	1	CUSTOMER ISSUE	-
DMS_04835	11684	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04837	11685	N	N	N	1	CUSTOMER ISSUE	-
DMS_04856	11686	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04857	11687	N	N	N	1	CUSTOMER ISSUE	-
DMS_04858	11688	N	N	N	1	CUSTOMER ISSUE	-
DMS_04860	11689	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04861	11690	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04864	11691	N	N	N	1	CUSTOMER ISSUE	-
DMS_04865	11692	N	N	N	1	CUSTOMER ISSUE	-
DMS_04866	11693	N	N	N	1	CUSTOMER ISSUE	-
DMS_04867	11694	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04868	11695	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04869	11696	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04870	11697	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04871	11698	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04872	11699	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04873	11700	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04875	11701	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04876	11702	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04877	11703	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04878	11704	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_04879	11705	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04880	11706	N	N	Y	1	TX - REPLACE	2500
DMS_04882	11707	N	N	N	1	CUSTOMER ISSUE	-
DMS_04883	11708	N	N	N	1	CUSTOMER ISSUE	-
DMS_04885	11709	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04886	11710	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_04887	11711	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04888	11712	N	N	N	1	CUSTOMER ISSUE	-
DMS_04889	11713	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04890	11714	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04891	11715	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04892	11716	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04893	11717	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04894	11718	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04895	11719	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04896	11720	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04897	11721	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04898	11722	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04899	11723	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04900	11724	N	N	N	1	CUSTOMER ISSUE	-
DMS_04901	11725	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04902	11726	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04904	11727	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04905	11728	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04906	11729	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04907	11730	N	N	N	1	CUSTOMER ISSUE	-
DMS_04908	11731	N	N	N	1	CUSTOMER ISSUE	-
DMS_04909	11732	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04910	11733	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04911	11734	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04912	11735	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04913	11736	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_04914	11737	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04915	11738	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04916	11739	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04917	11740	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04918	11741	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04919	11742	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04920	11743	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04921	11744	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04922	11745	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04923	11746	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04924	11747	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04925	11748	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04926	11749	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04927	11750	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04928	11751	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04929	11752	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04930	11753	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04931	11754	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04932	11755	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04933	11756	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04934	11757	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04935	11758	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04936	11759	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04937	11760	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04938	11761	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04939	11762	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04940	11763	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04941	11764	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04942	11765	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04943	11766	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04944	11767	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04945	11768	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04946	11769	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04947	11770	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04948	11771	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04949	11772	N	N	N	1	CUSTOMER ISSUE	-
DMS_04950	11773	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04951	11774	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04952	11775	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04953	11776	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04954	11777	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04955	11778	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04956	11779	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04957	11780	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04958	11781	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04959	11782	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04960	11783	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04961	11784	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04962	11785	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04963	11786	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04964	11787	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04965	11788	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04966	11789	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04967	11790	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04968	11791	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04969	11792	N	N	N	1	CUSTOMER ISSUE	-
DMS_04970	11793	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04971	11794	N	N	N	1	CUSTOMER ISSUE	-
DMS_04972	11795	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04973	11796	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04974	11797	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04975	11798	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04976	11799	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04977	11800	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04978	11801	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04979	11802	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04980	11803	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04981	11804	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04982	11805	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04983	11806	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04984	11807	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04985	11808	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04986	11809	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04987	11810	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04988	11811	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04989	11812	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04990	11813	N	N	N	1	CUSTOMER ISSUE	-
DMS_04991	11814	N	N	N	1	CUSTOMER ISSUE	-
DMS_04992	11815	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04993	11816	N	N	N	1	CUSTOMER ISSUE	-

DMS_04994	11817	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04995	11818	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04996	11819	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04997	11820	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04998	11821	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_04999	11822	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05000	11823	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05001	11824	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05002	11825	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05003	11826	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05004	11827	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05005	11828	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05006	11829	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05007	11830	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05008	11831	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05009	11832	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05010	11833	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05011	11834	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05012	11835	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05013	11836	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05014	11837	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05015	11838	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05016	11839	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05017	11840	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05018	11841	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05019	11842	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05020	11843	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05021	11844	N	N	N	1	CUSTOMER ISSUE	-
DMS_05022	11845	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05023	11846	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05024	11847	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05025	11848	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05026	11849	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05027	11850	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05028	11851	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05029	11852	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05030	11853	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05031	11854	N	N	N	1	CUSTOMER ISSUE	-
DMS_05032	11855	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05033	11856	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05034	11857	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05035	11858	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05036	11859	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05037	11860	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05038	11861	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05039	11862	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05040	11863	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05041	11864	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05042	11865	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05043	11866	N	N	N	1	CUSTOMER ISSUE	-
DMS_05044	11867	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05045	11868	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05046	11869	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05047	11870	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05048	11871	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05049	11872	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05050	11873	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05051	11874	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05052	11875	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05053	11876	N	N	N	1	CUSTOMER ISSUE	-
DMS_05054	11877	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05055	11878	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05056	11879	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05057	11880	N	N	N	1	CUSTOMER ISSUE	-
DMS_05058	11881	N	N	N	1	CUSTOMER ISSUE	-
DMS_05059	11882	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05060	11883	N	N	N	1	CUSTOMER ISSUE	-
DMS_05061	11884	N	N	N	1	CUSTOMER ISSUE	-
DMS_05062	11885	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05063	11886	N	N	N	1	CUSTOMER ISSUE	-
DMS_05064	11887	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05065	11888	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05066	11889	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05067	11890	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05068	11891	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05069	11892	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05070	11893	N	N	N	1	CUSTOMER ISSUE	-
DMS_05071	11894	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05072	11895	N	N	N	1	CUSTOMER ISSUE	-
DMS_05073	11896	N	N	N	1	CUSTOMER ISSUE	-

DMS_05074	11897	N	N	N	1	CUSTOMER ISSUE	-
DMS_05075	11898	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05076	11899	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05077	11900	N	N	N	1	CUSTOMER ISSUE	-
DMS_05078	11901	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05079	11902	N	N	N	1	CUSTOMER ISSUE	-
DMS_05080	11903	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05081	11904	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05082	11905	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05083	11906	N	N	N	1	CUSTOMER ISSUE	-
DMS_05085	11907	N	N	N	1	CUSTOMER ISSUE	-
DMS_05089	11908	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05090	11909	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05091	11910	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05092	11911	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05093	11912	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05094	11913	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05095	11914	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05096	11915	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05097	11916	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05098	11917	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05099	11918	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05100	11919	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05101	11920	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05102	11921	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05103	11922	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05104	11923	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05105	11924	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05106	11925	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05107	11926	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05108	11927	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05109	11928	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05110	11929	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05111	11930	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05112	11931	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05113	11932	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05115	11933	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05116	11934	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05117	11935	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05118	11936	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05119	11937	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05120	11938	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05121	11939	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05122	11940	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05123	11941	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05124	11942	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05125	11943	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05126	11944	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05127	11945	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05128	11946	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05129	11947	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05130	11948	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05131	11949	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05132	11950	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05133	11951	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05134	11952	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05135	11953	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05136	11954	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05137	11955	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05138	11956	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05139	11957	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05140	11958	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05141	11959	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05142	11960	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05143	11961	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05144	11962	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05145	11963	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05146	11964	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05147	11965	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05148	11966	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05149	11967	N	N	N	1	CUSTOMER ISSUE	-
DMS_05150	11968	N	N	N	1	CUSTOMER ISSUE	-
DMS_05151	11969	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05152	11970	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05153	11971	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05154	11972	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05155	11973	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05156	11974	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05157	11975	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05158	11976	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_05159	11977	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05160	11978	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05161	11979	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05162	11980	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05163	11981	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05164	11982	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05165	11983	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05166	11984	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05167	11985	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05168	11986	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05169	11987	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05170	11988	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05171	11989	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05172	11990	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05173	11991	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05174	11992	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05175	11993	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05176	11994	N	N	N	1	CUSTOMER ISSUE	-
DMS_05177	11995	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05178	11996	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05179	11997	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05180	11998	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05181	11999	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05182	12000	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05183	12001	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05184	12002	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05185	12003	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05186	12004	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05187	12005	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05188	12006	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05189	12007	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05190	12008	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05191	12009	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05192	12010	N	N	N	1	CUSTOMER ISSUE	-
DMS_05193	12011	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05194	12012	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05195	12013	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05196	12014	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05197	12015	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05198	12016	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05199	12017	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05201	12018	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05202	12019	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05203	12020	N	N	N	1	CUSTOMER ISSUE	-
DMS_05204	12021	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05206	12022	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05207	12023	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05208	12024	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05209	12025	N	N	N	1	CUSTOMER ISSUE	-
DMS_05210	12026	N	N	N	1	CUSTOMER ISSUE	-
DMS_05211	12027	N	N	N	1	CUSTOMER ISSUE	-
DMS_05212	12028	N	N	N	1	CUSTOMER ISSUE	-
DMS_05213	12029	N	N	N	1	CUSTOMER ISSUE	-
DMS_05214	12030	N	N	N	1	CUSTOMER ISSUE	-
DMS_05215	12031	N	N	N	1	CUSTOMER ISSUE	-
DMS_05216	12032	N	N	N	1	CUSTOMER ISSUE	-
DMS_05217	12033	N	N	N	1	CUSTOMER ISSUE	-
DMS_05218	12034	N	N	N	1	CUSTOMER ISSUE	-
DMS_05219	12035	N	N	N	1	CUSTOMER ISSUE	-
DMS_05221	12036	N	N	N	1	CUSTOMER ISSUE	-
DMS_05222	12037	N	N	N	1	CUSTOMER ISSUE	-
DMS_05223	12038	N	N	N	1	CUSTOMER ISSUE	-
DMS_05224	12039	N	N	N	1	CUSTOMER ISSUE	-
DMS_05225	12040	N	N	N	1	CUSTOMER ISSUE	-
DMS_05226	12041	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05227	12042	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05230	12043	N	N	N	1	CUSTOMER ISSUE	-
DMS_05231	12044	N	N	N	1	CUSTOMER ISSUE	-
DMS_05232	12045	N	N	N	1	CUSTOMER ISSUE	-
DMS_05233	12046	N	N	N	1	CUSTOMER ISSUE	-
DMS_05234	12047	N	N	N	1	CUSTOMER ISSUE	-
DMS_05235	12048	N	N	N	1	CUSTOMER ISSUE	-
DMS_05236	12049	N	N	N	1	CUSTOMER ISSUE	-
DMS_05237	12050	N	N	N	1	CUSTOMER ISSUE	-
DMS_05238	12051	N	N	N	1	CUSTOMER ISSUE	-
DMS_05239	12052	N	N	N	1	CUSTOMER ISSUE	-
DMS_05240	12053	N	N	N	1	CUSTOMER ISSUE	-
DMS_05241	12054	N	N	N	1	CUSTOMER ISSUE	-
DMS_05242	12055	N	N	N	1	CUSTOMER ISSUE	-
DMS_05244	12056	N	N	N	1	CUSTOMER ISSUE	-

DMS_05245	12057	N	N	N	1	CUSTOMER ISSUE	-
DMS_05246	12058	N	N	N	1	CUSTOMER ISSUE	-
DMS_05247	12059	N	N	N	1	CUSTOMER ISSUE	-
DMS_05248	12060	N	N	N	1	CUSTOMER ISSUE	-
DMS_05249	12061	N	N	N	1	CUSTOMER ISSUE	-
DMS_05250	12062	N	N	N	1	CUSTOMER ISSUE	-
DMS_05251	12063	N	N	N	1	CUSTOMER ISSUE	-
DMS_05252	12064	N	N	N	1	CUSTOMER ISSUE	-
DMS_05253	12065	N	N	N	1	CUSTOMER ISSUE	-
DMS_05254	12066	N	N	N	1	CUSTOMER ISSUE	-
DMS_05255	12067	N	N	N	1	CUSTOMER ISSUE	-
DMS_05256	12068	N	N	N	1	CUSTOMER ISSUE	-
DMS_05257	12069	N	N	N	1	CUSTOMER ISSUE	-
DMS_05258	12070	N	N	N	1	CUSTOMER ISSUE	-
DMS_05259	12071	N	N	N	1	CUSTOMER ISSUE	-
DMS_05260	12072	N	N	N	1	CUSTOMER ISSUE	-
DMS_05261	12073	N	N	N	1	CUSTOMER ISSUE	-
DMS_05262	12074	N	N	N	1	CUSTOMER ISSUE	-
DMS_05263	12075	N	N	N	1	CUSTOMER ISSUE	-
DMS_05264	12076	N	N	N	1	CUSTOMER ISSUE	-
DMS_05265	12077	N	N	N	1	CUSTOMER ISSUE	-
DMS_05266	12078	N	N	N	1	CUSTOMER ISSUE	-
DMS_05267	12079	N	N	N	1	CUSTOMER ISSUE	-
DMS_05268	12080	N	N	N	1	CUSTOMER ISSUE	-
DMS_05269	12081	N	N	N	1	CUSTOMER ISSUE	-
DMS_05270	12082	N	N	N	1	CUSTOMER ISSUE	-
DMS_05271	12083	N	N	N	1	CUSTOMER ISSUE	-
DMS_05272	12084	N	N	N	1	CUSTOMER ISSUE	-
DMS_05273	12085	N	N	N	1	CUSTOMER ISSUE	-
DMS_05274	12086	N	N	N	1	CUSTOMER ISSUE	-
DMS_05275	12087	N	N	N	1	CUSTOMER ISSUE	-
DMS_05276	12088	N	N	N	1	CUSTOMER ISSUE	-
DMS_05277	12089	N	N	N	1	CUSTOMER ISSUE	-
DMS_05278	12090	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_05279	12091	N	N	N	1	CUSTOMER ISSUE	-
DMS_05280	12092	N	N	N	1	CUSTOMER ISSUE	-
DMS_05281	12093	N	N	N	1	CUSTOMER ISSUE	-
DMS_05282	12094	N	N	N	1	CUSTOMER ISSUE	-
DMS_05283	12095	N	N	N	1	CUSTOMER ISSUE	-
DMS_05284	12096	N	N	N	1	CUSTOMER ISSUE	-
DMS_05285	12097	N	N	N	1	CUSTOMER ISSUE	-
DMS_05286	12098	N	N	N	1	CUSTOMER ISSUE	-
DMS_05290	12099	N	N	N	1	CUSTOMER ISSUE	-
DMS_05291	12100	N	N	N	1	CUSTOMER ISSUE	-
DMS_05293	12101	N	N	N	1	CUSTOMER ISSUE	-
DMS_05294	12102	N	N	N	1	CUSTOMER ISSUE	-
DMS_05295	12103	N	N	N	1	CUSTOMER ISSUE	-
DMS_05297	12104	N	N	N	1	CUSTOMER ISSUE	-
DMS_05298	12105	N	N	N	1	CUSTOMER ISSUE	-
DMS_05299	12106	N	N	N	1	CUSTOMER ISSUE	-
DMS_05301	12107	N	N	N	1	CUSTOMER ISSUE	-
DMS_05302	12108	N	N	N	1	CUSTOMER ISSUE	-
DMS_05303	12109	N	N	N	1	CUSTOMER ISSUE	-
DMS_05305	12110	N	N	N	1	CUSTOMER ISSUE	-
DMS_05306	12111	N	N	N	1	CUSTOMER ISSUE	-
DMS_05307	12112	N	N	N	1	CUSTOMER ISSUE	-
DMS_05310	12113	N	N	N	1	CUSTOMER ISSUE	-
DMS_05312	12114	N	N	N	2	CUSTOMER ISSUE	-
DMS_05313	12115	N	N	N	1	CUSTOMER ISSUE	-
DMS_05314	12116	N	N	N	1	CUSTOMER ISSUE	-
DMS_05315	12117	N	N	N	1	CUSTOMER ISSUE	-
DMS_05316	12118	N	N	N	1	CUSTOMER ISSUE	-
DMS_05317	12119	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05318	12120	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_05319	12121	N	N	N	1	CUSTOMER ISSUE	-
DMS_05320	12122	N	N	N	1	CUSTOMER ISSUE	-
DMS_05321	12123	N	N	N	1	CUSTOMER ISSUE	-
DMS_05322	12124	N	N	N	1	CUSTOMER ISSUE	-
DMS_05323	12125	N	N	N	1	CUSTOMER ISSUE	-
DMS_05324	12126	N	N	N	1	CUSTOMER ISSUE	-
DMS_05325	12127	N	N	N	1	CUSTOMER ISSUE	-
DMS_05328	12128	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05329	12129	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05330	12130	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05331	12131	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05332	12132	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05333	12133	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05334	12134	N	N	N	1	CUSTOMER ISSUE	-
DMS_05335	12135	N	N	N	1	CUSTOMER ISSUE	-
DMS_05337	12136	N	N	N	1	CUSTOMER ISSUE	-

DMS_05338	12137	N	N	N	1	CUSTOMER ISSUE	-
DMS_05339	12138	N	N	N	1	CUSTOMER ISSUE	-
DMS_05340	12139	N	N	N	1	CUSTOMER ISSUE	-
DMS_05341	12140	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05343	12141	N	N	N	1	CUSTOMER ISSUE	-
DMS_05344	12142	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_05345	12143	N	N	N	1	CUSTOMER ISSUE	-
DMS_05346	12144	N	N	N	1	CUSTOMER ISSUE	-
DMS_05347	12145	N	N	N	2	CUSTOMER ISSUE	-
DMS_05348	12146	N	N	N	1	CUSTOMER ISSUE	-
DMS_05349	12147	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05350	12148	N	N	N	1	CUSTOMER ISSUE	-
DMS_05351	12149	N	N	N	1	CUSTOMER ISSUE	-
DMS_05352	12150	N	N	N	1	CUSTOMER ISSUE	-
DMS_05353	12151	N	N	N	1	CUSTOMER ISSUE	-
DMS_05354	12152	N	N	N	1	CUSTOMER ISSUE	-
DMS_05355	12153	N	N	N	1	CUSTOMER ISSUE	-
DMS_05356	12154	N	N	N	1	CUSTOMER ISSUE	-
DMS_05358	12155	N	N	N	1	CUSTOMER ISSUE	-
DMS_05359	12156	N	N	N	1	CUSTOMER ISSUE	-
DMS_05360	12157	N	N	N	1	CUSTOMER ISSUE	-
DMS_05362	12158	N	N	N	1	CUSTOMER ISSUE	-
DMS_05363	12159	N	N	N	1	CUSTOMER ISSUE	-
DMS_05366	12160	N	N	N	1	CUSTOMER ISSUE	-
DMS_05367	12161	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05368	12162	N	N	N	1	CUSTOMER ISSUE	-
DMS_05369	12163	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_05370	12164	N	N	N	2	CUSTOMER ISSUE	-
DMS_05372	12165	N	N	N	1	CUSTOMER ISSUE	-
DMS_05373	12166	N	N	N	1	CUSTOMER ISSUE	-
DMS_05374	12167	N	N	N	1	CUSTOMER ISSUE	-
DMS_05375	12168	N	N	N	1	CUSTOMER ISSUE	-
DMS_05376	12169	N	N	N	1	CUSTOMER ISSUE	-
DMS_05377	12170	N	N	N	1	CUSTOMER ISSUE	-
DMS_05378	12171	N	N	N	1	CUSTOMER ISSUE	-
DMS_05379	12172	N	N	N	1	CUSTOMER ISSUE	-
DMS_05380	12173	N	N	N	1	CUSTOMER ISSUE	-
DMS_05381	12174	N	N	N	1	CUSTOMER ISSUE	-
DMS_05383	12175	N	N	N	1	CUSTOMER ISSUE	-
DMS_05384	12176	N	N	N	1	CUSTOMER ISSUE	-
DMS_05385	12177	N	N	N	1	CUSTOMER ISSUE	-
DMS_05386	12178	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05387	12179	N	N	N	1	CUSTOMER ISSUE	-
DMS_05388	12180	N	N	N	1	CUSTOMER ISSUE	-
DMS_05389	12181	N	N	N	1	CUSTOMER ISSUE	-
DMS_05390	12182	N	N	N	1	CUSTOMER ISSUE	-
DMS_05391	12183	N	N	N	1	CUSTOMER ISSUE	-
DMS_05392	12184	N	N	N	1	CUSTOMER ISSUE	-
DMS_05393	12185	N	N	N	1	CUSTOMER ISSUE	-
DMS_05394	12186	N	N	N	1	CUSTOMER ISSUE	-
DMS_05395	12187	N	N	N	1	CUSTOMER ISSUE	-
DMS_05396	12188	N	N	N	1	CUSTOMER ISSUE	-
DMS_05397	12189	N	N	N	1	CUSTOMER ISSUE	-
DMS_05398	12190	N	N	N	1	CUSTOMER ISSUE	-
DMS_05399	12191	N	N	N	1	CUSTOMER ISSUE	-
DMS_05400	12192	N	N	N	1	CUSTOMER ISSUE	-
DMS_05401	12193	N	N	N	1	CUSTOMER ISSUE	-
DMS_05402	12194	N	N	N	1	CUSTOMER ISSUE	-
DMS_05403	12195	N	N	N	1	CUSTOMER ISSUE	-
DMS_05404	12196	N	N	N	1	CUSTOMER ISSUE	-
DMS_05405	12197	N	N	N	1	CUSTOMER ISSUE	-
DMS_05406	12198	N	N	N	1	CUSTOMER ISSUE	-
DMS_05407	12199	N	N	N	1	CUSTOMER ISSUE	-
DMS_05408	12200	N	N	N	1	CUSTOMER ISSUE	-
DMS_05409	12201	N	N	N	1	CUSTOMER ISSUE	-
DMS_05410	12202	N	N	N	1	CUSTOMER ISSUE	-
DMS_05411	12203	N	N	N	1	CUSTOMER ISSUE	-
DMS_05412	12204	N	N	N	1	CUSTOMER ISSUE	-
DMS_05414	12205	N	N	N	1	CUSTOMER ISSUE	-
DMS_05415	12206	N	N	N	1	CUSTOMER ISSUE	-
DMS_05416	12207	N	N	N	1	CUSTOMER ISSUE	-
DMS_05417	12208	N	N	N	1	CUSTOMER ISSUE	-
DMS_05418	12209	N	N	N	1	CUSTOMER ISSUE	-
DMS_05419	12210	N	N	N	1	CUSTOMER ISSUE	-
DMS_05420	12211	N	N	N	1	CUSTOMER ISSUE	-
DMS_05421	12212	N	N	N	1	CUSTOMER ISSUE	-
DMS_05422	12213	N	N	N	1	CUSTOMER ISSUE	-
DMS_05423	12214	N	N	N	1	CUSTOMER ISSUE	-
DMS_05424	12215	N	N	N	1	CUSTOMER ISSUE	-
DMS_05425	12216	N	N	N	1	CUSTOMER ISSUE	-

DMS_05426	12217	N	N	N	1	CUSTOMER ISSUE	-
DMS_05427	12218	N	N	N	1	CUSTOMER ISSUE	-
DMS_05428	12219	N	N	N	1	CUSTOMER ISSUE	-
DMS_05429	12220	N	N	N	1	CUSTOMER ISSUE	-
DMS_05430	12221	N	N	N	1	CUSTOMER ISSUE	-
DMS_05431	12222	N	N	N	1	CUSTOMER ISSUE	-
DMS_05432	12223	N	N	N	1	CUSTOMER ISSUE	-
DMS_05433	12224	N	N	N	1	CUSTOMER ISSUE	-
DMS_05434	12225	N	N	N	1	CUSTOMER ISSUE	-
DMS_05435	12226	N	N	N	1	CUSTOMER ISSUE	-
DMS_05436	12227	N	N	N	1	CUSTOMER ISSUE	-
DMS_05437	12228	N	N	N	1	CUSTOMER ISSUE	-
DMS_05438	12229	N	N	N	1	CUSTOMER ISSUE	-
DMS_05439	12230	N	N	N	1	CUSTOMER ISSUE	-
DMS_05440	12231	N	N	N	1	CUSTOMER ISSUE	-
DMS_05441	12232	N	N	N	1	CUSTOMER ISSUE	-
DMS_05442	12233	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05443	12234	N	N	N	1	CUSTOMER ISSUE	-
DMS_05444	12235	N	N	N	1	CUSTOMER ISSUE	-
DMS_05445	12236	N	N	N	1	CUSTOMER ISSUE	-
DMS_05446	12237	N	N	N	1	CUSTOMER ISSUE	-
DMS_05447	12238	N	N	N	1	CUSTOMER ISSUE	-
DMS_05448	12239	N	N	N	1	CUSTOMER ISSUE	-
DMS_05449	12240	N	N	N	1	CUSTOMER ISSUE	-
DMS_05450	12241	N	N	N	1	CUSTOMER ISSUE	-
DMS_05451	12242	N	N	N	1	CUSTOMER ISSUE	-
DMS_05452	12243	N	N	N	1	CUSTOMER ISSUE	-
DMS_05453	12244	N	N	N	1	CUSTOMER ISSUE	-
DMS_05454	12245	N	N	N	1	CUSTOMER ISSUE	-
DMS_05455	12246	N	N	N	1	CUSTOMER ISSUE	-
DMS_05456	12247	N	N	N	1	CUSTOMER ISSUE	-
DMS_05457	12248	N	N	N	1	CUSTOMER ISSUE	-
DMS_05458	12249	N	N	N	1	CUSTOMER ISSUE	-
DMS_05459	12250	N	N	N	1	CUSTOMER ISSUE	-
DMS_05460	12251	N	N	N	1	CUSTOMER ISSUE	-
DMS_05461	12252	N	N	N	1	CUSTOMER ISSUE	-
DMS_05462	12253	N	N	N	1	CUSTOMER ISSUE	-
DMS_05463	12254	N	N	N	1	CUSTOMER ISSUE	-
DMS_05464	12255	N	N	N	1	CUSTOMER ISSUE	-
DMS_05465	12256	N	N	N	1	CUSTOMER ISSUE	-
DMS_05466	12257	N	N	N	1	CUSTOMER ISSUE	-
DMS_05467	12258	N	N	N	1	CUSTOMER ISSUE	-
DMS_05468	12259	N	N	N	1	CUSTOMER ISSUE	-
DMS_05469	12260	N	N	N	1	CUSTOMER ISSUE	-
DMS_05470	12261	N	N	N	1	CUSTOMER ISSUE	-
DMS_05471	12262	N	N	N	1	CUSTOMER ISSUE	-
DMS_05472	12263	N	N	N	1	CUSTOMER ISSUE	-
DMS_05473	12264	N	N	N	1	CUSTOMER ISSUE	-
DMS_05474	12265	N	N	N	1	CUSTOMER ISSUE	-
DMS_05475	12266	N	N	N	1	CUSTOMER ISSUE	-
DMS_05477	12267	N	N	N	1	CUSTOMER ISSUE	-
DMS_05478	12268	N	N	N	1	CUSTOMER ISSUE	-
DMS_05479	12269	N	N	N	1	CUSTOMER ISSUE	-
DMS_05480	12270	N	N	N	1	CUSTOMER ISSUE	-
DMS_05481	12271	N	N	N	1	CUSTOMER ISSUE	-
DMS_05482	12272	N	N	N	1	CUSTOMER ISSUE	-
DMS_05483	12273	N	N	N	1	CUSTOMER ISSUE	-
DMS_05484	12274	N	N	N	1	CUSTOMER ISSUE	-
DMS_05485	12275	N	N	N	1	CUSTOMER ISSUE	-
DMS_05486	12276	N	N	N	1	CUSTOMER ISSUE	-
DMS_05487	12277	N	N	N	1	CUSTOMER ISSUE	-
DMS_05488	12278	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_05489	12279	N	N	N	1	CUSTOMER ISSUE	-
DMS_05490	12280	N	N	N	1	CUSTOMER ISSUE	-
DMS_05492	12281	N	N	N	1	CUSTOMER ISSUE	-
DMS_05493	12282	N	N	N	1	CUSTOMER ISSUE	-
DMS_05494	12283	N	N	N	1	CUSTOMER ISSUE	-
DMS_05495	12284	N	N	N	1	CUSTOMER ISSUE	-
DMS_05496	12285	N	N	N	1	CUSTOMER ISSUE	-
DMS_05497	12286	N	N	N	1	CUSTOMER ISSUE	-
DMS_05498	12287	N	N	N	1	CUSTOMER ISSUE	-
DMS_05499	12288	N	N	N	1	CUSTOMER ISSUE	-
DMS_05500	12289	N	N	N	1	CUSTOMER ISSUE	-
DMS_05501	12290	N	N	N	1	CUSTOMER ISSUE	-
DMS_05502	12291	N	N	N	1	CUSTOMER ISSUE	-
DMS_05503	12292	N	N	N	1	CUSTOMER ISSUE	-
DMS_05504	12293	N	N	N	1	CUSTOMER ISSUE	-
DMS_05505	12294	N	N	N	1	CUSTOMER ISSUE	-
DMS_05506	12295	N	N	N	1	CUSTOMER ISSUE	-
DMS_05507	12296	N	N	N	1	CUSTOMER ISSUE	-

DMS_05508	12297	N	N	N	1	CUSTOMER ISSUE	-
DMS_05509	12298	N	N	N	1	CUSTOMER ISSUE	-
DMS_05510	12299	N	N	N	1	CUSTOMER ISSUE	-
DMS_05511	12300	N	N	N	1	CUSTOMER ISSUE	-
DMS_05512	12301	N	N	N	1	CUSTOMER ISSUE	-
DMS_05514	12302	N	N	N	1	CUSTOMER ISSUE	-
DMS_05515	12303	N	N	N	1	CUSTOMER ISSUE	-
DMS_05516	12304	N	N	N	1	CUSTOMER ISSUE	-
DMS_05517	12305	N	N	N	1	CUSTOMER ISSUE	-
DMS_05518	12306	N	N	N	1	CUSTOMER ISSUE	-
DMS_05519	12307	N	N	N	1	CUSTOMER ISSUE	-
DMS_05520	12308	N	N	N	1	CUSTOMER ISSUE	-
DMS_05521	12309	N	N	N	1	CUSTOMER ISSUE	-
DMS_05522	12310	N	N	N	1	CUSTOMER ISSUE	-
DMS_05523	12311	N	N	N	1	CUSTOMER ISSUE	-
DMS_05524	12312	N	N	N	1	CUSTOMER ISSUE	-
DMS_05525	12313	N	N	N	1	CUSTOMER ISSUE	-
DMS_05526	12314	N	N	N	1	CUSTOMER ISSUE	-
DMS_05527	12315	N	N	N	1	CUSTOMER ISSUE	-
DMS_05528	12316	N	N	N	1	CUSTOMER ISSUE	-
DMS_05529	12317	N	N	N	1	CUSTOMER ISSUE	-
DMS_05530	12318	N	N	N	1	CUSTOMER ISSUE	-
DMS_05531	12319	N	N	N	1	CUSTOMER ISSUE	-
DMS_05532	12320	N	N	N	1	CUSTOMER ISSUE	-
DMS_05533	12321	N	N	N	1	CUSTOMER ISSUE	-
DMS_05534	12322	N	N	N	1	CUSTOMER ISSUE	-
DMS_05535	12323	N	N	N	1	CUSTOMER ISSUE	-
DMS_05536	12324	N	N	N	1	CUSTOMER ISSUE	-
DMS_05537	12325	N	N	N	1	CUSTOMER ISSUE	-
DMS_05538	12326	N	N	N	1	CUSTOMER ISSUE	-
DMS_05539	12327	N	N	N	1	CUSTOMER ISSUE	-
DMS_05540	12328	N	N	N	1	CUSTOMER ISSUE	-
DMS_05545	12329	N	N	N	1	CUSTOMER ISSUE	-
DMS_05546	12330	N	N	N	1	CUSTOMER ISSUE	-
DMS_05547	12331	N	N	N	1	CUSTOMER ISSUE	-
DMS_05548	12332	N	N	N	1	CUSTOMER ISSUE	-
DMS_05549	12333	N	N	N	1	CUSTOMER ISSUE	-
DMS_05550	12334	N	N	N	1	CUSTOMER ISSUE	-
DMS_05551	12335	N	N	N	1	CUSTOMER ISSUE	-
DMS_05552	12336	N	N	N	1	CUSTOMER ISSUE	-
DMS_05553	12337	N	N	N	1	CUSTOMER ISSUE	-
DMS_05554	12338	N	N	N	1	CUSTOMER ISSUE	-
DMS_05555	12339	N	N	N	1	CUSTOMER ISSUE	-
DMS_05556	12340	N	N	N	1	CUSTOMER ISSUE	-
DMS_05557	12341	N	N	N	1	CUSTOMER ISSUE	-
DMS_05558	12342	N	N	N	1	CUSTOMER ISSUE	-
DMS_05559	12343	N	N	N	1	CUSTOMER ISSUE	-
DMS_05560	12344	N	N	N	1	CUSTOMER ISSUE	-
DMS_05561	12345	N	N	N	1	CUSTOMER ISSUE	-
DMS_05562	12346	N	N	N	1	CUSTOMER ISSUE	-
DMS_05563	12347	N	N	N	1	CUSTOMER ISSUE	-
DMS_05564	12348	N	N	N	1	CUSTOMER ISSUE	-
DMS_05565	12349	N	N	N	1	CUSTOMER ISSUE	-
DMS_05566	12350	N	N	N	1	CUSTOMER ISSUE	-
DMS_05567	12351	N	N	N	1	CUSTOMER ISSUE	-
DMS_05568	12352	N	N	N	1	CUSTOMER ISSUE	-
DMS_05569	12353	N	N	N	1	CUSTOMER ISSUE	-
DMS_05570	12354	N	N	N	1	CUSTOMER ISSUE	-
DMS_05571	12355	N	N	N	1	CUSTOMER ISSUE	-
DMS_05572	12356	N	N	N	1	CUSTOMER ISSUE	-
DMS_05573	12357	N	N	N	1	CUSTOMER ISSUE	-
DMS_05574	12358	N	N	N	1	CUSTOMER ISSUE	-
DMS_05575	12359	N	N	N	1	CUSTOMER ISSUE	-
DMS_05576	12360	N	N	N	1	CUSTOMER ISSUE	-
DMS_05577	12361	N	N	N	1	CUSTOMER ISSUE	-
DMS_05578	12362	N	N	N	1	CUSTOMER ISSUE	-
DMS_05579	12363	N	N	N	2	CUSTOMER ISSUE	-
DMS_05580	12364	N	N	N	1	CUSTOMER ISSUE	-
DMS_05582	12365	N	N	N	1	CUSTOMER ISSUE	-
DMS_05583	12366	N	N	N	1	CUSTOMER ISSUE	-
DMS_05584	12367	N	N	N	1	CUSTOMER ISSUE	-
DMS_05585	12368	N	N	N	1	CUSTOMER ISSUE	-
DMS_05586	12369	N	N	N	1	CUSTOMER ISSUE	-
DMS_05587	12370	N	N	N	1	CUSTOMER ISSUE	-
DMS_05588	12371	N	N	N	1	CUSTOMER ISSUE	-
DMS_05589	12372	N	N	N	1	CUSTOMER ISSUE	-
DMS_05590	12373	N	N	N	1	CUSTOMER ISSUE	-
DMS_05591	12374	N	N	N	1	CUSTOMER ISSUE	-
DMS_05593	12375	N	N	N	1	CUSTOMER ISSUE	-
DMS_05594	12376	N	N	N	1	CUSTOMER ISSUE	-

DMS_05595	12377	N	N	N	1	CUSTOMER ISSUE	-
DMS_05596	12378	N	N	N	1	CUSTOMER ISSUE	-
DMS_05597	12379	N	N	N	1	CUSTOMER ISSUE	-
DMS_05598	12380	N	N	N	1	CUSTOMER ISSUE	-
DMS_05599	12381	N	N	N	1	CUSTOMER ISSUE	-
DMS_05600	12382	N	N	N	1	CUSTOMER ISSUE	-
DMS_05601	12383	N	N	N	1	CUSTOMER ISSUE	-
DMS_05602	12384	N	N	N	1	CUSTOMER ISSUE	-
DMS_05603	12385	N	N	N	1	CUSTOMER ISSUE	-
DMS_05604	12386	N	N	N	1	CUSTOMER ISSUE	-
DMS_05606	12387	N	N	N	1	CUSTOMER ISSUE	-
DMS_05607	12388	N	N	N	1	CUSTOMER ISSUE	-
DMS_05608	12389	N	N	N	1	CUSTOMER ISSUE	-
DMS_05609	12390	N	N	N	1	CUSTOMER ISSUE	-
DMS_05610	12391	N	N	N	1	CUSTOMER ISSUE	-
DMS_05611	12392	N	N	N	1	CUSTOMER ISSUE	-
DMS_05612	12393	N	N	N	1	CUSTOMER ISSUE	-
DMS_05613	12394	N	N	N	1	CUSTOMER ISSUE	-
DMS_05614	12395	N	N	N	1	CUSTOMER ISSUE	-
DMS_05615	12396	N	N	N	1	CUSTOMER ISSUE	-
DMS_05616	12397	N	N	N	1	CUSTOMER ISSUE	-
DMS_05617	12398	N	N	N	1	CUSTOMER ISSUE	-
DMS_05618	12399	N	N	N	1	CUSTOMER ISSUE	-
DMS_05619	12400	N	N	N	1	CUSTOMER ISSUE	-
DMS_05621	12401	N	N	N	1	CUSTOMER ISSUE	-
DMS_05622	12402	N	N	N	1	CUSTOMER ISSUE	-
DMS_05623	12403	N	N	N	1	CUSTOMER ISSUE	-
DMS_05624	12404	N	N	N	1	CUSTOMER ISSUE	-
DMS_05625	12405	N	N	N	1	CUSTOMER ISSUE	-
DMS_05626	12406	N	N	N	2	CUSTOMER ISSUE	-
DMS_05627	12407	N	N	N	1	CUSTOMER ISSUE	-
DMS_05629	12408	N	N	N	1	CUSTOMER ISSUE	-
DMS_05630	12409	N	N	N	1	CUSTOMER ISSUE	-
DMS_05631	12410	N	N	N	1	CUSTOMER ISSUE	-
DMS_05632	12411	N	N	N	1	CUSTOMER ISSUE	-
DMS_05633	12412	N	N	N	1	CUSTOMER ISSUE	-
DMS_05634	12413	N	N	N	1	CUSTOMER ISSUE	-
DMS_05635	12414	N	N	N	1	CUSTOMER ISSUE	-
DMS_05636	12415	N	N	N	1	CUSTOMER ISSUE	-
DMS_05637	12416	N	N	N	1	CUSTOMER ISSUE	-
DMS_05638	12417	N	N	N	1	CUSTOMER ISSUE	-
DMS_05639	12418	N	N	N	1	CUSTOMER ISSUE	-
DMS_05640	12419	N	N	N	1	CUSTOMER ISSUE	-
DMS_05641	12420	N	N	N	1	CUSTOMER ISSUE	-
DMS_05642	12421	N	N	N	1	CUSTOMER ISSUE	-
DMS_05643	12422	N	N	N	1	CUSTOMER ISSUE	-
DMS_05645	12423	N	N	N	1	CUSTOMER ISSUE	-
DMS_05646	12424	N	N	N	1	CUSTOMER ISSUE	-
DMS_05647	12425	N	N	N	1	CUSTOMER ISSUE	-
DMS_05648	12426	N	N	N	1	CUSTOMER ISSUE	-
DMS_05649	12427	N	N	N	1	CUSTOMER ISSUE	-
DMS_05650	12428	N	N	N	1	CUSTOMER ISSUE	-
DMS_05651	12429	N	N	N	1	CUSTOMER ISSUE	-
DMS_05652	12430	N	N	N	1	CUSTOMER ISSUE	-
DMS_05653	12431	N	N	N	1	CUSTOMER ISSUE	-
DMS_05654	12432	N	N	N	1	CUSTOMER ISSUE	-
DMS_05655	12433	N	N	N	1	CUSTOMER ISSUE	-
DMS_05657	12434	N	N	N	1	CUSTOMER ISSUE	-
DMS_05658	12435	N	N	N	1	CUSTOMER ISSUE	-
DMS_05659	12436	N	N	N	1	CUSTOMER ISSUE	-
DMS_05660	12437	N	N	N	1	CUSTOMER ISSUE	-
DMS_05661	12438	N	N	N	1	CUSTOMER ISSUE	-
DMS_05662	12439	N	N	N	1	CUSTOMER ISSUE	-
DMS_05663	12440	N	N	N	1	CUSTOMER ISSUE	-
DMS_05664	12441	N	N	N	1	CUSTOMER ISSUE	-
DMS_05665	12442	N	N	N	1	CUSTOMER ISSUE	-
DMS_05666	12443	N	N	N	1	CUSTOMER ISSUE	-
DMS_05667	12444	N	N	N	1	CUSTOMER ISSUE	-
DMS_05668	12445	N	N	N	1	CUSTOMER ISSUE	-
DMS_05669	12446	N	N	N	1	CUSTOMER ISSUE	-
DMS_05670	12447	N	N	N	1	CUSTOMER ISSUE	-
DMS_05671	12448	N	N	N	1	CUSTOMER ISSUE	-
DMS_05672	12449	N	N	N	1	CUSTOMER ISSUE	-
DMS_05673	12450	N	N	N	1	CUSTOMER ISSUE	-
DMS_05674	12451	N	N	N	1	CUSTOMER ISSUE	-
DMS_05675	12452	N	N	N	1	CUSTOMER ISSUE	-
DMS_05676	12453	N	N	N	1	CUSTOMER ISSUE	-
DMS_05677	12454	N	N	N	1	CUSTOMER ISSUE	-
DMS_05678	12455	N	N	N	1	CUSTOMER ISSUE	-
DMS_05679	12456	N	N	N	1	CUSTOMER ISSUE	-

DMS_05680	12457	N	N	N	1	CUSTOMER ISSUE	-
DMS_05681	12458	N	N	N	1	CUSTOMER ISSUE	-
DMS_05682	12459	N	N	N	1	CUSTOMER ISSUE	-
DMS_05683	12460	N	N	N	1	CUSTOMER ISSUE	-
DMS_05685	12461	N	N	N	1	CUSTOMER ISSUE	-
DMS_05686	12462	N	N	N	1	CUSTOMER ISSUE	-
DMS_05687	12463	N	N	N	1	CUSTOMER ISSUE	-
DMS_05688	12464	N	N	N	1	CUSTOMER ISSUE	-
DMS_05689	12465	N	N	N	1	CUSTOMER ISSUE	-
DMS_05690	12466	N	N	N	1	CUSTOMER ISSUE	-
DMS_05691	12467	N	N	N	1	CUSTOMER ISSUE	-
DMS_05692	12468	N	N	N	1	CUSTOMER ISSUE	-
DMS_05693	12469	N	N	N	1	CUSTOMER ISSUE	-
DMS_05694	12470	N	N	N	1	CUSTOMER ISSUE	-
DMS_05695	12471	N	N	N	1	CUSTOMER ISSUE	-
DMS_05696	12472	N	N	N	1	CUSTOMER ISSUE	-
DMS_05697	12473	N	N	N	1	CUSTOMER ISSUE	-
DMS_05698	12474	N	N	N	1	CUSTOMER ISSUE	-
DMS_05700	12475	N	N	N	1	CUSTOMER ISSUE	-
DMS_05701	12476	N	N	N	1	CUSTOMER ISSUE	-
DMS_05702	12477	N	N	N	1	CUSTOMER ISSUE	-
DMS_05703	12478	N	N	N	1	CUSTOMER ISSUE	-
DMS_05704	12479	N	N	N	1	CUSTOMER ISSUE	-
DMS_05705	12480	N	N	N	1	CUSTOMER ISSUE	-
DMS_05706	12481	N	N	N	1	CUSTOMER ISSUE	-
DMS_05707	12482	N	N	N	1	CUSTOMER ISSUE	-
DMS_05708	12483	N	N	N	1	CUSTOMER ISSUE	-
DMS_05709	12484	N	N	N	1	CUSTOMER ISSUE	-
DMS_05710	12485	N	N	N	1	CUSTOMER ISSUE	-
DMS_05711	12486	N	N	N	1	CUSTOMER ISSUE	-
DMS_05712	12487	N	N	N	1	CUSTOMER ISSUE	-
DMS_05713	12488	N	N	N	1	CUSTOMER ISSUE	-
DMS_05714	12489	N	N	N	1	CUSTOMER ISSUE	-
DMS_05716	12490	N	N	N	1	CUSTOMER ISSUE	-
DMS_05717	12491	N	N	N	1	CUSTOMER ISSUE	-
DMS_05718	12492	N	N	N	1	CUSTOMER ISSUE	-
DMS_05719	12493	N	N	N	1	CUSTOMER ISSUE	-
DMS_05720	12494	N	N	N	1	CUSTOMER ISSUE	-
DMS_05721	12495	N	N	N	1	CUSTOMER ISSUE	-
DMS_05723	12496	N	N	N	1	CUSTOMER ISSUE	-
DMS_05725	12497	N	N	N	1	CUSTOMER ISSUE	-
DMS_05726	12498	N	N	N	1	CUSTOMER ISSUE	-
DMS_05727	12499	N	N	N	1	CUSTOMER ISSUE	-
DMS_05729	12500	N	N	N	1	CUSTOMER ISSUE	-
DMS_05730	12501	N	N	N	1	CUSTOMER ISSUE	-
DMS_05731	12502	N	N	N	1	CUSTOMER ISSUE	-
DMS_05732	12503	N	N	N	1	CUSTOMER ISSUE	-
DMS_05733	12504	N	N	N	1	CUSTOMER ISSUE	-
DMS_05734	12505	N	N	N	1	CUSTOMER ISSUE	-
DMS_05735	12506	N	N	N	1	CUSTOMER ISSUE	-
DMS_05736	12507	N	N	N	1	CUSTOMER ISSUE	-
DMS_05737	12508	N	N	N	1	CUSTOMER ISSUE	-
DMS_05739	12509	N	N	N	1	CUSTOMER ISSUE	-
DMS_05740	12510	N	N	N	1	CUSTOMER ISSUE	-
DMS_05741	12511	N	N	N	1	CUSTOMER ISSUE	-
DMS_05742	12512	N	N	N	1	CUSTOMER ISSUE	-
DMS_05743	12513	N	N	N	1	CUSTOMER ISSUE	-
DMS_05744	12514	N	N	N	1	CUSTOMER ISSUE	-
DMS_05745	12515	N	N	N	1	CUSTOMER ISSUE	-
DMS_05746	12516	N	N	N	1	CUSTOMER ISSUE	-
DMS_05748	12517	N	N	N	1	CUSTOMER ISSUE	-
DMS_05749	12518	N	N	N	1	CUSTOMER ISSUE	-
DMS_05750	12519	N	N	N	1	CUSTOMER ISSUE	-
DMS_05751	12520	N	N	N	1	CUSTOMER ISSUE	-
DMS_05752	12521	N	N	N	1	CUSTOMER ISSUE	-
DMS_05754	12522	N	N	N	1	CUSTOMER ISSUE	-
DMS_05755	12523	N	N	N	1	CUSTOMER ISSUE	-
DMS_05756	12524	N	N	N	1	CUSTOMER ISSUE	-
DMS_05757	12525	N	N	N	1	CUSTOMER ISSUE	-
DMS_05759	12526	N	N	N	1	CUSTOMER ISSUE	-
DMS_05760	12527	N	N	N	1	CUSTOMER ISSUE	-
DMS_05761	12528	N	N	N	1	CUSTOMER ISSUE	-
DMS_05762	12529	N	N	N	1	CUSTOMER ISSUE	-
DMS_05763	12530	N	N	N	1	CUSTOMER ISSUE	-
DMS_05764	12531	N	N	N	1	CUSTOMER ISSUE	-
DMS_05765	12532	N	N	N	1	CUSTOMER ISSUE	-
DMS_05766	12533	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05767	12534	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05768	12535	N	N	N	1	CUSTOMER ISSUE	-
DMS_05769	12536	N	N	N	1	CUSTOMER ISSUE	-

DMS_05770	12537	N	N	N	1	CUSTOMER ISSUE	-
DMS_05772	12538	N	N	N	1	CUSTOMER ISSUE	-
DMS_05773	12539	N	N	N	1	CUSTOMER ISSUE	-
DMS_05774	12540	N	N	N	1	CUSTOMER ISSUE	-
DMS_05775	12541	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05776	12542	N	N	N	1	CUSTOMER ISSUE	-
DMS_05777	12543	N	N	N	1	CUSTOMER ISSUE	-
DMS_05779	12544	N	N	N	1	CUSTOMER ISSUE	-
DMS_05780	12545	N	N	Y	1	TX - REPLACE	2500
DMS_05783	12546	N	N	N	1	CUSTOMER ISSUE	-
DMS_05784	12547	N	N	N	1	CUSTOMER ISSUE	-
DMS_05785	12548	N	N	N	1	CUSTOMER ISSUE	-
DMS_05786	12549	N	N	N	1	CUSTOMER ISSUE	-
DMS_05787	12550	N	N	N	1	CUSTOMER ISSUE	-
DMS_05788	12551	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_05789	12552	N	N	N	1	CUSTOMER ISSUE	-
DMS_05791	12553	N	N	N	1	CUSTOMER ISSUE	-
DMS_05792	12554	N	N	N	1	CUSTOMER ISSUE	-
DMS_05793	12555	N	N	N	1	CUSTOMER ISSUE	-
DMS_05794	12556	N	N	N	1	CUSTOMER ISSUE	-
DMS_05795	12557	N	N	N	1	CUSTOMER ISSUE	-
DMS_05796	12558	N	N	N	1	CUSTOMER ISSUE	-
DMS_05797	12559	N	N	N	1	CUSTOMER ISSUE	-
DMS_05798	12560	N	N	N	1	CUSTOMER ISSUE	-
DMS_05799	12561	N	N	N	1	CUSTOMER ISSUE	-
DMS_05800	12562	N	N	N	1	CUSTOMER ISSUE	-
DMS_05802	12563	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05803	12564	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05804	12565	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05805	12566	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05806	12567	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05807	12568	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05808	12569	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05809	12570	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05810	12571	N	N	N	1	CUSTOMER ISSUE	-
DMS_05811	12572	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05812	12573	N	N	N	1	CUSTOMER ISSUE	-
DMS_05813	12574	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05814	12575	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05815	12576	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05816	12577	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05817	12578	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05818	12579	N	N	N	1	CUSTOMER ISSUE	-
DMS_05819	12580	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05820	12581	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05822	12582	N	N	N	1	CUSTOMER ISSUE	-
DMS_05823	12583	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05824	12584	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05825	12585	N	N	N	1	CUSTOMER ISSUE	-
DMS_05826	12586	N	N	N	1	CUSTOMER ISSUE	-
DMS_05827	12587	N	N	N	1	CUSTOMER ISSUE	-
DMS_05828	12588	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_05829	12589	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_05830	12590	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05831	12591	N	N	N	1	CUSTOMER ISSUE	-
DMS_05832	12592	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05833	12593	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05834	12594	N	N	N	1	CUSTOMER ISSUE	-
DMS_05835	12595	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05836	12596	N	N	N	1	CUSTOMER ISSUE	-
DMS_05837	12597	N	N	N	1	CUSTOMER ISSUE	-
DMS_05838	12598	N	N	N	1	CUSTOMER ISSUE	-
DMS_05839	12599	N	N	N	1	CUSTOMER ISSUE	-
DMS_05840	12600	N	N	N	1	CUSTOMER ISSUE	-
DMS_05841	12601	N	N	N	1	CUSTOMER ISSUE	-
DMS_05842	12602	N	N	N	1	CUSTOMER ISSUE	-
DMS_05843	12603	N	N	N	1	CUSTOMER ISSUE	-
DMS_05844	12604	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_05845	12605	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_05846	12606	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_05847	12607	N	N	N	1	CUSTOMER ISSUE	-
DMS_05849	12608	N	N	N	1	CUSTOMER ISSUE	-
DMS_05850	12609	N	N	N	1	CUSTOMER ISSUE	-
DMS_05851	12610	N	N	N	1	CUSTOMER ISSUE	-
DMS_05852	12611	N	N	N	1	CUSTOMER ISSUE	-
DMS_05853	12612	N	N	N	1	CUSTOMER ISSUE	-
DMS_05854	12613	N	N	N	1	CUSTOMER ISSUE	-
DMS_05855	12614	N	N	N	1	CUSTOMER ISSUE	-
DMS_05856	12615	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05857	12616	N	N	N	1	CUSTOMER ISSUE	-

DMS_05859	12617	N	N	N	1	CUSTOMER ISSUE	-
DMS_05860	12618	N	N	N	1	CUSTOMER ISSUE	-
DMS_05861	12619	N	N	N	1	CUSTOMER ISSUE	-
DMS_05862	12620	N	N	N	1	CUSTOMER ISSUE	-
DMS_05863	12621	N	N	N	1	CUSTOMER ISSUE	-
DMS_05864	12622	N	N	N	1	CUSTOMER ISSUE	-
DMS_05865	12623	N	N	N	1	CUSTOMER ISSUE	-
DMS_05866	12624	N	N	N	1	CUSTOMER ISSUE	-
DMS_05867	12625	N	N	N	1	CUSTOMER ISSUE	-
DMS_05868	12626	N	N	N	1	CUSTOMER ISSUE	-
DMS_05869	12627	N	N	N	1	CUSTOMER ISSUE	-
DMS_05870	12628	N	N	N	1	CUSTOMER ISSUE	-
DMS_05871	12629	N	N	N	1	CUSTOMER ISSUE	-
DMS_05872	12630	N	N	N	1	CUSTOMER ISSUE	-
DMS_05873	12631	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05874	12632	N	N	N	1	CUSTOMER ISSUE	-
DMS_05875	12633	N	N	N	1	CUSTOMER ISSUE	-
DMS_05876	12634	N	N	N	1	CUSTOMER ISSUE	-
DMS_05877	12635	N	N	N	1	CUSTOMER ISSUE	-
DMS_05879	12636	N	N	N	1	CUSTOMER ISSUE	-
DMS_05880	12637	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05881	12638	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05882	12639	N	N	N	1	CUSTOMER ISSUE	-
DMS_05883	12640	N	N	N	1	CUSTOMER ISSUE	-
DMS_05884	12641	N	N	N	1	CUSTOMER ISSUE	-
DMS_05885	12642	N	N	N	1	CUSTOMER ISSUE	-
DMS_05886	12643	N	N	N	1	CUSTOMER ISSUE	-
DMS_05887	12644	N	N	N	1	CUSTOMER ISSUE	-
DMS_05888	12645	N	N	N	1	CUSTOMER ISSUE	-
DMS_05889	12646	N	N	N	1	CUSTOMER ISSUE	-
DMS_05890	12647	N	N	N	1	CUSTOMER ISSUE	-
DMS_05891	12648	N	N	N	1	CUSTOMER ISSUE	-
DMS_05892	12649	N	N	N	1	CUSTOMER ISSUE	-
DMS_05893	12650	N	N	N	1	CUSTOMER ISSUE	-
DMS_05894	12651	N	N	N	1	CUSTOMER ISSUE	-
DMS_05895	12652	N	N	N	1	CUSTOMER ISSUE	-
DMS_05896	12653	N	N	N	1	CUSTOMER ISSUE	-
DMS_05897	12654	N	N	N	1	CUSTOMER ISSUE	-
DMS_05898	12655	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05899	12656	N	N	N	1	CUSTOMER ISSUE	-
DMS_05900	12657	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_05901	12658	N	N	N	1	CUSTOMER ISSUE	-
DMS_05902	12659	N	N	N	1	CUSTOMER ISSUE	-
DMS_05903	12660	N	N	N	1	CUSTOMER ISSUE	-
DMS_05904	12661	N	N	N	1	CUSTOMER ISSUE	-
DMS_05905	12662	N	N	N	1	CUSTOMER ISSUE	-
DMS_05906	12663	N	N	N	1	CUSTOMER ISSUE	-
DMS_05908	12664	N	N	N	1	CUSTOMER ISSUE	-
DMS_05909	12665	N	N	N	1	CUSTOMER ISSUE	-
DMS_05910	12666	N	N	N	1	CUSTOMER ISSUE	-
DMS_05911	12667	N	N	N	1	CUSTOMER ISSUE	-
DMS_05912	12668	N	N	N	1	CUSTOMER ISSUE	-
DMS_05913	12669	N	N	N	1	CUSTOMER ISSUE	-
DMS_05914	12670	N	N	N	1	CUSTOMER ISSUE	-
DMS_05915	12671	N	N	N	1	CUSTOMER ISSUE	-
DMS_05916	12672	N	N	N	1	CUSTOMER ISSUE	-
DMS_05917	12673	N	N	N	1	CUSTOMER ISSUE	-
DMS_05918	12674	N	N	N	1	CUSTOMER ISSUE	-
DMS_05919	12675	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_05920	12676	N	N	N	1	CUSTOMER ISSUE	-
DMS_05921	12677	N	N	N	1	CUSTOMER ISSUE	-
DMS_05922	12678	N	N	N	1	CUSTOMER ISSUE	-
DMS_05923	12679	N	N	N	1	CUSTOMER ISSUE	-
DMS_05924	12680	N	N	N	1	CUSTOMER ISSUE	-
DMS_05925	12681	N	N	N	1	CUSTOMER ISSUE	-
DMS_05926	12682	N	N	N	1	CUSTOMER ISSUE	-
DMS_05927	12683	N	N	N	1	CUSTOMER ISSUE	-
DMS_05928	12684	N	N	N	1	CUSTOMER ISSUE	-
DMS_05929	12685	N	N	N	1	CUSTOMER ISSUE	-
DMS_05930	12686	N	N	N	1	CUSTOMER ISSUE	-
DMS_05931	12687	N	N	N	1	CUSTOMER ISSUE	-
DMS_05932	12688	N	N	N	1	CUSTOMER ISSUE	-
DMS_05933	12689	N	N	N	1	CUSTOMER ISSUE	-
DMS_05934	12690	N	N	N	1	CUSTOMER ISSUE	-
DMS_05935	12691	N	N	N	1	CUSTOMER ISSUE	-
DMS_05936	12692	N	N	N	1	CUSTOMER ISSUE	-
DMS_05937	12693	N	N	N	1	CUSTOMER ISSUE	-
DMS_05938	12694	N	N	N	1	CUSTOMER ISSUE	-
DMS_05939	12695	N	N	N	1	CUSTOMER ISSUE	-
DMS_05940	12696	N	N	N	1	CUSTOMER ISSUE	-

DMS_05941	12697	N	N	N	1	CUSTOMER ISSUE	-
DMS_05942	12698	N	N	Y	1	TX - REPLACE	2500
DMS_05943	12699	N	N	N	1	CUSTOMER ISSUE	-
DMS_05945	12700	N	N	N	1	CUSTOMER ISSUE	-
DMS_05946	12701	N	N	N	1	CUSTOMER ISSUE	-
DMS_05950	12702	N	N	N	1	CUSTOMER ISSUE	-
DMS_05951	12703	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_05952	12704	N	N	N	1	CUSTOMER ISSUE	-
DMS_05953	12705	N	N	N	1	CUSTOMER ISSUE	-
DMS_05954	12706	N	N	N	1	CUSTOMER ISSUE	-
DMS_05955	12707	N	N	N	1	CUSTOMER ISSUE	-
DMS_05956	12708	N	N	N	1	CUSTOMER ISSUE	-
DMS_05957	12709	N	N	N	1	CUSTOMER ISSUE	-
DMS_05958	12710	N	N	N	1	CUSTOMER ISSUE	-
DMS_05959	12711	N	N	N	1	CUSTOMER ISSUE	-
DMS_05960	12712	N	N	N	1	CUSTOMER ISSUE	-
DMS_05961	12713	N	N	N	1	CUSTOMER ISSUE	-
DMS_05963	12714	N	N	N	1	CUSTOMER ISSUE	-
DMS_05964	12715	N	N	N	1	CUSTOMER ISSUE	-
DMS_05967	12716	N	N	N	1	CUSTOMER ISSUE	-
DMS_05968	12717	N	N	N	1	CUSTOMER ISSUE	-
DMS_05969	12718	N	N	N	1	CUSTOMER ISSUE	-
DMS_05970	12719	N	N	N	1	CUSTOMER ISSUE	-
DMS_05971	12720	N	N	N	1	CUSTOMER ISSUE	-
DMS_05972	12721	N	N	N	1	CUSTOMER ISSUE	-
DMS_05973	12722	N	N	N	1	CUSTOMER ISSUE	-
DMS_05974	12723	N	N	N	1	CUSTOMER ISSUE	-
DMS_05975	12724	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_05977	12725	N	N	N	1	CUSTOMER ISSUE	-
DMS_05978	12726	N	N	N	1	CUSTOMER ISSUE	-
DMS_05980	12727	N	N	N	1	CUSTOMER ISSUE	-
DMS_05981	12728	N	N	N	1	CUSTOMER ISSUE	-
DMS_05986	12729	N	N	N	1	CUSTOMER ISSUE	-
DMS_05987	12730	N	N	N	1	CUSTOMER ISSUE	-
DMS_05989	12731	N	N	N	1	CUSTOMER ISSUE	-
DMS_05990	12732	N	N	N	1	CUSTOMER ISSUE	-
DMS_05991	12733	N	N	N	1	CUSTOMER ISSUE	-
DMS_05992	12734	N	N	N	1	CUSTOMER ISSUE	-
DMS_05993	12735	N	N	N	1	CUSTOMER ISSUE	-
DMS_05994	12736	N	N	N	1	CUSTOMER ISSUE	-
DMS_05995	12737	N	N	N	1	CUSTOMER ISSUE	-
DMS_05996	12738	N	N	N	1	CUSTOMER ISSUE	-
DMS_05997	12739	N	N	N	1	CUSTOMER ISSUE	-
DMS_05998	12740	N	N	N	1	CUSTOMER ISSUE	-
DMS_05999	12741	N	N	N	1	CUSTOMER ISSUE	-
DMS_06000	12742	N	N	N	1	CUSTOMER ISSUE	-
DMS_06001	12743	N	N	N	1	CUSTOMER ISSUE	-
DMS_06002	12744	N	N	N	1	CUSTOMER ISSUE	-
DMS_06004	12745	N	N	N	1	CUSTOMER ISSUE	-
DMS_06005	12746	N	N	N	1	CUSTOMER ISSUE	-
DMS_06006	12747	N	N	N	1	CUSTOMER ISSUE	-
DMS_06007	12748	N	N	N	1	CUSTOMER ISSUE	-
DMS_06008	12749	N	N	N	1	CUSTOMER ISSUE	-
DMS_06009	12750	N	N	N	1	CUSTOMER ISSUE	-
DMS_06010	12751	N	N	N	1	CUSTOMER ISSUE	-
DMS_06011	12752	N	N	N	1	CUSTOMER ISSUE	-
DMS_06012	12753	N	N	N	1	CUSTOMER ISSUE	-
DMS_06013	12754	N	N	N	1	CUSTOMER ISSUE	-
DMS_06015	12755	N	N	N	1	CUSTOMER ISSUE	-
DMS_06016	12756	N	N	N	1	CUSTOMER ISSUE	-
DMS_06017	12757	N	N	N	1	CUSTOMER ISSUE	-
DMS_06018	12758	N	N	N	1	CUSTOMER ISSUE	-
DMS_06019	12759	N	N	N	1	CUSTOMER ISSUE	-
DMS_06020	12760	N	N	N	1	CUSTOMER ISSUE	-
DMS_06021	12761	N	N	N	1	CUSTOMER ISSUE	-
DMS_06022	12762	N	N	N	1	CUSTOMER ISSUE	-
DMS_06024	12763	N	N	N	1	CUSTOMER ISSUE	-
DMS_06025	12764	N	N	N	1	CUSTOMER ISSUE	-
DMS_06026	12765	N	N	N	1	CUSTOMER ISSUE	-
DMS_06027	12766	N	N	N	1	CUSTOMER ISSUE	-
DMS_06028	12767	N	N	N	1	CUSTOMER ISSUE	-
DMS_06029	12768	N	N	N	1	CUSTOMER ISSUE	-
DMS_06030	12769	N	N	N	1	CUSTOMER ISSUE	-
DMS_06032	12770	N	N	N	1	CUSTOMER ISSUE	-
DMS_06034	12771	N	N	N	1	CUSTOMER ISSUE	-
DMS_06035	12772	N	N	N	1	CUSTOMER ISSUE	-
DMS_06036	12773	N	N	N	1	CUSTOMER ISSUE	-
DMS_06037	12774	N	N	N	1	CUSTOMER ISSUE	-
DMS_06038	12775	N	N	N	1	CUSTOMER ISSUE	-
DMS_06039	12776	N	N	N	1	CUSTOMER ISSUE	-

DMS_06040	12777	N	N	N	1	CUSTOMER ISSUE	-
DMS_06041	12778	N	N	N	1	CUSTOMER ISSUE	-
DMS_06042	12779	N	N	N	1	CUSTOMER ISSUE	-
DMS_06043	12780	N	N	N	1	CUSTOMER ISSUE	-
DMS_06044	12781	N	N	N	1	CUSTOMER ISSUE	-
DMS_06045	12782	N	N	N	1	CUSTOMER ISSUE	-
DMS_06046	12783	N	N	N	1	CUSTOMER ISSUE	-
DMS_06047	12784	N	N	N	1	CUSTOMER ISSUE	-
DMS_06048	12785	N	N	N	1	CUSTOMER ISSUE	-
DMS_06049	12786	N	N	N	1	CUSTOMER ISSUE	-
DMS_06050	12787	N	N	N	1	CUSTOMER ISSUE	-
DMS_06051	12788	N	N	N	1	CUSTOMER ISSUE	-
DMS_06052	12789	N	N	N	1	CUSTOMER ISSUE	-
DMS_06053	12790	N	N	N	1	CUSTOMER ISSUE	-
DMS_06054	12791	N	N	N	1	CUSTOMER ISSUE	-
DMS_06055	12792	N	N	N	1	CUSTOMER ISSUE	-
DMS_06056	12793	N	N	N	1	CUSTOMER ISSUE	-
DMS_06057	12794	N	N	N	1	CUSTOMER ISSUE	-
DMS_06058	12795	N	N	N	1	CUSTOMER ISSUE	-
DMS_06059	12796	N	N	N	1	CUSTOMER ISSUE	-
DMS_06060	12797	N	N	N	1	CUSTOMER ISSUE	-
DMS_06061	12798	N	N	N	1	CUSTOMER ISSUE	-
DMS_06062	12799	N	N	N	1	CUSTOMER ISSUE	-
DMS_06063	12800	N	N	N	1	CUSTOMER ISSUE	-
DMS_06064	12801	N	N	N	1	CUSTOMER ISSUE	-
DMS_06065	12802	N	N	N	1	CUSTOMER ISSUE	-
DMS_06066	12803	N	N	N	1	CUSTOMER ISSUE	-
DMS_06067	12804	N	N	N	1	CUSTOMER ISSUE	-
DMS_06068	12805	N	N	N	1	CUSTOMER ISSUE	-
DMS_06069	12806	N	N	N	1	CUSTOMER ISSUE	-
DMS_06070	12807	N	N	N	1	CUSTOMER ISSUE	-
DMS_06071	12808	N	N	N	1	CUSTOMER ISSUE	-
DMS_06072	12809	N	N	N	1	CUSTOMER ISSUE	-
DMS_06073	12810	N	N	N	1	CUSTOMER ISSUE	-
DMS_06074	12811	N	N	N	1	CUSTOMER ISSUE	-
DMS_06075	12812	N	N	N	1	CUSTOMER ISSUE	-
DMS_06076	12813	N	N	N	1	CUSTOMER ISSUE	-
DMS_06077	12814	N	N	N	1	CUSTOMER ISSUE	-
DMS_06078	12815	N	N	N	1	CUSTOMER ISSUE	-
DMS_06079	12816	N	N	N	1	CUSTOMER ISSUE	-
DMS_06080	12817	N	N	N	1	CUSTOMER ISSUE	-
DMS_06081	12818	N	N	N	1	CUSTOMER ISSUE	-
DMS_06082	12819	N	N	N	1	CUSTOMER ISSUE	-
DMS_06084	12820	N	N	N	1	CUSTOMER ISSUE	-
DMS_06085	12821	N	N	N	1	CUSTOMER ISSUE	-
DMS_06086	12822	N	N	N	1	CUSTOMER ISSUE	-
DMS_06087	12823	N	N	N	1	CUSTOMER ISSUE	-
DMS_06088	12824	N	N	N	1	CUSTOMER ISSUE	-
DMS_06089	12825	N	N	N	1	CUSTOMER ISSUE	-
DMS_06090	12826	N	N	N	1	CUSTOMER ISSUE	-
DMS_06091	12827	N	N	N	1	CUSTOMER ISSUE	-
DMS_06092	12828	N	N	N	1	CUSTOMER ISSUE	-
DMS_06093	12829	N	N	N	1	CUSTOMER ISSUE	-
DMS_06094	12830	N	N	N	1	CUSTOMER ISSUE	-
DMS_06095	12831	N	N	N	1	CUSTOMER ISSUE	-
DMS_06096	12832	N	N	N	1	CUSTOMER ISSUE	-
DMS_06097	12833	N	N	N	1	CUSTOMER ISSUE	-
DMS_06098	12834	N	N	N	1	CUSTOMER ISSUE	-
DMS_06099	12835	N	N	N	1	CUSTOMER ISSUE	-
DMS_06100	12836	N	N	N	1	CUSTOMER ISSUE	-
DMS_06101	12837	N	N	N	1	CUSTOMER ISSUE	-
DMS_06102	12838	N	N	N	1	CUSTOMER ISSUE	-
DMS_06103	12839	N	N	N	1	CUSTOMER ISSUE	-
DMS_06104	12840	N	N	N	1	CUSTOMER ISSUE	-
DMS_06106	12841	N	N	N	1	CUSTOMER ISSUE	-
DMS_06109	12842	N	N	N	1	CUSTOMER ISSUE	-
DMS_06110	12843	N	N	N	1	CUSTOMER ISSUE	-
DMS_06111	12844	N	N	N	1	CUSTOMER ISSUE	-
DMS_06112	12845	N	N	N	1	CUSTOMER ISSUE	-
DMS_06113	12846	N	N	N	1	CUSTOMER ISSUE	-
DMS_06114	12847	N	N	N	1	CUSTOMER ISSUE	-
DMS_06115	12848	N	N	N	1	CUSTOMER ISSUE	-
DMS_06116	12849	N	N	N	1	CUSTOMER ISSUE	-
DMS_06117	12850	N	N	N	1	CUSTOMER ISSUE	-
DMS_06118	12851	N	N	N	1	CUSTOMER ISSUE	-
DMS_06119	12852	N	N	N	1	CUSTOMER ISSUE	-
DMS_06120	12853	N	N	N	1	CUSTOMER ISSUE	-
DMS_06123	12854	N	N	N	1	CUSTOMER ISSUE	-
DMS_06124	12855	N	N	N	1	CUSTOMER ISSUE	-
DMS_06125	12856	N	N	N	1	CUSTOMER ISSUE	-

DMS_06126	12857	N	N	N	1	CUSTOMER ISSUE	-
DMS_06128	12858	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_06132	12859	N	N	N	1	CUSTOMER ISSUE	-
DMS_06133	12860	N	N	N	1	CUSTOMER ISSUE	-
DMS_06134	12861	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_06135	12862	N	N	N	1	CUSTOMER ISSUE	-
DMS_06136	12863	N	N	N	1	CUSTOMER ISSUE	-
DMS_06137	12864	N	N	N	1	CUSTOMER ISSUE	-
DMS_06138	12865	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06140	12866	N	N	N	1	CUSTOMER ISSUE	-
DMS_06141	12867	N	N	N	1	CUSTOMER ISSUE	-
DMS_06142	12868	N	N	N	1	CUSTOMER ISSUE	-
DMS_06143	12869	N	N	N	2	CUSTOMER ISSUE	-
DMS_06146	12870	N	N	N	1	CUSTOMER ISSUE	-
DMS_06147	12871	N	N	N	1	CUSTOMER ISSUE	-
DMS_06148	12872	N	N	N	1	CUSTOMER ISSUE	-
DMS_06149	12873	N	N	N	1	CUSTOMER ISSUE	-
DMS_06150	12874	N	N	N	1	CUSTOMER ISSUE	-
DMS_06167	12875	N	N	N	1	CUSTOMER ISSUE	-
DMS_06168	12876	N	N	N	1	CUSTOMER ISSUE	-
DMS_06169	12877	N	N	N	1	CUSTOMER ISSUE	-
DMS_06170	12878	N	N	N	1	CUSTOMER ISSUE	-
DMS_06171	12879	N	N	N	1	CUSTOMER ISSUE	-
DMS_06176	12880	N	N	N	1	CUSTOMER ISSUE	-
DMS_06177	12881	N	N	N	1	CUSTOMER ISSUE	-
DMS_06178	12882	N	N	N	1	CUSTOMER ISSUE	-
DMS_06179	12883	N	N	N	1	CUSTOMER ISSUE	-
DMS_06180	12884	N	N	N	1	CUSTOMER ISSUE	-
DMS_06181	12885	N	N	N	1	CUSTOMER ISSUE	-
DMS_06182	12886	N	N	N	1	CUSTOMER ISSUE	-
DMS_06183	12887	N	N	N	1	CUSTOMER ISSUE	-
DMS_06184	12888	N	N	N	1	CUSTOMER ISSUE	-
DMS_06185	12889	N	N	N	1	CUSTOMER ISSUE	-
DMS_06186	12890	N	N	N	1	CUSTOMER ISSUE	-
DMS_06187	12891	N	N	N	1	CUSTOMER ISSUE	-
DMS_06188	12892	N	N	N	1	CUSTOMER ISSUE	-
DMS_06189	12893	N	N	N	1	CUSTOMER ISSUE	-
DMS_06190	12894	N	N	N	1	CUSTOMER ISSUE	-
DMS_06191	12895	N	N	N	1	CUSTOMER ISSUE	-
DMS_06192	12896	N	N	N	1	CUSTOMER ISSUE	-
DMS_06193	12897	N	N	N	1	CUSTOMER ISSUE	-
DMS_06194	12898	N	N	N	1	CUSTOMER ISSUE	-
DMS_06195	12899	N	N	N	1	CUSTOMER ISSUE	-
DMS_06196	12900	N	N	N	1	CUSTOMER ISSUE	-
DMS_06199	12901	N	N	N	1	CUSTOMER ISSUE	-
DMS_06201	12902	N	N	N	1	CUSTOMER ISSUE	-
DMS_06202	12903	N	N	N	1	CUSTOMER ISSUE	-
DMS_06203	12904	N	N	N	1	CUSTOMER ISSUE	-
DMS_06204	12905	N	N	N	1	CUSTOMER ISSUE	-
DMS_06206	12906	N	N	N	1	CUSTOMER ISSUE	-
DMS_06207	12907	N	N	N	1	CUSTOMER ISSUE	-
DMS_06208	12908	N	N	N	1	CUSTOMER ISSUE	-
DMS_06209	12909	N	N	N	1	CUSTOMER ISSUE	-
DMS_06210	12910	N	N	N	1	CUSTOMER ISSUE	-
DMS_06211	12911	N	N	N	1	CUSTOMER ISSUE	-
DMS_06212	12912	N	N	N	1	CUSTOMER ISSUE	-
DMS_06213	12913	N	N	N	1	CUSTOMER ISSUE	-
DMS_06214	12914	N	N	N	1	CUSTOMER ISSUE	-
DMS_06215	12915	N	N	N	1	CUSTOMER ISSUE	-
DMS_06216	12916	N	N	N	1	CUSTOMER ISSUE	-
DMS_06218	12917	N	N	N	1	CUSTOMER ISSUE	-
DMS_06219	12918	N	N	N	1	CUSTOMER ISSUE	-
DMS_06220	12919	N	N	N	1	CUSTOMER ISSUE	-
DMS_06222	12920	N	N	N	1	CUSTOMER ISSUE	-
DMS_06223	12921	N	N	N	1	CUSTOMER ISSUE	-
DMS_06224	12922	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_06225	12923	N	N	N	1	CUSTOMER ISSUE	-
DMS_06226	12924	N	N	N	1	CUSTOMER ISSUE	-
DMS_06227	12925	N	N	N	1	CUSTOMER ISSUE	-
DMS_06228	12926	N	N	N	1	CUSTOMER ISSUE	-
DMS_06230	12927	N	N	N	1	CUSTOMER ISSUE	-
DMS_06231	12928	N	N	N	1	CUSTOMER ISSUE	-
DMS_06232	12929	N	N	N	1	CUSTOMER ISSUE	-
DMS_06234	12930	N	N	N	1	CUSTOMER ISSUE	-
DMS_06236	12931	N	N	N	1	CUSTOMER ISSUE	-
DMS_06237	12932	N	N	N	1	CUSTOMER ISSUE	-
DMS_06238	12933	N	N	N	1	CUSTOMER ISSUE	-
DMS_06239	12934	N	N	N	1	CUSTOMER ISSUE	-
DMS_06240	12935	N	N	N	1	CUSTOMER ISSUE	-
DMS_06241	12936	N	N	N	1	CUSTOMER ISSUE	-

DMS_06242	12937	N	N	N	1	CUSTOMER ISSUE	-
DMS_06243	12938	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06244	12939	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06245	12940	N	N	N	1	CUSTOMER ISSUE	-
DMS_06246	12941	N	N	N	1	CUSTOMER ISSUE	-
DMS_06247	12942	N	N	N	1	CUSTOMER ISSUE	-
DMS_06248	12943	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_06249	12944	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_06250	12945	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_06251	12946	N	N	Y	1	DIST - CIRCUIT RETURN TO NORMAL CONFIG	472.5
DMS_06253	12947	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_06255	12948	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_06259	12949	N	N	N	1	CUSTOMER ISSUE	-
DMS_06269	12950	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06275	12951	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06318	12952	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06319	12953	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06320	12954	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06321	12955	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06323	12956	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06324	12957	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06327	12958	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_06328	12959	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_06330	12960	N	N	N	1	CUSTOMER ISSUE	-
DMS_06331	12961	N	N	N	1	CUSTOMER ISSUE	-
DMS_06332	12962	N	N	N	1	CUSTOMER ISSUE	-
DMS_06333	12963	N	N	N	1	CUSTOMER ISSUE	-
DMS_06334	12964	N	N	N	1	CUSTOMER ISSUE	-
DMS_06335	12965	N	N	N	1	CUSTOMER ISSUE	-
DMS_06336	12966	N	N	N	1	CUSTOMER ISSUE	-
DMS_06337	12967	N	N	N	1	CUSTOMER ISSUE	-
DMS_06338	12968	N	N	N	1	CUSTOMER ISSUE	-
DMS_06339	12969	N	N	N	1	CUSTOMER ISSUE	-
DMS_06340	12970	N	N	N	1	CUSTOMER ISSUE	-
DMS_06341	12971	N	N	N	1	CUSTOMER ISSUE	-
DMS_06344	12972	N	N	N	1	CUSTOMER ISSUE	-
DMS_06345	12973	N	N	N	1	CUSTOMER ISSUE	-
DMS_06346	12974	N	N	N	1	CUSTOMER ISSUE	-
DMS_06348	12975	N	N	N	1	CUSTOMER ISSUE	-
DMS_06349	12976	N	N	N	1	CUSTOMER ISSUE	-
DMS_06350	12977	N	N	N	1	CUSTOMER ISSUE	-
DMS_06351	12978	N	N	N	1	CUSTOMER ISSUE	-
DMS_06352	12979	N	N	N	1	CUSTOMER ISSUE	-
DMS_06353	12980	N	N	N	1	CUSTOMER ISSUE	-
DMS_06354	12981	N	N	N	1	CUSTOMER ISSUE	-
DMS_06355	12982	N	N	N	1	CUSTOMER ISSUE	-
DMS_06356	12983	N	N	N	1	CUSTOMER ISSUE	-
DMS_06357	12984	N	N	N	1	CUSTOMER ISSUE	-
DMS_06358	12985	N	N	N	1	CUSTOMER ISSUE	-
DMS_06359	12986	N	N	N	1	CUSTOMER ISSUE	-
DMS_06360	12987	N	N	N	1	CUSTOMER ISSUE	-
DMS_06361	12988	N	N	N	1	CUSTOMER ISSUE	-
DMS_06362	12989	N	N	N	2	CUSTOMER ISSUE	-
DMS_06363	12990	N	N	N	1	CUSTOMER ISSUE	-
DMS_06364	12991	N	N	N	1	CUSTOMER ISSUE	-
DMS_06365	12992	N	N	N	1	CUSTOMER ISSUE	-
DMS_06366	12993	N	N	N	1	CUSTOMER ISSUE	-
DMS_06367	12994	N	N	N	1	CUSTOMER ISSUE	-
DMS_06368	12995	N	N	N	1	CUSTOMER ISSUE	-
DMS_06369	12996	N	N	N	1	CUSTOMER ISSUE	-
DMS_06370	12997	N	N	N	1	CUSTOMER ISSUE	-
DMS_06371	12998	N	N	N	1	CUSTOMER ISSUE	-
DMS_06372	12999	N	N	N	1	CUSTOMER ISSUE	-
DMS_06373	13000	N	N	N	1	CUSTOMER ISSUE	-
DMS_06374	13001	N	N	N	1	CUSTOMER ISSUE	-
DMS_06375	13002	N	N	N	1	CUSTOMER ISSUE	-
DMS_06378	13003	N	N	N	1	CUSTOMER ISSUE	-
DMS_06383	13004	N	N	N	1	CUSTOMER ISSUE	-
DMS_06384	13005	N	N	N	1	CUSTOMER ISSUE	-
DMS_06385	13006	N	N	N	1	CUSTOMER ISSUE	-
DMS_06386	13007	N	N	N	1	CUSTOMER ISSUE	-
DMS_06387	13008	N	N	N	1	CUSTOMER ISSUE	-
DMS_06388	13009	N	N	N	1	CUSTOMER ISSUE	-
DMS_06389	13010	N	N	N	1	CUSTOMER ISSUE	-
DMS_06390	13011	N	N	N	1	CUSTOMER ISSUE	-
DMS_06391	13012	N	N	N	1	CUSTOMER ISSUE	-
DMS_06395	13013	N	N	N	1	CUSTOMER ISSUE	-
DMS_06397	13014	N	N	N	1	CUSTOMER ISSUE	-
DMS_06398	13015	N	N	N	1	CUSTOMER ISSUE	-
DMS_06399	13016	N	N	N	1	CUSTOMER ISSUE	-

DMS_06400	13017	N	N	N	1	CUSTOMER ISSUE	-
DMS_06401	13018	N	N	N	1	CUSTOMER ISSUE	-
DMS_06402	13019	N	N	N	1	CUSTOMER ISSUE	-
DMS_06404	13020	N	N	N	1	CUSTOMER ISSUE	-
DMS_06405	13021	N	N	N	1	CUSTOMER ISSUE	-
DMS_06406	13022	N	N	N	1	CUSTOMER ISSUE	-
DMS_06407	13023	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06408	13024	N	N	N	1	CUSTOMER ISSUE	-
DMS_06409	13025	N	N	N	1	CUSTOMER ISSUE	-
DMS_06410	13026	N	N	N	1	CUSTOMER ISSUE	-
DMS_06411	13027	N	N	N	1	CUSTOMER ISSUE	-
DMS_06433	13028	N	N	N	1	CUSTOMER ISSUE	-
DMS_06434	13029	N	N	N	1	CUSTOMER ISSUE	-
DMS_06435	13030	N	N	N	1	CUSTOMER ISSUE	-
DMS_06436	13031	N	N	N	1	CUSTOMER ISSUE	-
DMS_06437	13032	N	N	N	1	CUSTOMER ISSUE	-
DMS_06438	13033	N	N	N	1	CUSTOMER ISSUE	-
DMS_06439	13034	N	N	N	2	CUSTOMER ISSUE	-
DMS_06440	13035	N	N	N	1	CUSTOMER ISSUE	-
DMS_06441	13036	N	N	N	2	CUSTOMER ISSUE	-
DMS_06442	13037	N	N	N	1	CUSTOMER ISSUE	-
DMS_06443	13038	N	N	N	1	CUSTOMER ISSUE	-
DMS_06444	13039	N	N	N	1	CUSTOMER ISSUE	-
DMS_06445	13040	N	N	N	1	CUSTOMER ISSUE	-
DMS_06446	13041	N	N	N	1	CUSTOMER ISSUE	-
DMS_06447	13042	N	N	N	1	CUSTOMER ISSUE	-
DMS_06448	13043	N	N	N	1	CUSTOMER ISSUE	-
DMS_06449	13044	N	N	N	1	CUSTOMER ISSUE	-
DMS_06450	13045	N	N	N	1	CUSTOMER ISSUE	-
DMS_06451	13046	N	N	N	1	CUSTOMER ISSUE	-
DMS_06453	13047	N	N	N	1	CUSTOMER ISSUE	-
DMS_06454	13048	N	N	N	1	CUSTOMER ISSUE	-
DMS_06455	13049	N	N	N	1	CUSTOMER ISSUE	-
DMS_06456	13050	N	N	N	1	CUSTOMER ISSUE	-
DMS_06457	13051	N	N	N	1	CUSTOMER ISSUE	-
DMS_06458	13052	N	N	N	1	CUSTOMER ISSUE	-
DMS_06459	13053	N	N	N	1	CUSTOMER ISSUE	-
DMS_06460	13054	N	N	N	1	CUSTOMER ISSUE	-
DMS_06461	13055	N	N	N	1	CUSTOMER ISSUE	-
DMS_06463	13056	N	N	N	1	CUSTOMER ISSUE	-
DMS_06464	13057	N	N	N	1	CUSTOMER ISSUE	-
DMS_06467	13058	N	N	N	1	CUSTOMER ISSUE	-
DMS_06468	13059	N	N	N	1	CUSTOMER ISSUE	-
DMS_06469	13060	N	N	N	1	CUSTOMER ISSUE	-
DMS_06470	13061	N	N	N	1	CUSTOMER ISSUE	-
DMS_06471	13062	N	N	N	1	CUSTOMER ISSUE	-
DMS_06472	13063	N	N	N	1	CUSTOMER ISSUE	-
DMS_06473	13064	N	N	N	1	CUSTOMER ISSUE	-
DMS_06474	13065	N	N	N	1	CUSTOMER ISSUE	-
DMS_06475	13066	N	N	N	1	CUSTOMER ISSUE	-
DMS_06476	13067	N	N	N	1	CUSTOMER ISSUE	-
DMS_06477	13068	N	N	N	1	CUSTOMER ISSUE	-
DMS_06478	13069	N	N	N	1	CUSTOMER ISSUE	-
DMS_06479	13070	N	N	N	1	CUSTOMER ISSUE	-
DMS_06480	13071	N	N	N	1	CUSTOMER ISSUE	-
DMS_06481	13072	N	N	N	1	CUSTOMER ISSUE	-
DMS_06482	13073	N	N	N	1	CUSTOMER ISSUE	-
DMS_06483	13074	N	N	N	1	CUSTOMER ISSUE	-
DMS_06484	13075	N	N	N	1	CUSTOMER ISSUE	-
DMS_06485	13076	N	N	N	1	CUSTOMER ISSUE	-
DMS_06486	13077	N	N	N	1	CUSTOMER ISSUE	-
DMS_06487	13078	N	N	N	1	CUSTOMER ISSUE	-
DMS_06488	13079	N	N	N	1	CUSTOMER ISSUE	-
DMS_06489	13080	N	N	N	1	CUSTOMER ISSUE	-
DMS_06491	13081	N	N	N	1	CUSTOMER ISSUE	-
DMS_06493	13082	N	N	N	1	CUSTOMER ISSUE	-
DMS_06494	13083	N	N	N	1	CUSTOMER ISSUE	-
DMS_06495	13084	N	N	N	1	CUSTOMER ISSUE	-
DMS_06496	13085	N	N	N	1	CUSTOMER ISSUE	-
DMS_06497	13086	N	N	N	1	CUSTOMER ISSUE	-
DMS_06498	13087	N	N	N	1	CUSTOMER ISSUE	-
DMS_06499	13088	N	N	N	1	CUSTOMER ISSUE	-
DMS_06500	13089	N	N	N	1	CUSTOMER ISSUE	-
DMS_06501	13090	N	N	N	1	CUSTOMER ISSUE	-
DMS_06502	13091	N	N	N	1	CUSTOMER ISSUE	-
DMS_06503	13092	N	N	N	1	CUSTOMER ISSUE	-
DMS_06504	13093	N	N	N	1	CUSTOMER ISSUE	-
DMS_06506	13094	N	N	N	1	CUSTOMER ISSUE	-
DMS_06507	13095	N	N	N	1	CUSTOMER ISSUE	-
DMS_06508	13096	N	N	N	1	CUSTOMER ISSUE	-

DMS_06509	13097	N	N	N	1	CUSTOMER ISSUE	-
DMS_06510	13098	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_06512	13099	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_06513	13100	N	N	N	1	CUSTOMER ISSUE	-
DMS_06514	13101	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06527	13102	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06530	13103	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_06536	13104	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_06541	13105	N	N	N	1	CUSTOMER ISSUE	-
DMS_06558	13106	N	N	N	1	CUSTOMER ISSUE	-
DMS_06568	13107	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_06579	13108	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06581	13109	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06583	13110	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06584	13111	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06585	13112	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06587	13113	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_06588	13114	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_06589	13115	N	N	N	1	CUSTOMER ISSUE	-
DMS_06590	13116	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_06591	13117	N	N	N	1	CUSTOMER ISSUE	-
DMS_06592	13118	N	N	N	1	CUSTOMER ISSUE	-
DMS_06593	13119	N	N	N	1	CUSTOMER ISSUE	-
DMS_06594	13120	N	N	N	1	CUSTOMER ISSUE	-
DMS_06595	13121	N	N	N	1	CUSTOMER ISSUE	-
DMS_06596	13122	N	N	N	2	CUSTOMER ISSUE	-
DMS_06597	13123	N	N	N	1	CUSTOMER ISSUE	-
DMS_06601	13124	N	N	N	1	CUSTOMER ISSUE	-
DMS_06602	13125	N	N	N	1	CUSTOMER ISSUE	-
DMS_06605	13126	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_06606	13127	N	N	N	2	CUSTOMER ISSUE	-
DMS_06607	13128	N	N	N	1	CUSTOMER ISSUE	-
DMS_06609	13129	N	N	N	1	CUSTOMER ISSUE	-
DMS_06611	13130	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_06612	13131	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_06613	13132	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_06614	13133	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_06615	13134	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_06616	13135	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_06617	13136	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_06618	13137	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_06619	13138	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_06620	13139	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_06621	13140	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_06627	13141	N	N	N	1	CUSTOMER ISSUE	-
DMS_06628	13142	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
DMS_06629	13143	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
DMS_06630	13144	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
DMS_06631	13145	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_06632	13146	N	N	N	1	CUSTOMER ISSUE	-
DMS_06633	13147	N	N	N	1	CUSTOMER ISSUE	-
DMS_06634	13148	N	N	N	1	CUSTOMER ISSUE	-
DMS_06635	13149	N	N	N	1	CUSTOMER ISSUE	-
DMS_06636	13150	N	N	N	1	CUSTOMER ISSUE	-
DMS_06637	13151	N	N	N	2	CUSTOMER ISSUE	-
DMS_06638	13152	N	N	N	1	CUSTOMER ISSUE	-
DMS_06639	13153	N	N	N	1	CUSTOMER ISSUE	-
DMS_06640	13154	N	N	N	1	CUSTOMER ISSUE	-
DMS_06641	13155	N	N	N	1	CUSTOMER ISSUE	-
DMS_06642	13156	N	N	N	1	CUSTOMER ISSUE	-
DMS_06644	13157	N	N	N	1	CUSTOMER ISSUE	-
DMS_06645	13158	N	N	N	1	CUSTOMER ISSUE	-
DMS_06647	13159	N	N	N	1	CUSTOMER ISSUE	-
DMS_06648	13160	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06649	13161	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_06650	13162	N	N	N	1	CUSTOMER ISSUE	-
DMS_06679	13163	N	N	N	1	CUSTOMER ISSUE	-
DMS_06680	13164	N	N	N	1	CUSTOMER ISSUE	-
DMS_06681	13165	N	N	N	1	CUSTOMER ISSUE	-
DMS_06682	13166	N	N	N	1	CUSTOMER ISSUE	-
DMS_06683	13167	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06684	13168	N	N	N	1	CUSTOMER ISSUE	-
DMS_06685	13169	N	N	N	1	CUSTOMER ISSUE	-
DMS_06686	13170	N	N	N	1	CUSTOMER ISSUE	-
DMS_06707	13171	N	N	N	1	CUSTOMER ISSUE	-
DMS_06708	13172	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06726	13173	N	N	N	1	CUSTOMER ISSUE	-
DMS_06728	13174	N	N	N	1	CUSTOMER ISSUE	-
DMS_06733	13175	N	N	N	1	CUSTOMER ISSUE	-
DMS_06734	13176	N	N	N	1	CUSTOMER ISSUE	-

DMS_06735	13177	N	N	N	1	CUSTOMER ISSUE	-
DMS_06738	13178	N	N	N	1	CUSTOMER ISSUE	-
DMS_06739	13179	N	N	N	1	CUSTOMER ISSUE	-
DMS_06756	13180	N	N	N	1	CUSTOMER ISSUE	-
DMS_06757	13181	N	N	N	1	CUSTOMER ISSUE	-
DMS_06758	13182	N	N	N	1	CUSTOMER ISSUE	-
DMS_06759	13183	N	N	N	1	CUSTOMER ISSUE	-
DMS_06760	13184	N	N	N	1	CUSTOMER ISSUE	-
DMS_06762	13185	N	N	N	1	CUSTOMER ISSUE	-
DMS_06763	13186	N	N	N	1	CUSTOMER ISSUE	-
DMS_06764	13187	N	N	N	1	CUSTOMER ISSUE	-
DMS_06765	13188	N	N	N	1	CUSTOMER ISSUE	-
DMS_06766	13189	N	N	N	1	CUSTOMER ISSUE	-
DMS_06770	13190	N	N	N	1	CUSTOMER ISSUE	-
DMS_06771	13191	N	N	N	1	CUSTOMER ISSUE	-
DMS_06777	13192	N	N	N	1	CUSTOMER ISSUE	-
DMS_06778	13193	N	N	N	1	CUSTOMER ISSUE	-
DMS_06781	13194	N	N	N	1	CUSTOMER ISSUE	-
DMS_06782	13195	N	N	N	1	CUSTOMER ISSUE	-
DMS_06783	13196	N	N	N	1	CUSTOMER ISSUE	-
DMS_06785	13197	N	N	Y	1	TX - REPLACE	2500
DMS_06786	13198	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06787	13199	N	N	N	1	CUSTOMER ISSUE	-
DMS_06788	13200	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_06789	13201	N	N	N	1	CUSTOMER ISSUE	-
DMS_06790	13202	N	N	N	1	CUSTOMER ISSUE	-
DMS_06791	13203	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06792	13204	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06793	13205	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06794	13206	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06795	13207	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06797	13208	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06798	13209	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06799	13210	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06800	13211	N	N	N	1	CUSTOMER ISSUE	-
DMS_06801	13212	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06802	13213	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06804	13214	N	N	N	1	CUSTOMER ISSUE	-
DMS_06805	13215	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06806	13216	N	N	N	1	CUSTOMER ISSUE	-
DMS_06809	13217	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06810	13218	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06811	13219	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06812	13220	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06813	13221	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06814	13222	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06815	13223	N	N	N	1	CUSTOMER ISSUE	-
DMS_06816	13224	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06817	13225	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06818	13226	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06819	13227	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06820	13228	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06821	13229	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06822	13230	N	N	N	1	CUSTOMER ISSUE	-
DMS_06823	13231	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06824	13232	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06825	13233	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06826	13234	N	N	N	1	CUSTOMER ISSUE	-
DMS_06827	13235	N	N	N	1	CUSTOMER ISSUE	-
DMS_06828	13236	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06829	13237	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06830	13238	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06831	13239	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06832	13240	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06833	13241	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06834	13242	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06835	13243	N	N	N	1	CUSTOMER ISSUE	-
DMS_06836	13244	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06837	13245	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06838	13246	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06839	13247	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06840	13248	N	N	N	1	CUSTOMER ISSUE	-
DMS_06841	13249	N	N	N	1	CUSTOMER ISSUE	-
DMS_06842	13250	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06843	13251	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06844	13252	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06845	13253	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06846	13254	N	N	N	1	CUSTOMER ISSUE	-
DMS_06847	13255	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06848	13256	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_06849	13257	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06850	13258	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06851	13259	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06852	13260	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06853	13261	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06854	13262	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06855	13263	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06856	13264	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06857	13265	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06858	13266	N	N	N	1	CUSTOMER ISSUE	-
DMS_06859	13267	N	N	N	1	CUSTOMER ISSUE	-
DMS_06860	13268	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06861	13269	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06862	13270	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06863	13271	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06864	13272	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06865	13273	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06866	13274	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06867	13275	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06868	13276	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06869	13277	N	N	N	1	CUSTOMER ISSUE	-
DMS_06870	13278	N	N	N	1	CUSTOMER ISSUE	-
DMS_06871	13279	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06872	13280	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06873	13281	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06874	13282	N	N	N	1	CUSTOMER ISSUE	-
DMS_06876	13283	N	N	N	1	CUSTOMER ISSUE	-
DMS_06877	13284	N	N	N	1	CUSTOMER ISSUE	-
DMS_06878	13285	N	N	N	1	CUSTOMER ISSUE	-
DMS_06879	13286	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_06880	13287	N	N	N	1	CUSTOMER ISSUE	-
DMS_06883	13288	N	N	N	1	CUSTOMER ISSUE	-
DMS_06884	13289	N	N	N	1	CUSTOMER ISSUE	-
DMS_06885	13290	N	N	N	1	CUSTOMER ISSUE	-
DMS_06886	13291	N	N	N	1	CUSTOMER ISSUE	-
DMS_06887	13292	N	N	N	1	CUSTOMER ISSUE	-
DMS_06889	13293	N	N	N	1	CUSTOMER ISSUE	-
DMS_06890	13294	N	N	N	1	CUSTOMER ISSUE	-
DMS_06891	13295	N	N	N	1	CUSTOMER ISSUE	-
DMS_06892	13296	N	N	N	1	CUSTOMER ISSUE	-
DMS_06893	13297	N	N	N	1	CUSTOMER ISSUE	-
DMS_06894	13298	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_06897	13299	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_06899	13300	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06900	13301	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06901	13302	N	N	N	1	CUSTOMER ISSUE	-
DMS_06902	13303	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06903	13304	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06904	13305	N	N	N	1	CUSTOMER ISSUE	-
DMS_06907	13306	N	N	N	1	CUSTOMER ISSUE	-
DMS_06908	13307	N	N	N	1	CUSTOMER ISSUE	-
DMS_06909	13308	N	N	N	1	CUSTOMER ISSUE	-
DMS_06910	13309	N	N	N	1	CUSTOMER ISSUE	-
DMS_06911	13310	N	N	N	1	CUSTOMER ISSUE	-
DMS_06912	13311	N	N	N	1	CUSTOMER ISSUE	-
DMS_06913	13312	N	N	N	1	CUSTOMER ISSUE	-
DMS_06914	13313	N	N	N	1	CUSTOMER ISSUE	-
DMS_06915	13314	N	N	N	1	CUSTOMER ISSUE	-
DMS_06916	13315	N	N	N	1	CUSTOMER ISSUE	-
DMS_06917	13316	N	N	N	1	CUSTOMER ISSUE	-
DMS_06918	13317	N	N	N	1	CUSTOMER ISSUE	-
DMS_06920	13318	N	N	N	1	CUSTOMER ISSUE	-
DMS_06921	13319	N	N	N	1	CUSTOMER ISSUE	-
DMS_06922	13320	N	N	N	1	CUSTOMER ISSUE	-
DMS_06923	13321	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06924	13322	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_06926	13323	N	N	N	1	CUSTOMER ISSUE	-
DMS_06928	13324	N	N	N	1	CUSTOMER ISSUE	-
DMS_06929	13325	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_06930	13326	N	N	N	1	CUSTOMER ISSUE	-
DMS_06931	13327	N	N	N	1	CUSTOMER ISSUE	-
DMS_06932	13328	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_06933	13329	N	N	N	1	CUSTOMER ISSUE	-
DMS_06934	13330	N	N	N	1	CUSTOMER ISSUE	-
DMS_06935	13331	N	N	N	1	CUSTOMER ISSUE	-
DMS_06936	13332	N	N	N	1	CUSTOMER ISSUE	-
DMS_06937	13333	N	N	N	1	CUSTOMER ISSUE	-
DMS_06938	13334	N	N	N	1	CUSTOMER ISSUE	-
DMS_06939	13335	N	N	N	1	CUSTOMER ISSUE	-
DMS_06940	13336	N	N	N	1	CUSTOMER ISSUE	-

DMS_06941	13337	N	N	N	1	CUSTOMER ISSUE	-
DMS_06942	13338	N	N	N	1	CUSTOMER ISSUE	-
DMS_06943	13339	N	N	N	1	CUSTOMER ISSUE	-
DMS_06944	13340	N	N	N	1	CUSTOMER ISSUE	-
DMS_06945	13341	N	N	N	1	CUSTOMER ISSUE	-
DMS_06946	13342	N	N	N	1	CUSTOMER ISSUE	-
DMS_06947	13343	N	N	N	1	CUSTOMER ISSUE	-
DMS_06948	13344	N	N	N	1	CUSTOMER ISSUE	-
DMS_06949	13345	N	N	N	1	CUSTOMER ISSUE	-
DMS_06950	13346	N	N	N	1	CUSTOMER ISSUE	-
DMS_06951	13347	N	N	N	1	CUSTOMER ISSUE	-
DMS_06952	13348	N	N	N	1	CUSTOMER ISSUE	-
DMS_06953	13349	N	N	N	1	CUSTOMER ISSUE	-
DMS_06954	13350	N	N	N	1	CUSTOMER ISSUE	-
DMS_06955	13351	N	N	N	1	CUSTOMER ISSUE	-
DMS_06956	13352	N	N	N	1	CUSTOMER ISSUE	-
DMS_06957	13353	N	N	N	1	CUSTOMER ISSUE	-
DMS_06958	13354	N	N	N	1	CUSTOMER ISSUE	-
DMS_06959	13355	N	N	N	1	CUSTOMER ISSUE	-
DMS_06960	13356	N	N	N	1	CUSTOMER ISSUE	-
DMS_06961	13357	N	N	N	1	CUSTOMER ISSUE	-
DMS_06962	13358	N	N	N	1	CUSTOMER ISSUE	-
DMS_06963	13359	N	N	N	1	CUSTOMER ISSUE	-
DMS_06964	13360	N	N	N	1	CUSTOMER ISSUE	-
DMS_06965	13361	N	N	N	1	CUSTOMER ISSUE	-
DMS_06966	13362	N	N	N	1	CUSTOMER ISSUE	-
DMS_06967	13363	N	N	N	1	CUSTOMER ISSUE	-
DMS_06968	13364	N	N	N	1	CUSTOMER ISSUE	-
DMS_06969	13365	N	N	N	1	CUSTOMER ISSUE	-
DMS_06970	13366	N	N	N	1	CUSTOMER ISSUE	-
DMS_06971	13367	N	N	N	1	CUSTOMER ISSUE	-
DMS_06972	13368	N	N	N	1	CUSTOMER ISSUE	-
DMS_06973	13369	N	N	N	1	CUSTOMER ISSUE	-
DMS_06974	13370	N	N	N	1	CUSTOMER ISSUE	-
DMS_06975	13371	N	N	N	1	CUSTOMER ISSUE	-
DMS_06976	13372	N	N	N	1	CUSTOMER ISSUE	-
DMS_06977	13373	N	N	N	1	CUSTOMER ISSUE	-
DMS_06978	13374	N	N	N	1	CUSTOMER ISSUE	-
DMS_06979	13375	N	N	N	1	CUSTOMER ISSUE	-
DMS_06980	13376	N	N	N	1	CUSTOMER ISSUE	-
DMS_06981	13377	N	N	N	1	CUSTOMER ISSUE	-
DMS_06982	13378	N	N	N	1	CUSTOMER ISSUE	-
DMS_06983	13379	N	N	N	1	CUSTOMER ISSUE	-
DMS_06984	13380	N	N	N	1	CUSTOMER ISSUE	-
DMS_06985	13381	N	N	N	1	CUSTOMER ISSUE	-
DMS_06986	13382	N	N	N	1	CUSTOMER ISSUE	-
DMS_06987	13383	N	N	N	1	CUSTOMER ISSUE	-
DMS_06988	13384	N	N	N	1	CUSTOMER ISSUE	-
DMS_06989	13385	N	N	N	1	CUSTOMER ISSUE	-
DMS_06990	13386	N	N	N	1	CUSTOMER ISSUE	-
DMS_06991	13387	N	N	N	1	CUSTOMER ISSUE	-
DMS_06992	13388	N	N	N	1	CUSTOMER ISSUE	-
DMS_06993	13389	N	N	N	1	CUSTOMER ISSUE	-
DMS_06994	13390	N	N	N	1	CUSTOMER ISSUE	-
DMS_06995	13391	N	N	N	1	CUSTOMER ISSUE	-
DMS_06996	13392	N	N	N	1	CUSTOMER ISSUE	-
DMS_06997	13393	N	N	N	1	CUSTOMER ISSUE	-
DMS_06998	13394	N	N	N	1	CUSTOMER ISSUE	-
DMS_06999	13395	N	N	N	1	CUSTOMER ISSUE	-
DMS_07000	13396	N	N	N	1	CUSTOMER ISSUE	-
DMS_07001	13397	N	N	N	1	CUSTOMER ISSUE	-
DMS_07002	13398	N	N	N	1	CUSTOMER ISSUE	-
DMS_07003	13399	N	N	N	1	CUSTOMER ISSUE	-
DMS_07009	13400	N	N	N	1	CUSTOMER ISSUE	-
DMS_07010	13401	N	N	N	1	CUSTOMER ISSUE	-
DMS_07011	13402	N	N	N	1	CUSTOMER ISSUE	-
DMS_07012	13403	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07013	13404	N	N	N	1	CUSTOMER ISSUE	-
DMS_07014	13405	N	N	N	1	CUSTOMER ISSUE	-
DMS_07015	13406	N	N	N	1	CUSTOMER ISSUE	-
DMS_07016	13407	N	N	Y	1	TX - REPLACE	2500
DMS_07020	13408	N	N	N	1	CUSTOMER ISSUE	-
DMS_07021	13409	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07023	13410	N	N	N	1	CUSTOMER ISSUE	-
DMS_07024	13411	N	N	N	1	CUSTOMER ISSUE	-
DMS_07025	13412	N	N	N	1	CUSTOMER ISSUE	-
DMS_07027	13413	N	N	N	1	CUSTOMER ISSUE	-
DMS_07028	13414	N	N	N	1	CUSTOMER ISSUE	-
DMS_07029	13415	N	N	N	1	CUSTOMER ISSUE	-
DMS_07030	13416	N	N	N	1	CUSTOMER ISSUE	-

DMS_07031	13417	N	N	N	1	CUSTOMER ISSUE	-
DMS_07032	13418	N	N	N	1	CUSTOMER ISSUE	-
DMS_07033	13419	N	N	N	1	CUSTOMER ISSUE	-
DMS_07034	13420	N	N	N	1	CUSTOMER ISSUE	-
DMS_07035	13421	N	N	N	1	CUSTOMER ISSUE	-
DMS_07036	13422	N	N	N	1	CUSTOMER ISSUE	-
DMS_07037	13423	N	N	N	1	CUSTOMER ISSUE	-
DMS_07038	13424	N	N	N	1	CUSTOMER ISSUE	-
DMS_07039	13425	N	N	N	1	CUSTOMER ISSUE	-
DMS_07040	13426	N	N	N	1	CUSTOMER ISSUE	-
DMS_07041	13427	N	N	N	1	CUSTOMER ISSUE	-
DMS_07042	13428	N	N	N	1	CUSTOMER ISSUE	-
DMS_07043	13429	N	N	N	1	CUSTOMER ISSUE	-
DMS_07044	13430	N	N	N	1	CUSTOMER ISSUE	-
DMS_07045	13431	N	N	N	1	CUSTOMER ISSUE	-
DMS_07046	13432	N	N	N	1	CUSTOMER ISSUE	-
DMS_07047	13433	N	N	N	1	CUSTOMER ISSUE	-
DMS_07048	13434	N	N	N	1	CUSTOMER ISSUE	-
DMS_07049	13435	N	N	N	1	CUSTOMER ISSUE	-
DMS_07050	13436	N	N	N	1	CUSTOMER ISSUE	-
DMS_07051	13437	N	N	N	1	CUSTOMER ISSUE	-
DMS_07052	13438	N	N	N	1	CUSTOMER ISSUE	-
DMS_07053	13439	N	N	N	1	CUSTOMER ISSUE	-
DMS_07054	13440	N	N	N	1	CUSTOMER ISSUE	-
DMS_07055	13441	N	N	N	1	CUSTOMER ISSUE	-
DMS_07056	13442	N	N	N	1	CUSTOMER ISSUE	-
DMS_07057	13443	N	N	N	1	CUSTOMER ISSUE	-
DMS_07058	13444	N	N	N	1	CUSTOMER ISSUE	-
DMS_07059	13445	N	N	N	1	CUSTOMER ISSUE	-
DMS_07060	13446	N	N	N	1	CUSTOMER ISSUE	-
DMS_07061	13447	N	N	N	1	CUSTOMER ISSUE	-
DMS_07062	13448	N	N	N	1	CUSTOMER ISSUE	-
DMS_07063	13449	N	N	N	1	CUSTOMER ISSUE	-
DMS_07064	13450	N	N	N	1	CUSTOMER ISSUE	-
DMS_07065	13451	N	N	N	1	CUSTOMER ISSUE	-
DMS_07066	13452	N	N	N	1	CUSTOMER ISSUE	-
DMS_07067	13453	N	N	N	1	CUSTOMER ISSUE	-
DMS_07068	13454	N	N	N	1	CUSTOMER ISSUE	-
DMS_07069	13455	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07070	13456	N	N	N	1	CUSTOMER ISSUE	-
DMS_07071	13457	N	N	N	1	CUSTOMER ISSUE	-
DMS_07072	13458	N	N	N	1	CUSTOMER ISSUE	-
DMS_07073	13459	N	N	N	1	CUSTOMER ISSUE	-
DMS_07074	13460	N	N	N	1	CUSTOMER ISSUE	-
DMS_07075	13461	N	N	N	1	CUSTOMER ISSUE	-
DMS_07076	13462	N	N	N	1	CUSTOMER ISSUE	-
DMS_07077	13463	N	N	N	1	CUSTOMER ISSUE	-
DMS_07078	13464	N	N	N	1	CUSTOMER ISSUE	-
DMS_07079	13465	N	N	N	1	CUSTOMER ISSUE	-
DMS_07080	13466	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07081	13467	N	N	N	1	CUSTOMER ISSUE	-
DMS_07083	13468	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07084	13469	N	N	N	1	CUSTOMER ISSUE	-
DMS_07085	13470	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07086	13471	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07087	13472	N	N	N	1	CUSTOMER ISSUE	-
DMS_07088	13473	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07089	13474	N	N	N	1	CUSTOMER ISSUE	-
DMS_07090	13475	N	N	N	1	CUSTOMER ISSUE	-
DMS_07091	13476	N	N	N	1	CUSTOMER ISSUE	-
DMS_07092	13477	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07093	13478	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07094	13479	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07095	13480	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07096	13481	N	N	N	1	CUSTOMER ISSUE	-
DMS_07097	13482	N	N	N	1	CUSTOMER ISSUE	-
DMS_07098	13483	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07099	13484	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07100	13485	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07101	13486	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07102	13487	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07103	13488	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07104	13489	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07105	13490	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07106	13491	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07107	13492	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07108	13493	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07109	13494	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07110	13495	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07111	13496	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_07112	13497	N	N	N	1	CUSTOMER ISSUE	-
DMS_07113	13498	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07114	13499	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07115	13500	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07116	13501	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07117	13502	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07118	13503	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07119	13504	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07120	13505	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07121	13506	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07122	13507	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07123	13508	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07124	13509	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07125	13510	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07126	13511	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07127	13512	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07128	13513	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07129	13514	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07130	13515	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07131	13516	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07132	13517	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07133	13518	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07134	13519	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07135	13520	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07136	13521	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07137	13522	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07138	13523	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07139	13524	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07140	13525	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07141	13526	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07142	13527	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07143	13528	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07144	13529	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07145	13530	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07146	13531	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07147	13532	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07148	13533	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07149	13534	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07150	13535	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07151	13536	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07152	13537	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07153	13538	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_07154	13539	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07155	13540	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07156	13541	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07157	13542	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07158	13543	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07159	13544	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07160	13545	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07161	13546	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07162	13547	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07163	13548	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07164	13549	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07165	13550	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07166	13551	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07167	13552	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07168	13553	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07169	13554	N	N	N	1	CUSTOMER ISSUE	-
DMS_07170	13555	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07171	13556	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07172	13557	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07173	13558	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07174	13559	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07175	13560	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07176	13561	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07177	13562	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07178	13563	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07179	13564	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07180	13565	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07181	13566	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07182	13567	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07183	13568	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07184	13569	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07185	13570	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07186	13571	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07187	13572	N	N	N	1	CUSTOMER ISSUE	-
DMS_07188	13573	N	N	N	1	CUSTOMER ISSUE	-
DMS_07189	13574	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07190	13575	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07191	13576	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_07192	13577	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07193	13578	N	N	N	1	CUSTOMER ISSUE	-
DMS_07194	13579	N	N	N	1	CUSTOMER ISSUE	-
DMS_07195	13580	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07196	13581	N	N	N	1	CUSTOMER ISSUE	-
DMS_07197	13582	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07198	13583	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07199	13584	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07200	13585	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07201	13586	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07202	13587	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07203	13588	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07204	13589	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07205	13590	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07206	13591	N	N	N	1	CUSTOMER ISSUE	-
DMS_07207	13592	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07208	13593	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07209	13594	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07210	13595	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07211	13596	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07212	13597	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07213	13598	N	N	N	1	CUSTOMER ISSUE	-
DMS_07214	13599	N	N	N	1	CUSTOMER ISSUE	-
DMS_07215	13600	N	N	N	1	CUSTOMER ISSUE	-
DMS_07216	13601	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07217	13602	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07218	13603	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07219	13604	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07220	13605	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07221	13606	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07222	13607	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07223	13608	N	N	N	1	CUSTOMER ISSUE	-
DMS_07224	13609	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07225	13610	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07226	13611	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07227	13612	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07228	13613	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07229	13614	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07230	13615	N	N	N	1	CUSTOMER ISSUE	-
DMS_07231	13616	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07232	13617	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07233	13618	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07234	13619	N	N	N	1	CUSTOMER ISSUE	-
DMS_07235	13620	N	N	N	1	CUSTOMER ISSUE	-
DMS_07236	13621	N	N	N	1	CUSTOMER ISSUE	-
DMS_07237	13622	N	N	N	1	CUSTOMER ISSUE	-
DMS_07238	13623	N	N	N	1	CUSTOMER ISSUE	-
DMS_07239	13624	N	N	N	1	CUSTOMER ISSUE	-
DMS_07240	13625	N	N	N	1	CUSTOMER ISSUE	-
DMS_07241	13626	N	N	N	1	CUSTOMER ISSUE	-
DMS_07242	13627	N	N	N	1	CUSTOMER ISSUE	-
DMS_07243	13628	N	N	N	1	CUSTOMER ISSUE	-
DMS_07244	13629	N	N	N	1	CUSTOMER ISSUE	-
DMS_07245	13630	N	N	N	1	CUSTOMER ISSUE	-
DMS_07246	13631	N	N	N	1	CUSTOMER ISSUE	-
DMS_07247	13632	N	N	N	1	CUSTOMER ISSUE	-
DMS_07248	13633	N	N	N	1	CUSTOMER ISSUE	-
DMS_07249	13634	N	N	N	1	CUSTOMER ISSUE	-
DMS_07250	13635	N	N	N	1	CUSTOMER ISSUE	-
DMS_07251	13636	N	N	N	1	CUSTOMER ISSUE	-
DMS_07252	13637	N	N	N	1	CUSTOMER ISSUE	-
DMS_07253	13638	N	N	N	1	CUSTOMER ISSUE	-
DMS_07254	13639	N	N	N	1	CUSTOMER ISSUE	-
DMS_07255	13640	N	N	N	1	CUSTOMER ISSUE	-
DMS_07256	13641	N	N	N	1	CUSTOMER ISSUE	-
DMS_07257	13642	N	N	N	1	CUSTOMER ISSUE	-
DMS_07258	13643	N	N	N	3	CUSTOMER ISSUE	-
DMS_07259	13644	N	N	N	1	CUSTOMER ISSUE	-
DMS_07260	13645	N	N	N	1	CUSTOMER ISSUE	-
DMS_07261	13646	N	N	N	1	CUSTOMER ISSUE	-
DMS_07262	13647	N	N	N	3	CUSTOMER ISSUE	-
DMS_07263	13648	N	N	N	1	CUSTOMER ISSUE	-
DMS_07264	13649	N	N	N	1	CUSTOMER ISSUE	-
DMS_07265	13650	N	N	N	1	CUSTOMER ISSUE	-
DMS_07266	13651	N	N	N	1	CUSTOMER ISSUE	-
DMS_07268	13652	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07270	13653	N	N	N	1	CUSTOMER ISSUE	-
DMS_07271	13654	N	N	N	1	CUSTOMER ISSUE	-
DMS_07272	13655	N	N	N	1	CUSTOMER ISSUE	-
DMS_07273	13656	N	N	N	1	CUSTOMER ISSUE	-

DMS_07274	13657	N	N	N	1	CUSTOMER ISSUE	-
DMS_07275	13658	N	N	N	1	CUSTOMER ISSUE	-
DMS_07276	13659	N	N	N	1	CUSTOMER ISSUE	-
DMS_07277	13660	N	N	N	1	CUSTOMER ISSUE	-
DMS_07278	13661	N	N	N	1	CUSTOMER ISSUE	-
DMS_07279	13662	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07280	13663	N	N	N	1	CUSTOMER ISSUE	-
DMS_07281	13664	N	N	N	1	CUSTOMER ISSUE	-
DMS_07282	13665	N	N	Y	1	TX - REPLACE	2500
DMS_07283	13666	N	N	N	1	CUSTOMER ISSUE	-
DMS_07284	13667	N	N	N	1	CUSTOMER ISSUE	-
DMS_07286	13668	N	N	N	1	CUSTOMER ISSUE	-
DMS_07288	13669	N	N	N	1	CUSTOMER ISSUE	-
DMS_07289	13670	N	N	N	1	CUSTOMER ISSUE	-
DMS_07290	13671	N	N	N	1	CUSTOMER ISSUE	-
DMS_07291	13672	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_07292	13673	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_07293	13674	N	N	N	1	CUSTOMER ISSUE	-
DMS_07294	13675	N	N	N	1	CUSTOMER ISSUE	-
DMS_07295	13676	N	N	N	1	CUSTOMER ISSUE	-
DMS_07296	13677	N	N	N	1	CUSTOMER ISSUE	-
DMS_07297	13678	N	N	N	1	CUSTOMER ISSUE	-
DMS_07298	13679	N	N	N	1	CUSTOMER ISSUE	-
DMS_07300	13680	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07301	13681	N	N	Y	1	TX - REPLACE	2500
DMS_07305	13682	N	N	N	1	CUSTOMER ISSUE	-
DMS_07306	13683	N	N	N	1	CUSTOMER ISSUE	-
DMS_07309	13684	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07310	13685	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07311	13686	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07312	13687	N	N	Y	1	TX - REPLACE	2500
DMS_07313	13688	N	N	Y	1	TX - REPLACE	2500
DMS_07314	13689	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07315	13690	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_07316	13691	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07317	13692	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07318	13693	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07319	13694	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07320	13695	N	N	N	1	CUSTOMER ISSUE	-
DMS_07321	13696	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07324	13697	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07325	13698	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07326	13699	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07327	13700	N	N	N	1	CUSTOMER ISSUE	-
DMS_07328	13701	N	N	N	1	CUSTOMER ISSUE	-
DMS_07329	13702	N	N	N	1	CUSTOMER ISSUE	-
DMS_07331	13703	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_07333	13704	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07334	13705	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07335	13706	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07336	13707	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07337	13708	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07338	13709	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07339	13710	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07340	13711	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07342	13712	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07343	13713	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07344	13714	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07345	13715	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07346	13716	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07347	13717	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07348	13718	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07349	13719	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07351	13720	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07352	13721	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07353	13722	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07355	13723	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07356	13724	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07357	13725	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07358	13726	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07359	13727	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07360	13728	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07361	13729	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07362	13730	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07363	13731	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07364	13732	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07365	13733	N	N	Y	1	TX - REPLACE	2500
DMS_07366	13734	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07368	13735	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07369	13736	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_07370	13737	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07371	13738	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07372	13739	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07373	13740	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07374	13741	N	N	N	1	CUSTOMER ISSUE	-
DMS_07375	13742	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07376	13743	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07378	13744	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07379	13745	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07380	13746	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07381	13747	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07382	13748	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07383	13749	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07384	13750	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07385	13751	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07386	13752	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07387	13753	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07388	13754	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07389	13755	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07393	13756	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07394	13757	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07395	13758	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07396	13759	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07397	13760	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07398	13761	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07399	13762	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07400	13763	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07401	13764	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07403	13765	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07404	13766	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_07405	13767	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07409	13768	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07411	13769	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07412	13770	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07413	13771	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07414	13772	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_07415	13773	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07416	13774	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07417	13775	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07418	13776	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07419	13777	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07420	13778	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07421	13779	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07422	13780	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07423	13781	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07424	13782	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07425	13783	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07426	13784	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07427	13785	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07428	13786	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07429	13787	N	N	N	1	CUSTOMER ISSUE	-
DMS_07431	13788	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07433	13789	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07434	13790	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07435	13791	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07436	13792	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07438	13793	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07439	13794	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07440	13795	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_07441	13796	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07442	13797	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07443	13798	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07445	13799	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07446	13800	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07447	13801	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07448	13802	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07449	13803	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07453	13804	N	N	N	1	CUSTOMER ISSUE	-
DMS_07455	13805	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07456	13806	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07457	13807	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07458	13808	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07459	13809	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07460	13810	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07461	13811	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07462	13812	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07463	13813	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07464	13814	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07465	13815	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07466	13816	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_07467	13817	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07468	13818	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07470	13819	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07471	13820	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07472	13821	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07473	13822	N	N	Y	1	TX - REPLACE	2500
DMS_07474	13823	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07475	13824	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07476	13825	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07477	13826	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07478	13827	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07479	13828	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07480	13829	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07481	13830	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07482	13831	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07483	13832	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07484	13833	N	N	Y	1	TX - REPLACE	2500
DMS_07485	13834	N	N	Y	1	TX - REPLACE	2500
DMS_07487	13835	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07488	13836	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07489	13837	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07490	13838	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07491	13839	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07492	13840	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07493	13841	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07495	13842	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07496	13843	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07498	13844	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07505	13845	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07508	13846	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07509	13847	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07511	13848	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07512	13849	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07513	13850	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07514	13851	N	N	N	1	CUSTOMER ISSUE	-
DMS_07515	13852	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07516	13853	N	N	N	2	CUSTOMER ISSUE	-
DMS_07517	13854	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07518	13855	N	N	N	1	CUSTOMER ISSUE	-
DMS_07520	13856	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07522	13857	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07523	13858	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07524	13859	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07525	13860	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07526	13861	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07527	13862	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07528	13863	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07529	13864	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
DMS_07530	13865	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07533	13866	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07534	13867	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07535	13868	N	N	N	1	CUSTOMER ISSUE	-
DMS_07536	13869	N	N	N	1	CUSTOMER ISSUE	-
DMS_07537	13870	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07538	13871	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07539	13872	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07541	13873	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07542	13874	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07543	13875	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07547	13876	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07548	13877	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07549	13878	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07550	13879	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07552	13880	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07553	13881	N	N	Y	1	TX - REPLACE	2500
DMS_07554	13882	N	N	Y	1	TX - REPLACE	2500
DMS_07555	13883	N	N	N	1	CUSTOMER ISSUE	-
DMS_07558	13884	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07559	13885	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07560	13886	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07562	13887	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07563	13888	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07564	13889	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07565	13890	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07566	13891	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07567	13892	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07568	13893	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07569	13894	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07570	13895	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07573	13896	N	N	Y	1	DIST - TREE TRIMMING	945

DMS_07574	13897	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07575	13898	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07576	13899	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07579	13900	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07580	13901	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07581	13902	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07582	13903	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07583	13904	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07584	13905	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07585	13906	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07586	13907	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07587	13908	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07588	13909	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07589	13910	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07590	13911	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07591	13912	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07592	13913	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07593	13914	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07594	13915	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07595	13916	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07596	13917	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07597	13918	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07601	13919	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07604	13920	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07606	13921	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07608	13922	N	N	N	1	CUSTOMER ISSUE	-
DMS_07610	13923	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07612	13924	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07613	13925	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07614	13926	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07615	13927	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07616	13928	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07617	13929	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07618	13930	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07619	13931	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07620	13932	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07621	13933	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07622	13934	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07623	13935	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07624	13936	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07625	13937	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07626	13938	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07627	13939	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07628	13940	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07629	13941	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07630	13942	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07631	13943	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07632	13944	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07633	13945	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07635	13946	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07636	13947	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07637	13948	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07638	13949	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07639	13950	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07640	13951	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07641	13952	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07642	13953	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07643	13954	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07644	13955	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07645	13956	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07646	13957	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07647	13958	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07648	13959	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07649	13960	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07650	13961	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07651	13962	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07652	13963	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07653	13964	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07654	13965	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07655	13966	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07656	13967	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07657	13968	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07658	13969	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07659	13970	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07660	13971	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07661	13972	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07662	13973	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07663	13974	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07664	13975	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07665	13976	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_07666	13977	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07667	13978	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07668	13979	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07669	13980	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07670	13981	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07671	13982	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07672	13983	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07673	13984	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07674	13985	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07675	13986	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07676	13987	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07677	13988	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07678	13989	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07679	13990	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07680	13991	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07681	13992	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07682	13993	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07684	13994	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07685	13995	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07686	13996	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07687	13997	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07688	13998	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07689	13999	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07690	14000	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07691	14001	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07692	14002	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07693	14003	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07694	14004	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07695	14005	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07696	14006	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07697	14007	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07698	14008	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07699	14009	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07700	14010	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07701	14011	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07702	14012	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07703	14013	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07704	14014	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07705	14015	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07706	14016	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07707	14017	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07708	14018	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07710	14019	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07711	14020	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07712	14021	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07713	14022	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07714	14023	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07715	14024	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07716	14025	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07717	14026	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07718	14027	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07719	14028	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07720	14029	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07721	14030	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07722	14031	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07723	14032	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07724	14033	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07725	14034	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07726	14035	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07727	14036	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07728	14037	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07729	14038	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07730	14039	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07731	14040	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07732	14041	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_07733	14042	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07734	14043	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07735	14044	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07736	14045	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07737	14046	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07738	14047	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07739	14048	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07740	14049	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07741	14050	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_07742	14051	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07743	14052	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_07744	14053	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07745	14054	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07747	14055	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07748	14056	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_07751	14057	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07752	14058	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07753	14059	N	N	Y	1	TX - REPLACE	2500
DMS_07756	14060	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07763	14061	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_07770	14062	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07771	14063	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07774	14064	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07775	14065	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07776	14066	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07777	14067	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07778	14068	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07779	14069	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07780	14070	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07781	14071	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_07782	14072	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07783	14073	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07784	14074	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07785	14075	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07786	14076	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07787	14077	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07788	14078	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07789	14079	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07790	14080	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07791	14081	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07792	14082	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07793	14083	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07794	14084	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07795	14085	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07796	14086	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07797	14087	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07798	14088	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07799	14089	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07800	14090	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07801	14091	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07802	14092	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07803	14093	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07804	14094	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07805	14095	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07806	14096	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07807	14097	N	N	Y	3	SEC/SVC - REPAIR	472.5
DMS_07808	14098	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07809	14099	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07810	14100	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07811	14101	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07812	14102	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07813	14103	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07814	14104	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07815	14105	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07816	14106	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07817	14107	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07818	14108	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07819	14109	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07820	14110	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07821	14111	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07822	14112	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07823	14113	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07824	14114	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07825	14115	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07826	14116	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07827	14117	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07828	14118	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07829	14119	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07830	14120	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07831	14121	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_07832	14122	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07833	14123	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07834	14124	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07835	14125	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07836	14126	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07837	14127	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07838	14128	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07839	14129	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07840	14130	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07841	14131	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07842	14132	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07843	14133	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07844	14134	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07845	14135	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07846	14136	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_07847	14137	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07848	14138	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07849	14139	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07850	14140	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07851	14141	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_07852	14142	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07853	14143	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07854	14144	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07855	14145	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07856	14146	N	N	Y	1	TX - REPLACE	2500
DMS_07857	14147	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07858	14148	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07859	14149	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07860	14150	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_07861	14151	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07862	14152	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07863	14153	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07864	14154	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07865	14155	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07866	14156	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07867	14157	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07868	14158	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07869	14159	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07870	14160	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07871	14161	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07872	14162	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07873	14163	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07874	14164	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07875	14165	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07876	14166	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07877	14167	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07878	14168	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07879	14169	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07880	14170	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07881	14171	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07882	14172	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07884	14173	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07885	14174	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07886	14175	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07887	14176	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07888	14177	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07889	14178	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07890	14179	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07891	14180	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07892	14181	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07893	14182	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07894	14183	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07895	14184	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07896	14185	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07897	14186	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_07898	14187	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07899	14188	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07901	14189	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07902	14190	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07903	14191	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07904	14192	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07905	14193	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07906	14194	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07907	14195	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_07908	14196	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07909	14197	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07910	14198	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07911	14199	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07912	14200	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07913	14201	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07914	14202	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07919	14203	N	N	Y	1	TX - REPLACE	2500
DMS_07920	14204	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07921	14205	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07922	14206	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07923	14207	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07925	14208	N	N	Y	1	TX - REPLACE	2500
DMS_07926	14209	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07927	14210	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07928	14211	N	N	Y	1	TX - REPLACE	2500
DMS_07929	14212	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_07930	14213	N	N	Y	1	TX - REPLACE	2500
DMS_07931	14214	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07933	14215	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07934	14216	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_07935	14217	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07936	14218	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07937	14219	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_07938	14220	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07939	14221	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_07940	14222	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07941	14223	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07942	14224	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07943	14225	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07944	14226	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07945	14227	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07946	14228	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07947	14229	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07948	14230	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07949	14231	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07950	14232	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07951	14233	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07952	14234	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07953	14235	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07954	14236	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07955	14237	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07956	14238	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07957	14239	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07958	14240	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07959	14241	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07960	14242	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07961	14243	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07962	14244	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07963	14245	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07964	14246	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07965	14247	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07966	14248	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07967	14249	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07969	14250	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07970	14251	N	N	Y	1	TX - REPLACE	2500
DMS_07971	14252	N	N	Y	1	TX - REPLACE	2500
DMS_07972	14253	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07973	14254	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07974	14255	N	N	Y	1	TX - REPLACE	2500
DMS_07975	14256	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
DMS_07976	14257	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07977	14258	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07978	14259	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07979	14260	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07980	14261	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07981	14262	N	N	Y	1	TX - REPLACE	2500
DMS_07982	14263	N	N	Y	1	TX - REPLACE	2500
DMS_07983	14264	N	N	Y	1	TX - REPLACE	2500
DMS_07984	14265	N	N	Y	1	TX - REPLACE	2500
DMS_07985	14266	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07986	14267	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07987	14268	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07989	14269	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_07990	14270	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07991	14271	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07992	14272	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07993	14273	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07994	14274	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07995	14275	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07996	14276	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07997	14277	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_07998	14278	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_07999	14279	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08000	14280	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08001	14281	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08002	14282	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08003	14283	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08004	14284	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08005	14285	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08006	14286	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08007	14287	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08008	14288	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08009	14289	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08010	14290	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08011	14291	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08012	14292	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08013	14293	N	N	Y	1	TX - REPLACE	2500
DMS_08014	14294	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08015	14295	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08016	14296	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_08017	14297	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_08018	14298	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08019	14299	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08020	14300	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08021	14301	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08022	14302	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08023	14303	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08024	14304	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08025	14305	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08026	14306	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08027	14307	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08028	14308	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08029	14309	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08030	14310	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08031	14311	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08032	14312	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08033	14313	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08034	14314	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08035	14315	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08036	14316	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08037	14317	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08038	14318	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08039	14319	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08041	14320	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08042	14321	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08043	14322	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08044	14323	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08045	14324	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08046	14325	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08047	14326	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08048	14327	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08049	14328	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08050	14329	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08051	14330	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08052	14331	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08053	14332	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08054	14333	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08055	14334	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08056	14335	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08057	14336	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08058	14337	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08059	14338	N	N	Y	1	TX - REPLACE	2500
DMS_08060	14339	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08061	14340	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08062	14341	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08064	14342	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08065	14343	N	N	Y	1	TX - REPLACE	2500
DMS_08066	14344	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08067	14345	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08068	14346	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08069	14347	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08070	14348	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08071	14349	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08072	14350	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08073	14351	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08074	14352	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08075	14353	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08076	14354	N	N	Y	1	TX - REPLACE	2500
DMS_08077	14355	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08078	14356	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08079	14357	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08080	14358	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08081	14359	N	N	Y	1	TX - REPLACE	2500
DMS_08082	14360	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08083	14361	N	N	Y	1	TX - REPLACE	2500
DMS_08084	14362	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08085	14363	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08086	14364	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08087	14365	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08088	14366	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08089	14367	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08090	14368	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08091	14369	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08092	14370	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08093	14371	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08094	14372	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08095	14373	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08096	14374	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08098	14375	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08099	14376	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_08100	14377	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08101	14378	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08102	14379	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08103	14380	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08104	14381	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08105	14382	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08106	14383	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08107	14384	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08108	14385	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08109	14386	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08110	14387	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08111	14388	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08112	14389	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08113	14390	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08114	14391	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08115	14392	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08116	14393	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08117	14394	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08118	14395	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08119	14396	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08120	14397	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08121	14398	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08122	14399	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08123	14400	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08124	14401	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08125	14402	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08126	14403	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08127	14404	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08128	14405	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08129	14406	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08130	14407	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08131	14408	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08132	14409	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08133	14410	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08134	14411	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08135	14412	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08136	14413	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08137	14414	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08138	14415	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08139	14416	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08140	14417	N	N	Y	1	TX - REPLACE	2500
DMS_08141	14418	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08142	14419	N	N	Y	1	TX - REPLACE	2500
DMS_08143	14420	N	N	Y	1	TX - REPLACE	2500
DMS_08144	14421	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_08145	14422	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_08146	14423	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_08147	14424	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08148	14425	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_08149	14426	N	N	Y	1	TX - REPLACE	2500
DMS_08150	14427	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_08151	14428	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_08152	14429	N	N	Y	1	TX - REPLACE	2500
DMS_08153	14430	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_08154	14431	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08155	14432	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_08156	14433	N	N	Y	1	TX - REPLACE	2500
DMS_08157	14434	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08158	14435	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08159	14436	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08160	14437	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08161	14438	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08162	14439	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08163	14440	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08164	14441	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08165	14442	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08166	14443	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08167	14444	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08168	14445	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08169	14446	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08170	14447	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08171	14448	N	N	Y	1	TX - REPLACE	2500
DMS_08172	14449	N	N	Y	1	TX - REPLACE	2500
DMS_08173	14450	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08174	14451	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08175	14452	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08177	14453	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08178	14454	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08179	14455	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08180	14456	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_08181	14457	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08182	14458	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08184	14459	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08186	14460	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08187	14461	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08188	14462	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08189	14463	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08190	14464	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08191	14465	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08192	14466	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08193	14467	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08194	14468	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08196	14469	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08197	14470	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08198	14471	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08199	14472	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08200	14473	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08201	14474	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08202	14475	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08203	14476	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08204	14477	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08205	14478	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08206	14479	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08207	14480	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08208	14481	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08209	14482	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08210	14483	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08211	14484	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08212	14485	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08213	14486	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08214	14487	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08215	14488	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08216	14489	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08217	14490	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08218	14491	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08219	14492	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08220	14493	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08221	14494	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08222	14495	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08223	14496	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08224	14497	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08225	14498	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08226	14499	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_08227	14500	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08228	14501	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08229	14502	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08230	14503	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08231	14504	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08232	14505	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08233	14506	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08234	14507	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08235	14508	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08236	14509	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08237	14510	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08238	14511	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08239	14512	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08240	14513	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08241	14514	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08242	14515	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08243	14516	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08244	14517	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08245	14518	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08246	14519	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08247	14520	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08248	14521	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08249	14522	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08250	14523	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08251	14524	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08252	14525	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08253	14526	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08254	14527	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08255	14528	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08256	14529	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08257	14530	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08258	14531	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08259	14532	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08260	14533	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08261	14534	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08262	14535	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08263	14536	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_08264	14537	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08265	14538	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08266	14539	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08267	14540	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08268	14541	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08269	14542	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08270	14543	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08271	14544	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08272	14545	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08273	14546	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08274	14547	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08275	14548	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08276	14549	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08277	14550	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08278	14551	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08279	14552	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08280	14553	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08281	14554	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08282	14555	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08283	14556	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08284	14557	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08285	14558	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08286	14559	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08287	14560	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08288	14561	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08289	14562	N	N	Y	4	SEC/SVC - REPLACE	708.75
DMS_08290	14563	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08291	14564	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08292	14565	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08293	14566	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08294	14567	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08295	14568	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08296	14569	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08297	14570	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08298	14571	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08299	14572	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08300	14573	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08301	14574	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08302	14575	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08303	14576	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08304	14577	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08306	14578	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08307	14579	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08308	14580	N	N	Y	1	TX - REPLACE	2500
DMS_08309	14581	N	N	Y	1	TX - REPLACE	2500
DMS_08310	14582	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_08311	14583	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_08312	14584	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_08313	14585	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_08314	14586	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_08315	14587	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_08316	14588	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_08317	14589	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_08318	14590	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_08319	14591	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_08320	14592	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08321	14593	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08322	14594	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08323	14595	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08324	14596	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08325	14597	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08326	14598	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08327	14599	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08328	14600	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08329	14601	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08330	14602	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08331	14603	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08333	14604	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08334	14605	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08335	14606	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08336	14607	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08337	14608	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08339	14609	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08340	14610	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08341	14611	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08342	14612	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08343	14613	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08345	14614	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08346	14615	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08347	14616	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_08349	14617	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08350	14618	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08351	14619	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08352	14620	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08353	14621	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08355	14622	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08359	14623	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08363	14624	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08364	14625	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08365	14626	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_08366	14627	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08367	14628	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08368	14629	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08369	14630	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08370	14631	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08371	14632	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08372	14633	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_08374	14634	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08375	14635	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08376	14636	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08377	14637	N	N	N	1	CUSTOMER ISSUE	-
DMS_08378	14638	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08382	14639	N	N	N	1	CUSTOMER ISSUE	-
DMS_08383	14640	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08385	14641	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08386	14642	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08387	14643	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_08390	14644	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_08410	14645	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08411	14646	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08413	14647	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08414	14648	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08415	14649	N	N	N	1	CUSTOMER ISSUE	-
DMS_08416	14650	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08417	14651	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08418	14652	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_08421	14653	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08422	14654	N	N	Y	1	TX - REPLACE	2500
DMS_08424	14655	N	N	N	1	CUSTOMER ISSUE	-
DMS_08425	14656	N	N	N	1	CUSTOMER ISSUE	-
DMS_08426	14657	N	N	N	1	CUSTOMER ISSUE	-
DMS_08427	14658	N	N	N	1	CUSTOMER ISSUE	-
DMS_08428	14659	N	N	N	1	CUSTOMER ISSUE	-
DMS_08429	14660	N	N	N	1	CUSTOMER ISSUE	-
DMS_08430	14661	N	N	N	1	CUSTOMER ISSUE	-
DMS_08431	14662	N	N	N	1	CUSTOMER ISSUE	-
DMS_08432	14663	N	N	N	1	CUSTOMER ISSUE	-
DMS_08433	14664	N	N	N	1	CUSTOMER ISSUE	-
DMS_08434	14665	N	N	N	1	CUSTOMER ISSUE	-
DMS_08435	14666	N	N	N	1	CUSTOMER ISSUE	-
DMS_08436	14667	N	N	N	1	CUSTOMER ISSUE	-
DMS_08437	14668	N	N	N	1	CUSTOMER ISSUE	-
DMS_08438	14669	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08439	14670	N	N	N	1	CUSTOMER ISSUE	-
DMS_08440	14671	N	N	N	1	CUSTOMER ISSUE	-
DMS_08441	14672	N	N	N	1	CUSTOMER ISSUE	-
DMS_08442	14673	N	N	N	1	CUSTOMER ISSUE	-
DMS_08443	14674	N	N	N	1	CUSTOMER ISSUE	-
DMS_08444	14675	N	N	N	1	CUSTOMER ISSUE	-
DMS_08445	14676	N	N	N	1	CUSTOMER ISSUE	-
DMS_08446	14677	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08447	14678	N	N	N	1	CUSTOMER ISSUE	-
DMS_08448	14679	N	N	N	1	CUSTOMER ISSUE	-
DMS_08449	14680	N	N	N	1	CUSTOMER ISSUE	-
DMS_08450	14681	N	N	N	1	CUSTOMER ISSUE	-
DMS_08451	14682	N	N	N	1	CUSTOMER ISSUE	-
DMS_08453	14683	N	N	N	1	CUSTOMER ISSUE	-
DMS_08454	14684	N	N	N	1	CUSTOMER ISSUE	-
DMS_08455	14685	N	N	N	1	CUSTOMER ISSUE	-
DMS_08456	14686	N	N	N	1	CUSTOMER ISSUE	-
DMS_08457	14687	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_08458	14688	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08459	14689	N	N	N	1	CUSTOMER ISSUE	-
DMS_08460	14690	N	N	N	1	CUSTOMER ISSUE	-
DMS_08461	14691	N	N	N	1	CUSTOMER ISSUE	-
DMS_08462	14692	N	N	N	1	CUSTOMER ISSUE	-
DMS_08463	14693	N	N	N	1	CUSTOMER ISSUE	-
DMS_08464	14694	N	N	N	1	CUSTOMER ISSUE	-
DMS_08465	14695	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_08466	14696	N	N	N	1	CUSTOMER ISSUE	-

DMS_08467	14697	N	N	N	1	CUSTOMER ISSUE	-
DMS_08468	14698	N	N	N	1	CUSTOMER ISSUE	-
DMS_08469	14699	N	N	N	1	CUSTOMER ISSUE	-
DMS_08470	14700	N	N	N	1	CUSTOMER ISSUE	-
DMS_08471	14701	N	N	N	1	CUSTOMER ISSUE	-
DMS_08472	14702	N	N	N	1	CUSTOMER ISSUE	-
DMS_08473	14703	N	N	N	1	CUSTOMER ISSUE	-
DMS_08474	14704	N	N	N	1	CUSTOMER ISSUE	-
DMS_08475	14705	N	N	N	1	CUSTOMER ISSUE	-
DMS_08476	14706	N	N	N	1	CUSTOMER ISSUE	-
DMS_08477	14707	N	N	N	1	CUSTOMER ISSUE	-
DMS_08478	14708	N	N	N	1	CUSTOMER ISSUE	-
DMS_08479	14709	N	N	N	1	CUSTOMER ISSUE	-
DMS_08480	14710	N	N	N	1	CUSTOMER ISSUE	-
DMS_08481	14711	N	N	N	1	CUSTOMER ISSUE	-
DMS_08482	14712	N	N	N	1	CUSTOMER ISSUE	-
DMS_08483	14713	N	N	N	1	CUSTOMER ISSUE	-
DMS_08484	14714	N	N	N	1	CUSTOMER ISSUE	-
DMS_08485	14715	N	N	N	1	CUSTOMER ISSUE	-
DMS_08486	14716	N	N	N	1	CUSTOMER ISSUE	-
DMS_08487	14717	N	N	N	1	CUSTOMER ISSUE	-
DMS_08488	14718	N	N	N	1	CUSTOMER ISSUE	-
DMS_08489	14719	N	N	N	1	CUSTOMER ISSUE	-
DMS_08490	14720	N	N	N	1	CUSTOMER ISSUE	-
DMS_08491	14721	N	N	N	1	CUSTOMER ISSUE	-
DMS_08492	14722	N	N	N	1	CUSTOMER ISSUE	-
DMS_08493	14723	N	N	N	1	CUSTOMER ISSUE	-
DMS_08494	14724	N	N	N	1	CUSTOMER ISSUE	-
DMS_08495	14725	N	N	N	1	CUSTOMER ISSUE	-
DMS_08496	14726	N	N	N	1	CUSTOMER ISSUE	-
DMS_08497	14727	N	N	N	1	CUSTOMER ISSUE	-
DMS_08498	14728	N	N	N	1	CUSTOMER ISSUE	-
DMS_08499	14729	N	N	N	1	CUSTOMER ISSUE	-
DMS_08500	14730	N	N	N	1	CUSTOMER ISSUE	-
DMS_08501	14731	N	N	N	2	CUSTOMER ISSUE	-
DMS_08502	14732	N	N	N	1	CUSTOMER ISSUE	-
DMS_08503	14733	N	N	N	1	CUSTOMER ISSUE	-
DMS_08504	14734	N	N	N	1	CUSTOMER ISSUE	-
DMS_08505	14735	N	N	N	1	CUSTOMER ISSUE	-
DMS_08506	14736	N	N	N	1	CUSTOMER ISSUE	-
DMS_08507	14737	N	N	N	1	CUSTOMER ISSUE	-
DMS_08508	14738	N	N	N	1	CUSTOMER ISSUE	-
DMS_08509	14739	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08510	14740	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_08511	14741	N	N	N	1	CUSTOMER ISSUE	-
DMS_08512	14742	N	N	N	1	CUSTOMER ISSUE	-
DMS_08513	14743	N	N	N	1	CUSTOMER ISSUE	-
DMS_08514	14744	N	N	N	1	CUSTOMER ISSUE	-
DMS_08515	14745	N	N	N	2	CUSTOMER ISSUE	-
DMS_08516	14746	N	N	N	1	CUSTOMER ISSUE	-
DMS_08517	14747	N	N	N	1	CUSTOMER ISSUE	-
DMS_08518	14748	N	N	N	1	CUSTOMER ISSUE	-
DMS_08519	14749	N	N	N	1	CUSTOMER ISSUE	-
DMS_08520	14750	N	N	N	1	CUSTOMER ISSUE	-
DMS_08521	14751	N	N	N	1	CUSTOMER ISSUE	-
DMS_08522	14752	N	N	N	1	CUSTOMER ISSUE	-
DMS_08523	14753	N	N	N	1	CUSTOMER ISSUE	-
DMS_08524	14754	N	N	N	1	CUSTOMER ISSUE	-
DMS_08525	14755	N	N	N	1	CUSTOMER ISSUE	-
DMS_08526	14756	N	N	N	1	CUSTOMER ISSUE	-
DMS_08527	14757	N	N	N	1	CUSTOMER ISSUE	-
DMS_08530	14758	N	N	N	1	CUSTOMER ISSUE	-
DMS_08531	14759	N	N	N	1	CUSTOMER ISSUE	-
DMS_08532	14760	N	N	N	1	CUSTOMER ISSUE	-
DMS_08533	14761	N	N	N	1	CUSTOMER ISSUE	-
DMS_08534	14762	N	N	N	1	CUSTOMER ISSUE	-
DMS_08535	14763	N	N	N	1	CUSTOMER ISSUE	-
DMS_08536	14764	N	N	N	1	CUSTOMER ISSUE	-
DMS_08537	14765	N	N	N	1	CUSTOMER ISSUE	-
DMS_08538	14766	N	N	N	1	CUSTOMER ISSUE	-
DMS_08539	14767	N	N	N	1	CUSTOMER ISSUE	-
DMS_08540	14768	N	N	N	1	CUSTOMER ISSUE	-
DMS_08541	14769	N	N	N	1	CUSTOMER ISSUE	-
DMS_08542	14770	N	N	N	1	CUSTOMER ISSUE	-
DMS_08543	14771	N	N	N	1	CUSTOMER ISSUE	-
DMS_08544	14772	N	N	N	1	CUSTOMER ISSUE	-
DMS_08545	14773	N	N	N	1	CUSTOMER ISSUE	-
DMS_08546	14774	N	N	N	1	CUSTOMER ISSUE	-
DMS_08547	14775	N	N	N	1	CUSTOMER ISSUE	-
DMS_08548	14776	N	N	N	1	CUSTOMER ISSUE	-

DMS_08549	14777	N	N	N	1	CUSTOMER ISSUE	-
DMS_08550	14778	N	N	N	1	CUSTOMER ISSUE	-
DMS_08551	14779	N	N	N	1	CUSTOMER ISSUE	-
DMS_08552	14780	N	N	N	1	CUSTOMER ISSUE	-
DMS_08553	14781	N	N	N	1	CUSTOMER ISSUE	-
DMS_08554	14782	N	N	N	2	CUSTOMER ISSUE	-
DMS_08555	14783	N	N	N	1	CUSTOMER ISSUE	-
DMS_08556	14784	N	N	N	1	CUSTOMER ISSUE	-
DMS_08557	14785	N	N	N	1	CUSTOMER ISSUE	-
DMS_08558	14786	N	N	N	1	CUSTOMER ISSUE	-
DMS_08559	14787	N	N	N	1	CUSTOMER ISSUE	-
DMS_08560	14788	N	N	N	1	CUSTOMER ISSUE	-
DMS_08561	14789	N	N	N	1	CUSTOMER ISSUE	-
DMS_08562	14790	N	N	N	1	CUSTOMER ISSUE	-
DMS_08563	14791	N	N	N	1	CUSTOMER ISSUE	-
DMS_08564	14792	N	N	N	1	CUSTOMER ISSUE	-
DMS_08565	14793	N	N	N	1	CUSTOMER ISSUE	-
DMS_08566	14794	N	N	N	1	CUSTOMER ISSUE	-
DMS_08567	14795	N	N	N	1	CUSTOMER ISSUE	-
DMS_08568	14796	N	N	N	1	CUSTOMER ISSUE	-
DMS_08569	14797	N	N	N	1	CUSTOMER ISSUE	-
DMS_08571	14798	N	N	N	1	CUSTOMER ISSUE	-
DMS_08572	14799	N	N	N	1	CUSTOMER ISSUE	-
DMS_08573	14800	N	N	N	1	CUSTOMER ISSUE	-
DMS_08574	14801	N	N	N	1	CUSTOMER ISSUE	-
DMS_08575	14802	N	N	N	1	CUSTOMER ISSUE	-
DMS_08576	14803	N	N	N	1	CUSTOMER ISSUE	-
DMS_08577	14804	N	N	N	1	CUSTOMER ISSUE	-
DMS_08578	14805	N	N	N	1	CUSTOMER ISSUE	-
DMS_08579	14806	N	N	N	1	CUSTOMER ISSUE	-
DMS_08580	14807	N	N	N	1	CUSTOMER ISSUE	-
DMS_08581	14808	N	N	N	1	CUSTOMER ISSUE	-
DMS_08582	14809	N	N	N	1	CUSTOMER ISSUE	-
DMS_08583	14810	N	N	N	1	CUSTOMER ISSUE	-
DMS_08584	14811	N	N	N	1	CUSTOMER ISSUE	-
DMS_08585	14812	N	N	N	1	CUSTOMER ISSUE	-
DMS_08586	14813	N	N	N	1	CUSTOMER ISSUE	-
DMS_08587	14814	N	N	N	1	CUSTOMER ISSUE	-
DMS_08588	14815	N	N	N	1	CUSTOMER ISSUE	-
DMS_08589	14816	N	N	N	1	CUSTOMER ISSUE	-
DMS_08590	14817	N	N	N	1	CUSTOMER ISSUE	-
DMS_08591	14818	N	N	N	1	CUSTOMER ISSUE	-
DMS_08592	14819	N	N	N	1	CUSTOMER ISSUE	-
DMS_08593	14820	N	N	N	1	CUSTOMER ISSUE	-
DMS_08594	14821	N	N	N	1	CUSTOMER ISSUE	-
DMS_08595	14822	N	N	N	1	CUSTOMER ISSUE	-
DMS_08596	14823	N	N	N	1	CUSTOMER ISSUE	-
DMS_08597	14824	N	N	N	1	CUSTOMER ISSUE	-
DMS_08598	14825	N	N	N	1	CUSTOMER ISSUE	-
DMS_08599	14826	N	N	N	1	CUSTOMER ISSUE	-
DMS_08600	14827	N	N	N	1	CUSTOMER ISSUE	-
DMS_08601	14828	N	N	N	1	CUSTOMER ISSUE	-
DMS_08602	14829	N	N	N	1	CUSTOMER ISSUE	-
DMS_08603	14830	N	N	N	1	CUSTOMER ISSUE	-
DMS_08604	14831	N	N	N	1	CUSTOMER ISSUE	-
DMS_08605	14832	N	N	N	1	CUSTOMER ISSUE	-
DMS_08606	14833	N	N	N	1	CUSTOMER ISSUE	-
DMS_08607	14834	N	N	N	1	CUSTOMER ISSUE	-
DMS_08608	14835	N	N	N	1	CUSTOMER ISSUE	-
DMS_08609	14836	N	N	N	1	CUSTOMER ISSUE	-
DMS_08610	14837	N	N	N	1	CUSTOMER ISSUE	-
DMS_08611	14838	N	N	N	1	CUSTOMER ISSUE	-
DMS_08612	14839	N	N	N	1	CUSTOMER ISSUE	-
DMS_08613	14840	N	N	N	1	CUSTOMER ISSUE	-
DMS_08614	14841	N	N	N	1	CUSTOMER ISSUE	-
DMS_08615	14842	N	N	N	1	CUSTOMER ISSUE	-
DMS_08616	14843	N	N	N	1	CUSTOMER ISSUE	-
DMS_08617	14844	N	N	N	1	CUSTOMER ISSUE	-
DMS_08618	14845	N	N	N	1	CUSTOMER ISSUE	-
DMS_08619	14846	N	N	N	1	CUSTOMER ISSUE	-
DMS_08620	14847	N	N	N	1	CUSTOMER ISSUE	-
DMS_08621	14848	N	N	N	1	CUSTOMER ISSUE	-
DMS_08622	14849	N	N	N	1	CUSTOMER ISSUE	-
DMS_08623	14850	N	N	N	1	CUSTOMER ISSUE	-
DMS_08624	14851	N	N	N	1	CUSTOMER ISSUE	-
DMS_08625	14852	N	N	N	1	CUSTOMER ISSUE	-
DMS_08626	14853	N	N	N	1	CUSTOMER ISSUE	-
DMS_08627	14854	N	N	N	1	CUSTOMER ISSUE	-
DMS_08628	14855	N	N	N	1	CUSTOMER ISSUE	-
DMS_08629	14856	N	N	N	1	CUSTOMER ISSUE	-

DMS_08630	14857	N	N	N	1	CUSTOMER ISSUE	-
DMS_08631	14858	N	N	N	1	CUSTOMER ISSUE	-
DMS_08632	14859	N	N	N	1	CUSTOMER ISSUE	-
DMS_08633	14860	N	N	N	1	CUSTOMER ISSUE	-
DMS_08634	14861	N	N	N	1	CUSTOMER ISSUE	-
DMS_08635	14862	N	N	N	1	CUSTOMER ISSUE	-
DMS_08636	14863	N	N	N	1	CUSTOMER ISSUE	-
DMS_08637	14864	N	N	N	1	CUSTOMER ISSUE	-
DMS_08638	14865	N	N	N	1	CUSTOMER ISSUE	-
DMS_08639	14866	N	N	N	1	CUSTOMER ISSUE	-
DMS_08640	14867	N	N	N	1	CUSTOMER ISSUE	-
DMS_08641	14868	N	N	N	1	CUSTOMER ISSUE	-
DMS_08642	14869	N	N	N	1	CUSTOMER ISSUE	-
DMS_08643	14870	N	N	N	1	CUSTOMER ISSUE	-
DMS_08644	14871	N	N	N	1	CUSTOMER ISSUE	-
DMS_08645	14872	N	N	N	1	CUSTOMER ISSUE	-
DMS_08646	14873	N	N	N	1	CUSTOMER ISSUE	-
DMS_08647	14874	N	N	N	1	CUSTOMER ISSUE	-
DMS_08648	14875	N	N	N	1	CUSTOMER ISSUE	-
DMS_08649	14876	N	N	N	1	CUSTOMER ISSUE	-
DMS_08650	14877	N	N	N	1	CUSTOMER ISSUE	-
DMS_08651	14878	N	N	N	1	CUSTOMER ISSUE	-
DMS_08652	14879	N	N	N	1	CUSTOMER ISSUE	-
DMS_08653	14880	N	N	N	1	CUSTOMER ISSUE	-
DMS_08654	14881	N	N	N	1	CUSTOMER ISSUE	-
DMS_08655	14882	N	N	N	1	CUSTOMER ISSUE	-
DMS_08656	14883	N	N	N	1	CUSTOMER ISSUE	-
DMS_08657	14884	N	N	N	1	CUSTOMER ISSUE	-
DMS_08658	14885	N	N	N	1	CUSTOMER ISSUE	-
DMS_08659	14886	N	N	N	1	CUSTOMER ISSUE	-
DMS_08660	14887	N	N	N	1	CUSTOMER ISSUE	-
DMS_08661	14888	N	N	N	1	CUSTOMER ISSUE	-
DMS_08662	14889	N	N	N	1	CUSTOMER ISSUE	-
DMS_08663	14890	N	N	N	1	CUSTOMER ISSUE	-
DMS_08664	14891	N	N	N	1	CUSTOMER ISSUE	-
DMS_08665	14892	N	N	N	1	CUSTOMER ISSUE	-
DMS_08666	14893	N	N	N	1	CUSTOMER ISSUE	-
DMS_08667	14894	N	N	N	1	CUSTOMER ISSUE	-
DMS_08668	14895	N	N	N	1	CUSTOMER ISSUE	-
DMS_08669	14896	N	N	N	1	CUSTOMER ISSUE	-
DMS_08670	14897	N	N	N	1	CUSTOMER ISSUE	-
DMS_08671	14898	N	N	N	1	CUSTOMER ISSUE	-
DMS_08672	14899	N	N	N	1	CUSTOMER ISSUE	-
DMS_08673	14900	N	N	N	1	CUSTOMER ISSUE	-
DMS_08674	14901	N	N	N	1	CUSTOMER ISSUE	-
DMS_08675	14902	N	N	N	1	CUSTOMER ISSUE	-
DMS_08676	14903	N	N	N	1	CUSTOMER ISSUE	-
DMS_08677	14904	N	N	N	1	CUSTOMER ISSUE	-
DMS_08678	14905	N	N	N	1	CUSTOMER ISSUE	-
DMS_08679	14906	N	N	N	1	CUSTOMER ISSUE	-
DMS_08680	14907	N	N	N	1	CUSTOMER ISSUE	-
DMS_08681	14908	N	N	N	1	CUSTOMER ISSUE	-
DMS_08682	14909	N	N	N	1	CUSTOMER ISSUE	-
DMS_08683	14910	N	N	N	1	CUSTOMER ISSUE	-
DMS_08684	14911	N	N	N	1	CUSTOMER ISSUE	-
DMS_08685	14912	N	N	N	1	CUSTOMER ISSUE	-
DMS_08686	14913	N	N	N	1	CUSTOMER ISSUE	-
DMS_08687	14914	N	N	N	1	CUSTOMER ISSUE	-
DMS_08688	14915	N	N	N	1	CUSTOMER ISSUE	-
DMS_08689	14916	N	N	N	1	CUSTOMER ISSUE	-
DMS_08690	14917	N	N	N	1	CUSTOMER ISSUE	-
DMS_08691	14918	N	N	N	1	CUSTOMER ISSUE	-
DMS_08692	14919	N	N	N	1	CUSTOMER ISSUE	-
DMS_08693	14920	N	N	N	1	CUSTOMER ISSUE	-
DMS_08694	14921	N	N	N	1	CUSTOMER ISSUE	-
DMS_08695	14922	N	N	N	1	CUSTOMER ISSUE	-
DMS_08696	14923	N	N	N	1	CUSTOMER ISSUE	-
DMS_08697	14924	N	N	N	1	CUSTOMER ISSUE	-
DMS_08698	14925	N	N	N	1	CUSTOMER ISSUE	-
DMS_08699	14926	N	N	N	1	CUSTOMER ISSUE	-
DMS_08700	14927	N	N	N	1	CUSTOMER ISSUE	-
DMS_08701	14928	N	N	N	2	CUSTOMER ISSUE	-
DMS_08702	14929	N	N	N	1	CUSTOMER ISSUE	-
DMS_08703	14930	N	N	N	1	CUSTOMER ISSUE	-
DMS_08704	14931	N	N	N	1	CUSTOMER ISSUE	-
DMS_08705	14932	N	N	N	1	CUSTOMER ISSUE	-
DMS_08706	14933	N	N	N	1	CUSTOMER ISSUE	-
DMS_08707	14934	N	N	N	1	CUSTOMER ISSUE	-
DMS_08708	14935	N	N	N	1	CUSTOMER ISSUE	-
DMS_08709	14936	N	N	N	1	CUSTOMER ISSUE	-

DMS_08710	14937	N	N	N	1	CUSTOMER ISSUE	-
DMS_08711	14938	N	N	N	1	CUSTOMER ISSUE	-
DMS_08712	14939	N	N	N	1	CUSTOMER ISSUE	-
DMS_08713	14940	N	N	N	1	CUSTOMER ISSUE	-
DMS_08714	14941	N	N	N	1	CUSTOMER ISSUE	-
DMS_08715	14942	N	N	N	1	CUSTOMER ISSUE	-
DMS_08716	14943	N	N	N	1	CUSTOMER ISSUE	-
DMS_08717	14944	N	N	N	1	CUSTOMER ISSUE	-
DMS_08718	14945	N	N	N	1	CUSTOMER ISSUE	-
DMS_08719	14946	N	N	N	1	CUSTOMER ISSUE	-
DMS_08720	14947	N	N	N	1	CUSTOMER ISSUE	-
DMS_08721	14948	N	N	N	1	CUSTOMER ISSUE	-
DMS_08722	14949	N	N	N	1	CUSTOMER ISSUE	-
DMS_08723	14950	N	N	N	1	CUSTOMER ISSUE	-
DMS_08724	14951	N	N	N	1	CUSTOMER ISSUE	-
DMS_08725	14952	N	N	N	1	CUSTOMER ISSUE	-
DMS_08726	14953	N	N	N	1	CUSTOMER ISSUE	-
DMS_08727	14954	N	N	N	1	CUSTOMER ISSUE	-
DMS_08728	14955	N	N	N	1	CUSTOMER ISSUE	-
DMS_08729	14956	N	N	N	1	CUSTOMER ISSUE	-
DMS_08730	14957	N	N	N	1	CUSTOMER ISSUE	-
DMS_08731	14958	N	N	N	1	CUSTOMER ISSUE	-
DMS_08732	14959	N	N	N	1	CUSTOMER ISSUE	-
DMS_08733	14960	N	N	N	1	CUSTOMER ISSUE	-
DMS_08734	14961	N	N	N	1	CUSTOMER ISSUE	-
DMS_08735	14962	N	N	N	1	CUSTOMER ISSUE	-
DMS_08736	14963	N	N	N	1	CUSTOMER ISSUE	-
DMS_08737	14964	N	N	N	1	CUSTOMER ISSUE	-
DMS_08738	14965	N	N	N	1	CUSTOMER ISSUE	-
DMS_08739	14966	N	N	N	1	CUSTOMER ISSUE	-
DMS_08740	14967	N	N	N	1	CUSTOMER ISSUE	-
DMS_08741	14968	N	N	N	1	CUSTOMER ISSUE	-
DMS_08742	14969	N	N	N	1	CUSTOMER ISSUE	-
DMS_08743	14970	N	N	N	1	CUSTOMER ISSUE	-
DMS_08744	14971	N	N	N	1	CUSTOMER ISSUE	-
DMS_08745	14972	N	N	N	1	CUSTOMER ISSUE	-
DMS_08746	14973	N	N	N	1	CUSTOMER ISSUE	-
DMS_08747	14974	N	N	N	1	CUSTOMER ISSUE	-
DMS_08748	14975	N	N	N	1	CUSTOMER ISSUE	-
DMS_08749	14976	N	N	N	1	CUSTOMER ISSUE	-
DMS_08750	14977	N	N	N	1	CUSTOMER ISSUE	-
DMS_08751	14978	N	N	N	1	CUSTOMER ISSUE	-
DMS_08752	14979	N	N	N	1	CUSTOMER ISSUE	-
DMS_08753	14980	N	N	N	1	CUSTOMER ISSUE	-
DMS_08754	14981	N	N	N	1	CUSTOMER ISSUE	-
DMS_08755	14982	N	N	N	1	CUSTOMER ISSUE	-
DMS_08756	14983	N	N	N	1	CUSTOMER ISSUE	-
DMS_08757	14984	N	N	N	1	CUSTOMER ISSUE	-
DMS_08758	14985	N	N	N	1	CUSTOMER ISSUE	-
DMS_08759	14986	N	N	N	1	CUSTOMER ISSUE	-
DMS_08760	14987	N	N	N	1	CUSTOMER ISSUE	-
DMS_08761	14988	N	N	N	1	CUSTOMER ISSUE	-
DMS_08762	14989	N	N	N	1	CUSTOMER ISSUE	-
DMS_08763	14990	N	N	N	1	CUSTOMER ISSUE	-
DMS_08764	14991	N	N	N	1	CUSTOMER ISSUE	-
DMS_08765	14992	N	N	N	1	CUSTOMER ISSUE	-
DMS_08766	14993	N	N	N	1	CUSTOMER ISSUE	-
DMS_08767	14994	N	N	N	1	CUSTOMER ISSUE	-
DMS_08768	14995	N	N	N	1	CUSTOMER ISSUE	-
DMS_08769	14996	N	N	N	1	CUSTOMER ISSUE	-
DMS_08770	14997	N	N	N	1	CUSTOMER ISSUE	-
DMS_08771	14998	N	N	N	1	CUSTOMER ISSUE	-
DMS_08772	14999	N	N	N	1	CUSTOMER ISSUE	-
DMS_08773	15000	N	N	N	1	CUSTOMER ISSUE	-
DMS_08774	15001	N	N	N	1	CUSTOMER ISSUE	-
DMS_08775	15002	N	N	N	1	CUSTOMER ISSUE	-
DMS_08776	15003	N	N	N	1	CUSTOMER ISSUE	-
DMS_08777	15004	N	N	N	1	CUSTOMER ISSUE	-
DMS_08778	15005	N	N	N	1	CUSTOMER ISSUE	-
DMS_08779	15006	N	N	N	1	CUSTOMER ISSUE	-
DMS_08780	15007	N	N	N	1	CUSTOMER ISSUE	-
DMS_08781	15008	N	N	N	1	CUSTOMER ISSUE	-
DMS_08782	15009	N	N	N	1	CUSTOMER ISSUE	-
DMS_08783	15010	N	N	N	1	CUSTOMER ISSUE	-
DMS_08784	15011	N	N	N	1	CUSTOMER ISSUE	-
DMS_08785	15012	N	N	N	1	CUSTOMER ISSUE	-
DMS_08786	15013	N	N	N	1	CUSTOMER ISSUE	-
DMS_08787	15014	N	N	N	1	CUSTOMER ISSUE	-
DMS_08788	15015	N	N	N	1	CUSTOMER ISSUE	-
DMS_08789	15016	N	N	N	1	CUSTOMER ISSUE	-

DMS_08790	15017	N	N	N	1	CUSTOMER ISSUE	-
DMS_08791	15018	N	N	N	1	CUSTOMER ISSUE	-
DMS_08792	15019	N	N	N	1	CUSTOMER ISSUE	-
DMS_08793	15020	N	N	N	1	CUSTOMER ISSUE	-
DMS_08794	15021	N	N	N	1	CUSTOMER ISSUE	-
DMS_08795	15022	N	N	N	1	CUSTOMER ISSUE	-
DMS_08796	15023	N	N	N	1	CUSTOMER ISSUE	-
DMS_08797	15024	N	N	N	1	CUSTOMER ISSUE	-
DMS_08798	15025	N	N	N	1	CUSTOMER ISSUE	-
DMS_08799	15026	N	N	N	1	CUSTOMER ISSUE	-
DMS_08800	15027	N	N	N	1	CUSTOMER ISSUE	-
DMS_08801	15028	N	N	N	1	CUSTOMER ISSUE	-
DMS_08802	15029	N	N	N	1	CUSTOMER ISSUE	-
DMS_08803	15030	N	N	N	1	CUSTOMER ISSUE	-
DMS_08804	15031	N	N	N	1	CUSTOMER ISSUE	-
DMS_08805	15032	N	N	N	1	CUSTOMER ISSUE	-
DMS_08806	15033	N	N	N	1	CUSTOMER ISSUE	-
DMS_08807	15034	N	N	N	1	CUSTOMER ISSUE	-
DMS_08808	15035	N	N	N	1	CUSTOMER ISSUE	-
DMS_08809	15036	N	N	N	1	CUSTOMER ISSUE	-
DMS_08810	15037	N	N	N	1	CUSTOMER ISSUE	-
DMS_08811	15038	N	N	N	1	CUSTOMER ISSUE	-
DMS_08812	15039	N	N	N	1	CUSTOMER ISSUE	-
DMS_08813	15040	N	N	N	1	CUSTOMER ISSUE	-
DMS_08814	15041	N	N	N	1	CUSTOMER ISSUE	-
DMS_08815	15042	N	N	N	1	CUSTOMER ISSUE	-
DMS_08816	15043	N	N	N	1	CUSTOMER ISSUE	-
DMS_08817	15044	N	N	N	1	CUSTOMER ISSUE	-
DMS_08818	15045	N	N	N	1	CUSTOMER ISSUE	-
DMS_08819	15046	N	N	N	1	CUSTOMER ISSUE	-
DMS_08820	15047	N	N	N	1	CUSTOMER ISSUE	-
DMS_08821	15048	N	N	N	1	CUSTOMER ISSUE	-
DMS_08822	15049	N	N	N	1	CUSTOMER ISSUE	-
DMS_08823	15050	N	N	N	1	CUSTOMER ISSUE	-
DMS_08824	15051	N	N	N	1	CUSTOMER ISSUE	-
DMS_08825	15052	N	N	N	1	CUSTOMER ISSUE	-
DMS_08826	15053	N	N	N	1	CUSTOMER ISSUE	-
DMS_08827	15054	N	N	N	1	CUSTOMER ISSUE	-
DMS_08828	15055	N	N	N	1	CUSTOMER ISSUE	-
DMS_08830	15056	N	N	N	1	CUSTOMER ISSUE	-
DMS_08831	15057	N	N	N	1	CUSTOMER ISSUE	-
DMS_08832	15058	N	N	N	1	CUSTOMER ISSUE	-
DMS_08833	15059	N	N	N	1	CUSTOMER ISSUE	-
DMS_08834	15060	N	N	N	1	CUSTOMER ISSUE	-
DMS_08835	15061	N	N	N	1	CUSTOMER ISSUE	-
DMS_08836	15062	N	N	N	1	CUSTOMER ISSUE	-
DMS_08837	15063	N	N	N	1	CUSTOMER ISSUE	-
DMS_08838	15064	N	N	N	1	CUSTOMER ISSUE	-
DMS_08839	15065	N	N	N	1	CUSTOMER ISSUE	-
DMS_08840	15066	N	N	N	1	CUSTOMER ISSUE	-
DMS_08841	15067	N	N	N	1	CUSTOMER ISSUE	-
DMS_08842	15068	N	N	N	1	CUSTOMER ISSUE	-
DMS_08843	15069	N	N	N	1	CUSTOMER ISSUE	-
DMS_08844	15070	N	N	N	1	CUSTOMER ISSUE	-
DMS_08845	15071	N	N	N	1	CUSTOMER ISSUE	-
DMS_08846	15072	N	N	N	1	CUSTOMER ISSUE	-
DMS_08847	15073	N	N	N	1	CUSTOMER ISSUE	-
DMS_08848	15074	N	N	N	1	CUSTOMER ISSUE	-
DMS_08849	15075	N	N	N	1	CUSTOMER ISSUE	-
DMS_08850	15076	N	N	N	1	CUSTOMER ISSUE	-
DMS_08851	15077	N	N	N	1	CUSTOMER ISSUE	-
DMS_08852	15078	N	N	N	1	CUSTOMER ISSUE	-
DMS_08853	15079	N	N	N	1	CUSTOMER ISSUE	-
DMS_08854	15080	N	N	N	1	CUSTOMER ISSUE	-
DMS_08855	15081	N	N	N	1	CUSTOMER ISSUE	-
DMS_08856	15082	N	N	N	1	CUSTOMER ISSUE	-
DMS_08857	15083	N	N	N	1	CUSTOMER ISSUE	-
DMS_08858	15084	N	N	N	1	CUSTOMER ISSUE	-
DMS_08859	15085	N	N	N	1	CUSTOMER ISSUE	-
DMS_08860	15086	N	N	N	1	CUSTOMER ISSUE	-
DMS_08861	15087	N	N	N	1	CUSTOMER ISSUE	-
DMS_08862	15088	N	N	N	1	CUSTOMER ISSUE	-
DMS_08863	15089	N	N	N	1	CUSTOMER ISSUE	-
DMS_08864	15090	N	N	N	1	CUSTOMER ISSUE	-
DMS_08865	15091	N	N	N	1	CUSTOMER ISSUE	-
DMS_08866	15092	N	N	N	1	CUSTOMER ISSUE	-
DMS_08867	15093	N	N	N	1	CUSTOMER ISSUE	-
DMS_08868	15094	N	N	N	1	CUSTOMER ISSUE	-
DMS_08869	15095	N	N	N	1	CUSTOMER ISSUE	-
DMS_08870	15096	N	N	N	1	CUSTOMER ISSUE	-

DMS_08871	15097	N	N	N	1	CUSTOMER ISSUE	-
DMS_08872	15098	N	N	N	1	CUSTOMER ISSUE	-
DMS_08873	15099	N	N	N	1	CUSTOMER ISSUE	-
DMS_08874	15100	N	N	N	1	CUSTOMER ISSUE	-
DMS_08875	15101	N	N	N	1	CUSTOMER ISSUE	-
DMS_08876	15102	N	N	N	1	CUSTOMER ISSUE	-
DMS_08877	15103	N	N	N	1	CUSTOMER ISSUE	-
DMS_08878	15104	N	N	N	1	CUSTOMER ISSUE	-
DMS_08879	15105	N	N	N	1	CUSTOMER ISSUE	-
DMS_08880	15106	N	N	N	1	CUSTOMER ISSUE	-
DMS_08881	15107	N	N	N	1	CUSTOMER ISSUE	-
DMS_08882	15108	N	N	N	1	CUSTOMER ISSUE	-
DMS_08883	15109	N	N	N	1	CUSTOMER ISSUE	-
DMS_08884	15110	N	N	N	1	CUSTOMER ISSUE	-
DMS_08885	15111	N	N	N	1	CUSTOMER ISSUE	-
DMS_08886	15112	N	N	N	1	CUSTOMER ISSUE	-
DMS_08887	15113	N	N	N	1	CUSTOMER ISSUE	-
DMS_08888	15114	N	N	N	1	CUSTOMER ISSUE	-
DMS_08889	15115	N	N	N	1	CUSTOMER ISSUE	-
DMS_08890	15116	N	N	N	1	CUSTOMER ISSUE	-
DMS_08891	15117	N	N	N	1	CUSTOMER ISSUE	-
DMS_08892	15118	N	N	N	1	CUSTOMER ISSUE	-
DMS_08893	15119	N	N	N	1	CUSTOMER ISSUE	-
DMS_08894	15120	N	N	N	1	CUSTOMER ISSUE	-
DMS_08895	15121	N	N	N	1	CUSTOMER ISSUE	-
DMS_08896	15122	N	N	N	1	CUSTOMER ISSUE	-
DMS_08897	15123	N	N	N	1	CUSTOMER ISSUE	-
DMS_08898	15124	N	N	N	2	CUSTOMER ISSUE	-
DMS_08899	15125	N	N	N	1	CUSTOMER ISSUE	-
DMS_08900	15126	N	N	N	1	CUSTOMER ISSUE	-
DMS_08901	15127	N	N	N	1	CUSTOMER ISSUE	-
DMS_08902	15128	N	N	N	1	CUSTOMER ISSUE	-
DMS_08903	15129	N	N	N	1	CUSTOMER ISSUE	-
DMS_08904	15130	N	N	N	1	CUSTOMER ISSUE	-
DMS_08905	15131	N	N	N	1	CUSTOMER ISSUE	-
DMS_08906	15132	N	N	N	1	CUSTOMER ISSUE	-
DMS_08907	15133	N	N	N	1	CUSTOMER ISSUE	-
DMS_08908	15134	N	N	N	1	CUSTOMER ISSUE	-
DMS_08909	15135	N	N	N	1	CUSTOMER ISSUE	-
DMS_08910	15136	N	N	N	1	CUSTOMER ISSUE	-
DMS_08911	15137	N	N	N	1	CUSTOMER ISSUE	-
DMS_08912	15138	N	N	N	1	CUSTOMER ISSUE	-
DMS_08913	15139	N	N	N	1	CUSTOMER ISSUE	-
DMS_08914	15140	N	N	N	1	CUSTOMER ISSUE	-
DMS_08915	15141	N	N	N	1	CUSTOMER ISSUE	-
DMS_08916	15142	N	N	N	1	CUSTOMER ISSUE	-
DMS_08917	15143	N	N	N	1	CUSTOMER ISSUE	-
DMS_08918	15144	N	N	N	1	CUSTOMER ISSUE	-
DMS_08919	15145	N	N	N	1	CUSTOMER ISSUE	-
DMS_08920	15146	N	N	N	1	CUSTOMER ISSUE	-
DMS_08921	15147	N	N	N	1	CUSTOMER ISSUE	-
DMS_08922	15148	N	N	N	1	CUSTOMER ISSUE	-
DMS_08923	15149	N	N	N	1	CUSTOMER ISSUE	-
DMS_08924	15150	N	N	N	1	CUSTOMER ISSUE	-
DMS_08925	15151	N	N	N	1	CUSTOMER ISSUE	-
DMS_08926	15152	N	N	N	1	CUSTOMER ISSUE	-
DMS_08927	15153	N	N	N	1	CUSTOMER ISSUE	-
DMS_08928	15154	N	N	N	1	CUSTOMER ISSUE	-
DMS_08929	15155	N	N	N	1	CUSTOMER ISSUE	-
DMS_08930	15156	N	N	N	1	CUSTOMER ISSUE	-
DMS_08931	15157	N	N	N	1	CUSTOMER ISSUE	-
DMS_08932	15158	N	N	N	1	CUSTOMER ISSUE	-
DMS_08933	15159	N	N	N	1	CUSTOMER ISSUE	-
DMS_08934	15160	N	N	N	1	CUSTOMER ISSUE	-
DMS_08935	15161	N	N	N	1	CUSTOMER ISSUE	-
DMS_08936	15162	N	N	N	1	CUSTOMER ISSUE	-
DMS_08937	15163	N	N	N	1	CUSTOMER ISSUE	-
DMS_08938	15164	N	N	N	1	CUSTOMER ISSUE	-
DMS_08939	15165	N	N	N	2	CUSTOMER ISSUE	-
DMS_08940	15166	N	N	N	1	CUSTOMER ISSUE	-
DMS_08941	15167	N	N	N	1	CUSTOMER ISSUE	-
DMS_08942	15168	N	N	N	1	CUSTOMER ISSUE	-
DMS_08943	15169	N	N	N	1	CUSTOMER ISSUE	-
DMS_08944	15170	N	N	N	1	CUSTOMER ISSUE	-
DMS_08945	15171	N	N	N	1	CUSTOMER ISSUE	-
DMS_08946	15172	N	N	N	1	CUSTOMER ISSUE	-
DMS_08947	15173	N	N	N	1	CUSTOMER ISSUE	-
DMS_08948	15174	N	N	N	1	CUSTOMER ISSUE	-
DMS_08949	15175	N	N	N	1	CUSTOMER ISSUE	-
DMS_08950	15176	N	N	N	1	CUSTOMER ISSUE	-

DMS_08951	15177	N	N	N	1	CUSTOMER ISSUE	-
DMS_08952	15178	N	N	N	1	CUSTOMER ISSUE	-
DMS_08953	15179	N	N	N	1	CUSTOMER ISSUE	-
DMS_08954	15180	N	N	N	1	CUSTOMER ISSUE	-
DMS_08955	15181	N	N	N	1	CUSTOMER ISSUE	-
DMS_08956	15182	N	N	N	1	CUSTOMER ISSUE	-
DMS_08957	15183	N	N	N	1	CUSTOMER ISSUE	-
DMS_08958	15184	N	N	N	1	CUSTOMER ISSUE	-
DMS_08959	15185	N	N	N	1	CUSTOMER ISSUE	-
DMS_08960	15186	N	N	N	1	CUSTOMER ISSUE	-
DMS_08961	15187	N	N	N	1	CUSTOMER ISSUE	-
DMS_08962	15188	N	N	N	1	CUSTOMER ISSUE	-
DMS_08963	15189	N	N	N	1	CUSTOMER ISSUE	-
DMS_08964	15190	N	N	N	1	CUSTOMER ISSUE	-
DMS_08965	15191	N	N	N	1	CUSTOMER ISSUE	-
DMS_08966	15192	N	N	N	1	CUSTOMER ISSUE	-
DMS_08967	15193	N	N	N	1	CUSTOMER ISSUE	-
DMS_08968	15194	N	N	N	1	CUSTOMER ISSUE	-
DMS_08969	15195	N	N	N	1	CUSTOMER ISSUE	-
DMS_08970	15196	N	N	N	1	CUSTOMER ISSUE	-
DMS_08971	15197	N	N	N	1	CUSTOMER ISSUE	-
DMS_08972	15198	N	N	N	1	CUSTOMER ISSUE	-
DMS_08973	15199	N	N	N	1	CUSTOMER ISSUE	-
DMS_08974	15200	N	N	N	1	CUSTOMER ISSUE	-
DMS_08975	15201	N	N	N	1	CUSTOMER ISSUE	-
DMS_08976	15202	N	N	N	1	CUSTOMER ISSUE	-
DMS_08977	15203	N	N	N	1	CUSTOMER ISSUE	-
DMS_08978	15204	N	N	N	1	CUSTOMER ISSUE	-
DMS_08979	15205	N	N	N	1	CUSTOMER ISSUE	-
DMS_08980	15206	N	N	N	1	CUSTOMER ISSUE	-
DMS_08981	15207	N	N	N	1	CUSTOMER ISSUE	-
DMS_08982	15208	N	N	N	1	CUSTOMER ISSUE	-
DMS_08983	15209	N	N	N	1	CUSTOMER ISSUE	-
DMS_08984	15210	N	N	N	1	CUSTOMER ISSUE	-
DMS_08985	15211	N	N	N	1	CUSTOMER ISSUE	-
DMS_08986	15212	N	N	N	1	CUSTOMER ISSUE	-
DMS_08987	15213	N	N	N	1	CUSTOMER ISSUE	-
DMS_08988	15214	N	N	N	1	CUSTOMER ISSUE	-
DMS_08989	15215	N	N	N	1	CUSTOMER ISSUE	-
DMS_08990	15216	N	N	N	1	CUSTOMER ISSUE	-
DMS_08991	15217	N	N	N	1	CUSTOMER ISSUE	-
DMS_08992	15218	N	N	N	1	CUSTOMER ISSUE	-
DMS_08993	15219	N	N	N	1	CUSTOMER ISSUE	-
DMS_08994	15220	N	N	N	1	CUSTOMER ISSUE	-
DMS_08995	15221	N	N	N	1	CUSTOMER ISSUE	-
DMS_08996	15222	N	N	N	1	CUSTOMER ISSUE	-
DMS_08997	15223	N	N	N	1	CUSTOMER ISSUE	-
DMS_08998	15224	N	N	N	2	CUSTOMER ISSUE	-
DMS_08999	15225	N	N	N	1	CUSTOMER ISSUE	-
DMS_09000	15226	N	N	N	1	CUSTOMER ISSUE	-
DMS_09001	15227	N	N	N	1	CUSTOMER ISSUE	-
DMS_09002	15228	N	N	N	1	CUSTOMER ISSUE	-
DMS_09003	15229	N	N	N	1	CUSTOMER ISSUE	-
DMS_09004	15230	N	N	N	1	CUSTOMER ISSUE	-
DMS_09005	15231	N	N	N	1	CUSTOMER ISSUE	-
DMS_09006	15232	N	N	N	1	CUSTOMER ISSUE	-
DMS_09007	15233	N	N	N	1	CUSTOMER ISSUE	-
DMS_09008	15234	N	N	N	1	CUSTOMER ISSUE	-
DMS_09009	15235	N	N	N	1	CUSTOMER ISSUE	-
DMS_09010	15236	N	N	N	1	CUSTOMER ISSUE	-
DMS_09011	15237	N	N	N	1	CUSTOMER ISSUE	-
DMS_09012	15238	N	N	N	1	CUSTOMER ISSUE	-
DMS_09013	15239	N	N	N	1	CUSTOMER ISSUE	-
DMS_09014	15240	N	N	N	2	CUSTOMER ISSUE	-
DMS_09015	15241	N	N	N	1	CUSTOMER ISSUE	-
DMS_09016	15242	N	N	N	1	CUSTOMER ISSUE	-
DMS_09017	15243	N	N	N	1	CUSTOMER ISSUE	-
DMS_09018	15244	N	N	N	1	CUSTOMER ISSUE	-
DMS_09019	15245	N	N	N	1	CUSTOMER ISSUE	-
DMS_09020	15246	N	N	N	1	CUSTOMER ISSUE	-
DMS_09021	15247	N	N	N	1	CUSTOMER ISSUE	-
DMS_09022	15248	N	N	N	1	CUSTOMER ISSUE	-
DMS_09023	15249	N	N	N	1	CUSTOMER ISSUE	-
DMS_09024	15250	N	N	N	1	CUSTOMER ISSUE	-
DMS_09025	15251	N	N	N	2	CUSTOMER ISSUE	-
DMS_09026	15252	N	N	N	1	CUSTOMER ISSUE	-
DMS_09027	15253	N	N	N	2	CUSTOMER ISSUE	-
DMS_09028	15254	N	N	N	1	CUSTOMER ISSUE	-
DMS_09029	15255	N	N	N	1	CUSTOMER ISSUE	-
DMS_09030	15256	N	N	N	1	CUSTOMER ISSUE	-

DMS_09031	15257	N	N	N	1	CUSTOMER ISSUE	-
DMS_09032	15258	N	N	N	1	CUSTOMER ISSUE	-
DMS_09033	15259	N	N	N	1	CUSTOMER ISSUE	-
DMS_09034	15260	N	N	N	1	CUSTOMER ISSUE	-
DMS_09035	15261	N	N	N	1	CUSTOMER ISSUE	-
DMS_09036	15262	N	N	N	1	CUSTOMER ISSUE	-
DMS_09037	15263	N	N	N	1	CUSTOMER ISSUE	-
DMS_09038	15264	N	N	N	1	CUSTOMER ISSUE	-
DMS_09039	15265	N	N	N	1	CUSTOMER ISSUE	-
DMS_09040	15266	N	N	N	1	CUSTOMER ISSUE	-
DMS_09041	15267	N	N	N	1	CUSTOMER ISSUE	-
DMS_09042	15268	N	N	N	1	CUSTOMER ISSUE	-
DMS_09043	15269	N	N	N	1	CUSTOMER ISSUE	-
DMS_09044	15270	N	N	N	1	CUSTOMER ISSUE	-
DMS_09045	15271	N	N	N	1	CUSTOMER ISSUE	-
DMS_09046	15272	N	N	N	1	CUSTOMER ISSUE	-
DMS_09047	15273	N	N	N	1	CUSTOMER ISSUE	-
DMS_09048	15274	N	N	N	1	CUSTOMER ISSUE	-
DMS_09049	15275	N	N	N	1	CUSTOMER ISSUE	-
DMS_09050	15276	N	N	N	1	CUSTOMER ISSUE	-
DMS_09051	15277	N	N	N	1	CUSTOMER ISSUE	-
DMS_09052	15278	N	N	N	1	CUSTOMER ISSUE	-
DMS_09053	15279	N	N	N	1	CUSTOMER ISSUE	-
DMS_09054	15280	N	N	N	1	CUSTOMER ISSUE	-
DMS_09055	15281	N	N	N	1	CUSTOMER ISSUE	-
DMS_09056	15282	N	N	N	2	CUSTOMER ISSUE	-
DMS_09057	15283	N	N	N	1	CUSTOMER ISSUE	-
DMS_09058	15284	N	N	N	1	CUSTOMER ISSUE	-
DMS_09059	15285	N	N	N	1	CUSTOMER ISSUE	-
DMS_09060	15286	N	N	N	1	CUSTOMER ISSUE	-
DMS_09061	15287	N	N	N	1	CUSTOMER ISSUE	-
DMS_09062	15288	N	N	N	1	CUSTOMER ISSUE	-
DMS_09063	15289	N	N	N	1	CUSTOMER ISSUE	-
DMS_09064	15290	N	N	N	1	CUSTOMER ISSUE	-
DMS_09065	15291	N	N	N	1	CUSTOMER ISSUE	-
DMS_09066	15292	N	N	N	1	CUSTOMER ISSUE	-
DMS_09067	15293	N	N	N	1	CUSTOMER ISSUE	-
DMS_09068	15294	N	N	N	1	CUSTOMER ISSUE	-
DMS_09069	15295	N	N	N	1	CUSTOMER ISSUE	-
DMS_09070	15296	N	N	N	1	CUSTOMER ISSUE	-
DMS_09071	15297	N	N	N	1	CUSTOMER ISSUE	-
DMS_09072	15298	N	N	N	1	CUSTOMER ISSUE	-
DMS_09073	15299	N	N	N	1	CUSTOMER ISSUE	-
DMS_09075	15300	N	N	N	1	CUSTOMER ISSUE	-
DMS_09076	15301	N	N	N	1	CUSTOMER ISSUE	-
DMS_09077	15302	N	N	N	1	CUSTOMER ISSUE	-
DMS_09078	15303	N	N	N	1	CUSTOMER ISSUE	-
DMS_09079	15304	N	N	N	1	CUSTOMER ISSUE	-
DMS_09080	15305	N	N	N	1	CUSTOMER ISSUE	-
DMS_09081	15306	N	N	N	1	CUSTOMER ISSUE	-
DMS_09082	15307	N	N	N	1	CUSTOMER ISSUE	-
DMS_09083	15308	N	N	N	1	CUSTOMER ISSUE	-
DMS_09084	15309	N	N	N	1	CUSTOMER ISSUE	-
DMS_09085	15310	N	N	N	1	CUSTOMER ISSUE	-
DMS_09086	15311	N	N	N	1	CUSTOMER ISSUE	-
DMS_09087	15312	N	N	N	1	CUSTOMER ISSUE	-
DMS_09088	15313	N	N	N	1	CUSTOMER ISSUE	-
DMS_09089	15314	N	N	N	2	CUSTOMER ISSUE	-
DMS_09090	15315	N	N	N	1	CUSTOMER ISSUE	-
DMS_09091	15316	N	N	N	1	CUSTOMER ISSUE	-
DMS_09092	15317	N	N	N	1	CUSTOMER ISSUE	-
DMS_09093	15318	N	N	N	1	CUSTOMER ISSUE	-
DMS_09094	15319	N	N	N	1	CUSTOMER ISSUE	-
DMS_09095	15320	N	N	N	1	CUSTOMER ISSUE	-
DMS_09096	15321	N	N	N	1	CUSTOMER ISSUE	-
DMS_09097	15322	N	N	N	1	CUSTOMER ISSUE	-
DMS_09098	15323	N	N	N	1	CUSTOMER ISSUE	-
DMS_09099	15324	N	N	N	1	CUSTOMER ISSUE	-
DMS_09100	15325	N	N	N	1	CUSTOMER ISSUE	-
DMS_09101	15326	N	N	N	1	CUSTOMER ISSUE	-
DMS_09102	15327	N	N	N	1	CUSTOMER ISSUE	-
DMS_09103	15328	N	N	N	1	CUSTOMER ISSUE	-
DMS_09104	15329	N	N	N	1	CUSTOMER ISSUE	-
DMS_09105	15330	N	N	N	1	CUSTOMER ISSUE	-
DMS_09106	15331	N	N	N	1	CUSTOMER ISSUE	-
DMS_09107	15332	N	N	N	1	CUSTOMER ISSUE	-
DMS_09108	15333	N	N	N	1	CUSTOMER ISSUE	-
DMS_09109	15334	N	N	N	1	CUSTOMER ISSUE	-
DMS_09110	15335	N	N	N	1	CUSTOMER ISSUE	-
DMS_09111	15336	N	N	N	1	CUSTOMER ISSUE	-

DMS_09112	15337	N	N	N	1	CUSTOMER ISSUE	-
DMS_09113	15338	N	N	N	1	CUSTOMER ISSUE	-
DMS_09114	15339	N	N	N	1	CUSTOMER ISSUE	-
DMS_09115	15340	N	N	N	1	CUSTOMER ISSUE	-
DMS_09116	15341	N	N	N	1	CUSTOMER ISSUE	-
DMS_09117	15342	N	N	N	1	CUSTOMER ISSUE	-
DMS_09118	15343	N	N	N	1	CUSTOMER ISSUE	-
DMS_09119	15344	N	N	N	1	CUSTOMER ISSUE	-
DMS_09120	15345	N	N	N	1	CUSTOMER ISSUE	-
DMS_09121	15346	N	N	N	1	CUSTOMER ISSUE	-
DMS_09122	15347	N	N	N	1	CUSTOMER ISSUE	-
DMS_09123	15348	N	N	N	1	CUSTOMER ISSUE	-
DMS_09124	15349	N	N	N	1	CUSTOMER ISSUE	-
DMS_09125	15350	N	N	N	1	CUSTOMER ISSUE	-
DMS_09126	15351	N	N	N	1	CUSTOMER ISSUE	-
DMS_09127	15352	N	N	N	1	CUSTOMER ISSUE	-
DMS_09128	15353	N	N	N	1	CUSTOMER ISSUE	-
DMS_09129	15354	N	N	N	1	CUSTOMER ISSUE	-
DMS_09130	15355	N	N	N	1	CUSTOMER ISSUE	-
DMS_09131	15356	N	N	N	1	CUSTOMER ISSUE	-
DMS_09132	15357	N	N	N	1	CUSTOMER ISSUE	-
DMS_09133	15358	N	N	N	1	CUSTOMER ISSUE	-
DMS_09134	15359	N	N	N	1	CUSTOMER ISSUE	-
DMS_09135	15360	N	N	N	1	CUSTOMER ISSUE	-
DMS_09136	15361	N	N	N	1	CUSTOMER ISSUE	-
DMS_09137	15362	N	N	N	1	CUSTOMER ISSUE	-
DMS_09138	15363	N	N	N	1	CUSTOMER ISSUE	-
DMS_09139	15364	N	N	N	1	CUSTOMER ISSUE	-
DMS_09140	15365	N	N	N	1	CUSTOMER ISSUE	-
DMS_09141	15366	N	N	N	1	CUSTOMER ISSUE	-
DMS_09142	15367	N	N	N	1	CUSTOMER ISSUE	-
DMS_09143	15368	N	N	N	1	CUSTOMER ISSUE	-
DMS_09144	15369	N	N	N	2	CUSTOMER ISSUE	-
DMS_09145	15370	N	N	N	2	CUSTOMER ISSUE	-
DMS_09146	15371	N	N	N	1	CUSTOMER ISSUE	-
DMS_09147	15372	N	N	N	1	CUSTOMER ISSUE	-
DMS_09148	15373	N	N	N	1	CUSTOMER ISSUE	-
DMS_09149	15374	N	N	N	2	CUSTOMER ISSUE	-
DMS_09150	15375	N	N	N	1	CUSTOMER ISSUE	-
DMS_09151	15376	N	N	N	1	CUSTOMER ISSUE	-
DMS_09152	15377	N	N	N	1	CUSTOMER ISSUE	-
DMS_09153	15378	N	N	N	1	CUSTOMER ISSUE	-
DMS_09154	15379	N	N	N	1	CUSTOMER ISSUE	-
DMS_09155	15380	N	N	N	1	CUSTOMER ISSUE	-
DMS_09156	15381	N	N	N	1	CUSTOMER ISSUE	-
DMS_09159	15382	N	N	N	1	CUSTOMER ISSUE	-
DMS_09160	15383	N	N	N	1	CUSTOMER ISSUE	-
DMS_09161	15384	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09162	15385	N	N	N	1	CUSTOMER ISSUE	-
DMS_09163	15386	N	N	N	1	CUSTOMER ISSUE	-
DMS_09164	15387	N	N	N	1	CUSTOMER ISSUE	-
DMS_09165	15388	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09166	15389	N	N	N	1	CUSTOMER ISSUE	-
DMS_09167	15390	N	N	N	1	CUSTOMER ISSUE	-
DMS_09168	15391	N	N	N	1	CUSTOMER ISSUE	-
DMS_09170	15392	N	N	N	1	CUSTOMER ISSUE	-
DMS_09171	15393	N	N	N	1	CUSTOMER ISSUE	-
DMS_09172	15394	N	N	N	1	CUSTOMER ISSUE	-
DMS_09173	15395	N	N	N	1	CUSTOMER ISSUE	-
DMS_09174	15396	N	N	N	1	CUSTOMER ISSUE	-
DMS_09175	15397	N	N	N	1	CUSTOMER ISSUE	-
DMS_09177	15398	N	N	N	1	CUSTOMER ISSUE	-
DMS_09178	15399	N	N	N	1	CUSTOMER ISSUE	-
DMS_09179	15400	N	N	N	1	CUSTOMER ISSUE	-
DMS_09180	15401	N	N	N	1	CUSTOMER ISSUE	-
DMS_09181	15402	N	N	N	1	CUSTOMER ISSUE	-
DMS_09182	15403	N	N	N	1	CUSTOMER ISSUE	-
DMS_09183	15404	N	N	N	1	CUSTOMER ISSUE	-
DMS_09184	15405	N	N	N	1	CUSTOMER ISSUE	-
DMS_09185	15406	N	N	N	1	CUSTOMER ISSUE	-
DMS_09186	15407	N	N	N	1	CUSTOMER ISSUE	-
DMS_09187	15408	N	N	N	1	CUSTOMER ISSUE	-
DMS_09188	15409	N	N	N	1	CUSTOMER ISSUE	-
DMS_09189	15410	N	N	N	1	CUSTOMER ISSUE	-
DMS_09190	15411	N	N	N	1	CUSTOMER ISSUE	-
DMS_09191	15412	N	N	N	1	CUSTOMER ISSUE	-
DMS_09192	15413	N	N	N	1	CUSTOMER ISSUE	-
DMS_09193	15414	N	N	N	1	CUSTOMER ISSUE	-
DMS_09194	15415	N	N	Y	1	TX - REPLACE	2500
DMS_09195	15416	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_09196	15417	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09197	15418	N	N	N	1	CUSTOMER ISSUE	-
DMS_09198	15419	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09200	15420	N	N	N	1	CUSTOMER ISSUE	-
DMS_09201	15421	N	N	N	2	CUSTOMER ISSUE	-
DMS_09204	15422	N	N	N	1	CUSTOMER ISSUE	-
DMS_09205	15423	N	N	N	1	CUSTOMER ISSUE	-
DMS_09206	15424	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_09207	15425	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09208	15426	N	N	N	2	CUSTOMER ISSUE	-
DMS_09211	15427	N	N	N	1	CUSTOMER ISSUE	-
DMS_09212	15428	N	N	N	1	CUSTOMER ISSUE	-
DMS_09213	15429	N	N	N	1	CUSTOMER ISSUE	-
DMS_09214	15430	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09215	15431	N	N	N	2	CUSTOMER ISSUE	-
DMS_09216	15432	N	N	N	1	CUSTOMER ISSUE	-
DMS_09217	15433	N	N	N	1	CUSTOMER ISSUE	-
DMS_09218	15434	N	N	N	1	CUSTOMER ISSUE	-
DMS_09219	15435	N	N	N	1	CUSTOMER ISSUE	-
DMS_09220	15436	N	N	N	1	CUSTOMER ISSUE	-
DMS_09221	15437	N	N	N	1	CUSTOMER ISSUE	-
DMS_09222	15438	N	N	N	1	CUSTOMER ISSUE	-
DMS_09223	15439	N	N	N	1	CUSTOMER ISSUE	-
DMS_09224	15440	N	N	N	1	CUSTOMER ISSUE	-
DMS_09225	15441	N	N	N	1	CUSTOMER ISSUE	-
DMS_09226	15442	N	N	N	1	CUSTOMER ISSUE	-
DMS_09232	15443	N	N	N	1	CUSTOMER ISSUE	-
DMS_09233	15444	N	N	N	1	CUSTOMER ISSUE	-
DMS_09234	15445	N	N	N	1	CUSTOMER ISSUE	-
DMS_09235	15446	N	N	N	1	CUSTOMER ISSUE	-
DMS_09236	15447	N	N	N	1	CUSTOMER ISSUE	-
DMS_09237	15448	N	N	N	1	CUSTOMER ISSUE	-
DMS_09238	15449	N	N	N	1	CUSTOMER ISSUE	-
DMS_09239	15450	N	N	N	1	CUSTOMER ISSUE	-
DMS_09240	15451	N	N	N	1	CUSTOMER ISSUE	-
DMS_09243	15452	N	N	N	1	CUSTOMER ISSUE	-
DMS_09244	15453	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09245	15454	N	N	N	1	CUSTOMER ISSUE	-
DMS_09246	15455	N	N	N	1	CUSTOMER ISSUE	-
DMS_09247	15456	N	N	N	1	CUSTOMER ISSUE	-
DMS_09248	15457	N	N	N	1	CUSTOMER ISSUE	-
DMS_09249	15458	N	N	N	1	CUSTOMER ISSUE	-
DMS_09250	15459	N	N	N	1	CUSTOMER ISSUE	-
DMS_09251	15460	N	N	N	1	CUSTOMER ISSUE	-
DMS_09252	15461	N	N	N	1	CUSTOMER ISSUE	-
DMS_09253	15462	N	N	N	1	CUSTOMER ISSUE	-
DMS_09254	15463	N	N	N	1	CUSTOMER ISSUE	-
DMS_09255	15464	N	N	N	1	CUSTOMER ISSUE	-
DMS_09256	15465	N	N	N	1	CUSTOMER ISSUE	-
DMS_09257	15466	N	N	N	1	CUSTOMER ISSUE	-
DMS_09258	15467	N	N	N	1	CUSTOMER ISSUE	-
DMS_09259	15468	N	N	N	1	CUSTOMER ISSUE	-
DMS_09260	15469	N	N	N	1	CUSTOMER ISSUE	-
DMS_09261	15470	N	N	N	1	CUSTOMER ISSUE	-
DMS_09262	15471	N	N	N	1	CUSTOMER ISSUE	-
DMS_09263	15472	N	N	N	1	CUSTOMER ISSUE	-
DMS_09264	15473	N	N	N	1	CUSTOMER ISSUE	-
DMS_09265	15474	N	N	N	1	CUSTOMER ISSUE	-
DMS_09266	15475	N	N	N	1	CUSTOMER ISSUE	-
DMS_09267	15476	N	N	N	1	CUSTOMER ISSUE	-
DMS_09268	15477	N	N	N	1	CUSTOMER ISSUE	-
DMS_09269	15478	N	N	N	1	CUSTOMER ISSUE	-
DMS_09270	15479	N	N	N	1	CUSTOMER ISSUE	-
DMS_09271	15480	N	N	N	1	CUSTOMER ISSUE	-
DMS_09272	15481	N	N	N	1	CUSTOMER ISSUE	-
DMS_09273	15482	N	N	N	1	CUSTOMER ISSUE	-
DMS_09274	15483	N	N	N	1	CUSTOMER ISSUE	-
DMS_09275	15484	N	N	N	1	CUSTOMER ISSUE	-
DMS_09276	15485	N	N	N	1	CUSTOMER ISSUE	-
DMS_09277	15486	N	N	N	1	CUSTOMER ISSUE	-
DMS_09278	15487	N	N	N	2	CUSTOMER ISSUE	-
DMS_09279	15488	N	N	N	1	CUSTOMER ISSUE	-
DMS_09280	15489	N	N	N	1	CUSTOMER ISSUE	-
DMS_09281	15490	N	N	N	1	CUSTOMER ISSUE	-
DMS_09282	15491	N	N	N	1	CUSTOMER ISSUE	-
DMS_09283	15492	N	N	N	1	CUSTOMER ISSUE	-
DMS_09284	15493	N	N	N	1	CUSTOMER ISSUE	-
DMS_09285	15494	N	N	N	1	CUSTOMER ISSUE	-
DMS_09286	15495	N	N	N	1	CUSTOMER ISSUE	-
DMS_09287	15496	N	N	N	1	CUSTOMER ISSUE	-

DMS_09288	15497	N	N	N	1	CUSTOMER ISSUE	-
DMS_09289	15498	N	N	N	1	CUSTOMER ISSUE	-
DMS_09290	15499	N	N	N	1	CUSTOMER ISSUE	-
DMS_09291	15500	N	N	N	1	CUSTOMER ISSUE	-
DMS_09292	15501	N	N	N	1	CUSTOMER ISSUE	-
DMS_09293	15502	N	N	N	1	CUSTOMER ISSUE	-
DMS_09294	15503	N	N	N	1	CUSTOMER ISSUE	-
DMS_09295	15504	N	N	N	1	CUSTOMER ISSUE	-
DMS_09296	15505	N	N	N	1	CUSTOMER ISSUE	-
DMS_09297	15506	N	N	N	1	CUSTOMER ISSUE	-
DMS_09298	15507	N	N	N	1	CUSTOMER ISSUE	-
DMS_09299	15508	N	N	N	1	CUSTOMER ISSUE	-
DMS_09300	15509	N	N	N	1	CUSTOMER ISSUE	-
DMS_09301	15510	N	N	N	1	CUSTOMER ISSUE	-
DMS_09302	15511	N	N	N	1	CUSTOMER ISSUE	-
DMS_09303	15512	N	N	N	1	CUSTOMER ISSUE	-
DMS_09304	15513	N	N	N	1	CUSTOMER ISSUE	-
DMS_09305	15514	N	N	N	1	CUSTOMER ISSUE	-
DMS_09306	15515	N	N	N	1	CUSTOMER ISSUE	-
DMS_09307	15516	N	N	N	1	CUSTOMER ISSUE	-
DMS_09308	15517	N	N	N	1	CUSTOMER ISSUE	-
DMS_09309	15518	N	N	N	1	CUSTOMER ISSUE	-
DMS_09310	15519	N	N	N	1	CUSTOMER ISSUE	-
DMS_09311	15520	N	N	N	1	CUSTOMER ISSUE	-
DMS_09312	15521	N	N	N	1	CUSTOMER ISSUE	-
DMS_09313	15522	N	N	N	1	CUSTOMER ISSUE	-
DMS_09314	15523	N	N	N	1	CUSTOMER ISSUE	-
DMS_09315	15524	N	N	N	1	CUSTOMER ISSUE	-
DMS_09316	15525	N	N	N	1	CUSTOMER ISSUE	-
DMS_09318	15526	N	N	N	1	CUSTOMER ISSUE	-
DMS_09319	15527	N	N	N	1	CUSTOMER ISSUE	-
DMS_09320	15528	N	N	N	1	CUSTOMER ISSUE	-
DMS_09321	15529	N	N	N	1	CUSTOMER ISSUE	-
DMS_09322	15530	N	N	N	1	CUSTOMER ISSUE	-
DMS_09323	15531	N	N	N	1	CUSTOMER ISSUE	-
DMS_09324	15532	N	N	N	1	CUSTOMER ISSUE	-
DMS_09325	15533	N	N	N	1	CUSTOMER ISSUE	-
DMS_09326	15534	N	N	N	1	CUSTOMER ISSUE	-
DMS_09327	15535	N	N	N	1	CUSTOMER ISSUE	-
DMS_09328	15536	N	N	N	1	CUSTOMER ISSUE	-
DMS_09329	15537	N	N	N	1	CUSTOMER ISSUE	-
DMS_09330	15538	N	N	N	1	CUSTOMER ISSUE	-
DMS_09331	15539	N	N	N	1	CUSTOMER ISSUE	-
DMS_09332	15540	N	N	N	1	CUSTOMER ISSUE	-
DMS_09333	15541	N	N	N	1	CUSTOMER ISSUE	-
DMS_09334	15542	N	N	N	1	CUSTOMER ISSUE	-
DMS_09335	15543	N	N	N	1	CUSTOMER ISSUE	-
DMS_09336	15544	N	N	N	1	CUSTOMER ISSUE	-
DMS_09337	15545	N	N	N	1	CUSTOMER ISSUE	-
DMS_09338	15546	N	N	N	1	CUSTOMER ISSUE	-
DMS_09339	15547	N	N	N	1	CUSTOMER ISSUE	-
DMS_09340	15548	N	N	N	1	CUSTOMER ISSUE	-
DMS_09341	15549	N	N	N	1	CUSTOMER ISSUE	-
DMS_09342	15550	N	N	N	1	CUSTOMER ISSUE	-
DMS_09343	15551	N	N	N	1	CUSTOMER ISSUE	-
DMS_09344	15552	N	N	N	1	CUSTOMER ISSUE	-
DMS_09345	15553	N	N	N	1	CUSTOMER ISSUE	-
DMS_09346	15554	N	N	N	1	CUSTOMER ISSUE	-
DMS_09347	15555	N	N	N	1	CUSTOMER ISSUE	-
DMS_09348	15556	N	N	N	1	CUSTOMER ISSUE	-
DMS_09349	15557	N	N	N	1	CUSTOMER ISSUE	-
DMS_09350	15558	N	N	N	1	CUSTOMER ISSUE	-
DMS_09351	15559	N	N	N	1	CUSTOMER ISSUE	-
DMS_09352	15560	N	N	N	1	CUSTOMER ISSUE	-
DMS_09353	15561	N	N	N	1	CUSTOMER ISSUE	-
DMS_09354	15562	N	N	N	1	CUSTOMER ISSUE	-
DMS_09355	15563	N	N	N	1	CUSTOMER ISSUE	-
DMS_09356	15564	N	N	N	1	CUSTOMER ISSUE	-
DMS_09357	15565	N	N	N	1	CUSTOMER ISSUE	-
DMS_09358	15566	N	N	N	1	CUSTOMER ISSUE	-
DMS_09359	15567	N	N	N	1	CUSTOMER ISSUE	-
DMS_09360	15568	N	N	N	1	CUSTOMER ISSUE	-
DMS_09361	15569	N	N	N	1	CUSTOMER ISSUE	-
DMS_09362	15570	N	N	N	1	CUSTOMER ISSUE	-
DMS_09363	15571	N	N	N	1	CUSTOMER ISSUE	-
DMS_09364	15572	N	N	N	1	CUSTOMER ISSUE	-
DMS_09365	15573	N	N	N	1	CUSTOMER ISSUE	-
DMS_09366	15574	N	N	N	1	CUSTOMER ISSUE	-
DMS_09367	15575	N	N	N	1	CUSTOMER ISSUE	-
DMS_09368	15576	N	N	N	1	CUSTOMER ISSUE	-

DMS_09369	15577	N	N	N	1	CUSTOMER ISSUE	-
DMS_09370	15578	N	N	N	1	CUSTOMER ISSUE	-
DMS_09371	15579	N	N	N	1	CUSTOMER ISSUE	-
DMS_09372	15580	N	N	N	1	CUSTOMER ISSUE	-
DMS_09373	15581	N	N	N	1	CUSTOMER ISSUE	-
DMS_09374	15582	N	N	N	1	CUSTOMER ISSUE	-
DMS_09375	15583	N	N	N	1	CUSTOMER ISSUE	-
DMS_09376	15584	N	N	N	2	CUSTOMER ISSUE	-
DMS_09377	15585	N	N	N	1	CUSTOMER ISSUE	-
DMS_09378	15586	N	N	N	2	CUSTOMER ISSUE	-
DMS_09379	15587	N	N	N	1	CUSTOMER ISSUE	-
DMS_09380	15588	N	N	N	1	CUSTOMER ISSUE	-
DMS_09381	15589	N	N	N	1	CUSTOMER ISSUE	-
DMS_09382	15590	N	N	N	1	CUSTOMER ISSUE	-
DMS_09383	15591	N	N	N	1	CUSTOMER ISSUE	-
DMS_09384	15592	N	N	N	1	CUSTOMER ISSUE	-
DMS_09385	15593	N	N	N	1	CUSTOMER ISSUE	-
DMS_09386	15594	N	N	N	1	CUSTOMER ISSUE	-
DMS_09387	15595	N	N	N	2	CUSTOMER ISSUE	-
DMS_09388	15596	N	N	N	1	CUSTOMER ISSUE	-
DMS_09389	15597	N	N	N	1	CUSTOMER ISSUE	-
DMS_09390	15598	N	N	N	1	CUSTOMER ISSUE	-
DMS_09391	15599	N	N	N	1	CUSTOMER ISSUE	-
DMS_09392	15600	N	N	N	1	CUSTOMER ISSUE	-
DMS_09393	15601	N	N	N	1	CUSTOMER ISSUE	-
DMS_09394	15602	N	N	N	1	CUSTOMER ISSUE	-
DMS_09395	15603	N	N	N	1	CUSTOMER ISSUE	-
DMS_09396	15604	N	N	N	1	CUSTOMER ISSUE	-
DMS_09397	15605	N	N	N	1	CUSTOMER ISSUE	-
DMS_09398	15606	N	N	N	1	CUSTOMER ISSUE	-
DMS_09399	15607	N	N	N	1	CUSTOMER ISSUE	-
DMS_09400	15608	N	N	N	2	CUSTOMER ISSUE	-
DMS_09401	15609	N	N	N	1	CUSTOMER ISSUE	-
DMS_09402	15610	N	N	N	1	CUSTOMER ISSUE	-
DMS_09403	15611	N	N	N	1	CUSTOMER ISSUE	-
DMS_09404	15612	N	N	N	1	CUSTOMER ISSUE	-
DMS_09405	15613	N	N	N	1	CUSTOMER ISSUE	-
DMS_09406	15614	N	N	N	1	CUSTOMER ISSUE	-
DMS_09407	15615	N	N	N	1	CUSTOMER ISSUE	-
DMS_09408	15616	N	N	N	1	CUSTOMER ISSUE	-
DMS_09409	15617	N	N	N	1	CUSTOMER ISSUE	-
DMS_09410	15618	N	N	N	1	CUSTOMER ISSUE	-
DMS_09411	15619	N	N	N	1	CUSTOMER ISSUE	-
DMS_09412	15620	N	N	N	1	CUSTOMER ISSUE	-
DMS_09413	15621	N	N	N	1	CUSTOMER ISSUE	-
DMS_09414	15622	N	N	N	1	CUSTOMER ISSUE	-
DMS_09415	15623	N	N	N	2	CUSTOMER ISSUE	-
DMS_09416	15624	N	N	N	1	CUSTOMER ISSUE	-
DMS_09417	15625	N	N	N	1	CUSTOMER ISSUE	-
DMS_09418	15626	N	N	N	1	CUSTOMER ISSUE	-
DMS_09419	15627	N	N	N	1	CUSTOMER ISSUE	-
DMS_09420	15628	N	N	N	1	CUSTOMER ISSUE	-
DMS_09421	15629	N	N	N	1	CUSTOMER ISSUE	-
DMS_09422	15630	N	N	N	1	CUSTOMER ISSUE	-
DMS_09423	15631	N	N	N	1	CUSTOMER ISSUE	-
DMS_09424	15632	N	N	N	1	CUSTOMER ISSUE	-
DMS_09425	15633	N	N	N	1	CUSTOMER ISSUE	-
DMS_09426	15634	N	N	N	1	CUSTOMER ISSUE	-
DMS_09427	15635	N	N	N	1	CUSTOMER ISSUE	-
DMS_09428	15636	N	N	N	1	CUSTOMER ISSUE	-
DMS_09429	15637	N	N	N	1	CUSTOMER ISSUE	-
DMS_09430	15638	N	N	N	1	CUSTOMER ISSUE	-
DMS_09431	15639	N	N	N	1	CUSTOMER ISSUE	-
DMS_09432	15640	N	N	N	2	CUSTOMER ISSUE	-
DMS_09433	15641	N	N	N	1	CUSTOMER ISSUE	-
DMS_09434	15642	N	N	N	1	CUSTOMER ISSUE	-
DMS_09435	15643	N	N	N	1	CUSTOMER ISSUE	-
DMS_09436	15644	N	N	N	1	CUSTOMER ISSUE	-
DMS_09437	15645	N	N	N	1	CUSTOMER ISSUE	-
DMS_09438	15646	N	N	N	1	CUSTOMER ISSUE	-
DMS_09439	15647	N	N	N	1	CUSTOMER ISSUE	-
DMS_09440	15648	N	N	N	1	CUSTOMER ISSUE	-
DMS_09441	15649	N	N	N	1	CUSTOMER ISSUE	-
DMS_09442	15650	N	N	N	1	CUSTOMER ISSUE	-
DMS_09443	15651	N	N	N	1	CUSTOMER ISSUE	-
DMS_09444	15652	N	N	N	1	CUSTOMER ISSUE	-
DMS_09445	15653	N	N	N	1	CUSTOMER ISSUE	-
DMS_09446	15654	N	N	N	1	CUSTOMER ISSUE	-
DMS_09447	15655	N	N	N	1	CUSTOMER ISSUE	-
DMS_09448	15656	N	N	N	1	CUSTOMER ISSUE	-

DMS_09449	15657	N	N	N	1	CUSTOMER ISSUE	-
DMS_09450	15658	N	N	N	1	CUSTOMER ISSUE	-
DMS_09451	15659	N	N	N	1	CUSTOMER ISSUE	-
DMS_09452	15660	N	N	N	1	CUSTOMER ISSUE	-
DMS_09453	15661	N	N	N	1	CUSTOMER ISSUE	-
DMS_09454	15662	N	N	N	1	CUSTOMER ISSUE	-
DMS_09455	15663	N	N	N	1	CUSTOMER ISSUE	-
DMS_09456	15664	N	N	N	1	CUSTOMER ISSUE	-
DMS_09457	15665	N	N	N	1	CUSTOMER ISSUE	-
DMS_09458	15666	N	N	N	1	CUSTOMER ISSUE	-
DMS_09459	15667	N	N	N	1	CUSTOMER ISSUE	-
DMS_09460	15668	N	N	N	1	CUSTOMER ISSUE	-
DMS_09461	15669	N	N	N	1	CUSTOMER ISSUE	-
DMS_09462	15670	N	N	N	1	CUSTOMER ISSUE	-
DMS_09463	15671	N	N	N	1	CUSTOMER ISSUE	-
DMS_09464	15672	N	N	N	1	CUSTOMER ISSUE	-
DMS_09465	15673	N	N	N	1	CUSTOMER ISSUE	-
DMS_09466	15674	N	N	N	1	CUSTOMER ISSUE	-
DMS_09467	15675	N	N	N	1	CUSTOMER ISSUE	-
DMS_09468	15676	N	N	N	1	CUSTOMER ISSUE	-
DMS_09469	15677	N	N	N	1	CUSTOMER ISSUE	-
DMS_09470	15678	N	N	N	1	CUSTOMER ISSUE	-
DMS_09471	15679	N	N	N	1	CUSTOMER ISSUE	-
DMS_09472	15680	N	N	N	1	CUSTOMER ISSUE	-
DMS_09473	15681	N	N	N	1	CUSTOMER ISSUE	-
DMS_09474	15682	N	N	N	1	CUSTOMER ISSUE	-
DMS_09475	15683	N	N	N	1	CUSTOMER ISSUE	-
DMS_09476	15684	N	N	N	1	CUSTOMER ISSUE	-
DMS_09477	15685	N	N	N	1	CUSTOMER ISSUE	-
DMS_09478	15686	N	N	N	1	CUSTOMER ISSUE	-
DMS_09479	15687	N	N	N	1	CUSTOMER ISSUE	-
DMS_09480	15688	N	N	N	1	CUSTOMER ISSUE	-
DMS_09481	15689	N	N	N	1	CUSTOMER ISSUE	-
DMS_09482	15690	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09483	15691	N	N	N	1	CUSTOMER ISSUE	-
DMS_09484	15692	N	N	N	1	CUSTOMER ISSUE	-
DMS_09485	15693	N	N	N	1	CUSTOMER ISSUE	-
DMS_09486	15694	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09487	15695	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_09488	15696	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09490	15697	N	N	N	1	CUSTOMER ISSUE	-
DMS_09491	15698	N	N	N	1	CUSTOMER ISSUE	-
DMS_09492	15699	N	N	N	1	CUSTOMER ISSUE	-
DMS_09493	15700	N	N	N	1	CUSTOMER ISSUE	-
DMS_09494	15701	N	N	N	1	CUSTOMER ISSUE	-
DMS_09496	15702	N	N	N	1	CUSTOMER ISSUE	-
DMS_09497	15703	N	N	N	1	CUSTOMER ISSUE	-
DMS_09498	15704	N	N	N	1	CUSTOMER ISSUE	-
DMS_09499	15705	N	N	N	1	CUSTOMER ISSUE	-
DMS_09500	15706	N	N	N	1	CUSTOMER ISSUE	-
DMS_09501	15707	N	N	N	1	CUSTOMER ISSUE	-
DMS_09502	15708	N	N	N	1	CUSTOMER ISSUE	-
DMS_09503	15709	N	N	N	1	CUSTOMER ISSUE	-
DMS_09504	15710	N	N	N	1	CUSTOMER ISSUE	-
DMS_09505	15711	N	N	N	1	CUSTOMER ISSUE	-
DMS_09506	15712	N	N	N	1	CUSTOMER ISSUE	-
DMS_09507	15713	N	N	N	1	CUSTOMER ISSUE	-
DMS_09508	15714	N	N	N	1	CUSTOMER ISSUE	-
DMS_09509	15715	N	N	N	1	CUSTOMER ISSUE	-
DMS_09510	15716	N	N	N	1	CUSTOMER ISSUE	-
DMS_09511	15717	N	N	N	1	CUSTOMER ISSUE	-
DMS_09512	15718	N	N	N	1	CUSTOMER ISSUE	-
DMS_09513	15719	N	N	N	1	CUSTOMER ISSUE	-
DMS_09514	15720	N	N	N	1	CUSTOMER ISSUE	-
DMS_09515	15721	N	N	N	1	CUSTOMER ISSUE	-
DMS_09516	15722	N	N	N	1	CUSTOMER ISSUE	-
DMS_09517	15723	N	N	N	1	CUSTOMER ISSUE	-
DMS_09518	15724	N	N	N	1	CUSTOMER ISSUE	-
DMS_09519	15725	N	N	N	1	CUSTOMER ISSUE	-
DMS_09520	15726	N	N	N	1	CUSTOMER ISSUE	-
DMS_09521	15727	N	N	N	1	CUSTOMER ISSUE	-
DMS_09522	15728	N	N	N	1	CUSTOMER ISSUE	-
DMS_09523	15729	N	N	N	1	CUSTOMER ISSUE	-
DMS_09524	15730	N	N	N	1	CUSTOMER ISSUE	-
DMS_09525	15731	N	N	N	1	CUSTOMER ISSUE	-
DMS_09526	15732	N	N	N	1	CUSTOMER ISSUE	-
DMS_09527	15733	N	N	N	1	CUSTOMER ISSUE	-
DMS_09528	15734	N	N	N	1	CUSTOMER ISSUE	-
DMS_09529	15735	N	N	N	1	CUSTOMER ISSUE	-
DMS_09530	15736	N	N	N	1	CUSTOMER ISSUE	-

DMS_09531	15737	N	N	N	1	CUSTOMER ISSUE	-
DMS_09532	15738	N	N	N	1	CUSTOMER ISSUE	-
DMS_09533	15739	N	N	N	1	CUSTOMER ISSUE	-
DMS_09534	15740	N	N	N	1	CUSTOMER ISSUE	-
DMS_09535	15741	N	N	N	1	CUSTOMER ISSUE	-
DMS_09536	15742	N	N	N	1	CUSTOMER ISSUE	-
DMS_09537	15743	N	N	N	1	CUSTOMER ISSUE	-
DMS_09538	15744	N	N	N	1	CUSTOMER ISSUE	-
DMS_09539	15745	N	N	N	1	CUSTOMER ISSUE	-
DMS_09540	15746	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_09541	15747	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_09542	15748	N	N	N	1	CUSTOMER ISSUE	-
DMS_09543	15749	N	N	N	1	CUSTOMER ISSUE	-
DMS_09544	15750	N	N	N	1	CUSTOMER ISSUE	-
DMS_09545	15751	N	N	N	1	CUSTOMER ISSUE	-
DMS_09546	15752	N	N	N	1	CUSTOMER ISSUE	-
DMS_09547	15753	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09548	15754	N	N	N	1	CUSTOMER ISSUE	-
DMS_09549	15755	N	N	N	1	CUSTOMER ISSUE	-
DMS_09550	15756	N	N	N	1	CUSTOMER ISSUE	-
DMS_09551	15757	N	N	N	1	CUSTOMER ISSUE	-
DMS_09552	15758	N	N	N	1	CUSTOMER ISSUE	-
DMS_09553	15759	N	N	N	1	CUSTOMER ISSUE	-
DMS_09554	15760	N	N	N	1	CUSTOMER ISSUE	-
DMS_09555	15761	N	N	N	1	CUSTOMER ISSUE	-
DMS_09556	15762	N	N	N	1	CUSTOMER ISSUE	-
DMS_09557	15763	N	N	N	1	CUSTOMER ISSUE	-
DMS_09558	15764	N	N	N	1	CUSTOMER ISSUE	-
DMS_09559	15765	N	N	N	1	CUSTOMER ISSUE	-
DMS_09560	15766	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09563	15767	N	N	N	1	CUSTOMER ISSUE	-
DMS_09564	15768	N	N	N	1	CUSTOMER ISSUE	-
DMS_09565	15769	N	N	N	1	CUSTOMER ISSUE	-
DMS_09566	15770	N	N	N	1	CUSTOMER ISSUE	-
DMS_09567	15771	N	N	N	1	CUSTOMER ISSUE	-
DMS_09568	15772	N	N	N	1	CUSTOMER ISSUE	-
DMS_09569	15773	N	N	N	1	CUSTOMER ISSUE	-
DMS_09570	15774	N	N	N	1	CUSTOMER ISSUE	-
DMS_09571	15775	N	N	N	1	CUSTOMER ISSUE	-
DMS_09572	15776	N	N	N	1	CUSTOMER ISSUE	-
DMS_09573	15777	N	N	N	1	CUSTOMER ISSUE	-
DMS_09574	15778	N	N	N	1	CUSTOMER ISSUE	-
DMS_09575	15779	N	N	N	1	CUSTOMER ISSUE	-
DMS_09576	15780	N	N	N	1	CUSTOMER ISSUE	-
DMS_09577	15781	N	N	N	1	CUSTOMER ISSUE	-
DMS_09578	15782	N	N	N	1	CUSTOMER ISSUE	-
DMS_09579	15783	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09580	15784	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09581	15785	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09582	15786	N	N	N	1	CUSTOMER ISSUE	-
DMS_09583	15787	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09584	15788	N	N	N	1	CUSTOMER ISSUE	-
DMS_09585	15789	N	N	N	1	CUSTOMER ISSUE	-
DMS_09587	15790	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09588	15791	N	N	N	1	CUSTOMER ISSUE	-
DMS_09589	15792	N	N	N	1	CUSTOMER ISSUE	-
DMS_09590	15793	N	N	N	1	CUSTOMER ISSUE	-
DMS_09591	15794	N	N	N	1	CUSTOMER ISSUE	-
DMS_09592	15795	N	N	N	1	CUSTOMER ISSUE	-
DMS_09593	15796	N	N	N	1	CUSTOMER ISSUE	-
DMS_09594	15797	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09595	15798	N	N	N	1	CUSTOMER ISSUE	-
DMS_09596	15799	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09597	15800	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09598	15801	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09599	15802	N	N	N	1	CUSTOMER ISSUE	-
DMS_09600	15803	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09601	15804	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09602	15805	N	N	N	1	CUSTOMER ISSUE	-
DMS_09603	15806	N	N	N	1	CUSTOMER ISSUE	-
DMS_09604	15807	N	N	N	1	CUSTOMER ISSUE	-
DMS_09605	15808	N	N	N	1	CUSTOMER ISSUE	-
DMS_09606	15809	N	N	N	1	CUSTOMER ISSUE	-
DMS_09607	15810	N	N	N	1	CUSTOMER ISSUE	-
DMS_09608	15811	N	N	N	1	CUSTOMER ISSUE	-
DMS_09609	15812	N	N	N	1	CUSTOMER ISSUE	-
DMS_09610	15813	N	N	N	1	CUSTOMER ISSUE	-
DMS_09611	15814	N	N	N	1	CUSTOMER ISSUE	-
DMS_09612	15815	N	N	N	1	CUSTOMER ISSUE	-
DMS_09613	15816	N	N	N	1	CUSTOMER ISSUE	-

DMS_09614	15817	N	N	N	1	CUSTOMER ISSUE	-
DMS_09615	15818	N	N	N	1	CUSTOMER ISSUE	-
DMS_09616	15819	N	N	N	1	CUSTOMER ISSUE	-
DMS_09617	15820	N	N	N	1	CUSTOMER ISSUE	-
DMS_09618	15821	N	N	N	1	CUSTOMER ISSUE	-
DMS_09619	15822	N	N	N	1	CUSTOMER ISSUE	-
DMS_09620	15823	N	N	N	1	CUSTOMER ISSUE	-
DMS_09621	15824	N	N	N	1	CUSTOMER ISSUE	-
DMS_09622	15825	N	N	N	1	CUSTOMER ISSUE	-
DMS_09623	15826	N	N	N	1	CUSTOMER ISSUE	-
DMS_09624	15827	N	N	N	1	CUSTOMER ISSUE	-
DMS_09625	15828	N	N	N	1	CUSTOMER ISSUE	-
DMS_09627	15829	N	N	N	1	CUSTOMER ISSUE	-
DMS_09628	15830	N	N	N	1	CUSTOMER ISSUE	-
DMS_09629	15831	N	N	N	1	CUSTOMER ISSUE	-
DMS_09630	15832	N	N	N	1	CUSTOMER ISSUE	-
DMS_09631	15833	N	N	N	1	CUSTOMER ISSUE	-
DMS_09632	15834	N	N	N	1	CUSTOMER ISSUE	-
DMS_09633	15835	N	N	N	1	CUSTOMER ISSUE	-
DMS_09634	15836	N	N	N	1	CUSTOMER ISSUE	-
DMS_09635	15837	N	N	N	1	CUSTOMER ISSUE	-
DMS_09636	15838	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09637	15839	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09638	15840	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09639	15841	N	N	N	1	CUSTOMER ISSUE	-
DMS_09641	15842	N	N	N	1	CUSTOMER ISSUE	-
DMS_09642	15843	N	N	N	1	CUSTOMER ISSUE	-
DMS_09643	15844	N	N	N	1	CUSTOMER ISSUE	-
DMS_09644	15845	N	N	N	1	CUSTOMER ISSUE	-
DMS_09645	15846	N	N	N	1	CUSTOMER ISSUE	-
DMS_09646	15847	N	N	N	1	CUSTOMER ISSUE	-
DMS_09647	15848	N	N	N	1	CUSTOMER ISSUE	-
DMS_09648	15849	N	N	N	1	CUSTOMER ISSUE	-
DMS_09649	15850	N	N	N	1	CUSTOMER ISSUE	-
DMS_09650	15851	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_09652	15852	N	N	N	1	CUSTOMER ISSUE	-
DMS_09653	15853	N	N	N	1	CUSTOMER ISSUE	-
DMS_09654	15854	N	N	N	1	CUSTOMER ISSUE	-
DMS_09655	15855	N	N	N	1	CUSTOMER ISSUE	-
DMS_09656	15856	N	N	N	1	CUSTOMER ISSUE	-
DMS_09657	15857	N	N	N	1	CUSTOMER ISSUE	-
DMS_09658	15858	N	N	N	1	CUSTOMER ISSUE	-
DMS_09659	15859	N	N	N	1	CUSTOMER ISSUE	-
DMS_09660	15860	N	N	N	1	CUSTOMER ISSUE	-
DMS_09661	15861	N	N	N	1	CUSTOMER ISSUE	-
DMS_09662	15862	N	N	N	1	CUSTOMER ISSUE	-
DMS_09663	15863	N	N	N	1	CUSTOMER ISSUE	-
DMS_09664	15864	N	N	N	1	CUSTOMER ISSUE	-
DMS_09665	15865	N	N	N	1	CUSTOMER ISSUE	-
DMS_09666	15866	N	N	N	1	CUSTOMER ISSUE	-
DMS_09667	15867	N	N	N	1	CUSTOMER ISSUE	-
DMS_09668	15868	N	N	N	1	CUSTOMER ISSUE	-
DMS_09669	15869	N	N	N	1	CUSTOMER ISSUE	-
DMS_09670	15870	N	N	N	1	CUSTOMER ISSUE	-
DMS_09671	15871	N	N	N	1	CUSTOMER ISSUE	-
DMS_09672	15872	N	N	N	1	CUSTOMER ISSUE	-
DMS_09673	15873	N	N	N	1	CUSTOMER ISSUE	-
DMS_09674	15874	N	N	N	1	CUSTOMER ISSUE	-
DMS_09675	15875	N	N	N	1	CUSTOMER ISSUE	-
DMS_09676	15876	N	N	N	1	CUSTOMER ISSUE	-
DMS_09677	15877	N	N	N	1	CUSTOMER ISSUE	-
DMS_09678	15878	N	N	N	1	CUSTOMER ISSUE	-
DMS_09679	15879	N	N	N	1	CUSTOMER ISSUE	-
DMS_09680	15880	N	N	N	1	CUSTOMER ISSUE	-
DMS_09681	15881	N	N	N	1	CUSTOMER ISSUE	-
DMS_09682	15882	N	N	N	1	CUSTOMER ISSUE	-
DMS_09683	15883	N	N	N	1	CUSTOMER ISSUE	-
DMS_09684	15884	N	N	N	1	CUSTOMER ISSUE	-
DMS_09686	15885	N	N	N	1	CUSTOMER ISSUE	-
DMS_09687	15886	N	N	N	1	CUSTOMER ISSUE	-
DMS_09689	15887	N	N	N	1	CUSTOMER ISSUE	-
DMS_09690	15888	N	N	N	1	CUSTOMER ISSUE	-
DMS_09691	15889	N	N	N	1	CUSTOMER ISSUE	-
DMS_09692	15890	N	N	N	1	CUSTOMER ISSUE	-
DMS_09693	15891	N	N	N	1	CUSTOMER ISSUE	-
DMS_09696	15892	N	N	N	1	CUSTOMER ISSUE	-
DMS_09697	15893	N	N	N	1	CUSTOMER ISSUE	-
DMS_09698	15894	N	N	N	1	CUSTOMER ISSUE	-
DMS_09700	15895	N	N	N	1	CUSTOMER ISSUE	-
DMS_09701	15896	N	N	N	1	CUSTOMER ISSUE	-

DMS_09702	15897	N	N	N	1	CUSTOMER ISSUE	-
DMS_09703	15898	N	N	N	1	CUSTOMER ISSUE	-
DMS_09704	15899	N	N	N	1	CUSTOMER ISSUE	-
DMS_09705	15900	N	N	N	1	CUSTOMER ISSUE	-
DMS_09706	15901	N	N	N	1	CUSTOMER ISSUE	-
DMS_09707	15902	N	N	N	1	CUSTOMER ISSUE	-
DMS_09708	15903	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09709	15904	N	N	N	1	CUSTOMER ISSUE	-
DMS_09710	15905	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09711	15906	N	N	N	1	CUSTOMER ISSUE	-
DMS_09712	15907	N	N	N	1	CUSTOMER ISSUE	-
DMS_09713	15908	N	N	N	1	CUSTOMER ISSUE	-
DMS_09714	15909	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09715	15910	N	N	N	1	CUSTOMER ISSUE	-
DMS_09716	15911	N	N	N	1	CUSTOMER ISSUE	-
DMS_09717	15912	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09718	15913	N	N	N	1	CUSTOMER ISSUE	-
DMS_09719	15914	N	N	N	1	CUSTOMER ISSUE	-
DMS_09720	15915	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09721	15916	N	N	N	1	CUSTOMER ISSUE	-
DMS_09722	15917	N	N	N	1	CUSTOMER ISSUE	-
DMS_09723	15918	N	N	N	1	CUSTOMER ISSUE	-
DMS_09724	15919	N	N	N	1	CUSTOMER ISSUE	-
DMS_09725	15920	N	N	N	1	CUSTOMER ISSUE	-
DMS_09726	15921	N	N	N	1	CUSTOMER ISSUE	-
DMS_09727	15922	N	N	N	1	CUSTOMER ISSUE	-
DMS_09728	15923	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09729	15924	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09730	15925	N	N	N	1	CUSTOMER ISSUE	-
DMS_09731	15926	N	N	N	1	CUSTOMER ISSUE	-
DMS_09732	15927	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09733	15928	N	N	N	1	CUSTOMER ISSUE	-
DMS_09734	15929	N	N	N	1	CUSTOMER ISSUE	-
DMS_09735	15930	N	N	N	1	CUSTOMER ISSUE	-
DMS_09736	15931	N	N	N	1	CUSTOMER ISSUE	-
DMS_09737	15932	N	N	N	1	CUSTOMER ISSUE	-
DMS_09738	15933	N	N	N	1	CUSTOMER ISSUE	-
DMS_09739	15934	N	N	N	1	CUSTOMER ISSUE	-
DMS_09740	15935	N	N	N	1	CUSTOMER ISSUE	-
DMS_09741	15936	N	N	N	1	CUSTOMER ISSUE	-
DMS_09742	15937	N	N	N	1	CUSTOMER ISSUE	-
DMS_09743	15938	N	N	N	1	CUSTOMER ISSUE	-
DMS_09744	15939	N	N	N	1	CUSTOMER ISSUE	-
DMS_09745	15940	N	N	N	1	CUSTOMER ISSUE	-
DMS_09746	15941	N	N	N	1	CUSTOMER ISSUE	-
DMS_09747	15942	N	N	N	1	CUSTOMER ISSUE	-
DMS_09748	15943	N	N	N	1	CUSTOMER ISSUE	-
DMS_09749	15944	N	N	N	1	CUSTOMER ISSUE	-
DMS_09750	15945	N	N	N	1	CUSTOMER ISSUE	-
DMS_09751	15946	N	N	N	1	CUSTOMER ISSUE	-
DMS_09752	15947	N	N	N	1	CUSTOMER ISSUE	-
DMS_09753	15948	N	N	N	1	CUSTOMER ISSUE	-
DMS_09754	15949	N	N	N	1	CUSTOMER ISSUE	-
DMS_09755	15950	N	N	N	1	CUSTOMER ISSUE	-
DMS_09756	15951	N	N	N	1	CUSTOMER ISSUE	-
DMS_09757	15952	N	N	N	1	CUSTOMER ISSUE	-
DMS_09758	15953	N	N	N	1	CUSTOMER ISSUE	-
DMS_09759	15954	N	N	N	1	CUSTOMER ISSUE	-
DMS_09760	15955	N	N	N	1	CUSTOMER ISSUE	-
DMS_09761	15956	N	N	N	1	CUSTOMER ISSUE	-
DMS_09762	15957	N	N	N	1	CUSTOMER ISSUE	-
DMS_09763	15958	N	N	N	1	CUSTOMER ISSUE	-
DMS_09764	15959	N	N	N	1	CUSTOMER ISSUE	-
DMS_09765	15960	N	N	N	1	CUSTOMER ISSUE	-
DMS_09766	15961	N	N	N	1	CUSTOMER ISSUE	-
DMS_09767	15962	N	N	N	1	CUSTOMER ISSUE	-
DMS_09768	15963	N	N	N	1	CUSTOMER ISSUE	-
DMS_09769	15964	N	N	N	1	CUSTOMER ISSUE	-
DMS_09770	15965	N	N	N	1	CUSTOMER ISSUE	-
DMS_09771	15966	N	N	N	1	CUSTOMER ISSUE	-
DMS_09772	15967	N	N	N	1	CUSTOMER ISSUE	-
DMS_09773	15968	N	N	N	1	CUSTOMER ISSUE	-
DMS_09774	15969	N	N	N	1	CUSTOMER ISSUE	-
DMS_09775	15970	N	N	N	1	CUSTOMER ISSUE	-
DMS_09776	15971	N	N	N	1	CUSTOMER ISSUE	-
DMS_09777	15972	N	N	N	1	CUSTOMER ISSUE	-
DMS_09778	15973	N	N	N	1	CUSTOMER ISSUE	-
DMS_09779	15974	N	N	N	1	CUSTOMER ISSUE	-
DMS_09780	15975	N	N	N	1	CUSTOMER ISSUE	-
DMS_09781	15976	N	N	N	1	CUSTOMER ISSUE	-

DMS_09782	15977	N	N	N	1	CUSTOMER ISSUE	-
DMS_09784	15978	N	N	N	1	CUSTOMER ISSUE	-
DMS_09785	15979	N	N	N	2	CUSTOMER ISSUE	-
DMS_09786	15980	N	N	N	1	CUSTOMER ISSUE	-
DMS_09787	15981	N	N	N	1	CUSTOMER ISSUE	-
DMS_09788	15982	N	N	N	1	CUSTOMER ISSUE	-
DMS_09789	15983	N	N	N	1	CUSTOMER ISSUE	-
DMS_09790	15984	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09791	15985	N	N	N	1	CUSTOMER ISSUE	-
DMS_09792	15986	N	N	N	1	CUSTOMER ISSUE	-
DMS_09793	15987	N	N	N	1	CUSTOMER ISSUE	-
DMS_09794	15988	N	N	N	1	CUSTOMER ISSUE	-
DMS_09795	15989	N	N	N	1	CUSTOMER ISSUE	-
DMS_09796	15990	N	N	N	1	CUSTOMER ISSUE	-
DMS_09797	15991	N	N	N	1	CUSTOMER ISSUE	-
DMS_09798	15992	N	N	N	1	CUSTOMER ISSUE	-
DMS_09799	15993	N	N	N	1	CUSTOMER ISSUE	-
DMS_09800	15994	N	N	N	1	CUSTOMER ISSUE	-
DMS_09801	15995	N	N	N	1	CUSTOMER ISSUE	-
DMS_09802	15996	N	N	N	1	CUSTOMER ISSUE	-
DMS_09803	15997	N	N	N	1	CUSTOMER ISSUE	-
DMS_09804	15998	N	N	N	1	CUSTOMER ISSUE	-
DMS_09805	15999	N	N	N	1	CUSTOMER ISSUE	-
DMS_09806	16000	N	N	N	1	CUSTOMER ISSUE	-
DMS_09807	16001	N	N	N	1	CUSTOMER ISSUE	-
DMS_09808	16002	N	N	N	1	CUSTOMER ISSUE	-
DMS_09809	16003	N	N	N	1	CUSTOMER ISSUE	-
DMS_09810	16004	N	N	N	1	CUSTOMER ISSUE	-
DMS_09811	16005	N	N	N	1	CUSTOMER ISSUE	-
DMS_09812	16006	N	N	N	1	CUSTOMER ISSUE	-
DMS_09813	16007	N	N	N	1	CUSTOMER ISSUE	-
DMS_09814	16008	N	N	N	1	CUSTOMER ISSUE	-
DMS_09815	16009	N	N	N	1	CUSTOMER ISSUE	-
DMS_09816	16010	N	N	N	1	CUSTOMER ISSUE	-
DMS_09817	16011	N	N	N	1	CUSTOMER ISSUE	-
DMS_09818	16012	N	N	N	1	CUSTOMER ISSUE	-
DMS_09819	16013	N	N	N	1	CUSTOMER ISSUE	-
DMS_09820	16014	N	N	N	1	CUSTOMER ISSUE	-
DMS_09821	16015	N	N	N	1	CUSTOMER ISSUE	-
DMS_09822	16016	N	N	N	1	CUSTOMER ISSUE	-
DMS_09823	16017	N	N	N	1	CUSTOMER ISSUE	-
DMS_09824	16018	N	N	N	1	CUSTOMER ISSUE	-
DMS_09825	16019	N	N	N	1	CUSTOMER ISSUE	-
DMS_09826	16020	N	N	N	1	CUSTOMER ISSUE	-
DMS_09827	16021	N	N	N	1	CUSTOMER ISSUE	-
DMS_09829	16022	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09830	16023	N	N	N	1	CUSTOMER ISSUE	-
DMS_09831	16024	N	N	N	1	CUSTOMER ISSUE	-
DMS_09832	16025	N	N	N	1	CUSTOMER ISSUE	-
DMS_09833	16026	N	N	N	1	CUSTOMER ISSUE	-
DMS_09834	16027	N	N	N	1	CUSTOMER ISSUE	-
DMS_09835	16028	N	N	N	1	CUSTOMER ISSUE	-
DMS_09836	16029	N	N	N	1	CUSTOMER ISSUE	-
DMS_09837	16030	N	N	N	1	CUSTOMER ISSUE	-
DMS_09838	16031	N	N	N	1	CUSTOMER ISSUE	-
DMS_09839	16032	N	N	N	1	CUSTOMER ISSUE	-
DMS_09840	16033	N	N	N	1	CUSTOMER ISSUE	-
DMS_09841	16034	N	N	N	1	CUSTOMER ISSUE	-
DMS_09844	16035	N	N	N	1	CUSTOMER ISSUE	-
DMS_09845	16036	N	N	N	1	CUSTOMER ISSUE	-
DMS_09846	16037	N	N	N	1	CUSTOMER ISSUE	-
DMS_09847	16038	N	N	N	1	CUSTOMER ISSUE	-
DMS_09848	16039	N	N	N	1	CUSTOMER ISSUE	-
DMS_09849	16040	N	N	N	1	CUSTOMER ISSUE	-
DMS_09850	16041	N	N	N	1	CUSTOMER ISSUE	-
DMS_09851	16042	N	N	N	1	CUSTOMER ISSUE	-
DMS_09853	16043	N	N	N	1	CUSTOMER ISSUE	-
DMS_09854	16044	N	N	N	1	CUSTOMER ISSUE	-
DMS_09855	16045	N	N	N	1	CUSTOMER ISSUE	-
DMS_09856	16046	N	N	N	1	CUSTOMER ISSUE	-
DMS_09857	16047	N	N	N	1	CUSTOMER ISSUE	-
DMS_09858	16048	N	N	N	1	CUSTOMER ISSUE	-
DMS_09859	16049	N	N	N	1	CUSTOMER ISSUE	-
DMS_09860	16050	N	N	N	1	CUSTOMER ISSUE	-
DMS_09861	16051	N	N	N	1	CUSTOMER ISSUE	-
DMS_09862	16052	N	N	N	1	CUSTOMER ISSUE	-
DMS_09863	16053	N	N	N	1	CUSTOMER ISSUE	-
DMS_09864	16054	N	N	N	1	CUSTOMER ISSUE	-
DMS_09865	16055	N	N	N	1	CUSTOMER ISSUE	-
DMS_09866	16056	N	N	N	1	CUSTOMER ISSUE	-

DMS_09867	16057	N	N	N	1	CUSTOMER ISSUE	-
DMS_09868	16058	N	N	N	1	CUSTOMER ISSUE	-
DMS_09869	16059	N	N	N	1	CUSTOMER ISSUE	-
DMS_09870	16060	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09871	16061	N	N	N	1	CUSTOMER ISSUE	-
DMS_09872	16062	N	N	N	1	CUSTOMER ISSUE	-
DMS_09873	16063	N	N	N	1	CUSTOMER ISSUE	-
DMS_09874	16064	N	N	N	1	CUSTOMER ISSUE	-
DMS_09875	16065	N	N	N	1	CUSTOMER ISSUE	-
DMS_09876	16066	N	N	N	1	CUSTOMER ISSUE	-
DMS_09877	16067	N	N	N	1	CUSTOMER ISSUE	-
DMS_09878	16068	N	N	N	1	CUSTOMER ISSUE	-
DMS_09879	16069	N	N	N	1	CUSTOMER ISSUE	-
DMS_09880	16070	N	N	N	1	CUSTOMER ISSUE	-
DMS_09881	16071	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09882	16072	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09884	16073	N	N	N	1	CUSTOMER ISSUE	-
DMS_09885	16074	N	N	N	1	CUSTOMER ISSUE	-
DMS_09886	16075	N	N	N	1	CUSTOMER ISSUE	-
DMS_09887	16076	N	N	N	1	CUSTOMER ISSUE	-
DMS_09888	16077	N	N	N	1	CUSTOMER ISSUE	-
DMS_09889	16078	N	N	N	1	CUSTOMER ISSUE	-
DMS_09890	16079	N	N	N	1	CUSTOMER ISSUE	-
DMS_09891	16080	N	N	N	1	CUSTOMER ISSUE	-
DMS_09892	16081	N	N	N	1	CUSTOMER ISSUE	-
DMS_09893	16082	N	N	N	1	CUSTOMER ISSUE	-
DMS_09894	16083	N	N	N	1	CUSTOMER ISSUE	-
DMS_09895	16084	N	N	N	1	CUSTOMER ISSUE	-
DMS_09896	16085	N	N	N	1	CUSTOMER ISSUE	-
DMS_09897	16086	N	N	N	1	CUSTOMER ISSUE	-
DMS_09898	16087	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09899	16088	N	N	N	1	CUSTOMER ISSUE	-
DMS_09900	16089	N	N	N	1	CUSTOMER ISSUE	-
DMS_09901	16090	N	N	N	1	CUSTOMER ISSUE	-
DMS_09902	16091	N	N	N	1	CUSTOMER ISSUE	-
DMS_09903	16092	N	N	N	1	CUSTOMER ISSUE	-
DMS_09904	16093	N	N	N	1	CUSTOMER ISSUE	-
DMS_09905	16094	N	N	N	1	CUSTOMER ISSUE	-
DMS_09906	16095	N	N	N	1	CUSTOMER ISSUE	-
DMS_09907	16096	N	N	N	1	CUSTOMER ISSUE	-
DMS_09908	16097	N	N	N	1	CUSTOMER ISSUE	-
DMS_09909	16098	N	N	N	1	CUSTOMER ISSUE	-
DMS_09910	16099	N	N	N	1	CUSTOMER ISSUE	-
DMS_09911	16100	N	N	N	1	CUSTOMER ISSUE	-
DMS_09912	16101	N	N	N	1	CUSTOMER ISSUE	-
DMS_09913	16102	N	N	N	1	CUSTOMER ISSUE	-
DMS_09914	16103	N	N	N	1	CUSTOMER ISSUE	-
DMS_09915	16104	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09916	16105	N	N	N	1	CUSTOMER ISSUE	-
DMS_09917	16106	N	N	N	1	CUSTOMER ISSUE	-
DMS_09918	16107	N	N	N	1	CUSTOMER ISSUE	-
DMS_09919	16108	N	N	N	1	CUSTOMER ISSUE	-
DMS_09920	16109	N	N	N	1	CUSTOMER ISSUE	-
DMS_09921	16110	N	N	N	1	CUSTOMER ISSUE	-
DMS_09922	16111	N	N	N	1	CUSTOMER ISSUE	-
DMS_09923	16112	N	N	N	1	CUSTOMER ISSUE	-
DMS_09924	16113	N	N	N	1	CUSTOMER ISSUE	-
DMS_09925	16114	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09926	16115	N	N	N	1	CUSTOMER ISSUE	-
DMS_09927	16116	N	N	N	1	CUSTOMER ISSUE	-
DMS_09928	16117	N	N	N	1	CUSTOMER ISSUE	-
DMS_09929	16118	N	N	N	1	CUSTOMER ISSUE	-
DMS_09930	16119	N	N	Y	1	TX - REPLACE	2500
DMS_09931	16120	N	N	N	1	CUSTOMER ISSUE	-
DMS_09932	16121	N	N	N	1	CUSTOMER ISSUE	-
DMS_09933	16122	N	N	N	1	CUSTOMER ISSUE	-
DMS_09934	16123	N	N	N	1	CUSTOMER ISSUE	-
DMS_09935	16124	N	N	N	1	CUSTOMER ISSUE	-
DMS_09936	16125	N	N	N	1	CUSTOMER ISSUE	-
DMS_09937	16126	N	N	N	1	CUSTOMER ISSUE	-
DMS_09938	16127	N	N	N	2	CUSTOMER ISSUE	-
DMS_09939	16128	N	N	N	1	CUSTOMER ISSUE	-
DMS_09940	16129	N	N	N	1	CUSTOMER ISSUE	-
DMS_09941	16130	N	N	N	1	CUSTOMER ISSUE	-
DMS_09942	16131	N	N	N	1	CUSTOMER ISSUE	-
DMS_09943	16132	N	N	N	1	CUSTOMER ISSUE	-
DMS_09944	16133	N	N	N	1	CUSTOMER ISSUE	-
DMS_09946	16134	N	N	N	1	CUSTOMER ISSUE	-
DMS_09947	16135	N	N	N	1	CUSTOMER ISSUE	-
DMS_09948	16136	N	N	N	1	CUSTOMER ISSUE	-

DMS_09949	16137	N	N	N	1	CUSTOMER ISSUE	-
DMS_09950	16138	N	N	N	1	CUSTOMER ISSUE	-
DMS_09951	16139	N	N	N	1	CUSTOMER ISSUE	-
DMS_09952	16140	N	N	N	1	CUSTOMER ISSUE	-
DMS_09953	16141	N	N	N	1	CUSTOMER ISSUE	-
DMS_09954	16142	N	N	N	1	CUSTOMER ISSUE	-
DMS_09955	16143	N	N	N	1	CUSTOMER ISSUE	-
DMS_09956	16144	N	N	N	1	CUSTOMER ISSUE	-
DMS_09957	16145	N	N	N	1	CUSTOMER ISSUE	-
DMS_09958	16146	N	N	N	1	CUSTOMER ISSUE	-
DMS_09960	16147	N	N	N	1	CUSTOMER ISSUE	-
DMS_09961	16148	N	N	N	1	CUSTOMER ISSUE	-
DMS_09962	16149	N	N	N	1	CUSTOMER ISSUE	-
DMS_09963	16150	N	N	N	1	CUSTOMER ISSUE	-
DMS_09964	16151	N	N	N	1	CUSTOMER ISSUE	-
DMS_09965	16152	N	N	N	1	CUSTOMER ISSUE	-
DMS_09966	16153	N	N	N	1	CUSTOMER ISSUE	-
DMS_09967	16154	N	N	N	1	CUSTOMER ISSUE	-
DMS_09968	16155	N	N	N	1	CUSTOMER ISSUE	-
DMS_09969	16156	N	N	N	1	CUSTOMER ISSUE	-
DMS_09970	16157	N	N	N	1	CUSTOMER ISSUE	-
DMS_09971	16158	N	N	N	1	CUSTOMER ISSUE	-
DMS_09972	16159	N	N	N	1	CUSTOMER ISSUE	-
DMS_09973	16160	N	N	N	1	CUSTOMER ISSUE	-
DMS_09974	16161	N	N	N	1	CUSTOMER ISSUE	-
DMS_09976	16162	N	N	N	1	CUSTOMER ISSUE	-
DMS_09977	16163	N	N	N	1	CUSTOMER ISSUE	-
DMS_09978	16164	N	N	N	1	CUSTOMER ISSUE	-
DMS_09979	16165	N	N	N	1	CUSTOMER ISSUE	-
DMS_09980	16166	N	N	N	1	CUSTOMER ISSUE	-
DMS_09981	16167	N	N	N	1	CUSTOMER ISSUE	-
DMS_09982	16168	N	N	N	1	CUSTOMER ISSUE	-
DMS_09984	16169	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09985	16170	N	N	N	1	CUSTOMER ISSUE	-
DMS_09986	16171	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_09987	16172	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09988	16173	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_09989	16174	N	N	N	1	CUSTOMER ISSUE	-
DMS_09990	16175	N	N	N	1	CUSTOMER ISSUE	-
DMS_09991	16176	N	N	N	1	CUSTOMER ISSUE	-
DMS_09992	16177	N	N	N	1	CUSTOMER ISSUE	-
DMS_09993	16178	N	N	N	1	CUSTOMER ISSUE	-
DMS_09994	16179	N	N	N	1	CUSTOMER ISSUE	-
DMS_09995	16180	N	N	N	1	CUSTOMER ISSUE	-
DMS_09996	16181	N	N	N	1	CUSTOMER ISSUE	-
DMS_09997	16182	N	N	N	1	CUSTOMER ISSUE	-
DMS_10001	16183	N	N	N	1	CUSTOMER ISSUE	-
DMS_10002	16184	N	N	N	1	CUSTOMER ISSUE	-
DMS_10003	16185	N	N	N	1	CUSTOMER ISSUE	-
DMS_10004	16186	N	N	N	1	CUSTOMER ISSUE	-
DMS_10005	16187	N	N	N	1	CUSTOMER ISSUE	-
DMS_10006	16188	N	N	N	1	CUSTOMER ISSUE	-
DMS_10007	16189	N	N	N	1	CUSTOMER ISSUE	-
DMS_10008	16190	N	N	N	1	CUSTOMER ISSUE	-
DMS_10009	16191	N	N	N	1	CUSTOMER ISSUE	-
DMS_10010	16192	N	N	N	1	CUSTOMER ISSUE	-
DMS_10011	16193	N	N	N	1	CUSTOMER ISSUE	-
DMS_10012	16194	N	N	N	1	CUSTOMER ISSUE	-
DMS_10013	16195	N	N	N	1	CUSTOMER ISSUE	-
DMS_10014	16196	N	N	N	1	CUSTOMER ISSUE	-
DMS_10015	16197	N	N	N	1	CUSTOMER ISSUE	-
DMS_10016	16198	N	N	N	1	CUSTOMER ISSUE	-
DMS_10017	16199	N	N	N	1	CUSTOMER ISSUE	-
DMS_10018	16200	N	N	N	1	CUSTOMER ISSUE	-
DMS_10019	16201	N	N	N	1	CUSTOMER ISSUE	-
DMS_10020	16202	N	N	N	1	CUSTOMER ISSUE	-
DMS_10021	16203	N	N	N	1	CUSTOMER ISSUE	-
DMS_10022	16204	N	N	N	1	CUSTOMER ISSUE	-
DMS_10023	16205	N	N	N	1	CUSTOMER ISSUE	-
DMS_10024	16206	N	N	N	1	CUSTOMER ISSUE	-
DMS_10025	16207	N	N	N	1	CUSTOMER ISSUE	-
DMS_10026	16208	N	N	N	1	CUSTOMER ISSUE	-
DMS_10027	16209	N	N	N	1	CUSTOMER ISSUE	-
DMS_10029	16210	N	N	N	1	CUSTOMER ISSUE	-
DMS_10030	16211	N	N	N	1	CUSTOMER ISSUE	-
DMS_10031	16212	N	N	N	1	CUSTOMER ISSUE	-
DMS_10032	16213	N	N	N	1	CUSTOMER ISSUE	-
DMS_10033	16214	N	N	N	1	CUSTOMER ISSUE	-
DMS_10034	16215	N	N	N	1	CUSTOMER ISSUE	-
DMS_10035	16216	N	N	N	2	CUSTOMER ISSUE	-

DMS_10036	16217	N	N	N	1	CUSTOMER ISSUE	-
DMS_10037	16218	N	N	N	1	CUSTOMER ISSUE	-
DMS_10038	16219	N	N	N	1	CUSTOMER ISSUE	-
DMS_10039	16220	N	N	N	1	CUSTOMER ISSUE	-
DMS_10040	16221	N	N	N	1	CUSTOMER ISSUE	-
DMS_10041	16222	N	N	N	1	CUSTOMER ISSUE	-
DMS_10042	16223	N	N	N	1	CUSTOMER ISSUE	-
DMS_10043	16224	N	N	N	1	CUSTOMER ISSUE	-
DMS_10044	16225	N	N	N	1	CUSTOMER ISSUE	-
DMS_10045	16226	N	N	N	1	CUSTOMER ISSUE	-
DMS_10046	16227	N	N	N	1	CUSTOMER ISSUE	-
DMS_10047	16228	N	N	N	1	CUSTOMER ISSUE	-
DMS_10048	16229	N	N	N	1	CUSTOMER ISSUE	-
DMS_10049	16230	N	N	N	1	CUSTOMER ISSUE	-
DMS_10050	16231	N	N	N	1	CUSTOMER ISSUE	-
DMS_10051	16232	N	N	N	1	CUSTOMER ISSUE	-
DMS_10052	16233	N	N	N	1	CUSTOMER ISSUE	-
DMS_10053	16234	N	N	N	1	CUSTOMER ISSUE	-
DMS_10054	16235	N	N	N	1	CUSTOMER ISSUE	-
DMS_10055	16236	N	N	N	1	CUSTOMER ISSUE	-
DMS_10056	16237	N	N	N	1	CUSTOMER ISSUE	-
DMS_10057	16238	N	N	N	1	CUSTOMER ISSUE	-
DMS_10058	16239	N	N	N	1	CUSTOMER ISSUE	-
DMS_10059	16240	N	N	N	1	CUSTOMER ISSUE	-
DMS_10060	16241	N	N	N	1	CUSTOMER ISSUE	-
DMS_10061	16242	N	N	N	1	CUSTOMER ISSUE	-
DMS_10062	16243	N	N	N	1	CUSTOMER ISSUE	-
DMS_10063	16244	N	N	N	1	CUSTOMER ISSUE	-
DMS_10064	16245	N	N	N	1	CUSTOMER ISSUE	-
DMS_10065	16246	N	N	N	1	CUSTOMER ISSUE	-
DMS_10066	16247	N	N	N	1	CUSTOMER ISSUE	-
DMS_10067	16248	N	N	N	1	CUSTOMER ISSUE	-
DMS_10068	16249	N	N	N	1	CUSTOMER ISSUE	-
DMS_10069	16250	N	N	N	1	CUSTOMER ISSUE	-
DMS_10070	16251	N	N	N	1	CUSTOMER ISSUE	-
DMS_10071	16252	N	N	N	1	CUSTOMER ISSUE	-
DMS_10072	16253	N	N	N	1	CUSTOMER ISSUE	-
DMS_10073	16254	N	N	N	1	CUSTOMER ISSUE	-
DMS_10074	16255	N	N	N	1	CUSTOMER ISSUE	-
DMS_10075	16256	N	N	N	1	CUSTOMER ISSUE	-
DMS_10076	16257	N	N	N	1	CUSTOMER ISSUE	-
DMS_10077	16258	N	N	N	1	CUSTOMER ISSUE	-
DMS_10078	16259	N	N	N	1	CUSTOMER ISSUE	-
DMS_10079	16260	N	N	N	1	CUSTOMER ISSUE	-
DMS_10080	16261	N	N	N	1	CUSTOMER ISSUE	-
DMS_10081	16262	N	N	N	1	CUSTOMER ISSUE	-
DMS_10082	16263	N	N	N	1	CUSTOMER ISSUE	-
DMS_10083	16264	N	N	N	1	CUSTOMER ISSUE	-
DMS_10084	16265	N	N	N	1	CUSTOMER ISSUE	-
DMS_10085	16266	N	N	N	1	CUSTOMER ISSUE	-
DMS_10086	16267	N	N	N	1	CUSTOMER ISSUE	-
DMS_10087	16268	N	N	N	1	CUSTOMER ISSUE	-
DMS_10088	16269	N	N	N	1	CUSTOMER ISSUE	-
DMS_10089	16270	N	N	N	1	CUSTOMER ISSUE	-
DMS_10090	16271	N	N	N	1	CUSTOMER ISSUE	-
DMS_10091	16272	N	N	N	1	CUSTOMER ISSUE	-
DMS_10092	16273	N	N	N	1	CUSTOMER ISSUE	-
DMS_10093	16274	N	N	N	1	CUSTOMER ISSUE	-
DMS_10094	16275	N	N	N	1	CUSTOMER ISSUE	-
DMS_10095	16276	N	N	N	1	CUSTOMER ISSUE	-
DMS_10096	16277	N	N	N	1	CUSTOMER ISSUE	-
DMS_10097	16278	N	N	N	1	CUSTOMER ISSUE	-
DMS_10098	16279	N	N	N	1	CUSTOMER ISSUE	-
DMS_10099	16280	N	N	N	1	CUSTOMER ISSUE	-
DMS_10100	16281	N	N	N	1	CUSTOMER ISSUE	-
DMS_10101	16282	N	N	N	1	CUSTOMER ISSUE	-
DMS_10102	16283	N	N	N	1	CUSTOMER ISSUE	-
DMS_10103	16284	N	N	N	1	CUSTOMER ISSUE	-
DMS_10104	16285	N	N	N	1	CUSTOMER ISSUE	-
DMS_10105	16286	N	N	N	1	CUSTOMER ISSUE	-
DMS_10106	16287	N	N	N	1	CUSTOMER ISSUE	-
DMS_10107	16288	N	N	N	1	CUSTOMER ISSUE	-
DMS_10108	16289	N	N	N	1	CUSTOMER ISSUE	-
DMS_10109	16290	N	N	N	1	CUSTOMER ISSUE	-
DMS_10110	16291	N	N	N	1	CUSTOMER ISSUE	-
DMS_10111	16292	N	N	N	1	CUSTOMER ISSUE	-
DMS_10112	16293	N	N	N	1	CUSTOMER ISSUE	-
DMS_10113	16294	N	N	N	1	CUSTOMER ISSUE	-
DMS_10114	16295	N	N	N	1	CUSTOMER ISSUE	-
DMS_10115	16296	N	N	N	1	CUSTOMER ISSUE	-

DMS_10116	16297	N	N	N	1	CUSTOMER ISSUE	-
DMS_10117	16298	N	N	N	1	CUSTOMER ISSUE	-
DMS_10118	16299	N	N	N	1	CUSTOMER ISSUE	-
DMS_10119	16300	N	N	N	1	CUSTOMER ISSUE	-
DMS_10120	16301	N	N	N	1	CUSTOMER ISSUE	-
DMS_10121	16302	N	N	N	1	CUSTOMER ISSUE	-
DMS_10122	16303	N	N	N	1	CUSTOMER ISSUE	-
DMS_10123	16304	N	N	N	1	CUSTOMER ISSUE	-
DMS_10124	16305	N	N	N	1	CUSTOMER ISSUE	-
DMS_10125	16306	N	N	N	1	CUSTOMER ISSUE	-
DMS_10126	16307	N	N	N	1	CUSTOMER ISSUE	-
DMS_10127	16308	N	N	N	1	CUSTOMER ISSUE	-
DMS_10128	16309	N	N	N	1	CUSTOMER ISSUE	-
DMS_10129	16310	N	N	N	1	CUSTOMER ISSUE	-
DMS_10130	16311	N	N	N	1	CUSTOMER ISSUE	-
DMS_10131	16312	N	N	N	1	CUSTOMER ISSUE	-
DMS_10132	16313	N	N	N	1	CUSTOMER ISSUE	-
DMS_10133	16314	N	N	N	1	CUSTOMER ISSUE	-
DMS_10134	16315	N	N	N	1	CUSTOMER ISSUE	-
DMS_10135	16316	N	N	N	1	CUSTOMER ISSUE	-
DMS_10136	16317	N	N	N	1	CUSTOMER ISSUE	-
DMS_10137	16318	N	N	N	1	CUSTOMER ISSUE	-
DMS_10138	16319	N	N	N	1	CUSTOMER ISSUE	-
DMS_10139	16320	N	N	N	1	CUSTOMER ISSUE	-
DMS_10140	16321	N	N	N	1	CUSTOMER ISSUE	-
DMS_10141	16322	N	N	N	1	CUSTOMER ISSUE	-
DMS_10142	16323	N	N	N	1	CUSTOMER ISSUE	-
DMS_10143	16324	N	N	N	1	CUSTOMER ISSUE	-
DMS_10144	16325	N	N	N	1	CUSTOMER ISSUE	-
DMS_10145	16326	N	N	N	1	CUSTOMER ISSUE	-
DMS_10146	16327	N	N	N	1	CUSTOMER ISSUE	-
DMS_10147	16328	N	N	N	1	CUSTOMER ISSUE	-
DMS_10148	16329	N	N	N	1	CUSTOMER ISSUE	-
DMS_10149	16330	N	N	N	1	CUSTOMER ISSUE	-
DMS_10150	16331	N	N	N	1	CUSTOMER ISSUE	-
DMS_10151	16332	N	N	N	1	CUSTOMER ISSUE	-
DMS_10152	16333	N	N	N	1	CUSTOMER ISSUE	-
DMS_10153	16334	N	N	N	1	CUSTOMER ISSUE	-
DMS_10154	16335	N	N	N	1	CUSTOMER ISSUE	-
DMS_10155	16336	N	N	N	1	CUSTOMER ISSUE	-
DMS_10156	16337	N	N	N	1	CUSTOMER ISSUE	-
DMS_10157	16338	N	N	N	1	CUSTOMER ISSUE	-
DMS_10158	16339	N	N	N	1	CUSTOMER ISSUE	-
DMS_10159	16340	N	N	N	1	CUSTOMER ISSUE	-
DMS_10160	16341	N	N	N	1	CUSTOMER ISSUE	-
DMS_10161	16342	N	N	N	1	CUSTOMER ISSUE	-
DMS_10162	16343	N	N	N	1	CUSTOMER ISSUE	-
DMS_10163	16344	N	N	N	1	CUSTOMER ISSUE	-
DMS_10164	16345	N	N	N	1	CUSTOMER ISSUE	-
DMS_10165	16346	N	N	N	3	CUSTOMER ISSUE	-
DMS_10166	16347	N	N	N	2	CUSTOMER ISSUE	-
DMS_10167	16348	N	N	N	1	CUSTOMER ISSUE	-
DMS_10169	16349	N	N	N	1	CUSTOMER ISSUE	-
DMS_10170	16350	N	N	N	1	CUSTOMER ISSUE	-
DMS_10171	16351	N	N	N	1	CUSTOMER ISSUE	-
DMS_10172	16352	N	N	N	1	CUSTOMER ISSUE	-
DMS_10173	16353	N	N	N	1	CUSTOMER ISSUE	-
DMS_10174	16354	N	N	N	1	CUSTOMER ISSUE	-
DMS_10175	16355	N	N	N	1	CUSTOMER ISSUE	-
DMS_10176	16356	N	N	N	1	CUSTOMER ISSUE	-
DMS_10177	16357	N	N	N	1	CUSTOMER ISSUE	-
DMS_10178	16358	N	N	N	1	CUSTOMER ISSUE	-
DMS_10179	16359	N	N	N	1	CUSTOMER ISSUE	-
DMS_10180	16360	N	N	N	1	CUSTOMER ISSUE	-
DMS_10181	16361	N	N	N	1	CUSTOMER ISSUE	-
DMS_10182	16362	N	N	N	1	CUSTOMER ISSUE	-
DMS_10183	16363	N	N	N	1	CUSTOMER ISSUE	-
DMS_10184	16364	N	N	N	1	CUSTOMER ISSUE	-
DMS_10185	16365	N	N	N	1	CUSTOMER ISSUE	-
DMS_10186	16366	N	N	N	1	CUSTOMER ISSUE	-
DMS_10187	16367	N	N	N	1	CUSTOMER ISSUE	-
DMS_10188	16368	N	N	N	1	CUSTOMER ISSUE	-
DMS_10189	16369	N	N	N	1	CUSTOMER ISSUE	-
DMS_10190	16370	N	N	N	1	CUSTOMER ISSUE	-
DMS_10191	16371	N	N	N	1	CUSTOMER ISSUE	-
DMS_10192	16372	N	N	N	2	CUSTOMER ISSUE	-
DMS_10193	16373	N	N	N	1	CUSTOMER ISSUE	-
DMS_10194	16374	N	N	N	1	CUSTOMER ISSUE	-
DMS_10195	16375	N	N	N	1	CUSTOMER ISSUE	-
DMS_10196	16376	N	N	N	1	CUSTOMER ISSUE	-

DMS_10197	16377	N	N	N	1	CUSTOMER ISSUE	-
DMS_10198	16378	N	N	N	1	CUSTOMER ISSUE	-
DMS_10199	16379	N	N	N	1	CUSTOMER ISSUE	-
DMS_10200	16380	N	N	N	1	CUSTOMER ISSUE	-
DMS_10201	16381	N	N	N	1	CUSTOMER ISSUE	-
DMS_10202	16382	N	N	N	1	CUSTOMER ISSUE	-
DMS_10203	16383	N	N	N	1	CUSTOMER ISSUE	-
DMS_10204	16384	N	N	N	1	CUSTOMER ISSUE	-
DMS_10205	16385	N	N	N	1	CUSTOMER ISSUE	-
DMS_10206	16386	N	N	N	1	CUSTOMER ISSUE	-
DMS_10207	16387	N	N	N	1	CUSTOMER ISSUE	-
DMS_10208	16388	N	N	N	1	CUSTOMER ISSUE	-
DMS_10209	16389	N	N	N	1	CUSTOMER ISSUE	-
DMS_10210	16390	N	N	N	1	CUSTOMER ISSUE	-
DMS_10211	16391	N	N	N	1	CUSTOMER ISSUE	-
DMS_10212	16392	N	N	N	1	CUSTOMER ISSUE	-
DMS_10213	16393	N	N	N	1	CUSTOMER ISSUE	-
DMS_10214	16394	N	N	N	1	CUSTOMER ISSUE	-
DMS_10215	16395	N	N	N	1	CUSTOMER ISSUE	-
DMS_10216	16396	N	N	N	1	CUSTOMER ISSUE	-
DMS_10217	16397	N	N	N	1	CUSTOMER ISSUE	-
DMS_10218	16398	N	N	N	1	CUSTOMER ISSUE	-
DMS_10219	16399	N	N	N	1	CUSTOMER ISSUE	-
DMS_10220	16400	N	N	N	1	CUSTOMER ISSUE	-
DMS_10221	16401	N	N	N	1	CUSTOMER ISSUE	-
DMS_10222	16402	N	N	N	1	CUSTOMER ISSUE	-
DMS_10223	16403	N	N	N	1	CUSTOMER ISSUE	-
DMS_10224	16404	N	N	N	1	CUSTOMER ISSUE	-
DMS_10225	16405	N	N	N	1	CUSTOMER ISSUE	-
DMS_10226	16406	N	N	N	1	CUSTOMER ISSUE	-
DMS_10227	16407	N	N	N	1	CUSTOMER ISSUE	-
DMS_10228	16408	N	N	N	1	CUSTOMER ISSUE	-
DMS_10229	16409	N	N	N	1	CUSTOMER ISSUE	-
DMS_10230	16410	N	N	N	1	CUSTOMER ISSUE	-
DMS_10231	16411	N	N	N	1	CUSTOMER ISSUE	-
DMS_10232	16412	N	N	N	1	CUSTOMER ISSUE	-
DMS_10233	16413	N	N	N	1	CUSTOMER ISSUE	-
DMS_10234	16414	N	N	N	1	CUSTOMER ISSUE	-
DMS_10235	16415	N	N	N	1	CUSTOMER ISSUE	-
DMS_10236	16416	N	N	N	1	CUSTOMER ISSUE	-
DMS_10237	16417	N	N	N	1	CUSTOMER ISSUE	-
DMS_10238	16418	N	N	N	1	CUSTOMER ISSUE	-
DMS_10239	16419	N	N	N	1	CUSTOMER ISSUE	-
DMS_10240	16420	N	N	N	1	CUSTOMER ISSUE	-
DMS_10241	16421	N	N	N	1	CUSTOMER ISSUE	-
DMS_10242	16422	N	N	N	1	CUSTOMER ISSUE	-
DMS_10243	16423	N	N	N	1	CUSTOMER ISSUE	-
DMS_10244	16424	N	N	N	1	CUSTOMER ISSUE	-
DMS_10245	16425	N	N	N	1	CUSTOMER ISSUE	-
DMS_10246	16426	N	N	N	1	CUSTOMER ISSUE	-
DMS_10247	16427	N	N	N	1	CUSTOMER ISSUE	-
DMS_10248	16428	N	N	N	1	CUSTOMER ISSUE	-
DMS_10249	16429	N	N	N	1	CUSTOMER ISSUE	-
DMS_10250	16430	N	N	N	1	CUSTOMER ISSUE	-
DMS_10251	16431	N	N	N	1	CUSTOMER ISSUE	-
DMS_10252	16432	N	N	N	1	CUSTOMER ISSUE	-
DMS_10253	16433	N	N	N	1	CUSTOMER ISSUE	-
DMS_10254	16434	N	N	N	1	CUSTOMER ISSUE	-
DMS_10255	16435	N	N	N	1	CUSTOMER ISSUE	-
DMS_10256	16436	N	N	N	1	CUSTOMER ISSUE	-
DMS_10257	16437	N	N	N	1	CUSTOMER ISSUE	-
DMS_10258	16438	N	N	N	1	CUSTOMER ISSUE	-
DMS_10259	16439	N	N	N	1	CUSTOMER ISSUE	-
DMS_10260	16440	N	N	N	1	CUSTOMER ISSUE	-
DMS_10261	16441	N	N	N	1	CUSTOMER ISSUE	-
DMS_10262	16442	N	N	N	1	CUSTOMER ISSUE	-
DMS_10263	16443	N	N	N	1	CUSTOMER ISSUE	-
DMS_10264	16444	N	N	N	1	CUSTOMER ISSUE	-
DMS_10265	16445	N	N	N	1	CUSTOMER ISSUE	-
DMS_10266	16446	N	N	N	1	CUSTOMER ISSUE	-
DMS_10267	16447	N	N	N	1	CUSTOMER ISSUE	-
DMS_10268	16448	N	N	N	1	CUSTOMER ISSUE	-
DMS_10269	16449	N	N	N	1	CUSTOMER ISSUE	-
DMS_10270	16450	N	N	N	1	CUSTOMER ISSUE	-
DMS_10271	16451	N	N	N	1	CUSTOMER ISSUE	-
DMS_10272	16452	N	N	N	1	CUSTOMER ISSUE	-
DMS_10273	16453	N	N	N	1	CUSTOMER ISSUE	-
DMS_10274	16454	N	N	N	1	CUSTOMER ISSUE	-
DMS_10275	16455	N	N	N	1	CUSTOMER ISSUE	-
DMS_10276	16456	N	N	N	1	CUSTOMER ISSUE	-

DMS_10277	16457	N	N	N	1	CUSTOMER ISSUE	-
DMS_10278	16458	N	N	N	1	CUSTOMER ISSUE	-
DMS_10279	16459	N	N	N	1	CUSTOMER ISSUE	-
DMS_10280	16460	N	N	N	1	CUSTOMER ISSUE	-
DMS_10281	16461	N	N	N	1	CUSTOMER ISSUE	-
DMS_10282	16462	N	N	N	1	CUSTOMER ISSUE	-
DMS_10283	16463	N	N	N	1	CUSTOMER ISSUE	-
DMS_10284	16464	N	N	N	1	CUSTOMER ISSUE	-
DMS_10285	16465	N	N	N	1	CUSTOMER ISSUE	-
DMS_10286	16466	N	N	N	1	CUSTOMER ISSUE	-
DMS_10287	16467	N	N	N	1	CUSTOMER ISSUE	-
DMS_10288	16468	N	N	N	1	CUSTOMER ISSUE	-
DMS_10289	16469	N	N	N	1	CUSTOMER ISSUE	-
DMS_10290	16470	N	N	N	1	CUSTOMER ISSUE	-
DMS_10291	16471	N	N	N	1	CUSTOMER ISSUE	-
DMS_10292	16472	N	N	N	1	CUSTOMER ISSUE	-
DMS_10293	16473	N	N	N	1	CUSTOMER ISSUE	-
DMS_10294	16474	N	N	N	1	CUSTOMER ISSUE	-
DMS_10295	16475	N	N	N	1	CUSTOMER ISSUE	-
DMS_10296	16476	N	N	N	1	CUSTOMER ISSUE	-
DMS_10297	16477	N	N	N	1	CUSTOMER ISSUE	-
DMS_10298	16478	N	N	N	1	CUSTOMER ISSUE	-
DMS_10299	16479	N	N	N	1	CUSTOMER ISSUE	-
DMS_10300	16480	N	N	N	1	CUSTOMER ISSUE	-
DMS_10301	16481	N	N	N	1	CUSTOMER ISSUE	-
DMS_10302	16482	N	N	N	1	CUSTOMER ISSUE	-
DMS_10303	16483	N	N	N	1	CUSTOMER ISSUE	-
DMS_10304	16484	N	N	N	1	CUSTOMER ISSUE	-
DMS_10305	16485	N	N	N	1	CUSTOMER ISSUE	-
DMS_10306	16486	N	N	N	1	CUSTOMER ISSUE	-
DMS_10307	16487	N	N	N	1	CUSTOMER ISSUE	-
DMS_10308	16488	N	N	N	1	CUSTOMER ISSUE	-
DMS_10309	16489	N	N	N	1	CUSTOMER ISSUE	-
DMS_10310	16490	N	N	N	1	CUSTOMER ISSUE	-
DMS_10311	16491	N	N	N	1	CUSTOMER ISSUE	-
DMS_10312	16492	N	N	N	1	CUSTOMER ISSUE	-
DMS_10313	16493	N	N	N	1	CUSTOMER ISSUE	-
DMS_10314	16494	N	N	N	1	CUSTOMER ISSUE	-
DMS_10315	16495	N	N	N	1	CUSTOMER ISSUE	-
DMS_10316	16496	N	N	N	1	CUSTOMER ISSUE	-
DMS_10317	16497	N	N	N	1	CUSTOMER ISSUE	-
DMS_10318	16498	N	N	N	1	CUSTOMER ISSUE	-
DMS_10319	16499	N	N	N	1	CUSTOMER ISSUE	-
DMS_10320	16500	N	N	N	1	CUSTOMER ISSUE	-
DMS_10321	16501	N	N	N	1	CUSTOMER ISSUE	-
DMS_10322	16502	N	N	N	1	CUSTOMER ISSUE	-
DMS_10323	16503	N	N	N	1	CUSTOMER ISSUE	-
DMS_10324	16504	N	N	N	1	CUSTOMER ISSUE	-
DMS_10325	16505	N	N	N	1	CUSTOMER ISSUE	-
DMS_10326	16506	N	N	N	1	CUSTOMER ISSUE	-
DMS_10327	16507	N	N	N	1	CUSTOMER ISSUE	-
DMS_10328	16508	N	N	N	1	CUSTOMER ISSUE	-
DMS_10329	16509	N	N	N	1	CUSTOMER ISSUE	-
DMS_10330	16510	N	N	N	1	CUSTOMER ISSUE	-
DMS_10331	16511	N	N	N	1	CUSTOMER ISSUE	-
DMS_10332	16512	N	N	N	1	CUSTOMER ISSUE	-
DMS_10333	16513	N	N	N	1	CUSTOMER ISSUE	-
DMS_10334	16514	N	N	N	1	CUSTOMER ISSUE	-
DMS_10335	16515	N	N	N	1	CUSTOMER ISSUE	-
DMS_10336	16516	N	N	N	1	CUSTOMER ISSUE	-
DMS_10337	16517	N	N	N	1	CUSTOMER ISSUE	-
DMS_10338	16518	N	N	N	1	CUSTOMER ISSUE	-
DMS_10339	16519	N	N	N	1	CUSTOMER ISSUE	-
DMS_10340	16520	N	N	N	1	CUSTOMER ISSUE	-
DMS_10341	16521	N	N	N	1	CUSTOMER ISSUE	-
DMS_10342	16522	N	N	N	1	CUSTOMER ISSUE	-
DMS_10343	16523	N	N	N	1	CUSTOMER ISSUE	-
DMS_10344	16524	N	N	N	1	CUSTOMER ISSUE	-
DMS_10345	16525	N	N	N	1	CUSTOMER ISSUE	-
DMS_10346	16526	N	N	N	1	CUSTOMER ISSUE	-
DMS_10347	16527	N	N	N	1	CUSTOMER ISSUE	-
DMS_10348	16528	N	N	N	1	CUSTOMER ISSUE	-
DMS_10349	16529	N	N	N	1	CUSTOMER ISSUE	-
DMS_10350	16530	N	N	N	1	CUSTOMER ISSUE	-
DMS_10351	16531	N	N	N	1	CUSTOMER ISSUE	-
DMS_10352	16532	N	N	N	1	CUSTOMER ISSUE	-
DMS_10353	16533	N	N	N	1	CUSTOMER ISSUE	-
DMS_10354	16534	N	N	N	1	CUSTOMER ISSUE	-
DMS_10355	16535	N	N	N	1	CUSTOMER ISSUE	-
DMS_10356	16536	N	N	N	1	CUSTOMER ISSUE	-

DMS_10357	16537	N	N	N	1	CUSTOMER ISSUE	-
DMS_10358	16538	N	N	N	1	CUSTOMER ISSUE	-
DMS_10359	16539	N	N	N	1	CUSTOMER ISSUE	-
DMS_10360	16540	N	N	N	1	CUSTOMER ISSUE	-
DMS_10361	16541	N	N	N	1	CUSTOMER ISSUE	-
DMS_10362	16542	N	N	N	1	CUSTOMER ISSUE	-
DMS_10363	16543	N	N	N	1	CUSTOMER ISSUE	-
DMS_10364	16544	N	N	N	1	CUSTOMER ISSUE	-
DMS_10365	16545	N	N	N	1	CUSTOMER ISSUE	-
DMS_10366	16546	N	N	N	1	CUSTOMER ISSUE	-
DMS_10367	16547	N	N	N	1	CUSTOMER ISSUE	-
DMS_10368	16548	N	N	N	1	CUSTOMER ISSUE	-
DMS_10369	16549	N	N	N	1	CUSTOMER ISSUE	-
DMS_10370	16550	N	N	N	1	CUSTOMER ISSUE	-
DMS_10371	16551	N	N	N	1	CUSTOMER ISSUE	-
DMS_10372	16552	N	N	N	1	CUSTOMER ISSUE	-
DMS_10373	16553	N	N	N	1	CUSTOMER ISSUE	-
DMS_10374	16554	N	N	N	1	CUSTOMER ISSUE	-
DMS_10375	16555	N	N	N	1	CUSTOMER ISSUE	-
DMS_10376	16556	N	N	N	1	CUSTOMER ISSUE	-
DMS_10377	16557	N	N	N	1	CUSTOMER ISSUE	-
DMS_10378	16558	N	N	N	1	CUSTOMER ISSUE	-
DMS_10379	16559	N	N	N	1	CUSTOMER ISSUE	-
DMS_10380	16560	N	N	N	1	CUSTOMER ISSUE	-
DMS_10381	16561	N	N	N	1	CUSTOMER ISSUE	-
DMS_10382	16562	N	N	N	1	CUSTOMER ISSUE	-
DMS_10383	16563	N	N	N	1	CUSTOMER ISSUE	-
DMS_10384	16564	N	N	N	1	CUSTOMER ISSUE	-
DMS_10385	16565	N	N	N	1	CUSTOMER ISSUE	-
DMS_10386	16566	N	N	N	1	CUSTOMER ISSUE	-
DMS_10387	16567	N	N	N	1	CUSTOMER ISSUE	-
DMS_10388	16568	N	N	N	1	CUSTOMER ISSUE	-
DMS_10389	16569	N	N	N	1	CUSTOMER ISSUE	-
DMS_10390	16570	N	N	N	1	CUSTOMER ISSUE	-
DMS_10391	16571	N	N	N	1	CUSTOMER ISSUE	-
DMS_10392	16572	N	N	N	1	CUSTOMER ISSUE	-
DMS_10393	16573	N	N	N	1	CUSTOMER ISSUE	-
DMS_10394	16574	N	N	N	1	CUSTOMER ISSUE	-
DMS_10395	16575	N	N	N	1	CUSTOMER ISSUE	-
DMS_10396	16576	N	N	N	1	CUSTOMER ISSUE	-
DMS_10397	16577	N	N	N	1	CUSTOMER ISSUE	-
DMS_10398	16578	N	N	N	1	CUSTOMER ISSUE	-
DMS_10399	16579	N	N	N	1	CUSTOMER ISSUE	-
DMS_10400	16580	N	N	N	1	CUSTOMER ISSUE	-
DMS_10401	16581	N	N	N	1	CUSTOMER ISSUE	-
DMS_10402	16582	N	N	N	1	CUSTOMER ISSUE	-
DMS_10403	16583	N	N	N	1	CUSTOMER ISSUE	-
DMS_10405	16584	N	N	N	1	CUSTOMER ISSUE	-
DMS_10406	16585	N	N	N	1	CUSTOMER ISSUE	-
DMS_10407	16586	N	N	N	1	CUSTOMER ISSUE	-
DMS_10408	16587	N	N	N	1	CUSTOMER ISSUE	-
DMS_10409	16588	N	N	N	1	CUSTOMER ISSUE	-
DMS_10410	16589	N	N	N	1	CUSTOMER ISSUE	-
DMS_10411	16590	N	N	N	2	CUSTOMER ISSUE	-
DMS_10412	16591	N	N	N	1	CUSTOMER ISSUE	-
DMS_10413	16592	N	N	N	1	CUSTOMER ISSUE	-
DMS_10414	16593	N	N	N	1	CUSTOMER ISSUE	-
DMS_10415	16594	N	N	N	1	CUSTOMER ISSUE	-
DMS_10416	16595	N	N	N	1	CUSTOMER ISSUE	-
DMS_10417	16596	N	N	N	1	CUSTOMER ISSUE	-
DMS_10418	16597	N	N	N	1	CUSTOMER ISSUE	-
DMS_10419	16598	N	N	N	1	CUSTOMER ISSUE	-
DMS_10420	16599	N	N	N	1	CUSTOMER ISSUE	-
DMS_10421	16600	N	N	N	1	CUSTOMER ISSUE	-
DMS_10422	16601	N	N	N	1	CUSTOMER ISSUE	-
DMS_10423	16602	N	N	N	1	CUSTOMER ISSUE	-
DMS_10424	16603	N	N	N	1	CUSTOMER ISSUE	-
DMS_10425	16604	N	N	N	1	CUSTOMER ISSUE	-
DMS_10426	16605	N	N	N	1	CUSTOMER ISSUE	-
DMS_10427	16606	N	N	N	1	CUSTOMER ISSUE	-
DMS_10428	16607	N	N	N	1	CUSTOMER ISSUE	-
DMS_10429	16608	N	N	N	1	CUSTOMER ISSUE	-
DMS_10430	16609	N	N	N	1	CUSTOMER ISSUE	-
DMS_10431	16610	N	N	N	1	CUSTOMER ISSUE	-
DMS_10432	16611	N	N	N	1	CUSTOMER ISSUE	-
DMS_10433	16612	N	N	N	1	CUSTOMER ISSUE	-
DMS_10434	16613	N	N	N	1	CUSTOMER ISSUE	-
DMS_10435	16614	N	N	N	1	CUSTOMER ISSUE	-
DMS_10436	16615	N	N	N	1	CUSTOMER ISSUE	-
DMS_10437	16616	N	N	N	1	CUSTOMER ISSUE	-

DMS_10438	16617	N	N	N	1	CUSTOMER ISSUE	-
DMS_10439	16618	N	N	N	1	CUSTOMER ISSUE	-
DMS_10440	16619	N	N	N	1	CUSTOMER ISSUE	-
DMS_10441	16620	N	N	N	1	CUSTOMER ISSUE	-
DMS_10442	16621	N	N	N	1	CUSTOMER ISSUE	-
DMS_10443	16622	N	N	N	1	CUSTOMER ISSUE	-
DMS_10444	16623	N	N	N	1	CUSTOMER ISSUE	-
DMS_10445	16624	N	N	N	1	CUSTOMER ISSUE	-
DMS_10446	16625	N	N	N	1	CUSTOMER ISSUE	-
DMS_10447	16626	N	N	N	1	CUSTOMER ISSUE	-
DMS_10448	16627	N	N	N	1	CUSTOMER ISSUE	-
DMS_10449	16628	N	N	N	1	CUSTOMER ISSUE	-
DMS_10450	16629	N	N	N	1	CUSTOMER ISSUE	-
DMS_10451	16630	N	N	N	1	CUSTOMER ISSUE	-
DMS_10452	16631	N	N	N	1	CUSTOMER ISSUE	-
DMS_10453	16632	N	N	N	1	CUSTOMER ISSUE	-
DMS_10454	16633	N	N	N	1	CUSTOMER ISSUE	-
DMS_10455	16634	N	N	N	1	CUSTOMER ISSUE	-
DMS_10456	16635	N	N	N	1	CUSTOMER ISSUE	-
DMS_10457	16636	N	N	N	1	CUSTOMER ISSUE	-
DMS_10458	16637	N	N	N	1	CUSTOMER ISSUE	-
DMS_10459	16638	N	N	N	1	CUSTOMER ISSUE	-
DMS_10460	16639	N	N	N	1	CUSTOMER ISSUE	-
DMS_10461	16640	N	N	N	1	CUSTOMER ISSUE	-
DMS_10462	16641	N	N	N	1	CUSTOMER ISSUE	-
DMS_10463	16642	N	N	N	1	CUSTOMER ISSUE	-
DMS_10464	16643	N	N	N	1	CUSTOMER ISSUE	-
DMS_10465	16644	N	N	N	1	CUSTOMER ISSUE	-
DMS_10466	16645	N	N	N	1	CUSTOMER ISSUE	-
DMS_10467	16646	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_10468	16647	N	N	N	1	CUSTOMER ISSUE	-
DMS_10469	16648	N	N	N	1	CUSTOMER ISSUE	-
DMS_10470	16649	N	N	N	1	CUSTOMER ISSUE	-
DMS_10471	16650	N	N	N	1	CUSTOMER ISSUE	-
DMS_10472	16651	N	N	N	1	CUSTOMER ISSUE	-
DMS_10473	16652	N	N	N	1	CUSTOMER ISSUE	-
DMS_10474	16653	N	N	N	1	CUSTOMER ISSUE	-
DMS_10475	16654	N	N	N	1	CUSTOMER ISSUE	-
DMS_10476	16655	N	N	N	1	CUSTOMER ISSUE	-
DMS_10477	16656	N	N	N	1	CUSTOMER ISSUE	-
DMS_10478	16657	N	N	N	1	CUSTOMER ISSUE	-
DMS_10479	16658	N	N	N	1	CUSTOMER ISSUE	-
DMS_10480	16659	N	N	N	1	CUSTOMER ISSUE	-
DMS_10481	16660	N	N	N	2	CUSTOMER ISSUE	-
DMS_10482	16661	N	N	N	1	CUSTOMER ISSUE	-
DMS_10483	16662	N	N	N	1	CUSTOMER ISSUE	-
DMS_10484	16663	N	N	N	1	CUSTOMER ISSUE	-
DMS_10485	16664	N	N	N	1	CUSTOMER ISSUE	-
DMS_10486	16665	N	N	N	1	CUSTOMER ISSUE	-
DMS_10487	16666	N	N	N	1	CUSTOMER ISSUE	-
DMS_10488	16667	N	N	N	1	CUSTOMER ISSUE	-
DMS_10489	16668	N	N	N	1	CUSTOMER ISSUE	-
DMS_10490	16669	N	N	N	1	CUSTOMER ISSUE	-
DMS_10491	16670	N	N	N	1	CUSTOMER ISSUE	-
DMS_10492	16671	N	N	N	1	CUSTOMER ISSUE	-
DMS_10493	16672	N	N	N	1	CUSTOMER ISSUE	-
DMS_10494	16673	N	N	N	1	CUSTOMER ISSUE	-
DMS_10495	16674	N	N	N	1	CUSTOMER ISSUE	-
DMS_10496	16675	N	N	N	1	CUSTOMER ISSUE	-
DMS_10497	16676	N	N	N	1	CUSTOMER ISSUE	-
DMS_10498	16677	N	N	N	1	CUSTOMER ISSUE	-
DMS_10499	16678	N	N	N	1	CUSTOMER ISSUE	-
DMS_10500	16679	N	N	N	1	CUSTOMER ISSUE	-
DMS_10501	16680	N	N	N	1	CUSTOMER ISSUE	-
DMS_10502	16681	N	N	N	1	CUSTOMER ISSUE	-
DMS_10503	16682	N	N	N	1	CUSTOMER ISSUE	-
DMS_10504	16683	N	N	N	1	CUSTOMER ISSUE	-
DMS_10505	16684	N	N	N	1	CUSTOMER ISSUE	-
DMS_10506	16685	N	N	N	1	CUSTOMER ISSUE	-
DMS_10507	16686	N	N	N	1	CUSTOMER ISSUE	-
DMS_10508	16687	N	N	N	1	CUSTOMER ISSUE	-
DMS_10509	16688	N	N	N	1	CUSTOMER ISSUE	-
DMS_10510	16689	N	N	N	1	CUSTOMER ISSUE	-
DMS_10511	16690	N	N	N	1	CUSTOMER ISSUE	-
DMS_10512	16691	N	N	N	1	CUSTOMER ISSUE	-
DMS_10513	16692	N	N	N	1	CUSTOMER ISSUE	-
DMS_10514	16693	N	N	N	1	CUSTOMER ISSUE	-
DMS_10515	16694	N	N	N	1	CUSTOMER ISSUE	-
DMS_10516	16695	N	N	N	1	CUSTOMER ISSUE	-
DMS_10517	16696	N	N	N	1	CUSTOMER ISSUE	-

DMS_10518	16697	N	N	N	1	CUSTOMER ISSUE	-
DMS_10519	16698	N	N	N	1	CUSTOMER ISSUE	-
DMS_10520	16699	N	N	N	1	CUSTOMER ISSUE	-
DMS_10521	16700	N	N	N	1	CUSTOMER ISSUE	-
DMS_10522	16701	N	N	N	1	CUSTOMER ISSUE	-
DMS_10523	16702	N	N	N	1	CUSTOMER ISSUE	-
DMS_10524	16703	N	N	N	1	CUSTOMER ISSUE	-
DMS_10525	16704	N	N	N	1	CUSTOMER ISSUE	-
DMS_10526	16705	N	N	N	1	CUSTOMER ISSUE	-
DMS_10527	16706	N	N	N	1	CUSTOMER ISSUE	-
DMS_10528	16707	N	N	N	1	CUSTOMER ISSUE	-
DMS_10529	16708	N	N	N	1	CUSTOMER ISSUE	-
DMS_10530	16709	N	N	N	1	CUSTOMER ISSUE	-
DMS_10531	16710	N	N	N	1	CUSTOMER ISSUE	-
DMS_10532	16711	N	N	N	1	CUSTOMER ISSUE	-
DMS_10533	16712	N	N	N	1	CUSTOMER ISSUE	-
DMS_10534	16713	N	N	N	1	CUSTOMER ISSUE	-
DMS_10535	16714	N	N	N	1	CUSTOMER ISSUE	-
DMS_10536	16715	N	N	N	1	CUSTOMER ISSUE	-
DMS_10537	16716	N	N	N	1	CUSTOMER ISSUE	-
DMS_10538	16717	N	N	N	1	CUSTOMER ISSUE	-
DMS_10539	16718	N	N	N	1	CUSTOMER ISSUE	-
DMS_10540	16719	N	N	N	1	CUSTOMER ISSUE	-
DMS_10541	16720	N	N	N	1	CUSTOMER ISSUE	-
DMS_10542	16721	N	N	N	1	CUSTOMER ISSUE	-
DMS_10543	16722	N	N	N	1	CUSTOMER ISSUE	-
DMS_10544	16723	N	N	N	1	CUSTOMER ISSUE	-
DMS_10545	16724	N	N	N	1	CUSTOMER ISSUE	-
DMS_10546	16725	N	N	N	1	CUSTOMER ISSUE	-
DMS_10547	16726	N	N	N	1	CUSTOMER ISSUE	-
DMS_10548	16727	N	N	N	1	CUSTOMER ISSUE	-
DMS_10549	16728	N	N	N	1	CUSTOMER ISSUE	-
DMS_10550	16729	N	N	N	1	CUSTOMER ISSUE	-
DMS_10551	16730	N	N	N	1	CUSTOMER ISSUE	-
DMS_10552	16731	N	N	N	1	CUSTOMER ISSUE	-
DMS_10553	16732	N	N	N	1	CUSTOMER ISSUE	-
DMS_10554	16733	N	N	N	1	CUSTOMER ISSUE	-
DMS_10555	16734	N	N	N	1	CUSTOMER ISSUE	-
DMS_10556	16735	N	N	N	1	CUSTOMER ISSUE	-
DMS_10557	16736	N	N	N	1	CUSTOMER ISSUE	-
DMS_10558	16737	N	N	N	1	CUSTOMER ISSUE	-
DMS_10559	16738	N	N	N	1	CUSTOMER ISSUE	-
DMS_10560	16739	N	N	N	1	CUSTOMER ISSUE	-
DMS_10561	16740	N	N	N	1	CUSTOMER ISSUE	-
DMS_10562	16741	N	N	N	1	CUSTOMER ISSUE	-
DMS_10563	16742	N	N	N	1	CUSTOMER ISSUE	-
DMS_10564	16743	N	N	N	1	CUSTOMER ISSUE	-
DMS_10565	16744	N	N	N	1	CUSTOMER ISSUE	-
DMS_10566	16745	N	N	N	1	CUSTOMER ISSUE	-
DMS_10567	16746	N	N	N	1	CUSTOMER ISSUE	-
DMS_10568	16747	N	N	N	1	CUSTOMER ISSUE	-
DMS_10569	16748	N	N	N	1	CUSTOMER ISSUE	-
DMS_10570	16749	N	N	N	1	CUSTOMER ISSUE	-
DMS_10571	16750	N	N	N	1	CUSTOMER ISSUE	-
DMS_10572	16751	N	N	N	1	CUSTOMER ISSUE	-
DMS_10573	16752	N	N	N	1	CUSTOMER ISSUE	-
DMS_10574	16753	N	N	N	1	CUSTOMER ISSUE	-
DMS_10575	16754	N	N	N	1	CUSTOMER ISSUE	-
DMS_10576	16755	N	N	N	1	CUSTOMER ISSUE	-
DMS_10577	16756	N	N	N	1	CUSTOMER ISSUE	-
DMS_10578	16757	N	N	N	1	CUSTOMER ISSUE	-
DMS_10579	16758	N	N	N	1	CUSTOMER ISSUE	-
DMS_10580	16759	N	N	N	1	CUSTOMER ISSUE	-
DMS_10581	16760	N	N	N	1	CUSTOMER ISSUE	-
DMS_10582	16761	N	N	N	1	CUSTOMER ISSUE	-
DMS_10583	16762	N	N	N	1	CUSTOMER ISSUE	-
DMS_10584	16763	N	N	N	1	CUSTOMER ISSUE	-
DMS_10585	16764	N	N	N	1	CUSTOMER ISSUE	-
DMS_10586	16765	N	N	N	1	CUSTOMER ISSUE	-
DMS_10587	16766	N	N	N	1	CUSTOMER ISSUE	-
DMS_10588	16767	N	N	N	1	CUSTOMER ISSUE	-
DMS_10589	16768	N	N	N	1	CUSTOMER ISSUE	-
DMS_10590	16769	N	N	N	1	CUSTOMER ISSUE	-
DMS_10591	16770	N	N	N	1	CUSTOMER ISSUE	-
DMS_10592	16771	N	N	N	1	CUSTOMER ISSUE	-
DMS_10593	16772	N	N	N	1	CUSTOMER ISSUE	-
DMS_10594	16773	N	N	N	1	CUSTOMER ISSUE	-
DMS_10595	16774	N	N	N	1	CUSTOMER ISSUE	-
DMS_10596	16775	N	N	N	1	CUSTOMER ISSUE	-
DMS_10597	16776	N	N	N	1	CUSTOMER ISSUE	-

DMS_10598	16777	N	N	N	1	CUSTOMER ISSUE	-
DMS_10599	16778	N	N	N	1	CUSTOMER ISSUE	-
DMS_10600	16779	N	N	N	1	CUSTOMER ISSUE	-
DMS_10601	16780	N	N	N	1	CUSTOMER ISSUE	-
DMS_10602	16781	N	N	N	1	CUSTOMER ISSUE	-
DMS_10603	16782	N	N	N	1	CUSTOMER ISSUE	-
DMS_10604	16783	N	N	N	1	CUSTOMER ISSUE	-
DMS_10605	16784	N	N	N	1	CUSTOMER ISSUE	-
DMS_10606	16785	N	N	N	1	CUSTOMER ISSUE	-
DMS_10607	16786	N	N	N	1	CUSTOMER ISSUE	-
DMS_10608	16787	N	N	N	1	CUSTOMER ISSUE	-
DMS_10609	16788	N	N	N	1	CUSTOMER ISSUE	-
DMS_10610	16789	N	N	N	1	CUSTOMER ISSUE	-
DMS_10611	16790	N	N	N	1	CUSTOMER ISSUE	-
DMS_10612	16791	N	N	N	1	CUSTOMER ISSUE	-
DMS_10613	16792	N	N	N	1	CUSTOMER ISSUE	-
DMS_10614	16793	N	N	N	1	CUSTOMER ISSUE	-
DMS_10615	16794	N	N	N	1	CUSTOMER ISSUE	-
DMS_10616	16795	N	N	N	1	CUSTOMER ISSUE	-
DMS_10617	16796	N	N	N	1	CUSTOMER ISSUE	-
DMS_10618	16797	N	N	N	1	CUSTOMER ISSUE	-
DMS_10619	16798	N	N	N	1	CUSTOMER ISSUE	-
DMS_10620	16799	N	N	N	1	CUSTOMER ISSUE	-
DMS_10621	16800	N	N	N	1	CUSTOMER ISSUE	-
DMS_10622	16801	N	N	N	1	CUSTOMER ISSUE	-
DMS_10623	16802	N	N	N	1	CUSTOMER ISSUE	-
DMS_10624	16803	N	N	N	1	CUSTOMER ISSUE	-
DMS_10625	16804	N	N	N	1	CUSTOMER ISSUE	-
DMS_10626	16805	N	N	N	1	CUSTOMER ISSUE	-
DMS_10627	16806	N	N	N	1	CUSTOMER ISSUE	-
DMS_10628	16807	N	N	N	1	CUSTOMER ISSUE	-
DMS_10629	16808	N	N	N	1	CUSTOMER ISSUE	-
DMS_10630	16809	N	N	N	1	CUSTOMER ISSUE	-
DMS_10631	16810	N	N	N	1	CUSTOMER ISSUE	-
DMS_10632	16811	N	N	N	1	CUSTOMER ISSUE	-
DMS_10633	16812	N	N	N	1	CUSTOMER ISSUE	-
DMS_10634	16813	N	N	N	1	CUSTOMER ISSUE	-
DMS_10635	16814	N	N	N	1	CUSTOMER ISSUE	-
DMS_10636	16815	N	N	N	1	CUSTOMER ISSUE	-
DMS_10637	16816	N	N	N	1	CUSTOMER ISSUE	-
DMS_10638	16817	N	N	N	1	CUSTOMER ISSUE	-
DMS_10639	16818	N	N	N	1	CUSTOMER ISSUE	-
DMS_10640	16819	N	N	N	1	CUSTOMER ISSUE	-
DMS_10641	16820	N	N	N	1	CUSTOMER ISSUE	-
DMS_10642	16821	N	N	N	1	CUSTOMER ISSUE	-
DMS_10643	16822	N	N	N	1	CUSTOMER ISSUE	-
DMS_10644	16823	N	N	N	1	CUSTOMER ISSUE	-
DMS_10645	16824	N	N	N	1	CUSTOMER ISSUE	-
DMS_10646	16825	N	N	N	1	CUSTOMER ISSUE	-
DMS_10647	16826	N	N	N	1	CUSTOMER ISSUE	-
DMS_10648	16827	N	N	N	1	CUSTOMER ISSUE	-
DMS_10649	16828	N	N	N	1	CUSTOMER ISSUE	-
DMS_10650	16829	N	N	N	1	CUSTOMER ISSUE	-
DMS_10651	16830	N	N	N	1	CUSTOMER ISSUE	-
DMS_10652	16831	N	N	N	1	CUSTOMER ISSUE	-
DMS_10653	16832	N	N	N	1	CUSTOMER ISSUE	-
DMS_10654	16833	N	N	N	1	CUSTOMER ISSUE	-
DMS_10655	16834	N	N	N	1	CUSTOMER ISSUE	-
DMS_10656	16835	N	N	N	1	CUSTOMER ISSUE	-
DMS_10657	16836	N	N	N	1	CUSTOMER ISSUE	-
DMS_10658	16837	N	N	N	1	CUSTOMER ISSUE	-
DMS_10659	16838	N	N	N	1	CUSTOMER ISSUE	-
DMS_10660	16839	N	N	N	1	CUSTOMER ISSUE	-
DMS_10661	16840	N	N	N	1	CUSTOMER ISSUE	-
DMS_10662	16841	N	N	N	1	CUSTOMER ISSUE	-
DMS_10663	16842	N	N	N	1	CUSTOMER ISSUE	-
DMS_10664	16843	N	N	N	1	CUSTOMER ISSUE	-
DMS_10665	16844	N	N	N	1	CUSTOMER ISSUE	-
DMS_10666	16845	N	N	N	1	CUSTOMER ISSUE	-
DMS_10667	16846	N	N	N	1	CUSTOMER ISSUE	-
DMS_10668	16847	N	N	N	1	CUSTOMER ISSUE	-
DMS_10669	16848	N	N	N	1	CUSTOMER ISSUE	-
DMS_10670	16849	N	N	N	1	CUSTOMER ISSUE	-
DMS_10671	16850	N	N	N	1	CUSTOMER ISSUE	-
DMS_10672	16851	N	N	N	1	CUSTOMER ISSUE	-
DMS_10673	16852	N	N	N	1	CUSTOMER ISSUE	-
DMS_10674	16853	N	N	N	1	CUSTOMER ISSUE	-
DMS_10675	16854	N	N	N	1	CUSTOMER ISSUE	-
DMS_10676	16855	N	N	N	1	CUSTOMER ISSUE	-
DMS_10677	16856	N	N	N	1	CUSTOMER ISSUE	-

DMS_10678	16857	N	N	N	1	CUSTOMER ISSUE	-
DMS_10679	16858	N	N	N	1	CUSTOMER ISSUE	-
DMS_10680	16859	N	N	N	1	CUSTOMER ISSUE	-
DMS_10681	16860	N	N	N	1	CUSTOMER ISSUE	-
DMS_10682	16861	N	N	N	1	CUSTOMER ISSUE	-
DMS_10683	16862	N	N	N	1	CUSTOMER ISSUE	-
DMS_10684	16863	N	N	N	1	CUSTOMER ISSUE	-
DMS_10685	16864	N	N	N	1	CUSTOMER ISSUE	-
DMS_10686	16865	N	N	N	1	CUSTOMER ISSUE	-
DMS_10687	16866	N	N	N	1	CUSTOMER ISSUE	-
DMS_10688	16867	N	N	N	1	CUSTOMER ISSUE	-
DMS_10689	16868	N	N	N	1	CUSTOMER ISSUE	-
DMS_10690	16869	N	N	N	1	CUSTOMER ISSUE	-
DMS_10691	16870	N	N	N	1	CUSTOMER ISSUE	-
DMS_10692	16871	N	N	N	1	CUSTOMER ISSUE	-
DMS_10693	16872	N	N	N	1	CUSTOMER ISSUE	-
DMS_10694	16873	N	N	N	1	CUSTOMER ISSUE	-
DMS_10695	16874	N	N	N	1	CUSTOMER ISSUE	-
DMS_10696	16875	N	N	N	1	CUSTOMER ISSUE	-
DMS_10697	16876	N	N	N	1	CUSTOMER ISSUE	-
DMS_10698	16877	N	N	N	1	CUSTOMER ISSUE	-
DMS_10699	16878	N	N	N	1	CUSTOMER ISSUE	-
DMS_10700	16879	N	N	N	1	CUSTOMER ISSUE	-
DMS_10701	16880	N	N	N	1	CUSTOMER ISSUE	-
DMS_10702	16881	N	N	N	1	CUSTOMER ISSUE	-
DMS_10703	16882	N	N	N	1	CUSTOMER ISSUE	-
DMS_10704	16883	N	N	N	1	CUSTOMER ISSUE	-
DMS_10705	16884	N	N	N	1	CUSTOMER ISSUE	-
DMS_10706	16885	N	N	N	1	CUSTOMER ISSUE	-
DMS_10707	16886	N	N	N	1	CUSTOMER ISSUE	-
DMS_10708	16887	N	N	N	1	CUSTOMER ISSUE	-
DMS_10709	16888	N	N	N	1	CUSTOMER ISSUE	-
DMS_10710	16889	N	N	N	1	CUSTOMER ISSUE	-
DMS_10711	16890	N	N	N	1	CUSTOMER ISSUE	-
DMS_10712	16891	N	N	N	1	CUSTOMER ISSUE	-
DMS_10713	16892	N	N	N	1	CUSTOMER ISSUE	-
DMS_10714	16893	N	N	N	1	CUSTOMER ISSUE	-
DMS_10715	16894	N	N	N	1	CUSTOMER ISSUE	-
DMS_10716	16895	N	N	N	1	CUSTOMER ISSUE	-
DMS_10717	16896	N	N	N	1	CUSTOMER ISSUE	-
DMS_10718	16897	N	N	N	2	CUSTOMER ISSUE	-
DMS_10719	16898	N	N	N	1	CUSTOMER ISSUE	-
DMS_10720	16899	N	N	N	1	CUSTOMER ISSUE	-
DMS_10721	16900	N	N	N	1	CUSTOMER ISSUE	-
DMS_10722	16901	N	N	N	1	CUSTOMER ISSUE	-
DMS_10723	16902	N	N	N	1	CUSTOMER ISSUE	-
DMS_10724	16903	N	N	N	1	CUSTOMER ISSUE	-
DMS_10725	16904	N	N	N	1	CUSTOMER ISSUE	-
DMS_10726	16905	N	N	N	1	CUSTOMER ISSUE	-
DMS_10727	16906	N	N	N	1	CUSTOMER ISSUE	-
DMS_10728	16907	N	N	N	1	CUSTOMER ISSUE	-
DMS_10729	16908	N	N	N	1	CUSTOMER ISSUE	-
DMS_10730	16909	N	N	N	1	CUSTOMER ISSUE	-
DMS_10731	16910	N	N	N	1	CUSTOMER ISSUE	-
DMS_10732	16911	N	N	N	1	CUSTOMER ISSUE	-
DMS_10733	16912	N	N	N	1	CUSTOMER ISSUE	-
DMS_10734	16913	N	N	N	1	CUSTOMER ISSUE	-
DMS_10735	16914	N	N	N	1	CUSTOMER ISSUE	-
DMS_10736	16915	N	N	N	1	CUSTOMER ISSUE	-
DMS_10737	16916	N	N	N	1	CUSTOMER ISSUE	-
DMS_10738	16917	N	N	N	1	CUSTOMER ISSUE	-
DMS_10739	16918	N	N	N	1	CUSTOMER ISSUE	-
DMS_10740	16919	N	N	N	1	CUSTOMER ISSUE	-
DMS_10741	16920	N	N	N	1	CUSTOMER ISSUE	-
DMS_10742	16921	N	N	N	1	CUSTOMER ISSUE	-
DMS_10743	16922	N	N	N	1	CUSTOMER ISSUE	-
DMS_10744	16923	N	N	N	1	CUSTOMER ISSUE	-
DMS_10745	16924	N	N	N	1	CUSTOMER ISSUE	-
DMS_10746	16925	N	N	N	1	CUSTOMER ISSUE	-
DMS_10747	16926	N	N	N	1	CUSTOMER ISSUE	-
DMS_10748	16927	N	N	N	1	CUSTOMER ISSUE	-
DMS_10749	16928	N	N	N	1	CUSTOMER ISSUE	-
DMS_10750	16929	N	N	N	1	CUSTOMER ISSUE	-
DMS_10751	16930	N	N	N	1	CUSTOMER ISSUE	-
DMS_10752	16931	N	N	N	1	CUSTOMER ISSUE	-
DMS_10753	16932	N	N	N	1	CUSTOMER ISSUE	-
DMS_10754	16933	N	N	N	1	CUSTOMER ISSUE	-
DMS_10755	16934	N	N	N	1	CUSTOMER ISSUE	-
DMS_10756	16935	N	N	N	1	CUSTOMER ISSUE	-
DMS_10757	16936	N	N	N	1	CUSTOMER ISSUE	-

DMS_10758	16937	N	N	N	1	CUSTOMER ISSUE	-
DMS_10759	16938	N	N	N	1	CUSTOMER ISSUE	-
DMS_10760	16939	N	N	N	1	CUSTOMER ISSUE	-
DMS_10761	16940	N	N	N	1	CUSTOMER ISSUE	-
DMS_10762	16941	N	N	N	1	CUSTOMER ISSUE	-
DMS_10763	16942	N	N	N	1	CUSTOMER ISSUE	-
DMS_10764	16943	N	N	N	1	CUSTOMER ISSUE	-
DMS_10765	16944	N	N	N	1	CUSTOMER ISSUE	-
DMS_10766	16945	N	N	N	1	CUSTOMER ISSUE	-
DMS_10767	16946	N	N	N	2	CUSTOMER ISSUE	-
DMS_10768	16947	N	N	N	1	CUSTOMER ISSUE	-
DMS_10769	16948	N	N	N	1	CUSTOMER ISSUE	-
DMS_10770	16949	N	N	N	1	CUSTOMER ISSUE	-
DMS_10771	16950	N	N	N	1	CUSTOMER ISSUE	-
DMS_10772	16951	N	N	N	1	CUSTOMER ISSUE	-
DMS_10773	16952	N	N	N	1	CUSTOMER ISSUE	-
DMS_10774	16953	N	N	N	1	CUSTOMER ISSUE	-
DMS_10775	16954	N	N	N	1	CUSTOMER ISSUE	-
DMS_10776	16955	N	N	N	1	CUSTOMER ISSUE	-
DMS_10777	16956	N	N	N	1	CUSTOMER ISSUE	-
DMS_10778	16957	N	N	N	1	CUSTOMER ISSUE	-
DMS_10779	16958	N	N	N	1	CUSTOMER ISSUE	-
DMS_10780	16959	N	N	N	1	CUSTOMER ISSUE	-
DMS_10781	16960	N	N	N	1	CUSTOMER ISSUE	-
DMS_10782	16961	N	N	N	1	CUSTOMER ISSUE	-
DMS_10783	16962	N	N	N	1	CUSTOMER ISSUE	-
DMS_10784	16963	N	N	N	1	CUSTOMER ISSUE	-
DMS_10785	16964	N	N	N	1	CUSTOMER ISSUE	-
DMS_10786	16965	N	N	N	1	CUSTOMER ISSUE	-
DMS_10787	16966	N	N	N	1	CUSTOMER ISSUE	-
DMS_10788	16967	N	N	N	1	CUSTOMER ISSUE	-
DMS_10789	16968	N	N	N	1	CUSTOMER ISSUE	-
DMS_10790	16969	N	N	N	1	CUSTOMER ISSUE	-
DMS_10791	16970	N	N	N	1	CUSTOMER ISSUE	-
DMS_10792	16971	N	N	N	1	CUSTOMER ISSUE	-
DMS_10793	16972	N	N	N	1	CUSTOMER ISSUE	-
DMS_10794	16973	N	N	N	1	CUSTOMER ISSUE	-
DMS_10795	16974	N	N	N	1	CUSTOMER ISSUE	-
DMS_10797	16975	N	N	N	1	CUSTOMER ISSUE	-
DMS_10798	16976	N	N	N	1	CUSTOMER ISSUE	-
DMS_10799	16977	N	N	N	1	CUSTOMER ISSUE	-
DMS_10800	16978	N	N	N	1	CUSTOMER ISSUE	-
DMS_10801	16979	N	N	N	1	CUSTOMER ISSUE	-
DMS_10802	16980	N	N	N	1	CUSTOMER ISSUE	-
DMS_10803	16981	N	N	N	1	CUSTOMER ISSUE	-
DMS_10804	16982	N	N	N	1	CUSTOMER ISSUE	-
DMS_10806	16983	N	N	N	1	CUSTOMER ISSUE	-
DMS_10807	16984	N	N	N	1	CUSTOMER ISSUE	-
DMS_10808	16985	N	N	N	1	CUSTOMER ISSUE	-
DMS_10810	16986	N	N	N	1	CUSTOMER ISSUE	-
DMS_10811	16987	N	N	N	1	CUSTOMER ISSUE	-
DMS_10812	16988	N	N	N	1	CUSTOMER ISSUE	-
DMS_10813	16989	N	N	N	1	CUSTOMER ISSUE	-
DMS_10814	16990	N	N	N	1	CUSTOMER ISSUE	-
DMS_10815	16991	N	N	N	1	CUSTOMER ISSUE	-
DMS_10816	16992	N	N	N	1	CUSTOMER ISSUE	-
DMS_10817	16993	N	N	N	1	CUSTOMER ISSUE	-
DMS_10818	16994	N	N	N	1	CUSTOMER ISSUE	-
DMS_10819	16995	N	N	N	1	CUSTOMER ISSUE	-
DMS_10820	16996	N	N	N	1	CUSTOMER ISSUE	-
DMS_10821	16997	N	N	N	1	CUSTOMER ISSUE	-
DMS_10822	16998	N	N	N	1	CUSTOMER ISSUE	-
DMS_10823	16999	N	N	N	1	CUSTOMER ISSUE	-
DMS_10824	17000	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_10825	17001	N	N	N	1	CUSTOMER ISSUE	-
DMS_10826	17002	N	N	N	1	CUSTOMER ISSUE	-
DMS_10827	17003	N	N	N	2	CUSTOMER ISSUE	-
DMS_10828	17004	N	N	N	1	CUSTOMER ISSUE	-
DMS_10829	17005	N	N	N	1	CUSTOMER ISSUE	-
DMS_10830	17006	N	N	N	1	CUSTOMER ISSUE	-
DMS_10831	17007	N	N	N	1	CUSTOMER ISSUE	-
DMS_10832	17008	N	N	N	1	CUSTOMER ISSUE	-
DMS_10833	17009	N	N	N	1	CUSTOMER ISSUE	-
DMS_10834	17010	N	N	N	1	CUSTOMER ISSUE	-
DMS_10835	17011	N	N	N	1	CUSTOMER ISSUE	-
DMS_10836	17012	N	N	N	1	CUSTOMER ISSUE	-
DMS_10837	17013	N	N	N	2	CUSTOMER ISSUE	-
DMS_10838	17014	N	N	N	1	CUSTOMER ISSUE	-
DMS_10839	17015	N	N	N	1	CUSTOMER ISSUE	-
DMS_10840	17016	N	N	N	1	CUSTOMER ISSUE	-

DMS_10841	17017	N	N	N	1	CUSTOMER ISSUE	-
DMS_10842	17018	N	N	N	1	CUSTOMER ISSUE	-
DMS_10843	17019	N	N	N	1	CUSTOMER ISSUE	-
DMS_10844	17020	N	N	N	1	CUSTOMER ISSUE	-
DMS_10845	17021	N	N	N	1	CUSTOMER ISSUE	-
DMS_10846	17022	N	N	N	1	CUSTOMER ISSUE	-
DMS_10847	17023	N	N	N	1	CUSTOMER ISSUE	-
DMS_10848	17024	N	N	N	1	CUSTOMER ISSUE	-
DMS_10849	17025	N	N	N	1	CUSTOMER ISSUE	-
DMS_10850	17026	N	N	N	1	CUSTOMER ISSUE	-
DMS_10851	17027	N	N	N	1	CUSTOMER ISSUE	-
DMS_10852	17028	N	N	N	1	CUSTOMER ISSUE	-
DMS_10853	17029	N	N	N	1	CUSTOMER ISSUE	-
DMS_10854	17030	N	N	N	1	CUSTOMER ISSUE	-
DMS_10855	17031	N	N	N	1	CUSTOMER ISSUE	-
DMS_10856	17032	N	N	N	1	CUSTOMER ISSUE	-
DMS_10857	17033	N	N	N	1	CUSTOMER ISSUE	-
DMS_10858	17034	N	N	N	1	CUSTOMER ISSUE	-
DMS_10859	17035	N	N	N	1	CUSTOMER ISSUE	-
DMS_10860	17036	N	N	N	1	CUSTOMER ISSUE	-
DMS_10861	17037	N	N	N	1	CUSTOMER ISSUE	-
DMS_10862	17038	N	N	N	1	CUSTOMER ISSUE	-
DMS_10863	17039	N	N	N	1	CUSTOMER ISSUE	-
DMS_10864	17040	N	N	N	1	CUSTOMER ISSUE	-
DMS_10865	17041	N	N	N	1	CUSTOMER ISSUE	-
DMS_10866	17042	N	N	N	1	CUSTOMER ISSUE	-
DMS_10867	17043	N	N	N	1	CUSTOMER ISSUE	-
DMS_10868	17044	N	N	N	1	CUSTOMER ISSUE	-
DMS_10869	17045	N	N	N	1	CUSTOMER ISSUE	-
DMS_10870	17046	N	N	N	1	CUSTOMER ISSUE	-
DMS_10871	17047	N	N	N	1	CUSTOMER ISSUE	-
DMS_10873	17048	N	N	N	1	CUSTOMER ISSUE	-
DMS_10874	17049	N	N	N	1	CUSTOMER ISSUE	-
DMS_10875	17050	N	N	N	1	CUSTOMER ISSUE	-
DMS_10876	17051	N	N	N	1	CUSTOMER ISSUE	-
DMS_10877	17052	N	N	N	1	CUSTOMER ISSUE	-
DMS_10878	17053	N	N	N	1	CUSTOMER ISSUE	-
DMS_10879	17054	N	N	N	1	CUSTOMER ISSUE	-
DMS_10880	17055	N	N	N	1	CUSTOMER ISSUE	-
DMS_10881	17056	N	N	N	1	CUSTOMER ISSUE	-
DMS_10882	17057	N	N	N	1	CUSTOMER ISSUE	-
DMS_10883	17058	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_10884	17059	N	N	N	1	CUSTOMER ISSUE	-
DMS_10885	17060	N	N	N	1	CUSTOMER ISSUE	-
DMS_10886	17061	N	N	N	1	CUSTOMER ISSUE	-
DMS_10887	17062	N	N	N	1	CUSTOMER ISSUE	-
DMS_10888	17063	N	N	N	1	CUSTOMER ISSUE	-
DMS_10889	17064	N	N	N	1	CUSTOMER ISSUE	-
DMS_10890	17065	N	N	N	1	CUSTOMER ISSUE	-
DMS_10891	17066	N	N	N	1	CUSTOMER ISSUE	-
DMS_10892	17067	N	N	N	1	CUSTOMER ISSUE	-
DMS_10893	17068	N	N	N	1	CUSTOMER ISSUE	-
DMS_10894	17069	N	N	N	1	CUSTOMER ISSUE	-
DMS_10895	17070	N	N	N	1	CUSTOMER ISSUE	-
DMS_10896	17071	N	N	N	1	CUSTOMER ISSUE	-
DMS_10897	17072	N	N	N	1	CUSTOMER ISSUE	-
DMS_10898	17073	N	N	N	1	CUSTOMER ISSUE	-
DMS_10899	17074	N	N	N	1	CUSTOMER ISSUE	-
DMS_10900	17075	N	N	N	1	CUSTOMER ISSUE	-
DMS_10901	17076	N	N	N	1	CUSTOMER ISSUE	-
DMS_10902	17077	N	N	N	1	CUSTOMER ISSUE	-
DMS_10903	17078	N	N	N	1	CUSTOMER ISSUE	-
DMS_10904	17079	N	N	N	1	CUSTOMER ISSUE	-
DMS_10905	17080	N	N	N	1	CUSTOMER ISSUE	-
DMS_10906	17081	N	N	N	1	CUSTOMER ISSUE	-
DMS_10907	17082	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_10908	17083	N	N	N	1	CUSTOMER ISSUE	-
DMS_10909	17084	N	N	N	1	CUSTOMER ISSUE	-
DMS_10910	17085	N	N	N	1	CUSTOMER ISSUE	-
DMS_10911	17086	N	N	N	1	CUSTOMER ISSUE	-
DMS_10912	17087	N	N	N	1	CUSTOMER ISSUE	-
DMS_10913	17088	N	N	N	1	CUSTOMER ISSUE	-
DMS_10914	17089	N	N	N	1	CUSTOMER ISSUE	-
DMS_10915	17090	N	N	N	1	CUSTOMER ISSUE	-
DMS_10916	17091	N	N	N	1	CUSTOMER ISSUE	-
DMS_10917	17092	N	N	N	1	CUSTOMER ISSUE	-
DMS_10918	17093	N	N	N	1	CUSTOMER ISSUE	-
DMS_10919	17094	N	N	N	1	CUSTOMER ISSUE	-
DMS_10920	17095	N	N	N	1	CUSTOMER ISSUE	-
DMS_10921	17096	N	N	N	1	CUSTOMER ISSUE	-

DMS_10922	17097	N	N	N	1	CUSTOMER ISSUE	-
DMS_10928	17098	N	N	N	1	CUSTOMER ISSUE	-
DMS_10934	17099	N	N	N	1	CUSTOMER ISSUE	-
DMS_10936	17100	N	N	N	1	CUSTOMER ISSUE	-
DMS_10937	17101	N	N	N	1	CUSTOMER ISSUE	-
DMS_10938	17102	N	N	N	1	CUSTOMER ISSUE	-
DMS_10940	17103	N	N	N	1	CUSTOMER ISSUE	-
DMS_10941	17104	N	N	N	1	CUSTOMER ISSUE	-
DMS_10942	17105	N	N	N	1	CUSTOMER ISSUE	-
DMS_10943	17106	N	N	N	1	CUSTOMER ISSUE	-
DMS_10944	17107	N	N	N	1	CUSTOMER ISSUE	-
DMS_10945	17108	N	N	N	1	CUSTOMER ISSUE	-
DMS_10947	17109	N	N	N	1	CUSTOMER ISSUE	-
DMS_10948	17110	N	N	N	1	CUSTOMER ISSUE	-
DMS_10949	17111	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_10950	17112	N	N	N	1	CUSTOMER ISSUE	-
DMS_10951	17113	N	N	N	1	CUSTOMER ISSUE	-
DMS_10952	17114	N	N	N	1	CUSTOMER ISSUE	-
DMS_10953	17115	N	N	N	1	CUSTOMER ISSUE	-
DMS_10955	17116	N	N	N	1	CUSTOMER ISSUE	-
DMS_10956	17117	N	N	N	1	CUSTOMER ISSUE	-
DMS_10957	17118	N	N	N	1	CUSTOMER ISSUE	-
DMS_10958	17119	N	N	N	1	CUSTOMER ISSUE	-
DMS_10959	17120	N	N	N	1	CUSTOMER ISSUE	-
DMS_10960	17121	N	N	N	1	CUSTOMER ISSUE	-
DMS_10961	17122	N	N	N	1	CUSTOMER ISSUE	-
DMS_10962	17123	N	N	N	1	CUSTOMER ISSUE	-
DMS_10963	17124	N	N	N	1	CUSTOMER ISSUE	-
DMS_10964	17125	N	N	N	1	CUSTOMER ISSUE	-
DMS_10965	17126	N	N	N	1	CUSTOMER ISSUE	-
DMS_10966	17127	N	N	N	1	CUSTOMER ISSUE	-
DMS_10967	17128	N	N	N	1	CUSTOMER ISSUE	-
DMS_10968	17129	N	N	N	1	CUSTOMER ISSUE	-
DMS_10969	17130	N	N	N	1	CUSTOMER ISSUE	-
DMS_10970	17131	N	N	N	1	CUSTOMER ISSUE	-
DMS_10971	17132	N	N	N	1	CUSTOMER ISSUE	-
DMS_10972	17133	N	N	N	1	CUSTOMER ISSUE	-
DMS_10973	17134	N	N	N	1	CUSTOMER ISSUE	-
DMS_10974	17135	N	N	N	1	CUSTOMER ISSUE	-
DMS_10975	17136	N	N	N	1	CUSTOMER ISSUE	-
DMS_10976	17137	N	N	N	1	CUSTOMER ISSUE	-
DMS_10977	17138	N	N	N	2	CUSTOMER ISSUE	-
DMS_10978	17139	N	N	N	2	CUSTOMER ISSUE	-
DMS_10979	17140	N	N	N	1	CUSTOMER ISSUE	-
DMS_10980	17141	N	N	N	1	CUSTOMER ISSUE	-
DMS_10981	17142	N	N	N	1	CUSTOMER ISSUE	-
DMS_10982	17143	N	N	N	1	CUSTOMER ISSUE	-
DMS_10983	17144	N	N	N	1	CUSTOMER ISSUE	-
DMS_10984	17145	N	N	N	1	CUSTOMER ISSUE	-
DMS_10985	17146	N	N	N	1	CUSTOMER ISSUE	-
DMS_10986	17147	N	N	N	1	CUSTOMER ISSUE	-
DMS_10987	17148	N	N	N	1	CUSTOMER ISSUE	-
DMS_10988	17149	N	N	N	1	CUSTOMER ISSUE	-
DMS_10989	17150	N	N	N	1	CUSTOMER ISSUE	-
DMS_10990	17151	N	N	N	1	CUSTOMER ISSUE	-
DMS_10991	17152	N	N	N	1	CUSTOMER ISSUE	-
DMS_10992	17153	N	N	N	2	CUSTOMER ISSUE	-
DMS_10993	17154	N	N	N	1	CUSTOMER ISSUE	-
DMS_10994	17155	N	N	N	1	CUSTOMER ISSUE	-
DMS_10995	17156	N	N	N	1	CUSTOMER ISSUE	-
DMS_10996	17157	N	N	N	1	CUSTOMER ISSUE	-
DMS_10997	17158	N	N	N	1	CUSTOMER ISSUE	-
DMS_10998	17159	N	N	N	1	CUSTOMER ISSUE	-
DMS_10999	17160	N	N	N	1	CUSTOMER ISSUE	-
DMS_11000	17161	N	N	N	1	CUSTOMER ISSUE	-
DMS_11001	17162	N	N	N	1	CUSTOMER ISSUE	-
DMS_11002	17163	N	N	N	1	CUSTOMER ISSUE	-
DMS_11003	17164	N	N	N	1	CUSTOMER ISSUE	-
DMS_11004	17165	N	N	N	1	CUSTOMER ISSUE	-
DMS_11005	17166	N	N	N	1	CUSTOMER ISSUE	-
DMS_11006	17167	N	N	N	1	CUSTOMER ISSUE	-
DMS_11007	17168	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11008	17169	N	N	N	1	CUSTOMER ISSUE	-
DMS_11009	17170	N	N	N	1	CUSTOMER ISSUE	-
DMS_11010	17171	N	N	N	1	CUSTOMER ISSUE	-
DMS_11011	17172	N	N	N	1	CUSTOMER ISSUE	-
DMS_11012	17173	N	N	N	1	CUSTOMER ISSUE	-
DMS_11013	17174	N	N	N	1	CUSTOMER ISSUE	-
DMS_11014	17175	N	N	N	1	CUSTOMER ISSUE	-
DMS_11015	17176	N	N	N	1	CUSTOMER ISSUE	-

DMS_11016	17177	N	N	N	1	CUSTOMER ISSUE	-
DMS_11017	17178	N	N	N	1	CUSTOMER ISSUE	-
DMS_11018	17179	N	N	N	1	CUSTOMER ISSUE	-
DMS_11019	17180	N	N	N	1	CUSTOMER ISSUE	-
DMS_11020	17181	N	N	N	1	CUSTOMER ISSUE	-
DMS_11021	17182	N	N	N	1	CUSTOMER ISSUE	-
DMS_11023	17183	N	N	N	1	CUSTOMER ISSUE	-
DMS_11024	17184	N	N	N	1	CUSTOMER ISSUE	-
DMS_11025	17185	N	N	N	1	CUSTOMER ISSUE	-
DMS_11026	17186	N	N	N	1	CUSTOMER ISSUE	-
DMS_11027	17187	N	N	N	1	CUSTOMER ISSUE	-
DMS_11028	17188	N	N	N	1	CUSTOMER ISSUE	-
DMS_11029	17189	N	N	N	1	CUSTOMER ISSUE	-
DMS_11030	17190	N	N	N	1	CUSTOMER ISSUE	-
DMS_11031	17191	N	N	N	1	CUSTOMER ISSUE	-
DMS_11032	17192	N	N	N	1	CUSTOMER ISSUE	-
DMS_11033	17193	N	N	N	1	CUSTOMER ISSUE	-
DMS_11034	17194	N	N	N	1	CUSTOMER ISSUE	-
DMS_11035	17195	N	N	N	1	CUSTOMER ISSUE	-
DMS_11036	17196	N	N	N	1	CUSTOMER ISSUE	-
DMS_11037	17197	N	N	N	1	CUSTOMER ISSUE	-
DMS_11038	17198	N	N	N	1	CUSTOMER ISSUE	-
DMS_11039	17199	N	N	N	1	CUSTOMER ISSUE	-
DMS_11040	17200	N	N	N	1	CUSTOMER ISSUE	-
DMS_11041	17201	N	N	N	1	CUSTOMER ISSUE	-
DMS_11042	17202	N	N	N	1	CUSTOMER ISSUE	-
DMS_11043	17203	N	N	N	1	CUSTOMER ISSUE	-
DMS_11044	17204	N	N	N	1	CUSTOMER ISSUE	-
DMS_11045	17205	N	N	N	1	CUSTOMER ISSUE	-
DMS_11046	17206	N	N	N	1	CUSTOMER ISSUE	-
DMS_11047	17207	N	N	N	1	CUSTOMER ISSUE	-
DMS_11048	17208	N	N	N	1	CUSTOMER ISSUE	-
DMS_11049	17209	N	N	N	1	CUSTOMER ISSUE	-
DMS_11050	17210	N	N	N	1	CUSTOMER ISSUE	-
DMS_11051	17211	N	N	N	1	CUSTOMER ISSUE	-
DMS_11052	17212	N	N	N	1	CUSTOMER ISSUE	-
DMS_11053	17213	N	N	N	1	CUSTOMER ISSUE	-
DMS_11054	17214	N	N	N	1	CUSTOMER ISSUE	-
DMS_11055	17215	N	N	N	1	CUSTOMER ISSUE	-
DMS_11056	17216	N	N	N	1	CUSTOMER ISSUE	-
DMS_11057	17217	N	N	N	1	CUSTOMER ISSUE	-
DMS_11058	17218	N	N	N	1	CUSTOMER ISSUE	-
DMS_11059	17219	N	N	N	1	CUSTOMER ISSUE	-
DMS_11060	17220	N	N	N	1	CUSTOMER ISSUE	-
DMS_11061	17221	N	N	N	1	CUSTOMER ISSUE	-
DMS_11062	17222	N	N	N	1	CUSTOMER ISSUE	-
DMS_11063	17223	N	N	N	1	CUSTOMER ISSUE	-
DMS_11064	17224	N	N	N	1	CUSTOMER ISSUE	-
DMS_11065	17225	N	N	N	1	CUSTOMER ISSUE	-
DMS_11066	17226	N	N	N	1	CUSTOMER ISSUE	-
DMS_11067	17227	N	N	N	1	CUSTOMER ISSUE	-
DMS_11068	17228	N	N	N	1	CUSTOMER ISSUE	-
DMS_11069	17229	N	N	N	1	CUSTOMER ISSUE	-
DMS_11070	17230	N	N	N	1	CUSTOMER ISSUE	-
DMS_11071	17231	N	N	N	1	CUSTOMER ISSUE	-
DMS_11072	17232	N	N	N	1	CUSTOMER ISSUE	-
DMS_11073	17233	N	N	N	1	CUSTOMER ISSUE	-
DMS_11074	17234	N	N	N	1	CUSTOMER ISSUE	-
DMS_11075	17235	N	N	N	1	CUSTOMER ISSUE	-
DMS_11076	17236	N	N	N	1	CUSTOMER ISSUE	-
DMS_11077	17237	N	N	N	1	CUSTOMER ISSUE	-
DMS_11078	17238	N	N	N	1	CUSTOMER ISSUE	-
DMS_11079	17239	N	N	N	1	CUSTOMER ISSUE	-
DMS_11080	17240	N	N	N	1	CUSTOMER ISSUE	-
DMS_11081	17241	N	N	N	1	CUSTOMER ISSUE	-
DMS_11082	17242	N	N	N	1	CUSTOMER ISSUE	-
DMS_11083	17243	N	N	N	1	CUSTOMER ISSUE	-
DMS_11084	17244	N	N	N	1	CUSTOMER ISSUE	-
DMS_11085	17245	N	N	N	1	CUSTOMER ISSUE	-
DMS_11086	17246	N	N	N	1	CUSTOMER ISSUE	-
DMS_11087	17247	N	N	N	1	CUSTOMER ISSUE	-
DMS_11088	17248	N	N	N	1	CUSTOMER ISSUE	-
DMS_11089	17249	N	N	N	1	CUSTOMER ISSUE	-
DMS_11090	17250	N	N	N	1	CUSTOMER ISSUE	-
DMS_11091	17251	N	N	N	1	CUSTOMER ISSUE	-
DMS_11092	17252	N	N	N	1	CUSTOMER ISSUE	-
DMS_11093	17253	N	N	N	1	CUSTOMER ISSUE	-
DMS_11094	17254	N	N	N	1	CUSTOMER ISSUE	-
DMS_11095	17255	N	N	N	1	CUSTOMER ISSUE	-
DMS_11096	17256	N	N	N	1	CUSTOMER ISSUE	-

DMS_11097	17257	N	N	N	1	CUSTOMER ISSUE	-
DMS_11098	17258	N	N	N	1	CUSTOMER ISSUE	-
DMS_11099	17259	N	N	N	1	CUSTOMER ISSUE	-
DMS_11100	17260	N	N	N	1	CUSTOMER ISSUE	-
DMS_11101	17261	N	N	N	1	CUSTOMER ISSUE	-
DMS_11102	17262	N	N	N	1	CUSTOMER ISSUE	-
DMS_11103	17263	N	N	N	1	CUSTOMER ISSUE	-
DMS_11104	17264	N	N	N	1	CUSTOMER ISSUE	-
DMS_11105	17265	N	N	N	1	CUSTOMER ISSUE	-
DMS_11106	17266	N	N	N	1	CUSTOMER ISSUE	-
DMS_11107	17267	N	N	N	1	CUSTOMER ISSUE	-
DMS_11108	17268	N	N	N	1	CUSTOMER ISSUE	-
DMS_11109	17269	N	N	N	1	CUSTOMER ISSUE	-
DMS_11110	17270	N	N	N	1	CUSTOMER ISSUE	-
DMS_11111	17271	N	N	N	1	CUSTOMER ISSUE	-
DMS_11112	17272	N	N	N	1	CUSTOMER ISSUE	-
DMS_11113	17273	N	N	N	1	CUSTOMER ISSUE	-
DMS_11114	17274	N	N	N	1	CUSTOMER ISSUE	-
DMS_11115	17275	N	N	N	1	CUSTOMER ISSUE	-
DMS_11116	17276	N	N	N	1	CUSTOMER ISSUE	-
DMS_11117	17277	N	N	N	1	CUSTOMER ISSUE	-
DMS_11118	17278	N	N	N	1	CUSTOMER ISSUE	-
DMS_11119	17279	N	N	N	1	CUSTOMER ISSUE	-
DMS_11120	17280	N	N	N	1	CUSTOMER ISSUE	-
DMS_11121	17281	N	N	N	1	CUSTOMER ISSUE	-
DMS_11122	17282	N	N	N	1	CUSTOMER ISSUE	-
DMS_11123	17283	N	N	N	1	CUSTOMER ISSUE	-
DMS_11124	17284	N	N	N	1	CUSTOMER ISSUE	-
DMS_11125	17285	N	N	N	1	CUSTOMER ISSUE	-
DMS_11126	17286	N	N	N	1	CUSTOMER ISSUE	-
DMS_11127	17287	N	N	N	1	CUSTOMER ISSUE	-
DMS_11128	17288	N	N	N	1	CUSTOMER ISSUE	-
DMS_11129	17289	N	N	N	1	CUSTOMER ISSUE	-
DMS_11130	17290	N	N	N	1	CUSTOMER ISSUE	-
DMS_11131	17291	N	N	N	1	CUSTOMER ISSUE	-
DMS_11132	17292	N	N	N	1	CUSTOMER ISSUE	-
DMS_11133	17293	N	N	N	1	CUSTOMER ISSUE	-
DMS_11134	17294	N	N	N	1	CUSTOMER ISSUE	-
DMS_11135	17295	N	N	N	1	CUSTOMER ISSUE	-
DMS_11136	17296	N	N	N	1	CUSTOMER ISSUE	-
DMS_11137	17297	N	N	N	1	CUSTOMER ISSUE	-
DMS_11138	17298	N	N	N	1	CUSTOMER ISSUE	-
DMS_11139	17299	N	N	N	1	CUSTOMER ISSUE	-
DMS_11140	17300	N	N	N	1	CUSTOMER ISSUE	-
DMS_11141	17301	N	N	N	1	CUSTOMER ISSUE	-
DMS_11142	17302	N	N	N	1	CUSTOMER ISSUE	-
DMS_11143	17303	N	N	N	1	CUSTOMER ISSUE	-
DMS_11144	17304	N	N	N	1	CUSTOMER ISSUE	-
DMS_11145	17305	N	N	N	1	CUSTOMER ISSUE	-
DMS_11146	17306	N	N	N	1	CUSTOMER ISSUE	-
DMS_11147	17307	N	N	N	1	CUSTOMER ISSUE	-
DMS_11148	17308	N	N	N	1	CUSTOMER ISSUE	-
DMS_11149	17309	N	N	N	1	CUSTOMER ISSUE	-
DMS_11150	17310	N	N	N	1	CUSTOMER ISSUE	-
DMS_11151	17311	N	N	N	1	CUSTOMER ISSUE	-
DMS_11152	17312	N	N	N	1	CUSTOMER ISSUE	-
DMS_11153	17313	N	N	N	1	CUSTOMER ISSUE	-
DMS_11155	17314	N	N	N	1	CUSTOMER ISSUE	-
DMS_11156	17315	N	N	N	1	CUSTOMER ISSUE	-
DMS_11157	17316	N	N	N	1	CUSTOMER ISSUE	-
DMS_11158	17317	N	N	N	1	CUSTOMER ISSUE	-
DMS_11159	17318	N	N	N	1	CUSTOMER ISSUE	-
DMS_11160	17319	N	N	N	1	CUSTOMER ISSUE	-
DMS_11161	17320	N	N	N	1	CUSTOMER ISSUE	-
DMS_11162	17321	N	N	N	1	CUSTOMER ISSUE	-
DMS_11163	17322	N	N	N	1	CUSTOMER ISSUE	-
DMS_11164	17323	N	N	N	1	CUSTOMER ISSUE	-
DMS_11165	17324	N	N	N	1	CUSTOMER ISSUE	-
DMS_11166	17325	N	N	N	1	CUSTOMER ISSUE	-
DMS_11167	17326	N	N	N	1	CUSTOMER ISSUE	-
DMS_11168	17327	N	N	N	1	CUSTOMER ISSUE	-
DMS_11169	17328	N	N	N	1	CUSTOMER ISSUE	-
DMS_11170	17329	N	N	N	1	CUSTOMER ISSUE	-
DMS_11171	17330	N	N	N	1	CUSTOMER ISSUE	-
DMS_11172	17331	N	N	N	1	CUSTOMER ISSUE	-
DMS_11173	17332	N	N	N	1	CUSTOMER ISSUE	-
DMS_11174	17333	N	N	N	1	CUSTOMER ISSUE	-
DMS_11175	17334	N	N	N	1	CUSTOMER ISSUE	-
DMS_11176	17335	N	N	N	1	CUSTOMER ISSUE	-
DMS_11177	17336	N	N	N	1	CUSTOMER ISSUE	-

DMS_11178	17337	N	N	N	1	CUSTOMER ISSUE	-
DMS_11179	17338	N	N	N	1	CUSTOMER ISSUE	-
DMS_11180	17339	N	N	N	1	CUSTOMER ISSUE	-
DMS_11181	17340	N	N	N	1	CUSTOMER ISSUE	-
DMS_11182	17341	N	N	N	1	CUSTOMER ISSUE	-
DMS_11183	17342	N	N	N	1	CUSTOMER ISSUE	-
DMS_11184	17343	N	N	N	1	CUSTOMER ISSUE	-
DMS_11185	17344	N	N	N	1	CUSTOMER ISSUE	-
DMS_11186	17345	N	N	N	1	CUSTOMER ISSUE	-
DMS_11187	17346	N	N	N	1	CUSTOMER ISSUE	-
DMS_11188	17347	N	N	N	1	CUSTOMER ISSUE	-
DMS_11189	17348	N	N	N	1	CUSTOMER ISSUE	-
DMS_11190	17349	N	N	N	1	CUSTOMER ISSUE	-
DMS_11191	17350	N	N	N	1	CUSTOMER ISSUE	-
DMS_11192	17351	N	N	N	1	CUSTOMER ISSUE	-
DMS_11193	17352	N	N	N	1	CUSTOMER ISSUE	-
DMS_11194	17353	N	N	N	1	CUSTOMER ISSUE	-
DMS_11195	17354	N	N	N	1	CUSTOMER ISSUE	-
DMS_11196	17355	N	N	N	1	CUSTOMER ISSUE	-
DMS_11198	17356	N	N	N	1	CUSTOMER ISSUE	-
DMS_11199	17357	N	N	N	1	CUSTOMER ISSUE	-
DMS_11200	17358	N	N	N	1	CUSTOMER ISSUE	-
DMS_11201	17359	N	N	N	1	CUSTOMER ISSUE	-
DMS_11202	17360	N	N	N	1	CUSTOMER ISSUE	-
DMS_11203	17361	N	N	N	1	CUSTOMER ISSUE	-
DMS_11204	17362	N	N	N	1	CUSTOMER ISSUE	-
DMS_11205	17363	N	N	N	1	CUSTOMER ISSUE	-
DMS_11206	17364	N	N	N	1	CUSTOMER ISSUE	-
DMS_11207	17365	N	N	N	1	CUSTOMER ISSUE	-
DMS_11208	17366	N	N	N	1	CUSTOMER ISSUE	-
DMS_11209	17367	N	N	N	1	CUSTOMER ISSUE	-
DMS_11210	17368	N	N	N	1	CUSTOMER ISSUE	-
DMS_11211	17369	N	N	N	1	CUSTOMER ISSUE	-
DMS_11212	17370	N	N	N	1	CUSTOMER ISSUE	-
DMS_11213	17371	N	N	N	1	CUSTOMER ISSUE	-
DMS_11214	17372	N	N	N	1	CUSTOMER ISSUE	-
DMS_11215	17373	N	N	N	1	CUSTOMER ISSUE	-
DMS_11217	17374	N	N	N	1	CUSTOMER ISSUE	-
DMS_11218	17375	N	N	N	1	CUSTOMER ISSUE	-
DMS_11219	17376	N	N	N	1	CUSTOMER ISSUE	-
DMS_11220	17377	N	N	N	1	CUSTOMER ISSUE	-
DMS_11221	17378	N	N	N	1	CUSTOMER ISSUE	-
DMS_11222	17379	N	N	N	1	CUSTOMER ISSUE	-
DMS_11223	17380	N	N	N	1	CUSTOMER ISSUE	-
DMS_11224	17381	N	N	N	1	CUSTOMER ISSUE	-
DMS_11225	17382	N	N	N	1	CUSTOMER ISSUE	-
DMS_11226	17383	N	N	N	1	CUSTOMER ISSUE	-
DMS_11227	17384	N	N	N	1	CUSTOMER ISSUE	-
DMS_11228	17385	N	N	N	1	CUSTOMER ISSUE	-
DMS_11229	17386	N	N	N	1	CUSTOMER ISSUE	-
DMS_11230	17387	N	N	N	1	CUSTOMER ISSUE	-
DMS_11231	17388	N	N	N	1	CUSTOMER ISSUE	-
DMS_11232	17389	N	N	N	1	CUSTOMER ISSUE	-
DMS_11233	17390	N	N	N	1	CUSTOMER ISSUE	-
DMS_11234	17391	N	N	N	1	CUSTOMER ISSUE	-
DMS_11235	17392	N	N	N	1	CUSTOMER ISSUE	-
DMS_11236	17393	N	N	N	1	CUSTOMER ISSUE	-
DMS_11237	17394	N	N	N	1	CUSTOMER ISSUE	-
DMS_11238	17395	N	N	N	1	CUSTOMER ISSUE	-
DMS_11239	17396	N	N	N	1	CUSTOMER ISSUE	-
DMS_11240	17397	N	N	N	1	CUSTOMER ISSUE	-
DMS_11241	17398	N	N	N	1	CUSTOMER ISSUE	-
DMS_11242	17399	N	N	N	1	CUSTOMER ISSUE	-
DMS_11243	17400	N	N	N	1	CUSTOMER ISSUE	-
DMS_11244	17401	N	N	N	1	CUSTOMER ISSUE	-
DMS_11245	17402	N	N	N	1	CUSTOMER ISSUE	-
DMS_11246	17403	N	N	N	1	CUSTOMER ISSUE	-
DMS_11247	17404	N	N	N	1	CUSTOMER ISSUE	-
DMS_11248	17405	N	N	N	1	CUSTOMER ISSUE	-
DMS_11249	17406	N	N	N	1	CUSTOMER ISSUE	-
DMS_11250	17407	N	N	N	1	CUSTOMER ISSUE	-
DMS_11251	17408	N	N	N	1	CUSTOMER ISSUE	-
DMS_11252	17409	N	N	N	1	CUSTOMER ISSUE	-
DMS_11253	17410	N	N	N	1	CUSTOMER ISSUE	-
DMS_11254	17411	N	N	N	1	CUSTOMER ISSUE	-
DMS_11255	17412	N	N	N	1	CUSTOMER ISSUE	-
DMS_11256	17413	N	N	N	1	CUSTOMER ISSUE	-
DMS_11257	17414	N	N	N	1	CUSTOMER ISSUE	-
DMS_11258	17415	N	N	N	1	CUSTOMER ISSUE	-
DMS_11259	17416	N	N	N	1	CUSTOMER ISSUE	-

DMS_11260	17417	N	N	N	1	CUSTOMER ISSUE	-
DMS_11261	17418	N	N	N	1	CUSTOMER ISSUE	-
DMS_11262	17419	N	N	N	1	CUSTOMER ISSUE	-
DMS_11263	17420	N	N	N	1	CUSTOMER ISSUE	-
DMS_11264	17421	N	N	N	1	CUSTOMER ISSUE	-
DMS_11265	17422	N	N	N	1	CUSTOMER ISSUE	-
DMS_11266	17423	N	N	N	1	CUSTOMER ISSUE	-
DMS_11267	17424	N	N	N	1	CUSTOMER ISSUE	-
DMS_11268	17425	N	N	N	1	CUSTOMER ISSUE	-
DMS_11269	17426	N	N	N	1	CUSTOMER ISSUE	-
DMS_11270	17427	N	N	N	1	CUSTOMER ISSUE	-
DMS_11271	17428	N	N	N	1	CUSTOMER ISSUE	-
DMS_11272	17429	N	N	N	1	CUSTOMER ISSUE	-
DMS_11273	17430	N	N	N	1	CUSTOMER ISSUE	-
DMS_11274	17431	N	N	N	1	CUSTOMER ISSUE	-
DMS_11275	17432	N	N	N	1	CUSTOMER ISSUE	-
DMS_11276	17433	N	N	N	1	CUSTOMER ISSUE	-
DMS_11277	17434	N	N	N	1	CUSTOMER ISSUE	-
DMS_11278	17435	N	N	N	1	CUSTOMER ISSUE	-
DMS_11279	17436	N	N	N	1	CUSTOMER ISSUE	-
DMS_11280	17437	N	N	N	1	CUSTOMER ISSUE	-
DMS_11281	17438	N	N	N	1	CUSTOMER ISSUE	-
DMS_11282	17439	N	N	N	1	CUSTOMER ISSUE	-
DMS_11283	17440	N	N	N	1	CUSTOMER ISSUE	-
DMS_11284	17441	N	N	N	1	CUSTOMER ISSUE	-
DMS_11285	17442	N	N	N	1	CUSTOMER ISSUE	-
DMS_11286	17443	N	N	N	1	CUSTOMER ISSUE	-
DMS_11287	17444	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11288	17445	N	N	N	1	CUSTOMER ISSUE	-
DMS_11289	17446	N	N	N	1	CUSTOMER ISSUE	-
DMS_11290	17447	N	N	N	1	CUSTOMER ISSUE	-
DMS_11291	17448	N	N	N	1	CUSTOMER ISSUE	-
DMS_11292	17449	N	N	N	1	CUSTOMER ISSUE	-
DMS_11293	17450	N	N	N	1	CUSTOMER ISSUE	-
DMS_11294	17451	N	N	N	1	CUSTOMER ISSUE	-
DMS_11295	17452	N	N	N	1	CUSTOMER ISSUE	-
DMS_11296	17453	N	N	N	1	CUSTOMER ISSUE	-
DMS_11297	17454	N	N	N	1	CUSTOMER ISSUE	-
DMS_11298	17455	N	N	N	1	CUSTOMER ISSUE	-
DMS_11299	17456	N	N	N	1	CUSTOMER ISSUE	-
DMS_11300	17457	N	N	N	1	CUSTOMER ISSUE	-
DMS_11301	17458	N	N	N	1	CUSTOMER ISSUE	-
DMS_11302	17459	N	N	N	1	CUSTOMER ISSUE	-
DMS_11303	17460	N	N	N	1	CUSTOMER ISSUE	-
DMS_11304	17461	N	N	N	1	CUSTOMER ISSUE	-
DMS_11305	17462	N	N	N	1	CUSTOMER ISSUE	-
DMS_11306	17463	N	N	N	1	CUSTOMER ISSUE	-
DMS_11307	17464	N	N	N	1	CUSTOMER ISSUE	-
DMS_11308	17465	N	N	N	1	CUSTOMER ISSUE	-
DMS_11309	17466	N	N	N	1	CUSTOMER ISSUE	-
DMS_11310	17467	N	N	N	1	CUSTOMER ISSUE	-
DMS_11311	17468	N	N	N	1	CUSTOMER ISSUE	-
DMS_11312	17469	N	N	N	1	CUSTOMER ISSUE	-
DMS_11313	17470	N	N	N	1	CUSTOMER ISSUE	-
DMS_11314	17471	N	N	N	1	CUSTOMER ISSUE	-
DMS_11315	17472	N	N	N	1	CUSTOMER ISSUE	-
DMS_11316	17473	N	N	N	1	CUSTOMER ISSUE	-
DMS_11317	17474	N	N	N	1	CUSTOMER ISSUE	-
DMS_11318	17475	N	N	N	1	CUSTOMER ISSUE	-
DMS_11319	17476	N	N	N	1	CUSTOMER ISSUE	-
DMS_11320	17477	N	N	N	1	CUSTOMER ISSUE	-
DMS_11321	17478	N	N	N	1	CUSTOMER ISSUE	-
DMS_11322	17479	N	N	N	1	CUSTOMER ISSUE	-
DMS_11323	17480	N	N	N	1	CUSTOMER ISSUE	-
DMS_11324	17481	N	N	N	1	CUSTOMER ISSUE	-
DMS_11325	17482	N	N	N	1	CUSTOMER ISSUE	-
DMS_11326	17483	N	N	N	1	CUSTOMER ISSUE	-
DMS_11327	17484	N	N	N	1	CUSTOMER ISSUE	-
DMS_11328	17485	N	N	N	1	CUSTOMER ISSUE	-
DMS_11329	17486	N	N	N	1	CUSTOMER ISSUE	-
DMS_11330	17487	N	N	N	1	CUSTOMER ISSUE	-
DMS_11331	17488	N	N	N	1	CUSTOMER ISSUE	-
DMS_11332	17489	N	N	N	1	CUSTOMER ISSUE	-
DMS_11333	17490	N	N	N	1	CUSTOMER ISSUE	-
DMS_11334	17491	N	N	N	1	CUSTOMER ISSUE	-
DMS_11335	17492	N	N	N	1	CUSTOMER ISSUE	-
DMS_11336	17493	N	N	N	1	CUSTOMER ISSUE	-
DMS_11337	17494	N	N	N	1	CUSTOMER ISSUE	-
DMS_11338	17495	N	N	N	1	CUSTOMER ISSUE	-
DMS_11339	17496	N	N	N	1	CUSTOMER ISSUE	-

DMS_11340	17497	N	N	N	1	CUSTOMER ISSUE	-
DMS_11341	17498	N	N	N	1	CUSTOMER ISSUE	-
DMS_11342	17499	N	N	N	1	CUSTOMER ISSUE	-
DMS_11343	17500	N	N	N	1	CUSTOMER ISSUE	-
DMS_11344	17501	N	N	N	1	CUSTOMER ISSUE	-
DMS_11345	17502	N	N	N	1	CUSTOMER ISSUE	-
DMS_11346	17503	N	N	N	1	CUSTOMER ISSUE	-
DMS_11347	17504	N	N	N	1	CUSTOMER ISSUE	-
DMS_11348	17505	N	N	N	1	CUSTOMER ISSUE	-
DMS_11349	17506	N	N	N	1	CUSTOMER ISSUE	-
DMS_11350	17507	N	N	N	1	CUSTOMER ISSUE	-
DMS_11351	17508	N	N	N	1	CUSTOMER ISSUE	-
DMS_11352	17509	N	N	N	1	CUSTOMER ISSUE	-
DMS_11353	17510	N	N	N	1	CUSTOMER ISSUE	-
DMS_11354	17511	N	N	N	1	CUSTOMER ISSUE	-
DMS_11355	17512	N	N	N	1	CUSTOMER ISSUE	-
DMS_11356	17513	N	N	N	1	CUSTOMER ISSUE	-
DMS_11357	17514	N	N	N	1	CUSTOMER ISSUE	-
DMS_11358	17515	N	N	N	1	CUSTOMER ISSUE	-
DMS_11359	17516	N	N	N	1	CUSTOMER ISSUE	-
DMS_11360	17517	N	N	N	1	CUSTOMER ISSUE	-
DMS_11361	17518	N	N	N	1	CUSTOMER ISSUE	-
DMS_11362	17519	N	N	N	1	CUSTOMER ISSUE	-
DMS_11363	17520	N	N	N	1	CUSTOMER ISSUE	-
DMS_11364	17521	N	N	N	1	CUSTOMER ISSUE	-
DMS_11365	17522	N	N	N	1	CUSTOMER ISSUE	-
DMS_11366	17523	N	N	N	1	CUSTOMER ISSUE	-
DMS_11367	17524	N	N	N	1	CUSTOMER ISSUE	-
DMS_11368	17525	N	N	N	1	CUSTOMER ISSUE	-
DMS_11369	17526	N	N	N	1	CUSTOMER ISSUE	-
DMS_11370	17527	N	N	N	1	CUSTOMER ISSUE	-
DMS_11371	17528	N	N	N	1	CUSTOMER ISSUE	-
DMS_11372	17529	N	N	N	1	CUSTOMER ISSUE	-
DMS_11373	17530	N	N	N	1	CUSTOMER ISSUE	-
DMS_11374	17531	N	N	N	1	CUSTOMER ISSUE	-
DMS_11375	17532	N	N	N	1	CUSTOMER ISSUE	-
DMS_11376	17533	N	N	N	1	CUSTOMER ISSUE	-
DMS_11377	17534	N	N	N	1	CUSTOMER ISSUE	-
DMS_11378	17535	N	N	N	1	CUSTOMER ISSUE	-
DMS_11379	17536	N	N	N	1	CUSTOMER ISSUE	-
DMS_11380	17537	N	N	N	1	CUSTOMER ISSUE	-
DMS_11381	17538	N	N	N	1	CUSTOMER ISSUE	-
DMS_11382	17539	N	N	N	1	CUSTOMER ISSUE	-
DMS_11383	17540	N	N	N	1	CUSTOMER ISSUE	-
DMS_11388	17541	N	N	N	1	CUSTOMER ISSUE	-
DMS_11389	17542	N	N	N	1	CUSTOMER ISSUE	-
DMS_11391	17543	N	N	N	1	CUSTOMER ISSUE	-
DMS_11392	17544	N	N	N	1	CUSTOMER ISSUE	-
DMS_11393	17545	N	N	N	1	CUSTOMER ISSUE	-
DMS_11394	17546	N	N	N	1	CUSTOMER ISSUE	-
DMS_11395	17547	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_11396	17548	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_11397	17549	N	N	N	1	CUSTOMER ISSUE	-
DMS_11398	17550	N	N	N	1	CUSTOMER ISSUE	-
DMS_11400	17551	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_11401	17552	N	N	N	1	CUSTOMER ISSUE	-
DMS_11402	17553	N	N	N	1	CUSTOMER ISSUE	-
DMS_11403	17554	N	N	N	1	CUSTOMER ISSUE	-
DMS_11404	17555	N	N	N	1	CUSTOMER ISSUE	-
DMS_11405	17556	N	N	N	1	CUSTOMER ISSUE	-
DMS_11406	17557	N	N	N	1	CUSTOMER ISSUE	-
DMS_11407	17558	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11408	17559	N	N	N	1	CUSTOMER ISSUE	-
DMS_11409	17560	N	N	N	1	CUSTOMER ISSUE	-
DMS_11410	17561	N	N	N	1	CUSTOMER ISSUE	-
DMS_11411	17562	N	N	N	1	CUSTOMER ISSUE	-
DMS_11412	17563	N	N	N	1	CUSTOMER ISSUE	-
DMS_11413	17564	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_11414	17565	N	N	N	1	CUSTOMER ISSUE	-
DMS_11415	17566	N	N	N	1	CUSTOMER ISSUE	-
DMS_11416	17567	N	N	N	1	CUSTOMER ISSUE	-
DMS_11417	17568	N	N	N	1	CUSTOMER ISSUE	-
DMS_11418	17569	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_11419	17570	N	N	N	1	CUSTOMER ISSUE	-
DMS_11420	17571	N	N	N	1	CUSTOMER ISSUE	-
DMS_11421	17572	N	N	N	1	CUSTOMER ISSUE	-
DMS_11422	17573	N	N	N	1	CUSTOMER ISSUE	-
DMS_11423	17574	N	N	N	1	CUSTOMER ISSUE	-
DMS_11424	17575	N	N	N	1	CUSTOMER ISSUE	-
DMS_11425	17576	N	N	N	1	CUSTOMER ISSUE	-

DMS_11426	17577	N	N	N	1	CUSTOMER ISSUE	-
DMS_11427	17578	N	N	N	1	CUSTOMER ISSUE	-
DMS_11428	17579	N	N	N	1	CUSTOMER ISSUE	-
DMS_11429	17580	N	N	N	1	CUSTOMER ISSUE	-
DMS_11430	17581	N	N	N	1	CUSTOMER ISSUE	-
DMS_11431	17582	N	N	N	1	CUSTOMER ISSUE	-
DMS_11432	17583	N	N	N	1	CUSTOMER ISSUE	-
DMS_11433	17584	N	N	N	1	CUSTOMER ISSUE	-
DMS_11434	17585	N	N	N	1	CUSTOMER ISSUE	-
DMS_11435	17586	N	N	N	1	CUSTOMER ISSUE	-
DMS_11436	17587	N	N	N	1	CUSTOMER ISSUE	-
DMS_11437	17588	N	N	N	1	CUSTOMER ISSUE	-
DMS_11438	17589	N	N	N	1	CUSTOMER ISSUE	-
DMS_11439	17590	N	N	N	1	CUSTOMER ISSUE	-
DMS_11440	17591	N	N	N	1	CUSTOMER ISSUE	-
DMS_11441	17592	N	N	N	1	CUSTOMER ISSUE	-
DMS_11442	17593	N	N	N	1	CUSTOMER ISSUE	-
DMS_11443	17594	N	N	N	1	CUSTOMER ISSUE	-
DMS_11444	17595	N	N	N	1	CUSTOMER ISSUE	-
DMS_11445	17596	N	N	N	1	CUSTOMER ISSUE	-
DMS_11446	17597	N	N	N	1	CUSTOMER ISSUE	-
DMS_11447	17598	N	N	N	1	CUSTOMER ISSUE	-
DMS_11448	17599	N	N	N	1	CUSTOMER ISSUE	-
DMS_11449	17600	N	N	N	1	CUSTOMER ISSUE	-
DMS_11450	17601	N	N	N	1	CUSTOMER ISSUE	-
DMS_11451	17602	N	N	N	1	CUSTOMER ISSUE	-
DMS_11452	17603	N	N	N	1	CUSTOMER ISSUE	-
DMS_11453	17604	N	N	N	1	CUSTOMER ISSUE	-
DMS_11454	17605	N	N	N	1	CUSTOMER ISSUE	-
DMS_11455	17606	N	N	N	1	CUSTOMER ISSUE	-
DMS_11456	17607	N	N	N	1	CUSTOMER ISSUE	-
DMS_11457	17608	N	N	N	1	CUSTOMER ISSUE	-
DMS_11458	17609	N	N	N	1	CUSTOMER ISSUE	-
DMS_11459	17610	N	N	N	1	CUSTOMER ISSUE	-
DMS_11460	17611	N	N	N	1	CUSTOMER ISSUE	-
DMS_11461	17612	N	N	N	1	CUSTOMER ISSUE	-
DMS_11462	17613	N	N	N	1	CUSTOMER ISSUE	-
DMS_11463	17614	N	N	N	1	CUSTOMER ISSUE	-
DMS_11464	17615	N	N	N	1	CUSTOMER ISSUE	-
DMS_11465	17616	N	N	N	1	CUSTOMER ISSUE	-
DMS_11466	17617	N	N	N	1	CUSTOMER ISSUE	-
DMS_11467	17618	N	N	N	1	CUSTOMER ISSUE	-
DMS_11468	17619	N	N	N	1	CUSTOMER ISSUE	-
DMS_11469	17620	N	N	N	1	CUSTOMER ISSUE	-
DMS_11470	17621	N	N	N	1	CUSTOMER ISSUE	-
DMS_11471	17622	N	N	N	1	CUSTOMER ISSUE	-
DMS_11472	17623	N	N	N	1	CUSTOMER ISSUE	-
DMS_11473	17624	N	N	N	1	CUSTOMER ISSUE	-
DMS_11474	17625	N	N	N	1	CUSTOMER ISSUE	-
DMS_11475	17626	N	N	N	1	CUSTOMER ISSUE	-
DMS_11476	17627	N	N	N	1	CUSTOMER ISSUE	-
DMS_11477	17628	N	N	N	1	CUSTOMER ISSUE	-
DMS_11478	17629	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_11479	17630	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11480	17631	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11482	17632	N	N	N	1	CUSTOMER ISSUE	-
DMS_11483	17633	N	N	N	1	CUSTOMER ISSUE	-
DMS_11484	17634	N	N	N	1	CUSTOMER ISSUE	-
DMS_11485	17635	N	N	N	1	CUSTOMER ISSUE	-
DMS_11486	17636	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11487	17637	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11488	17638	N	N	N	1	CUSTOMER ISSUE	-
DMS_11489	17639	N	N	N	1	CUSTOMER ISSUE	-
DMS_11490	17640	N	N	N	1	CUSTOMER ISSUE	-
DMS_11491	17641	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11492	17642	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_11493	17643	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11494	17644	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11495	17645	N	N	N	1	CUSTOMER ISSUE	-
DMS_11496	17646	N	N	N	1	CUSTOMER ISSUE	-
DMS_11497	17647	N	N	N	1	CUSTOMER ISSUE	-
DMS_11498	17648	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11499	17649	N	N	N	1	CUSTOMER ISSUE	-
DMS_11500	17650	N	N	N	1	CUSTOMER ISSUE	-
DMS_11501	17651	N	N	N	1	CUSTOMER ISSUE	-
DMS_11502	17652	N	N	N	1	CUSTOMER ISSUE	-
DMS_11504	17653	N	N	N	1	CUSTOMER ISSUE	-
DMS_11505	17654	N	N	N	1	CUSTOMER ISSUE	-
DMS_11506	17655	N	N	N	1	CUSTOMER ISSUE	-
DMS_11507	17656	N	N	N	1	CUSTOMER ISSUE	-

DMS_11508	17657	N	N	N	1	CUSTOMER ISSUE	-
DMS_11509	17658	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11510	17659	N	N	N	1	CUSTOMER ISSUE	-
DMS_11511	17660	N	N	N	1	CUSTOMER ISSUE	-
DMS_11512	17661	N	N	N	1	CUSTOMER ISSUE	-
DMS_11513	17662	N	N	N	1	CUSTOMER ISSUE	-
DMS_11514	17663	N	N	N	1	CUSTOMER ISSUE	-
DMS_11515	17664	N	N	N	1	CUSTOMER ISSUE	-
DMS_11516	17665	N	N	N	1	CUSTOMER ISSUE	-
DMS_11517	17666	N	N	N	1	CUSTOMER ISSUE	-
DMS_11518	17667	N	N	N	1	CUSTOMER ISSUE	-
DMS_11519	17668	N	N	N	1	CUSTOMER ISSUE	-
DMS_11520	17669	N	N	N	1	CUSTOMER ISSUE	-
DMS_11521	17670	N	N	N	1	CUSTOMER ISSUE	-
DMS_11522	17671	N	N	N	1	CUSTOMER ISSUE	-
DMS_11523	17672	N	N	N	1	CUSTOMER ISSUE	-
DMS_11524	17673	N	N	N	1	CUSTOMER ISSUE	-
DMS_11525	17674	N	N	N	1	CUSTOMER ISSUE	-
DMS_11526	17675	N	N	N	1	CUSTOMER ISSUE	-
DMS_11527	17676	N	N	N	1	CUSTOMER ISSUE	-
DMS_11528	17677	N	N	N	1	CUSTOMER ISSUE	-
DMS_11529	17678	N	N	N	1	CUSTOMER ISSUE	-
DMS_11530	17679	N	N	N	1	CUSTOMER ISSUE	-
DMS_11531	17680	N	N	N	1	CUSTOMER ISSUE	-
DMS_11532	17681	N	N	N	1	CUSTOMER ISSUE	-
DMS_11533	17682	N	N	N	1	CUSTOMER ISSUE	-
DMS_11534	17683	N	N	N	1	CUSTOMER ISSUE	-
DMS_11535	17684	N	N	N	1	CUSTOMER ISSUE	-
DMS_11536	17685	N	N	N	1	CUSTOMER ISSUE	-
DMS_11537	17686	N	N	N	1	CUSTOMER ISSUE	-
DMS_11538	17687	N	N	N	1	CUSTOMER ISSUE	-
DMS_11539	17688	N	N	N	1	CUSTOMER ISSUE	-
DMS_11540	17689	N	N	N	1	CUSTOMER ISSUE	-
DMS_11541	17690	N	N	N	1	CUSTOMER ISSUE	-
DMS_11542	17691	N	N	N	1	CUSTOMER ISSUE	-
DMS_11543	17692	N	N	N	1	CUSTOMER ISSUE	-
DMS_11544	17693	N	N	N	1	CUSTOMER ISSUE	-
DMS_11545	17694	N	N	N	1	CUSTOMER ISSUE	-
DMS_11546	17695	N	N	N	1	CUSTOMER ISSUE	-
DMS_11547	17696	N	N	N	1	CUSTOMER ISSUE	-
DMS_11548	17697	N	N	N	1	CUSTOMER ISSUE	-
DMS_11549	17698	N	N	N	1	CUSTOMER ISSUE	-
DMS_11550	17699	N	N	N	1	CUSTOMER ISSUE	-
DMS_11551	17700	N	N	N	1	CUSTOMER ISSUE	-
DMS_11552	17701	N	N	N	1	CUSTOMER ISSUE	-
DMS_11553	17702	N	N	N	1	CUSTOMER ISSUE	-
DMS_11554	17703	N	N	N	1	CUSTOMER ISSUE	-
DMS_11555	17704	N	N	N	1	CUSTOMER ISSUE	-
DMS_11556	17705	N	N	N	1	CUSTOMER ISSUE	-
DMS_11557	17706	N	N	N	1	CUSTOMER ISSUE	-
DMS_11558	17707	N	N	N	1	CUSTOMER ISSUE	-
DMS_11559	17708	N	N	N	1	CUSTOMER ISSUE	-
DMS_11560	17709	N	N	N	1	CUSTOMER ISSUE	-
DMS_11561	17710	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11562	17711	N	N	N	1	CUSTOMER ISSUE	-
DMS_11563	17712	N	N	N	1	CUSTOMER ISSUE	-
DMS_11564	17713	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11565	17714	N	N	N	1	CUSTOMER ISSUE	-
DMS_11566	17715	N	N	N	1	CUSTOMER ISSUE	-
DMS_11567	17716	N	N	N	1	CUSTOMER ISSUE	-
DMS_11568	17717	N	N	N	1	CUSTOMER ISSUE	-
DMS_11569	17718	N	N	N	1	CUSTOMER ISSUE	-
DMS_11570	17719	N	N	N	1	CUSTOMER ISSUE	-
DMS_11571	17720	N	N	N	1	CUSTOMER ISSUE	-
DMS_11572	17721	N	N	N	1	CUSTOMER ISSUE	-
DMS_11574	17722	N	N	N	1	CUSTOMER ISSUE	-
DMS_11575	17723	N	N	N	1	CUSTOMER ISSUE	-
DMS_11576	17724	N	N	N	1	CUSTOMER ISSUE	-
DMS_11577	17725	N	N	N	1	CUSTOMER ISSUE	-
DMS_11579	17726	N	N	N	1	CUSTOMER ISSUE	-
DMS_11580	17727	N	N	N	1	CUSTOMER ISSUE	-
DMS_11581	17728	N	N	N	1	CUSTOMER ISSUE	-
DMS_11582	17729	N	N	N	2	CUSTOMER ISSUE	-
DMS_11583	17730	N	N	N	1	CUSTOMER ISSUE	-
DMS_11584	17731	N	N	N	1	CUSTOMER ISSUE	-
DMS_11585	17732	N	N	N	1	CUSTOMER ISSUE	-
DMS_11586	17733	N	N	N	1	CUSTOMER ISSUE	-
DMS_11587	17734	N	N	N	1	CUSTOMER ISSUE	-
DMS_11588	17735	N	N	N	1	CUSTOMER ISSUE	-
DMS_11589	17736	N	N	N	1	CUSTOMER ISSUE	-

DMS_11590	17737	N	N	N	1	CUSTOMER ISSUE	-
DMS_11591	17738	N	N	N	1	CUSTOMER ISSUE	-
DMS_11592	17739	N	N	N	1	CUSTOMER ISSUE	-
DMS_11593	17740	N	N	N	1	CUSTOMER ISSUE	-
DMS_11594	17741	N	N	N	1	CUSTOMER ISSUE	-
DMS_11595	17742	N	N	N	1	CUSTOMER ISSUE	-
DMS_11596	17743	N	N	N	1	CUSTOMER ISSUE	-
DMS_11597	17744	N	N	N	1	CUSTOMER ISSUE	-
DMS_11598	17745	N	N	N	1	CUSTOMER ISSUE	-
DMS_11599	17746	N	N	N	1	CUSTOMER ISSUE	-
DMS_11600	17747	N	N	N	1	CUSTOMER ISSUE	-
DMS_11601	17748	N	N	N	1	CUSTOMER ISSUE	-
DMS_11602	17749	N	N	N	1	CUSTOMER ISSUE	-
DMS_11603	17750	N	N	N	1	CUSTOMER ISSUE	-
DMS_11604	17751	N	N	N	1	CUSTOMER ISSUE	-
DMS_11605	17752	N	N	N	1	CUSTOMER ISSUE	-
DMS_11606	17753	N	N	N	1	CUSTOMER ISSUE	-
DMS_11607	17754	N	N	N	1	CUSTOMER ISSUE	-
DMS_11608	17755	N	N	N	1	CUSTOMER ISSUE	-
DMS_11609	17756	N	N	N	1	CUSTOMER ISSUE	-
DMS_11610	17757	N	N	N	1	CUSTOMER ISSUE	-
DMS_11611	17758	N	N	N	1	CUSTOMER ISSUE	-
DMS_11612	17759	N	N	N	2	CUSTOMER ISSUE	-
DMS_11614	17760	N	N	N	1	CUSTOMER ISSUE	-
DMS_11615	17761	N	N	N	1	CUSTOMER ISSUE	-
DMS_11616	17762	N	N	N	1	CUSTOMER ISSUE	-
DMS_11617	17763	N	N	N	1	CUSTOMER ISSUE	-
DMS_11618	17764	N	N	N	1	CUSTOMER ISSUE	-
DMS_11619	17765	N	N	N	1	CUSTOMER ISSUE	-
DMS_11620	17766	N	N	N	1	CUSTOMER ISSUE	-
DMS_11621	17767	N	N	N	1	CUSTOMER ISSUE	-
DMS_11622	17768	N	N	N	1	CUSTOMER ISSUE	-
DMS_11623	17769	N	N	N	1	CUSTOMER ISSUE	-
DMS_11624	17770	N	N	N	1	CUSTOMER ISSUE	-
DMS_11625	17771	N	N	N	1	CUSTOMER ISSUE	-
DMS_11627	17772	N	N	N	1	CUSTOMER ISSUE	-
DMS_11628	17773	N	N	N	1	CUSTOMER ISSUE	-
DMS_11629	17774	N	N	N	2	CUSTOMER ISSUE	-
DMS_11630	17775	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_11631	17776	N	N	N	1	CUSTOMER ISSUE	-
DMS_11632	17777	N	N	N	1	CUSTOMER ISSUE	-
DMS_11633	17778	N	N	N	1	CUSTOMER ISSUE	-
DMS_11635	17779	N	N	N	2	CUSTOMER ISSUE	-
DMS_11636	17780	N	N	N	1	CUSTOMER ISSUE	-
DMS_11637	17781	N	N	N	1	CUSTOMER ISSUE	-
DMS_11638	17782	N	N	N	1	CUSTOMER ISSUE	-
DMS_11640	17783	N	N	N	1	CUSTOMER ISSUE	-
DMS_11641	17784	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11642	17785	N	N	N	1	CUSTOMER ISSUE	-
DMS_11643	17786	N	N	N	1	CUSTOMER ISSUE	-
DMS_11644	17787	N	N	N	1	CUSTOMER ISSUE	-
DMS_11645	17788	N	N	N	1	CUSTOMER ISSUE	-
DMS_11646	17789	N	N	N	1	CUSTOMER ISSUE	-
DMS_11647	17790	N	N	N	1	CUSTOMER ISSUE	-
DMS_11648	17791	N	N	N	1	CUSTOMER ISSUE	-
DMS_11649	17792	N	N	N	1	CUSTOMER ISSUE	-
DMS_11650	17793	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_11651	17794	N	N	N	1	CUSTOMER ISSUE	-
DMS_11653	17795	N	N	N	1	CUSTOMER ISSUE	-
DMS_11654	17796	N	N	N	1	CUSTOMER ISSUE	-
DMS_11655	17797	N	N	N	1	CUSTOMER ISSUE	-
DMS_11657	17798	N	N	N	1	CUSTOMER ISSUE	-
DMS_11658	17799	N	N	N	1	CUSTOMER ISSUE	-
DMS_11659	17800	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11662	17801	N	N	N	1	CUSTOMER ISSUE	-
DMS_11664	17802	N	N	N	1	CUSTOMER ISSUE	-
DMS_11665	17803	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_11666	17804	N	N	N	1	CUSTOMER ISSUE	-
DMS_11667	17805	N	N	N	1	CUSTOMER ISSUE	-
DMS_11668	17806	N	N	N	1	CUSTOMER ISSUE	-
DMS_11669	17807	N	N	N	1	CUSTOMER ISSUE	-
DMS_11672	17808	N	N	N	1	CUSTOMER ISSUE	-
DMS_11673	17809	N	N	N	1	CUSTOMER ISSUE	-
DMS_11674	17810	N	N	N	1	CUSTOMER ISSUE	-
DMS_11675	17811	N	N	N	1	CUSTOMER ISSUE	-
DMS_11676	17812	N	N	N	1	CUSTOMER ISSUE	-
DMS_11677	17813	N	N	N	1	CUSTOMER ISSUE	-
DMS_11678	17814	N	N	N	1	CUSTOMER ISSUE	-
DMS_11679	17815	N	N	N	1	CUSTOMER ISSUE	-
DMS_11680	17816	N	N	N	1	CUSTOMER ISSUE	-

DMS_11681	17817	N	N	N	1	CUSTOMER ISSUE	-
DMS_11682	17818	N	N	N	1	CUSTOMER ISSUE	-
DMS_11683	17819	N	N	N	1	CUSTOMER ISSUE	-
DMS_11684	17820	N	N	N	1	CUSTOMER ISSUE	-
DMS_11685	17821	N	N	N	1	CUSTOMER ISSUE	-
DMS_11686	17822	N	N	N	1	CUSTOMER ISSUE	-
DMS_11687	17823	N	N	N	1	CUSTOMER ISSUE	-
DMS_11688	17824	N	N	N	1	CUSTOMER ISSUE	-
DMS_11689	17825	N	N	N	1	CUSTOMER ISSUE	-
DMS_11690	17826	N	N	N	1	CUSTOMER ISSUE	-
DMS_11691	17827	N	N	N	1	CUSTOMER ISSUE	-
DMS_11692	17828	N	N	N	1	CUSTOMER ISSUE	-
DMS_11693	17829	N	N	N	1	CUSTOMER ISSUE	-
DMS_11694	17830	N	N	N	1	CUSTOMER ISSUE	-
DMS_11695	17831	N	N	N	1	CUSTOMER ISSUE	-
DMS_11696	17832	N	N	N	1	CUSTOMER ISSUE	-
DMS_11697	17833	N	N	N	1	CUSTOMER ISSUE	-
DMS_11698	17834	N	N	N	1	CUSTOMER ISSUE	-
DMS_11699	17835	N	N	N	1	CUSTOMER ISSUE	-
DMS_11700	17836	N	N	N	1	CUSTOMER ISSUE	-
DMS_11701	17837	N	N	N	1	CUSTOMER ISSUE	-
DMS_11702	17838	N	N	N	1	CUSTOMER ISSUE	-
DMS_11703	17839	N	N	N	1	CUSTOMER ISSUE	-
DMS_11704	17840	N	N	N	1	CUSTOMER ISSUE	-
DMS_11705	17841	N	N	N	1	CUSTOMER ISSUE	-
DMS_11706	17842	N	N	N	1	CUSTOMER ISSUE	-
DMS_11707	17843	N	N	N	1	CUSTOMER ISSUE	-
DMS_11708	17844	N	N	N	1	CUSTOMER ISSUE	-
DMS_11709	17845	N	N	N	1	CUSTOMER ISSUE	-
DMS_11710	17846	N	N	N	1	CUSTOMER ISSUE	-
DMS_11711	17847	N	N	N	1	CUSTOMER ISSUE	-
DMS_11712	17848	N	N	N	1	CUSTOMER ISSUE	-
DMS_11713	17849	N	N	N	1	CUSTOMER ISSUE	-
DMS_11714	17850	N	N	N	1	CUSTOMER ISSUE	-
DMS_11715	17851	N	N	N	1	CUSTOMER ISSUE	-
DMS_11716	17852	N	N	N	1	CUSTOMER ISSUE	-
DMS_11717	17853	N	N	N	1	CUSTOMER ISSUE	-
DMS_11718	17854	N	N	N	1	CUSTOMER ISSUE	-
DMS_11719	17855	N	N	N	1	CUSTOMER ISSUE	-
DMS_11720	17856	N	N	N	1	CUSTOMER ISSUE	-
DMS_11721	17857	N	N	N	1	CUSTOMER ISSUE	-
DMS_11722	17858	N	N	N	1	CUSTOMER ISSUE	-
DMS_11723	17859	N	N	N	1	CUSTOMER ISSUE	-
DMS_11724	17860	N	N	N	1	CUSTOMER ISSUE	-
DMS_11725	17861	N	N	N	1	CUSTOMER ISSUE	-
DMS_11726	17862	N	N	N	1	CUSTOMER ISSUE	-
DMS_11727	17863	N	N	N	1	CUSTOMER ISSUE	-
DMS_11728	17864	N	N	N	1	CUSTOMER ISSUE	-
DMS_11729	17865	N	N	N	1	CUSTOMER ISSUE	-
DMS_11730	17866	N	N	N	1	CUSTOMER ISSUE	-
DMS_11731	17867	N	N	N	1	CUSTOMER ISSUE	-
DMS_11732	17868	N	N	N	1	CUSTOMER ISSUE	-
DMS_11733	17869	N	N	N	1	CUSTOMER ISSUE	-
DMS_11734	17870	N	N	N	1	CUSTOMER ISSUE	-
DMS_11735	17871	N	N	N	1	CUSTOMER ISSUE	-
DMS_11736	17872	N	N	N	1	CUSTOMER ISSUE	-
DMS_11737	17873	N	N	N	1	CUSTOMER ISSUE	-
DMS_11738	17874	N	N	N	1	CUSTOMER ISSUE	-
DMS_11739	17875	N	N	N	1	CUSTOMER ISSUE	-
DMS_11740	17876	N	N	N	1	CUSTOMER ISSUE	-
DMS_11741	17877	N	N	N	1	CUSTOMER ISSUE	-
DMS_11742	17878	N	N	N	1	CUSTOMER ISSUE	-
DMS_11743	17879	N	N	N	1	CUSTOMER ISSUE	-
DMS_11744	17880	N	N	N	1	CUSTOMER ISSUE	-
DMS_11745	17881	N	N	N	1	CUSTOMER ISSUE	-
DMS_11746	17882	N	N	N	1	CUSTOMER ISSUE	-
DMS_11747	17883	N	N	N	1	CUSTOMER ISSUE	-
DMS_11748	17884	N	N	N	1	CUSTOMER ISSUE	-
DMS_11749	17885	N	N	N	1	CUSTOMER ISSUE	-
DMS_11750	17886	N	N	N	1	CUSTOMER ISSUE	-
DMS_11751	17887	N	N	N	1	CUSTOMER ISSUE	-
DMS_11752	17888	N	N	N	1	CUSTOMER ISSUE	-
DMS_11753	17889	N	N	N	1	CUSTOMER ISSUE	-
DMS_11754	17890	N	N	N	1	CUSTOMER ISSUE	-
DMS_11755	17891	N	N	N	1	CUSTOMER ISSUE	-
DMS_11756	17892	N	N	N	1	CUSTOMER ISSUE	-
DMS_11757	17893	N	N	N	1	CUSTOMER ISSUE	-
DMS_11758	17894	N	N	N	1	CUSTOMER ISSUE	-
DMS_11759	17895	N	N	N	1	CUSTOMER ISSUE	-
DMS_11760	17896	N	N	N	1	CUSTOMER ISSUE	-

DMS_11761	17897	N	N	N	1	CUSTOMER ISSUE	-
DMS_11762	17898	N	N	N	1	CUSTOMER ISSUE	-
DMS_11763	17899	N	N	N	1	CUSTOMER ISSUE	-
DMS_11764	17900	N	N	N	1	CUSTOMER ISSUE	-
DMS_11765	17901	N	N	N	1	CUSTOMER ISSUE	-
DMS_11766	17902	N	N	N	1	CUSTOMER ISSUE	-
DMS_11767	17903	N	N	N	1	CUSTOMER ISSUE	-
DMS_11768	17904	N	N	N	1	CUSTOMER ISSUE	-
DMS_11769	17905	N	N	N	1	CUSTOMER ISSUE	-
DMS_11770	17906	N	N	N	1	CUSTOMER ISSUE	-
DMS_11771	17907	N	N	N	1	CUSTOMER ISSUE	-
DMS_11772	17908	N	N	N	1	CUSTOMER ISSUE	-
DMS_11773	17909	N	N	N	1	CUSTOMER ISSUE	-
DMS_11774	17910	N	N	N	1	CUSTOMER ISSUE	-
DMS_11775	17911	N	N	N	1	CUSTOMER ISSUE	-
DMS_11776	17912	N	N	N	1	CUSTOMER ISSUE	-
DMS_11777	17913	N	N	N	1	CUSTOMER ISSUE	-
DMS_11778	17914	N	N	N	1	CUSTOMER ISSUE	-
DMS_11779	17915	N	N	N	1	CUSTOMER ISSUE	-
DMS_11780	17916	N	N	N	1	CUSTOMER ISSUE	-
DMS_11781	17917	N	N	N	1	CUSTOMER ISSUE	-
DMS_11782	17918	N	N	N	1	CUSTOMER ISSUE	-
DMS_11783	17919	N	N	N	1	CUSTOMER ISSUE	-
DMS_11784	17920	N	N	N	1	CUSTOMER ISSUE	-
DMS_11786	17921	N	N	N	1	CUSTOMER ISSUE	-
DMS_11787	17922	N	N	N	1	CUSTOMER ISSUE	-
DMS_11788	17923	N	N	N	1	CUSTOMER ISSUE	-
DMS_11789	17924	N	N	N	1	CUSTOMER ISSUE	-
DMS_11790	17925	N	N	N	1	CUSTOMER ISSUE	-
DMS_11791	17926	N	N	N	1	CUSTOMER ISSUE	-
DMS_11792	17927	N	N	N	1	CUSTOMER ISSUE	-
DMS_11793	17928	N	N	N	1	CUSTOMER ISSUE	-
DMS_11794	17929	N	N	N	1	CUSTOMER ISSUE	-
DMS_11795	17930	N	N	N	1	CUSTOMER ISSUE	-
DMS_11796	17931	N	N	N	1	CUSTOMER ISSUE	-
DMS_11797	17932	N	N	N	1	CUSTOMER ISSUE	-
DMS_11798	17933	N	N	N	1	CUSTOMER ISSUE	-
DMS_11799	17934	N	N	N	1	CUSTOMER ISSUE	-
DMS_11800	17935	N	N	N	1	CUSTOMER ISSUE	-
DMS_11801	17936	N	N	N	1	CUSTOMER ISSUE	-
DMS_11802	17937	N	N	N	1	CUSTOMER ISSUE	-
DMS_11803	17938	N	N	N	1	CUSTOMER ISSUE	-
DMS_11804	17939	N	N	N	1	CUSTOMER ISSUE	-
DMS_11805	17940	N	N	N	1	CUSTOMER ISSUE	-
DMS_11806	17941	N	N	N	1	CUSTOMER ISSUE	-
DMS_11807	17942	N	N	N	1	CUSTOMER ISSUE	-
DMS_11808	17943	N	N	N	1	CUSTOMER ISSUE	-
DMS_11810	17944	N	N	N	1	CUSTOMER ISSUE	-
DMS_11811	17945	N	N	N	1	CUSTOMER ISSUE	-
DMS_11812	17946	N	N	N	1	CUSTOMER ISSUE	-
DMS_11814	17947	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_11815	17948	N	N	N	1	CUSTOMER ISSUE	-
DMS_11816	17949	N	N	N	1	CUSTOMER ISSUE	-
DMS_11817	17950	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11818	17951	N	N	N	1	CUSTOMER ISSUE	-
DMS_11820	17952	N	N	N	1	CUSTOMER ISSUE	-
DMS_11821	17953	N	N	N	1	CUSTOMER ISSUE	-
DMS_11822	17954	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_11823	17955	N	N	N	1	CUSTOMER ISSUE	-
DMS_11825	17956	N	N	N	1	CUSTOMER ISSUE	-
DMS_11826	17957	N	N	N	1	CUSTOMER ISSUE	-
DMS_11827	17958	N	N	N	1	CUSTOMER ISSUE	-
DMS_11828	17959	N	N	N	1	CUSTOMER ISSUE	-
DMS_11829	17960	N	N	N	1	CUSTOMER ISSUE	-
DMS_11830	17961	N	N	N	2	CUSTOMER ISSUE	-
DMS_11831	17962	N	N	N	1	CUSTOMER ISSUE	-
DMS_11832	17963	N	N	N	1	CUSTOMER ISSUE	-
DMS_11833	17964	N	N	N	1	CUSTOMER ISSUE	-
DMS_11834	17965	N	N	N	1	CUSTOMER ISSUE	-
DMS_11835	17966	N	N	N	1	CUSTOMER ISSUE	-
DMS_11836	17967	N	N	N	1	CUSTOMER ISSUE	-
DMS_11837	17968	N	N	N	1	CUSTOMER ISSUE	-
DMS_11838	17969	N	N	N	1	CUSTOMER ISSUE	-
DMS_11839	17970	N	N	N	1	CUSTOMER ISSUE	-
DMS_11840	17971	N	N	N	1	CUSTOMER ISSUE	-
DMS_11841	17972	N	N	N	1	CUSTOMER ISSUE	-
DMS_11842	17973	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11843	17974	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_11844	17975	N	N	N	1	CUSTOMER ISSUE	-
DMS_11845	17976	N	N	N	1	CUSTOMER ISSUE	-

DMS_11846	17977	N	N	N	1	CUSTOMER ISSUE	-
DMS_11847	17978	N	N	N	1	CUSTOMER ISSUE	-
DMS_11848	17979	N	N	N	1	CUSTOMER ISSUE	-
DMS_11850	17980	N	N	N	1	CUSTOMER ISSUE	-
DMS_11851	17981	N	N	N	1	CUSTOMER ISSUE	-
DMS_11852	17982	N	N	N	1	CUSTOMER ISSUE	-
DMS_11853	17983	N	N	N	1	CUSTOMER ISSUE	-
DMS_11854	17984	N	N	N	1	CUSTOMER ISSUE	-
DMS_11855	17985	N	N	N	1	CUSTOMER ISSUE	-
DMS_11856	17986	N	N	N	1	CUSTOMER ISSUE	-
DMS_11857	17987	N	N	N	1	CUSTOMER ISSUE	-
DMS_11858	17988	N	N	N	1	CUSTOMER ISSUE	-
DMS_11859	17989	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_11860	17990	N	N	N	1	CUSTOMER ISSUE	-
DMS_11861	17991	N	N	N	1	CUSTOMER ISSUE	-
DMS_11862	17992	N	N	N	1	CUSTOMER ISSUE	-
DMS_11863	17993	N	N	N	1	CUSTOMER ISSUE	-
DMS_11864	17994	N	N	N	1	CUSTOMER ISSUE	-
DMS_11865	17995	N	N	N	1	CUSTOMER ISSUE	-
DMS_11866	17996	N	N	N	1	CUSTOMER ISSUE	-
DMS_11867	17997	N	N	N	1	CUSTOMER ISSUE	-
DMS_11868	17998	N	N	N	1	CUSTOMER ISSUE	-
DMS_11869	17999	N	N	N	1	CUSTOMER ISSUE	-
DMS_11870	18000	N	N	N	1	CUSTOMER ISSUE	-
DMS_11871	18001	N	N	N	1	CUSTOMER ISSUE	-
DMS_11872	18002	N	N	N	1	CUSTOMER ISSUE	-
DMS_11873	18003	N	N	N	1	CUSTOMER ISSUE	-
DMS_11874	18004	N	N	N	1	CUSTOMER ISSUE	-
DMS_11875	18005	N	N	N	1	CUSTOMER ISSUE	-
DMS_11876	18006	N	N	N	1	CUSTOMER ISSUE	-
DMS_11877	18007	N	N	N	1	CUSTOMER ISSUE	-
DMS_11878	18008	N	N	N	1	CUSTOMER ISSUE	-
DMS_11879	18009	N	N	N	1	CUSTOMER ISSUE	-
DMS_11880	18010	N	N	N	1	CUSTOMER ISSUE	-
DMS_11881	18011	N	N	N	1	CUSTOMER ISSUE	-
DMS_11882	18012	N	N	N	1	CUSTOMER ISSUE	-
DMS_11884	18013	N	N	N	1	CUSTOMER ISSUE	-
DMS_11885	18014	N	N	N	1	CUSTOMER ISSUE	-
DMS_11886	18015	N	N	N	1	CUSTOMER ISSUE	-
DMS_11887	18016	N	N	N	1	CUSTOMER ISSUE	-
DMS_11888	18017	N	N	N	1	CUSTOMER ISSUE	-
DMS_11889	18018	N	N	N	1	CUSTOMER ISSUE	-
DMS_11890	18019	N	N	N	1	CUSTOMER ISSUE	-
DMS_11891	18020	N	N	N	1	CUSTOMER ISSUE	-
DMS_11892	18021	N	N	N	1	CUSTOMER ISSUE	-
DMS_11893	18022	N	N	N	1	CUSTOMER ISSUE	-
DMS_11894	18023	N	N	N	1	CUSTOMER ISSUE	-
DMS_11895	18024	N	N	N	1	CUSTOMER ISSUE	-
DMS_11896	18025	N	N	N	1	CUSTOMER ISSUE	-
DMS_11897	18026	N	N	N	1	CUSTOMER ISSUE	-
DMS_11898	18027	N	N	N	1	CUSTOMER ISSUE	-
DMS_11899	18028	N	N	N	1	CUSTOMER ISSUE	-
DMS_11900	18029	N	N	N	1	CUSTOMER ISSUE	-
DMS_11901	18030	N	N	N	1	CUSTOMER ISSUE	-
DMS_11902	18031	N	N	N	1	CUSTOMER ISSUE	-
DMS_11903	18032	N	N	N	1	CUSTOMER ISSUE	-
DMS_11904	18033	N	N	N	1	CUSTOMER ISSUE	-
DMS_11905	18034	N	N	N	1	CUSTOMER ISSUE	-
DMS_11906	18035	N	N	N	1	CUSTOMER ISSUE	-
DMS_11907	18036	N	N	N	1	CUSTOMER ISSUE	-
DMS_11909	18037	N	N	N	1	CUSTOMER ISSUE	-
DMS_11910	18038	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_11911	18039	N	N	N	1	CUSTOMER ISSUE	-
DMS_11912	18040	N	N	N	1	CUSTOMER ISSUE	-
DMS_11913	18041	N	N	N	1	CUSTOMER ISSUE	-
DMS_11914	18042	N	N	N	1	CUSTOMER ISSUE	-
DMS_11915	18043	N	N	N	1	CUSTOMER ISSUE	-
DMS_11916	18044	N	N	N	1	CUSTOMER ISSUE	-
DMS_11917	18045	N	N	N	1	CUSTOMER ISSUE	-
DMS_11918	18046	N	N	N	1	CUSTOMER ISSUE	-
DMS_11919	18047	N	N	N	1	CUSTOMER ISSUE	-
DMS_11920	18048	N	N	N	1	CUSTOMER ISSUE	-
DMS_11921	18049	N	N	N	1	CUSTOMER ISSUE	-
DMS_11922	18050	N	N	N	1	CUSTOMER ISSUE	-
DMS_11923	18051	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11924	18052	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11925	18053	N	N	N	1	CUSTOMER ISSUE	-
DMS_11926	18054	N	N	N	1	CUSTOMER ISSUE	-
DMS_11927	18055	N	N	N	1	CUSTOMER ISSUE	-
DMS_11928	18056	N	N	N	1	CUSTOMER ISSUE	-

DMS_11929	18057	N	N	N	1	CUSTOMER ISSUE	-
DMS_11930	18058	N	N	N	1	CUSTOMER ISSUE	-
DMS_11931	18059	N	N	N	1	CUSTOMER ISSUE	-
DMS_11932	18060	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_11933	18061	N	N	N	1	CUSTOMER ISSUE	-
DMS_11934	18062	N	N	N	1	CUSTOMER ISSUE	-
DMS_11935	18063	N	N	N	1	CUSTOMER ISSUE	-
DMS_11936	18064	N	N	N	1	CUSTOMER ISSUE	-
DMS_11937	18065	N	N	N	1	CUSTOMER ISSUE	-
DMS_11938	18066	N	N	N	1	CUSTOMER ISSUE	-
DMS_11939	18067	N	N	N	1	CUSTOMER ISSUE	-
DMS_11940	18068	N	N	N	1	CUSTOMER ISSUE	-
DMS_11941	18069	N	N	N	1	CUSTOMER ISSUE	-
DMS_11942	18070	N	N	N	1	CUSTOMER ISSUE	-
DMS_11943	18071	N	N	N	1	CUSTOMER ISSUE	-
DMS_11944	18072	N	N	N	1	CUSTOMER ISSUE	-
DMS_11945	18073	N	N	N	1	CUSTOMER ISSUE	-
DMS_11946	18074	N	N	N	1	CUSTOMER ISSUE	-
DMS_11947	18075	N	N	N	1	CUSTOMER ISSUE	-
DMS_11948	18076	N	N	N	1	CUSTOMER ISSUE	-
DMS_11949	18077	N	N	N	1	CUSTOMER ISSUE	-
DMS_11950	18078	N	N	N	1	CUSTOMER ISSUE	-
DMS_11951	18079	N	N	N	1	CUSTOMER ISSUE	-
DMS_11952	18080	N	N	N	1	CUSTOMER ISSUE	-
DMS_11953	18081	N	N	N	1	CUSTOMER ISSUE	-
DMS_11954	18082	N	N	N	1	CUSTOMER ISSUE	-
DMS_11955	18083	N	N	N	1	CUSTOMER ISSUE	-
DMS_11956	18084	N	N	N	1	CUSTOMER ISSUE	-
DMS_11957	18085	N	N	N	1	CUSTOMER ISSUE	-
DMS_11958	18086	N	N	N	1	CUSTOMER ISSUE	-
DMS_11959	18087	N	N	N	1	CUSTOMER ISSUE	-
DMS_11960	18088	N	N	N	1	CUSTOMER ISSUE	-
DMS_11961	18089	N	N	N	1	CUSTOMER ISSUE	-
DMS_11962	18090	N	N	N	1	CUSTOMER ISSUE	-
DMS_11963	18091	N	N	N	1	CUSTOMER ISSUE	-
DMS_11964	18092	N	N	N	1	CUSTOMER ISSUE	-
DMS_11965	18093	N	N	N	1	CUSTOMER ISSUE	-
DMS_11966	18094	N	N	N	1	CUSTOMER ISSUE	-
DMS_11967	18095	N	N	N	1	CUSTOMER ISSUE	-
DMS_11968	18096	N	N	N	1	CUSTOMER ISSUE	-
DMS_11969	18097	N	N	N	1	CUSTOMER ISSUE	-
DMS_11970	18098	N	N	N	1	CUSTOMER ISSUE	-
DMS_11971	18099	N	N	N	1	CUSTOMER ISSUE	-
DMS_11972	18100	N	N	N	1	CUSTOMER ISSUE	-
DMS_11974	18101	N	N	N	1	CUSTOMER ISSUE	-
DMS_11975	18102	N	N	N	1	CUSTOMER ISSUE	-
DMS_11976	18103	N	N	N	1	CUSTOMER ISSUE	-
DMS_11977	18104	N	N	N	1	CUSTOMER ISSUE	-
DMS_11978	18105	N	N	N	1	CUSTOMER ISSUE	-
DMS_11979	18106	N	N	N	1	CUSTOMER ISSUE	-
DMS_11980	18107	N	N	N	1	CUSTOMER ISSUE	-
DMS_11981	18108	N	N	N	1	CUSTOMER ISSUE	-
DMS_11982	18109	N	N	N	1	CUSTOMER ISSUE	-
DMS_11983	18110	N	N	N	1	CUSTOMER ISSUE	-
DMS_11984	18111	N	N	N	1	CUSTOMER ISSUE	-
DMS_11985	18112	N	N	N	1	CUSTOMER ISSUE	-
DMS_11986	18113	N	N	N	1	CUSTOMER ISSUE	-
DMS_11987	18114	N	N	N	1	CUSTOMER ISSUE	-
DMS_11988	18115	N	N	N	1	CUSTOMER ISSUE	-
DMS_11989	18116	N	N	N	1	CUSTOMER ISSUE	-
DMS_11990	18117	N	N	N	1	CUSTOMER ISSUE	-
DMS_11991	18118	N	N	N	1	CUSTOMER ISSUE	-
DMS_11992	18119	N	N	N	1	CUSTOMER ISSUE	-
DMS_11993	18120	N	N	N	1	CUSTOMER ISSUE	-
DMS_11994	18121	N	N	N	1	CUSTOMER ISSUE	-
DMS_11995	18122	N	N	N	1	CUSTOMER ISSUE	-
DMS_11996	18123	N	N	N	1	CUSTOMER ISSUE	-
DMS_11997	18124	N	N	N	1	CUSTOMER ISSUE	-
DMS_11998	18125	N	N	N	1	CUSTOMER ISSUE	-
DMS_11999	18126	N	N	N	1	CUSTOMER ISSUE	-
DMS_12000	18127	N	N	N	1	CUSTOMER ISSUE	-
DMS_12001	18128	N	N	N	1	CUSTOMER ISSUE	-
DMS_12002	18129	N	N	N	1	CUSTOMER ISSUE	-
DMS_12003	18130	N	N	N	1	CUSTOMER ISSUE	-
DMS_12004	18131	N	N	N	1	CUSTOMER ISSUE	-
DMS_12005	18132	N	N	N	1	CUSTOMER ISSUE	-
DMS_12006	18133	N	N	N	1	CUSTOMER ISSUE	-
DMS_12007	18134	N	N	N	1	CUSTOMER ISSUE	-
DMS_12008	18135	N	N	N	1	CUSTOMER ISSUE	-
DMS_12009	18136	N	N	N	1	CUSTOMER ISSUE	-

DMS_12010	18137	N	N	N	1	CUSTOMER ISSUE	-
DMS_12011	18138	N	N	N	1	CUSTOMER ISSUE	-
DMS_12013	18139	N	N	N	1	CUSTOMER ISSUE	-
DMS_12014	18140	N	N	N	1	CUSTOMER ISSUE	-
DMS_12016	18141	N	N	N	1	CUSTOMER ISSUE	-
DMS_12017	18142	N	N	N	1	CUSTOMER ISSUE	-
DMS_12018	18143	N	N	N	1	CUSTOMER ISSUE	-
DMS_12019	18144	N	N	N	1	CUSTOMER ISSUE	-
DMS_12020	18145	N	N	N	1	CUSTOMER ISSUE	-
DMS_12021	18146	N	N	N	1	CUSTOMER ISSUE	-
DMS_12022	18147	N	N	N	1	CUSTOMER ISSUE	-
DMS_12023	18148	N	N	N	1	CUSTOMER ISSUE	-
DMS_12024	18149	N	N	N	1	CUSTOMER ISSUE	-
DMS_12025	18150	N	N	N	1	CUSTOMER ISSUE	-
DMS_12026	18151	N	N	N	1	CUSTOMER ISSUE	-
DMS_12027	18152	N	N	N	1	CUSTOMER ISSUE	-
DMS_12028	18153	N	N	N	1	CUSTOMER ISSUE	-
DMS_12029	18154	N	N	N	1	CUSTOMER ISSUE	-
DMS_12030	18155	N	N	N	1	CUSTOMER ISSUE	-
DMS_12031	18156	N	N	N	1	CUSTOMER ISSUE	-
DMS_12032	18157	N	N	N	1	CUSTOMER ISSUE	-
DMS_12033	18158	N	N	N	1	CUSTOMER ISSUE	-
DMS_12034	18159	N	N	N	1	CUSTOMER ISSUE	-
DMS_12035	18160	N	N	N	1	CUSTOMER ISSUE	-
DMS_12036	18161	N	N	N	1	CUSTOMER ISSUE	-
DMS_12037	18162	N	N	N	1	CUSTOMER ISSUE	-
DMS_12038	18163	N	N	N	1	CUSTOMER ISSUE	-
DMS_12039	18164	N	N	N	1	CUSTOMER ISSUE	-
DMS_12040	18165	N	N	N	1	CUSTOMER ISSUE	-
DMS_12041	18166	N	N	N	1	CUSTOMER ISSUE	-
DMS_12042	18167	N	N	N	1	CUSTOMER ISSUE	-
DMS_12043	18168	N	N	N	1	CUSTOMER ISSUE	-
DMS_12044	18169	N	N	N	1	CUSTOMER ISSUE	-
DMS_12045	18170	N	N	N	1	CUSTOMER ISSUE	-
DMS_12046	18171	N	N	N	1	CUSTOMER ISSUE	-
DMS_12047	18172	N	N	N	1	CUSTOMER ISSUE	-
DMS_12048	18173	N	N	N	1	CUSTOMER ISSUE	-
DMS_12049	18174	N	N	N	1	CUSTOMER ISSUE	-
DMS_12050	18175	N	N	N	1	CUSTOMER ISSUE	-
DMS_12051	18176	N	N	N	1	CUSTOMER ISSUE	-
DMS_12052	18177	N	N	N	1	CUSTOMER ISSUE	-
DMS_12053	18178	N	N	N	1	CUSTOMER ISSUE	-
DMS_12054	18179	N	N	N	1	CUSTOMER ISSUE	-
DMS_12055	18180	N	N	N	1	CUSTOMER ISSUE	-
DMS_12056	18181	N	N	N	1	CUSTOMER ISSUE	-
DMS_12057	18182	N	N	N	1	CUSTOMER ISSUE	-
DMS_12058	18183	N	N	N	1	CUSTOMER ISSUE	-
DMS_12059	18184	N	N	N	1	CUSTOMER ISSUE	-
DMS_12060	18185	N	N	N	1	CUSTOMER ISSUE	-
DMS_12061	18186	N	N	N	1	CUSTOMER ISSUE	-
DMS_12062	18187	N	N	N	1	CUSTOMER ISSUE	-
DMS_12063	18188	N	N	N	1	CUSTOMER ISSUE	-
DMS_12064	18189	N	N	N	1	CUSTOMER ISSUE	-
DMS_12065	18190	N	N	N	1	CUSTOMER ISSUE	-
DMS_12066	18191	N	N	N	1	CUSTOMER ISSUE	-
DMS_12067	18192	N	N	N	1	CUSTOMER ISSUE	-
DMS_12068	18193	N	N	N	1	CUSTOMER ISSUE	-
DMS_12069	18194	N	N	N	1	CUSTOMER ISSUE	-
DMS_12070	18195	N	N	N	1	CUSTOMER ISSUE	-
DMS_12071	18196	N	N	N	1	CUSTOMER ISSUE	-
DMS_12072	18197	N	N	N	1	CUSTOMER ISSUE	-
DMS_12073	18198	N	N	N	1	CUSTOMER ISSUE	-
DMS_12074	18199	N	N	N	1	CUSTOMER ISSUE	-
DMS_12075	18200	N	N	N	1	CUSTOMER ISSUE	-
DMS_12076	18201	N	N	N	1	CUSTOMER ISSUE	-
DMS_12077	18202	N	N	N	1	CUSTOMER ISSUE	-
DMS_12078	18203	N	N	N	1	CUSTOMER ISSUE	-
DMS_12079	18204	N	N	N	1	CUSTOMER ISSUE	-
DMS_12080	18205	N	N	N	1	CUSTOMER ISSUE	-
DMS_12081	18206	N	N	N	1	CUSTOMER ISSUE	-
DMS_12082	18207	N	N	N	1	CUSTOMER ISSUE	-
DMS_12083	18208	N	N	N	1	CUSTOMER ISSUE	-
DMS_12084	18209	N	N	N	1	CUSTOMER ISSUE	-
DMS_12085	18210	N	N	N	1	CUSTOMER ISSUE	-
DMS_12086	18211	N	N	N	1	CUSTOMER ISSUE	-
DMS_12087	18212	N	N	N	1	CUSTOMER ISSUE	-
DMS_12088	18213	N	N	N	1	CUSTOMER ISSUE	-
DMS_12089	18214	N	N	N	1	CUSTOMER ISSUE	-
DMS_12090	18215	N	N	N	1	CUSTOMER ISSUE	-
DMS_12091	18216	N	N	N	1	CUSTOMER ISSUE	-

DMS_12092	18217	N	N	N	1	CUSTOMER ISSUE	-
DMS_12093	18218	N	N	N	1	CUSTOMER ISSUE	-
DMS_12094	18219	N	N	N	1	CUSTOMER ISSUE	-
DMS_12095	18220	N	N	N	1	CUSTOMER ISSUE	-
DMS_12096	18221	N	N	N	1	CUSTOMER ISSUE	-
DMS_12097	18222	N	N	N	1	CUSTOMER ISSUE	-
DMS_12098	18223	N	N	N	1	CUSTOMER ISSUE	-
DMS_12099	18224	N	N	N	1	CUSTOMER ISSUE	-
DMS_12100	18225	N	N	N	1	CUSTOMER ISSUE	-
DMS_12101	18226	N	N	N	1	CUSTOMER ISSUE	-
DMS_12102	18227	N	N	N	1	CUSTOMER ISSUE	-
DMS_12103	18228	N	N	N	1	CUSTOMER ISSUE	-
DMS_12104	18229	N	N	N	1	CUSTOMER ISSUE	-
DMS_12105	18230	N	N	N	1	CUSTOMER ISSUE	-
DMS_12106	18231	N	N	N	1	CUSTOMER ISSUE	-
DMS_12107	18232	N	N	N	1	CUSTOMER ISSUE	-
DMS_12108	18233	N	N	N	1	CUSTOMER ISSUE	-
DMS_12109	18234	N	N	N	1	CUSTOMER ISSUE	-
DMS_12110	18235	N	N	N	1	CUSTOMER ISSUE	-
DMS_12111	18236	N	N	N	1	CUSTOMER ISSUE	-
DMS_12112	18237	N	N	N	1	CUSTOMER ISSUE	-
DMS_12113	18238	N	N	N	1	CUSTOMER ISSUE	-
DMS_12114	18239	N	N	N	1	CUSTOMER ISSUE	-
DMS_12115	18240	N	N	N	1	CUSTOMER ISSUE	-
DMS_12116	18241	N	N	N	1	CUSTOMER ISSUE	-
DMS_12117	18242	N	N	N	1	CUSTOMER ISSUE	-
DMS_12118	18243	N	N	N	1	CUSTOMER ISSUE	-
DMS_12119	18244	N	N	N	1	CUSTOMER ISSUE	-
DMS_12120	18245	N	N	N	1	CUSTOMER ISSUE	-
DMS_12121	18246	N	N	N	1	CUSTOMER ISSUE	-
DMS_12122	18247	N	N	N	1	CUSTOMER ISSUE	-
DMS_12123	18248	N	N	N	1	CUSTOMER ISSUE	-
DMS_12124	18249	N	N	N	1	CUSTOMER ISSUE	-
DMS_12125	18250	N	N	N	1	CUSTOMER ISSUE	-
DMS_12126	18251	N	N	N	1	CUSTOMER ISSUE	-
DMS_12127	18252	N	N	N	1	CUSTOMER ISSUE	-
DMS_12128	18253	N	N	N	1	CUSTOMER ISSUE	-
DMS_12129	18254	N	N	N	1	CUSTOMER ISSUE	-
DMS_12130	18255	N	N	N	1	CUSTOMER ISSUE	-
DMS_12131	18256	N	N	N	1	CUSTOMER ISSUE	-
DMS_12132	18257	N	N	N	1	CUSTOMER ISSUE	-
DMS_12133	18258	N	N	N	1	CUSTOMER ISSUE	-
DMS_12134	18259	N	N	N	1	CUSTOMER ISSUE	-
DMS_12135	18260	N	N	N	1	CUSTOMER ISSUE	-
DMS_12136	18261	N	N	N	1	CUSTOMER ISSUE	-
DMS_12137	18262	N	N	N	1	CUSTOMER ISSUE	-
DMS_12138	18263	N	N	N	1	CUSTOMER ISSUE	-
DMS_12139	18264	N	N	N	1	CUSTOMER ISSUE	-
DMS_12140	18265	N	N	N	1	CUSTOMER ISSUE	-
DMS_12141	18266	N	N	N	1	CUSTOMER ISSUE	-
DMS_12142	18267	N	N	N	1	CUSTOMER ISSUE	-
DMS_12143	18268	N	N	N	1	CUSTOMER ISSUE	-
DMS_12144	18269	N	N	N	1	CUSTOMER ISSUE	-
DMS_12145	18270	N	N	N	1	CUSTOMER ISSUE	-
DMS_12146	18271	N	N	N	1	CUSTOMER ISSUE	-
DMS_12147	18272	N	N	N	1	CUSTOMER ISSUE	-
DMS_12149	18273	N	N	N	1	CUSTOMER ISSUE	-
DMS_12150	18274	N	N	N	1	CUSTOMER ISSUE	-
DMS_12152	18275	N	N	N	1	CUSTOMER ISSUE	-
DMS_12153	18276	N	N	N	1	CUSTOMER ISSUE	-
DMS_12154	18277	N	N	N	1	CUSTOMER ISSUE	-
DMS_12155	18278	N	N	N	1	CUSTOMER ISSUE	-
DMS_12157	18279	N	N	N	1	CUSTOMER ISSUE	-
DMS_12158	18280	N	N	N	1	CUSTOMER ISSUE	-
DMS_12159	18281	N	N	N	1	CUSTOMER ISSUE	-
DMS_12161	18282	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_12163	18283	N	N	N	1	CUSTOMER ISSUE	-
DMS_12164	18284	N	N	N	1	CUSTOMER ISSUE	-
DMS_12165	18285	N	N	N	1	CUSTOMER ISSUE	-
DMS_12166	18286	N	N	N	2	CUSTOMER ISSUE	-
DMS_12167	18287	N	N	N	1	CUSTOMER ISSUE	-
DMS_12168	18288	N	N	N	1	CUSTOMER ISSUE	-
DMS_12169	18289	N	N	N	1	CUSTOMER ISSUE	-
DMS_12170	18290	N	N	N	1	CUSTOMER ISSUE	-
DMS_12171	18291	N	N	N	1	CUSTOMER ISSUE	-
DMS_12172	18292	N	N	N	1	CUSTOMER ISSUE	-
DMS_12173	18293	N	N	N	1	CUSTOMER ISSUE	-
DMS_12174	18294	N	N	N	1	CUSTOMER ISSUE	-
DMS_12175	18295	N	N	N	1	CUSTOMER ISSUE	-
DMS_12176	18296	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_12177	18297	N	N	N	1	CUSTOMER ISSUE	-
DMS_12178	18298	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_12179	18299	N	N	N	1	CUSTOMER ISSUE	-
DMS_12180	18300	N	N	N	1	CUSTOMER ISSUE	-
DMS_12181	18301	N	N	N	1	CUSTOMER ISSUE	-
DMS_12182	18302	N	N	N	1	CUSTOMER ISSUE	-
DMS_12183	18303	N	N	N	1	CUSTOMER ISSUE	-
DMS_12184	18304	N	N	N	1	CUSTOMER ISSUE	-
DMS_12185	18305	N	N	N	1	CUSTOMER ISSUE	-
DMS_12186	18306	N	N	N	1	CUSTOMER ISSUE	-
DMS_12187	18307	N	N	N	2	CUSTOMER ISSUE	-
DMS_12188	18308	N	N	N	1	CUSTOMER ISSUE	-
DMS_12189	18309	N	N	N	1	CUSTOMER ISSUE	-
DMS_12190	18310	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_12191	18311	N	N	N	1	CUSTOMER ISSUE	-
DMS_12192	18312	N	N	N	1	CUSTOMER ISSUE	-
DMS_12193	18313	N	N	N	1	CUSTOMER ISSUE	-
DMS_12194	18314	N	N	N	1	CUSTOMER ISSUE	-
DMS_12195	18315	N	N	N	1	CUSTOMER ISSUE	-
DMS_12196	18316	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_12197	18317	N	N	N	1	CUSTOMER ISSUE	-
DMS_12198	18318	N	N	N	1	CUSTOMER ISSUE	-
DMS_12199	18319	N	N	N	1	CUSTOMER ISSUE	-
DMS_12200	18320	N	N	N	1	CUSTOMER ISSUE	-
DMS_12201	18321	N	N	N	1	CUSTOMER ISSUE	-
DMS_12202	18322	N	N	N	1	CUSTOMER ISSUE	-
DMS_12203	18323	N	N	N	1	CUSTOMER ISSUE	-
DMS_12204	18324	N	N	N	1	CUSTOMER ISSUE	-
DMS_12205	18325	N	N	N	1	CUSTOMER ISSUE	-
DMS_12206	18326	N	N	N	1	CUSTOMER ISSUE	-
DMS_12207	18327	N	N	N	1	CUSTOMER ISSUE	-
DMS_12208	18328	N	N	N	1	CUSTOMER ISSUE	-
DMS_12209	18329	N	N	N	1	CUSTOMER ISSUE	-
DMS_12210	18330	N	N	N	1	CUSTOMER ISSUE	-
DMS_12211	18331	N	N	N	1	CUSTOMER ISSUE	-
DMS_12212	18332	N	N	N	1	CUSTOMER ISSUE	-
DMS_12214	18333	N	N	N	1	CUSTOMER ISSUE	-
DMS_12215	18334	N	N	N	1	CUSTOMER ISSUE	-
DMS_12216	18335	N	N	N	1	CUSTOMER ISSUE	-
DMS_12217	18336	N	N	N	1	CUSTOMER ISSUE	-
DMS_12218	18337	N	N	N	1	CUSTOMER ISSUE	-
DMS_12219	18338	N	N	N	1	CUSTOMER ISSUE	-
DMS_12220	18339	N	N	N	1	CUSTOMER ISSUE	-
DMS_12221	18340	N	N	N	1	CUSTOMER ISSUE	-
DMS_12222	18341	N	N	N	1	CUSTOMER ISSUE	-
DMS_12223	18342	N	N	N	1	CUSTOMER ISSUE	-
DMS_12224	18343	N	N	N	1	CUSTOMER ISSUE	-
DMS_12225	18344	N	N	N	1	CUSTOMER ISSUE	-
DMS_12226	18345	N	N	N	1	CUSTOMER ISSUE	-
DMS_12227	18346	N	N	N	1	CUSTOMER ISSUE	-
DMS_12228	18347	N	N	N	1	CUSTOMER ISSUE	-
DMS_12229	18348	N	N	N	1	CUSTOMER ISSUE	-
DMS_12230	18349	N	N	N	1	CUSTOMER ISSUE	-
DMS_12231	18350	N	N	N	1	CUSTOMER ISSUE	-
DMS_12232	18351	N	N	N	1	CUSTOMER ISSUE	-
DMS_12233	18352	N	N	N	1	CUSTOMER ISSUE	-
DMS_12234	18353	N	N	N	1	CUSTOMER ISSUE	-
DMS_12235	18354	N	N	N	1	CUSTOMER ISSUE	-
DMS_12236	18355	N	N	N	1	CUSTOMER ISSUE	-
DMS_12237	18356	N	N	N	1	CUSTOMER ISSUE	-
DMS_12238	18357	N	N	N	1	CUSTOMER ISSUE	-
DMS_12239	18358	N	N	N	1	CUSTOMER ISSUE	-
DMS_12240	18359	N	N	N	1	CUSTOMER ISSUE	-
DMS_12241	18360	N	N	N	1	CUSTOMER ISSUE	-
DMS_12242	18361	N	N	N	1	CUSTOMER ISSUE	-
DMS_12243	18362	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_12244	18363	N	N	N	1	CUSTOMER ISSUE	-
DMS_12245	18364	N	N	N	1	CUSTOMER ISSUE	-
DMS_12246	18365	N	N	N	1	CUSTOMER ISSUE	-
DMS_12247	18366	N	N	N	1	CUSTOMER ISSUE	-
DMS_12248	18367	N	N	N	1	CUSTOMER ISSUE	-
DMS_12249	18368	N	N	N	1	CUSTOMER ISSUE	-
DMS_12250	18369	N	N	N	1	CUSTOMER ISSUE	-
DMS_12251	18370	N	N	N	1	CUSTOMER ISSUE	-
DMS_12252	18371	N	N	N	1	CUSTOMER ISSUE	-
DMS_12253	18372	N	N	N	1	CUSTOMER ISSUE	-
DMS_12254	18373	N	N	N	1	CUSTOMER ISSUE	-
DMS_12255	18374	N	N	Y	1	TX - REPLACE	2500
DMS_12258	18375	N	N	N	1	CUSTOMER ISSUE	-
DMS_12259	18376	N	N	N	1	CUSTOMER ISSUE	-

DMS_12260	18377	N	N	N	1	CUSTOMER ISSUE	-
DMS_12261	18378	N	N	N	1	CUSTOMER ISSUE	-
DMS_12262	18379	N	N	N	1	CUSTOMER ISSUE	-
DMS_12263	18380	N	N	N	1	CUSTOMER ISSUE	-
DMS_12265	18381	N	N	N	1	CUSTOMER ISSUE	-
DMS_12266	18382	N	N	N	1	CUSTOMER ISSUE	-
DMS_12267	18383	N	N	N	1	CUSTOMER ISSUE	-
DMS_12268	18384	N	N	N	1	CUSTOMER ISSUE	-
DMS_12269	18385	N	N	N	1	CUSTOMER ISSUE	-
DMS_12270	18386	N	N	N	1	CUSTOMER ISSUE	-
DMS_12271	18387	N	N	N	1	CUSTOMER ISSUE	-
DMS_12272	18388	N	N	N	1	CUSTOMER ISSUE	-
DMS_12273	18389	N	N	N	1	CUSTOMER ISSUE	-
DMS_12275	18390	N	N	N	1	CUSTOMER ISSUE	-
DMS_12276	18391	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_12278	18392	N	N	N	1	CUSTOMER ISSUE	-
DMS_12279	18393	N	N	N	1	CUSTOMER ISSUE	-
DMS_12280	18394	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_12281	18395	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_12282	18396	N	N	Y	1	TX - REPLACE	2500
DMS_12283	18397	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_12284	18398	N	N	N	1	CUSTOMER ISSUE	-
DMS_12285	18399	N	N	N	1	CUSTOMER ISSUE	-
DMS_12286	18400	N	N	N	1	CUSTOMER ISSUE	-
DMS_12287	18401	N	N	N	1	CUSTOMER ISSUE	-
DMS_12288	18402	N	N	N	1	CUSTOMER ISSUE	-
DMS_12289	18403	N	N	N	1	CUSTOMER ISSUE	-
DMS_12290	18404	N	N	N	1	CUSTOMER ISSUE	-
DMS_12291	18405	N	N	N	1	CUSTOMER ISSUE	-
DMS_12292	18406	N	N	N	1	CUSTOMER ISSUE	-
DMS_12293	18407	N	N	N	1	CUSTOMER ISSUE	-
DMS_12294	18408	N	N	N	1	CUSTOMER ISSUE	-
DMS_12295	18409	N	N	N	1	CUSTOMER ISSUE	-
DMS_12296	18410	N	N	N	1	CUSTOMER ISSUE	-
DMS_12297	18411	N	N	N	1	CUSTOMER ISSUE	-
DMS_12298	18412	N	N	N	1	CUSTOMER ISSUE	-
DMS_12299	18413	N	N	N	1	CUSTOMER ISSUE	-
DMS_12300	18414	N	N	N	1	CUSTOMER ISSUE	-
DMS_12301	18415	N	N	N	1	CUSTOMER ISSUE	-
DMS_12302	18416	N	N	N	1	CUSTOMER ISSUE	-
DMS_12303	18417	N	N	N	1	CUSTOMER ISSUE	-
DMS_12304	18418	N	N	N	1	CUSTOMER ISSUE	-
DMS_12305	18419	N	N	N	1	CUSTOMER ISSUE	-
DMS_12306	18420	N	N	N	1	CUSTOMER ISSUE	-
DMS_12307	18421	N	N	N	1	CUSTOMER ISSUE	-
DMS_12308	18422	N	N	N	1	CUSTOMER ISSUE	-
DMS_12309	18423	N	N	N	1	CUSTOMER ISSUE	-
DMS_12310	18424	N	N	N	1	CUSTOMER ISSUE	-
DMS_12311	18425	N	N	N	1	CUSTOMER ISSUE	-
DMS_12312	18426	N	N	N	1	CUSTOMER ISSUE	-
DMS_12313	18427	N	N	N	1	CUSTOMER ISSUE	-
DMS_12314	18428	N	N	N	1	CUSTOMER ISSUE	-
DMS_12315	18429	N	N	N	1	CUSTOMER ISSUE	-
DMS_12316	18430	N	N	N	1	CUSTOMER ISSUE	-
DMS_12317	18431	N	N	N	1	CUSTOMER ISSUE	-
DMS_12318	18432	N	N	N	1	CUSTOMER ISSUE	-
DMS_12319	18433	N	N	N	1	CUSTOMER ISSUE	-
DMS_12320	18434	N	N	N	1	CUSTOMER ISSUE	-
DMS_12321	18435	N	N	N	1	CUSTOMER ISSUE	-
DMS_12322	18436	N	N	N	2	CUSTOMER ISSUE	-
DMS_12323	18437	N	N	N	1	CUSTOMER ISSUE	-
DMS_12324	18438	N	N	N	1	CUSTOMER ISSUE	-
DMS_12325	18439	N	N	N	1	CUSTOMER ISSUE	-
DMS_12326	18440	N	N	N	1	CUSTOMER ISSUE	-
DMS_12327	18441	N	N	N	1	CUSTOMER ISSUE	-
DMS_12328	18442	N	N	N	1	CUSTOMER ISSUE	-
DMS_12329	18443	N	N	N	1	CUSTOMER ISSUE	-
DMS_12330	18444	N	N	N	1	CUSTOMER ISSUE	-
DMS_12331	18445	N	N	N	1	CUSTOMER ISSUE	-
DMS_12332	18446	N	N	N	1	CUSTOMER ISSUE	-
DMS_12333	18447	N	N	N	1	CUSTOMER ISSUE	-
DMS_12334	18448	N	N	N	1	CUSTOMER ISSUE	-
DMS_12335	18449	N	N	N	1	CUSTOMER ISSUE	-
DMS_12336	18450	N	N	N	1	CUSTOMER ISSUE	-
DMS_12337	18451	N	N	N	1	CUSTOMER ISSUE	-
DMS_12338	18452	N	N	N	1	CUSTOMER ISSUE	-
DMS_12339	18453	N	N	N	1	CUSTOMER ISSUE	-
DMS_12340	18454	N	N	N	1	CUSTOMER ISSUE	-
DMS_12341	18455	N	N	N	1	CUSTOMER ISSUE	-
DMS_12342	18456	N	N	N	1	CUSTOMER ISSUE	-

DMS_12343	18457	N	N	N	1	CUSTOMER ISSUE	-
DMS_12344	18458	N	N	N	1	CUSTOMER ISSUE	-
DMS_12345	18459	N	N	N	1	CUSTOMER ISSUE	-
DMS_12346	18460	N	N	N	1	CUSTOMER ISSUE	-
DMS_12347	18461	N	N	N	2	CUSTOMER ISSUE	-
DMS_12348	18462	N	N	N	1	CUSTOMER ISSUE	-
DMS_12349	18463	N	N	N	1	CUSTOMER ISSUE	-
DMS_12350	18464	N	N	N	1	CUSTOMER ISSUE	-
DMS_12351	18465	N	N	N	1	CUSTOMER ISSUE	-
DMS_12352	18466	N	N	N	1	CUSTOMER ISSUE	-
DMS_12353	18467	N	N	N	1	CUSTOMER ISSUE	-
DMS_12354	18468	N	N	N	1	CUSTOMER ISSUE	-
DMS_12355	18469	N	N	N	1	CUSTOMER ISSUE	-
DMS_12356	18470	N	N	N	1	CUSTOMER ISSUE	-
DMS_12357	18471	N	N	N	1	CUSTOMER ISSUE	-
DMS_12358	18472	N	N	N	1	CUSTOMER ISSUE	-
DMS_12359	18473	N	N	N	2	CUSTOMER ISSUE	-
DMS_12360	18474	N	N	N	1	CUSTOMER ISSUE	-
DMS_12361	18475	N	N	N	1	CUSTOMER ISSUE	-
DMS_12362	18476	N	N	N	1	CUSTOMER ISSUE	-
DMS_12363	18477	N	N	N	1	CUSTOMER ISSUE	-
DMS_12364	18478	N	N	N	1	CUSTOMER ISSUE	-
DMS_12365	18479	N	N	N	1	CUSTOMER ISSUE	-
DMS_12366	18480	N	N	N	1	CUSTOMER ISSUE	-
DMS_12367	18481	N	N	N	1	CUSTOMER ISSUE	-
DMS_12368	18482	N	N	N	1	CUSTOMER ISSUE	-
DMS_12369	18483	N	N	N	1	CUSTOMER ISSUE	-
DMS_12370	18484	N	N	N	1	CUSTOMER ISSUE	-
DMS_12371	18485	N	N	N	1	CUSTOMER ISSUE	-
DMS_12372	18486	N	N	N	1	CUSTOMER ISSUE	-
DMS_12373	18487	N	N	N	1	CUSTOMER ISSUE	-
DMS_12374	18488	N	N	N	1	CUSTOMER ISSUE	-
DMS_12375	18489	N	N	N	1	CUSTOMER ISSUE	-
DMS_12376	18490	N	N	N	1	CUSTOMER ISSUE	-
DMS_12377	18491	N	N	N	1	CUSTOMER ISSUE	-
DMS_12378	18492	N	N	N	1	CUSTOMER ISSUE	-
DMS_12379	18493	N	N	N	1	CUSTOMER ISSUE	-
DMS_12380	18494	N	N	N	1	CUSTOMER ISSUE	-
DMS_12381	18495	N	N	N	1	CUSTOMER ISSUE	-
DMS_12382	18496	N	N	N	1	CUSTOMER ISSUE	-
DMS_12383	18497	N	N	N	1	CUSTOMER ISSUE	-
DMS_12384	18498	N	N	N	1	CUSTOMER ISSUE	-
DMS_12385	18499	N	N	N	1	CUSTOMER ISSUE	-
DMS_12386	18500	N	N	N	1	CUSTOMER ISSUE	-
DMS_12387	18501	N	N	N	1	CUSTOMER ISSUE	-
DMS_12388	18502	N	N	N	1	CUSTOMER ISSUE	-
DMS_12389	18503	N	N	N	1	CUSTOMER ISSUE	-
DMS_12390	18504	N	N	N	1	CUSTOMER ISSUE	-
DMS_12391	18505	N	N	N	1	CUSTOMER ISSUE	-
DMS_12392	18506	N	N	N	1	CUSTOMER ISSUE	-
DMS_12393	18507	N	N	N	1	CUSTOMER ISSUE	-
DMS_12394	18508	N	N	N	1	CUSTOMER ISSUE	-
DMS_12395	18509	N	N	N	1	CUSTOMER ISSUE	-
DMS_12396	18510	N	N	N	1	CUSTOMER ISSUE	-
DMS_12397	18511	N	N	N	1	CUSTOMER ISSUE	-
DMS_12398	18512	N	N	N	1	CUSTOMER ISSUE	-
DMS_12399	18513	N	N	N	1	CUSTOMER ISSUE	-
DMS_12400	18514	N	N	N	1	CUSTOMER ISSUE	-
DMS_12401	18515	N	N	N	1	CUSTOMER ISSUE	-
DMS_12402	18516	N	N	N	1	CUSTOMER ISSUE	-
DMS_12403	18517	N	N	N	1	CUSTOMER ISSUE	-
DMS_12404	18518	N	N	N	1	CUSTOMER ISSUE	-
DMS_12405	18519	N	N	N	1	CUSTOMER ISSUE	-
DMS_12406	18520	N	N	N	1	CUSTOMER ISSUE	-
DMS_12407	18521	N	N	N	1	CUSTOMER ISSUE	-
DMS_12408	18522	N	N	N	1	CUSTOMER ISSUE	-
DMS_12409	18523	N	N	N	1	CUSTOMER ISSUE	-
DMS_12410	18524	N	N	N	1	CUSTOMER ISSUE	-
DMS_12411	18525	N	N	N	1	CUSTOMER ISSUE	-
DMS_12412	18526	N	N	N	1	CUSTOMER ISSUE	-
DMS_12413	18527	N	N	N	1	CUSTOMER ISSUE	-
DMS_12414	18528	N	N	N	1	CUSTOMER ISSUE	-
DMS_12415	18529	N	N	N	1	CUSTOMER ISSUE	-
DMS_12416	18530	N	N	N	1	CUSTOMER ISSUE	-
DMS_12417	18531	N	N	N	1	CUSTOMER ISSUE	-
DMS_12418	18532	N	N	N	1	CUSTOMER ISSUE	-
DMS_12419	18533	N	N	N	1	CUSTOMER ISSUE	-
DMS_12420	18534	N	N	N	1	CUSTOMER ISSUE	-
DMS_12421	18535	N	N	N	1	CUSTOMER ISSUE	-
DMS_12422	18536	N	N	N	1	CUSTOMER ISSUE	-

DMS_12423	18537	N	N	N	1	CUSTOMER ISSUE	-
DMS_12424	18538	N	N	N	1	CUSTOMER ISSUE	-
DMS_12425	18539	N	N	N	1	CUSTOMER ISSUE	-
DMS_12426	18540	N	N	N	1	CUSTOMER ISSUE	-
DMS_12427	18541	N	N	N	1	CUSTOMER ISSUE	-
DMS_12428	18542	N	N	N	1	CUSTOMER ISSUE	-
DMS_12429	18543	N	N	N	1	CUSTOMER ISSUE	-
DMS_12430	18544	N	N	N	1	CUSTOMER ISSUE	-
DMS_12431	18545	N	N	N	1	CUSTOMER ISSUE	-
DMS_12432	18546	N	N	N	1	CUSTOMER ISSUE	-
DMS_12433	18547	N	N	N	1	CUSTOMER ISSUE	-
DMS_12434	18548	N	N	N	1	CUSTOMER ISSUE	-
DMS_12435	18549	N	N	N	1	CUSTOMER ISSUE	-
DMS_12436	18550	N	N	N	1	CUSTOMER ISSUE	-
DMS_12437	18551	N	N	N	1	CUSTOMER ISSUE	-
DMS_12438	18552	N	N	N	1	CUSTOMER ISSUE	-
DMS_12439	18553	N	N	N	1	CUSTOMER ISSUE	-
DMS_12440	18554	N	N	N	1	CUSTOMER ISSUE	-
DMS_12441	18555	N	N	N	1	CUSTOMER ISSUE	-
DMS_12442	18556	N	N	N	1	CUSTOMER ISSUE	-
DMS_12443	18557	N	N	N	1	CUSTOMER ISSUE	-
DMS_12444	18558	N	N	N	1	CUSTOMER ISSUE	-
DMS_12445	18559	N	N	N	1	CUSTOMER ISSUE	-
DMS_12446	18560	N	N	N	1	CUSTOMER ISSUE	-
DMS_12447	18561	N	N	N	1	CUSTOMER ISSUE	-
DMS_12448	18562	N	N	N	1	CUSTOMER ISSUE	-
DMS_12449	18563	N	N	N	1	CUSTOMER ISSUE	-
DMS_12450	18564	N	N	N	1	CUSTOMER ISSUE	-
DMS_12451	18565	N	N	N	1	CUSTOMER ISSUE	-
DMS_12452	18566	N	N	N	1	CUSTOMER ISSUE	-
DMS_12453	18567	N	N	N	1	CUSTOMER ISSUE	-
DMS_12454	18568	N	N	N	1	CUSTOMER ISSUE	-
DMS_12455	18569	N	N	N	1	CUSTOMER ISSUE	-
DMS_12457	18570	N	N	N	1	CUSTOMER ISSUE	-
DMS_12458	18571	N	N	N	1	CUSTOMER ISSUE	-
DMS_12459	18572	N	N	N	1	CUSTOMER ISSUE	-
DMS_12460	18573	N	N	N	1	CUSTOMER ISSUE	-
DMS_12461	18574	N	N	N	1	CUSTOMER ISSUE	-
DMS_12462	18575	N	N	N	1	CUSTOMER ISSUE	-
DMS_12463	18576	N	N	N	1	CUSTOMER ISSUE	-
DMS_12464	18577	N	N	N	1	CUSTOMER ISSUE	-
DMS_12465	18578	N	N	N	1	CUSTOMER ISSUE	-
DMS_12466	18579	N	N	N	1	CUSTOMER ISSUE	-
DMS_12467	18580	N	N	N	1	CUSTOMER ISSUE	-
DMS_12468	18581	N	N	N	1	CUSTOMER ISSUE	-
DMS_12469	18582	N	N	N	1	CUSTOMER ISSUE	-
DMS_12470	18583	N	N	N	1	CUSTOMER ISSUE	-
DMS_12471	18584	N	N	N	1	CUSTOMER ISSUE	-
DMS_12472	18585	N	N	N	1	CUSTOMER ISSUE	-
DMS_12473	18586	N	N	N	1	CUSTOMER ISSUE	-
DMS_12474	18587	N	N	N	1	CUSTOMER ISSUE	-
DMS_12475	18588	N	N	N	1	CUSTOMER ISSUE	-
DMS_12476	18589	N	N	N	1	CUSTOMER ISSUE	-
DMS_12477	18590	N	N	N	1	CUSTOMER ISSUE	-
DMS_12478	18591	N	N	N	1	CUSTOMER ISSUE	-
DMS_12479	18592	N	N	N	1	CUSTOMER ISSUE	-
DMS_12480	18593	N	N	N	1	CUSTOMER ISSUE	-
DMS_12481	18594	N	N	N	1	CUSTOMER ISSUE	-
DMS_12482	18595	N	N	N	1	CUSTOMER ISSUE	-
DMS_12483	18596	N	N	N	1	CUSTOMER ISSUE	-
DMS_12484	18597	N	N	N	1	CUSTOMER ISSUE	-
DMS_12485	18598	N	N	N	1	CUSTOMER ISSUE	-
DMS_12486	18599	N	N	N	1	CUSTOMER ISSUE	-
DMS_12487	18600	N	N	N	1	CUSTOMER ISSUE	-
DMS_12488	18601	N	N	N	1	CUSTOMER ISSUE	-
DMS_12489	18602	N	N	N	1	CUSTOMER ISSUE	-
DMS_12490	18603	N	N	N	1	CUSTOMER ISSUE	-
DMS_12491	18604	N	N	N	1	CUSTOMER ISSUE	-
DMS_12492	18605	N	N	N	1	CUSTOMER ISSUE	-
DMS_12493	18606	N	N	N	1	CUSTOMER ISSUE	-
DMS_12494	18607	N	N	N	1	CUSTOMER ISSUE	-
DMS_12495	18608	N	N	N	1	CUSTOMER ISSUE	-
DMS_12496	18609	N	N	N	1	CUSTOMER ISSUE	-
DMS_12497	18610	N	N	N	1	CUSTOMER ISSUE	-
DMS_12498	18611	N	N	N	1	CUSTOMER ISSUE	-
DMS_12499	18612	N	N	N	1	CUSTOMER ISSUE	-
DMS_12500	18613	N	N	N	1	CUSTOMER ISSUE	-
DMS_12501	18614	N	N	N	1	CUSTOMER ISSUE	-
DMS_12502	18615	N	N	N	1	CUSTOMER ISSUE	-
DMS_12503	18616	N	N	N	1	CUSTOMER ISSUE	-

DMS_12504	18617	N	N	N	1	CUSTOMER ISSUE	-
DMS_12505	18618	N	N	N	1	CUSTOMER ISSUE	-
DMS_12506	18619	N	N	N	1	CUSTOMER ISSUE	-
DMS_12507	18620	N	N	N	1	CUSTOMER ISSUE	-
DMS_12508	18621	N	N	N	1	CUSTOMER ISSUE	-
DMS_12509	18622	N	N	N	1	CUSTOMER ISSUE	-
DMS_12510	18623	N	N	N	1	CUSTOMER ISSUE	-
DMS_12511	18624	N	N	N	1	CUSTOMER ISSUE	-
DMS_12512	18625	N	N	N	1	CUSTOMER ISSUE	-
DMS_12513	18626	N	N	N	1	CUSTOMER ISSUE	-
DMS_12514	18627	N	N	N	1	CUSTOMER ISSUE	-
DMS_12515	18628	N	N	N	1	CUSTOMER ISSUE	-
DMS_12516	18629	N	N	N	1	CUSTOMER ISSUE	-
DMS_12517	18630	N	N	N	1	CUSTOMER ISSUE	-
DMS_12518	18631	N	N	N	1	CUSTOMER ISSUE	-
DMS_12519	18632	N	N	N	1	CUSTOMER ISSUE	-
DMS_12520	18633	N	N	N	1	CUSTOMER ISSUE	-
DMS_12521	18634	N	N	N	1	CUSTOMER ISSUE	-
DMS_12522	18635	N	N	N	1	CUSTOMER ISSUE	-
DMS_12523	18636	N	N	N	1	CUSTOMER ISSUE	-
DMS_12524	18637	N	N	N	1	CUSTOMER ISSUE	-
DMS_12525	18638	N	N	N	1	CUSTOMER ISSUE	-
DMS_12526	18639	N	N	N	1	CUSTOMER ISSUE	-
DMS_12527	18640	N	N	N	1	CUSTOMER ISSUE	-
DMS_12528	18641	N	N	N	1	CUSTOMER ISSUE	-
DMS_12529	18642	N	N	N	1	CUSTOMER ISSUE	-
DMS_12530	18643	N	N	N	1	CUSTOMER ISSUE	-
DMS_12531	18644	N	N	N	1	CUSTOMER ISSUE	-
DMS_12532	18645	N	N	N	1	CUSTOMER ISSUE	-
DMS_12533	18646	N	N	N	1	CUSTOMER ISSUE	-
DMS_12534	18647	N	N	N	1	CUSTOMER ISSUE	-
DMS_12535	18648	N	N	N	1	CUSTOMER ISSUE	-
DMS_12536	18649	N	N	N	1	CUSTOMER ISSUE	-
DMS_12537	18650	N	N	N	1	CUSTOMER ISSUE	-
DMS_12538	18651	N	N	N	1	CUSTOMER ISSUE	-
DMS_12539	18652	N	N	N	1	CUSTOMER ISSUE	-
DMS_12540	18653	N	N	N	1	CUSTOMER ISSUE	-
DMS_12541	18654	N	N	N	1	CUSTOMER ISSUE	-
DMS_12542	18655	N	N	N	1	CUSTOMER ISSUE	-
DMS_12543	18656	N	N	N	1	CUSTOMER ISSUE	-
DMS_12544	18657	N	N	N	1	CUSTOMER ISSUE	-
DMS_12545	18658	N	N	N	1	CUSTOMER ISSUE	-
DMS_12546	18659	N	N	N	1	CUSTOMER ISSUE	-
DMS_12547	18660	N	N	N	1	CUSTOMER ISSUE	-
DMS_12548	18661	N	N	N	1	CUSTOMER ISSUE	-
DMS_12549	18662	N	N	N	1	CUSTOMER ISSUE	-
DMS_12550	18663	N	N	N	1	CUSTOMER ISSUE	-
DMS_12551	18664	N	N	N	1	CUSTOMER ISSUE	-
DMS_12552	18665	N	N	N	1	CUSTOMER ISSUE	-
DMS_12553	18666	N	N	N	1	CUSTOMER ISSUE	-
DMS_12554	18667	N	N	N	1	CUSTOMER ISSUE	-
DMS_12555	18668	N	N	N	1	CUSTOMER ISSUE	-
DMS_12556	18669	N	N	N	1	CUSTOMER ISSUE	-
DMS_12557	18670	N	N	N	1	CUSTOMER ISSUE	-
DMS_12558	18671	N	N	N	1	CUSTOMER ISSUE	-
DMS_12559	18672	N	N	N	1	CUSTOMER ISSUE	-
DMS_12560	18673	N	N	N	1	CUSTOMER ISSUE	-
DMS_12561	18674	N	N	N	1	CUSTOMER ISSUE	-
DMS_12562	18675	N	N	N	1	CUSTOMER ISSUE	-
DMS_12563	18676	N	N	N	1	CUSTOMER ISSUE	-
DMS_12564	18677	N	N	N	1	CUSTOMER ISSUE	-
DMS_12565	18678	N	N	N	1	CUSTOMER ISSUE	-
DMS_12567	18679	N	N	N	1	CUSTOMER ISSUE	-
DMS_12568	18680	N	N	N	1	CUSTOMER ISSUE	-
DMS_12569	18681	N	N	N	1	CUSTOMER ISSUE	-
DMS_12570	18682	N	N	N	1	CUSTOMER ISSUE	-
DMS_12571	18683	N	N	N	1	CUSTOMER ISSUE	-
DMS_12572	18684	N	N	N	1	CUSTOMER ISSUE	-
DMS_12573	18685	N	N	N	1	CUSTOMER ISSUE	-
DMS_12574	18686	N	N	N	1	CUSTOMER ISSUE	-
DMS_12575	18687	N	N	N	1	CUSTOMER ISSUE	-
DMS_12576	18688	N	N	N	1	CUSTOMER ISSUE	-
DMS_12577	18689	N	N	N	1	CUSTOMER ISSUE	-
DMS_12578	18690	N	N	N	1	CUSTOMER ISSUE	-
DMS_12579	18691	N	N	N	1	CUSTOMER ISSUE	-
DMS_12580	18692	N	N	N	1	CUSTOMER ISSUE	-
DMS_12581	18693	N	N	N	1	CUSTOMER ISSUE	-
DMS_12582	18694	N	N	N	1	CUSTOMER ISSUE	-
DMS_12583	18695	N	N	N	1	CUSTOMER ISSUE	-
DMS_12584	18696	N	N	N	1	CUSTOMER ISSUE	-

DMS_12585	18697	N	N	N	1	CUSTOMER ISSUE	-
DMS_12586	18698	N	N	N	1	CUSTOMER ISSUE	-
DMS_12587	18699	N	N	N	1	CUSTOMER ISSUE	-
DMS_12588	18700	N	N	N	1	CUSTOMER ISSUE	-
DMS_12589	18701	N	N	N	1	CUSTOMER ISSUE	-
DMS_12590	18702	N	N	N	1	CUSTOMER ISSUE	-
DMS_12591	18703	N	N	N	1	CUSTOMER ISSUE	-
DMS_12592	18704	N	N	N	1	CUSTOMER ISSUE	-
DMS_12593	18705	N	N	N	1	CUSTOMER ISSUE	-
DMS_12594	18706	N	N	N	1	CUSTOMER ISSUE	-
DMS_12595	18707	N	N	N	1	CUSTOMER ISSUE	-
DMS_12596	18708	N	N	N	1	CUSTOMER ISSUE	-
DMS_12597	18709	N	N	N	1	CUSTOMER ISSUE	-
DMS_12598	18710	N	N	N	1	CUSTOMER ISSUE	-
DMS_12599	18711	N	N	N	1	CUSTOMER ISSUE	-
DMS_12600	18712	N	N	N	1	CUSTOMER ISSUE	-
DMS_12601	18713	N	N	N	1	CUSTOMER ISSUE	-
DMS_12602	18714	N	N	N	1	CUSTOMER ISSUE	-
DMS_12603	18715	N	N	N	1	CUSTOMER ISSUE	-
DMS_12604	18716	N	N	N	1	CUSTOMER ISSUE	-
DMS_12605	18717	N	N	N	1	CUSTOMER ISSUE	-
DMS_12606	18718	N	N	N	1	CUSTOMER ISSUE	-
DMS_12607	18719	N	N	N	1	CUSTOMER ISSUE	-
DMS_12608	18720	N	N	N	1	CUSTOMER ISSUE	-
DMS_12609	18721	N	N	N	1	CUSTOMER ISSUE	-
DMS_12610	18722	N	N	N	1	CUSTOMER ISSUE	-
DMS_12611	18723	N	N	N	1	CUSTOMER ISSUE	-
DMS_12612	18724	N	N	N	1	CUSTOMER ISSUE	-
DMS_12613	18725	N	N	N	1	CUSTOMER ISSUE	-
DMS_12614	18726	N	N	N	1	CUSTOMER ISSUE	-
DMS_12615	18727	N	N	N	1	CUSTOMER ISSUE	-
DMS_12616	18728	N	N	N	1	CUSTOMER ISSUE	-
DMS_12617	18729	N	N	N	1	CUSTOMER ISSUE	-
DMS_12618	18730	N	N	N	1	CUSTOMER ISSUE	-
DMS_12619	18731	N	N	N	1	CUSTOMER ISSUE	-
DMS_12620	18732	N	N	N	1	CUSTOMER ISSUE	-
DMS_12621	18733	N	N	N	1	CUSTOMER ISSUE	-
DMS_12622	18734	N	N	N	1	CUSTOMER ISSUE	-
DMS_12623	18735	N	N	N	1	CUSTOMER ISSUE	-
DMS_12624	18736	N	N	N	1	CUSTOMER ISSUE	-
DMS_12625	18737	N	N	N	1	CUSTOMER ISSUE	-
DMS_12626	18738	N	N	N	1	CUSTOMER ISSUE	-
DMS_12627	18739	N	N	N	1	CUSTOMER ISSUE	-
DMS_12628	18740	N	N	N	1	CUSTOMER ISSUE	-
DMS_12629	18741	N	N	N	1	CUSTOMER ISSUE	-
DMS_12630	18742	N	N	N	1	CUSTOMER ISSUE	-
DMS_12631	18743	N	N	N	1	CUSTOMER ISSUE	-
DMS_12632	18744	N	N	N	1	CUSTOMER ISSUE	-
DMS_12633	18745	N	N	N	1	CUSTOMER ISSUE	-
DMS_12634	18746	N	N	N	1	CUSTOMER ISSUE	-
DMS_12635	18747	N	N	N	1	CUSTOMER ISSUE	-
DMS_12636	18748	N	N	N	1	CUSTOMER ISSUE	-
DMS_12637	18749	N	N	N	1	CUSTOMER ISSUE	-
DMS_12638	18750	N	N	N	1	CUSTOMER ISSUE	-
DMS_12639	18751	N	N	N	1	CUSTOMER ISSUE	-
DMS_12640	18752	N	N	N	1	CUSTOMER ISSUE	-
DMS_12641	18753	N	N	N	1	CUSTOMER ISSUE	-
DMS_12642	18754	N	N	N	1	CUSTOMER ISSUE	-
DMS_12643	18755	N	N	N	1	CUSTOMER ISSUE	-
DMS_12644	18756	N	N	N	1	CUSTOMER ISSUE	-
DMS_12645	18757	N	N	N	1	CUSTOMER ISSUE	-
DMS_12646	18758	N	N	N	1	CUSTOMER ISSUE	-
DMS_12647	18759	N	N	N	1	CUSTOMER ISSUE	-
DMS_12648	18760	N	N	N	1	CUSTOMER ISSUE	-
DMS_12649	18761	N	N	N	1	CUSTOMER ISSUE	-
DMS_12650	18762	N	N	N	1	CUSTOMER ISSUE	-
DMS_12651	18763	N	N	N	1	CUSTOMER ISSUE	-
DMS_12652	18764	N	N	N	1	CUSTOMER ISSUE	-
DMS_12653	18765	N	N	N	1	CUSTOMER ISSUE	-
DMS_12654	18766	N	N	N	1	CUSTOMER ISSUE	-
DMS_12655	18767	N	N	N	1	CUSTOMER ISSUE	-
DMS_12656	18768	N	N	N	1	CUSTOMER ISSUE	-
DMS_12657	18769	N	N	N	1	CUSTOMER ISSUE	-
DMS_12658	18770	N	N	N	1	CUSTOMER ISSUE	-
DMS_12659	18771	N	N	N	1	CUSTOMER ISSUE	-
DMS_12660	18772	N	N	N	1	CUSTOMER ISSUE	-
DMS_12661	18773	N	N	N	1	CUSTOMER ISSUE	-
DMS_12662	18774	N	N	N	1	CUSTOMER ISSUE	-
DMS_12663	18775	N	N	N	1	CUSTOMER ISSUE	-
DMS_12664	18776	N	N	N	1	CUSTOMER ISSUE	-

DMS_12665	18777	N	N	N	1	CUSTOMER ISSUE	-
DMS_12666	18778	N	N	N	1	CUSTOMER ISSUE	-
DMS_12667	18779	N	N	N	1	CUSTOMER ISSUE	-
DMS_12668	18780	N	N	N	1	CUSTOMER ISSUE	-
DMS_12669	18781	N	N	N	1	CUSTOMER ISSUE	-
DMS_12670	18782	N	N	N	1	CUSTOMER ISSUE	-
DMS_12671	18783	N	N	N	1	CUSTOMER ISSUE	-
DMS_12672	18784	N	N	N	1	CUSTOMER ISSUE	-
DMS_12673	18785	N	N	N	1	CUSTOMER ISSUE	-
DMS_12674	18786	N	N	N	1	CUSTOMER ISSUE	-
DMS_12675	18787	N	N	N	1	CUSTOMER ISSUE	-
DMS_12676	18788	N	N	N	1	CUSTOMER ISSUE	-
DMS_12677	18789	N	N	N	1	CUSTOMER ISSUE	-
DMS_12678	18790	N	N	N	1	CUSTOMER ISSUE	-
DMS_12679	18791	N	N	N	1	CUSTOMER ISSUE	-
DMS_12680	18792	N	N	N	1	CUSTOMER ISSUE	-
DMS_12681	18793	N	N	N	1	CUSTOMER ISSUE	-
DMS_12682	18794	N	N	N	1	CUSTOMER ISSUE	-
DMS_12683	18795	N	N	N	1	CUSTOMER ISSUE	-
DMS_12684	18796	N	N	N	1	CUSTOMER ISSUE	-
DMS_12685	18797	N	N	N	2	CUSTOMER ISSUE	-
DMS_12686	18798	N	N	N	1	CUSTOMER ISSUE	-
DMS_12687	18799	N	N	N	1	CUSTOMER ISSUE	-
DMS_12688	18800	N	N	N	1	CUSTOMER ISSUE	-
DMS_12689	18801	N	N	N	1	CUSTOMER ISSUE	-
DMS_12690	18802	N	N	N	1	CUSTOMER ISSUE	-
DMS_12691	18803	N	N	N	1	CUSTOMER ISSUE	-
DMS_12692	18804	N	N	N	1	CUSTOMER ISSUE	-
DMS_12693	18805	N	N	N	1	CUSTOMER ISSUE	-
DMS_12694	18806	N	N	N	1	CUSTOMER ISSUE	-
DMS_12695	18807	N	N	N	1	CUSTOMER ISSUE	-
DMS_12696	18808	N	N	N	1	CUSTOMER ISSUE	-
DMS_12697	18809	N	N	N	1	CUSTOMER ISSUE	-
DMS_12698	18810	N	N	N	1	CUSTOMER ISSUE	-
DMS_12699	18811	N	N	N	1	CUSTOMER ISSUE	-
DMS_12700	18812	N	N	N	1	CUSTOMER ISSUE	-
DMS_12701	18813	N	N	N	1	CUSTOMER ISSUE	-
DMS_12702	18814	N	N	N	1	CUSTOMER ISSUE	-
DMS_12703	18815	N	N	N	1	CUSTOMER ISSUE	-
DMS_12704	18816	N	N	N	1	CUSTOMER ISSUE	-
DMS_12705	18817	N	N	N	1	CUSTOMER ISSUE	-
DMS_12706	18818	N	N	N	1	CUSTOMER ISSUE	-
DMS_12707	18819	N	N	N	1	CUSTOMER ISSUE	-
DMS_12708	18820	N	N	N	1	CUSTOMER ISSUE	-
DMS_12709	18821	N	N	N	1	CUSTOMER ISSUE	-
DMS_12710	18822	N	N	N	1	CUSTOMER ISSUE	-
DMS_12711	18823	N	N	N	1	CUSTOMER ISSUE	-
DMS_12712	18824	N	N	N	1	CUSTOMER ISSUE	-
DMS_12713	18825	N	N	N	1	CUSTOMER ISSUE	-
DMS_12714	18826	N	N	N	1	CUSTOMER ISSUE	-
DMS_12715	18827	N	N	N	1	CUSTOMER ISSUE	-
DMS_12716	18828	N	N	N	1	CUSTOMER ISSUE	-
DMS_12717	18829	N	N	N	1	CUSTOMER ISSUE	-
DMS_12718	18830	N	N	N	1	CUSTOMER ISSUE	-
DMS_12719	18831	N	N	N	1	CUSTOMER ISSUE	-
DMS_12720	18832	N	N	N	1	CUSTOMER ISSUE	-
DMS_12721	18833	N	N	N	1	CUSTOMER ISSUE	-
DMS_12722	18834	N	N	N	1	CUSTOMER ISSUE	-
DMS_12723	18835	N	N	N	1	CUSTOMER ISSUE	-
DMS_12724	18836	N	N	N	1	CUSTOMER ISSUE	-
DMS_12725	18837	N	N	N	1	CUSTOMER ISSUE	-
DMS_12726	18838	N	N	N	1	CUSTOMER ISSUE	-
DMS_12727	18839	N	N	N	1	CUSTOMER ISSUE	-
DMS_12728	18840	N	N	N	1	CUSTOMER ISSUE	-
DMS_12729	18841	N	N	N	1	CUSTOMER ISSUE	-
DMS_12730	18842	N	N	N	1	CUSTOMER ISSUE	-
DMS_12731	18843	N	N	N	1	CUSTOMER ISSUE	-
DMS_12732	18844	N	N	N	1	CUSTOMER ISSUE	-
DMS_12733	18845	N	N	N	1	CUSTOMER ISSUE	-
DMS_12734	18846	N	N	N	1	CUSTOMER ISSUE	-
DMS_12735	18847	N	N	N	1	CUSTOMER ISSUE	-
DMS_12736	18848	N	N	N	1	CUSTOMER ISSUE	-
DMS_12737	18849	N	N	N	1	CUSTOMER ISSUE	-
DMS_12738	18850	N	N	N	1	CUSTOMER ISSUE	-
DMS_12739	18851	N	N	N	1	CUSTOMER ISSUE	-
DMS_12740	18852	N	N	N	1	CUSTOMER ISSUE	-
DMS_12741	18853	N	N	N	1	CUSTOMER ISSUE	-
DMS_12742	18854	N	N	N	1	CUSTOMER ISSUE	-
DMS_12743	18855	N	N	N	1	CUSTOMER ISSUE	-
DMS_12744	18856	N	N	N	1	CUSTOMER ISSUE	-

DMS_12745	18857	N	N	N	1	CUSTOMER ISSUE	-
DMS_12746	18858	N	N	N	1	CUSTOMER ISSUE	-
DMS_12747	18859	N	N	N	1	CUSTOMER ISSUE	-
DMS_12748	18860	N	N	N	1	CUSTOMER ISSUE	-
DMS_12749	18861	N	N	N	1	CUSTOMER ISSUE	-
DMS_12750	18862	N	N	N	1	CUSTOMER ISSUE	-
DMS_12751	18863	N	N	N	1	CUSTOMER ISSUE	-
DMS_12752	18864	N	N	N	1	CUSTOMER ISSUE	-
DMS_12753	18865	N	N	N	1	CUSTOMER ISSUE	-
DMS_12754	18866	N	N	N	1	CUSTOMER ISSUE	-
DMS_12755	18867	N	N	N	1	CUSTOMER ISSUE	-
DMS_12756	18868	N	N	N	1	CUSTOMER ISSUE	-
DMS_12757	18869	N	N	N	1	CUSTOMER ISSUE	-
DMS_12758	18870	N	N	N	1	CUSTOMER ISSUE	-
DMS_12759	18871	N	N	N	1	CUSTOMER ISSUE	-
DMS_12760	18872	N	N	N	1	CUSTOMER ISSUE	-
DMS_12761	18873	N	N	N	1	CUSTOMER ISSUE	-
DMS_12762	18874	N	N	N	1	CUSTOMER ISSUE	-
DMS_12763	18875	N	N	N	1	CUSTOMER ISSUE	-
DMS_12764	18876	N	N	N	1	CUSTOMER ISSUE	-
DMS_12765	18877	N	N	N	1	CUSTOMER ISSUE	-
DMS_12766	18878	N	N	N	1	CUSTOMER ISSUE	-
DMS_12767	18879	N	N	N	1	CUSTOMER ISSUE	-
DMS_12768	18880	N	N	N	1	CUSTOMER ISSUE	-
DMS_12769	18881	N	N	N	1	CUSTOMER ISSUE	-
DMS_12770	18882	N	N	N	1	CUSTOMER ISSUE	-
DMS_12771	18883	N	N	N	1	CUSTOMER ISSUE	-
DMS_12772	18884	N	N	N	1	CUSTOMER ISSUE	-
DMS_12773	18885	N	N	N	1	CUSTOMER ISSUE	-
DMS_12774	18886	N	N	N	1	CUSTOMER ISSUE	-
DMS_12775	18887	N	N	N	1	CUSTOMER ISSUE	-
DMS_12776	18888	N	N	N	1	CUSTOMER ISSUE	-
DMS_12777	18889	N	N	N	1	CUSTOMER ISSUE	-
DMS_12778	18890	N	N	N	1	CUSTOMER ISSUE	-
DMS_12779	18891	N	N	N	1	CUSTOMER ISSUE	-
DMS_12784	18892	N	N	N	1	CUSTOMER ISSUE	-
DMS_12785	18893	N	N	N	1	CUSTOMER ISSUE	-
DMS_12786	18894	N	N	N	1	CUSTOMER ISSUE	-
DMS_12787	18895	N	N	N	1	CUSTOMER ISSUE	-
DMS_12788	18896	N	N	N	1	CUSTOMER ISSUE	-
DMS_12789	18897	N	N	N	1	CUSTOMER ISSUE	-
DMS_12790	18898	N	N	N	1	CUSTOMER ISSUE	-
DMS_12791	18899	N	N	N	1	CUSTOMER ISSUE	-
DMS_12792	18900	N	N	N	1	CUSTOMER ISSUE	-
DMS_12793	18901	N	N	N	1	CUSTOMER ISSUE	-
DMS_12794	18902	N	N	N	1	CUSTOMER ISSUE	-
DMS_12795	18903	N	N	N	1	CUSTOMER ISSUE	-
DMS_12796	18904	N	N	N	1	CUSTOMER ISSUE	-
DMS_12797	18905	N	N	N	1	CUSTOMER ISSUE	-
DMS_12798	18906	N	N	N	1	CUSTOMER ISSUE	-
DMS_12799	18907	N	N	N	1	CUSTOMER ISSUE	-
DMS_12800	18908	N	N	N	1	CUSTOMER ISSUE	-
DMS_12801	18909	N	N	N	1	CUSTOMER ISSUE	-
DMS_12802	18910	N	N	N	1	CUSTOMER ISSUE	-
DMS_12803	18911	N	N	N	1	CUSTOMER ISSUE	-
DMS_12804	18912	N	N	N	1	CUSTOMER ISSUE	-
DMS_12805	18913	N	N	N	1	CUSTOMER ISSUE	-
DMS_12806	18914	N	N	N	1	CUSTOMER ISSUE	-
DMS_12807	18915	N	N	N	1	CUSTOMER ISSUE	-
DMS_12808	18916	N	N	N	1	CUSTOMER ISSUE	-
DMS_12809	18917	N	N	N	1	CUSTOMER ISSUE	-
DMS_12810	18918	N	N	N	1	CUSTOMER ISSUE	-
DMS_12811	18919	N	N	N	1	CUSTOMER ISSUE	-
DMS_12812	18920	N	N	N	1	CUSTOMER ISSUE	-
DMS_12813	18921	N	N	N	1	CUSTOMER ISSUE	-
DMS_12814	18922	N	N	N	1	CUSTOMER ISSUE	-
DMS_12815	18923	N	N	N	1	CUSTOMER ISSUE	-
DMS_12816	18924	N	N	N	1	CUSTOMER ISSUE	-
DMS_12817	18925	N	N	N	1	CUSTOMER ISSUE	-
DMS_12818	18926	N	N	N	1	CUSTOMER ISSUE	-
DMS_12819	18927	N	N	N	1	CUSTOMER ISSUE	-
DMS_12820	18928	N	N	N	1	CUSTOMER ISSUE	-
DMS_12821	18929	N	N	N	1	CUSTOMER ISSUE	-
DMS_12822	18930	N	N	N	1	CUSTOMER ISSUE	-
DMS_12823	18931	N	N	N	1	CUSTOMER ISSUE	-
DMS_12824	18932	N	N	N	1	CUSTOMER ISSUE	-
DMS_12825	18933	N	N	N	1	CUSTOMER ISSUE	-
DMS_12826	18934	N	N	N	1	CUSTOMER ISSUE	-
DMS_12827	18935	N	N	N	1	CUSTOMER ISSUE	-
DMS_12828	18936	N	N	N	1	CUSTOMER ISSUE	-

DMS_12829	18937	N	N	N	1	CUSTOMER ISSUE	-
DMS_12830	18938	N	N	N	1	CUSTOMER ISSUE	-
DMS_12831	18939	N	N	N	1	CUSTOMER ISSUE	-
DMS_12832	18940	N	N	N	1	CUSTOMER ISSUE	-
DMS_12833	18941	N	N	N	1	CUSTOMER ISSUE	-
DMS_12834	18942	N	N	N	1	CUSTOMER ISSUE	-
DMS_12835	18943	N	N	N	1	CUSTOMER ISSUE	-
DMS_12836	18944	N	N	N	1	CUSTOMER ISSUE	-
DMS_12837	18945	N	N	N	1	CUSTOMER ISSUE	-
DMS_12838	18946	N	N	N	2	CUSTOMER ISSUE	-
DMS_12839	18947	N	N	N	1	CUSTOMER ISSUE	-
DMS_12840	18948	N	N	N	1	CUSTOMER ISSUE	-
DMS_12841	18949	N	N	N	1	CUSTOMER ISSUE	-
DMS_12842	18950	N	N	N	1	CUSTOMER ISSUE	-
DMS_12843	18951	N	N	N	1	CUSTOMER ISSUE	-
DMS_12844	18952	N	N	N	1	CUSTOMER ISSUE	-
DMS_12845	18953	N	N	N	1	CUSTOMER ISSUE	-
DMS_12846	18954	N	N	N	1	CUSTOMER ISSUE	-
DMS_12847	18955	N	N	N	1	CUSTOMER ISSUE	-
DMS_12848	18956	N	N	N	1	CUSTOMER ISSUE	-
DMS_12849	18957	N	N	N	1	CUSTOMER ISSUE	-
DMS_12850	18958	N	N	N	1	CUSTOMER ISSUE	-
DMS_12851	18959	N	N	N	1	CUSTOMER ISSUE	-
DMS_12852	18960	N	N	N	1	CUSTOMER ISSUE	-
DMS_12853	18961	N	N	N	1	CUSTOMER ISSUE	-
DMS_12854	18962	N	N	N	1	CUSTOMER ISSUE	-
DMS_12855	18963	N	N	N	1	CUSTOMER ISSUE	-
DMS_12856	18964	N	N	N	1	CUSTOMER ISSUE	-
DMS_12857	18965	N	N	N	1	CUSTOMER ISSUE	-
DMS_12858	18966	N	N	N	1	CUSTOMER ISSUE	-
DMS_12859	18967	N	N	N	1	CUSTOMER ISSUE	-
DMS_12860	18968	N	N	N	1	CUSTOMER ISSUE	-
DMS_12861	18969	N	N	N	1	CUSTOMER ISSUE	-
DMS_12862	18970	N	N	N	1	CUSTOMER ISSUE	-
DMS_12863	18971	N	N	N	1	CUSTOMER ISSUE	-
DMS_12864	18972	N	N	N	1	CUSTOMER ISSUE	-
DMS_12865	18973	N	N	N	1	CUSTOMER ISSUE	-
DMS_12866	18974	N	N	N	1	CUSTOMER ISSUE	-
DMS_12867	18975	N	N	N	1	CUSTOMER ISSUE	-
DMS_12868	18976	N	N	N	1	CUSTOMER ISSUE	-
DMS_12869	18977	N	N	N	1	CUSTOMER ISSUE	-
DMS_12870	18978	N	N	N	1	CUSTOMER ISSUE	-
DMS_12871	18979	N	N	N	1	CUSTOMER ISSUE	-
DMS_12872	18980	N	N	N	1	CUSTOMER ISSUE	-
DMS_12873	18981	N	N	N	1	CUSTOMER ISSUE	-
DMS_12874	18982	N	N	N	1	CUSTOMER ISSUE	-
DMS_12875	18983	N	N	N	1	CUSTOMER ISSUE	-
DMS_12876	18984	N	N	N	1	CUSTOMER ISSUE	-
DMS_12877	18985	N	N	N	1	CUSTOMER ISSUE	-
DMS_12878	18986	N	N	N	1	CUSTOMER ISSUE	-
DMS_12879	18987	N	N	N	1	CUSTOMER ISSUE	-
DMS_12880	18988	N	N	N	1	CUSTOMER ISSUE	-
DMS_12881	18989	N	N	N	1	CUSTOMER ISSUE	-
DMS_12882	18990	N	N	N	1	CUSTOMER ISSUE	-
DMS_12883	18991	N	N	N	1	CUSTOMER ISSUE	-
DMS_12884	18992	N	N	N	1	CUSTOMER ISSUE	-
DMS_12885	18993	N	N	N	1	CUSTOMER ISSUE	-
DMS_12886	18994	N	N	N	1	CUSTOMER ISSUE	-
DMS_12887	18995	N	N	N	1	CUSTOMER ISSUE	-
DMS_12888	18996	N	N	N	1	CUSTOMER ISSUE	-
DMS_12889	18997	N	N	N	1	CUSTOMER ISSUE	-
DMS_12890	18998	N	N	N	1	CUSTOMER ISSUE	-
DMS_12891	18999	N	N	N	1	CUSTOMER ISSUE	-
DMS_12892	19000	N	N	N	1	CUSTOMER ISSUE	-
DMS_12893	19001	N	N	N	1	CUSTOMER ISSUE	-
DMS_12894	19002	N	N	N	1	CUSTOMER ISSUE	-
DMS_12895	19003	N	N	N	1	CUSTOMER ISSUE	-
DMS_12896	19004	N	N	N	1	CUSTOMER ISSUE	-
DMS_12897	19005	N	N	N	1	CUSTOMER ISSUE	-
DMS_12898	19006	N	N	N	1	CUSTOMER ISSUE	-
DMS_12899	19007	N	N	N	1	CUSTOMER ISSUE	-
DMS_12900	19008	N	N	N	1	CUSTOMER ISSUE	-
DMS_12901	19009	N	N	N	1	CUSTOMER ISSUE	-
DMS_12902	19010	N	N	N	1	CUSTOMER ISSUE	-
DMS_12903	19011	N	N	N	1	CUSTOMER ISSUE	-
DMS_12904	19012	N	N	N	1	CUSTOMER ISSUE	-
DMS_12905	19013	N	N	N	1	CUSTOMER ISSUE	-
DMS_12906	19014	N	N	N	1	CUSTOMER ISSUE	-
DMS_12907	19015	N	N	N	1	CUSTOMER ISSUE	-
DMS_12908	19016	N	N	N	1	CUSTOMER ISSUE	-

DMS_12909	19017	N	N	N	1	CUSTOMER ISSUE	-
DMS_12910	19018	N	N	N	1	CUSTOMER ISSUE	-
DMS_12911	19019	N	N	N	1	CUSTOMER ISSUE	-
DMS_12912	19020	N	N	N	1	CUSTOMER ISSUE	-
DMS_12913	19021	N	N	N	1	CUSTOMER ISSUE	-
DMS_12914	19022	N	N	N	1	CUSTOMER ISSUE	-
DMS_12915	19023	N	N	N	1	CUSTOMER ISSUE	-
DMS_12916	19024	N	N	N	1	CUSTOMER ISSUE	-
DMS_12917	19025	N	N	N	1	CUSTOMER ISSUE	-
DMS_12918	19026	N	N	N	1	CUSTOMER ISSUE	-
DMS_12919	19027	N	N	N	1	CUSTOMER ISSUE	-
DMS_12920	19028	N	N	N	1	CUSTOMER ISSUE	-
DMS_12921	19029	N	N	N	1	CUSTOMER ISSUE	-
DMS_12922	19030	N	N	N	1	CUSTOMER ISSUE	-
DMS_12923	19031	N	N	N	1	CUSTOMER ISSUE	-
DMS_12924	19032	N	N	N	1	CUSTOMER ISSUE	-
DMS_12925	19033	N	N	N	1	CUSTOMER ISSUE	-
DMS_12926	19034	N	N	N	1	CUSTOMER ISSUE	-
DMS_12928	19035	N	N	N	1	CUSTOMER ISSUE	-
DMS_12929	19036	N	N	N	1	CUSTOMER ISSUE	-
DMS_12930	19037	N	N	N	1	CUSTOMER ISSUE	-
DMS_12931	19038	N	N	N	1	CUSTOMER ISSUE	-
DMS_12932	19039	N	N	N	1	CUSTOMER ISSUE	-
DMS_12933	19040	N	N	N	1	CUSTOMER ISSUE	-
DMS_12934	19041	N	N	N	1	CUSTOMER ISSUE	-
DMS_12935	19042	N	N	N	1	CUSTOMER ISSUE	-
DMS_12936	19043	N	N	N	1	CUSTOMER ISSUE	-
DMS_12937	19044	N	N	N	1	CUSTOMER ISSUE	-
DMS_12938	19045	N	N	N	1	CUSTOMER ISSUE	-
DMS_12939	19046	N	N	N	1	CUSTOMER ISSUE	-
DMS_12940	19047	N	N	N	1	CUSTOMER ISSUE	-
DMS_12941	19048	N	N	N	1	CUSTOMER ISSUE	-
DMS_12942	19049	N	N	N	1	CUSTOMER ISSUE	-
DMS_12943	19050	N	N	N	1	CUSTOMER ISSUE	-
DMS_12944	19051	N	N	N	1	CUSTOMER ISSUE	-
DMS_12945	19052	N	N	N	1	CUSTOMER ISSUE	-
DMS_12946	19053	N	N	N	1	CUSTOMER ISSUE	-
DMS_12947	19054	N	N	N	1	CUSTOMER ISSUE	-
DMS_12948	19055	N	N	N	1	CUSTOMER ISSUE	-
DMS_12949	19056	N	N	N	1	CUSTOMER ISSUE	-
DMS_12950	19057	N	N	N	1	CUSTOMER ISSUE	-
DMS_12951	19058	N	N	N	1	CUSTOMER ISSUE	-
DMS_12952	19059	N	N	N	1	CUSTOMER ISSUE	-
DMS_12953	19060	N	N	N	1	CUSTOMER ISSUE	-
DMS_12954	19061	N	N	N	1	CUSTOMER ISSUE	-
DMS_12955	19062	N	N	N	1	CUSTOMER ISSUE	-
DMS_12956	19063	N	N	N	1	CUSTOMER ISSUE	-
DMS_12957	19064	N	N	N	1	CUSTOMER ISSUE	-
DMS_12958	19065	N	N	N	1	CUSTOMER ISSUE	-
DMS_12959	19066	N	N	N	1	CUSTOMER ISSUE	-
DMS_12960	19067	N	N	N	1	CUSTOMER ISSUE	-
DMS_12961	19068	N	N	N	2	CUSTOMER ISSUE	-
DMS_12962	19069	N	N	N	1	CUSTOMER ISSUE	-
DMS_12963	19070	N	N	N	1	CUSTOMER ISSUE	-
DMS_12964	19071	N	N	N	1	CUSTOMER ISSUE	-
DMS_12965	19072	N	N	N	1	CUSTOMER ISSUE	-
DMS_12966	19073	N	N	N	1	CUSTOMER ISSUE	-
DMS_12967	19074	N	N	N	1	CUSTOMER ISSUE	-
DMS_12968	19075	N	N	N	1	CUSTOMER ISSUE	-
DMS_12969	19076	N	N	N	1	CUSTOMER ISSUE	-
DMS_12970	19077	N	N	N	1	CUSTOMER ISSUE	-
DMS_12971	19078	N	N	N	1	CUSTOMER ISSUE	-
DMS_12972	19079	N	N	N	1	CUSTOMER ISSUE	-
DMS_12973	19080	N	N	N	1	CUSTOMER ISSUE	-
DMS_12974	19081	N	N	N	1	CUSTOMER ISSUE	-
DMS_12975	19082	N	N	N	1	CUSTOMER ISSUE	-
DMS_12976	19083	N	N	N	1	CUSTOMER ISSUE	-
DMS_12977	19084	N	N	N	1	CUSTOMER ISSUE	-
DMS_12978	19085	N	N	N	1	CUSTOMER ISSUE	-
DMS_12979	19086	N	N	N	1	CUSTOMER ISSUE	-
DMS_12980	19087	N	N	N	1	CUSTOMER ISSUE	-
DMS_12981	19088	N	N	N	1	CUSTOMER ISSUE	-
DMS_12982	19089	N	N	N	1	CUSTOMER ISSUE	-
DMS_12983	19090	N	N	N	1	CUSTOMER ISSUE	-
DMS_12984	19091	N	N	N	1	CUSTOMER ISSUE	-
DMS_12985	19092	N	N	N	1	CUSTOMER ISSUE	-
DMS_12986	19093	N	N	N	1	CUSTOMER ISSUE	-
DMS_12987	19094	N	N	N	1	CUSTOMER ISSUE	-
DMS_12988	19095	N	N	N	1	CUSTOMER ISSUE	-
DMS_12989	19096	N	N	N	1	CUSTOMER ISSUE	-

DMS_12990	19097	N	N	N	1	CUSTOMER ISSUE	-
DMS_12991	19098	N	N	N	1	CUSTOMER ISSUE	-
DMS_12992	19099	N	N	N	1	CUSTOMER ISSUE	-
DMS_12993	19100	N	N	N	1	CUSTOMER ISSUE	-
DMS_12994	19101	N	N	N	1	CUSTOMER ISSUE	-
DMS_12995	19102	N	N	N	1	CUSTOMER ISSUE	-
DMS_12996	19103	N	N	N	1	CUSTOMER ISSUE	-
DMS_12997	19104	N	N	N	1	CUSTOMER ISSUE	-
DMS_12998	19105	N	N	N	1	CUSTOMER ISSUE	-
DMS_12999	19106	N	N	N	1	CUSTOMER ISSUE	-
DMS_13000	19107	N	N	N	1	CUSTOMER ISSUE	-
DMS_13001	19108	N	N	N	1	CUSTOMER ISSUE	-
DMS_13002	19109	N	N	N	1	CUSTOMER ISSUE	-
DMS_13003	19110	N	N	N	1	CUSTOMER ISSUE	-
DMS_13004	19111	N	N	N	1	CUSTOMER ISSUE	-
DMS_13005	19112	N	N	N	1	CUSTOMER ISSUE	-
DMS_13006	19113	N	N	N	1	CUSTOMER ISSUE	-
DMS_13007	19114	N	N	N	1	CUSTOMER ISSUE	-
DMS_13008	19115	N	N	N	1	CUSTOMER ISSUE	-
DMS_13009	19116	N	N	N	1	CUSTOMER ISSUE	-
DMS_13010	19117	N	N	N	1	CUSTOMER ISSUE	-
DMS_13011	19118	N	N	N	1	CUSTOMER ISSUE	-
DMS_13012	19119	N	N	N	1	CUSTOMER ISSUE	-
DMS_13013	19120	N	N	N	1	CUSTOMER ISSUE	-
DMS_13014	19121	N	N	N	1	CUSTOMER ISSUE	-
DMS_13015	19122	N	N	N	1	CUSTOMER ISSUE	-
DMS_13016	19123	N	N	N	1	CUSTOMER ISSUE	-
DMS_13017	19124	N	N	N	1	CUSTOMER ISSUE	-
DMS_13018	19125	N	N	N	1	CUSTOMER ISSUE	-
DMS_13019	19126	N	N	N	1	CUSTOMER ISSUE	-
DMS_13020	19127	N	N	N	1	CUSTOMER ISSUE	-
DMS_13021	19128	N	N	N	1	CUSTOMER ISSUE	-
DMS_13022	19129	N	N	N	1	CUSTOMER ISSUE	-
DMS_13023	19130	N	N	N	1	CUSTOMER ISSUE	-
DMS_13024	19131	N	N	N	1	CUSTOMER ISSUE	-
DMS_13025	19132	N	N	N	1	CUSTOMER ISSUE	-
DMS_13026	19133	N	N	N	1	CUSTOMER ISSUE	-
DMS_13027	19134	N	N	N	1	CUSTOMER ISSUE	-
DMS_13028	19135	N	N	N	1	CUSTOMER ISSUE	-
DMS_13029	19136	N	N	N	1	CUSTOMER ISSUE	-
DMS_13030	19137	N	N	N	1	CUSTOMER ISSUE	-
DMS_13031	19138	N	N	N	1	CUSTOMER ISSUE	-
DMS_13032	19139	N	N	N	1	CUSTOMER ISSUE	-
DMS_13033	19140	N	N	N	1	CUSTOMER ISSUE	-
DMS_13034	19141	N	N	N	1	CUSTOMER ISSUE	-
DMS_13035	19142	N	N	N	1	CUSTOMER ISSUE	-
DMS_13036	19143	N	N	N	1	CUSTOMER ISSUE	-
DMS_13037	19144	N	N	N	1	CUSTOMER ISSUE	-
DMS_13038	19145	N	N	N	1	CUSTOMER ISSUE	-
DMS_13039	19146	N	N	N	1	CUSTOMER ISSUE	-
DMS_13040	19147	N	N	N	1	CUSTOMER ISSUE	-
DMS_13041	19148	N	N	N	1	CUSTOMER ISSUE	-
DMS_13042	19149	N	N	N	1	CUSTOMER ISSUE	-
DMS_13043	19150	N	N	N	1	CUSTOMER ISSUE	-
DMS_13044	19151	N	N	N	1	CUSTOMER ISSUE	-
DMS_13045	19152	N	N	N	1	CUSTOMER ISSUE	-
DMS_13046	19153	N	N	N	1	CUSTOMER ISSUE	-
DMS_13047	19154	N	N	N	1	CUSTOMER ISSUE	-
DMS_13048	19155	N	N	N	1	CUSTOMER ISSUE	-
DMS_13049	19156	N	N	N	1	CUSTOMER ISSUE	-
DMS_13050	19157	N	N	N	1	CUSTOMER ISSUE	-
DMS_13051	19158	N	N	N	1	CUSTOMER ISSUE	-
DMS_13052	19159	N	N	N	1	CUSTOMER ISSUE	-
DMS_13053	19160	N	N	N	1	CUSTOMER ISSUE	-
DMS_13054	19161	N	N	N	1	CUSTOMER ISSUE	-
DMS_13055	19162	N	N	N	1	CUSTOMER ISSUE	-
DMS_13056	19163	N	N	N	1	CUSTOMER ISSUE	-
DMS_13057	19164	N	N	N	1	CUSTOMER ISSUE	-
DMS_13058	19165	N	N	N	4	CUSTOMER ISSUE	-
DMS_13059	19166	N	N	N	2	CUSTOMER ISSUE	-
DMS_13060	19167	N	N	N	1	CUSTOMER ISSUE	-
DMS_13061	19168	N	N	N	1	CUSTOMER ISSUE	-
DMS_13062	19169	N	N	N	1	CUSTOMER ISSUE	-
DMS_13063	19170	N	N	N	1	CUSTOMER ISSUE	-
DMS_13064	19171	N	N	N	1	CUSTOMER ISSUE	-
DMS_13065	19172	N	N	N	1	CUSTOMER ISSUE	-
DMS_13066	19173	N	N	N	1	CUSTOMER ISSUE	-
DMS_13067	19174	N	N	N	1	CUSTOMER ISSUE	-
DMS_13068	19175	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13069	19176	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_13070	19177	N	N	N	1	CUSTOMER ISSUE	-
DMS_13071	19178	N	N	N	1	CUSTOMER ISSUE	-
DMS_13072	19179	N	N	N	1	CUSTOMER ISSUE	-
DMS_13073	19180	N	N	N	1	CUSTOMER ISSUE	-
DMS_13074	19181	N	N	N	1	CUSTOMER ISSUE	-
DMS_13075	19182	N	N	N	1	CUSTOMER ISSUE	-
DMS_13076	19183	N	N	N	1	CUSTOMER ISSUE	-
DMS_13077	19184	N	N	N	1	CUSTOMER ISSUE	-
DMS_13078	19185	N	N	N	1	CUSTOMER ISSUE	-
DMS_13079	19186	N	N	N	1	CUSTOMER ISSUE	-
DMS_13080	19187	N	N	N	1	CUSTOMER ISSUE	-
DMS_13081	19188	N	N	N	1	CUSTOMER ISSUE	-
DMS_13082	19189	N	N	N	1	CUSTOMER ISSUE	-
DMS_13083	19190	N	N	N	1	CUSTOMER ISSUE	-
DMS_13084	19191	N	N	N	1	CUSTOMER ISSUE	-
DMS_13085	19192	N	N	N	1	CUSTOMER ISSUE	-
DMS_13086	19193	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13087	19194	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_13088	19195	N	N	N	1	CUSTOMER ISSUE	-
DMS_13089	19196	N	N	N	1	CUSTOMER ISSUE	-
DMS_13090	19197	N	N	N	1	CUSTOMER ISSUE	-
DMS_13091	19198	N	N	N	1	CUSTOMER ISSUE	-
DMS_13094	19199	N	N	N	1	CUSTOMER ISSUE	-
DMS_13095	19200	N	N	N	1	CUSTOMER ISSUE	-
DMS_13096	19201	N	N	N	1	CUSTOMER ISSUE	-
DMS_13099	19202	N	N	N	1	CUSTOMER ISSUE	-
DMS_13100	19203	N	N	N	1	CUSTOMER ISSUE	-
DMS_13101	19204	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_13102	19205	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13103	19206	N	N	N	1	CUSTOMER ISSUE	-
DMS_13105	19207	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13106	19208	N	N	N	1	CUSTOMER ISSUE	-
DMS_13107	19209	N	N	N	1	CUSTOMER ISSUE	-
DMS_13108	19210	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_13109	19211	N	N	N	1	CUSTOMER ISSUE	-
DMS_13110	19212	N	N	N	1	CUSTOMER ISSUE	-
DMS_13111	19213	N	N	N	1	CUSTOMER ISSUE	-
DMS_13112	19214	N	N	N	1	CUSTOMER ISSUE	-
DMS_13113	19215	N	N	N	1	CUSTOMER ISSUE	-
DMS_13114	19216	N	N	N	1	CUSTOMER ISSUE	-
DMS_13116	19217	N	N	N	1	CUSTOMER ISSUE	-
DMS_13117	19218	N	N	N	2	CUSTOMER ISSUE	-
DMS_13118	19219	N	N	N	1	CUSTOMER ISSUE	-
DMS_13120	19220	N	N	N	1	CUSTOMER ISSUE	-
DMS_13122	19221	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_13123	19222	N	N	N	1	CUSTOMER ISSUE	-
DMS_13124	19223	N	N	N	1	CUSTOMER ISSUE	-
DMS_13125	19224	N	N	N	1	CUSTOMER ISSUE	-
DMS_13126	19225	N	N	N	1	CUSTOMER ISSUE	-
DMS_13127	19226	N	N	N	1	CUSTOMER ISSUE	-
DMS_13128	19227	N	N	N	1	CUSTOMER ISSUE	-
DMS_13129	19228	N	N	N	1	CUSTOMER ISSUE	-
DMS_13130	19229	N	N	N	1	CUSTOMER ISSUE	-
DMS_13131	19230	N	N	N	1	CUSTOMER ISSUE	-
DMS_13132	19231	N	N	N	1	CUSTOMER ISSUE	-
DMS_13133	19232	N	N	N	1	CUSTOMER ISSUE	-
DMS_13134	19233	N	N	N	1	CUSTOMER ISSUE	-
DMS_13135	19234	N	N	N	1	CUSTOMER ISSUE	-
DMS_13136	19235	N	N	N	1	CUSTOMER ISSUE	-
DMS_13137	19236	N	N	N	1	CUSTOMER ISSUE	-
DMS_13138	19237	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_13139	19238	N	N	N	1	CUSTOMER ISSUE	-
DMS_13141	19239	N	N	N	1	CUSTOMER ISSUE	-
DMS_13142	19240	N	N	N	1	CUSTOMER ISSUE	-
DMS_13143	19241	N	N	N	1	CUSTOMER ISSUE	-
DMS_13144	19242	N	N	N	1	CUSTOMER ISSUE	-
DMS_13145	19243	N	N	N	1	CUSTOMER ISSUE	-
DMS_13146	19244	N	N	N	1	CUSTOMER ISSUE	-
DMS_13147	19245	N	N	N	1	CUSTOMER ISSUE	-
DMS_13148	19246	N	N	N	1	CUSTOMER ISSUE	-
DMS_13149	19247	N	N	N	1	CUSTOMER ISSUE	-
DMS_13150	19248	N	N	N	1	CUSTOMER ISSUE	-
DMS_13152	19249	N	N	N	1	CUSTOMER ISSUE	-
DMS_13153	19250	N	N	N	1	CUSTOMER ISSUE	-
DMS_13154	19251	N	N	N	1	CUSTOMER ISSUE	-
DMS_13155	19252	N	N	N	1	CUSTOMER ISSUE	-
DMS_13156	19253	N	N	N	1	CUSTOMER ISSUE	-
DMS_13157	19254	N	N	N	1	CUSTOMER ISSUE	-
DMS_13158	19255	N	N	N	1	CUSTOMER ISSUE	-
DMS_13159	19256	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_13160	19257	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13161	19258	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13162	19259	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13163	19260	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13164	19261	N	N	N	1	CUSTOMER ISSUE	-
DMS_13165	19262	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13166	19263	N	N	N	1	CUSTOMER ISSUE	-
DMS_13168	19264	N	N	N	1	CUSTOMER ISSUE	-
DMS_13169	19265	N	N	N	1	CUSTOMER ISSUE	-
DMS_13170	19266	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13171	19267	N	N	N	1	CUSTOMER ISSUE	-
DMS_13172	19268	N	N	N	1	CUSTOMER ISSUE	-
DMS_13173	19269	N	N	N	1	CUSTOMER ISSUE	-
DMS_13174	19270	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_13175	19271	N	N	N	1	CUSTOMER ISSUE	-
DMS_13176	19272	N	N	N	1	CUSTOMER ISSUE	-
DMS_13177	19273	N	N	N	1	CUSTOMER ISSUE	-
DMS_13178	19274	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_13179	19275	N	N	N	1	CUSTOMER ISSUE	-
DMS_13180	19276	N	N	N	1	CUSTOMER ISSUE	-
DMS_13182	19277	N	N	N	1	CUSTOMER ISSUE	-
DMS_13183	19278	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13184	19279	N	N	N	1	CUSTOMER ISSUE	-
DMS_13185	19280	N	N	N	1	CUSTOMER ISSUE	-
DMS_13186	19281	N	N	N	1	CUSTOMER ISSUE	-
DMS_13187	19282	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13188	19283	N	N	N	1	CUSTOMER ISSUE	-
DMS_13189	19284	N	N	N	1	CUSTOMER ISSUE	-
DMS_13191	19285	N	N	N	1	CUSTOMER ISSUE	-
DMS_13193	19286	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_13195	19287	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_13196	19288	N	N	N	1	CUSTOMER ISSUE	-
DMS_13198	19289	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_13200	19290	N	N	N	1	CUSTOMER ISSUE	-
DMS_13201	19291	N	N	N	1	CUSTOMER ISSUE	-
DMS_13202	19292	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_13203	19293	N	N	N	1	CUSTOMER ISSUE	-
DMS_13205	19294	N	N	N	1	CUSTOMER ISSUE	-
DMS_13207	19295	N	N	N	1	CUSTOMER ISSUE	-
DMS_13208	19296	N	N	N	1	CUSTOMER ISSUE	-
DMS_13209	19297	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13210	19298	N	N	N	1	CUSTOMER ISSUE	-
DMS_13211	19299	N	N	N	1	CUSTOMER ISSUE	-
DMS_13212	19300	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13213	19301	N	N	N	1	CUSTOMER ISSUE	-
DMS_13214	19302	N	N	N	1	CUSTOMER ISSUE	-
DMS_13215	19303	N	N	N	1	CUSTOMER ISSUE	-
DMS_13216	19304	N	N	N	1	CUSTOMER ISSUE	-
DMS_13217	19305	N	N	N	1	CUSTOMER ISSUE	-
DMS_13218	19306	N	N	N	1	CUSTOMER ISSUE	-
DMS_13219	19307	N	N	N	1	CUSTOMER ISSUE	-
DMS_13220	19308	N	N	N	1	CUSTOMER ISSUE	-
DMS_13221	19309	N	N	N	1	CUSTOMER ISSUE	-
DMS_13222	19310	N	N	N	1	CUSTOMER ISSUE	-
DMS_13223	19311	N	N	N	1	CUSTOMER ISSUE	-
DMS_13224	19312	N	N	N	1	CUSTOMER ISSUE	-
DMS_13225	19313	N	N	N	1	CUSTOMER ISSUE	-
DMS_13226	19314	N	N	N	1	CUSTOMER ISSUE	-
DMS_13227	19315	N	N	N	1	CUSTOMER ISSUE	-
DMS_13228	19316	N	N	N	1	CUSTOMER ISSUE	-
DMS_13229	19317	N	N	N	1	CUSTOMER ISSUE	-
DMS_13230	19318	N	N	N	1	CUSTOMER ISSUE	-
DMS_13231	19319	N	N	N	1	CUSTOMER ISSUE	-
DMS_13232	19320	N	N	N	1	CUSTOMER ISSUE	-
DMS_13233	19321	N	N	N	1	CUSTOMER ISSUE	-
DMS_13235	19322	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13236	19323	N	N	N	1	CUSTOMER ISSUE	-
DMS_13237	19324	N	N	N	1	CUSTOMER ISSUE	-
DMS_13238	19325	N	N	N	1	CUSTOMER ISSUE	-
DMS_13239	19326	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13241	19327	N	N	N	1	CUSTOMER ISSUE	-
DMS_13242	19328	N	N	N	1	CUSTOMER ISSUE	-
DMS_13243	19329	N	N	N	1	CUSTOMER ISSUE	-
DMS_13244	19330	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13245	19331	N	N	N	1	CUSTOMER ISSUE	-
DMS_13246	19332	N	N	N	1	CUSTOMER ISSUE	-
DMS_13247	19333	N	N	N	1	CUSTOMER ISSUE	-
DMS_13248	19334	N	N	N	1	CUSTOMER ISSUE	-
DMS_13249	19335	N	N	N	1	CUSTOMER ISSUE	-
DMS_13250	19336	N	N	N	1	CUSTOMER ISSUE	-

DMS_13251	19337	N	N	N	1	CUSTOMER ISSUE	-
DMS_13252	19338	N	N	N	1	CUSTOMER ISSUE	-
DMS_13253	19339	N	N	N	1	CUSTOMER ISSUE	-
DMS_13254	19340	N	N	N	1	CUSTOMER ISSUE	-
DMS_13256	19341	N	N	N	1	CUSTOMER ISSUE	-
DMS_13257	19342	N	N	N	1	CUSTOMER ISSUE	-
DMS_13258	19343	N	N	N	1	CUSTOMER ISSUE	-
DMS_13259	19344	N	N	N	1	CUSTOMER ISSUE	-
DMS_13260	19345	N	N	N	1	CUSTOMER ISSUE	-
DMS_13261	19346	N	N	N	1	CUSTOMER ISSUE	-
DMS_13263	19347	N	N	N	1	CUSTOMER ISSUE	-
DMS_13264	19348	N	N	N	1	CUSTOMER ISSUE	-
DMS_13265	19349	N	N	N	1	CUSTOMER ISSUE	-
DMS_13266	19350	N	N	N	1	CUSTOMER ISSUE	-
DMS_13267	19351	N	N	N	1	CUSTOMER ISSUE	-
DMS_13268	19352	N	N	N	1	CUSTOMER ISSUE	-
DMS_13269	19353	N	N	N	1	CUSTOMER ISSUE	-
DMS_13270	19354	N	N	N	1	CUSTOMER ISSUE	-
DMS_13271	19355	N	N	N	1	CUSTOMER ISSUE	-
DMS_13272	19356	N	N	N	1	CUSTOMER ISSUE	-
DMS_13274	19357	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13275	19358	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13276	19359	N	N	N	1	CUSTOMER ISSUE	-
DMS_13277	19360	N	N	N	1	CUSTOMER ISSUE	-
DMS_13278	19361	N	N	N	1	CUSTOMER ISSUE	-
DMS_13279	19362	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13280	19363	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13281	19364	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13282	19365	N	N	N	1	CUSTOMER ISSUE	-
DMS_13283	19366	N	N	N	1	CUSTOMER ISSUE	-
DMS_13284	19367	N	N	N	1	CUSTOMER ISSUE	-
DMS_13285	19368	N	N	N	1	CUSTOMER ISSUE	-
DMS_13286	19369	N	N	N	1	CUSTOMER ISSUE	-
DMS_13287	19370	N	N	N	1	CUSTOMER ISSUE	-
DMS_13288	19371	N	N	N	1	CUSTOMER ISSUE	-
DMS_13289	19372	N	N	N	1	CUSTOMER ISSUE	-
DMS_13290	19373	N	N	N	1	CUSTOMER ISSUE	-
DMS_13291	19374	N	N	N	1	CUSTOMER ISSUE	-
DMS_13292	19375	N	N	N	1	CUSTOMER ISSUE	-
DMS_13293	19376	N	N	N	1	CUSTOMER ISSUE	-
DMS_13294	19377	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_13295	19378	N	N	N	1	CUSTOMER ISSUE	-
DMS_13296	19379	N	N	N	1	CUSTOMER ISSUE	-
DMS_13297	19380	N	N	N	1	CUSTOMER ISSUE	-
DMS_13298	19381	N	N	N	1	CUSTOMER ISSUE	-
DMS_13299	19382	N	N	N	1	CUSTOMER ISSUE	-
DMS_13300	19383	N	N	N	1	CUSTOMER ISSUE	-
DMS_13301	19384	N	N	N	1	CUSTOMER ISSUE	-
DMS_13302	19385	N	N	N	1	CUSTOMER ISSUE	-
DMS_13303	19386	N	N	N	1	CUSTOMER ISSUE	-
DMS_13304	19387	N	N	N	1	CUSTOMER ISSUE	-
DMS_13305	19388	N	N	N	1	CUSTOMER ISSUE	-
DMS_13306	19389	N	N	N	1	CUSTOMER ISSUE	-
DMS_13307	19390	N	N	N	1	CUSTOMER ISSUE	-
DMS_13308	19391	N	N	N	1	CUSTOMER ISSUE	-
DMS_13309	19392	N	N	N	1	CUSTOMER ISSUE	-
DMS_13310	19393	N	N	N	1	CUSTOMER ISSUE	-
DMS_13311	19394	N	N	N	1	CUSTOMER ISSUE	-
DMS_13312	19395	N	N	N	1	CUSTOMER ISSUE	-
DMS_13313	19396	N	N	N	1	CUSTOMER ISSUE	-
DMS_13314	19397	N	N	N	1	CUSTOMER ISSUE	-
DMS_13315	19398	N	N	N	1	CUSTOMER ISSUE	-
DMS_13316	19399	N	N	N	1	CUSTOMER ISSUE	-
DMS_13317	19400	N	N	N	1	CUSTOMER ISSUE	-
DMS_13318	19401	N	N	N	1	CUSTOMER ISSUE	-
DMS_13319	19402	N	N	N	1	CUSTOMER ISSUE	-
DMS_13320	19403	N	N	N	1	CUSTOMER ISSUE	-
DMS_13321	19404	N	N	N	1	CUSTOMER ISSUE	-
DMS_13322	19405	N	N	N	1	CUSTOMER ISSUE	-
DMS_13323	19406	N	N	N	1	CUSTOMER ISSUE	-
DMS_13324	19407	N	N	N	1	CUSTOMER ISSUE	-
DMS_13325	19408	N	N	N	1	CUSTOMER ISSUE	-
DMS_13326	19409	N	N	N	1	CUSTOMER ISSUE	-
DMS_13327	19410	N	N	N	1	CUSTOMER ISSUE	-
DMS_13328	19411	N	N	N	1	CUSTOMER ISSUE	-
DMS_13329	19412	N	N	N	1	CUSTOMER ISSUE	-
DMS_13330	19413	N	N	N	1	CUSTOMER ISSUE	-
DMS_13331	19414	N	N	N	1	CUSTOMER ISSUE	-
DMS_13332	19415	N	N	N	1	CUSTOMER ISSUE	-
DMS_13333	19416	N	N	N	1	CUSTOMER ISSUE	-

DMS_13334	19417	N	N	N	1	CUSTOMER ISSUE	-
DMS_13335	19418	N	N	N	1	CUSTOMER ISSUE	-
DMS_13336	19419	N	N	N	1	CUSTOMER ISSUE	-
DMS_13337	19420	N	N	N	1	CUSTOMER ISSUE	-
DMS_13338	19421	N	N	N	1	CUSTOMER ISSUE	-
DMS_13339	19422	N	N	N	1	CUSTOMER ISSUE	-
DMS_13340	19423	N	N	N	1	CUSTOMER ISSUE	-
DMS_13341	19424	N	N	N	1	CUSTOMER ISSUE	-
DMS_13342	19425	N	N	N	1	CUSTOMER ISSUE	-
DMS_13343	19426	N	N	N	1	CUSTOMER ISSUE	-
DMS_13344	19427	N	N	N	1	CUSTOMER ISSUE	-
DMS_13345	19428	N	N	N	1	CUSTOMER ISSUE	-
DMS_13346	19429	N	N	N	1	CUSTOMER ISSUE	-
DMS_13347	19430	N	N	N	1	CUSTOMER ISSUE	-
DMS_13348	19431	N	N	N	1	CUSTOMER ISSUE	-
DMS_13349	19432	N	N	N	1	CUSTOMER ISSUE	-
DMS_13350	19433	N	N	N	1	CUSTOMER ISSUE	-
DMS_13351	19434	N	N	N	1	CUSTOMER ISSUE	-
DMS_13352	19435	N	N	N	1	CUSTOMER ISSUE	-
DMS_13353	19436	N	N	N	1	CUSTOMER ISSUE	-
DMS_13354	19437	N	N	N	1	CUSTOMER ISSUE	-
DMS_13355	19438	N	N	N	1	CUSTOMER ISSUE	-
DMS_13356	19439	N	N	N	1	CUSTOMER ISSUE	-
DMS_13357	19440	N	N	N	1	CUSTOMER ISSUE	-
DMS_13358	19441	N	N	N	1	CUSTOMER ISSUE	-
DMS_13359	19442	N	N	N	1	CUSTOMER ISSUE	-
DMS_13360	19443	N	N	N	1	CUSTOMER ISSUE	-
DMS_13361	19444	N	N	N	1	CUSTOMER ISSUE	-
DMS_13362	19445	N	N	N	1	CUSTOMER ISSUE	-
DMS_13363	19446	N	N	N	1	CUSTOMER ISSUE	-
DMS_13364	19447	N	N	N	1	CUSTOMER ISSUE	-
DMS_13365	19448	N	N	N	1	CUSTOMER ISSUE	-
DMS_13366	19449	N	N	N	1	CUSTOMER ISSUE	-
DMS_13367	19450	N	N	N	1	CUSTOMER ISSUE	-
DMS_13368	19451	N	N	N	1	CUSTOMER ISSUE	-
DMS_13369	19452	N	N	N	1	CUSTOMER ISSUE	-
DMS_13370	19453	N	N	N	1	CUSTOMER ISSUE	-
DMS_13371	19454	N	N	N	1	CUSTOMER ISSUE	-
DMS_13372	19455	N	N	N	1	CUSTOMER ISSUE	-
DMS_13373	19456	N	N	N	1	CUSTOMER ISSUE	-
DMS_13374	19457	N	N	N	1	CUSTOMER ISSUE	-
DMS_13375	19458	N	N	N	1	CUSTOMER ISSUE	-
DMS_13376	19459	N	N	N	1	CUSTOMER ISSUE	-
DMS_13377	19460	N	N	N	1	CUSTOMER ISSUE	-
DMS_13378	19461	N	N	N	1	CUSTOMER ISSUE	-
DMS_13379	19462	N	N	N	1	CUSTOMER ISSUE	-
DMS_13380	19463	N	N	N	1	CUSTOMER ISSUE	-
DMS_13381	19464	N	N	N	1	CUSTOMER ISSUE	-
DMS_13382	19465	N	N	N	2	CUSTOMER ISSUE	-
DMS_13383	19466	N	N	N	1	CUSTOMER ISSUE	-
DMS_13384	19467	N	N	N	1	CUSTOMER ISSUE	-
DMS_13385	19468	N	N	N	1	CUSTOMER ISSUE	-
DMS_13386	19469	N	N	N	1	CUSTOMER ISSUE	-
DMS_13387	19470	N	N	N	1	CUSTOMER ISSUE	-
DMS_13388	19471	N	N	N	1	CUSTOMER ISSUE	-
DMS_13389	19472	N	N	N	1	CUSTOMER ISSUE	-
DMS_13390	19473	N	N	N	1	CUSTOMER ISSUE	-
DMS_13391	19474	N	N	N	1	CUSTOMER ISSUE	-
DMS_13392	19475	N	N	N	1	CUSTOMER ISSUE	-
DMS_13393	19476	N	N	N	1	CUSTOMER ISSUE	-
DMS_13394	19477	N	N	N	1	CUSTOMER ISSUE	-
DMS_13395	19478	N	N	N	1	CUSTOMER ISSUE	-
DMS_13396	19479	N	N	N	1	CUSTOMER ISSUE	-
DMS_13397	19480	N	N	N	1	CUSTOMER ISSUE	-
DMS_13398	19481	N	N	N	1	CUSTOMER ISSUE	-
DMS_13399	19482	N	N	N	1	CUSTOMER ISSUE	-
DMS_13400	19483	N	N	N	1	CUSTOMER ISSUE	-
DMS_13401	19484	N	N	N	1	CUSTOMER ISSUE	-
DMS_13402	19485	N	N	N	1	CUSTOMER ISSUE	-
DMS_13403	19486	N	N	N	1	CUSTOMER ISSUE	-
DMS_13404	19487	N	N	N	1	CUSTOMER ISSUE	-
DMS_13405	19488	N	N	N	1	CUSTOMER ISSUE	-
DMS_13406	19489	N	N	N	1	CUSTOMER ISSUE	-
DMS_13407	19490	N	N	N	1	CUSTOMER ISSUE	-
DMS_13408	19491	N	N	N	1	CUSTOMER ISSUE	-
DMS_13409	19492	N	N	N	1	CUSTOMER ISSUE	-
DMS_13410	19493	N	N	N	1	CUSTOMER ISSUE	-
DMS_13411	19494	N	N	N	1	CUSTOMER ISSUE	-
DMS_13412	19495	N	N	N	1	CUSTOMER ISSUE	-
DMS_13413	19496	N	N	N	1	CUSTOMER ISSUE	-

DMS_13414	19497	N	N	N	1	CUSTOMER ISSUE	-
DMS_13415	19498	N	N	N	1	CUSTOMER ISSUE	-
DMS_13416	19499	N	N	N	1	CUSTOMER ISSUE	-
DMS_13417	19500	N	N	N	1	CUSTOMER ISSUE	-
DMS_13418	19501	N	N	N	1	CUSTOMER ISSUE	-
DMS_13419	19502	N	N	N	1	CUSTOMER ISSUE	-
DMS_13420	19503	N	N	N	1	CUSTOMER ISSUE	-
DMS_13421	19504	N	N	N	1	CUSTOMER ISSUE	-
DMS_13422	19505	N	N	N	1	CUSTOMER ISSUE	-
DMS_13423	19506	N	N	N	1	CUSTOMER ISSUE	-
DMS_13424	19507	N	N	N	1	CUSTOMER ISSUE	-
DMS_13425	19508	N	N	N	1	CUSTOMER ISSUE	-
DMS_13426	19509	N	N	N	1	CUSTOMER ISSUE	-
DMS_13427	19510	N	N	N	1	CUSTOMER ISSUE	-
DMS_13428	19511	N	N	N	1	CUSTOMER ISSUE	-
DMS_13429	19512	N	N	N	1	CUSTOMER ISSUE	-
DMS_13430	19513	N	N	N	1	CUSTOMER ISSUE	-
DMS_13431	19514	N	N	N	1	CUSTOMER ISSUE	-
DMS_13432	19515	N	N	N	1	CUSTOMER ISSUE	-
DMS_13433	19516	N	N	N	1	CUSTOMER ISSUE	-
DMS_13434	19517	N	N	N	1	CUSTOMER ISSUE	-
DMS_13435	19518	N	N	N	1	CUSTOMER ISSUE	-
DMS_13436	19519	N	N	N	1	CUSTOMER ISSUE	-
DMS_13437	19520	N	N	N	1	CUSTOMER ISSUE	-
DMS_13438	19521	N	N	N	1	CUSTOMER ISSUE	-
DMS_13439	19522	N	N	N	1	CUSTOMER ISSUE	-
DMS_13440	19523	N	N	N	1	CUSTOMER ISSUE	-
DMS_13441	19524	N	N	N	1	CUSTOMER ISSUE	-
DMS_13442	19525	N	N	N	1	CUSTOMER ISSUE	-
DMS_13443	19526	N	N	N	1	CUSTOMER ISSUE	-
DMS_13444	19527	N	N	N	1	CUSTOMER ISSUE	-
DMS_13445	19528	N	N	N	1	CUSTOMER ISSUE	-
DMS_13446	19529	N	N	N	1	CUSTOMER ISSUE	-
DMS_13447	19530	N	N	N	1	CUSTOMER ISSUE	-
DMS_13448	19531	N	N	N	1	CUSTOMER ISSUE	-
DMS_13449	19532	N	N	N	1	CUSTOMER ISSUE	-
DMS_13450	19533	N	N	N	1	CUSTOMER ISSUE	-
DMS_13451	19534	N	N	N	1	CUSTOMER ISSUE	-
DMS_13452	19535	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13453	19536	N	N	N	1	CUSTOMER ISSUE	-
DMS_13454	19537	N	N	N	1	CUSTOMER ISSUE	-
DMS_13455	19538	N	N	N	1	CUSTOMER ISSUE	-
DMS_13456	19539	N	N	N	1	CUSTOMER ISSUE	-
DMS_13457	19540	N	N	N	1	CUSTOMER ISSUE	-
DMS_13458	19541	N	N	N	1	CUSTOMER ISSUE	-
DMS_13459	19542	N	N	N	1	CUSTOMER ISSUE	-
DMS_13460	19543	N	N	N	1	CUSTOMER ISSUE	-
DMS_13461	19544	N	N	N	1	CUSTOMER ISSUE	-
DMS_13462	19545	N	N	N	1	CUSTOMER ISSUE	-
DMS_13463	19546	N	N	N	1	CUSTOMER ISSUE	-
DMS_13464	19547	N	N	N	1	CUSTOMER ISSUE	-
DMS_13465	19548	N	N	N	1	CUSTOMER ISSUE	-
DMS_13466	19549	N	N	N	1	CUSTOMER ISSUE	-
DMS_13467	19550	N	N	N	1	CUSTOMER ISSUE	-
DMS_13468	19551	N	N	N	1	CUSTOMER ISSUE	-
DMS_13469	19552	N	N	N	1	CUSTOMER ISSUE	-
DMS_13470	19553	N	N	N	1	CUSTOMER ISSUE	-
DMS_13471	19554	N	N	N	1	CUSTOMER ISSUE	-
DMS_13472	19555	N	N	N	1	CUSTOMER ISSUE	-
DMS_13473	19556	N	N	N	1	CUSTOMER ISSUE	-
DMS_13474	19557	N	N	N	1	CUSTOMER ISSUE	-
DMS_13475	19558	N	N	N	1	CUSTOMER ISSUE	-
DMS_13476	19559	N	N	N	1	CUSTOMER ISSUE	-
DMS_13477	19560	N	N	N	1	CUSTOMER ISSUE	-
DMS_13478	19561	N	N	N	1	CUSTOMER ISSUE	-
DMS_13479	19562	N	N	N	1	CUSTOMER ISSUE	-
DMS_13480	19563	N	N	N	1	CUSTOMER ISSUE	-
DMS_13481	19564	N	N	N	1	CUSTOMER ISSUE	-
DMS_13482	19565	N	N	N	1	CUSTOMER ISSUE	-
DMS_13483	19566	N	N	N	1	CUSTOMER ISSUE	-
DMS_13484	19567	N	N	N	1	CUSTOMER ISSUE	-
DMS_13485	19568	N	N	N	1	CUSTOMER ISSUE	-
DMS_13486	19569	N	N	N	1	CUSTOMER ISSUE	-
DMS_13487	19570	N	N	N	1	CUSTOMER ISSUE	-
DMS_13488	19571	N	N	N	1	CUSTOMER ISSUE	-
DMS_13489	19572	N	N	N	1	CUSTOMER ISSUE	-
DMS_13490	19573	N	N	N	1	CUSTOMER ISSUE	-
DMS_13491	19574	N	N	N	1	CUSTOMER ISSUE	-
DMS_13492	19575	N	N	N	1	CUSTOMER ISSUE	-
DMS_13493	19576	N	N	N	1	CUSTOMER ISSUE	-

DMS_13494	19577	N	N	N	1	CUSTOMER ISSUE	-
DMS_13495	19578	N	N	N	1	CUSTOMER ISSUE	-
DMS_13496	19579	N	N	N	1	CUSTOMER ISSUE	-
DMS_13497	19580	N	N	N	1	CUSTOMER ISSUE	-
DMS_13498	19581	N	N	N	1	CUSTOMER ISSUE	-
DMS_13499	19582	N	N	N	1	CUSTOMER ISSUE	-
DMS_13500	19583	N	N	N	1	CUSTOMER ISSUE	-
DMS_13501	19584	N	N	N	1	CUSTOMER ISSUE	-
DMS_13502	19585	N	N	N	1	CUSTOMER ISSUE	-
DMS_13503	19586	N	N	N	1	CUSTOMER ISSUE	-
DMS_13504	19587	N	N	N	1	CUSTOMER ISSUE	-
DMS_13505	19588	N	N	N	1	CUSTOMER ISSUE	-
DMS_13506	19589	N	N	N	1	CUSTOMER ISSUE	-
DMS_13507	19590	N	N	N	1	CUSTOMER ISSUE	-
DMS_13508	19591	N	N	N	1	CUSTOMER ISSUE	-
DMS_13509	19592	N	N	N	1	CUSTOMER ISSUE	-
DMS_13510	19593	N	N	N	1	CUSTOMER ISSUE	-
DMS_13511	19594	N	N	N	1	CUSTOMER ISSUE	-
DMS_13512	19595	N	N	N	1	CUSTOMER ISSUE	-
DMS_13513	19596	N	N	N	1	CUSTOMER ISSUE	-
DMS_13514	19597	N	N	N	1	CUSTOMER ISSUE	-
DMS_13515	19598	N	N	N	1	CUSTOMER ISSUE	-
DMS_13516	19599	N	N	N	1	CUSTOMER ISSUE	-
DMS_13517	19600	N	N	N	1	CUSTOMER ISSUE	-
DMS_13518	19601	N	N	N	1	CUSTOMER ISSUE	-
DMS_13519	19602	N	N	N	1	CUSTOMER ISSUE	-
DMS_13520	19603	N	N	N	1	CUSTOMER ISSUE	-
DMS_13521	19604	N	N	N	1	CUSTOMER ISSUE	-
DMS_13522	19605	N	N	N	1	CUSTOMER ISSUE	-
DMS_13523	19606	N	N	N	1	CUSTOMER ISSUE	-
DMS_13524	19607	N	N	N	1	CUSTOMER ISSUE	-
DMS_13525	19608	N	N	N	1	CUSTOMER ISSUE	-
DMS_13526	19609	N	N	N	1	CUSTOMER ISSUE	-
DMS_13527	19610	N	N	N	1	CUSTOMER ISSUE	-
DMS_13528	19611	N	N	N	1	CUSTOMER ISSUE	-
DMS_13529	19612	N	N	N	1	CUSTOMER ISSUE	-
DMS_13530	19613	N	N	N	1	CUSTOMER ISSUE	-
DMS_13531	19614	N	N	N	1	CUSTOMER ISSUE	-
DMS_13532	19615	N	N	N	1	CUSTOMER ISSUE	-
DMS_13533	19616	N	N	N	1	CUSTOMER ISSUE	-
DMS_13534	19617	N	N	N	1	CUSTOMER ISSUE	-
DMS_13535	19618	N	N	N	1	CUSTOMER ISSUE	-
DMS_13536	19619	N	N	N	1	CUSTOMER ISSUE	-
DMS_13537	19620	N	N	N	1	CUSTOMER ISSUE	-
DMS_13538	19621	N	N	N	1	CUSTOMER ISSUE	-
DMS_13539	19622	N	N	N	2	CUSTOMER ISSUE	-
DMS_13540	19623	N	N	N	1	CUSTOMER ISSUE	-
DMS_13541	19624	N	N	N	1	CUSTOMER ISSUE	-
DMS_13542	19625	N	N	N	1	CUSTOMER ISSUE	-
DMS_13543	19626	N	N	N	1	CUSTOMER ISSUE	-
DMS_13544	19627	N	N	N	1	CUSTOMER ISSUE	-
DMS_13545	19628	N	N	N	1	CUSTOMER ISSUE	-
DMS_13546	19629	N	N	N	1	CUSTOMER ISSUE	-
DMS_13547	19630	N	N	N	1	CUSTOMER ISSUE	-
DMS_13548	19631	N	N	N	1	CUSTOMER ISSUE	-
DMS_13550	19632	N	N	N	1	CUSTOMER ISSUE	-
DMS_13551	19633	N	N	N	1	CUSTOMER ISSUE	-
DMS_13552	19634	N	N	N	1	CUSTOMER ISSUE	-
DMS_13553	19635	N	N	N	1	CUSTOMER ISSUE	-
DMS_13554	19636	N	N	N	1	CUSTOMER ISSUE	-
DMS_13555	19637	N	N	N	1	CUSTOMER ISSUE	-
DMS_13556	19638	N	N	N	1	CUSTOMER ISSUE	-
DMS_13557	19639	N	N	N	1	CUSTOMER ISSUE	-
DMS_13558	19640	N	N	N	1	CUSTOMER ISSUE	-
DMS_13559	19641	N	N	N	1	CUSTOMER ISSUE	-
DMS_13560	19642	N	N	N	1	CUSTOMER ISSUE	-
DMS_13561	19643	N	N	N	1	CUSTOMER ISSUE	-
DMS_13562	19644	N	N	N	1	CUSTOMER ISSUE	-
DMS_13563	19645	N	N	N	1	CUSTOMER ISSUE	-
DMS_13564	19646	N	N	N	1	CUSTOMER ISSUE	-
DMS_13565	19647	N	N	N	1	CUSTOMER ISSUE	-
DMS_13566	19648	N	N	N	1	CUSTOMER ISSUE	-
DMS_13567	19649	N	N	N	1	CUSTOMER ISSUE	-
DMS_13568	19650	N	N	N	1	CUSTOMER ISSUE	-
DMS_13569	19651	N	N	N	1	CUSTOMER ISSUE	-
DMS_13570	19652	N	N	N	1	CUSTOMER ISSUE	-
DMS_13571	19653	N	N	N	1	CUSTOMER ISSUE	-
DMS_13572	19654	N	N	N	1	CUSTOMER ISSUE	-
DMS_13573	19655	N	N	N	1	CUSTOMER ISSUE	-
DMS_13574	19656	N	N	N	1	CUSTOMER ISSUE	-

DMS_13575	19657	N	N	N	1	CUSTOMER ISSUE	-
DMS_13576	19658	N	N	N	1	CUSTOMER ISSUE	-
DMS_13577	19659	N	N	N	1	CUSTOMER ISSUE	-
DMS_13578	19660	N	N	N	1	CUSTOMER ISSUE	-
DMS_13579	19661	N	N	N	1	CUSTOMER ISSUE	-
DMS_13580	19662	N	N	N	1	CUSTOMER ISSUE	-
DMS_13581	19663	N	N	N	1	CUSTOMER ISSUE	-
DMS_13582	19664	N	N	N	1	CUSTOMER ISSUE	-
DMS_13583	19665	N	N	N	1	CUSTOMER ISSUE	-
DMS_13584	19666	N	N	N	1	CUSTOMER ISSUE	-
DMS_13585	19667	N	N	N	1	CUSTOMER ISSUE	-
DMS_13586	19668	N	N	N	1	CUSTOMER ISSUE	-
DMS_13587	19669	N	N	N	1	CUSTOMER ISSUE	-
DMS_13588	19670	N	N	N	1	CUSTOMER ISSUE	-
DMS_13589	19671	N	N	N	1	CUSTOMER ISSUE	-
DMS_13590	19672	N	N	N	1	CUSTOMER ISSUE	-
DMS_13591	19673	N	N	N	1	CUSTOMER ISSUE	-
DMS_13592	19674	N	N	N	1	CUSTOMER ISSUE	-
DMS_13593	19675	N	N	N	1	CUSTOMER ISSUE	-
DMS_13594	19676	N	N	N	1	CUSTOMER ISSUE	-
DMS_13595	19677	N	N	N	1	CUSTOMER ISSUE	-
DMS_13596	19678	N	N	N	1	CUSTOMER ISSUE	-
DMS_13597	19679	N	N	N	1	CUSTOMER ISSUE	-
DMS_13598	19680	N	N	N	1	CUSTOMER ISSUE	-
DMS_13599	19681	N	N	N	1	CUSTOMER ISSUE	-
DMS_13600	19682	N	N	N	1	CUSTOMER ISSUE	-
DMS_13601	19683	N	N	N	1	CUSTOMER ISSUE	-
DMS_13602	19684	N	N	N	1	CUSTOMER ISSUE	-
DMS_13603	19685	N	N	N	1	CUSTOMER ISSUE	-
DMS_13604	19686	N	N	N	1	CUSTOMER ISSUE	-
DMS_13605	19687	N	N	N	1	CUSTOMER ISSUE	-
DMS_13606	19688	N	N	N	1	CUSTOMER ISSUE	-
DMS_13607	19689	N	N	N	1	CUSTOMER ISSUE	-
DMS_13608	19690	N	N	N	1	CUSTOMER ISSUE	-
DMS_13609	19691	N	N	N	1	CUSTOMER ISSUE	-
DMS_13610	19692	N	N	N	1	CUSTOMER ISSUE	-
DMS_13611	19693	N	N	N	1	CUSTOMER ISSUE	-
DMS_13612	19694	N	N	N	1	CUSTOMER ISSUE	-
DMS_13613	19695	N	N	N	1	CUSTOMER ISSUE	-
DMS_13614	19696	N	N	N	1	CUSTOMER ISSUE	-
DMS_13615	19697	N	N	N	1	CUSTOMER ISSUE	-
DMS_13616	19698	N	N	N	1	CUSTOMER ISSUE	-
DMS_13618	19699	N	N	N	1	CUSTOMER ISSUE	-
DMS_13619	19700	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13620	19701	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13621	19702	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13622	19703	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13623	19704	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13624	19705	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13625	19706	N	N	N	1	CUSTOMER ISSUE	-
DMS_13626	19707	N	N	N	1	CUSTOMER ISSUE	-
DMS_13627	19708	N	N	N	1	CUSTOMER ISSUE	-
DMS_13628	19709	N	N	N	1	CUSTOMER ISSUE	-
DMS_13630	19710	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13631	19711	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13632	19712	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13633	19713	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13634	19714	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13635	19715	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13636	19716	N	N	N	1	CUSTOMER ISSUE	-
DMS_13637	19717	N	N	N	1	CUSTOMER ISSUE	-
DMS_13638	19718	N	N	N	1	CUSTOMER ISSUE	-
DMS_13639	19719	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_13640	19720	N	N	N	1	CUSTOMER ISSUE	-
DMS_13641	19721	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13642	19722	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13643	19723	N	N	N	1	CUSTOMER ISSUE	-
DMS_13644	19724	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13645	19725	N	N	N	1	CUSTOMER ISSUE	-
DMS_13647	19726	N	N	N	1	CUSTOMER ISSUE	-
DMS_13648	19727	N	N	N	1	CUSTOMER ISSUE	-
DMS_13650	19728	N	N	N	1	CUSTOMER ISSUE	-
DMS_13651	19729	N	N	N	1	CUSTOMER ISSUE	-
DMS_13652	19730	N	N	N	1	CUSTOMER ISSUE	-
DMS_13653	19731	N	N	N	1	CUSTOMER ISSUE	-
DMS_13654	19732	N	N	N	1	CUSTOMER ISSUE	-
DMS_13655	19733	N	N	N	1	CUSTOMER ISSUE	-
DMS_13656	19734	N	N	N	1	CUSTOMER ISSUE	-
DMS_13657	19735	N	N	N	1	CUSTOMER ISSUE	-
DMS_13658	19736	N	N	N	1	CUSTOMER ISSUE	-

DMS_13659	19737	N	N	N	1	CUSTOMER ISSUE	-
DMS_13660	19738	N	N	N	1	CUSTOMER ISSUE	-
DMS_13661	19739	N	N	N	1	CUSTOMER ISSUE	-
DMS_13662	19740	N	N	N	1	CUSTOMER ISSUE	-
DMS_13663	19741	N	N	N	1	CUSTOMER ISSUE	-
DMS_13664	19742	N	N	N	1	CUSTOMER ISSUE	-
DMS_13665	19743	N	N	N	1	CUSTOMER ISSUE	-
DMS_13666	19744	N	N	N	1	CUSTOMER ISSUE	-
DMS_13667	19745	N	N	N	1	CUSTOMER ISSUE	-
DMS_13668	19746	N	N	N	1	CUSTOMER ISSUE	-
DMS_13669	19747	N	N	N	1	CUSTOMER ISSUE	-
DMS_13670	19748	N	N	N	1	CUSTOMER ISSUE	-
DMS_13671	19749	N	N	N	1	CUSTOMER ISSUE	-
DMS_13672	19750	N	N	N	1	CUSTOMER ISSUE	-
DMS_13673	19751	N	N	N	1	CUSTOMER ISSUE	-
DMS_13674	19752	N	N	N	1	CUSTOMER ISSUE	-
DMS_13675	19753	N	N	N	1	CUSTOMER ISSUE	-
DMS_13676	19754	N	N	N	1	CUSTOMER ISSUE	-
DMS_13677	19755	N	N	N	1	CUSTOMER ISSUE	-
DMS_13678	19756	N	N	N	1	CUSTOMER ISSUE	-
DMS_13679	19757	N	N	N	1	CUSTOMER ISSUE	-
DMS_13680	19758	N	N	N	1	CUSTOMER ISSUE	-
DMS_13681	19759	N	N	N	1	CUSTOMER ISSUE	-
DMS_13682	19760	N	N	N	1	CUSTOMER ISSUE	-
DMS_13683	19761	N	N	N	1	CUSTOMER ISSUE	-
DMS_13684	19762	N	N	N	1	CUSTOMER ISSUE	-
DMS_13685	19763	N	N	N	1	CUSTOMER ISSUE	-
DMS_13686	19764	N	N	N	1	CUSTOMER ISSUE	-
DMS_13687	19765	N	N	N	1	CUSTOMER ISSUE	-
DMS_13688	19766	N	N	N	1	CUSTOMER ISSUE	-
DMS_13689	19767	N	N	N	1	CUSTOMER ISSUE	-
DMS_13690	19768	N	N	N	1	CUSTOMER ISSUE	-
DMS_13691	19769	N	N	N	1	CUSTOMER ISSUE	-
DMS_13692	19770	N	N	N	1	CUSTOMER ISSUE	-
DMS_13693	19771	N	N	N	1	CUSTOMER ISSUE	-
DMS_13694	19772	N	N	N	1	CUSTOMER ISSUE	-
DMS_13695	19773	N	N	N	1	CUSTOMER ISSUE	-
DMS_13696	19774	N	N	N	1	CUSTOMER ISSUE	-
DMS_13697	19775	N	N	N	1	CUSTOMER ISSUE	-
DMS_13698	19776	N	N	N	1	CUSTOMER ISSUE	-
DMS_13699	19777	N	N	N	1	CUSTOMER ISSUE	-
DMS_13700	19778	N	N	N	1	CUSTOMER ISSUE	-
DMS_13701	19779	N	N	N	1	CUSTOMER ISSUE	-
DMS_13702	19780	N	N	N	1	CUSTOMER ISSUE	-
DMS_13703	19781	N	N	N	1	CUSTOMER ISSUE	-
DMS_13704	19782	N	N	N	1	CUSTOMER ISSUE	-
DMS_13705	19783	N	N	N	1	CUSTOMER ISSUE	-
DMS_13706	19784	N	N	N	1	CUSTOMER ISSUE	-
DMS_13707	19785	N	N	N	1	CUSTOMER ISSUE	-
DMS_13709	19786	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13710	19787	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_13711	19788	N	N	N	1	CUSTOMER ISSUE	-
DMS_13712	19789	N	N	N	1	CUSTOMER ISSUE	-
DMS_13713	19790	N	N	N	1	CUSTOMER ISSUE	-
DMS_13714	19791	N	N	N	1	CUSTOMER ISSUE	-
DMS_13715	19792	N	N	N	1	CUSTOMER ISSUE	-
DMS_13716	19793	N	N	N	1	CUSTOMER ISSUE	-
DMS_13717	19794	N	N	N	1	CUSTOMER ISSUE	-
DMS_13718	19795	N	N	N	1	CUSTOMER ISSUE	-
DMS_13719	19796	N	N	N	1	CUSTOMER ISSUE	-
DMS_13720	19797	N	N	N	1	CUSTOMER ISSUE	-
DMS_13721	19798	N	N	N	1	CUSTOMER ISSUE	-
DMS_13722	19799	N	N	N	1	CUSTOMER ISSUE	-
DMS_13723	19800	N	N	N	1	CUSTOMER ISSUE	-
DMS_13724	19801	N	N	N	1	CUSTOMER ISSUE	-
DMS_13725	19802	N	N	N	1	CUSTOMER ISSUE	-
DMS_13726	19803	N	N	N	1	CUSTOMER ISSUE	-
DMS_13727	19804	N	N	N	1	CUSTOMER ISSUE	-
DMS_13728	19805	N	N	N	1	CUSTOMER ISSUE	-
DMS_13729	19806	N	N	N	1	CUSTOMER ISSUE	-
DMS_13730	19807	N	N	N	1	CUSTOMER ISSUE	-
DMS_13731	19808	N	N	N	1	CUSTOMER ISSUE	-
DMS_13732	19809	N	N	N	1	CUSTOMER ISSUE	-
DMS_13733	19810	N	N	N	1	CUSTOMER ISSUE	-
DMS_13734	19811	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13735	19812	N	N	N	1	CUSTOMER ISSUE	-
DMS_13736	19813	N	N	N	1	CUSTOMER ISSUE	-
DMS_13737	19814	N	N	N	1	CUSTOMER ISSUE	-
DMS_13738	19815	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13739	19816	N	N	N	1	CUSTOMER ISSUE	-

DMS_13740	19817	N	N	N	1	CUSTOMER ISSUE	-
DMS_13741	19818	N	N	N	1	CUSTOMER ISSUE	-
DMS_13742	19819	N	N	N	1	CUSTOMER ISSUE	-
DMS_13743	19820	N	N	N	1	CUSTOMER ISSUE	-
DMS_13744	19821	N	N	N	1	CUSTOMER ISSUE	-
DMS_13745	19822	N	N	N	1	CUSTOMER ISSUE	-
DMS_13746	19823	N	N	N	1	CUSTOMER ISSUE	-
DMS_13747	19824	N	N	N	1	CUSTOMER ISSUE	-
DMS_13748	19825	N	N	N	1	CUSTOMER ISSUE	-
DMS_13749	19826	N	N	N	1	CUSTOMER ISSUE	-
DMS_13750	19827	N	N	N	1	CUSTOMER ISSUE	-
DMS_13751	19828	N	N	N	1	CUSTOMER ISSUE	-
DMS_13752	19829	N	N	N	1	CUSTOMER ISSUE	-
DMS_13753	19830	N	N	N	1	CUSTOMER ISSUE	-
DMS_13754	19831	N	N	N	1	CUSTOMER ISSUE	-
DMS_13755	19832	N	N	N	1	CUSTOMER ISSUE	-
DMS_13756	19833	N	N	N	1	CUSTOMER ISSUE	-
DMS_13757	19834	N	N	N	1	CUSTOMER ISSUE	-
DMS_13758	19835	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13759	19836	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13760	19837	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_13761	19838	N	N	N	1	CUSTOMER ISSUE	-
DMS_13762	19839	N	N	N	1	CUSTOMER ISSUE	-
DMS_13764	19840	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13765	19841	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13766	19842	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13767	19843	N	N	N	1	CUSTOMER ISSUE	-
DMS_13768	19844	N	N	N	1	CUSTOMER ISSUE	-
DMS_13769	19845	N	N	N	1	CUSTOMER ISSUE	-
DMS_13770	19846	N	N	N	1	CUSTOMER ISSUE	-
DMS_13771	19847	N	N	N	1	CUSTOMER ISSUE	-
DMS_13772	19848	N	N	N	1	CUSTOMER ISSUE	-
DMS_13773	19849	N	N	N	1	CUSTOMER ISSUE	-
DMS_13774	19850	N	N	N	1	CUSTOMER ISSUE	-
DMS_13775	19851	N	N	N	1	CUSTOMER ISSUE	-
DMS_13776	19852	N	N	N	1	CUSTOMER ISSUE	-
DMS_13777	19853	N	N	N	1	CUSTOMER ISSUE	-
DMS_13778	19854	N	N	N	1	CUSTOMER ISSUE	-
DMS_13779	19855	N	N	N	1	CUSTOMER ISSUE	-
DMS_13780	19856	N	N	N	1	CUSTOMER ISSUE	-
DMS_13781	19857	N	N	N	1	CUSTOMER ISSUE	-
DMS_13782	19858	N	N	N	1	CUSTOMER ISSUE	-
DMS_13783	19859	N	N	N	1	CUSTOMER ISSUE	-
DMS_13784	19860	N	N	N	1	CUSTOMER ISSUE	-
DMS_13785	19861	N	N	N	1	CUSTOMER ISSUE	-
DMS_13786	19862	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13787	19863	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13788	19864	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_13789	19865	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13790	19866	N	N	N	1	CUSTOMER ISSUE	-
DMS_13791	19867	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13792	19868	N	N	N	1	CUSTOMER ISSUE	-
DMS_13795	19869	N	N	N	1	CUSTOMER ISSUE	-
DMS_13796	19870	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13797	19871	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13799	19872	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13800	19873	N	N	N	1	CUSTOMER ISSUE	-
DMS_13801	19874	N	N	N	1	CUSTOMER ISSUE	-
DMS_13802	19875	N	N	N	1	CUSTOMER ISSUE	-
DMS_13803	19876	N	N	N	1	CUSTOMER ISSUE	-
DMS_13804	19877	N	N	N	1	CUSTOMER ISSUE	-
DMS_13805	19878	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13806	19879	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13807	19880	N	N	N	1	CUSTOMER ISSUE	-
DMS_13808	19881	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_13809	19882	N	N	N	1	CUSTOMER ISSUE	-
DMS_13810	19883	N	N	N	1	CUSTOMER ISSUE	-
DMS_13811	19884	N	N	N	1	CUSTOMER ISSUE	-
DMS_13812	19885	N	N	N	1	CUSTOMER ISSUE	-
DMS_13813	19886	N	N	N	1	CUSTOMER ISSUE	-
DMS_13814	19887	N	N	N	1	CUSTOMER ISSUE	-
DMS_13815	19888	N	N	N	1	CUSTOMER ISSUE	-
DMS_13816	19889	N	N	N	1	CUSTOMER ISSUE	-
DMS_13818	19890	N	N	N	1	CUSTOMER ISSUE	-
DMS_13819	19891	N	N	N	1	CUSTOMER ISSUE	-
DMS_13820	19892	N	N	N	1	CUSTOMER ISSUE	-
DMS_13821	19893	N	N	N	1	CUSTOMER ISSUE	-
DMS_13822	19894	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13823	19895	N	N	N	1	CUSTOMER ISSUE	-
DMS_13824	19896	N	N	N	1	CUSTOMER ISSUE	-

DMS_13825	19897	N	N	N	1	CUSTOMER ISSUE	-
DMS_13826	19898	N	N	N	1	CUSTOMER ISSUE	-
DMS_13827	19899	N	N	N	1	CUSTOMER ISSUE	-
DMS_13828	19900	N	N	N	1	CUSTOMER ISSUE	-
DMS_13829	19901	N	N	N	1	CUSTOMER ISSUE	-
DMS_13830	19902	N	N	N	1	CUSTOMER ISSUE	-
DMS_13831	19903	N	N	N	1	CUSTOMER ISSUE	-
DMS_13832	19904	N	N	N	1	CUSTOMER ISSUE	-
DMS_13833	19905	N	N	N	1	CUSTOMER ISSUE	-
DMS_13834	19906	N	N	N	1	CUSTOMER ISSUE	-
DMS_13835	19907	N	N	N	1	CUSTOMER ISSUE	-
DMS_13836	19908	N	N	N	1	CUSTOMER ISSUE	-
DMS_13837	19909	N	N	N	1	CUSTOMER ISSUE	-
DMS_13838	19910	N	N	N	1	CUSTOMER ISSUE	-
DMS_13839	19911	N	N	N	1	CUSTOMER ISSUE	-
DMS_13840	19912	N	N	N	1	CUSTOMER ISSUE	-
DMS_13841	19913	N	N	N	1	CUSTOMER ISSUE	-
DMS_13842	19914	N	N	N	1	CUSTOMER ISSUE	-
DMS_13843	19915	N	N	N	1	CUSTOMER ISSUE	-
DMS_13844	19916	N	N	N	1	CUSTOMER ISSUE	-
DMS_13845	19917	N	N	N	1	CUSTOMER ISSUE	-
DMS_13846	19918	N	N	N	1	CUSTOMER ISSUE	-
DMS_13847	19919	N	N	N	1	CUSTOMER ISSUE	-
DMS_13849	19920	N	N	N	1	CUSTOMER ISSUE	-
DMS_13850	19921	N	N	N	1	CUSTOMER ISSUE	-
DMS_13851	19922	N	N	N	1	CUSTOMER ISSUE	-
DMS_13852	19923	N	N	N	1	CUSTOMER ISSUE	-
DMS_13853	19924	N	N	N	1	CUSTOMER ISSUE	-
DMS_13854	19925	N	N	N	1	CUSTOMER ISSUE	-
DMS_13855	19926	N	N	N	1	CUSTOMER ISSUE	-
DMS_13856	19927	N	N	N	1	CUSTOMER ISSUE	-
DMS_13857	19928	N	N	N	1	CUSTOMER ISSUE	-
DMS_13858	19929	N	N	N	1	CUSTOMER ISSUE	-
DMS_13859	19930	N	N	N	1	CUSTOMER ISSUE	-
DMS_13860	19931	N	N	N	1	CUSTOMER ISSUE	-
DMS_13861	19932	N	N	N	1	CUSTOMER ISSUE	-
DMS_13862	19933	N	N	N	1	CUSTOMER ISSUE	-
DMS_13863	19934	N	N	N	1	CUSTOMER ISSUE	-
DMS_13864	19935	N	N	N	1	CUSTOMER ISSUE	-
DMS_13865	19936	N	N	N	1	CUSTOMER ISSUE	-
DMS_13866	19937	N	N	N	1	CUSTOMER ISSUE	-
DMS_13867	19938	N	N	N	1	CUSTOMER ISSUE	-
DMS_13868	19939	N	N	N	1	CUSTOMER ISSUE	-
DMS_13869	19940	N	N	N	1	CUSTOMER ISSUE	-
DMS_13870	19941	N	N	N	1	CUSTOMER ISSUE	-
DMS_13871	19942	N	N	N	1	CUSTOMER ISSUE	-
DMS_13872	19943	N	N	N	1	CUSTOMER ISSUE	-
DMS_13873	19944	N	N	N	1	CUSTOMER ISSUE	-
DMS_13874	19945	N	N	N	1	CUSTOMER ISSUE	-
DMS_13875	19946	N	N	N	1	CUSTOMER ISSUE	-
DMS_13876	19947	N	N	N	1	CUSTOMER ISSUE	-
DMS_13877	19948	N	N	N	1	CUSTOMER ISSUE	-
DMS_13878	19949	N	N	N	1	CUSTOMER ISSUE	-
DMS_13879	19950	N	N	N	1	CUSTOMER ISSUE	-
DMS_13880	19951	N	N	N	1	CUSTOMER ISSUE	-
DMS_13881	19952	N	N	N	1	CUSTOMER ISSUE	-
DMS_13882	19953	N	N	N	1	CUSTOMER ISSUE	-
DMS_13883	19954	N	N	N	1	CUSTOMER ISSUE	-
DMS_13884	19955	N	N	N	1	CUSTOMER ISSUE	-
DMS_13885	19956	N	N	N	1	CUSTOMER ISSUE	-
DMS_13886	19957	N	N	N	1	CUSTOMER ISSUE	-
DMS_13887	19958	N	N	N	1	CUSTOMER ISSUE	-
DMS_13888	19959	N	N	N	1	CUSTOMER ISSUE	-
DMS_13889	19960	N	N	N	1	CUSTOMER ISSUE	-
DMS_13890	19961	N	N	N	1	CUSTOMER ISSUE	-
DMS_13891	19962	N	N	N	1	CUSTOMER ISSUE	-
DMS_13892	19963	N	N	N	1	CUSTOMER ISSUE	-
DMS_13893	19964	N	N	N	1	CUSTOMER ISSUE	-
DMS_13894	19965	N	N	N	1	CUSTOMER ISSUE	-
DMS_13895	19966	N	N	N	1	CUSTOMER ISSUE	-
DMS_13896	19967	N	N	N	1	CUSTOMER ISSUE	-
DMS_13897	19968	N	N	N	1	CUSTOMER ISSUE	-
DMS_13898	19969	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13899	19970	N	N	N	1	CUSTOMER ISSUE	-
DMS_13900	19971	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13901	19972	N	N	N	1	CUSTOMER ISSUE	-
DMS_13902	19973	N	N	N	1	CUSTOMER ISSUE	-
DMS_13903	19974	N	N	N	1	CUSTOMER ISSUE	-
DMS_13904	19975	N	N	N	1	CUSTOMER ISSUE	-
DMS_13905	19976	N	N	N	1	CUSTOMER ISSUE	-

DMS_13906	19977	N	N	N	1	CUSTOMER ISSUE	-
DMS_13907	19978	N	N	N	1	CUSTOMER ISSUE	-
DMS_13908	19979	N	N	N	1	CUSTOMER ISSUE	-
DMS_13909	19980	N	N	N	1	CUSTOMER ISSUE	-
DMS_13910	19981	N	N	N	1	CUSTOMER ISSUE	-
DMS_13911	19982	N	N	N	1	CUSTOMER ISSUE	-
DMS_13912	19983	N	N	N	1	CUSTOMER ISSUE	-
DMS_13914	19984	N	N	N	1	CUSTOMER ISSUE	-
DMS_13915	19985	N	N	N	1	CUSTOMER ISSUE	-
DMS_13916	19986	N	N	N	1	CUSTOMER ISSUE	-
DMS_13917	19987	N	N	N	1	CUSTOMER ISSUE	-
DMS_13918	19988	N	N	N	1	CUSTOMER ISSUE	-
DMS_13919	19989	N	N	N	1	CUSTOMER ISSUE	-
DMS_13920	19990	N	N	N	1	CUSTOMER ISSUE	-
DMS_13921	19991	N	N	N	1	CUSTOMER ISSUE	-
DMS_13922	19992	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13923	19993	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13924	19994	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13925	19995	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13926	19996	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13927	19997	N	N	N	1	CUSTOMER ISSUE	-
DMS_13928	19998	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13929	19999	N	N	N	1	CUSTOMER ISSUE	-
DMS_13930	20000	N	N	N	1	CUSTOMER ISSUE	-
DMS_13931	20001	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13932	20002	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13933	20003	N	N	N	1	CUSTOMER ISSUE	-
DMS_13934	20004	N	N	N	1	CUSTOMER ISSUE	-
DMS_13935	20005	N	N	N	1	CUSTOMER ISSUE	-
DMS_13936	20006	N	N	N	1	CUSTOMER ISSUE	-
DMS_13937	20007	N	N	N	1	CUSTOMER ISSUE	-
DMS_13938	20008	N	N	N	1	CUSTOMER ISSUE	-
DMS_13939	20009	N	N	N	1	CUSTOMER ISSUE	-
DMS_13940	20010	N	N	N	1	CUSTOMER ISSUE	-
DMS_13941	20011	N	N	N	1	CUSTOMER ISSUE	-
DMS_13942	20012	N	N	N	1	CUSTOMER ISSUE	-
DMS_13943	20013	N	N	N	1	CUSTOMER ISSUE	-
DMS_13944	20014	N	N	N	1	CUSTOMER ISSUE	-
DMS_13945	20015	N	N	N	1	CUSTOMER ISSUE	-
DMS_13946	20016	N	N	N	1	CUSTOMER ISSUE	-
DMS_13947	20017	N	N	N	1	CUSTOMER ISSUE	-
DMS_13948	20018	N	N	N	1	CUSTOMER ISSUE	-
DMS_13949	20019	N	N	N	1	CUSTOMER ISSUE	-
DMS_13950	20020	N	N	N	1	CUSTOMER ISSUE	-
DMS_13952	20021	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13953	20022	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13954	20023	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13955	20024	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13956	20025	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13957	20026	N	N	N	1	CUSTOMER ISSUE	-
DMS_13958	20027	N	N	N	1	CUSTOMER ISSUE	-
DMS_13959	20028	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13960	20029	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13961	20030	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_13962	20031	N	N	N	1	CUSTOMER ISSUE	-
DMS_13963	20032	N	N	N	1	CUSTOMER ISSUE	-
DMS_13964	20033	N	N	N	1	CUSTOMER ISSUE	-
DMS_13965	20034	N	N	N	1	CUSTOMER ISSUE	-
DMS_13966	20035	N	N	N	1	CUSTOMER ISSUE	-
DMS_13967	20036	N	N	N	1	CUSTOMER ISSUE	-
DMS_13968	20037	N	N	N	1	CUSTOMER ISSUE	-
DMS_13969	20038	N	N	N	1	CUSTOMER ISSUE	-
DMS_13970	20039	N	N	N	1	CUSTOMER ISSUE	-
DMS_13971	20040	N	N	N	1	CUSTOMER ISSUE	-
DMS_13972	20041	N	N	N	1	CUSTOMER ISSUE	-
DMS_13973	20042	N	N	N	1	CUSTOMER ISSUE	-
DMS_13974	20043	N	N	N	1	CUSTOMER ISSUE	-
DMS_13975	20044	N	N	N	1	CUSTOMER ISSUE	-
DMS_13976	20045	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_13977	20046	N	N	N	1	CUSTOMER ISSUE	-
DMS_13978	20047	N	N	N	1	CUSTOMER ISSUE	-
DMS_13979	20048	N	N	N	1	CUSTOMER ISSUE	-
DMS_13980	20049	N	N	N	1	CUSTOMER ISSUE	-
DMS_13981	20050	N	N	N	1	CUSTOMER ISSUE	-
DMS_13982	20051	N	N	N	1	CUSTOMER ISSUE	-
DMS_13983	20052	N	N	N	1	CUSTOMER ISSUE	-
DMS_13984	20053	N	N	N	1	CUSTOMER ISSUE	-
DMS_13985	20054	N	N	N	1	CUSTOMER ISSUE	-
DMS_13986	20055	N	N	N	1	CUSTOMER ISSUE	-
DMS_13987	20056	N	N	N	1	CUSTOMER ISSUE	-

DMS_13988	20057	N	N	N	1	CUSTOMER ISSUE	-
DMS_13989	20058	N	N	N	1	CUSTOMER ISSUE	-
DMS_13990	20059	N	N	N	1	CUSTOMER ISSUE	-
DMS_13991	20060	N	N	N	1	CUSTOMER ISSUE	-
DMS_13992	20061	N	N	N	1	CUSTOMER ISSUE	-
DMS_13993	20062	N	N	N	1	CUSTOMER ISSUE	-
DMS_13994	20063	N	N	N	1	CUSTOMER ISSUE	-
DMS_13995	20064	N	N	N	1	CUSTOMER ISSUE	-
DMS_13996	20065	N	N	N	1	CUSTOMER ISSUE	-
DMS_13997	20066	N	N	N	1	CUSTOMER ISSUE	-
DMS_13998	20067	N	N	N	1	CUSTOMER ISSUE	-
DMS_13999	20068	N	N	N	1	CUSTOMER ISSUE	-
DMS_14000	20069	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14001	20070	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14002	20071	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14003	20072	N	N	N	1	CUSTOMER ISSUE	-
DMS_14004	20073	N	N	N	1	CUSTOMER ISSUE	-
DMS_14005	20074	N	N	N	1	CUSTOMER ISSUE	-
DMS_14006	20075	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14007	20076	N	N	N	1	CUSTOMER ISSUE	-
DMS_14008	20077	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14009	20078	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14010	20079	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14011	20080	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14012	20081	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14013	20082	N	N	N	1	CUSTOMER ISSUE	-
DMS_14014	20083	N	N	N	1	CUSTOMER ISSUE	-
DMS_14015	20084	N	N	N	1	CUSTOMER ISSUE	-
DMS_14016	20085	N	N	N	1	CUSTOMER ISSUE	-
DMS_14017	20086	N	N	N	1	CUSTOMER ISSUE	-
DMS_14018	20087	N	N	N	1	CUSTOMER ISSUE	-
DMS_14019	20088	N	N	N	1	CUSTOMER ISSUE	-
DMS_14020	20089	N	N	N	1	CUSTOMER ISSUE	-
DMS_14021	20090	N	N	N	1	CUSTOMER ISSUE	-
DMS_14022	20091	N	N	N	1	CUSTOMER ISSUE	-
DMS_14023	20092	N	N	N	1	CUSTOMER ISSUE	-
DMS_14024	20093	N	N	N	1	CUSTOMER ISSUE	-
DMS_14025	20094	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14026	20095	N	N	N	1	CUSTOMER ISSUE	-
DMS_14027	20096	N	N	N	1	CUSTOMER ISSUE	-
DMS_14028	20097	N	N	N	1	CUSTOMER ISSUE	-
DMS_14029	20098	N	N	N	1	CUSTOMER ISSUE	-
DMS_14030	20099	N	N	N	1	CUSTOMER ISSUE	-
DMS_14031	20100	N	N	N	1	CUSTOMER ISSUE	-
DMS_14032	20101	N	N	N	1	CUSTOMER ISSUE	-
DMS_14033	20102	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14034	20103	N	N	N	1	CUSTOMER ISSUE	-
DMS_14035	20104	N	N	N	1	CUSTOMER ISSUE	-
DMS_14036	20105	N	N	N	1	CUSTOMER ISSUE	-
DMS_14037	20106	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14038	20107	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14039	20108	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14040	20109	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14041	20110	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14042	20111	N	N	N	1	CUSTOMER ISSUE	-
DMS_14043	20112	N	N	N	1	CUSTOMER ISSUE	-
DMS_14044	20113	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14045	20114	N	N	N	1	CUSTOMER ISSUE	-
DMS_14046	20115	N	N	N	1	CUSTOMER ISSUE	-
DMS_14047	20116	N	N	N	1	CUSTOMER ISSUE	-
DMS_14048	20117	N	N	N	1	CUSTOMER ISSUE	-
DMS_14049	20118	N	N	N	1	CUSTOMER ISSUE	-
DMS_14050	20119	N	N	N	1	CUSTOMER ISSUE	-
DMS_14051	20120	N	N	N	1	CUSTOMER ISSUE	-
DMS_14052	20121	N	N	N	1	CUSTOMER ISSUE	-
DMS_14053	20122	N	N	N	1	CUSTOMER ISSUE	-
DMS_14054	20123	N	N	N	1	CUSTOMER ISSUE	-
DMS_14055	20124	N	N	N	1	CUSTOMER ISSUE	-
DMS_14056	20125	N	N	N	1	CUSTOMER ISSUE	-
DMS_14057	20126	N	N	N	1	CUSTOMER ISSUE	-
DMS_14058	20127	N	N	N	1	CUSTOMER ISSUE	-
DMS_14059	20128	N	N	N	1	CUSTOMER ISSUE	-
DMS_14060	20129	N	N	N	1	CUSTOMER ISSUE	-
DMS_14061	20130	N	N	N	1	CUSTOMER ISSUE	-
DMS_14064	20131	N	N	N	1	CUSTOMER ISSUE	-
DMS_14065	20132	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14066	20133	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14067	20134	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14068	20135	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14069	20136	N	N	Y	1	DIST - CHANGE SETTINGS	708.75

DMS_14070	20137	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_14071	20138	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14072	20139	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14073	20140	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14074	20141	N	N	N	1	CUSTOMER ISSUE	-
DMS_14075	20142	N	N	N	1	CUSTOMER ISSUE	-
DMS_14076	20143	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14077	20144	N	N	N	1	CUSTOMER ISSUE	-
DMS_14078	20145	N	N	N	1	CUSTOMER ISSUE	-
DMS_14079	20146	N	N	N	1	CUSTOMER ISSUE	-
DMS_14080	20147	N	N	N	1	CUSTOMER ISSUE	-
DMS_14081	20148	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14082	20149	N	N	N	1	CUSTOMER ISSUE	-
DMS_14083	20150	N	N	N	1	CUSTOMER ISSUE	-
DMS_14084	20151	N	N	N	3	CUSTOMER ISSUE	-
DMS_14085	20152	N	N	N	1	CUSTOMER ISSUE	-
DMS_14086	20153	N	N	N	1	CUSTOMER ISSUE	-
DMS_14087	20154	N	N	N	1	CUSTOMER ISSUE	-
DMS_14088	20155	N	N	N	1	CUSTOMER ISSUE	-
DMS_14089	20156	N	N	N	1	CUSTOMER ISSUE	-
DMS_14090	20157	N	N	N	1	CUSTOMER ISSUE	-
DMS_14091	20158	N	N	N	1	CUSTOMER ISSUE	-
DMS_14092	20159	N	N	N	1	CUSTOMER ISSUE	-
DMS_14093	20160	N	N	N	1	CUSTOMER ISSUE	-
DMS_14094	20161	N	N	N	1	CUSTOMER ISSUE	-
DMS_14095	20162	N	N	N	1	CUSTOMER ISSUE	-
DMS_14096	20163	N	N	N	1	CUSTOMER ISSUE	-
DMS_14097	20164	N	N	N	1	CUSTOMER ISSUE	-
DMS_14098	20165	N	N	N	1	CUSTOMER ISSUE	-
DMS_14099	20166	N	N	N	1	CUSTOMER ISSUE	-
DMS_14100	20167	N	N	N	1	CUSTOMER ISSUE	-
DMS_14101	20168	N	N	N	1	CUSTOMER ISSUE	-
DMS_14102	20169	N	N	N	1	CUSTOMER ISSUE	-
DMS_14103	20170	N	N	N	1	CUSTOMER ISSUE	-
DMS_14104	20171	N	N	N	1	CUSTOMER ISSUE	-
DMS_14105	20172	N	N	N	1	CUSTOMER ISSUE	-
DMS_14106	20173	N	N	N	1	CUSTOMER ISSUE	-
DMS_14107	20174	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14108	20175	N	N	N	1	CUSTOMER ISSUE	-
DMS_14109	20176	N	N	N	1	CUSTOMER ISSUE	-
DMS_14110	20177	N	N	N	1	CUSTOMER ISSUE	-
DMS_14111	20178	N	N	N	1	CUSTOMER ISSUE	-
DMS_14112	20179	N	N	N	1	CUSTOMER ISSUE	-
DMS_14113	20180	N	N	N	1	CUSTOMER ISSUE	-
DMS_14114	20181	N	N	N	1	CUSTOMER ISSUE	-
DMS_14115	20182	N	N	N	1	CUSTOMER ISSUE	-
DMS_14117	20183	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14118	20184	N	N	N	1	CUSTOMER ISSUE	-
DMS_14119	20185	N	N	N	1	CUSTOMER ISSUE	-
DMS_14120	20186	N	N	N	1	CUSTOMER ISSUE	-
DMS_14121	20187	N	N	N	1	CUSTOMER ISSUE	-
DMS_14122	20188	N	N	N	1	CUSTOMER ISSUE	-
DMS_14123	20189	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14124	20190	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14125	20191	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14126	20192	N	N	N	1	CUSTOMER ISSUE	-
DMS_14127	20193	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14128	20194	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14129	20195	N	N	N	1	CUSTOMER ISSUE	-
DMS_14130	20196	N	N	N	1	CUSTOMER ISSUE	-
DMS_14131	20197	N	N	N	1	CUSTOMER ISSUE	-
DMS_14132	20198	N	N	N	1	CUSTOMER ISSUE	-
DMS_14133	20199	N	N	N	1	CUSTOMER ISSUE	-
DMS_14134	20200	N	N	N	1	CUSTOMER ISSUE	-
DMS_14135	20201	N	N	N	1	CUSTOMER ISSUE	-
DMS_14136	20202	N	N	N	1	CUSTOMER ISSUE	-
DMS_14137	20203	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14138	20204	N	N	N	1	CUSTOMER ISSUE	-
DMS_14139	20205	N	N	N	1	CUSTOMER ISSUE	-
DMS_14140	20206	N	N	N	1	CUSTOMER ISSUE	-
DMS_14141	20207	N	N	N	1	CUSTOMER ISSUE	-
DMS_14143	20208	N	N	N	1	CUSTOMER ISSUE	-
DMS_14144	20209	N	N	N	1	CUSTOMER ISSUE	-
DMS_14145	20210	N	N	N	1	CUSTOMER ISSUE	-
DMS_14146	20211	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14147	20212	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14148	20213	N	N	N	1	CUSTOMER ISSUE	-
DMS_14149	20214	N	N	N	1	CUSTOMER ISSUE	-
DMS_14150	20215	N	N	N	1	CUSTOMER ISSUE	-
DMS_14151	20216	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_14152	20217	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14153	20218	N	N	N	1	CUSTOMER ISSUE	-
DMS_14154	20219	N	N	N	1	CUSTOMER ISSUE	-
DMS_14155	20220	N	N	N	1	CUSTOMER ISSUE	-
DMS_14156	20221	N	N	N	1	CUSTOMER ISSUE	-
DMS_14157	20222	N	N	N	1	CUSTOMER ISSUE	-
DMS_14158	20223	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14159	20224	N	N	N	1	CUSTOMER ISSUE	-
DMS_14160	20225	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14161	20226	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14162	20227	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14163	20228	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14164	20229	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14165	20230	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14166	20231	N	N	N	1	CUSTOMER ISSUE	-
DMS_14167	20232	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14168	20233	N	N	N	1	CUSTOMER ISSUE	-
DMS_14169	20234	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14170	20235	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14171	20236	N	N	N	1	CUSTOMER ISSUE	-
DMS_14172	20237	N	N	N	1	CUSTOMER ISSUE	-
DMS_14173	20238	N	N	N	1	CUSTOMER ISSUE	-
DMS_14174	20239	N	N	N	1	CUSTOMER ISSUE	-
DMS_14176	20240	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14177	20241	N	N	N	1	CUSTOMER ISSUE	-
DMS_14178	20242	N	N	N	1	CUSTOMER ISSUE	-
DMS_14179	20243	N	N	N	1	CUSTOMER ISSUE	-
DMS_14180	20244	N	N	N	1	CUSTOMER ISSUE	-
DMS_14181	20245	N	N	N	1	CUSTOMER ISSUE	-
DMS_14182	20246	N	N	N	1	CUSTOMER ISSUE	-
DMS_14183	20247	N	N	N	1	CUSTOMER ISSUE	-
DMS_14184	20248	N	N	N	1	CUSTOMER ISSUE	-
DMS_14185	20249	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14186	20250	N	N	N	1	CUSTOMER ISSUE	-
DMS_14187	20251	N	N	N	1	CUSTOMER ISSUE	-
DMS_14188	20252	N	N	N	1	CUSTOMER ISSUE	-
DMS_14189	20253	N	N	N	1	CUSTOMER ISSUE	-
DMS_14190	20254	N	N	N	1	CUSTOMER ISSUE	-
DMS_14191	20255	N	N	N	1	CUSTOMER ISSUE	-
DMS_14192	20256	N	N	N	1	CUSTOMER ISSUE	-
DMS_14193	20257	N	N	N	1	CUSTOMER ISSUE	-
DMS_14194	20258	N	N	N	1	CUSTOMER ISSUE	-
DMS_14195	20259	N	N	N	1	CUSTOMER ISSUE	-
DMS_14196	20260	N	N	N	1	CUSTOMER ISSUE	-
DMS_14197	20261	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14198	20262	N	N	N	1	CUSTOMER ISSUE	-
DMS_14199	20263	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14200	20264	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14201	20265	N	N	N	1	CUSTOMER ISSUE	-
DMS_14202	20266	N	N	N	1	CUSTOMER ISSUE	-
DMS_14203	20267	N	N	N	1	CUSTOMER ISSUE	-
DMS_14204	20268	N	N	N	1	CUSTOMER ISSUE	-
DMS_14205	20269	N	N	N	1	CUSTOMER ISSUE	-
DMS_14206	20270	N	N	N	1	CUSTOMER ISSUE	-
DMS_14207	20271	N	N	N	1	CUSTOMER ISSUE	-
DMS_14208	20272	N	N	N	1	CUSTOMER ISSUE	-
DMS_14209	20273	N	N	N	1	CUSTOMER ISSUE	-
DMS_14210	20274	N	N	N	1	CUSTOMER ISSUE	-
DMS_14211	20275	N	N	N	1	CUSTOMER ISSUE	-
DMS_14212	20276	N	N	N	1	CUSTOMER ISSUE	-
DMS_14213	20277	N	N	N	1	CUSTOMER ISSUE	-
DMS_14214	20278	N	N	N	1	CUSTOMER ISSUE	-
DMS_14215	20279	N	N	N	1	CUSTOMER ISSUE	-
DMS_14216	20280	N	N	N	1	CUSTOMER ISSUE	-
DMS_14217	20281	N	N	N	1	CUSTOMER ISSUE	-
DMS_14218	20282	N	N	N	1	CUSTOMER ISSUE	-
DMS_14219	20283	N	N	N	1	CUSTOMER ISSUE	-
DMS_14221	20284	N	N	N	1	CUSTOMER ISSUE	-
DMS_14222	20285	N	N	N	1	CUSTOMER ISSUE	-
DMS_14223	20286	N	N	N	1	CUSTOMER ISSUE	-
DMS_14224	20287	N	N	N	1	CUSTOMER ISSUE	-
DMS_14225	20288	N	N	N	1	CUSTOMER ISSUE	-
DMS_14226	20289	N	N	N	1	CUSTOMER ISSUE	-
DMS_14227	20290	N	N	N	1	CUSTOMER ISSUE	-
DMS_14228	20291	N	N	N	1	CUSTOMER ISSUE	-
DMS_14229	20292	N	N	N	1	CUSTOMER ISSUE	-
DMS_14230	20293	N	N	N	1	CUSTOMER ISSUE	-
DMS_14231	20294	N	N	N	1	CUSTOMER ISSUE	-
DMS_14232	20295	N	N	N	1	CUSTOMER ISSUE	-
DMS_14233	20296	N	N	N	1	CUSTOMER ISSUE	-

DMS_14234	20297	N	N	N	1	CUSTOMER ISSUE	-
DMS_14235	20298	N	N	N	1	CUSTOMER ISSUE	-
DMS_14236	20299	N	N	N	1	CUSTOMER ISSUE	-
DMS_14237	20300	N	N	N	1	CUSTOMER ISSUE	-
DMS_14238	20301	N	N	N	1	CUSTOMER ISSUE	-
DMS_14239	20302	N	N	N	1	CUSTOMER ISSUE	-
DMS_14240	20303	N	N	N	1	CUSTOMER ISSUE	-
DMS_14241	20304	N	N	N	1	CUSTOMER ISSUE	-
DMS_14242	20305	N	N	N	1	CUSTOMER ISSUE	-
DMS_14243	20306	N	N	N	1	CUSTOMER ISSUE	-
DMS_14244	20307	N	N	N	1	CUSTOMER ISSUE	-
DMS_14245	20308	N	N	N	1	CUSTOMER ISSUE	-
DMS_14246	20309	N	N	N	1	CUSTOMER ISSUE	-
DMS_14247	20310	N	N	N	1	CUSTOMER ISSUE	-
DMS_14248	20311	N	N	N	1	CUSTOMER ISSUE	-
DMS_14249	20312	N	N	N	1	CUSTOMER ISSUE	-
DMS_14250	20313	N	N	N	1	CUSTOMER ISSUE	-
DMS_14251	20314	N	N	N	1	CUSTOMER ISSUE	-
DMS_14252	20315	N	N	N	1	CUSTOMER ISSUE	-
DMS_14253	20316	N	N	N	1	CUSTOMER ISSUE	-
DMS_14254	20317	N	N	N	1	CUSTOMER ISSUE	-
DMS_14255	20318	N	N	N	1	CUSTOMER ISSUE	-
DMS_14256	20319	N	N	N	1	CUSTOMER ISSUE	-
DMS_14257	20320	N	N	N	1	CUSTOMER ISSUE	-
DMS_14258	20321	N	N	N	1	CUSTOMER ISSUE	-
DMS_14259	20322	N	N	N	1	CUSTOMER ISSUE	-
DMS_14260	20323	N	N	N	1	CUSTOMER ISSUE	-
DMS_14261	20324	N	N	N	1	CUSTOMER ISSUE	-
DMS_14263	20325	N	N	N	1	CUSTOMER ISSUE	-
DMS_14264	20326	N	N	N	1	CUSTOMER ISSUE	-
DMS_14265	20327	N	N	N	1	CUSTOMER ISSUE	-
DMS_14266	20328	N	N	N	1	CUSTOMER ISSUE	-
DMS_14267	20329	N	N	N	1	CUSTOMER ISSUE	-
DMS_14268	20330	N	N	N	1	CUSTOMER ISSUE	-
DMS_14269	20331	N	N	N	1	CUSTOMER ISSUE	-
DMS_14270	20332	N	N	N	1	CUSTOMER ISSUE	-
DMS_14271	20333	N	N	N	1	CUSTOMER ISSUE	-
DMS_14272	20334	N	N	N	1	CUSTOMER ISSUE	-
DMS_14273	20335	N	N	N	1	CUSTOMER ISSUE	-
DMS_14274	20336	N	N	N	1	CUSTOMER ISSUE	-
DMS_14275	20337	N	N	N	1	CUSTOMER ISSUE	-
DMS_14276	20338	N	N	N	1	CUSTOMER ISSUE	-
DMS_14277	20339	N	N	N	1	CUSTOMER ISSUE	-
DMS_14278	20340	N	N	N	1	CUSTOMER ISSUE	-
DMS_14280	20341	N	N	N	1	CUSTOMER ISSUE	-
DMS_14281	20342	N	N	N	1	CUSTOMER ISSUE	-
DMS_14282	20343	N	N	N	1	CUSTOMER ISSUE	-
DMS_14283	20344	N	N	N	1	CUSTOMER ISSUE	-
DMS_14284	20345	N	N	N	1	CUSTOMER ISSUE	-
DMS_14285	20346	N	N	N	1	CUSTOMER ISSUE	-
DMS_14286	20347	N	N	N	1	CUSTOMER ISSUE	-
DMS_14287	20348	N	N	N	1	CUSTOMER ISSUE	-
DMS_14288	20349	N	N	N	1	CUSTOMER ISSUE	-
DMS_14289	20350	N	N	N	1	CUSTOMER ISSUE	-
DMS_14290	20351	N	N	N	1	CUSTOMER ISSUE	-
DMS_14291	20352	N	N	N	1	CUSTOMER ISSUE	-
DMS_14292	20353	N	N	N	1	CUSTOMER ISSUE	-
DMS_14293	20354	N	N	N	1	CUSTOMER ISSUE	-
DMS_14294	20355	N	N	N	1	CUSTOMER ISSUE	-
DMS_14295	20356	N	N	N	1	CUSTOMER ISSUE	-
DMS_14296	20357	N	N	N	1	CUSTOMER ISSUE	-
DMS_14297	20358	N	N	N	1	CUSTOMER ISSUE	-
DMS_14298	20359	N	N	N	1	CUSTOMER ISSUE	-
DMS_14299	20360	N	N	N	1	CUSTOMER ISSUE	-
DMS_14300	20361	N	N	N	1	CUSTOMER ISSUE	-
DMS_14301	20362	N	N	N	1	CUSTOMER ISSUE	-
DMS_14302	20363	N	N	N	1	CUSTOMER ISSUE	-
DMS_14303	20364	N	N	N	1	CUSTOMER ISSUE	-
DMS_14304	20365	N	N	N	1	CUSTOMER ISSUE	-
DMS_14305	20366	N	N	N	1	CUSTOMER ISSUE	-
DMS_14306	20367	N	N	N	1	CUSTOMER ISSUE	-
DMS_14307	20368	N	N	N	1	CUSTOMER ISSUE	-
DMS_14308	20369	N	N	N	1	CUSTOMER ISSUE	-
DMS_14309	20370	N	N	N	1	CUSTOMER ISSUE	-
DMS_14310	20371	N	N	N	1	CUSTOMER ISSUE	-
DMS_14311	20372	N	N	N	1	CUSTOMER ISSUE	-
DMS_14312	20373	N	N	N	1	CUSTOMER ISSUE	-
DMS_14313	20374	N	N	N	1	CUSTOMER ISSUE	-
DMS_14314	20375	N	N	N	1	CUSTOMER ISSUE	-
DMS_14315	20376	N	N	N	1	CUSTOMER ISSUE	-

DMS_14316	20377	N	N	N	1	CUSTOMER ISSUE	-
DMS_14317	20378	N	N	N	1	CUSTOMER ISSUE	-
DMS_14318	20379	N	N	N	1	CUSTOMER ISSUE	-
DMS_14319	20380	N	N	N	1	CUSTOMER ISSUE	-
DMS_14320	20381	N	N	N	1	CUSTOMER ISSUE	-
DMS_14321	20382	N	N	N	1	CUSTOMER ISSUE	-
DMS_14322	20383	N	N	N	1	CUSTOMER ISSUE	-
DMS_14323	20384	N	N	N	1	CUSTOMER ISSUE	-
DMS_14324	20385	N	N	N	1	CUSTOMER ISSUE	-
DMS_14325	20386	N	N	N	1	CUSTOMER ISSUE	-
DMS_14326	20387	N	N	N	1	CUSTOMER ISSUE	-
DMS_14327	20388	N	N	N	1	CUSTOMER ISSUE	-
DMS_14328	20389	N	N	N	1	CUSTOMER ISSUE	-
DMS_14329	20390	N	N	N	1	CUSTOMER ISSUE	-
DMS_14330	20391	N	N	N	1	CUSTOMER ISSUE	-
DMS_14331	20392	N	N	N	1	CUSTOMER ISSUE	-
DMS_14332	20393	N	N	N	1	CUSTOMER ISSUE	-
DMS_14333	20394	N	N	N	1	CUSTOMER ISSUE	-
DMS_14334	20395	N	N	N	1	CUSTOMER ISSUE	-
DMS_14335	20396	N	N	N	1	CUSTOMER ISSUE	-
DMS_14336	20397	N	N	N	1	CUSTOMER ISSUE	-
DMS_14337	20398	N	N	N	1	CUSTOMER ISSUE	-
DMS_14338	20399	N	N	N	1	CUSTOMER ISSUE	-
DMS_14339	20400	N	N	N	1	CUSTOMER ISSUE	-
DMS_14340	20401	N	N	N	1	CUSTOMER ISSUE	-
DMS_14341	20402	N	N	N	1	CUSTOMER ISSUE	-
DMS_14342	20403	N	N	N	1	CUSTOMER ISSUE	-
DMS_14343	20404	N	N	N	1	CUSTOMER ISSUE	-
DMS_14344	20405	N	N	N	1	CUSTOMER ISSUE	-
DMS_14345	20406	N	N	N	1	CUSTOMER ISSUE	-
DMS_14346	20407	N	N	N	1	CUSTOMER ISSUE	-
DMS_14347	20408	N	N	N	1	CUSTOMER ISSUE	-
DMS_14348	20409	N	N	N	1	CUSTOMER ISSUE	-
DMS_14349	20410	N	N	N	1	CUSTOMER ISSUE	-
DMS_14350	20411	N	N	N	1	CUSTOMER ISSUE	-
DMS_14351	20412	N	N	N	1	CUSTOMER ISSUE	-
DMS_14352	20413	N	N	N	1	CUSTOMER ISSUE	-
DMS_14353	20414	N	N	N	1	CUSTOMER ISSUE	-
DMS_14354	20415	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14355	20416	N	N	N	1	CUSTOMER ISSUE	-
DMS_14356	20417	N	N	N	1	CUSTOMER ISSUE	-
DMS_14357	20418	N	N	N	1	CUSTOMER ISSUE	-
DMS_14358	20419	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14359	20420	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_14360	20421	N	N	N	1	CUSTOMER ISSUE	-
DMS_14361	20422	N	N	N	1	CUSTOMER ISSUE	-
DMS_14362	20423	N	N	N	1	CUSTOMER ISSUE	-
DMS_14363	20424	N	N	N	1	CUSTOMER ISSUE	-
DMS_14364	20425	N	N	N	1	CUSTOMER ISSUE	-
DMS_14365	20426	N	N	N	1	CUSTOMER ISSUE	-
DMS_14366	20427	N	N	N	1	CUSTOMER ISSUE	-
DMS_14367	20428	N	N	N	1	CUSTOMER ISSUE	-
DMS_14368	20429	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14369	20430	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14370	20431	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14371	20432	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14372	20433	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14373	20434	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14374	20435	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14375	20436	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14376	20437	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14377	20438	N	N	N	1	CUSTOMER ISSUE	-
DMS_14378	20439	N	N	N	1	CUSTOMER ISSUE	-
DMS_14379	20440	N	N	N	1	CUSTOMER ISSUE	-
DMS_14380	20441	N	N	N	1	CUSTOMER ISSUE	-
DMS_14381	20442	N	N	N	1	CUSTOMER ISSUE	-
DMS_14382	20443	N	N	N	1	CUSTOMER ISSUE	-
DMS_14383	20444	N	N	N	1	CUSTOMER ISSUE	-
DMS_14384	20445	N	N	N	1	CUSTOMER ISSUE	-
DMS_14385	20446	N	N	N	1	CUSTOMER ISSUE	-
DMS_14386	20447	N	N	N	1	CUSTOMER ISSUE	-
DMS_14387	20448	N	N	N	1	CUSTOMER ISSUE	-
DMS_14388	20449	N	N	N	1	CUSTOMER ISSUE	-
DMS_14389	20450	N	N	N	1	CUSTOMER ISSUE	-
DMS_14390	20451	N	N	N	1	CUSTOMER ISSUE	-
DMS_14391	20452	N	N	N	1	CUSTOMER ISSUE	-
DMS_14392	20453	N	N	N	1	CUSTOMER ISSUE	-
DMS_14393	20454	N	N	N	1	CUSTOMER ISSUE	-
DMS_14394	20455	N	N	N	1	CUSTOMER ISSUE	-
DMS_14395	20456	N	N	N	2	CUSTOMER ISSUE	-

DMS_14396	20457	N	N	N	1	CUSTOMER ISSUE	-
DMS_14397	20458	N	N	N	1	CUSTOMER ISSUE	-
DMS_14398	20459	N	N	N	1	CUSTOMER ISSUE	-
DMS_14399	20460	N	N	N	1	CUSTOMER ISSUE	-
DMS_14400	20461	N	N	N	1	CUSTOMER ISSUE	-
DMS_14401	20462	N	N	N	1	CUSTOMER ISSUE	-
DMS_14402	20463	N	N	N	1	CUSTOMER ISSUE	-
DMS_14403	20464	N	N	N	1	CUSTOMER ISSUE	-
DMS_14404	20465	N	N	N	1	CUSTOMER ISSUE	-
DMS_14405	20466	N	N	N	1	CUSTOMER ISSUE	-
DMS_14406	20467	N	N	N	1	CUSTOMER ISSUE	-
DMS_14407	20468	N	N	N	1	CUSTOMER ISSUE	-
DMS_14408	20469	N	N	N	1	CUSTOMER ISSUE	-
DMS_14409	20470	N	N	N	1	CUSTOMER ISSUE	-
DMS_14410	20471	N	N	N	1	CUSTOMER ISSUE	-
DMS_14411	20472	N	N	N	1	CUSTOMER ISSUE	-
DMS_14412	20473	N	N	N	1	CUSTOMER ISSUE	-
DMS_14413	20474	N	N	N	1	CUSTOMER ISSUE	-
DMS_14414	20475	N	N	N	1	CUSTOMER ISSUE	-
DMS_14415	20476	N	N	N	1	CUSTOMER ISSUE	-
DMS_14416	20477	N	N	N	1	CUSTOMER ISSUE	-
DMS_14417	20478	N	N	N	1	CUSTOMER ISSUE	-
DMS_14418	20479	N	N	N	1	CUSTOMER ISSUE	-
DMS_14419	20480	N	N	N	1	CUSTOMER ISSUE	-
DMS_14420	20481	N	N	N	1	CUSTOMER ISSUE	-
DMS_14421	20482	N	N	N	1	CUSTOMER ISSUE	-
DMS_14422	20483	N	N	N	1	CUSTOMER ISSUE	-
DMS_14423	20484	N	N	N	1	CUSTOMER ISSUE	-
DMS_14424	20485	N	N	N	1	CUSTOMER ISSUE	-
DMS_14425	20486	N	N	N	1	CUSTOMER ISSUE	-
DMS_14426	20487	N	N	N	1	CUSTOMER ISSUE	-
DMS_14427	20488	N	N	N	1	CUSTOMER ISSUE	-
DMS_14428	20489	N	N	N	1	CUSTOMER ISSUE	-
DMS_14429	20490	N	N	N	1	CUSTOMER ISSUE	-
DMS_14430	20491	N	N	N	1	CUSTOMER ISSUE	-
DMS_14431	20492	N	N	N	1	CUSTOMER ISSUE	-
DMS_14432	20493	N	N	N	1	CUSTOMER ISSUE	-
DMS_14433	20494	N	N	N	1	CUSTOMER ISSUE	-
DMS_14434	20495	N	N	N	1	CUSTOMER ISSUE	-
DMS_14435	20496	N	N	N	1	CUSTOMER ISSUE	-
DMS_14436	20497	N	N	N	1	CUSTOMER ISSUE	-
DMS_14437	20498	N	N	N	1	CUSTOMER ISSUE	-
DMS_14438	20499	N	N	N	1	CUSTOMER ISSUE	-
DMS_14439	20500	N	N	N	1	CUSTOMER ISSUE	-
DMS_14440	20501	N	N	N	1	CUSTOMER ISSUE	-
DMS_14441	20502	N	N	N	1	CUSTOMER ISSUE	-
DMS_14442	20503	N	N	N	1	CUSTOMER ISSUE	-
DMS_14443	20504	N	N	N	1	CUSTOMER ISSUE	-
DMS_14444	20505	N	N	N	1	CUSTOMER ISSUE	-
DMS_14445	20506	N	N	N	1	CUSTOMER ISSUE	-
DMS_14446	20507	N	N	N	1	CUSTOMER ISSUE	-
DMS_14447	20508	N	N	N	1	CUSTOMER ISSUE	-
DMS_14448	20509	N	N	N	1	CUSTOMER ISSUE	-
DMS_14449	20510	N	N	N	1	CUSTOMER ISSUE	-
DMS_14450	20511	N	N	N	1	CUSTOMER ISSUE	-
DMS_14451	20512	N	N	N	1	CUSTOMER ISSUE	-
DMS_14452	20513	N	N	N	1	CUSTOMER ISSUE	-
DMS_14453	20514	N	N	N	1	CUSTOMER ISSUE	-
DMS_14454	20515	N	N	N	1	CUSTOMER ISSUE	-
DMS_14455	20516	N	N	N	1	CUSTOMER ISSUE	-
DMS_14456	20517	N	N	N	1	CUSTOMER ISSUE	-
DMS_14457	20518	N	N	N	1	CUSTOMER ISSUE	-
DMS_14458	20519	N	N	N	1	CUSTOMER ISSUE	-
DMS_14459	20520	N	N	N	1	CUSTOMER ISSUE	-
DMS_14460	20521	N	N	N	1	CUSTOMER ISSUE	-
DMS_14461	20522	N	N	N	1	CUSTOMER ISSUE	-
DMS_14462	20523	N	N	N	1	CUSTOMER ISSUE	-
DMS_14463	20524	N	N	N	1	CUSTOMER ISSUE	-
DMS_14464	20525	N	N	N	1	CUSTOMER ISSUE	-
DMS_14465	20526	N	N	N	1	CUSTOMER ISSUE	-
DMS_14466	20527	N	N	N	1	CUSTOMER ISSUE	-
DMS_14467	20528	N	N	N	1	CUSTOMER ISSUE	-
DMS_14468	20529	N	N	N	1	CUSTOMER ISSUE	-
DMS_14469	20530	N	N	N	1	CUSTOMER ISSUE	-
DMS_14470	20531	N	N	N	1	CUSTOMER ISSUE	-
DMS_14471	20532	N	N	N	1	CUSTOMER ISSUE	-
DMS_14472	20533	N	N	N	1	CUSTOMER ISSUE	-
DMS_14473	20534	N	N	N	1	CUSTOMER ISSUE	-
DMS_14474	20535	N	N	N	1	CUSTOMER ISSUE	-
DMS_14475	20536	N	N	N	1	CUSTOMER ISSUE	-

DMS_14476	20537	N	N	N	1	CUSTOMER ISSUE	-
DMS_14477	20538	N	N	N	1	CUSTOMER ISSUE	-
DMS_14478	20539	N	N	N	1	CUSTOMER ISSUE	-
DMS_14479	20540	N	N	N	1	CUSTOMER ISSUE	-
DMS_14480	20541	N	N	N	1	CUSTOMER ISSUE	-
DMS_14481	20542	N	N	N	1	CUSTOMER ISSUE	-
DMS_14482	20543	N	N	N	1	CUSTOMER ISSUE	-
DMS_14483	20544	N	N	N	1	CUSTOMER ISSUE	-
DMS_14484	20545	N	N	N	1	CUSTOMER ISSUE	-
DMS_14485	20546	N	N	N	1	CUSTOMER ISSUE	-
DMS_14486	20547	N	N	N	1	CUSTOMER ISSUE	-
DMS_14487	20548	N	N	N	1	CUSTOMER ISSUE	-
DMS_14488	20549	N	N	N	1	CUSTOMER ISSUE	-
DMS_14489	20550	N	N	N	1	CUSTOMER ISSUE	-
DMS_14490	20551	N	N	N	1	CUSTOMER ISSUE	-
DMS_14491	20552	N	N	N	1	CUSTOMER ISSUE	-
DMS_14492	20553	N	N	N	1	CUSTOMER ISSUE	-
DMS_14493	20554	N	N	N	1	CUSTOMER ISSUE	-
DMS_14494	20555	N	N	N	1	CUSTOMER ISSUE	-
DMS_14495	20556	N	N	N	1	CUSTOMER ISSUE	-
DMS_14496	20557	N	N	N	1	CUSTOMER ISSUE	-
DMS_14497	20558	N	N	N	1	CUSTOMER ISSUE	-
DMS_14498	20559	N	N	N	1	CUSTOMER ISSUE	-
DMS_14499	20560	N	N	N	1	CUSTOMER ISSUE	-
DMS_14500	20561	N	N	N	1	CUSTOMER ISSUE	-
DMS_14501	20562	N	N	N	1	CUSTOMER ISSUE	-
DMS_14502	20563	N	N	N	1	CUSTOMER ISSUE	-
DMS_14503	20564	N	N	N	1	CUSTOMER ISSUE	-
DMS_14504	20565	N	N	N	1	CUSTOMER ISSUE	-
DMS_14505	20566	N	N	N	1	CUSTOMER ISSUE	-
DMS_14506	20567	N	N	N	1	CUSTOMER ISSUE	-
DMS_14507	20568	N	N	N	1	CUSTOMER ISSUE	-
DMS_14508	20569	N	N	N	1	CUSTOMER ISSUE	-
DMS_14509	20570	N	N	N	1	CUSTOMER ISSUE	-
DMS_14510	20571	N	N	N	1	CUSTOMER ISSUE	-
DMS_14511	20572	N	N	N	1	CUSTOMER ISSUE	-
DMS_14512	20573	N	N	N	1	CUSTOMER ISSUE	-
DMS_14513	20574	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14514	20575	N	N	N	1	CUSTOMER ISSUE	-
DMS_14515	20576	N	N	N	1	CUSTOMER ISSUE	-
DMS_14516	20577	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14517	20578	N	N	N	1	CUSTOMER ISSUE	-
DMS_14518	20579	N	N	N	1	CUSTOMER ISSUE	-
DMS_14519	20580	N	N	N	1	CUSTOMER ISSUE	-
DMS_14520	20581	N	N	N	1	CUSTOMER ISSUE	-
DMS_14521	20582	N	N	N	1	CUSTOMER ISSUE	-
DMS_14522	20583	N	N	N	1	CUSTOMER ISSUE	-
DMS_14523	20584	N	N	N	1	CUSTOMER ISSUE	-
DMS_14524	20585	N	N	N	1	CUSTOMER ISSUE	-
DMS_14525	20586	N	N	N	1	CUSTOMER ISSUE	-
DMS_14526	20587	N	N	N	1	CUSTOMER ISSUE	-
DMS_14527	20588	N	N	N	1	CUSTOMER ISSUE	-
DMS_14528	20589	N	N	N	1	CUSTOMER ISSUE	-
DMS_14529	20590	N	N	N	1	CUSTOMER ISSUE	-
DMS_14530	20591	N	N	N	1	CUSTOMER ISSUE	-
DMS_14531	20592	N	N	N	1	CUSTOMER ISSUE	-
DMS_14532	20593	N	N	N	1	CUSTOMER ISSUE	-
DMS_14533	20594	N	N	N	2	CUSTOMER ISSUE	-
DMS_14534	20595	N	N	N	1	CUSTOMER ISSUE	-
DMS_14535	20596	N	N	N	1	CUSTOMER ISSUE	-
DMS_14536	20597	N	N	N	1	CUSTOMER ISSUE	-
DMS_14537	20598	N	N	N	1	CUSTOMER ISSUE	-
DMS_14538	20599	N	N	N	1	CUSTOMER ISSUE	-
DMS_14539	20600	N	N	N	1	CUSTOMER ISSUE	-
DMS_14540	20601	N	N	N	1	CUSTOMER ISSUE	-
DMS_14541	20602	N	N	N	1	CUSTOMER ISSUE	-
DMS_14542	20603	N	N	N	1	CUSTOMER ISSUE	-
DMS_14543	20604	N	N	N	1	CUSTOMER ISSUE	-
DMS_14544	20605	N	N	N	1	CUSTOMER ISSUE	-
DMS_14545	20606	N	N	N	1	CUSTOMER ISSUE	-
DMS_14546	20607	N	N	N	1	CUSTOMER ISSUE	-
DMS_14547	20608	N	N	N	1	CUSTOMER ISSUE	-
DMS_14548	20609	N	N	N	1	CUSTOMER ISSUE	-
DMS_14549	20610	N	N	N	1	CUSTOMER ISSUE	-
DMS_14550	20611	N	N	N	1	CUSTOMER ISSUE	-
DMS_14551	20612	N	N	N	1	CUSTOMER ISSUE	-
DMS_14552	20613	N	N	N	1	CUSTOMER ISSUE	-
DMS_14553	20614	N	N	N	1	CUSTOMER ISSUE	-
DMS_14554	20615	N	N	N	1	CUSTOMER ISSUE	-
DMS_14555	20616	N	N	N	1	CUSTOMER ISSUE	-

DMS_14556	20617	N	N	N	1	CUSTOMER ISSUE	-
DMS_14557	20618	N	N	N	1	CUSTOMER ISSUE	-
DMS_14558	20619	N	N	N	1	CUSTOMER ISSUE	-
DMS_14559	20620	N	N	N	1	CUSTOMER ISSUE	-
DMS_14560	20621	N	N	N	1	CUSTOMER ISSUE	-
DMS_14561	20622	N	N	N	1	CUSTOMER ISSUE	-
DMS_14562	20623	N	N	N	1	CUSTOMER ISSUE	-
DMS_14563	20624	N	N	N	1	CUSTOMER ISSUE	-
DMS_14564	20625	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14565	20626	N	N	N	1	CUSTOMER ISSUE	-
DMS_14566	20627	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14567	20628	N	N	N	1	CUSTOMER ISSUE	-
DMS_14568	20629	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14569	20630	N	N	N	1	CUSTOMER ISSUE	-
DMS_14570	20631	N	N	N	1	CUSTOMER ISSUE	-
DMS_14571	20632	N	N	N	1	CUSTOMER ISSUE	-
DMS_14572	20633	N	N	N	1	CUSTOMER ISSUE	-
DMS_14573	20634	N	N	N	1	CUSTOMER ISSUE	-
DMS_14574	20635	N	N	N	1	CUSTOMER ISSUE	-
DMS_14575	20636	N	N	N	1	CUSTOMER ISSUE	-
DMS_14576	20637	N	N	N	1	CUSTOMER ISSUE	-
DMS_14577	20638	N	N	N	1	CUSTOMER ISSUE	-
DMS_14578	20639	N	N	N	1	CUSTOMER ISSUE	-
DMS_14579	20640	N	N	N	1	CUSTOMER ISSUE	-
DMS_14580	20641	N	N	N	1	CUSTOMER ISSUE	-
DMS_14581	20642	N	N	N	1	CUSTOMER ISSUE	-
DMS_14582	20643	N	N	N	1	CUSTOMER ISSUE	-
DMS_14583	20644	N	N	N	1	CUSTOMER ISSUE	-
DMS_14584	20645	N	N	N	1	CUSTOMER ISSUE	-
DMS_14585	20646	N	N	N	1	CUSTOMER ISSUE	-
DMS_14586	20647	N	N	N	1	CUSTOMER ISSUE	-
DMS_14587	20648	N	N	N	1	CUSTOMER ISSUE	-
DMS_14588	20649	N	N	N	1	CUSTOMER ISSUE	-
DMS_14589	20650	N	N	N	1	CUSTOMER ISSUE	-
DMS_14590	20651	N	N	N	1	CUSTOMER ISSUE	-
DMS_14591	20652	N	N	N	1	CUSTOMER ISSUE	-
DMS_14592	20653	N	N	N	1	CUSTOMER ISSUE	-
DMS_14593	20654	N	N	N	1	CUSTOMER ISSUE	-
DMS_14594	20655	N	N	N	1	CUSTOMER ISSUE	-
DMS_14595	20656	N	N	N	1	CUSTOMER ISSUE	-
DMS_14596	20657	N	N	N	1	CUSTOMER ISSUE	-
DMS_14597	20658	N	N	N	1	CUSTOMER ISSUE	-
DMS_14598	20659	N	N	N	1	CUSTOMER ISSUE	-
DMS_14599	20660	N	N	N	1	CUSTOMER ISSUE	-
DMS_14600	20661	N	N	N	1	CUSTOMER ISSUE	-
DMS_14601	20662	N	N	N	1	CUSTOMER ISSUE	-
DMS_14602	20663	N	N	N	1	CUSTOMER ISSUE	-
DMS_14603	20664	N	N	N	1	CUSTOMER ISSUE	-
DMS_14604	20665	N	N	N	1	CUSTOMER ISSUE	-
DMS_14605	20666	N	N	N	1	CUSTOMER ISSUE	-
DMS_14606	20667	N	N	N	1	CUSTOMER ISSUE	-
DMS_14607	20668	N	N	N	1	CUSTOMER ISSUE	-
DMS_14608	20669	N	N	N	1	CUSTOMER ISSUE	-
DMS_14609	20670	N	N	N	1	CUSTOMER ISSUE	-
DMS_14610	20671	N	N	N	1	CUSTOMER ISSUE	-
DMS_14611	20672	N	N	N	1	CUSTOMER ISSUE	-
DMS_14612	20673	N	N	N	1	CUSTOMER ISSUE	-
DMS_14613	20674	N	N	N	1	CUSTOMER ISSUE	-
DMS_14614	20675	N	N	N	1	CUSTOMER ISSUE	-
DMS_14615	20676	N	N	N	1	CUSTOMER ISSUE	-
DMS_14616	20677	N	N	N	1	CUSTOMER ISSUE	-
DMS_14617	20678	N	N	N	1	CUSTOMER ISSUE	-
DMS_14618	20679	N	N	N	1	CUSTOMER ISSUE	-
DMS_14619	20680	N	N	N	1	CUSTOMER ISSUE	-
DMS_14620	20681	N	N	N	1	CUSTOMER ISSUE	-
DMS_14621	20682	N	N	N	1	CUSTOMER ISSUE	-
DMS_14622	20683	N	N	N	1	CUSTOMER ISSUE	-
DMS_14623	20684	N	N	N	1	CUSTOMER ISSUE	-
DMS_14624	20685	N	N	N	1	CUSTOMER ISSUE	-
DMS_14625	20686	N	N	N	2	CUSTOMER ISSUE	-
DMS_14626	20687	N	N	N	1	CUSTOMER ISSUE	-
DMS_14627	20688	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14628	20689	N	N	N	1	CUSTOMER ISSUE	-
DMS_14629	20690	N	N	N	1	CUSTOMER ISSUE	-
DMS_14630	20691	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14631	20692	N	N	N	1	CUSTOMER ISSUE	-
DMS_14632	20693	N	N	N	1	CUSTOMER ISSUE	-
DMS_14633	20694	N	N	N	1	CUSTOMER ISSUE	-
DMS_14634	20695	N	N	N	1	CUSTOMER ISSUE	-
DMS_14635	20696	N	N	N	1	CUSTOMER ISSUE	-

DMS_14636	20697	N	N	N	1	CUSTOMER ISSUE	-
DMS_14637	20698	N	N	N	1	CUSTOMER ISSUE	-
DMS_14638	20699	N	N	N	1	CUSTOMER ISSUE	-
DMS_14639	20700	N	N	N	1	CUSTOMER ISSUE	-
DMS_14640	20701	N	N	N	1	CUSTOMER ISSUE	-
DMS_14641	20702	N	N	N	1	CUSTOMER ISSUE	-
DMS_14642	20703	N	N	N	1	CUSTOMER ISSUE	-
DMS_14643	20704	N	N	N	1	CUSTOMER ISSUE	-
DMS_14644	20705	N	N	N	1	CUSTOMER ISSUE	-
DMS_14645	20706	N	N	N	1	CUSTOMER ISSUE	-
DMS_14646	20707	N	N	N	1	CUSTOMER ISSUE	-
DMS_14647	20708	N	N	N	1	CUSTOMER ISSUE	-
DMS_14648	20709	N	N	N	1	CUSTOMER ISSUE	-
DMS_14649	20710	N	N	N	1	CUSTOMER ISSUE	-
DMS_14650	20711	N	N	N	1	CUSTOMER ISSUE	-
DMS_14651	20712	N	N	N	1	CUSTOMER ISSUE	-
DMS_14652	20713	N	N	N	1	CUSTOMER ISSUE	-
DMS_14653	20714	N	N	N	1	CUSTOMER ISSUE	-
DMS_14654	20715	N	N	N	1	CUSTOMER ISSUE	-
DMS_14655	20716	N	N	N	1	CUSTOMER ISSUE	-
DMS_14656	20717	N	N	N	1	CUSTOMER ISSUE	-
DMS_14657	20718	N	N	N	1	CUSTOMER ISSUE	-
DMS_14658	20719	N	N	N	1	CUSTOMER ISSUE	-
DMS_14659	20720	N	N	N	1	CUSTOMER ISSUE	-
DMS_14660	20721	N	N	N	1	CUSTOMER ISSUE	-
DMS_14661	20722	N	N	N	1	CUSTOMER ISSUE	-
DMS_14662	20723	N	N	N	1	CUSTOMER ISSUE	-
DMS_14664	20724	N	N	N	1	CUSTOMER ISSUE	-
DMS_14665	20725	N	N	N	1	CUSTOMER ISSUE	-
DMS_14666	20726	N	N	N	1	CUSTOMER ISSUE	-
DMS_14667	20727	N	N	N	1	CUSTOMER ISSUE	-
DMS_14668	20728	N	N	N	1	CUSTOMER ISSUE	-
DMS_14669	20729	N	N	N	1	CUSTOMER ISSUE	-
DMS_14670	20730	N	N	N	1	CUSTOMER ISSUE	-
DMS_14671	20731	N	N	N	1	CUSTOMER ISSUE	-
DMS_14672	20732	N	N	N	1	CUSTOMER ISSUE	-
DMS_14673	20733	N	N	N	1	CUSTOMER ISSUE	-
DMS_14674	20734	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14675	20735	N	N	N	1	CUSTOMER ISSUE	-
DMS_14676	20736	N	N	N	1	CUSTOMER ISSUE	-
DMS_14677	20737	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14678	20738	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14679	20739	N	N	N	1	CUSTOMER ISSUE	-
DMS_14680	20740	N	N	N	1	CUSTOMER ISSUE	-
DMS_14681	20741	N	N	N	1	CUSTOMER ISSUE	-
DMS_14682	20742	N	N	N	1	CUSTOMER ISSUE	-
DMS_14683	20743	N	N	N	1	CUSTOMER ISSUE	-
DMS_14684	20744	N	N	N	1	CUSTOMER ISSUE	-
DMS_14685	20745	N	N	N	1	CUSTOMER ISSUE	-
DMS_14686	20746	N	N	N	1	CUSTOMER ISSUE	-
DMS_14687	20747	N	N	N	1	CUSTOMER ISSUE	-
DMS_14688	20748	N	N	N	1	CUSTOMER ISSUE	-
DMS_14689	20749	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14690	20750	N	N	N	1	CUSTOMER ISSUE	-
DMS_14691	20751	N	N	N	1	CUSTOMER ISSUE	-
DMS_14692	20752	N	N	N	1	CUSTOMER ISSUE	-
DMS_14693	20753	N	N	N	1	CUSTOMER ISSUE	-
DMS_14694	20754	N	N	N	1	CUSTOMER ISSUE	-
DMS_14695	20755	N	N	N	1	CUSTOMER ISSUE	-
DMS_14696	20756	N	N	N	1	CUSTOMER ISSUE	-
DMS_14697	20757	N	N	N	1	CUSTOMER ISSUE	-
DMS_14698	20758	N	N	N	1	CUSTOMER ISSUE	-
DMS_14699	20759	N	N	N	1	CUSTOMER ISSUE	-
DMS_14700	20760	N	N	N	1	CUSTOMER ISSUE	-
DMS_14701	20761	N	N	N	1	CUSTOMER ISSUE	-
DMS_14702	20762	N	N	N	1	CUSTOMER ISSUE	-
DMS_14703	20763	N	N	N	1	CUSTOMER ISSUE	-
DMS_14704	20764	N	N	N	1	CUSTOMER ISSUE	-
DMS_14705	20765	N	N	N	1	CUSTOMER ISSUE	-
DMS_14706	20766	N	N	N	1	CUSTOMER ISSUE	-
DMS_14707	20767	N	N	N	1	CUSTOMER ISSUE	-
DMS_14708	20768	N	N	N	1	CUSTOMER ISSUE	-
DMS_14709	20769	N	N	N	1	CUSTOMER ISSUE	-
DMS_14710	20770	N	N	N	1	CUSTOMER ISSUE	-
DMS_14711	20771	N	N	N	1	CUSTOMER ISSUE	-
DMS_14712	20772	N	N	N	1	CUSTOMER ISSUE	-
DMS_14713	20773	N	N	N	1	CUSTOMER ISSUE	-
DMS_14714	20774	N	N	N	1	CUSTOMER ISSUE	-
DMS_14715	20775	N	N	N	1	CUSTOMER ISSUE	-
DMS_14716	20776	N	N	N	1	CUSTOMER ISSUE	-

DMS_14717	20777	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14718	20778	N	N	N	1	CUSTOMER ISSUE	-
DMS_14719	20779	N	N	N	1	CUSTOMER ISSUE	-
DMS_14720	20780	N	N	N	1	CUSTOMER ISSUE	-
DMS_14721	20781	N	N	N	1	CUSTOMER ISSUE	-
DMS_14722	20782	N	N	N	1	CUSTOMER ISSUE	-
DMS_14723	20783	N	N	N	1	CUSTOMER ISSUE	-
DMS_14724	20784	N	N	N	1	CUSTOMER ISSUE	-
DMS_14725	20785	N	N	N	1	CUSTOMER ISSUE	-
DMS_14726	20786	N	N	N	1	CUSTOMER ISSUE	-
DMS_14727	20787	N	N	N	1	CUSTOMER ISSUE	-
DMS_14728	20788	N	N	N	1	CUSTOMER ISSUE	-
DMS_14729	20789	N	N	N	1	CUSTOMER ISSUE	-
DMS_14730	20790	N	N	N	1	CUSTOMER ISSUE	-
DMS_14731	20791	N	N	N	1	CUSTOMER ISSUE	-
DMS_14732	20792	N	N	N	1	CUSTOMER ISSUE	-
DMS_14733	20793	N	N	N	1	CUSTOMER ISSUE	-
DMS_14734	20794	N	N	N	1	CUSTOMER ISSUE	-
DMS_14735	20795	N	N	N	1	CUSTOMER ISSUE	-
DMS_14736	20796	N	N	N	1	CUSTOMER ISSUE	-
DMS_14737	20797	N	N	N	1	CUSTOMER ISSUE	-
DMS_14738	20798	N	N	N	1	CUSTOMER ISSUE	-
DMS_14739	20799	N	N	N	1	CUSTOMER ISSUE	-
DMS_14740	20800	N	N	N	1	CUSTOMER ISSUE	-
DMS_14741	20801	N	N	N	1	CUSTOMER ISSUE	-
DMS_14742	20802	N	N	N	1	CUSTOMER ISSUE	-
DMS_14743	20803	N	N	N	1	CUSTOMER ISSUE	-
DMS_14744	20804	N	N	N	1	CUSTOMER ISSUE	-
DMS_14745	20805	N	N	N	1	CUSTOMER ISSUE	-
DMS_14746	20806	N	N	N	1	CUSTOMER ISSUE	-
DMS_14747	20807	N	N	N	1	CUSTOMER ISSUE	-
DMS_14748	20808	N	N	N	1	CUSTOMER ISSUE	-
DMS_14749	20809	N	N	N	1	CUSTOMER ISSUE	-
DMS_14750	20810	N	N	N	1	CUSTOMER ISSUE	-
DMS_14751	20811	N	N	N	1	CUSTOMER ISSUE	-
DMS_14752	20812	N	N	N	1	CUSTOMER ISSUE	-
DMS_14753	20813	N	N	N	1	CUSTOMER ISSUE	-
DMS_14754	20814	N	N	N	1	CUSTOMER ISSUE	-
DMS_14755	20815	N	N	N	1	CUSTOMER ISSUE	-
DMS_14756	20816	N	N	N	1	CUSTOMER ISSUE	-
DMS_14757	20817	N	N	N	1	CUSTOMER ISSUE	-
DMS_14758	20818	N	N	N	1	CUSTOMER ISSUE	-
DMS_14759	20819	N	N	N	1	CUSTOMER ISSUE	-
DMS_14760	20820	N	N	N	1	CUSTOMER ISSUE	-
DMS_14761	20821	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14763	20822	N	N	N	1	CUSTOMER ISSUE	-
DMS_14764	20823	N	N	N	1	CUSTOMER ISSUE	-
DMS_14765	20824	N	N	N	1	CUSTOMER ISSUE	-
DMS_14766	20825	N	N	N	1	CUSTOMER ISSUE	-
DMS_14767	20826	N	N	N	1	CUSTOMER ISSUE	-
DMS_14768	20827	N	N	N	1	CUSTOMER ISSUE	-
DMS_14769	20828	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14770	20829	N	N	N	1	CUSTOMER ISSUE	-
DMS_14771	20830	N	N	N	1	CUSTOMER ISSUE	-
DMS_14772	20831	N	N	N	1	CUSTOMER ISSUE	-
DMS_14773	20832	N	N	N	1	CUSTOMER ISSUE	-
DMS_14774	20833	N	N	N	1	CUSTOMER ISSUE	-
DMS_14775	20834	N	N	N	1	CUSTOMER ISSUE	-
DMS_14776	20835	N	N	N	1	CUSTOMER ISSUE	-
DMS_14777	20836	N	N	N	1	CUSTOMER ISSUE	-
DMS_14778	20837	N	N	N	1	CUSTOMER ISSUE	-
DMS_14779	20838	N	N	N	1	CUSTOMER ISSUE	-
DMS_14780	20839	N	N	N	1	CUSTOMER ISSUE	-
DMS_14781	20840	N	N	N	1	CUSTOMER ISSUE	-
DMS_14782	20841	N	N	N	1	CUSTOMER ISSUE	-
DMS_14783	20842	N	N	N	1	CUSTOMER ISSUE	-
DMS_14784	20843	N	N	N	1	CUSTOMER ISSUE	-
DMS_14785	20844	N	N	N	1	CUSTOMER ISSUE	-
DMS_14786	20845	N	N	N	1	CUSTOMER ISSUE	-
DMS_14787	20846	N	N	N	1	CUSTOMER ISSUE	-
DMS_14788	20847	N	N	N	1	CUSTOMER ISSUE	-
DMS_14789	20848	N	N	N	1	CUSTOMER ISSUE	-
DMS_14790	20849	N	N	N	1	CUSTOMER ISSUE	-
DMS_14791	20850	N	N	N	1	CUSTOMER ISSUE	-
DMS_14793	20851	N	N	N	1	CUSTOMER ISSUE	-
DMS_14794	20852	N	N	N	1	CUSTOMER ISSUE	-
DMS_14795	20853	N	N	N	1	CUSTOMER ISSUE	-
DMS_14796	20854	N	N	N	1	CUSTOMER ISSUE	-
DMS_14797	20855	N	N	N	1	CUSTOMER ISSUE	-
DMS_14798	20856	N	N	N	1	CUSTOMER ISSUE	-

DMS_14799	20857	N	N	N	1	CUSTOMER ISSUE	-
DMS_14800	20858	N	N	N	1	CUSTOMER ISSUE	-
DMS_14801	20859	N	N	N	1	CUSTOMER ISSUE	-
DMS_14802	20860	N	N	N	1	CUSTOMER ISSUE	-
DMS_14803	20861	N	N	N	1	CUSTOMER ISSUE	-
DMS_14804	20862	N	N	N	1	CUSTOMER ISSUE	-
DMS_14805	20863	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14806	20864	N	N	N	1	CUSTOMER ISSUE	-
DMS_14807	20865	N	N	N	1	CUSTOMER ISSUE	-
DMS_14808	20866	N	N	N	1	CUSTOMER ISSUE	-
DMS_14809	20867	N	N	N	1	CUSTOMER ISSUE	-
DMS_14810	20868	N	N	N	1	CUSTOMER ISSUE	-
DMS_14811	20869	N	N	N	1	CUSTOMER ISSUE	-
DMS_14812	20870	N	N	N	1	CUSTOMER ISSUE	-
DMS_14813	20871	N	N	N	1	CUSTOMER ISSUE	-
DMS_14814	20872	N	N	N	1	CUSTOMER ISSUE	-
DMS_14815	20873	N	N	N	1	CUSTOMER ISSUE	-
DMS_14816	20874	N	N	N	1	CUSTOMER ISSUE	-
DMS_14817	20875	N	N	N	1	CUSTOMER ISSUE	-
DMS_14818	20876	N	N	N	1	CUSTOMER ISSUE	-
DMS_14819	20877	N	N	N	1	CUSTOMER ISSUE	-
DMS_14821	20878	N	N	N	1	CUSTOMER ISSUE	-
DMS_14822	20879	N	N	N	1	CUSTOMER ISSUE	-
DMS_14823	20880	N	N	N	1	CUSTOMER ISSUE	-
DMS_14824	20881	N	N	N	1	CUSTOMER ISSUE	-
DMS_14825	20882	N	N	N	1	CUSTOMER ISSUE	-
DMS_14826	20883	N	N	N	1	CUSTOMER ISSUE	-
DMS_14827	20884	N	N	N	1	CUSTOMER ISSUE	-
DMS_14828	20885	N	N	N	1	CUSTOMER ISSUE	-
DMS_14829	20886	N	N	N	1	CUSTOMER ISSUE	-
DMS_14830	20887	N	N	N	1	CUSTOMER ISSUE	-
DMS_14832	20888	N	N	N	1	CUSTOMER ISSUE	-
DMS_14834	20889	N	N	N	1	CUSTOMER ISSUE	-
DMS_14835	20890	N	N	N	1	CUSTOMER ISSUE	-
DMS_14836	20891	N	N	N	1	CUSTOMER ISSUE	-
DMS_14837	20892	N	N	N	1	CUSTOMER ISSUE	-
DMS_14838	20893	N	N	N	1	CUSTOMER ISSUE	-
DMS_14839	20894	N	N	N	1	CUSTOMER ISSUE	-
DMS_14840	20895	N	N	N	1	CUSTOMER ISSUE	-
DMS_14841	20896	N	N	N	1	CUSTOMER ISSUE	-
DMS_14843	20897	N	N	N	1	CUSTOMER ISSUE	-
DMS_14844	20898	N	N	N	1	CUSTOMER ISSUE	-
DMS_14845	20899	N	N	N	1	CUSTOMER ISSUE	-
DMS_14846	20900	N	N	N	1	CUSTOMER ISSUE	-
DMS_14847	20901	N	N	N	1	CUSTOMER ISSUE	-
DMS_14849	20902	N	N	N	1	CUSTOMER ISSUE	-
DMS_14850	20903	N	N	N	1	CUSTOMER ISSUE	-
DMS_14851	20904	N	N	N	1	CUSTOMER ISSUE	-
DMS_14852	20905	N	N	N	1	CUSTOMER ISSUE	-
DMS_14853	20906	N	N	N	1	CUSTOMER ISSUE	-
DMS_14854	20907	N	N	N	1	CUSTOMER ISSUE	-
DMS_14855	20908	N	N	N	1	CUSTOMER ISSUE	-
DMS_14856	20909	N	N	N	1	CUSTOMER ISSUE	-
DMS_14857	20910	N	N	N	1	CUSTOMER ISSUE	-
DMS_14858	20911	N	N	N	1	CUSTOMER ISSUE	-
DMS_14859	20912	N	N	N	1	CUSTOMER ISSUE	-
DMS_14860	20913	N	N	N	1	CUSTOMER ISSUE	-
DMS_14861	20914	N	N	N	1	CUSTOMER ISSUE	-
DMS_14862	20915	N	N	N	1	CUSTOMER ISSUE	-
DMS_14863	20916	N	N	N	1	CUSTOMER ISSUE	-
DMS_14864	20917	N	N	N	1	CUSTOMER ISSUE	-
DMS_14865	20918	N	N	N	1	CUSTOMER ISSUE	-
DMS_14866	20919	N	N	N	1	CUSTOMER ISSUE	-
DMS_14867	20920	N	N	N	1	CUSTOMER ISSUE	-
DMS_14868	20921	N	N	N	1	CUSTOMER ISSUE	-
DMS_14870	20922	N	N	N	1	CUSTOMER ISSUE	-
DMS_14871	20923	N	N	N	1	CUSTOMER ISSUE	-
DMS_14872	20924	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14873	20925	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14874	20926	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14875	20927	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14876	20928	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14877	20929	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14878	20930	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14879	20931	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_14880	20932	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14881	20933	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14882	20934	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14883	20935	N	N	N	1	CUSTOMER ISSUE	-
DMS_14884	20936	N	N	N	1	CUSTOMER ISSUE	-

DMS_14885	20937	N	N	N	1	CUSTOMER ISSUE	-
DMS_14886	20938	N	N	N	1	CUSTOMER ISSUE	-
DMS_14887	20939	N	N	N	1	CUSTOMER ISSUE	-
DMS_14888	20940	N	N	N	1	CUSTOMER ISSUE	-
DMS_14889	20941	N	N	N	1	CUSTOMER ISSUE	-
DMS_14890	20942	N	N	N	1	CUSTOMER ISSUE	-
DMS_14891	20943	N	N	N	1	CUSTOMER ISSUE	-
DMS_14892	20944	N	N	N	1	CUSTOMER ISSUE	-
DMS_14893	20945	N	N	N	1	CUSTOMER ISSUE	-
DMS_14894	20946	N	N	N	1	CUSTOMER ISSUE	-
DMS_14895	20947	N	N	N	1	CUSTOMER ISSUE	-
DMS_14896	20948	N	N	N	1	CUSTOMER ISSUE	-
DMS_14897	20949	N	N	N	1	CUSTOMER ISSUE	-
DMS_14898	20950	N	N	N	1	CUSTOMER ISSUE	-
DMS_14899	20951	N	N	N	1	CUSTOMER ISSUE	-
DMS_14900	20952	N	N	N	1	CUSTOMER ISSUE	-
DMS_14901	20953	N	N	N	1	CUSTOMER ISSUE	-
DMS_14902	20954	N	N	N	1	CUSTOMER ISSUE	-
DMS_14903	20955	N	N	N	1	CUSTOMER ISSUE	-
DMS_14904	20956	N	N	N	1	CUSTOMER ISSUE	-
DMS_14905	20957	N	N	N	1	CUSTOMER ISSUE	-
DMS_14906	20958	N	N	N	1	CUSTOMER ISSUE	-
DMS_14907	20959	N	N	N	1	CUSTOMER ISSUE	-
DMS_14908	20960	N	N	N	1	CUSTOMER ISSUE	-
DMS_14909	20961	N	N	N	1	CUSTOMER ISSUE	-
DMS_14910	20962	N	N	N	1	CUSTOMER ISSUE	-
DMS_14911	20963	N	N	N	1	CUSTOMER ISSUE	-
DMS_14912	20964	N	N	N	1	CUSTOMER ISSUE	-
DMS_14913	20965	N	N	N	1	CUSTOMER ISSUE	-
DMS_14914	20966	N	N	N	1	CUSTOMER ISSUE	-
DMS_14915	20967	N	N	N	1	CUSTOMER ISSUE	-
DMS_14916	20968	N	N	N	1	CUSTOMER ISSUE	-
DMS_14917	20969	N	N	N	1	CUSTOMER ISSUE	-
DMS_14918	20970	N	N	N	1	CUSTOMER ISSUE	-
DMS_14919	20971	N	N	N	1	CUSTOMER ISSUE	-
DMS_14920	20972	N	N	N	1	CUSTOMER ISSUE	-
DMS_14921	20973	N	N	N	1	CUSTOMER ISSUE	-
DMS_14922	20974	N	N	N	1	CUSTOMER ISSUE	-
DMS_14923	20975	N	N	N	1	CUSTOMER ISSUE	-
DMS_14924	20976	N	N	N	1	CUSTOMER ISSUE	-
DMS_14925	20977	N	N	N	1	CUSTOMER ISSUE	-
DMS_14926	20978	N	N	N	1	CUSTOMER ISSUE	-
DMS_14927	20979	N	N	N	1	CUSTOMER ISSUE	-
DMS_14928	20980	N	N	N	1	CUSTOMER ISSUE	-
DMS_14929	20981	N	N	N	1	CUSTOMER ISSUE	-
DMS_14930	20982	N	N	N	1	CUSTOMER ISSUE	-
DMS_14931	20983	N	N	N	1	CUSTOMER ISSUE	-
DMS_14932	20984	N	N	N	1	CUSTOMER ISSUE	-
DMS_14933	20985	N	N	N	1	CUSTOMER ISSUE	-
DMS_14934	20986	N	N	N	1	CUSTOMER ISSUE	-
DMS_14935	20987	N	N	N	1	CUSTOMER ISSUE	-
DMS_14936	20988	N	N	N	1	CUSTOMER ISSUE	-
DMS_14937	20989	N	N	N	1	CUSTOMER ISSUE	-
DMS_14938	20990	N	N	N	1	CUSTOMER ISSUE	-
DMS_14939	20991	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14940	20992	N	N	N	1	CUSTOMER ISSUE	-
DMS_14941	20993	N	N	N	1	CUSTOMER ISSUE	-
DMS_14942	20994	N	N	N	1	CUSTOMER ISSUE	-
DMS_14943	20995	N	N	N	1	CUSTOMER ISSUE	-
DMS_14944	20996	N	N	N	1	CUSTOMER ISSUE	-
DMS_14946	20997	N	N	N	1	CUSTOMER ISSUE	-
DMS_14947	20998	N	N	N	1	CUSTOMER ISSUE	-
DMS_14948	20999	N	N	N	1	CUSTOMER ISSUE	-
DMS_14949	21000	N	N	N	1	CUSTOMER ISSUE	-
DMS_14950	21001	N	N	N	1	CUSTOMER ISSUE	-
DMS_14951	21002	N	N	N	1	CUSTOMER ISSUE	-
DMS_14952	21003	N	N	N	1	CUSTOMER ISSUE	-
DMS_14953	21004	N	N	N	1	CUSTOMER ISSUE	-
DMS_14954	21005	N	N	N	1	CUSTOMER ISSUE	-
DMS_14955	21006	N	N	N	1	CUSTOMER ISSUE	-
DMS_14956	21007	N	N	N	1	CUSTOMER ISSUE	-
DMS_14957	21008	N	N	N	1	CUSTOMER ISSUE	-
DMS_14958	21009	N	N	N	1	CUSTOMER ISSUE	-
DMS_14959	21010	N	N	N	1	CUSTOMER ISSUE	-
DMS_14960	21011	N	N	N	1	CUSTOMER ISSUE	-
DMS_14961	21012	N	N	N	1	CUSTOMER ISSUE	-
DMS_14962	21013	N	N	N	1	CUSTOMER ISSUE	-
DMS_14963	21014	N	N	N	1	CUSTOMER ISSUE	-
DMS_14965	21015	N	N	N	1	CUSTOMER ISSUE	-
DMS_14966	21016	N	N	N	1	CUSTOMER ISSUE	-

DMS_14967	21017	N	N	N	1	CUSTOMER ISSUE	-
DMS_14968	21018	N	N	N	1	CUSTOMER ISSUE	-
DMS_14969	21019	N	N	N	1	CUSTOMER ISSUE	-
DMS_14970	21020	N	N	N	1	CUSTOMER ISSUE	-
DMS_14971	21021	N	N	N	1	CUSTOMER ISSUE	-
DMS_14972	21022	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_14973	21023	N	N	N	1	CUSTOMER ISSUE	-
DMS_14974	21024	N	N	N	1	CUSTOMER ISSUE	-
DMS_14975	21025	N	N	N	1	CUSTOMER ISSUE	-
DMS_14977	21026	N	N	N	1	CUSTOMER ISSUE	-
DMS_14978	21027	N	N	N	1	CUSTOMER ISSUE	-
DMS_14979	21028	N	N	N	1	CUSTOMER ISSUE	-
DMS_14980	21029	N	N	N	1	CUSTOMER ISSUE	-
DMS_14981	21030	N	N	N	1	CUSTOMER ISSUE	-
DMS_14982	21031	N	N	N	1	CUSTOMER ISSUE	-
DMS_14984	21032	N	N	N	1	CUSTOMER ISSUE	-
DMS_14985	21033	N	N	N	1	CUSTOMER ISSUE	-
DMS_14986	21034	N	N	N	1	CUSTOMER ISSUE	-
DMS_14987	21035	N	N	N	1	CUSTOMER ISSUE	-
DMS_14988	21036	N	N	N	1	CUSTOMER ISSUE	-
DMS_14989	21037	N	N	N	1	CUSTOMER ISSUE	-
DMS_14990	21038	N	N	N	1	CUSTOMER ISSUE	-
DMS_14991	21039	N	N	N	1	CUSTOMER ISSUE	-
DMS_14992	21040	N	N	N	1	CUSTOMER ISSUE	-
DMS_14993	21041	N	N	N	1	CUSTOMER ISSUE	-
DMS_14994	21042	N	N	N	1	CUSTOMER ISSUE	-
DMS_14995	21043	N	N	N	1	CUSTOMER ISSUE	-
DMS_14996	21044	N	N	N	1	CUSTOMER ISSUE	-
DMS_14997	21045	N	N	N	1	CUSTOMER ISSUE	-
DMS_14998	21046	N	N	N	1	CUSTOMER ISSUE	-
DMS_14999	21047	N	N	N	2	CUSTOMER ISSUE	-
DMS_15000	21048	N	N	N	1	CUSTOMER ISSUE	-
DMS_15001	21049	N	N	N	1	CUSTOMER ISSUE	-
DMS_15002	21050	N	N	N	1	CUSTOMER ISSUE	-
DMS_15003	21051	N	N	N	1	CUSTOMER ISSUE	-
DMS_15004	21052	N	N	N	1	CUSTOMER ISSUE	-
DMS_15005	21053	N	N	N	1	CUSTOMER ISSUE	-
DMS_15006	21054	N	N	N	1	CUSTOMER ISSUE	-
DMS_15007	21055	N	N	N	1	CUSTOMER ISSUE	-
DMS_15008	21056	N	N	N	1	CUSTOMER ISSUE	-
DMS_15009	21057	N	N	N	1	CUSTOMER ISSUE	-
DMS_15010	21058	N	N	N	1	CUSTOMER ISSUE	-
DMS_15011	21059	N	N	N	1	CUSTOMER ISSUE	-
DMS_15012	21060	N	N	N	1	CUSTOMER ISSUE	-
DMS_15013	21061	N	N	N	1	CUSTOMER ISSUE	-
DMS_15014	21062	N	N	N	1	CUSTOMER ISSUE	-
DMS_15015	21063	N	N	N	1	CUSTOMER ISSUE	-
DMS_15016	21064	N	N	N	1	CUSTOMER ISSUE	-
DMS_15017	21065	N	N	N	1	CUSTOMER ISSUE	-
DMS_15018	21066	N	N	N	1	CUSTOMER ISSUE	-
DMS_15019	21067	N	N	N	1	CUSTOMER ISSUE	-
DMS_15020	21068	N	N	N	1	CUSTOMER ISSUE	-
DMS_15021	21069	N	N	N	1	CUSTOMER ISSUE	-
DMS_15022	21070	N	N	N	1	CUSTOMER ISSUE	-
DMS_15023	21071	N	N	N	1	CUSTOMER ISSUE	-
DMS_15024	21072	N	N	N	1	CUSTOMER ISSUE	-
DMS_15025	21073	N	N	N	1	CUSTOMER ISSUE	-
DMS_15026	21074	N	N	N	1	CUSTOMER ISSUE	-
DMS_15027	21075	N	N	N	1	CUSTOMER ISSUE	-
DMS_15028	21076	N	N	N	1	CUSTOMER ISSUE	-
DMS_15029	21077	N	N	N	1	CUSTOMER ISSUE	-
DMS_15030	21078	N	N	N	1	CUSTOMER ISSUE	-
DMS_15031	21079	N	N	N	1	CUSTOMER ISSUE	-
DMS_15032	21080	N	N	N	1	CUSTOMER ISSUE	-
DMS_15033	21081	N	N	N	1	CUSTOMER ISSUE	-
DMS_15034	21082	N	N	N	1	CUSTOMER ISSUE	-
DMS_15035	21083	N	N	N	1	CUSTOMER ISSUE	-
DMS_15036	21084	N	N	N	1	CUSTOMER ISSUE	-
DMS_15037	21085	N	N	N	1	CUSTOMER ISSUE	-
DMS_15038	21086	N	N	N	1	CUSTOMER ISSUE	-
DMS_15039	21087	N	N	N	1	CUSTOMER ISSUE	-
DMS_15040	21088	N	N	N	1	CUSTOMER ISSUE	-
DMS_15041	21089	N	N	N	1	CUSTOMER ISSUE	-
DMS_15042	21090	N	N	N	1	CUSTOMER ISSUE	-
DMS_15043	21091	N	N	N	1	CUSTOMER ISSUE	-
DMS_15044	21092	N	N	N	1	CUSTOMER ISSUE	-
DMS_15045	21093	N	N	N	1	CUSTOMER ISSUE	-
DMS_15046	21094	N	N	N	1	CUSTOMER ISSUE	-
DMS_15047	21095	N	N	N	1	CUSTOMER ISSUE	-
DMS_15048	21096	N	N	N	1	CUSTOMER ISSUE	-

DMS_15049	21097	N	N	N	1	CUSTOMER ISSUE	-
DMS_15050	21098	N	N	N	1	CUSTOMER ISSUE	-
DMS_15051	21099	N	N	N	1	CUSTOMER ISSUE	-
DMS_15052	21100	N	N	N	1	CUSTOMER ISSUE	-
DMS_15053	21101	N	N	N	1	CUSTOMER ISSUE	-
DMS_15054	21102	N	N	N	1	CUSTOMER ISSUE	-
DMS_15055	21103	N	N	N	1	CUSTOMER ISSUE	-
DMS_15056	21104	N	N	N	2	CUSTOMER ISSUE	-
DMS_15057	21105	N	N	N	1	CUSTOMER ISSUE	-
DMS_15058	21106	N	N	N	1	CUSTOMER ISSUE	-
DMS_15059	21107	N	N	N	1	CUSTOMER ISSUE	-
DMS_15060	21108	N	N	N	1	CUSTOMER ISSUE	-
DMS_15061	21109	N	N	N	1	CUSTOMER ISSUE	-
DMS_15062	21110	N	N	N	1	CUSTOMER ISSUE	-
DMS_15063	21111	N	N	N	1	CUSTOMER ISSUE	-
DMS_15064	21112	N	N	N	1	CUSTOMER ISSUE	-
DMS_15065	21113	N	N	N	1	CUSTOMER ISSUE	-
DMS_15066	21114	N	N	N	1	CUSTOMER ISSUE	-
DMS_15067	21115	N	N	N	1	CUSTOMER ISSUE	-
DMS_15068	21116	N	N	N	1	CUSTOMER ISSUE	-
DMS_15069	21117	N	N	N	1	CUSTOMER ISSUE	-
DMS_15070	21118	N	N	N	1	CUSTOMER ISSUE	-
DMS_15071	21119	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_15072	21120	N	N	N	1	CUSTOMER ISSUE	-
DMS_15073	21121	N	N	N	1	CUSTOMER ISSUE	-
DMS_15074	21122	N	N	N	1	CUSTOMER ISSUE	-
DMS_15075	21123	N	N	N	1	CUSTOMER ISSUE	-
DMS_15076	21124	N	N	N	1	CUSTOMER ISSUE	-
DMS_15077	21125	N	N	N	1	CUSTOMER ISSUE	-
DMS_15078	21126	N	N	N	1	CUSTOMER ISSUE	-
DMS_15080	21127	N	N	N	1	CUSTOMER ISSUE	-
DMS_15081	21128	N	N	N	1	CUSTOMER ISSUE	-
DMS_15082	21129	N	N	N	1	CUSTOMER ISSUE	-
DMS_15083	21130	N	N	N	1	CUSTOMER ISSUE	-
DMS_15084	21131	N	N	N	1	CUSTOMER ISSUE	-
DMS_15085	21132	N	N	N	1	CUSTOMER ISSUE	-
DMS_15086	21133	N	N	N	1	CUSTOMER ISSUE	-
DMS_15087	21134	N	N	N	1	CUSTOMER ISSUE	-
DMS_15088	21135	N	N	N	1	CUSTOMER ISSUE	-
DMS_15089	21136	N	N	N	1	CUSTOMER ISSUE	-
DMS_15090	21137	N	N	N	1	CUSTOMER ISSUE	-
DMS_15091	21138	N	N	N	1	CUSTOMER ISSUE	-
DMS_15092	21139	N	N	N	1	CUSTOMER ISSUE	-
DMS_15093	21140	N	N	N	1	CUSTOMER ISSUE	-
DMS_15094	21141	N	N	N	1	CUSTOMER ISSUE	-
DMS_15095	21142	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_15096	21143	N	N	N	1	CUSTOMER ISSUE	-
DMS_15097	21144	N	N	N	1	CUSTOMER ISSUE	-
DMS_15098	21145	N	N	N	1	CUSTOMER ISSUE	-
DMS_15099	21146	N	N	N	1	CUSTOMER ISSUE	-
DMS_15100	21147	N	N	N	1	CUSTOMER ISSUE	-
DMS_15101	21148	N	N	N	1	CUSTOMER ISSUE	-
DMS_15102	21149	N	N	N	1	CUSTOMER ISSUE	-
DMS_15103	21150	N	N	N	1	CUSTOMER ISSUE	-
DMS_15104	21151	N	N	N	1	CUSTOMER ISSUE	-
DMS_15105	21152	N	N	N	1	CUSTOMER ISSUE	-
DMS_15106	21153	N	N	N	1	CUSTOMER ISSUE	-
DMS_15107	21154	N	N	N	1	CUSTOMER ISSUE	-
DMS_15108	21155	N	N	N	1	CUSTOMER ISSUE	-
DMS_15109	21156	N	N	N	1	CUSTOMER ISSUE	-
DMS_15110	21157	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_15111	21158	N	N	N	1	CUSTOMER ISSUE	-
DMS_15112	21159	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_15113	21160	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_15114	21161	N	N	N	1	CUSTOMER ISSUE	-
DMS_15115	21162	N	N	N	1	CUSTOMER ISSUE	-
DMS_15116	21163	N	N	N	1	CUSTOMER ISSUE	-
DMS_15117	21164	N	N	N	1	CUSTOMER ISSUE	-
DMS_15118	21165	N	N	N	1	CUSTOMER ISSUE	-
DMS_15119	21166	N	N	N	1	CUSTOMER ISSUE	-
DMS_15120	21167	N	N	N	1	CUSTOMER ISSUE	-
DMS_15121	21168	N	N	N	1	CUSTOMER ISSUE	-
DMS_15122	21169	N	N	N	1	CUSTOMER ISSUE	-
DMS_15123	21170	N	N	N	1	CUSTOMER ISSUE	-
DMS_15124	21171	N	N	N	1	CUSTOMER ISSUE	-
DMS_15125	21172	N	N	N	1	CUSTOMER ISSUE	-
DMS_15126	21173	N	N	N	1	CUSTOMER ISSUE	-
DMS_15127	21174	N	N	N	1	CUSTOMER ISSUE	-
DMS_15128	21175	N	N	N	1	CUSTOMER ISSUE	-
DMS_15129	21176	N	N	N	1	CUSTOMER ISSUE	-

DMS_15131	21177	N	N	N	1	CUSTOMER ISSUE	-
DMS_15132	21178	N	N	N	1	CUSTOMER ISSUE	-
DMS_15133	21179	N	N	N	1	CUSTOMER ISSUE	-
DMS_15134	21180	N	N	N	1	CUSTOMER ISSUE	-
DMS_15135	21181	N	N	N	1	CUSTOMER ISSUE	-
DMS_15136	21182	N	N	N	1	CUSTOMER ISSUE	-
DMS_15137	21183	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_15138	21184	N	N	N	1	CUSTOMER ISSUE	-
DMS_15139	21185	N	N	N	1	CUSTOMER ISSUE	-
DMS_15140	21186	N	N	N	1	CUSTOMER ISSUE	-
DMS_15141	21187	N	N	N	1	CUSTOMER ISSUE	-
DMS_15142	21188	N	N	N	1	CUSTOMER ISSUE	-
DMS_15143	21189	N	N	N	1	CUSTOMER ISSUE	-
DMS_15144	21190	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_15145	21191	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_15146	21192	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_15147	21193	N	N	N	1	CUSTOMER ISSUE	-
DMS_15148	21194	N	N	N	1	CUSTOMER ISSUE	-
DMS_15149	21195	N	N	N	1	CUSTOMER ISSUE	-
DMS_15150	21196	N	N	N	1	CUSTOMER ISSUE	-
DMS_15151	21197	N	N	N	1	CUSTOMER ISSUE	-
DMS_15152	21198	N	N	N	1	CUSTOMER ISSUE	-
DMS_15153	21199	N	N	N	1	CUSTOMER ISSUE	-
DMS_15154	21200	N	N	N	4	CUSTOMER ISSUE	-
DMS_15155	21201	N	N	N	1	CUSTOMER ISSUE	-
DMS_15156	21202	N	N	N	1	CUSTOMER ISSUE	-
DMS_15157	21203	N	N	N	1	CUSTOMER ISSUE	-
DMS_15158	21204	N	N	N	1	CUSTOMER ISSUE	-
DMS_15159	21205	N	N	N	1	CUSTOMER ISSUE	-
DMS_15160	21206	N	N	N	1	CUSTOMER ISSUE	-
DMS_15161	21207	N	N	N	1	CUSTOMER ISSUE	-
DMS_15162	21208	N	N	N	1	CUSTOMER ISSUE	-
DMS_15163	21209	N	N	N	1	CUSTOMER ISSUE	-
DMS_15164	21210	N	N	N	1	CUSTOMER ISSUE	-
DMS_15165	21211	N	N	N	1	CUSTOMER ISSUE	-
DMS_15166	21212	N	N	N	1	CUSTOMER ISSUE	-
DMS_15167	21213	N	N	N	1	CUSTOMER ISSUE	-
DMS_15168	21214	N	N	N	1	CUSTOMER ISSUE	-
DMS_15169	21215	N	N	N	1	CUSTOMER ISSUE	-
DMS_15170	21216	N	N	N	1	CUSTOMER ISSUE	-
DMS_15171	21217	N	N	N	1	CUSTOMER ISSUE	-
DMS_15172	21218	N	N	N	1	CUSTOMER ISSUE	-
DMS_15173	21219	N	N	N	1	CUSTOMER ISSUE	-
DMS_15174	21220	N	N	N	1	CUSTOMER ISSUE	-
DMS_15175	21221	N	N	N	1	CUSTOMER ISSUE	-
DMS_15176	21222	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_15177	21223	N	N	N	1	CUSTOMER ISSUE	-
DMS_15178	21224	N	N	N	1	CUSTOMER ISSUE	-
DMS_15179	21225	N	N	N	1	CUSTOMER ISSUE	-
DMS_15180	21226	N	N	N	1	CUSTOMER ISSUE	-
DMS_15181	21227	N	N	N	1	CUSTOMER ISSUE	-
DMS_15182	21228	N	N	N	1	CUSTOMER ISSUE	-
DMS_15183	21229	N	N	N	1	CUSTOMER ISSUE	-
DMS_15184	21230	N	N	N	1	CUSTOMER ISSUE	-
DMS_15185	21231	N	N	N	1	CUSTOMER ISSUE	-
DMS_15186	21232	N	N	N	1	CUSTOMER ISSUE	-
DMS_15187	21233	N	N	N	1	CUSTOMER ISSUE	-
DMS_15188	21234	N	N	N	1	CUSTOMER ISSUE	-
DMS_15189	21235	N	N	N	1	CUSTOMER ISSUE	-
DMS_15190	21236	N	N	N	1	CUSTOMER ISSUE	-
DMS_15191	21237	N	N	N	1	CUSTOMER ISSUE	-
DMS_15192	21238	N	N	N	1	CUSTOMER ISSUE	-
DMS_15193	21239	N	N	N	1	CUSTOMER ISSUE	-
DMS_15194	21240	N	N	N	1	CUSTOMER ISSUE	-
DMS_15195	21241	N	N	N	1	CUSTOMER ISSUE	-
DMS_15196	21242	N	N	N	1	CUSTOMER ISSUE	-
DMS_15197	21243	N	N	N	1	CUSTOMER ISSUE	-
DMS_15198	21244	N	N	N	1	CUSTOMER ISSUE	-
DMS_15199	21245	N	N	N	1	CUSTOMER ISSUE	-
DMS_15200	21246	N	N	N	1	CUSTOMER ISSUE	-
DMS_15201	21247	N	N	N	1	CUSTOMER ISSUE	-
DMS_15202	21248	N	N	N	1	CUSTOMER ISSUE	-
DMS_15203	21249	N	N	N	1	CUSTOMER ISSUE	-
DMS_15204	21250	N	N	N	1	CUSTOMER ISSUE	-
DMS_15205	21251	N	N	N	1	CUSTOMER ISSUE	-
DMS_15206	21252	N	N	N	1	CUSTOMER ISSUE	-
DMS_15208	21253	N	N	N	1	CUSTOMER ISSUE	-
DMS_15209	21254	N	N	N	1	CUSTOMER ISSUE	-
DMS_15210	21255	N	N	N	1	CUSTOMER ISSUE	-
DMS_15211	21256	N	N	N	1	CUSTOMER ISSUE	-

DMS_15212	21257	N	N	N	1	CUSTOMER ISSUE	-
DMS_15213	21258	N	N	N	1	CUSTOMER ISSUE	-
DMS_15214	21259	N	N	N	1	CUSTOMER ISSUE	-
DMS_15215	21260	N	N	N	1	CUSTOMER ISSUE	-
DMS_15216	21261	N	N	N	1	CUSTOMER ISSUE	-
DMS_15217	21262	N	N	N	1	CUSTOMER ISSUE	-
DMS_15218	21263	N	N	N	1	CUSTOMER ISSUE	-
DMS_15219	21264	N	N	N	1	CUSTOMER ISSUE	-
DMS_15220	21265	N	N	N	1	CUSTOMER ISSUE	-
DMS_15221	21266	N	N	N	1	CUSTOMER ISSUE	-
DMS_15222	21267	N	N	N	1	CUSTOMER ISSUE	-
DMS_15223	21268	N	N	N	1	CUSTOMER ISSUE	-
DMS_15224	21269	N	N	N	1	CUSTOMER ISSUE	-
DMS_15225	21270	N	N	N	1	CUSTOMER ISSUE	-
DMS_15226	21271	N	N	N	1	CUSTOMER ISSUE	-
DMS_15227	21272	N	N	N	1	CUSTOMER ISSUE	-
DMS_15228	21273	N	N	N	1	CUSTOMER ISSUE	-
DMS_15229	21274	N	N	N	1	CUSTOMER ISSUE	-
DMS_15230	21275	N	N	N	1	CUSTOMER ISSUE	-
DMS_15231	21276	N	N	N	1	CUSTOMER ISSUE	-
DMS_15232	21277	N	N	N	1	CUSTOMER ISSUE	-
DMS_15233	21278	N	N	N	1	CUSTOMER ISSUE	-
DMS_15234	21279	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_15235	21280	N	N	N	1	CUSTOMER ISSUE	-
DMS_15236	21281	N	N	N	1	CUSTOMER ISSUE	-
DMS_15238	21282	N	N	N	1	CUSTOMER ISSUE	-
DMS_15239	21283	N	N	N	1	CUSTOMER ISSUE	-
DMS_15240	21284	N	N	N	1	CUSTOMER ISSUE	-
DMS_15241	21285	N	N	N	1	CUSTOMER ISSUE	-
DMS_15242	21286	N	N	N	1	CUSTOMER ISSUE	-
DMS_15243	21287	N	N	N	1	CUSTOMER ISSUE	-
DMS_15244	21288	N	N	N	1	CUSTOMER ISSUE	-
DMS_15245	21289	N	N	N	1	CUSTOMER ISSUE	-
DMS_15246	21290	N	N	N	1	CUSTOMER ISSUE	-
DMS_15247	21291	N	N	N	1	CUSTOMER ISSUE	-
DMS_15248	21292	N	N	N	1	CUSTOMER ISSUE	-
DMS_15249	21293	N	N	N	1	CUSTOMER ISSUE	-
DMS_15250	21294	N	N	N	1	CUSTOMER ISSUE	-
DMS_15251	21295	N	N	N	1	CUSTOMER ISSUE	-
DMS_15252	21296	N	N	N	1	CUSTOMER ISSUE	-
DMS_15253	21297	N	N	N	1	CUSTOMER ISSUE	-
DMS_15254	21298	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_15255	21299	N	N	N	1	CUSTOMER ISSUE	-
DMS_15256	21300	N	N	N	1	CUSTOMER ISSUE	-
DMS_15257	21301	N	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
DMS_15258	21302	N	N	N	1	CUSTOMER ISSUE	-
DMS_15260	21303	N	N	N	1	CUSTOMER ISSUE	-
DMS_15261	21304	N	N	N	1	CUSTOMER ISSUE	-
DMS_15263	21305	N	N	N	1	CUSTOMER ISSUE	-
DMS_15264	21306	N	N	N	1	CUSTOMER ISSUE	-
DMS_15265	21307	N	N	N	1	CUSTOMER ISSUE	-
DMS_15266	21308	N	N	N	1	CUSTOMER ISSUE	-
DMS_15267	21309	N	N	N	1	CUSTOMER ISSUE	-
DMS_15268	21310	N	N	N	1	CUSTOMER ISSUE	-
DMS_15269	21311	N	N	N	1	CUSTOMER ISSUE	-
DMS_15270	21312	N	N	N	1	CUSTOMER ISSUE	-
DMS_15271	21313	N	N	N	1	CUSTOMER ISSUE	-
DMS_15272	21314	N	N	N	1	CUSTOMER ISSUE	-
DMS_15273	21315	N	N	N	1	CUSTOMER ISSUE	-
DMS_15274	21316	N	N	N	1	CUSTOMER ISSUE	-
DMS_15275	21317	N	N	N	1	CUSTOMER ISSUE	-
DMS_15276	21318	N	N	N	1	CUSTOMER ISSUE	-
DMS_15277	21319	N	N	N	1	CUSTOMER ISSUE	-
DMS_15278	21320	N	N	N	1	CUSTOMER ISSUE	-
DMS_15279	21321	N	N	N	1	CUSTOMER ISSUE	-
DMS_15280	21322	N	N	N	1	CUSTOMER ISSUE	-
DMS_15281	21323	N	N	N	1	CUSTOMER ISSUE	-
DMS_15282	21324	N	N	N	1	CUSTOMER ISSUE	-
DMS_15283	21325	N	N	N	2	CUSTOMER ISSUE	-
DMS_15284	21326	N	N	N	1	CUSTOMER ISSUE	-
DMS_15285	21327	N	N	N	1	CUSTOMER ISSUE	-
DMS_15286	21328	N	N	N	1	CUSTOMER ISSUE	-
DMS_15287	21329	N	N	N	1	CUSTOMER ISSUE	-
DMS_15288	21330	N	N	N	1	CUSTOMER ISSUE	-
DMS_15290	21331	N	N	N	1	CUSTOMER ISSUE	-
DMS_15291	21332	N	N	N	1	CUSTOMER ISSUE	-
DMS_15292	21333	N	N	N	1	CUSTOMER ISSUE	-
DMS_15293	21334	N	N	N	1	CUSTOMER ISSUE	-
DMS_15294	21335	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_15295	21336	N	N	N	1	CUSTOMER ISSUE	-

DMS_15296	21337	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_15297	21338	N	N	N	1	CUSTOMER ISSUE	-
DMS_15298	21339	N	N	N	1	CUSTOMER ISSUE	-
DMS_15299	21340	N	N	N	1	CUSTOMER ISSUE	-
DMS_15300	21341	N	N	N	1	CUSTOMER ISSUE	-
DMS_15301	21342	N	N	N	1	CUSTOMER ISSUE	-
DMS_15302	21343	N	N	N	1	CUSTOMER ISSUE	-
DMS_15304	21344	N	N	N	1	CUSTOMER ISSUE	-
DMS_15305	21345	N	N	N	1	CUSTOMER ISSUE	-
DMS_15306	21346	N	N	N	1	CUSTOMER ISSUE	-
DMS_15307	21347	N	N	N	1	CUSTOMER ISSUE	-
DMS_15309	21348	N	N	N	1	CUSTOMER ISSUE	-
DMS_15310	21349	N	N	N	1	CUSTOMER ISSUE	-
DMS_15311	21350	N	N	N	1	CUSTOMER ISSUE	-
DMS_15312	21351	N	N	N	1	CUSTOMER ISSUE	-
DMS_15313	21352	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_15314	21353	N	N	N	1	CUSTOMER ISSUE	-
DMS_15315	21354	N	N	N	1	CUSTOMER ISSUE	-
DMS_15316	21355	N	N	N	1	CUSTOMER ISSUE	-
DMS_15317	21356	N	N	N	1	CUSTOMER ISSUE	-
DMS_15318	21357	N	N	N	1	CUSTOMER ISSUE	-
DMS_15319	21358	N	N	N	1	CUSTOMER ISSUE	-
DMS_15320	21359	N	N	N	1	CUSTOMER ISSUE	-
DMS_15321	21360	N	N	N	1	CUSTOMER ISSUE	-
DMS_15322	21361	N	N	N	1	CUSTOMER ISSUE	-
DMS_15324	21362	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_15325	21363	N	N	N	1	CUSTOMER ISSUE	-
DMS_15326	21364	N	N	N	1	CUSTOMER ISSUE	-
DMS_15328	21365	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_15330	21366	N	N	N	1	CUSTOMER ISSUE	-
DMS_15331	21367	N	N	N	1	CUSTOMER ISSUE	-
DMS_15332	21368	N	N	N	1	CUSTOMER ISSUE	-
DMS_15333	21369	N	N	N	1	CUSTOMER ISSUE	-
DMS_15334	21370	N	N	N	1	CUSTOMER ISSUE	-
DMS_15335	21371	N	N	N	1	CUSTOMER ISSUE	-
DMS_15336	21372	N	N	N	1	CUSTOMER ISSUE	-
DMS_15337	21373	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_15338	21374	N	N	N	1	CUSTOMER ISSUE	-
DMS_15339	21375	N	N	N	1	CUSTOMER ISSUE	-
DMS_15340	21376	N	N	N	1	CUSTOMER ISSUE	-
DMS_15342	21377	N	N	N	1	CUSTOMER ISSUE	-
DMS_15343	21378	N	N	Y	1	TX - REPLACE	2500
DMS_15344	21379	N	N	N	1	CUSTOMER ISSUE	-
DMS_15346	21380	N	N	N	1	CUSTOMER ISSUE	-
DMS_15347	21381	N	N	N	1	CUSTOMER ISSUE	-
DMS_15348	21382	N	N	N	1	CUSTOMER ISSUE	-
DMS_15349	21383	N	N	N	1	CUSTOMER ISSUE	-
DMS_15350	21384	N	N	N	1	CUSTOMER ISSUE	-
DMS_15351	21385	N	N	N	1	CUSTOMER ISSUE	-
DMS_15352	21386	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_15353	21387	N	N	N	1	CUSTOMER ISSUE	-
DMS_15354	21388	N	N	N	1	CUSTOMER ISSUE	-
DMS_15355	21389	N	N	N	1	CUSTOMER ISSUE	-
DMS_15356	21390	N	N	N	1	CUSTOMER ISSUE	-
DMS_15357	21391	N	N	N	1	CUSTOMER ISSUE	-
DMS_15358	21392	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_15360	21393	N	N	N	1	CUSTOMER ISSUE	-
DMS_15361	21394	N	N	N	1	CUSTOMER ISSUE	-
DMS_15362	21395	N	N	N	1	CUSTOMER ISSUE	-
DMS_15363	21396	N	N	N	1	CUSTOMER ISSUE	-
DMS_15364	21397	N	N	N	1	CUSTOMER ISSUE	-
DMS_15365	21398	N	N	N	1	CUSTOMER ISSUE	-
DMS_15366	21399	N	N	N	1	CUSTOMER ISSUE	-
DMS_15367	21400	N	N	N	1	CUSTOMER ISSUE	-
DMS_15368	21401	N	N	N	1	CUSTOMER ISSUE	-
DMS_15369	21402	N	N	N	1	CUSTOMER ISSUE	-
DMS_15370	21403	N	N	N	1	CUSTOMER ISSUE	-
DMS_15371	21404	N	N	N	1	CUSTOMER ISSUE	-
DMS_15372	21405	N	N	N	1	CUSTOMER ISSUE	-
DMS_15373	21406	N	N	N	1	CUSTOMER ISSUE	-
DMS_15374	21407	N	N	N	1	CUSTOMER ISSUE	-
DMS_15375	21408	N	N	N	1	CUSTOMER ISSUE	-
DMS_15376	21409	N	N	N	1	CUSTOMER ISSUE	-
DMS_15377	21410	N	N	N	1	CUSTOMER ISSUE	-
DMS_15378	21411	N	N	N	1	CUSTOMER ISSUE	-
DMS_15379	21412	N	N	N	1	CUSTOMER ISSUE	-
DMS_15381	21413	N	N	N	1	CUSTOMER ISSUE	-
DMS_15383	21414	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_15384	21415	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_15385	21416	N	N	N	1	CUSTOMER ISSUE	-

DMS_15386	21417	N	N	N	1	CUSTOMER ISSUE	-
DMS_15387	21418	N	N	N	1	CUSTOMER ISSUE	-
DMS_15388	21419	N	N	N	1	CUSTOMER ISSUE	-
DMS_15390	21420	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_15391	21421	N	N	N	1	CUSTOMER ISSUE	-
DMS_15392	21422	N	N	N	1	CUSTOMER ISSUE	-
DMS_15393	21423	N	N	N	1	CUSTOMER ISSUE	-
DMS_15394	21424	N	N	N	1	CUSTOMER ISSUE	-
DMS_15396	21425	N	N	N	1	CUSTOMER ISSUE	-
DMS_15397	21426	N	N	N	1	CUSTOMER ISSUE	-
DMS_15398	21427	N	N	N	1	CUSTOMER ISSUE	-
DMS_15399	21428	N	N	N	1	CUSTOMER ISSUE	-
DMS_15400	21429	N	N	N	1	CUSTOMER ISSUE	-
DMS_15401	21430	N	N	N	1	CUSTOMER ISSUE	-
DMS_15402	21431	N	N	N	1	CUSTOMER ISSUE	-
DMS_15403	21432	N	N	Y	1	TX - REPLACE	2500
DMS_15404	21433	N	N	N	1	CUSTOMER ISSUE	-
DMS_15405	21434	N	N	N	1	CUSTOMER ISSUE	-
DMS_15406	21435	N	N	N	1	CUSTOMER ISSUE	-
DMS_15407	21436	N	N	N	1	CUSTOMER ISSUE	-
DMS_15408	21437	N	N	N	1	CUSTOMER ISSUE	-
DMS_15409	21438	N	N	N	1	CUSTOMER ISSUE	-
DMS_15410	21439	N	N	N	1	CUSTOMER ISSUE	-
DMS_15411	21440	N	N	N	1	CUSTOMER ISSUE	-
DMS_15412	21441	N	N	N	1	CUSTOMER ISSUE	-
DMS_15413	21442	N	N	N	1	CUSTOMER ISSUE	-
DMS_15414	21443	N	N	N	1	CUSTOMER ISSUE	-
DMS_15415	21444	N	N	N	1	CUSTOMER ISSUE	-
DMS_15416	21445	N	N	N	1	CUSTOMER ISSUE	-
DMS_15417	21446	N	N	N	1	CUSTOMER ISSUE	-
DMS_15418	21447	N	N	N	1	CUSTOMER ISSUE	-
DMS_15419	21448	N	N	N	1	CUSTOMER ISSUE	-
DMS_15420	21449	N	N	N	1	CUSTOMER ISSUE	-
DMS_15421	21450	N	N	N	1	CUSTOMER ISSUE	-
DMS_15422	21451	N	N	N	1	CUSTOMER ISSUE	-
DMS_15423	21452	N	N	N	1	CUSTOMER ISSUE	-
DMS_15424	21453	N	N	N	1	CUSTOMER ISSUE	-
DMS_15425	21454	N	N	N	1	CUSTOMER ISSUE	-
DMS_15426	21455	N	N	N	1	CUSTOMER ISSUE	-
DMS_15427	21456	N	N	N	1	CUSTOMER ISSUE	-
DMS_15428	21457	N	N	N	1	CUSTOMER ISSUE	-
DMS_15429	21458	N	N	N	1	CUSTOMER ISSUE	-
DMS_15430	21459	N	N	N	1	CUSTOMER ISSUE	-
DMS_15431	21460	N	N	N	1	CUSTOMER ISSUE	-
DMS_15432	21461	N	N	N	1	CUSTOMER ISSUE	-
DMS_15433	21462	N	N	N	1	CUSTOMER ISSUE	-
DMS_15434	21463	N	N	N	1	CUSTOMER ISSUE	-
DMS_15435	21464	N	N	N	1	CUSTOMER ISSUE	-
DMS_15436	21465	N	N	N	1	CUSTOMER ISSUE	-
DMS_15437	21466	N	N	N	1	CUSTOMER ISSUE	-
DMS_15438	21467	N	N	N	1	CUSTOMER ISSUE	-
DMS_15439	21468	N	N	N	1	CUSTOMER ISSUE	-
DMS_15440	21469	N	N	N	1	CUSTOMER ISSUE	-
DMS_15441	21470	N	N	N	1	CUSTOMER ISSUE	-
DMS_15442	21471	N	N	N	1	CUSTOMER ISSUE	-
DMS_15443	21472	N	N	N	1	CUSTOMER ISSUE	-
DMS_15444	21473	N	N	N	1	CUSTOMER ISSUE	-
DMS_15445	21474	N	N	N	1	CUSTOMER ISSUE	-
DMS_15446	21475	N	N	N	1	CUSTOMER ISSUE	-
DMS_15447	21476	N	N	N	1	CUSTOMER ISSUE	-
DMS_15448	21477	N	N	N	1	CUSTOMER ISSUE	-
DMS_15449	21478	N	N	N	1	CUSTOMER ISSUE	-
DMS_15450	21479	N	N	N	1	CUSTOMER ISSUE	-
DMS_15451	21480	N	N	N	1	CUSTOMER ISSUE	-
DMS_15452	21481	N	N	N	1	CUSTOMER ISSUE	-
DMS_15453	21482	N	N	N	1	CUSTOMER ISSUE	-
DMS_15454	21483	N	N	N	1	CUSTOMER ISSUE	-
DMS_15455	21484	N	N	N	1	CUSTOMER ISSUE	-
DMS_15456	21485	N	N	N	1	CUSTOMER ISSUE	-
DMS_15457	21486	N	N	N	1	CUSTOMER ISSUE	-
DMS_15458	21487	N	N	N	1	CUSTOMER ISSUE	-
DMS_15459	21488	N	N	N	1	CUSTOMER ISSUE	-
DMS_15460	21489	N	N	N	2	CUSTOMER ISSUE	-
DMS_15461	21490	N	N	N	1	CUSTOMER ISSUE	-
DMS_15462	21491	N	N	N	1	CUSTOMER ISSUE	-
DMS_15463	21492	N	N	N	1	CUSTOMER ISSUE	-
DMS_15464	21493	N	N	N	1	CUSTOMER ISSUE	-
DMS_15465	21494	N	N	N	1	CUSTOMER ISSUE	-
DMS_15466	21495	N	N	N	1	CUSTOMER ISSUE	-
DMS_15467	21496	N	N	N	1	CUSTOMER ISSUE	-

DMS_15468	21497	N	N	N	1	CUSTOMER ISSUE	-
DMS_15469	21498	N	N	N	1	CUSTOMER ISSUE	-
DMS_15470	21499	N	N	N	1	CUSTOMER ISSUE	-
DMS_15471	21500	N	N	N	1	CUSTOMER ISSUE	-
DMS_15472	21501	N	N	N	1	CUSTOMER ISSUE	-
DMS_15473	21502	N	N	N	1	CUSTOMER ISSUE	-
DMS_15474	21503	N	N	N	1	CUSTOMER ISSUE	-
DMS_15476	21504	N	N	N	1	CUSTOMER ISSUE	-
DMS_15477	21505	N	N	N	1	CUSTOMER ISSUE	-
DMS_15478	21506	N	N	N	1	CUSTOMER ISSUE	-
DMS_15479	21507	N	N	N	1	CUSTOMER ISSUE	-
DMS_15480	21508	N	N	N	1	CUSTOMER ISSUE	-
DMS_15481	21509	N	N	N	1	CUSTOMER ISSUE	-
DMS_15482	21510	N	N	N	1	CUSTOMER ISSUE	-
DMS_15483	21511	N	N	N	1	CUSTOMER ISSUE	-
DMS_15484	21512	N	N	N	1	CUSTOMER ISSUE	-
DMS_15485	21513	N	N	N	1	CUSTOMER ISSUE	-
DMS_15486	21514	N	N	N	1	CUSTOMER ISSUE	-
DMS_15487	21515	N	N	N	1	CUSTOMER ISSUE	-
DMS_15488	21516	N	N	N	1	CUSTOMER ISSUE	-
DMS_15489	21517	N	N	N	1	CUSTOMER ISSUE	-
DMS_15490	21518	N	N	N	1	CUSTOMER ISSUE	-
DMS_15491	21519	N	N	N	2	CUSTOMER ISSUE	-
DMS_15492	21520	N	N	N	1	CUSTOMER ISSUE	-
DMS_15493	21521	N	N	N	1	CUSTOMER ISSUE	-
DMS_15494	21522	N	N	N	1	CUSTOMER ISSUE	-
DMS_15495	21523	N	N	N	1	CUSTOMER ISSUE	-
DMS_15496	21524	N	N	N	1	CUSTOMER ISSUE	-
DMS_15497	21525	N	N	N	1	CUSTOMER ISSUE	-
DMS_15498	21526	N	N	N	1	CUSTOMER ISSUE	-
DMS_15499	21527	N	N	N	1	CUSTOMER ISSUE	-
DMS_15500	21528	N	N	N	1	CUSTOMER ISSUE	-
DMS_15501	21529	N	N	N	1	CUSTOMER ISSUE	-
DMS_15502	21530	N	N	N	1	CUSTOMER ISSUE	-
DMS_15503	21531	N	N	N	1	CUSTOMER ISSUE	-
DMS_15504	21532	N	N	N	1	CUSTOMER ISSUE	-
DMS_15505	21533	N	N	N	1	CUSTOMER ISSUE	-
DMS_15506	21534	N	N	N	1	CUSTOMER ISSUE	-
DMS_15507	21535	N	N	N	1	CUSTOMER ISSUE	-
DMS_15508	21536	N	N	N	1	CUSTOMER ISSUE	-
DMS_15509	21537	N	N	N	1	CUSTOMER ISSUE	-
DMS_15510	21538	N	N	N	1	CUSTOMER ISSUE	-
DMS_15511	21539	N	N	N	1	CUSTOMER ISSUE	-
DMS_15512	21540	N	N	N	1	CUSTOMER ISSUE	-
DMS_15513	21541	N	N	N	1	CUSTOMER ISSUE	-
DMS_15514	21542	N	N	N	1	CUSTOMER ISSUE	-
DMS_15515	21543	N	N	N	1	CUSTOMER ISSUE	-
DMS_15516	21544	N	N	N	1	CUSTOMER ISSUE	-
DMS_15517	21545	N	N	N	1	CUSTOMER ISSUE	-
DMS_15518	21546	N	N	N	1	CUSTOMER ISSUE	-
DMS_15520	21547	N	N	N	1	CUSTOMER ISSUE	-
DMS_15521	21548	N	N	N	1	CUSTOMER ISSUE	-
DMS_15522	21549	N	N	N	1	CUSTOMER ISSUE	-
DMS_15523	21550	N	N	N	1	CUSTOMER ISSUE	-
DMS_15524	21551	N	N	N	1	CUSTOMER ISSUE	-
DMS_15526	21552	N	N	N	1	CUSTOMER ISSUE	-
DMS_15527	21553	N	N	N	1	CUSTOMER ISSUE	-
DMS_15528	21554	N	N	N	1	CUSTOMER ISSUE	-
DMS_15529	21555	N	N	N	1	CUSTOMER ISSUE	-
DMS_15530	21556	N	N	N	1	CUSTOMER ISSUE	-
DMS_15531	21557	N	N	N	1	CUSTOMER ISSUE	-
DMS_15532	21558	N	N	N	1	CUSTOMER ISSUE	-
DMS_15533	21559	N	N	N	1	CUSTOMER ISSUE	-
DMS_15534	21560	N	N	N	1	CUSTOMER ISSUE	-
DMS_15535	21561	N	N	N	1	CUSTOMER ISSUE	-
DMS_15536	21562	N	N	N	1	CUSTOMER ISSUE	-
DMS_15537	21563	N	N	N	1	CUSTOMER ISSUE	-
DMS_15538	21564	N	N	N	1	CUSTOMER ISSUE	-
DMS_15539	21565	N	N	N	1	CUSTOMER ISSUE	-
DMS_15540	21566	N	N	N	1	CUSTOMER ISSUE	-
DMS_15541	21567	N	N	N	1	CUSTOMER ISSUE	-
DMS_15542	21568	N	N	N	1	CUSTOMER ISSUE	-
DMS_15543	21569	N	N	N	1	CUSTOMER ISSUE	-
DMS_15544	21570	N	N	N	1	CUSTOMER ISSUE	-
DMS_15545	21571	N	N	N	1	CUSTOMER ISSUE	-
DMS_15546	21572	N	N	N	1	CUSTOMER ISSUE	-
DMS_15547	21573	N	N	N	1	CUSTOMER ISSUE	-
DMS_15548	21574	N	N	N	1	CUSTOMER ISSUE	-
DMS_15549	21575	N	N	N	1	CUSTOMER ISSUE	-
DMS_15550	21576	N	N	N	1	CUSTOMER ISSUE	-

DMS_15551	21577	N	N	N	1	CUSTOMER ISSUE	-
DMS_15552	21578	N	N	N	1	CUSTOMER ISSUE	-
DMS_15553	21579	N	N	N	1	CUSTOMER ISSUE	-
DMS_15554	21580	N	N	N	1	CUSTOMER ISSUE	-
DMS_15555	21581	N	N	N	1	CUSTOMER ISSUE	-
DMS_15556	21582	N	N	N	1	CUSTOMER ISSUE	-
DMS_15557	21583	N	N	N	1	CUSTOMER ISSUE	-
DMS_15558	21584	N	N	N	1	CUSTOMER ISSUE	-
DMS_15559	21585	N	N	N	1	CUSTOMER ISSUE	-
DMS_15560	21586	N	N	N	1	CUSTOMER ISSUE	-
DMS_15561	21587	N	N	N	1	CUSTOMER ISSUE	-
DMS_15562	21588	N	N	N	1	CUSTOMER ISSUE	-
DMS_15563	21589	N	N	N	1	CUSTOMER ISSUE	-
DMS_15564	21590	N	N	N	1	CUSTOMER ISSUE	-
DMS_15565	21591	N	N	N	1	CUSTOMER ISSUE	-
DMS_15566	21592	N	N	N	1	CUSTOMER ISSUE	-
DMS_15567	21593	N	N	N	1	CUSTOMER ISSUE	-
DMS_15568	21594	N	N	N	1	CUSTOMER ISSUE	-
DMS_15569	21595	N	N	N	1	CUSTOMER ISSUE	-
DMS_15570	21596	N	N	N	1	CUSTOMER ISSUE	-
DMS_15571	21597	N	N	N	1	CUSTOMER ISSUE	-
DMS_15572	21598	N	N	N	1	CUSTOMER ISSUE	-
DMS_15573	21599	N	N	N	1	CUSTOMER ISSUE	-
DMS_15574	21600	N	N	N	1	CUSTOMER ISSUE	-
DMS_15575	21601	N	N	N	1	CUSTOMER ISSUE	-
DMS_15576	21602	N	N	N	1	CUSTOMER ISSUE	-
DMS_15577	21603	N	N	N	1	CUSTOMER ISSUE	-
DMS_15578	21604	N	N	N	1	CUSTOMER ISSUE	-
DMS_15579	21605	N	N	N	1	CUSTOMER ISSUE	-
DMS_15580	21606	N	N	N	1	CUSTOMER ISSUE	-
DMS_15581	21607	N	N	N	1	CUSTOMER ISSUE	-
DMS_15582	21608	N	N	N	1	CUSTOMER ISSUE	-
DMS_15583	21609	N	N	N	1	CUSTOMER ISSUE	-
DMS_15584	21610	N	N	N	1	CUSTOMER ISSUE	-
DMS_15585	21611	N	N	N	1	CUSTOMER ISSUE	-
DMS_15586	21612	N	N	N	1	CUSTOMER ISSUE	-
DMS_15587	21613	N	N	N	1	CUSTOMER ISSUE	-
DMS_15588	21614	N	N	N	1	CUSTOMER ISSUE	-
DMS_15589	21615	N	N	N	1	CUSTOMER ISSUE	-
DMS_15590	21616	N	N	N	1	CUSTOMER ISSUE	-
DMS_15591	21617	N	N	N	1	CUSTOMER ISSUE	-
DMS_15592	21618	N	N	N	1	CUSTOMER ISSUE	-
DMS_15593	21619	N	N	N	1	CUSTOMER ISSUE	-
DMS_15594	21620	N	N	N	1	CUSTOMER ISSUE	-
DMS_15595	21621	N	N	N	1	CUSTOMER ISSUE	-
DMS_15596	21622	N	N	N	1	CUSTOMER ISSUE	-
DMS_15597	21623	N	N	N	1	CUSTOMER ISSUE	-
DMS_15598	21624	N	N	N	1	CUSTOMER ISSUE	-
DMS_15599	21625	N	N	N	1	CUSTOMER ISSUE	-
DMS_15600	21626	N	N	N	1	CUSTOMER ISSUE	-
DMS_15601	21627	N	N	N	1	CUSTOMER ISSUE	-
DMS_15602	21628	N	N	N	1	CUSTOMER ISSUE	-
DMS_15603	21629	N	N	N	1	CUSTOMER ISSUE	-
DMS_15604	21630	N	N	N	1	CUSTOMER ISSUE	-
DMS_15605	21631	N	N	N	1	CUSTOMER ISSUE	-
DMS_15606	21632	N	N	N	1	CUSTOMER ISSUE	-
DMS_15607	21633	N	N	N	1	CUSTOMER ISSUE	-
DMS_15608	21634	N	N	N	1	CUSTOMER ISSUE	-
DMS_15609	21635	N	N	N	1	CUSTOMER ISSUE	-
DMS_15610	21636	N	N	N	1	CUSTOMER ISSUE	-
DMS_15611	21637	N	N	N	1	CUSTOMER ISSUE	-
DMS_15612	21638	N	N	N	1	CUSTOMER ISSUE	-
DMS_15613	21639	N	N	N	1	CUSTOMER ISSUE	-
DMS_15614	21640	N	N	N	1	CUSTOMER ISSUE	-
DMS_15615	21641	N	N	N	1	CUSTOMER ISSUE	-
DMS_15616	21642	N	N	N	1	CUSTOMER ISSUE	-
DMS_15617	21643	N	N	N	1	CUSTOMER ISSUE	-
DMS_15618	21644	N	N	N	1	CUSTOMER ISSUE	-
DMS_15619	21645	N	N	N	1	CUSTOMER ISSUE	-
DMS_15620	21646	N	N	N	1	CUSTOMER ISSUE	-
DMS_15621	21647	N	N	N	1	CUSTOMER ISSUE	-
DMS_15622	21648	N	N	N	1	CUSTOMER ISSUE	-
DMS_15623	21649	N	N	N	1	CUSTOMER ISSUE	-
DMS_15624	21650	N	N	N	1	CUSTOMER ISSUE	-
DMS_15625	21651	N	N	N	1	CUSTOMER ISSUE	-
DMS_15626	21652	N	N	N	1	CUSTOMER ISSUE	-
DMS_15627	21653	N	N	N	1	CUSTOMER ISSUE	-
DMS_15628	21654	N	N	N	1	CUSTOMER ISSUE	-
DMS_15629	21655	N	N	N	1	CUSTOMER ISSUE	-
DMS_15630	21656	N	N	N	1	CUSTOMER ISSUE	-

DMS_15631	21657	N	N	N	1	CUSTOMER ISSUE	-
DMS_15632	21658	N	N	N	1	CUSTOMER ISSUE	-
DMS_15633	21659	N	N	N	1	CUSTOMER ISSUE	-
DMS_15634	21660	N	N	N	1	CUSTOMER ISSUE	-
DMS_15635	21661	N	N	N	1	CUSTOMER ISSUE	-
DMS_15636	21662	N	N	N	1	CUSTOMER ISSUE	-
DMS_15637	21663	N	N	N	1	CUSTOMER ISSUE	-
DMS_15638	21664	N	N	N	1	CUSTOMER ISSUE	-
DMS_15639	21665	N	N	N	1	CUSTOMER ISSUE	-
DMS_15640	21666	N	N	N	1	CUSTOMER ISSUE	-
DMS_15641	21667	N	N	N	1	CUSTOMER ISSUE	-
DMS_15642	21668	N	N	N	1	CUSTOMER ISSUE	-
DMS_15643	21669	N	N	N	1	CUSTOMER ISSUE	-
DMS_15644	21670	N	N	N	1	CUSTOMER ISSUE	-
DMS_15645	21671	N	N	N	1	CUSTOMER ISSUE	-
DMS_15646	21672	N	N	N	1	CUSTOMER ISSUE	-
DMS_15647	21673	N	N	N	1	CUSTOMER ISSUE	-
DMS_15648	21674	N	N	N	1	CUSTOMER ISSUE	-
DMS_15649	21675	N	N	N	1	CUSTOMER ISSUE	-
DMS_15650	21676	N	N	N	1	CUSTOMER ISSUE	-
DMS_15651	21677	N	N	N	1	CUSTOMER ISSUE	-
DMS_15652	21678	N	N	N	1	CUSTOMER ISSUE	-
DMS_15653	21679	N	N	N	1	CUSTOMER ISSUE	-
DMS_15654	21680	N	N	N	1	CUSTOMER ISSUE	-
DMS_15655	21681	N	N	N	1	CUSTOMER ISSUE	-
DMS_15656	21682	N	N	N	1	CUSTOMER ISSUE	-
DMS_15657	21683	N	N	N	1	CUSTOMER ISSUE	-
DMS_15658	21684	N	N	N	1	CUSTOMER ISSUE	-
DMS_15659	21685	N	N	N	1	CUSTOMER ISSUE	-
DMS_15660	21686	N	N	N	1	CUSTOMER ISSUE	-
DMS_15661	21687	N	N	N	1	CUSTOMER ISSUE	-
DMS_15662	21688	N	N	N	1	CUSTOMER ISSUE	-
DMS_15663	21689	N	N	N	1	CUSTOMER ISSUE	-
DMS_15664	21690	N	N	N	1	CUSTOMER ISSUE	-
DMS_15665	21691	N	N	N	1	CUSTOMER ISSUE	-
DMS_15666	21692	N	N	N	1	CUSTOMER ISSUE	-
DMS_15667	21693	N	N	N	1	CUSTOMER ISSUE	-
DMS_15668	21694	N	N	N	1	CUSTOMER ISSUE	-
DMS_15669	21695	N	N	N	1	CUSTOMER ISSUE	-
DMS_15670	21696	N	N	N	1	CUSTOMER ISSUE	-
DMS_15671	21697	N	N	N	1	CUSTOMER ISSUE	-
DMS_15672	21698	N	N	N	1	CUSTOMER ISSUE	-
DMS_15673	21699	N	N	N	1	CUSTOMER ISSUE	-
DMS_15674	21700	N	N	N	1	CUSTOMER ISSUE	-
DMS_15675	21701	N	N	N	1	CUSTOMER ISSUE	-
DMS_15676	21702	N	N	N	1	CUSTOMER ISSUE	-
DMS_15677	21703	N	N	N	1	CUSTOMER ISSUE	-
DMS_15678	21704	N	N	N	1	CUSTOMER ISSUE	-
DMS_15679	21705	N	N	N	1	CUSTOMER ISSUE	-
DMS_15680	21706	N	N	N	1	CUSTOMER ISSUE	-
DMS_15681	21707	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_15682	21708	N	N	N	1	CUSTOMER ISSUE	-
DMS_15683	21709	N	N	N	1	CUSTOMER ISSUE	-
DMS_15684	21710	N	N	N	1	CUSTOMER ISSUE	-
DMS_15685	21711	N	N	N	1	CUSTOMER ISSUE	-
DMS_15686	21712	N	N	N	1	CUSTOMER ISSUE	-
DMS_15687	21713	N	N	N	1	CUSTOMER ISSUE	-
DMS_15688	21714	N	N	N	1	CUSTOMER ISSUE	-
DMS_15689	21715	N	N	N	1	CUSTOMER ISSUE	-
DMS_15690	21716	N	N	N	1	CUSTOMER ISSUE	-
DMS_15691	21717	N	N	N	1	CUSTOMER ISSUE	-
DMS_15692	21718	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_15693	21719	N	N	N	1	CUSTOMER ISSUE	-
DMS_15694	21720	N	N	N	1	CUSTOMER ISSUE	-
DMS_15695	21721	N	N	N	1	CUSTOMER ISSUE	-
DMS_15696	21722	N	N	N	1	CUSTOMER ISSUE	-
DMS_15697	21723	N	N	N	1	CUSTOMER ISSUE	-
DMS_15698	21724	N	N	N	1	CUSTOMER ISSUE	-
DMS_15699	21725	N	N	N	1	CUSTOMER ISSUE	-
DMS_15700	21726	N	N	N	1	CUSTOMER ISSUE	-
DMS_15701	21727	N	N	N	1	CUSTOMER ISSUE	-
DMS_15702	21728	N	N	N	1	CUSTOMER ISSUE	-
DMS_15703	21729	N	N	N	1	CUSTOMER ISSUE	-
DMS_15704	21730	N	N	N	1	CUSTOMER ISSUE	-
DMS_15705	21731	N	N	N	1	CUSTOMER ISSUE	-
DMS_15706	21732	N	N	N	1	CUSTOMER ISSUE	-
DMS_15707	21733	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_15708	21734	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_15709	21735	N	N	N	1	CUSTOMER ISSUE	-
DMS_15710	21736	N	N	Y	1	DIST - REPLACE FUSE	708.75

DMS_15711	21737	N	N	N	1	CUSTOMER ISSUE	-
DMS_15712	21738	N	N	N	1	CUSTOMER ISSUE	-
DMS_15713	21739	N	N	N	1	CUSTOMER ISSUE	-
DMS_15714	21740	N	N	N	1	CUSTOMER ISSUE	-
DMS_15715	21741	N	N	N	1	CUSTOMER ISSUE	-
DMS_15716	21742	N	N	N	1	CUSTOMER ISSUE	-
DMS_15717	21743	N	N	N	1	CUSTOMER ISSUE	-
DMS_15718	21744	N	N	N	1	CUSTOMER ISSUE	-
DMS_15719	21745	N	N	N	1	CUSTOMER ISSUE	-
DMS_15720	21746	N	N	N	1	CUSTOMER ISSUE	-
DMS_15721	21747	N	N	N	1	CUSTOMER ISSUE	-
DMS_15722	21748	N	N	N	1	CUSTOMER ISSUE	-
DMS_15723	21749	N	N	N	1	CUSTOMER ISSUE	-
DMS_15724	21750	N	N	N	1	CUSTOMER ISSUE	-
DMS_15725	21751	N	N	N	1	CUSTOMER ISSUE	-
DMS_15726	21752	N	N	N	1	CUSTOMER ISSUE	-
DMS_15727	21753	N	N	N	1	CUSTOMER ISSUE	-
DMS_15728	21754	N	N	N	1	CUSTOMER ISSUE	-
DMS_15729	21755	N	N	N	1	CUSTOMER ISSUE	-
DMS_15730	21756	N	N	N	1	CUSTOMER ISSUE	-
DMS_15731	21757	N	N	N	1	CUSTOMER ISSUE	-
DMS_15732	21758	N	N	N	1	CUSTOMER ISSUE	-
DMS_15733	21759	N	N	N	1	CUSTOMER ISSUE	-
DMS_15734	21760	N	N	N	1	CUSTOMER ISSUE	-
DMS_15735	21761	N	N	N	1	CUSTOMER ISSUE	-
DMS_15736	21762	N	N	N	1	CUSTOMER ISSUE	-
DMS_15737	21763	N	N	N	1	CUSTOMER ISSUE	-
DMS_15738	21764	N	N	N	1	CUSTOMER ISSUE	-
DMS_15739	21765	N	N	N	1	CUSTOMER ISSUE	-
DMS_15740	21766	N	N	N	1	CUSTOMER ISSUE	-
DMS_15741	21767	N	N	N	1	CUSTOMER ISSUE	-
DMS_15742	21768	N	N	N	1	CUSTOMER ISSUE	-
DMS_15743	21769	N	N	N	1	CUSTOMER ISSUE	-
DMS_15744	21770	N	N	N	1	CUSTOMER ISSUE	-
DMS_15745	21771	N	N	N	1	CUSTOMER ISSUE	-
DMS_15746	21772	N	N	N	1	CUSTOMER ISSUE	-
DMS_15747	21773	N	N	N	1	CUSTOMER ISSUE	-
DMS_15748	21774	N	N	N	1	CUSTOMER ISSUE	-
DMS_15749	21775	N	N	N	1	CUSTOMER ISSUE	-
DMS_15750	21776	N	N	N	1	CUSTOMER ISSUE	-
DMS_15751	21777	N	N	N	1	CUSTOMER ISSUE	-
DMS_15752	21778	N	N	N	1	CUSTOMER ISSUE	-
DMS_15753	21779	N	N	N	1	CUSTOMER ISSUE	-
DMS_15754	21780	N	N	N	1	CUSTOMER ISSUE	-
DMS_15755	21781	N	N	N	1	CUSTOMER ISSUE	-
DMS_15756	21782	N	N	N	1	CUSTOMER ISSUE	-
DMS_15757	21783	N	N	N	1	CUSTOMER ISSUE	-
DMS_15758	21784	N	N	N	1	CUSTOMER ISSUE	-
DMS_15759	21785	N	N	N	1	CUSTOMER ISSUE	-
DMS_15760	21786	N	N	N	1	CUSTOMER ISSUE	-
DMS_15761	21787	N	N	N	1	CUSTOMER ISSUE	-
DMS_15762	21788	N	N	N	1	CUSTOMER ISSUE	-
DMS_15763	21789	N	N	N	1	CUSTOMER ISSUE	-
DMS_15764	21790	N	N	N	1	CUSTOMER ISSUE	-
DMS_15765	21791	N	N	N	1	CUSTOMER ISSUE	-
DMS_15766	21792	N	N	N	1	CUSTOMER ISSUE	-
DMS_15767	21793	N	N	N	1	CUSTOMER ISSUE	-
DMS_15768	21794	N	N	N	1	CUSTOMER ISSUE	-
DMS_15769	21795	N	N	N	1	CUSTOMER ISSUE	-
DMS_15770	21796	N	N	N	1	CUSTOMER ISSUE	-
DMS_15771	21797	N	N	N	1	CUSTOMER ISSUE	-
DMS_15772	21798	N	N	N	1	CUSTOMER ISSUE	-
DMS_15773	21799	N	N	N	1	CUSTOMER ISSUE	-
DMS_15774	21800	N	N	N	1	CUSTOMER ISSUE	-
DMS_15775	21801	N	N	N	1	CUSTOMER ISSUE	-
DMS_15776	21802	N	N	N	1	CUSTOMER ISSUE	-
DMS_15777	21803	N	N	N	1	CUSTOMER ISSUE	-
DMS_15778	21804	N	N	N	1	CUSTOMER ISSUE	-
DMS_15779	21805	N	N	N	1	CUSTOMER ISSUE	-
DMS_15781	21806	N	N	N	1	CUSTOMER ISSUE	-
DMS_15782	21807	N	N	N	1	CUSTOMER ISSUE	-
DMS_15783	21808	N	N	N	1	CUSTOMER ISSUE	-
DMS_15784	21809	N	N	N	1	CUSTOMER ISSUE	-
DMS_15785	21810	N	N	N	1	CUSTOMER ISSUE	-
DMS_15786	21811	N	N	N	1	CUSTOMER ISSUE	-
DMS_15787	21812	N	N	N	1	CUSTOMER ISSUE	-
DMS_15788	21813	N	N	N	1	CUSTOMER ISSUE	-
DMS_15789	21814	N	N	N	1	CUSTOMER ISSUE	-
DMS_15790	21815	N	N	N	1	CUSTOMER ISSUE	-
DMS_15791	21816	N	N	N	1	CUSTOMER ISSUE	-

DMS_15792	21817	N	N	N	1	CUSTOMER ISSUE	-
DMS_15793	21818	N	N	N	1	CUSTOMER ISSUE	-
DMS_15794	21819	N	N	N	1	CUSTOMER ISSUE	-
DMS_15795	21820	N	N	N	1	CUSTOMER ISSUE	-
DMS_15796	21821	N	N	N	1	CUSTOMER ISSUE	-
DMS_15797	21822	N	N	N	1	CUSTOMER ISSUE	-
DMS_15798	21823	N	N	N	1	CUSTOMER ISSUE	-
DMS_15799	21824	N	N	N	1	CUSTOMER ISSUE	-
DMS_15800	21825	N	N	N	1	CUSTOMER ISSUE	-
DMS_15801	21826	N	N	N	1	CUSTOMER ISSUE	-
DMS_15802	21827	N	N	N	1	CUSTOMER ISSUE	-
DMS_15803	21828	N	N	N	1	CUSTOMER ISSUE	-
DMS_15804	21829	N	N	N	1	CUSTOMER ISSUE	-
DMS_15805	21830	N	N	N	1	CUSTOMER ISSUE	-
DMS_15806	21831	N	N	N	1	CUSTOMER ISSUE	-
DMS_15807	21832	N	N	N	1	CUSTOMER ISSUE	-
DMS_15808	21833	N	N	N	1	CUSTOMER ISSUE	-
DMS_15809	21834	N	N	N	1	CUSTOMER ISSUE	-
DMS_15810	21835	N	N	N	1	CUSTOMER ISSUE	-
DMS_15811	21836	N	N	N	1	CUSTOMER ISSUE	-
DMS_15812	21837	N	N	N	1	CUSTOMER ISSUE	-
DMS_15813	21838	N	N	N	1	CUSTOMER ISSUE	-
DMS_15814	21839	N	N	N	1	CUSTOMER ISSUE	-
DMS_15815	21840	N	N	N	1	CUSTOMER ISSUE	-
DMS_15816	21841	N	N	N	1	CUSTOMER ISSUE	-
DMS_15817	21842	N	N	N	1	CUSTOMER ISSUE	-
DMS_15818	21843	N	N	N	1	CUSTOMER ISSUE	-
DMS_15819	21844	N	N	N	1	CUSTOMER ISSUE	-
DMS_15820	21845	N	N	N	1	CUSTOMER ISSUE	-
DMS_15821	21846	N	N	N	1	CUSTOMER ISSUE	-
DMS_15822	21847	N	N	N	1	CUSTOMER ISSUE	-
DMS_15823	21848	N	N	N	1	CUSTOMER ISSUE	-
DMS_15824	21849	N	N	N	1	CUSTOMER ISSUE	-
DMS_15825	21850	N	N	N	1	CUSTOMER ISSUE	-
DMS_15826	21851	N	N	N	1	CUSTOMER ISSUE	-
DMS_15827	21852	N	N	N	1	CUSTOMER ISSUE	-
DMS_15828	21853	N	N	N	1	CUSTOMER ISSUE	-
DMS_15829	21854	N	N	N	1	CUSTOMER ISSUE	-
DMS_15830	21855	N	N	N	1	CUSTOMER ISSUE	-
DMS_15831	21856	N	N	N	1	CUSTOMER ISSUE	-
DMS_15832	21857	N	N	N	1	CUSTOMER ISSUE	-
DMS_15833	21858	N	N	N	1	CUSTOMER ISSUE	-
DMS_15834	21859	N	N	N	1	CUSTOMER ISSUE	-
DMS_15835	21860	N	N	N	1	CUSTOMER ISSUE	-
DMS_15836	21861	N	N	N	1	CUSTOMER ISSUE	-
DMS_15837	21862	N	N	N	1	CUSTOMER ISSUE	-
DMS_15838	21863	N	N	N	1	CUSTOMER ISSUE	-
DMS_15839	21864	N	N	N	1	CUSTOMER ISSUE	-
DMS_15840	21865	N	N	N	1	CUSTOMER ISSUE	-
DMS_15841	21866	N	N	N	1	CUSTOMER ISSUE	-
DMS_15842	21867	N	N	N	1	CUSTOMER ISSUE	-
DMS_15843	21868	N	N	N	1	CUSTOMER ISSUE	-
DMS_15844	21869	N	N	N	1	CUSTOMER ISSUE	-
DMS_15845	21870	N	N	N	1	CUSTOMER ISSUE	-
DMS_15846	21871	N	N	N	1	CUSTOMER ISSUE	-
DMS_15847	21872	N	N	N	1	CUSTOMER ISSUE	-
DMS_15848	21873	N	N	N	1	CUSTOMER ISSUE	-
DMS_15849	21874	N	N	N	1	CUSTOMER ISSUE	-
DMS_15850	21875	N	N	N	1	CUSTOMER ISSUE	-
DMS_15851	21876	N	N	N	1	CUSTOMER ISSUE	-
DMS_15852	21877	N	N	N	1	CUSTOMER ISSUE	-
DMS_15853	21878	N	N	N	1	CUSTOMER ISSUE	-
DMS_15854	21879	N	N	N	1	CUSTOMER ISSUE	-
DMS_15855	21880	N	N	N	1	CUSTOMER ISSUE	-
DMS_15856	21881	N	N	N	1	CUSTOMER ISSUE	-
DMS_15857	21882	N	N	N	1	CUSTOMER ISSUE	-
DMS_15858	21883	N	N	N	1	CUSTOMER ISSUE	-
DMS_15859	21884	N	N	N	1	CUSTOMER ISSUE	-
DMS_15860	21885	N	N	N	1	CUSTOMER ISSUE	-
DMS_15861	21886	N	N	N	1	CUSTOMER ISSUE	-
DMS_15862	21887	N	N	N	1	CUSTOMER ISSUE	-
DMS_15863	21888	N	N	N	1	CUSTOMER ISSUE	-
DMS_15864	21889	N	N	N	1	CUSTOMER ISSUE	-
DMS_15865	21890	N	N	N	1	CUSTOMER ISSUE	-
DMS_15866	21891	N	N	N	1	CUSTOMER ISSUE	-
DMS_15867	21892	N	N	N	1	CUSTOMER ISSUE	-
DMS_15868	21893	N	N	N	1	CUSTOMER ISSUE	-
DMS_15869	21894	N	N	N	1	CUSTOMER ISSUE	-
DMS_15870	21895	N	N	N	1	CUSTOMER ISSUE	-
DMS_15871	21896	N	N	N	1	CUSTOMER ISSUE	-

DMS_15872	21897	N	N	N	1	CUSTOMER ISSUE	-
DMS_15873	21898	N	N	N	1	CUSTOMER ISSUE	-
DMS_15874	21899	N	N	N	1	CUSTOMER ISSUE	-
DMS_15875	21900	N	N	N	1	CUSTOMER ISSUE	-
DMS_15876	21901	N	N	N	1	CUSTOMER ISSUE	-
DMS_15877	21902	N	N	N	1	CUSTOMER ISSUE	-
DMS_15878	21903	N	N	N	1	CUSTOMER ISSUE	-
DMS_15879	21904	N	N	N	1	CUSTOMER ISSUE	-
DMS_15880	21905	N	N	N	1	CUSTOMER ISSUE	-
DMS_15881	21906	N	N	N	1	CUSTOMER ISSUE	-
DMS_15882	21907	N	N	N	1	CUSTOMER ISSUE	-
DMS_15883	21908	N	N	N	1	CUSTOMER ISSUE	-
DMS_15884	21909	N	N	N	1	CUSTOMER ISSUE	-
DMS_15885	21910	N	N	N	1	CUSTOMER ISSUE	-
DMS_15886	21911	N	N	N	1	CUSTOMER ISSUE	-
DMS_15887	21912	N	N	N	1	CUSTOMER ISSUE	-
DMS_15888	21913	N	N	N	1	CUSTOMER ISSUE	-
DMS_15889	21914	N	N	N	1	CUSTOMER ISSUE	-
DMS_15890	21915	N	N	N	1	CUSTOMER ISSUE	-
DMS_15891	21916	N	N	N	1	CUSTOMER ISSUE	-
DMS_15892	21917	N	N	N	1	CUSTOMER ISSUE	-
DMS_15893	21918	N	N	N	1	CUSTOMER ISSUE	-
DMS_15894	21919	N	N	N	1	CUSTOMER ISSUE	-
DMS_15895	21920	N	N	N	1	CUSTOMER ISSUE	-
DMS_15896	21921	N	N	N	1	CUSTOMER ISSUE	-
DMS_15897	21922	N	N	N	1	CUSTOMER ISSUE	-
DMS_15898	21923	N	N	N	1	CUSTOMER ISSUE	-
DMS_15899	21924	N	N	N	1	CUSTOMER ISSUE	-
DMS_15900	21925	N	N	N	1	CUSTOMER ISSUE	-
DMS_15901	21926	N	N	N	1	CUSTOMER ISSUE	-
DMS_15902	21927	N	N	N	1	CUSTOMER ISSUE	-
DMS_15903	21928	N	N	N	1	CUSTOMER ISSUE	-
DMS_15904	21929	N	N	N	1	CUSTOMER ISSUE	-
DMS_15905	21930	N	N	N	1	CUSTOMER ISSUE	-
DMS_15906	21931	N	N	N	1	CUSTOMER ISSUE	-
DMS_15907	21932	N	N	N	1	CUSTOMER ISSUE	-
DMS_15908	21933	N	N	N	1	CUSTOMER ISSUE	-
DMS_15909	21934	N	N	N	1	CUSTOMER ISSUE	-
DMS_15910	21935	N	N	N	1	CUSTOMER ISSUE	-
DMS_15911	21936	N	N	N	1	CUSTOMER ISSUE	-
DMS_15912	21937	N	N	N	1	CUSTOMER ISSUE	-
DMS_15913	21938	N	N	N	1	CUSTOMER ISSUE	-
DMS_15914	21939	N	N	N	1	CUSTOMER ISSUE	-
DMS_15915	21940	N	N	N	1	CUSTOMER ISSUE	-
DMS_15916	21941	N	N	N	1	CUSTOMER ISSUE	-
DMS_15917	21942	N	N	N	1	CUSTOMER ISSUE	-
DMS_15918	21943	N	N	N	1	CUSTOMER ISSUE	-
DMS_15919	21944	N	N	N	1	CUSTOMER ISSUE	-
DMS_15920	21945	N	N	N	1	CUSTOMER ISSUE	-
DMS_15921	21946	N	N	N	1	CUSTOMER ISSUE	-
DMS_15922	21947	N	N	N	1	CUSTOMER ISSUE	-
DMS_15923	21948	N	N	N	1	CUSTOMER ISSUE	-
DMS_15924	21949	N	N	N	1	CUSTOMER ISSUE	-
DMS_15925	21950	N	N	N	1	CUSTOMER ISSUE	-
DMS_15926	21951	N	N	N	1	CUSTOMER ISSUE	-
DMS_15927	21952	N	N	N	1	CUSTOMER ISSUE	-
DMS_15928	21953	N	N	N	1	CUSTOMER ISSUE	-
DMS_15929	21954	N	N	N	1	CUSTOMER ISSUE	-
DMS_15930	21955	N	N	N	1	CUSTOMER ISSUE	-
DMS_15931	21956	N	N	N	1	CUSTOMER ISSUE	-
DMS_15932	21957	N	N	N	1	CUSTOMER ISSUE	-
DMS_15933	21958	N	N	N	1	CUSTOMER ISSUE	-
DMS_15934	21959	N	N	N	1	CUSTOMER ISSUE	-
DMS_15935	21960	N	N	N	1	CUSTOMER ISSUE	-
DMS_15936	21961	N	N	N	1	CUSTOMER ISSUE	-
DMS_15937	21962	N	N	N	1	CUSTOMER ISSUE	-
DMS_15938	21963	N	N	N	1	CUSTOMER ISSUE	-
DMS_15939	21964	N	N	N	1	CUSTOMER ISSUE	-
DMS_15940	21965	N	N	N	1	CUSTOMER ISSUE	-
DMS_15941	21966	N	N	N	1	CUSTOMER ISSUE	-
DMS_15942	21967	N	N	N	1	CUSTOMER ISSUE	-
DMS_15944	21968	N	N	N	1	CUSTOMER ISSUE	-
DMS_15945	21969	N	N	N	1	CUSTOMER ISSUE	-
DMS_15946	21970	N	N	N	1	CUSTOMER ISSUE	-
DMS_15947	21971	N	N	N	1	CUSTOMER ISSUE	-
DMS_15948	21972	N	N	N	1	CUSTOMER ISSUE	-
DMS_15949	21973	N	N	N	1	CUSTOMER ISSUE	-
DMS_15950	21974	N	N	N	1	CUSTOMER ISSUE	-
DMS_15951	21975	N	N	N	1	CUSTOMER ISSUE	-
DMS_15952	21976	N	N	N	1	CUSTOMER ISSUE	-

DMS_15953	21977	N	N	N	1	CUSTOMER ISSUE	-
DMS_15954	21978	N	N	N	1	CUSTOMER ISSUE	-
DMS_15955	21979	N	N	N	1	CUSTOMER ISSUE	-
DMS_15956	21980	N	N	N	1	CUSTOMER ISSUE	-
DMS_15957	21981	N	N	N	1	CUSTOMER ISSUE	-
DMS_15958	21982	N	N	N	1	CUSTOMER ISSUE	-
DMS_15959	21983	N	N	N	1	CUSTOMER ISSUE	-
DMS_15960	21984	N	N	N	1	CUSTOMER ISSUE	-
DMS_15961	21985	N	N	N	1	CUSTOMER ISSUE	-
DMS_15962	21986	N	N	N	1	CUSTOMER ISSUE	-
DMS_15963	21987	N	N	N	1	CUSTOMER ISSUE	-
DMS_15964	21988	N	N	N	1	CUSTOMER ISSUE	-
DMS_15965	21989	N	N	N	1	CUSTOMER ISSUE	-
DMS_15966	21990	N	N	N	1	CUSTOMER ISSUE	-
DMS_15967	21991	N	N	N	1	CUSTOMER ISSUE	-
DMS_15968	21992	N	N	N	1	CUSTOMER ISSUE	-
DMS_15969	21993	N	N	N	1	CUSTOMER ISSUE	-
DMS_15970	21994	N	N	N	1	CUSTOMER ISSUE	-
DMS_15971	21995	N	N	N	1	CUSTOMER ISSUE	-
DMS_15972	21996	N	N	N	1	CUSTOMER ISSUE	-
DMS_15973	21997	N	N	N	1	CUSTOMER ISSUE	-
DMS_15974	21998	N	N	N	1	CUSTOMER ISSUE	-
DMS_15975	21999	N	N	N	1	CUSTOMER ISSUE	-
DMS_15976	22000	N	N	N	1	CUSTOMER ISSUE	-
DMS_15977	22001	N	N	N	1	CUSTOMER ISSUE	-
DMS_15978	22002	N	N	N	1	CUSTOMER ISSUE	-
DMS_15979	22003	N	N	N	1	CUSTOMER ISSUE	-
DMS_15980	22004	N	N	N	1	CUSTOMER ISSUE	-
DMS_15981	22005	N	N	N	1	CUSTOMER ISSUE	-
DMS_15982	22006	N	N	N	1	CUSTOMER ISSUE	-
DMS_15983	22007	N	N	N	1	CUSTOMER ISSUE	-
DMS_15984	22008	N	N	N	1	CUSTOMER ISSUE	-
DMS_15985	22009	N	N	N	1	CUSTOMER ISSUE	-
DMS_15986	22010	N	N	N	1	CUSTOMER ISSUE	-
DMS_15987	22011	N	N	N	1	CUSTOMER ISSUE	-
DMS_15988	22012	N	N	N	1	CUSTOMER ISSUE	-
DMS_15989	22013	N	N	N	1	CUSTOMER ISSUE	-
DMS_15990	22014	N	N	N	1	CUSTOMER ISSUE	-
DMS_15991	22015	N	N	N	1	CUSTOMER ISSUE	-
DMS_15992	22016	N	N	N	1	CUSTOMER ISSUE	-
DMS_15993	22017	N	N	N	1	CUSTOMER ISSUE	-
DMS_15994	22018	N	N	N	1	CUSTOMER ISSUE	-
DMS_15995	22019	N	N	N	1	CUSTOMER ISSUE	-
DMS_15996	22020	N	N	N	1	CUSTOMER ISSUE	-
DMS_15997	22021	N	N	N	1	CUSTOMER ISSUE	-
DMS_15998	22022	N	N	N	1	CUSTOMER ISSUE	-
DMS_15999	22023	N	N	N	1	CUSTOMER ISSUE	-
DMS_16000	22024	N	N	N	1	CUSTOMER ISSUE	-
DMS_16001	22025	N	N	N	1	CUSTOMER ISSUE	-
DMS_16002	22026	N	N	N	1	CUSTOMER ISSUE	-
DMS_16003	22027	N	N	N	1	CUSTOMER ISSUE	-
DMS_16004	22028	N	N	N	1	CUSTOMER ISSUE	-
DMS_16005	22029	N	N	N	1	CUSTOMER ISSUE	-
DMS_16006	22030	N	N	N	1	CUSTOMER ISSUE	-
DMS_16007	22031	N	N	N	1	CUSTOMER ISSUE	-
DMS_16008	22032	N	N	N	1	CUSTOMER ISSUE	-
DMS_16009	22033	N	N	N	1	CUSTOMER ISSUE	-
DMS_16010	22034	N	N	N	1	CUSTOMER ISSUE	-
DMS_16011	22035	N	N	N	1	CUSTOMER ISSUE	-
DMS_16012	22036	N	N	N	1	CUSTOMER ISSUE	-
DMS_16013	22037	N	N	N	1	CUSTOMER ISSUE	-
DMS_16014	22038	N	N	N	1	CUSTOMER ISSUE	-
DMS_16015	22039	N	N	N	1	CUSTOMER ISSUE	-
DMS_16016	22040	N	N	N	1	CUSTOMER ISSUE	-
DMS_16017	22041	N	N	N	1	CUSTOMER ISSUE	-
DMS_16018	22042	N	N	N	1	CUSTOMER ISSUE	-
DMS_16019	22043	N	N	N	1	CUSTOMER ISSUE	-
DMS_16020	22044	N	N	N	1	CUSTOMER ISSUE	-
DMS_16021	22045	N	N	N	1	CUSTOMER ISSUE	-
DMS_16022	22046	N	N	N	1	CUSTOMER ISSUE	-
DMS_16023	22047	N	N	N	1	CUSTOMER ISSUE	-
DMS_16024	22048	N	N	N	1	CUSTOMER ISSUE	-
DMS_16025	22049	N	N	N	1	CUSTOMER ISSUE	-
DMS_16026	22050	N	N	N	1	CUSTOMER ISSUE	-
DMS_16027	22051	N	N	N	1	CUSTOMER ISSUE	-
DMS_16028	22052	N	N	N	1	CUSTOMER ISSUE	-
DMS_16029	22053	N	N	N	1	CUSTOMER ISSUE	-
DMS_16030	22054	N	N	N	1	CUSTOMER ISSUE	-
DMS_16031	22055	N	N	N	1	CUSTOMER ISSUE	-
DMS_16032	22056	N	N	N	1	CUSTOMER ISSUE	-

DMS_16033	22057	N	N	N	1	CUSTOMER ISSUE	-
DMS_16034	22058	N	N	N	1	CUSTOMER ISSUE	-
DMS_16035	22059	N	N	N	1	CUSTOMER ISSUE	-
DMS_16036	22060	N	N	N	1	CUSTOMER ISSUE	-
DMS_16037	22061	N	N	N	1	CUSTOMER ISSUE	-
DMS_16038	22062	N	N	N	1	CUSTOMER ISSUE	-
DMS_16039	22063	N	N	N	1	CUSTOMER ISSUE	-
DMS_16040	22064	N	N	N	1	CUSTOMER ISSUE	-
DMS_16041	22065	N	N	N	1	CUSTOMER ISSUE	-
DMS_16042	22066	N	N	N	1	CUSTOMER ISSUE	-
DMS_16043	22067	N	N	N	1	CUSTOMER ISSUE	-
DMS_16044	22068	N	N	N	1	CUSTOMER ISSUE	-
DMS_16045	22069	N	N	N	1	CUSTOMER ISSUE	-
DMS_16046	22070	N	N	N	1	CUSTOMER ISSUE	-
DMS_16047	22071	N	N	N	1	CUSTOMER ISSUE	-
DMS_16048	22072	N	N	N	1	CUSTOMER ISSUE	-
DMS_16049	22073	N	N	N	1	CUSTOMER ISSUE	-
DMS_16050	22074	N	N	N	1	CUSTOMER ISSUE	-
DMS_16051	22075	N	N	N	1	CUSTOMER ISSUE	-
DMS_16052	22076	N	N	N	1	CUSTOMER ISSUE	-
DMS_16053	22077	N	N	N	1	CUSTOMER ISSUE	-
DMS_16054	22078	N	N	N	1	CUSTOMER ISSUE	-
DMS_16055	22079	N	N	N	1	CUSTOMER ISSUE	-
DMS_16056	22080	N	N	N	1	CUSTOMER ISSUE	-
DMS_16057	22081	N	N	N	1	CUSTOMER ISSUE	-
DMS_16058	22082	N	N	N	1	CUSTOMER ISSUE	-
DMS_16059	22083	N	N	N	1	CUSTOMER ISSUE	-
DMS_16060	22084	N	N	N	1	CUSTOMER ISSUE	-
DMS_16061	22085	N	N	N	1	CUSTOMER ISSUE	-
DMS_16062	22086	N	N	N	1	CUSTOMER ISSUE	-
DMS_16063	22087	N	N	N	1	CUSTOMER ISSUE	-
DMS_16064	22088	N	N	N	1	CUSTOMER ISSUE	-
DMS_16065	22089	N	N	N	1	CUSTOMER ISSUE	-
DMS_16066	22090	N	N	N	1	CUSTOMER ISSUE	-
DMS_16067	22091	N	N	N	1	CUSTOMER ISSUE	-
DMS_16068	22092	N	N	N	1	CUSTOMER ISSUE	-
DMS_16069	22093	N	N	N	1	CUSTOMER ISSUE	-
DMS_16070	22094	N	N	N	1	CUSTOMER ISSUE	-
DMS_16071	22095	N	N	N	1	CUSTOMER ISSUE	-
DMS_16072	22096	N	N	N	1	CUSTOMER ISSUE	-
DMS_16073	22097	N	N	N	1	CUSTOMER ISSUE	-
DMS_16074	22098	N	N	N	1	CUSTOMER ISSUE	-
DMS_16075	22099	N	N	N	1	CUSTOMER ISSUE	-
DMS_16076	22100	N	N	N	1	CUSTOMER ISSUE	-
DMS_16077	22101	N	N	N	1	CUSTOMER ISSUE	-
DMS_16078	22102	N	N	N	1	CUSTOMER ISSUE	-
DMS_16079	22103	N	N	N	1	CUSTOMER ISSUE	-
DMS_16080	22104	N	N	N	1	CUSTOMER ISSUE	-
DMS_16081	22105	N	N	N	1	CUSTOMER ISSUE	-
DMS_16082	22106	N	N	N	1	CUSTOMER ISSUE	-
DMS_16083	22107	N	N	N	1	CUSTOMER ISSUE	-
DMS_16084	22108	N	N	N	1	CUSTOMER ISSUE	-
DMS_16085	22109	N	N	N	1	CUSTOMER ISSUE	-
DMS_16086	22110	N	N	N	1	CUSTOMER ISSUE	-
DMS_16087	22111	N	N	N	1	CUSTOMER ISSUE	-
DMS_16088	22112	N	N	N	1	CUSTOMER ISSUE	-
DMS_16089	22113	N	N	N	1	CUSTOMER ISSUE	-
DMS_16090	22114	N	N	N	1	CUSTOMER ISSUE	-
DMS_16091	22115	N	N	N	1	CUSTOMER ISSUE	-
DMS_16092	22116	N	N	N	1	CUSTOMER ISSUE	-
DMS_16093	22117	N	N	N	1	CUSTOMER ISSUE	-
DMS_16094	22118	N	N	N	1	CUSTOMER ISSUE	-
DMS_16095	22119	N	N	N	1	CUSTOMER ISSUE	-
DMS_16096	22120	N	N	N	1	CUSTOMER ISSUE	-
DMS_16097	22121	N	N	N	1	CUSTOMER ISSUE	-
DMS_16098	22122	N	N	N	1	CUSTOMER ISSUE	-
DMS_16099	22123	N	N	N	1	CUSTOMER ISSUE	-
DMS_16100	22124	N	N	N	1	CUSTOMER ISSUE	-
DMS_16101	22125	N	N	N	1	CUSTOMER ISSUE	-
DMS_16102	22126	N	N	N	1	CUSTOMER ISSUE	-
DMS_16103	22127	N	N	N	1	CUSTOMER ISSUE	-
DMS_16104	22128	N	N	N	1	CUSTOMER ISSUE	-
DMS_16105	22129	N	N	N	1	CUSTOMER ISSUE	-
DMS_16106	22130	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_16107	22131	N	N	N	1	CUSTOMER ISSUE	-
DMS_16108	22132	N	N	N	1	CUSTOMER ISSUE	-
DMS_16109	22133	N	N	N	1	CUSTOMER ISSUE	-
DMS_16110	22134	N	N	N	1	CUSTOMER ISSUE	-
DMS_16111	22135	N	N	N	1	CUSTOMER ISSUE	-
DMS_16112	22136	N	N	N	1	CUSTOMER ISSUE	-

DMS_16113	22137	N	N	N	2	CUSTOMER ISSUE	-
DMS_16114	22138	N	N	N	1	CUSTOMER ISSUE	-
DMS_16115	22139	N	N	N	1	CUSTOMER ISSUE	-
DMS_16116	22140	N	N	N	1	CUSTOMER ISSUE	-
DMS_16117	22141	N	N	N	1	CUSTOMER ISSUE	-
DMS_16118	22142	N	N	N	1	CUSTOMER ISSUE	-
DMS_16119	22143	N	N	N	1	CUSTOMER ISSUE	-
DMS_16120	22144	N	N	N	1	CUSTOMER ISSUE	-
DMS_16121	22145	N	N	N	1	CUSTOMER ISSUE	-
DMS_16122	22146	N	N	N	1	CUSTOMER ISSUE	-
DMS_16123	22147	N	N	N	1	CUSTOMER ISSUE	-
DMS_16124	22148	N	N	N	1	CUSTOMER ISSUE	-
DMS_16125	22149	N	N	N	1	CUSTOMER ISSUE	-
DMS_16126	22150	N	N	N	1	CUSTOMER ISSUE	-
DMS_16127	22151	N	N	N	1	CUSTOMER ISSUE	-
DMS_16128	22152	N	N	N	1	CUSTOMER ISSUE	-
DMS_16129	22153	N	N	N	1	CUSTOMER ISSUE	-
DMS_16131	22154	N	N	N	1	CUSTOMER ISSUE	-
DMS_16132	22155	N	N	N	1	CUSTOMER ISSUE	-
DMS_16133	22156	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_16134	22157	N	N	N	1	CUSTOMER ISSUE	-
DMS_16135	22158	N	N	N	1	CUSTOMER ISSUE	-
DMS_16136	22159	N	N	N	1	CUSTOMER ISSUE	-
DMS_16137	22160	N	N	N	1	CUSTOMER ISSUE	-
DMS_16139	22161	N	N	N	1	CUSTOMER ISSUE	-
DMS_16140	22162	N	N	N	1	CUSTOMER ISSUE	-
DMS_16141	22163	N	N	N	1	CUSTOMER ISSUE	-
DMS_16142	22164	N	N	N	1	CUSTOMER ISSUE	-
DMS_16143	22165	N	N	N	1	CUSTOMER ISSUE	-
DMS_16144	22166	N	N	N	1	CUSTOMER ISSUE	-
DMS_16145	22167	N	N	N	1	CUSTOMER ISSUE	-
DMS_16146	22168	N	N	N	1	CUSTOMER ISSUE	-
DMS_16147	22169	N	N	N	1	CUSTOMER ISSUE	-
DMS_16148	22170	N	N	N	1	CUSTOMER ISSUE	-
DMS_16149	22171	N	N	N	1	CUSTOMER ISSUE	-
DMS_16150	22172	N	N	N	1	CUSTOMER ISSUE	-
DMS_16151	22173	N	N	N	1	CUSTOMER ISSUE	-
DMS_16152	22174	N	N	N	1	CUSTOMER ISSUE	-
DMS_16153	22175	N	N	N	1	CUSTOMER ISSUE	-
DMS_16154	22176	N	N	N	1	CUSTOMER ISSUE	-
DMS_16155	22177	N	N	N	1	CUSTOMER ISSUE	-
DMS_16156	22178	N	N	N	1	CUSTOMER ISSUE	-
DMS_16157	22179	N	N	N	1	CUSTOMER ISSUE	-
DMS_16158	22180	N	N	N	1	CUSTOMER ISSUE	-
DMS_16160	22181	N	N	N	1	CUSTOMER ISSUE	-
DMS_16161	22182	N	N	N	1	CUSTOMER ISSUE	-
DMS_16162	22183	N	N	N	1	CUSTOMER ISSUE	-
DMS_16163	22184	N	N	N	1	CUSTOMER ISSUE	-
DMS_16164	22185	N	N	N	1	CUSTOMER ISSUE	-
DMS_16165	22186	N	N	N	1	CUSTOMER ISSUE	-
DMS_16166	22187	N	N	N	1	CUSTOMER ISSUE	-
DMS_16167	22188	N	N	N	1	CUSTOMER ISSUE	-
DMS_16168	22189	N	N	N	1	CUSTOMER ISSUE	-
DMS_16169	22190	N	N	N	1	CUSTOMER ISSUE	-
DMS_16170	22191	N	N	N	1	CUSTOMER ISSUE	-
DMS_16171	22192	N	N	N	1	CUSTOMER ISSUE	-
DMS_16172	22193	N	N	N	1	CUSTOMER ISSUE	-
DMS_16173	22194	N	N	N	1	CUSTOMER ISSUE	-
DMS_16174	22195	N	N	N	1	CUSTOMER ISSUE	-
DMS_16175	22196	N	N	N	1	CUSTOMER ISSUE	-
DMS_16176	22197	N	N	N	1	CUSTOMER ISSUE	-
DMS_16177	22198	N	N	N	1	CUSTOMER ISSUE	-
DMS_16178	22199	N	N	N	1	CUSTOMER ISSUE	-
DMS_16179	22200	N	N	N	1	CUSTOMER ISSUE	-
DMS_16180	22201	N	N	N	1	CUSTOMER ISSUE	-
DMS_16181	22202	N	N	N	1	CUSTOMER ISSUE	-
DMS_16182	22203	N	N	N	1	CUSTOMER ISSUE	-
DMS_16183	22204	N	N	N	1	CUSTOMER ISSUE	-
DMS_16184	22205	N	N	N	1	CUSTOMER ISSUE	-
DMS_16185	22206	N	N	N	1	CUSTOMER ISSUE	-
DMS_16186	22207	N	N	N	1	CUSTOMER ISSUE	-
DMS_16187	22208	N	N	N	1	CUSTOMER ISSUE	-
DMS_16188	22209	N	N	N	1	CUSTOMER ISSUE	-
DMS_16189	22210	N	N	N	1	CUSTOMER ISSUE	-
DMS_16190	22211	N	N	N	1	CUSTOMER ISSUE	-
DMS_16191	22212	N	N	N	1	CUSTOMER ISSUE	-
DMS_16192	22213	N	N	N	1	CUSTOMER ISSUE	-
DMS_16193	22214	N	N	N	1	CUSTOMER ISSUE	-
DMS_16194	22215	N	N	N	1	CUSTOMER ISSUE	-
DMS_16195	22216	N	N	N	1	CUSTOMER ISSUE	-

DMS_16196	22217	N	N	N	1	CUSTOMER ISSUE	-
DMS_16197	22218	N	N	N	1	CUSTOMER ISSUE	-
DMS_16198	22219	N	N	N	1	CUSTOMER ISSUE	-
DMS_16199	22220	N	N	N	1	CUSTOMER ISSUE	-
DMS_16200	22221	N	N	N	1	CUSTOMER ISSUE	-
DMS_16201	22222	N	N	N	1	CUSTOMER ISSUE	-
DMS_16202	22223	N	N	N	1	CUSTOMER ISSUE	-
DMS_16203	22224	N	N	N	1	CUSTOMER ISSUE	-
DMS_16204	22225	N	N	N	1	CUSTOMER ISSUE	-
DMS_16205	22226	N	N	N	1	CUSTOMER ISSUE	-
DMS_16206	22227	N	N	N	1	CUSTOMER ISSUE	-
DMS_16207	22228	N	N	N	1	CUSTOMER ISSUE	-
DMS_16208	22229	N	N	N	1	CUSTOMER ISSUE	-
DMS_16209	22230	N	N	N	1	CUSTOMER ISSUE	-
DMS_16210	22231	N	N	N	1	CUSTOMER ISSUE	-
DMS_16211	22232	N	N	N	1	CUSTOMER ISSUE	-
DMS_16212	22233	N	N	N	1	CUSTOMER ISSUE	-
DMS_16213	22234	N	N	N	1	CUSTOMER ISSUE	-
DMS_16214	22235	N	N	N	1	CUSTOMER ISSUE	-
DMS_16215	22236	N	N	N	1	CUSTOMER ISSUE	-
DMS_16216	22237	N	N	N	1	CUSTOMER ISSUE	-
DMS_16217	22238	N	N	N	1	CUSTOMER ISSUE	-
DMS_16218	22239	N	N	N	1	CUSTOMER ISSUE	-
DMS_16219	22240	N	N	N	1	CUSTOMER ISSUE	-
DMS_16220	22241	N	N	N	1	CUSTOMER ISSUE	-
DMS_16221	22242	N	N	N	1	CUSTOMER ISSUE	-
DMS_16222	22243	N	N	N	1	CUSTOMER ISSUE	-
DMS_16223	22244	N	N	N	1	CUSTOMER ISSUE	-
DMS_16224	22245	N	N	N	1	CUSTOMER ISSUE	-
DMS_16225	22246	N	N	N	1	CUSTOMER ISSUE	-
DMS_16226	22247	N	N	N	1	CUSTOMER ISSUE	-
DMS_16227	22248	N	N	N	1	CUSTOMER ISSUE	-
DMS_16228	22249	N	N	N	1	CUSTOMER ISSUE	-
DMS_16229	22250	N	N	N	2	CUSTOMER ISSUE	-
DMS_16230	22251	N	N	N	1	CUSTOMER ISSUE	-
DMS_16231	22252	N	N	N	1	CUSTOMER ISSUE	-
DMS_16232	22253	N	N	N	1	CUSTOMER ISSUE	-
DMS_16233	22254	N	N	N	1	CUSTOMER ISSUE	-
DMS_16234	22255	N	N	N	1	CUSTOMER ISSUE	-
DMS_16235	22256	N	N	N	1	CUSTOMER ISSUE	-
DMS_16236	22257	N	N	N	1	CUSTOMER ISSUE	-
DMS_16237	22258	N	N	N	1	CUSTOMER ISSUE	-
DMS_16238	22259	N	N	N	1	CUSTOMER ISSUE	-
DMS_16239	22260	N	N	N	1	CUSTOMER ISSUE	-
DMS_16240	22261	N	N	N	2	CUSTOMER ISSUE	-
DMS_16241	22262	N	N	N	1	CUSTOMER ISSUE	-
DMS_16242	22263	N	N	N	1	CUSTOMER ISSUE	-
DMS_16243	22264	N	N	N	1	CUSTOMER ISSUE	-
DMS_16244	22265	N	N	N	2	CUSTOMER ISSUE	-
DMS_16245	22266	N	N	N	1	CUSTOMER ISSUE	-
DMS_16246	22267	N	N	N	1	CUSTOMER ISSUE	-
DMS_16247	22268	N	N	N	1	CUSTOMER ISSUE	-
DMS_16248	22269	N	N	N	1	CUSTOMER ISSUE	-
DMS_16249	22270	N	N	N	1	CUSTOMER ISSUE	-
DMS_16250	22271	N	N	N	1	CUSTOMER ISSUE	-
DMS_16251	22272	N	N	N	1	CUSTOMER ISSUE	-
DMS_16252	22273	N	N	N	1	CUSTOMER ISSUE	-
DMS_16253	22274	N	N	N	1	CUSTOMER ISSUE	-
DMS_16254	22275	N	N	N	1	CUSTOMER ISSUE	-
DMS_16255	22276	N	N	N	1	CUSTOMER ISSUE	-
DMS_16256	22277	N	N	N	1	CUSTOMER ISSUE	-
DMS_16257	22278	N	N	N	1	CUSTOMER ISSUE	-
DMS_16258	22279	N	N	N	1	CUSTOMER ISSUE	-
DMS_16259	22280	N	N	N	1	CUSTOMER ISSUE	-
DMS_16260	22281	N	N	N	1	CUSTOMER ISSUE	-
DMS_16261	22282	N	N	N	1	CUSTOMER ISSUE	-
DMS_16262	22283	N	N	N	1	CUSTOMER ISSUE	-
DMS_16263	22284	N	N	N	1	CUSTOMER ISSUE	-
DMS_16264	22285	N	N	N	1	CUSTOMER ISSUE	-
DMS_16265	22286	N	N	N	1	CUSTOMER ISSUE	-
DMS_16266	22287	N	N	N	1	CUSTOMER ISSUE	-
DMS_16267	22288	N	N	N	1	CUSTOMER ISSUE	-
DMS_16268	22289	N	N	N	1	CUSTOMER ISSUE	-
DMS_16269	22290	N	N	N	1	CUSTOMER ISSUE	-
DMS_16270	22291	N	N	N	1	CUSTOMER ISSUE	-
DMS_16271	22292	N	N	N	1	CUSTOMER ISSUE	-
DMS_16272	22293	N	N	N	1	CUSTOMER ISSUE	-
DMS_16273	22294	N	N	N	1	CUSTOMER ISSUE	-
DMS_16274	22295	N	N	N	1	CUSTOMER ISSUE	-
DMS_16275	22296	N	N	N	1	CUSTOMER ISSUE	-

DMS_16276	22297	N	N	N	1	CUSTOMER ISSUE	-
DMS_16277	22298	N	N	N	1	CUSTOMER ISSUE	-
DMS_16278	22299	N	N	N	1	CUSTOMER ISSUE	-
DMS_16279	22300	N	N	N	1	CUSTOMER ISSUE	-
DMS_16280	22301	N	N	N	1	CUSTOMER ISSUE	-
DMS_16281	22302	N	N	N	1	CUSTOMER ISSUE	-
DMS_16282	22303	N	N	N	1	CUSTOMER ISSUE	-
DMS_16283	22304	N	N	N	1	CUSTOMER ISSUE	-
DMS_16284	22305	N	N	N	1	CUSTOMER ISSUE	-
DMS_16285	22306	N	N	N	1	CUSTOMER ISSUE	-
DMS_16286	22307	N	N	N	1	CUSTOMER ISSUE	-
DMS_16287	22308	N	N	N	1	CUSTOMER ISSUE	-
DMS_16288	22309	N	N	N	1	CUSTOMER ISSUE	-
DMS_16290	22310	N	N	N	1	CUSTOMER ISSUE	-
DMS_16291	22311	N	N	N	1	CUSTOMER ISSUE	-
DMS_16292	22312	N	N	N	1	CUSTOMER ISSUE	-
DMS_16293	22313	N	N	N	1	CUSTOMER ISSUE	-
DMS_16295	22314	N	N	N	1	CUSTOMER ISSUE	-
DMS_16296	22315	N	N	N	1	CUSTOMER ISSUE	-
DMS_16297	22316	N	N	N	1	CUSTOMER ISSUE	-
DMS_16298	22317	N	N	N	1	CUSTOMER ISSUE	-
DMS_16299	22318	N	N	N	1	CUSTOMER ISSUE	-
DMS_16300	22319	N	N	N	1	CUSTOMER ISSUE	-
DMS_16301	22320	N	N	N	1	CUSTOMER ISSUE	-
DMS_16302	22321	N	N	N	1	CUSTOMER ISSUE	-
DMS_16303	22322	N	N	N	1	CUSTOMER ISSUE	-
DMS_16304	22323	N	N	N	1	CUSTOMER ISSUE	-
DMS_16305	22324	N	N	N	1	CUSTOMER ISSUE	-
DMS_16306	22325	N	N	N	1	CUSTOMER ISSUE	-
DMS_16307	22326	N	N	N	1	CUSTOMER ISSUE	-
DMS_16308	22327	N	N	N	1	CUSTOMER ISSUE	-
DMS_16309	22328	N	N	N	1	CUSTOMER ISSUE	-
DMS_16310	22329	N	N	N	1	CUSTOMER ISSUE	-
DMS_16311	22330	N	N	N	1	CUSTOMER ISSUE	-
DMS_16312	22331	N	N	N	1	CUSTOMER ISSUE	-
DMS_16313	22332	N	N	N	1	CUSTOMER ISSUE	-
DMS_16314	22333	N	N	N	1	CUSTOMER ISSUE	-
DMS_16315	22334	N	N	N	1	CUSTOMER ISSUE	-
DMS_16316	22335	N	N	N	1	CUSTOMER ISSUE	-
DMS_16317	22336	N	N	N	1	CUSTOMER ISSUE	-
DMS_16318	22337	N	N	N	1	CUSTOMER ISSUE	-
DMS_16319	22338	N	N	N	1	CUSTOMER ISSUE	-
DMS_16320	22339	N	N	N	1	CUSTOMER ISSUE	-
DMS_16321	22340	N	N	N	1	CUSTOMER ISSUE	-
DMS_16322	22341	N	N	N	1	CUSTOMER ISSUE	-
DMS_16323	22342	N	N	N	1	CUSTOMER ISSUE	-
DMS_16324	22343	N	N	N	1	CUSTOMER ISSUE	-
DMS_16325	22344	N	N	N	1	CUSTOMER ISSUE	-
DMS_16326	22345	N	N	N	1	CUSTOMER ISSUE	-
DMS_16327	22346	N	N	N	1	CUSTOMER ISSUE	-
DMS_16328	22347	N	N	N	1	CUSTOMER ISSUE	-
DMS_16329	22348	N	N	N	1	CUSTOMER ISSUE	-
DMS_16330	22349	N	N	N	1	CUSTOMER ISSUE	-
DMS_16331	22350	N	N	N	1	CUSTOMER ISSUE	-
DMS_16332	22351	N	N	N	1	CUSTOMER ISSUE	-
DMS_16333	22352	N	N	N	1	CUSTOMER ISSUE	-
DMS_16334	22353	N	N	N	1	CUSTOMER ISSUE	-
DMS_16335	22354	N	N	N	1	CUSTOMER ISSUE	-
DMS_16336	22355	N	N	N	1	CUSTOMER ISSUE	-
DMS_16337	22356	N	N	N	1	CUSTOMER ISSUE	-
DMS_16338	22357	N	N	N	1	CUSTOMER ISSUE	-
DMS_16339	22358	N	N	N	1	CUSTOMER ISSUE	-
DMS_16340	22359	N	N	N	1	CUSTOMER ISSUE	-
DMS_16341	22360	N	N	N	1	CUSTOMER ISSUE	-
DMS_16342	22361	N	N	N	1	CUSTOMER ISSUE	-
DMS_16343	22362	N	N	N	1	CUSTOMER ISSUE	-
DMS_16344	22363	N	N	N	1	CUSTOMER ISSUE	-
DMS_16345	22364	N	N	N	1	CUSTOMER ISSUE	-
DMS_16346	22365	N	N	N	1	CUSTOMER ISSUE	-
DMS_16347	22366	N	N	N	1	CUSTOMER ISSUE	-
DMS_16348	22367	N	N	N	1	CUSTOMER ISSUE	-
DMS_16349	22368	N	N	N	1	CUSTOMER ISSUE	-
DMS_16350	22369	N	N	N	1	CUSTOMER ISSUE	-
DMS_16351	22370	N	N	N	1	CUSTOMER ISSUE	-
DMS_16352	22371	N	N	N	1	CUSTOMER ISSUE	-
DMS_16353	22372	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_16354	22373	N	N	N	1	CUSTOMER ISSUE	-
DMS_16355	22374	N	N	N	1	CUSTOMER ISSUE	-
DMS_16356	22375	N	N	N	1	CUSTOMER ISSUE	-
DMS_16357	22376	N	N	N	1	CUSTOMER ISSUE	-

DMS_16358	22377	N	N	N	1	CUSTOMER ISSUE	-
DMS_16359	22378	N	N	N	1	CUSTOMER ISSUE	-
DMS_16360	22379	N	N	N	1	CUSTOMER ISSUE	-
DMS_16361	22380	N	N	N	1	CUSTOMER ISSUE	-
DMS_16364	22381	N	N	N	1	CUSTOMER ISSUE	-
DMS_16365	22382	N	N	N	1	CUSTOMER ISSUE	-
DMS_16366	22383	N	N	N	1	CUSTOMER ISSUE	-
DMS_16367	22384	N	N	N	1	CUSTOMER ISSUE	-
DMS_16368	22385	N	N	N	1	CUSTOMER ISSUE	-
DMS_16369	22386	N	N	N	1	CUSTOMER ISSUE	-
DMS_16370	22387	N	N	N	1	CUSTOMER ISSUE	-
DMS_16371	22388	N	N	N	1	CUSTOMER ISSUE	-
DMS_16372	22389	N	N	N	1	CUSTOMER ISSUE	-
DMS_16373	22390	N	N	N	1	CUSTOMER ISSUE	-
DMS_16374	22391	N	N	N	1	CUSTOMER ISSUE	-
DMS_16375	22392	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_16376	22393	N	N	N	1	CUSTOMER ISSUE	-
DMS_16377	22394	N	N	N	1	CUSTOMER ISSUE	-
DMS_16378	22395	N	N	N	1	CUSTOMER ISSUE	-
DMS_16379	22396	N	N	N	1	CUSTOMER ISSUE	-
DMS_16380	22397	N	N	N	1	CUSTOMER ISSUE	-
DMS_16381	22398	N	N	N	1	CUSTOMER ISSUE	-
DMS_16382	22399	N	N	N	1	CUSTOMER ISSUE	-
DMS_16383	22400	N	N	N	1	CUSTOMER ISSUE	-
DMS_16384	22401	N	N	N	1	CUSTOMER ISSUE	-
DMS_16385	22402	N	N	N	1	CUSTOMER ISSUE	-
DMS_16386	22403	N	N	N	1	CUSTOMER ISSUE	-
DMS_16387	22404	N	N	N	1	CUSTOMER ISSUE	-
DMS_16388	22405	N	N	N	1	CUSTOMER ISSUE	-
DMS_16389	22406	N	N	N	1	CUSTOMER ISSUE	-
DMS_16390	22407	N	N	N	1	CUSTOMER ISSUE	-
DMS_16391	22408	N	N	N	1	CUSTOMER ISSUE	-
DMS_16392	22409	N	N	N	1	CUSTOMER ISSUE	-
DMS_16393	22410	N	N	N	1	CUSTOMER ISSUE	-
DMS_16394	22411	N	N	N	1	CUSTOMER ISSUE	-
DMS_16395	22412	N	N	N	1	CUSTOMER ISSUE	-
DMS_16396	22413	N	N	N	1	CUSTOMER ISSUE	-
DMS_16397	22414	N	N	N	1	CUSTOMER ISSUE	-
DMS_16398	22415	N	N	N	1	CUSTOMER ISSUE	-
DMS_16399	22416	N	N	N	1	CUSTOMER ISSUE	-
DMS_16400	22417	N	N	N	1	CUSTOMER ISSUE	-
DMS_16402	22418	N	N	N	1	CUSTOMER ISSUE	-
DMS_16403	22419	N	N	N	1	CUSTOMER ISSUE	-
DMS_16405	22420	N	N	N	1	CUSTOMER ISSUE	-
DMS_16406	22421	N	N	N	1	CUSTOMER ISSUE	-
DMS_16407	22422	N	N	N	1	CUSTOMER ISSUE	-
DMS_16408	22423	N	N	N	1	CUSTOMER ISSUE	-
DMS_16409	22424	N	N	N	1	CUSTOMER ISSUE	-
DMS_16410	22425	N	N	N	1	CUSTOMER ISSUE	-
DMS_16411	22426	N	N	N	1	CUSTOMER ISSUE	-
DMS_16412	22427	N	N	N	1	CUSTOMER ISSUE	-
DMS_16413	22428	N	N	N	1	CUSTOMER ISSUE	-
DMS_16414	22429	N	N	N	1	CUSTOMER ISSUE	-
DMS_16416	22430	N	N	N	1	CUSTOMER ISSUE	-
DMS_16417	22431	N	N	N	1	CUSTOMER ISSUE	-
DMS_16418	22432	N	N	N	1	CUSTOMER ISSUE	-
DMS_16419	22433	N	N	N	1	CUSTOMER ISSUE	-
DMS_16420	22434	N	N	N	1	CUSTOMER ISSUE	-
DMS_16421	22435	N	N	N	1	CUSTOMER ISSUE	-
DMS_16422	22436	N	N	N	1	CUSTOMER ISSUE	-
DMS_16423	22437	N	N	N	1	CUSTOMER ISSUE	-
DMS_16424	22438	N	N	N	1	CUSTOMER ISSUE	-
DMS_16426	22439	N	N	N	1	CUSTOMER ISSUE	-
DMS_16427	22440	N	N	N	1	CUSTOMER ISSUE	-
DMS_16428	22441	N	N	N	1	CUSTOMER ISSUE	-
DMS_16429	22442	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_16430	22443	N	N	N	1	CUSTOMER ISSUE	-
DMS_16431	22444	N	N	N	1	CUSTOMER ISSUE	-
DMS_16432	22445	N	N	N	1	CUSTOMER ISSUE	-
DMS_16433	22446	N	N	N	1	CUSTOMER ISSUE	-
DMS_16434	22447	N	N	N	1	CUSTOMER ISSUE	-
DMS_16435	22448	N	N	N	1	CUSTOMER ISSUE	-
DMS_16436	22449	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_16437	22450	N	N	N	1	CUSTOMER ISSUE	-
DMS_16438	22451	N	N	N	1	CUSTOMER ISSUE	-
DMS_16439	22452	N	N	N	1	CUSTOMER ISSUE	-
DMS_16440	22453	N	N	N	1	CUSTOMER ISSUE	-
DMS_16441	22454	N	N	N	1	CUSTOMER ISSUE	-
DMS_16442	22455	N	N	N	1	CUSTOMER ISSUE	-
DMS_16443	22456	N	N	N	1	CUSTOMER ISSUE	-

DMS_16444	22457	N	N	N	1	CUSTOMER ISSUE	-
DMS_16445	22458	N	N	N	1	CUSTOMER ISSUE	-
DMS_16446	22459	N	N	N	1	CUSTOMER ISSUE	-
DMS_16447	22460	N	N	N	1	CUSTOMER ISSUE	-
DMS_16448	22461	N	N	N	1	CUSTOMER ISSUE	-
DMS_16449	22462	N	N	N	1	CUSTOMER ISSUE	-
DMS_16450	22463	N	N	N	1	CUSTOMER ISSUE	-
DMS_16451	22464	N	N	N	1	CUSTOMER ISSUE	-
DMS_16452	22465	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_16453	22466	N	N	N	1	CUSTOMER ISSUE	-
DMS_16454	22467	N	N	N	1	CUSTOMER ISSUE	-
DMS_16455	22468	N	N	N	1	CUSTOMER ISSUE	-
DMS_16456	22469	N	N	N	1	CUSTOMER ISSUE	-
DMS_16457	22470	N	N	N	1	CUSTOMER ISSUE	-
DMS_16458	22471	N	N	N	1	CUSTOMER ISSUE	-
DMS_16459	22472	N	N	N	1	CUSTOMER ISSUE	-
DMS_16460	22473	N	N	N	1	CUSTOMER ISSUE	-
DMS_16461	22474	N	N	N	1	CUSTOMER ISSUE	-
DMS_16462	22475	N	N	N	1	CUSTOMER ISSUE	-
DMS_16463	22476	N	N	N	1	CUSTOMER ISSUE	-
DMS_16464	22477	N	N	N	1	CUSTOMER ISSUE	-
DMS_16465	22478	N	N	N	1	CUSTOMER ISSUE	-
DMS_16466	22479	N	N	N	2	CUSTOMER ISSUE	-
DMS_16467	22480	N	N	N	1	CUSTOMER ISSUE	-
DMS_16468	22481	N	N	N	1	CUSTOMER ISSUE	-
DMS_16469	22482	N	N	N	1	CUSTOMER ISSUE	-
DMS_16470	22483	N	N	N	1	CUSTOMER ISSUE	-
DMS_16471	22484	N	N	N	1	CUSTOMER ISSUE	-
DMS_16472	22485	N	N	N	1	CUSTOMER ISSUE	-
DMS_16473	22486	N	N	N	1	CUSTOMER ISSUE	-
DMS_16474	22487	N	N	N	1	CUSTOMER ISSUE	-
DMS_16475	22488	N	N	N	1	CUSTOMER ISSUE	-
DMS_16476	22489	N	N	N	1	CUSTOMER ISSUE	-
DMS_16477	22490	N	N	N	1	CUSTOMER ISSUE	-
DMS_16478	22491	N	N	N	1	CUSTOMER ISSUE	-
DMS_16479	22492	N	N	N	1	CUSTOMER ISSUE	-
DMS_16480	22493	N	N	N	1	CUSTOMER ISSUE	-
DMS_16481	22494	N	N	N	1	CUSTOMER ISSUE	-
DMS_16482	22495	N	N	N	1	CUSTOMER ISSUE	-
DMS_16483	22496	N	N	N	1	CUSTOMER ISSUE	-
DMS_16484	22497	N	N	N	1	CUSTOMER ISSUE	-
DMS_16485	22498	N	N	N	1	CUSTOMER ISSUE	-
DMS_16486	22499	N	N	N	1	CUSTOMER ISSUE	-
DMS_16487	22500	N	N	N	1	CUSTOMER ISSUE	-
DMS_16488	22501	N	N	N	1	CUSTOMER ISSUE	-
DMS_16489	22502	N	N	N	1	CUSTOMER ISSUE	-
DMS_16490	22503	N	N	N	1	CUSTOMER ISSUE	-
DMS_16491	22504	N	N	N	1	CUSTOMER ISSUE	-
DMS_16492	22505	N	N	N	1	CUSTOMER ISSUE	-
DMS_16494	22506	N	N	N	1	CUSTOMER ISSUE	-
DMS_16495	22507	N	N	N	1	CUSTOMER ISSUE	-
DMS_16496	22508	N	N	N	1	CUSTOMER ISSUE	-
DMS_16497	22509	N	N	N	1	CUSTOMER ISSUE	-
DMS_16498	22510	N	N	N	1	CUSTOMER ISSUE	-
DMS_16499	22511	N	N	N	1	CUSTOMER ISSUE	-
DMS_16500	22512	N	N	N	1	CUSTOMER ISSUE	-
DMS_16501	22513	N	N	N	1	CUSTOMER ISSUE	-
DMS_16502	22514	N	N	N	1	CUSTOMER ISSUE	-
DMS_16504	22515	N	N	N	1	CUSTOMER ISSUE	-
DMS_16505	22516	N	N	N	1	CUSTOMER ISSUE	-
DMS_16506	22517	N	N	N	1	CUSTOMER ISSUE	-
DMS_16507	22518	N	N	N	1	CUSTOMER ISSUE	-
DMS_16508	22519	N	N	N	1	CUSTOMER ISSUE	-
DMS_16509	22520	N	N	N	1	CUSTOMER ISSUE	-
DMS_16510	22521	N	N	N	1	CUSTOMER ISSUE	-
DMS_16511	22522	N	N	N	1	CUSTOMER ISSUE	-
DMS_16512	22523	N	N	N	1	CUSTOMER ISSUE	-
DMS_16513	22524	N	N	N	1	CUSTOMER ISSUE	-
DMS_16514	22525	N	N	N	1	CUSTOMER ISSUE	-
DMS_16515	22526	N	N	N	1	CUSTOMER ISSUE	-
DMS_16516	22527	N	N	N	1	CUSTOMER ISSUE	-
DMS_16517	22528	N	N	N	1	CUSTOMER ISSUE	-
DMS_16518	22529	N	N	N	1	CUSTOMER ISSUE	-
DMS_16519	22530	N	N	N	1	CUSTOMER ISSUE	-
DMS_16520	22531	N	N	N	1	CUSTOMER ISSUE	-
DMS_16521	22532	N	N	N	1	CUSTOMER ISSUE	-
DMS_16522	22533	N	N	N	1	CUSTOMER ISSUE	-
DMS_16523	22534	N	N	N	1	CUSTOMER ISSUE	-
DMS_16524	22535	N	N	N	1	CUSTOMER ISSUE	-
DMS_16525	22536	N	N	N	1	CUSTOMER ISSUE	-

DMS_16526	22537	N	N	N	1	CUSTOMER ISSUE	-
DMS_16527	22538	N	N	N	1	CUSTOMER ISSUE	-
DMS_16528	22539	N	N	N	1	CUSTOMER ISSUE	-
DMS_16529	22540	N	N	N	1	CUSTOMER ISSUE	-
DMS_16530	22541	N	N	N	1	CUSTOMER ISSUE	-
DMS_16531	22542	N	N	N	1	CUSTOMER ISSUE	-
DMS_16532	22543	N	N	N	1	CUSTOMER ISSUE	-
DMS_16533	22544	N	N	N	1	CUSTOMER ISSUE	-
DMS_16534	22545	N	N	N	1	CUSTOMER ISSUE	-
DMS_16535	22546	N	N	N	1	CUSTOMER ISSUE	-
DMS_16536	22547	N	N	N	1	CUSTOMER ISSUE	-
DMS_16537	22548	N	N	N	1	CUSTOMER ISSUE	-
DMS_16538	22549	N	N	N	1	CUSTOMER ISSUE	-
DMS_16539	22550	N	N	N	1	CUSTOMER ISSUE	-
DMS_16540	22551	N	N	N	1	CUSTOMER ISSUE	-
DMS_16541	22552	N	N	N	1	CUSTOMER ISSUE	-
DMS_16542	22553	N	N	N	1	CUSTOMER ISSUE	-
DMS_16543	22554	N	N	N	1	CUSTOMER ISSUE	-
DMS_16544	22555	N	N	N	1	CUSTOMER ISSUE	-
DMS_16545	22556	N	N	N	1	CUSTOMER ISSUE	-
DMS_16546	22557	N	N	N	1	CUSTOMER ISSUE	-
DMS_16547	22558	N	N	N	1	CUSTOMER ISSUE	-
DMS_16548	22559	N	N	N	1	CUSTOMER ISSUE	-
DMS_16549	22560	N	N	N	1	CUSTOMER ISSUE	-
DMS_16550	22561	N	N	N	1	CUSTOMER ISSUE	-
DMS_16551	22562	N	N	N	1	CUSTOMER ISSUE	-
DMS_16552	22563	N	N	N	1	CUSTOMER ISSUE	-
DMS_16553	22564	N	N	N	1	CUSTOMER ISSUE	-
DMS_16554	22565	N	N	N	1	CUSTOMER ISSUE	-
DMS_16555	22566	N	N	N	1	CUSTOMER ISSUE	-
DMS_16556	22567	N	N	N	1	CUSTOMER ISSUE	-
DMS_16557	22568	N	N	N	1	CUSTOMER ISSUE	-
DMS_16558	22569	N	N	N	1	CUSTOMER ISSUE	-
DMS_16559	22570	N	N	N	1	CUSTOMER ISSUE	-
DMS_16560	22571	N	N	N	1	CUSTOMER ISSUE	-
DMS_16561	22572	N	N	N	1	CUSTOMER ISSUE	-
DMS_16562	22573	N	N	N	1	CUSTOMER ISSUE	-
DMS_16563	22574	N	N	N	1	CUSTOMER ISSUE	-
DMS_16564	22575	N	N	N	1	CUSTOMER ISSUE	-
DMS_16565	22576	N	N	N	1	CUSTOMER ISSUE	-
DMS_16566	22577	N	N	N	1	CUSTOMER ISSUE	-
DMS_16567	22578	N	N	N	1	CUSTOMER ISSUE	-
DMS_16568	22579	N	N	N	1	CUSTOMER ISSUE	-
DMS_16569	22580	N	N	N	1	CUSTOMER ISSUE	-
DMS_16570	22581	N	N	N	1	CUSTOMER ISSUE	-
DMS_16571	22582	N	N	N	1	CUSTOMER ISSUE	-
DMS_16572	22583	N	N	N	1	CUSTOMER ISSUE	-
DMS_16573	22584	N	N	N	1	CUSTOMER ISSUE	-
DMS_16574	22585	N	N	N	1	CUSTOMER ISSUE	-
DMS_16575	22586	N	N	N	1	CUSTOMER ISSUE	-
DMS_16576	22587	N	N	N	1	CUSTOMER ISSUE	-
DMS_16577	22588	N	N	N	1	CUSTOMER ISSUE	-
DMS_16578	22589	N	N	N	1	CUSTOMER ISSUE	-
DMS_16579	22590	N	N	N	1	CUSTOMER ISSUE	-
DMS_16580	22591	N	N	N	1	CUSTOMER ISSUE	-
DMS_16581	22592	N	N	N	1	CUSTOMER ISSUE	-
DMS_16582	22593	N	N	N	1	CUSTOMER ISSUE	-
DMS_16583	22594	N	N	N	1	CUSTOMER ISSUE	-
DMS_16584	22595	N	N	N	1	CUSTOMER ISSUE	-
DMS_16585	22596	N	N	N	1	CUSTOMER ISSUE	-
DMS_16586	22597	N	N	N	1	CUSTOMER ISSUE	-
DMS_16587	22598	N	N	N	1	CUSTOMER ISSUE	-
DMS_16588	22599	N	N	N	1	CUSTOMER ISSUE	-
DMS_16589	22600	N	N	N	1	CUSTOMER ISSUE	-
DMS_16590	22601	N	N	N	1	CUSTOMER ISSUE	-
DMS_16591	22602	N	N	N	1	CUSTOMER ISSUE	-
DMS_16592	22603	N	N	N	1	CUSTOMER ISSUE	-
DMS_16593	22604	N	N	N	1	CUSTOMER ISSUE	-
DMS_16594	22605	N	N	N	1	CUSTOMER ISSUE	-
DMS_16595	22606	N	N	N	1	CUSTOMER ISSUE	-
DMS_16596	22607	N	N	N	1	CUSTOMER ISSUE	-
DMS_16597	22608	N	N	N	1	CUSTOMER ISSUE	-
DMS_16598	22609	N	N	N	1	CUSTOMER ISSUE	-
DMS_16599	22610	N	N	N	1	CUSTOMER ISSUE	-
DMS_16600	22611	N	N	N	1	CUSTOMER ISSUE	-
DMS_16601	22612	N	N	N	1	CUSTOMER ISSUE	-
DMS_16602	22613	N	N	N	1	CUSTOMER ISSUE	-
DMS_16603	22614	N	N	N	1	CUSTOMER ISSUE	-
DMS_16604	22615	N	N	N	1	CUSTOMER ISSUE	-
DMS_16605	22616	N	N	N	1	CUSTOMER ISSUE	-

DMS_16606	22617	N	N	N	1	CUSTOMER ISSUE	-
DMS_16607	22618	N	N	N	1	CUSTOMER ISSUE	-
DMS_16608	22619	N	N	N	1	CUSTOMER ISSUE	-
DMS_16609	22620	N	N	N	1	CUSTOMER ISSUE	-
DMS_16610	22621	N	N	N	1	CUSTOMER ISSUE	-
DMS_16611	22622	N	N	N	1	CUSTOMER ISSUE	-
DMS_16612	22623	N	N	N	1	CUSTOMER ISSUE	-
DMS_16613	22624	N	N	N	1	CUSTOMER ISSUE	-
DMS_16614	22625	N	N	N	1	CUSTOMER ISSUE	-
DMS_16615	22626	N	N	N	1	CUSTOMER ISSUE	-
DMS_16616	22627	N	N	N	1	CUSTOMER ISSUE	-
DMS_16617	22628	N	N	N	1	CUSTOMER ISSUE	-
DMS_16618	22629	N	N	N	1	CUSTOMER ISSUE	-
DMS_16619	22630	N	N	N	1	CUSTOMER ISSUE	-
DMS_16620	22631	N	N	N	1	CUSTOMER ISSUE	-
DMS_16621	22632	N	N	N	1	CUSTOMER ISSUE	-
DMS_16622	22633	N	N	N	1	CUSTOMER ISSUE	-
DMS_16623	22634	N	N	N	1	CUSTOMER ISSUE	-
DMS_16624	22635	N	N	N	1	CUSTOMER ISSUE	-
DMS_16625	22636	N	N	N	1	CUSTOMER ISSUE	-
DMS_16626	22637	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_16627	22638	N	N	N	1	CUSTOMER ISSUE	-
DMS_16628	22639	N	N	N	1	CUSTOMER ISSUE	-
DMS_16629	22640	N	N	N	1	CUSTOMER ISSUE	-
DMS_16630	22641	N	N	N	1	CUSTOMER ISSUE	-
DMS_16631	22642	N	N	N	1	CUSTOMER ISSUE	-
DMS_16632	22643	N	N	N	1	CUSTOMER ISSUE	-
DMS_16633	22644	N	N	N	1	CUSTOMER ISSUE	-
DMS_16634	22645	N	N	N	1	CUSTOMER ISSUE	-
DMS_16635	22646	N	N	N	1	CUSTOMER ISSUE	-
DMS_16636	22647	N	N	N	1	CUSTOMER ISSUE	-
DMS_16637	22648	N	N	N	1	CUSTOMER ISSUE	-
DMS_16638	22649	N	N	N	1	CUSTOMER ISSUE	-
DMS_16639	22650	N	N	N	1	CUSTOMER ISSUE	-
DMS_16640	22651	N	N	N	1	CUSTOMER ISSUE	-
DMS_16641	22652	N	N	N	1	CUSTOMER ISSUE	-
DMS_16642	22653	N	N	N	1	CUSTOMER ISSUE	-
DMS_16643	22654	N	N	N	1	CUSTOMER ISSUE	-
DMS_16644	22655	N	N	N	1	CUSTOMER ISSUE	-
DMS_16645	22656	N	N	N	1	CUSTOMER ISSUE	-
DMS_16646	22657	N	N	N	1	CUSTOMER ISSUE	-
DMS_16647	22658	N	N	N	1	CUSTOMER ISSUE	-
DMS_16648	22659	N	N	N	1	CUSTOMER ISSUE	-
DMS_16649	22660	N	N	N	1	CUSTOMER ISSUE	-
DMS_16650	22661	N	N	N	1	CUSTOMER ISSUE	-
DMS_16651	22662	N	N	N	1	CUSTOMER ISSUE	-
DMS_16652	22663	N	N	N	1	CUSTOMER ISSUE	-
DMS_16653	22664	N	N	N	1	CUSTOMER ISSUE	-
DMS_16654	22665	N	N	N	1	CUSTOMER ISSUE	-
DMS_16655	22666	N	N	N	1	CUSTOMER ISSUE	-
DMS_16656	22667	N	N	N	1	CUSTOMER ISSUE	-
DMS_16657	22668	N	N	N	1	CUSTOMER ISSUE	-
DMS_16658	22669	N	N	N	1	CUSTOMER ISSUE	-
DMS_16659	22670	N	N	N	1	CUSTOMER ISSUE	-
DMS_16660	22671	N	N	N	1	CUSTOMER ISSUE	-
DMS_16661	22672	N	N	N	1	CUSTOMER ISSUE	-
DMS_16662	22673	N	N	N	1	CUSTOMER ISSUE	-
DMS_16663	22674	N	N	N	1	CUSTOMER ISSUE	-
DMS_16664	22675	N	N	N	1	CUSTOMER ISSUE	-
DMS_16665	22676	N	N	N	1	CUSTOMER ISSUE	-
DMS_16666	22677	N	N	N	1	CUSTOMER ISSUE	-
DMS_16667	22678	N	N	N	1	CUSTOMER ISSUE	-
DMS_16668	22679	N	N	N	1	CUSTOMER ISSUE	-
DMS_16669	22680	N	N	N	1	CUSTOMER ISSUE	-
DMS_16670	22681	N	N	N	1	CUSTOMER ISSUE	-
DMS_16671	22682	N	N	N	1	CUSTOMER ISSUE	-
DMS_16672	22683	N	N	N	1	CUSTOMER ISSUE	-
DMS_16673	22684	N	N	N	1	CUSTOMER ISSUE	-
DMS_16674	22685	N	N	N	1	CUSTOMER ISSUE	-
DMS_16675	22686	N	N	N	1	CUSTOMER ISSUE	-
DMS_16676	22687	N	N	N	1	CUSTOMER ISSUE	-
DMS_16677	22688	N	N	N	1	CUSTOMER ISSUE	-
DMS_16678	22689	N	N	N	1	CUSTOMER ISSUE	-
DMS_16679	22690	N	N	N	1	CUSTOMER ISSUE	-
DMS_16680	22691	N	N	N	1	CUSTOMER ISSUE	-
DMS_16681	22692	N	N	N	1	CUSTOMER ISSUE	-
DMS_16682	22693	N	N	N	1	CUSTOMER ISSUE	-
DMS_16683	22694	N	N	N	1	CUSTOMER ISSUE	-
DMS_16684	22695	N	N	N	1	CUSTOMER ISSUE	-
DMS_16685	22696	N	N	N	1	CUSTOMER ISSUE	-

DMS_16686	22697	N	N	N	1	CUSTOMER ISSUE	-
DMS_16687	22698	N	N	N	1	CUSTOMER ISSUE	-
DMS_16688	22699	N	N	N	1	CUSTOMER ISSUE	-
DMS_16689	22700	N	N	N	1	CUSTOMER ISSUE	-
DMS_16690	22701	N	N	N	1	CUSTOMER ISSUE	-
DMS_16691	22702	N	N	N	1	CUSTOMER ISSUE	-
DMS_16692	22703	N	N	N	1	CUSTOMER ISSUE	-
DMS_16693	22704	N	N	N	1	CUSTOMER ISSUE	-
DMS_16694	22705	N	N	N	1	CUSTOMER ISSUE	-
DMS_16695	22706	N	N	N	1	CUSTOMER ISSUE	-
DMS_16696	22707	N	N	N	1	CUSTOMER ISSUE	-
DMS_16697	22708	N	N	N	1	CUSTOMER ISSUE	-
DMS_16698	22709	N	N	N	1	CUSTOMER ISSUE	-
DMS_16699	22710	N	N	N	1	CUSTOMER ISSUE	-
DMS_16700	22711	N	N	N	1	CUSTOMER ISSUE	-
DMS_16701	22712	N	N	N	1	CUSTOMER ISSUE	-
DMS_16702	22713	N	N	N	3	CUSTOMER ISSUE	-
DMS_16703	22714	N	N	N	1	CUSTOMER ISSUE	-
DMS_16704	22715	N	N	N	1	CUSTOMER ISSUE	-
DMS_16705	22716	N	N	N	1	CUSTOMER ISSUE	-
DMS_16706	22717	N	N	N	1	CUSTOMER ISSUE	-
DMS_16707	22718	N	N	N	1	CUSTOMER ISSUE	-
DMS_16708	22719	N	N	N	1	CUSTOMER ISSUE	-
DMS_16709	22720	N	N	N	1	CUSTOMER ISSUE	-
DMS_16711	22721	N	N	N	1	CUSTOMER ISSUE	-
DMS_16712	22722	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_16713	22723	N	N	N	1	CUSTOMER ISSUE	-
DMS_16714	22724	N	N	N	1	CUSTOMER ISSUE	-
DMS_16715	22725	N	N	N	1	CUSTOMER ISSUE	-
DMS_16716	22726	N	N	N	1	CUSTOMER ISSUE	-
DMS_16717	22727	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_16718	22728	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_16719	22729	N	N	N	1	CUSTOMER ISSUE	-
DMS_16720	22730	N	N	N	1	CUSTOMER ISSUE	-
DMS_16721	22731	N	N	N	1	CUSTOMER ISSUE	-
DMS_16722	22732	N	N	N	1	CUSTOMER ISSUE	-
DMS_16724	22733	N	N	N	1	CUSTOMER ISSUE	-
DMS_16725	22734	N	N	N	1	CUSTOMER ISSUE	-
DMS_16731	22735	N	N	N	1	CUSTOMER ISSUE	-
DMS_16732	22736	N	N	N	1	CUSTOMER ISSUE	-
DMS_16733	22737	N	N	N	1	CUSTOMER ISSUE	-
DMS_16734	22738	N	N	N	1	CUSTOMER ISSUE	-
DMS_16735	22739	N	N	N	1	CUSTOMER ISSUE	-
DMS_16736	22740	N	N	N	1	CUSTOMER ISSUE	-
DMS_16737	22741	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_16738	22742	N	N	N	1	CUSTOMER ISSUE	-
DMS_16739	22743	N	N	N	1	CUSTOMER ISSUE	-
DMS_16740	22744	N	N	N	1	CUSTOMER ISSUE	-
DMS_16741	22745	N	N	N	1	CUSTOMER ISSUE	-
DMS_16742	22746	N	N	N	1	CUSTOMER ISSUE	-
DMS_16743	22747	N	N	N	1	CUSTOMER ISSUE	-
DMS_16744	22748	N	N	N	1	CUSTOMER ISSUE	-
DMS_16745	22749	N	N	N	1	CUSTOMER ISSUE	-
DMS_16746	22750	N	N	N	1	CUSTOMER ISSUE	-
DMS_16747	22751	N	N	N	1	CUSTOMER ISSUE	-
DMS_16748	22752	N	N	N	1	CUSTOMER ISSUE	-
DMS_16749	22753	N	N	N	1	CUSTOMER ISSUE	-
DMS_16750	22754	N	N	N	1	CUSTOMER ISSUE	-
DMS_16751	22755	N	N	N	1	CUSTOMER ISSUE	-
DMS_16752	22756	N	N	N	1	CUSTOMER ISSUE	-
DMS_16753	22757	N	N	N	1	CUSTOMER ISSUE	-
DMS_16754	22758	N	N	N	1	CUSTOMER ISSUE	-
DMS_16755	22759	N	N	N	1	CUSTOMER ISSUE	-
DMS_16756	22760	N	N	N	1	CUSTOMER ISSUE	-
DMS_16758	22761	N	N	N	1	CUSTOMER ISSUE	-
DMS_16759	22762	N	N	N	1	CUSTOMER ISSUE	-
DMS_16760	22763	N	N	N	1	CUSTOMER ISSUE	-
DMS_16761	22764	N	N	N	1	CUSTOMER ISSUE	-
DMS_16762	22765	N	N	N	1	CUSTOMER ISSUE	-
DMS_16763	22766	N	N	N	1	CUSTOMER ISSUE	-
DMS_16764	22767	N	N	N	1	CUSTOMER ISSUE	-
DMS_16765	22768	N	N	N	1	CUSTOMER ISSUE	-
DMS_16766	22769	N	N	N	1	CUSTOMER ISSUE	-
DMS_16767	22770	N	N	N	1	CUSTOMER ISSUE	-
DMS_16768	22771	N	N	N	1	CUSTOMER ISSUE	-
DMS_16769	22772	N	N	N	1	CUSTOMER ISSUE	-
DMS_16770	22773	N	N	N	1	CUSTOMER ISSUE	-
DMS_16771	22774	N	N	N	1	CUSTOMER ISSUE	-
DMS_16772	22775	N	N	N	1	CUSTOMER ISSUE	-
DMS_16773	22776	N	N	N	1	CUSTOMER ISSUE	-

DMS_16775	22777	N	N	N	1	CUSTOMER ISSUE	-
DMS_16776	22778	N	N	N	1	CUSTOMER ISSUE	-
DMS_16777	22779	N	N	N	1	CUSTOMER ISSUE	-
DMS_16778	22780	N	N	N	1	CUSTOMER ISSUE	-
DMS_16779	22781	N	N	N	1	CUSTOMER ISSUE	-
DMS_16780	22782	N	N	N	1	CUSTOMER ISSUE	-
DMS_16781	22783	N	N	N	1	CUSTOMER ISSUE	-
DMS_16782	22784	N	N	N	1	CUSTOMER ISSUE	-
DMS_16783	22785	N	N	N	1	CUSTOMER ISSUE	-
DMS_16784	22786	N	N	N	1	CUSTOMER ISSUE	-
DMS_16785	22787	N	N	N	1	CUSTOMER ISSUE	-
DMS_16786	22788	N	N	N	1	CUSTOMER ISSUE	-
DMS_16787	22789	N	N	N	1	CUSTOMER ISSUE	-
DMS_16788	22790	N	N	N	1	CUSTOMER ISSUE	-
DMS_16789	22791	N	N	N	1	CUSTOMER ISSUE	-
DMS_16790	22792	N	N	N	1	CUSTOMER ISSUE	-
DMS_16791	22793	N	N	N	1	CUSTOMER ISSUE	-
DMS_16792	22794	N	N	N	1	CUSTOMER ISSUE	-
DMS_16793	22795	N	N	N	1	CUSTOMER ISSUE	-
DMS_16794	22796	N	N	N	1	CUSTOMER ISSUE	-
DMS_16795	22797	N	N	N	1	CUSTOMER ISSUE	-
DMS_16796	22798	N	N	N	1	CUSTOMER ISSUE	-
DMS_16797	22799	N	N	N	1	CUSTOMER ISSUE	-
DMS_16798	22800	N	N	N	1	CUSTOMER ISSUE	-
DMS_16799	22801	N	N	N	1	CUSTOMER ISSUE	-
DMS_16800	22802	N	N	N	1	CUSTOMER ISSUE	-
DMS_16801	22803	N	N	N	1	CUSTOMER ISSUE	-
DMS_16802	22804	N	N	N	1	CUSTOMER ISSUE	-
DMS_16803	22805	N	N	N	1	CUSTOMER ISSUE	-
DMS_16804	22806	N	N	N	1	CUSTOMER ISSUE	-
DMS_16805	22807	N	N	N	1	CUSTOMER ISSUE	-
DMS_16806	22808	N	N	N	1	CUSTOMER ISSUE	-
DMS_16807	22809	N	N	N	1	CUSTOMER ISSUE	-
DMS_16808	22810	N	N	N	1	CUSTOMER ISSUE	-
DMS_16809	22811	N	N	N	1	CUSTOMER ISSUE	-
DMS_16810	22812	N	N	N	1	CUSTOMER ISSUE	-
DMS_16811	22813	N	N	N	1	CUSTOMER ISSUE	-
DMS_16812	22814	N	N	N	1	CUSTOMER ISSUE	-
DMS_16813	22815	N	N	N	1	CUSTOMER ISSUE	-
DMS_16814	22816	N	N	N	1	CUSTOMER ISSUE	-
DMS_16815	22817	N	N	N	1	CUSTOMER ISSUE	-
DMS_16816	22818	N	N	N	1	CUSTOMER ISSUE	-
DMS_16817	22819	N	N	N	1	CUSTOMER ISSUE	-
DMS_16818	22820	N	N	N	1	CUSTOMER ISSUE	-
DMS_16819	22821	N	N	N	1	CUSTOMER ISSUE	-
DMS_16820	22822	N	N	N	1	CUSTOMER ISSUE	-
DMS_16821	22823	N	N	N	1	CUSTOMER ISSUE	-
DMS_16822	22824	N	N	N	1	CUSTOMER ISSUE	-
DMS_16823	22825	N	N	N	1	CUSTOMER ISSUE	-
DMS_16824	22826	N	N	N	1	CUSTOMER ISSUE	-
DMS_16825	22827	N	N	N	1	CUSTOMER ISSUE	-
DMS_16826	22828	N	N	N	1	CUSTOMER ISSUE	-
DMS_16827	22829	N	N	N	1	CUSTOMER ISSUE	-
DMS_16828	22830	N	N	N	1	CUSTOMER ISSUE	-
DMS_16829	22831	N	N	N	1	CUSTOMER ISSUE	-
DMS_16830	22832	N	N	N	1	CUSTOMER ISSUE	-
DMS_16831	22833	N	N	N	1	CUSTOMER ISSUE	-
DMS_16832	22834	N	N	N	1	CUSTOMER ISSUE	-
DMS_16833	22835	N	N	N	1	CUSTOMER ISSUE	-
DMS_16834	22836	N	N	N	1	CUSTOMER ISSUE	-
DMS_16835	22837	N	N	N	1	CUSTOMER ISSUE	-
DMS_16836	22838	N	N	N	1	CUSTOMER ISSUE	-
DMS_16837	22839	N	N	N	1	CUSTOMER ISSUE	-
DMS_16838	22840	N	N	N	1	CUSTOMER ISSUE	-
DMS_16839	22841	N	N	N	1	CUSTOMER ISSUE	-
DMS_16840	22842	N	N	N	1	CUSTOMER ISSUE	-
DMS_16841	22843	N	N	N	1	CUSTOMER ISSUE	-
DMS_16842	22844	N	N	N	1	CUSTOMER ISSUE	-
DMS_16843	22845	N	N	N	1	CUSTOMER ISSUE	-
DMS_16844	22846	N	N	N	1	CUSTOMER ISSUE	-
DMS_16845	22847	N	N	N	1	CUSTOMER ISSUE	-
DMS_16846	22848	N	N	N	1	CUSTOMER ISSUE	-
DMS_16847	22849	N	N	N	1	CUSTOMER ISSUE	-
DMS_16848	22850	N	N	N	1	CUSTOMER ISSUE	-
DMS_16849	22851	N	N	N	1	CUSTOMER ISSUE	-
DMS_16850	22852	N	N	N	1	CUSTOMER ISSUE	-
DMS_16851	22853	N	N	N	1	CUSTOMER ISSUE	-
DMS_16852	22854	N	N	N	1	CUSTOMER ISSUE	-
DMS_16853	22855	N	N	N	1	CUSTOMER ISSUE	-
DMS_16854	22856	N	N	N	1	CUSTOMER ISSUE	-

DMS_16855	22857	N	N	N	1	CUSTOMER ISSUE	-
DMS_16856	22858	N	N	N	1	CUSTOMER ISSUE	-
DMS_16857	22859	N	N	N	1	CUSTOMER ISSUE	-
DMS_16858	22860	N	N	N	1	CUSTOMER ISSUE	-
DMS_16859	22861	N	N	N	1	CUSTOMER ISSUE	-
DMS_16860	22862	N	N	N	1	CUSTOMER ISSUE	-
DMS_16861	22863	N	N	N	1	CUSTOMER ISSUE	-
DMS_16862	22864	N	N	N	1	CUSTOMER ISSUE	-
DMS_16863	22865	N	N	N	1	CUSTOMER ISSUE	-
DMS_16864	22866	N	N	N	1	CUSTOMER ISSUE	-
DMS_16865	22867	N	N	N	1	CUSTOMER ISSUE	-
DMS_16866	22868	N	N	N	1	CUSTOMER ISSUE	-
DMS_16867	22869	N	N	N	1	CUSTOMER ISSUE	-
DMS_16868	22870	N	N	N	1	CUSTOMER ISSUE	-
DMS_16869	22871	N	N	N	1	CUSTOMER ISSUE	-
DMS_16870	22872	N	N	N	1	CUSTOMER ISSUE	-
DMS_16871	22873	N	N	N	1	CUSTOMER ISSUE	-
DMS_16872	22874	N	N	N	1	CUSTOMER ISSUE	-
DMS_16873	22875	N	N	N	1	CUSTOMER ISSUE	-
DMS_16874	22876	N	N	N	1	CUSTOMER ISSUE	-
DMS_16875	22877	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_16877	22878	N	N	N	1	CUSTOMER ISSUE	-
DMS_16878	22879	N	N	N	1	CUSTOMER ISSUE	-
DMS_16879	22880	N	N	N	1	CUSTOMER ISSUE	-
DMS_16880	22881	N	N	N	1	CUSTOMER ISSUE	-
DMS_16881	22882	N	N	N	1	CUSTOMER ISSUE	-
DMS_16882	22883	N	N	N	2	CUSTOMER ISSUE	-
DMS_16884	22884	N	N	N	1	CUSTOMER ISSUE	-
DMS_16885	22885	N	N	N	1	CUSTOMER ISSUE	-
DMS_16886	22886	N	N	N	1	CUSTOMER ISSUE	-
DMS_16887	22887	N	N	N	1	CUSTOMER ISSUE	-
DMS_16888	22888	N	N	N	1	CUSTOMER ISSUE	-
DMS_16889	22889	N	N	N	1	CUSTOMER ISSUE	-
DMS_16890	22890	N	N	N	1	CUSTOMER ISSUE	-
DMS_16891	22891	N	N	N	1	CUSTOMER ISSUE	-
DMS_16892	22892	N	N	N	1	CUSTOMER ISSUE	-
DMS_16893	22893	N	N	N	1	CUSTOMER ISSUE	-
DMS_16894	22894	N	N	N	1	CUSTOMER ISSUE	-
DMS_16895	22895	N	N	N	1	CUSTOMER ISSUE	-
DMS_16896	22896	N	N	N	1	CUSTOMER ISSUE	-
DMS_16897	22897	N	N	N	1	CUSTOMER ISSUE	-
DMS_16898	22898	N	N	N	1	CUSTOMER ISSUE	-
DMS_16899	22899	N	N	N	1	CUSTOMER ISSUE	-
DMS_16900	22900	N	N	N	1	CUSTOMER ISSUE	-
DMS_16901	22901	N	N	N	1	CUSTOMER ISSUE	-
DMS_16902	22902	N	N	N	1	CUSTOMER ISSUE	-
DMS_16903	22903	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_16904	22904	N	N	N	1	CUSTOMER ISSUE	-
DMS_16905	22905	N	N	N	1	CUSTOMER ISSUE	-
DMS_16906	22906	N	N	N	1	CUSTOMER ISSUE	-
DMS_16907	22907	N	N	N	1	CUSTOMER ISSUE	-
DMS_16908	22908	N	N	N	1	CUSTOMER ISSUE	-
DMS_16910	22909	N	N	N	1	CUSTOMER ISSUE	-
DMS_16911	22910	N	N	N	2	CUSTOMER ISSUE	-
DMS_16912	22911	N	N	N	1	CUSTOMER ISSUE	-
DMS_16913	22912	N	N	N	1	CUSTOMER ISSUE	-
DMS_16914	22913	N	N	N	1	CUSTOMER ISSUE	-
DMS_16916	22914	N	N	N	1	CUSTOMER ISSUE	-
DMS_16917	22915	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_16918	22916	N	N	N	1	CUSTOMER ISSUE	-
DMS_16919	22917	N	N	N	1	CUSTOMER ISSUE	-
DMS_16920	22918	N	N	N	1	CUSTOMER ISSUE	-
DMS_16921	22919	N	N	N	1	CUSTOMER ISSUE	-
DMS_16922	22920	N	N	N	1	CUSTOMER ISSUE	-
DMS_16923	22921	N	N	N	1	CUSTOMER ISSUE	-
DMS_16925	22922	N	N	N	1	CUSTOMER ISSUE	-
DMS_16926	22923	N	N	N	1	CUSTOMER ISSUE	-
DMS_16927	22924	N	N	N	1	CUSTOMER ISSUE	-
DMS_16928	22925	N	N	N	1	CUSTOMER ISSUE	-
DMS_16929	22926	N	N	N	1	CUSTOMER ISSUE	-
DMS_16930	22927	N	N	N	1	CUSTOMER ISSUE	-
DMS_16931	22928	N	N	N	1	CUSTOMER ISSUE	-
DMS_16932	22929	N	N	N	1	CUSTOMER ISSUE	-
DMS_16933	22930	N	N	N	1	CUSTOMER ISSUE	-
DMS_16934	22931	N	N	N	1	CUSTOMER ISSUE	-
DMS_16935	22932	N	N	N	1	CUSTOMER ISSUE	-
DMS_16936	22933	N	N	N	1	CUSTOMER ISSUE	-
DMS_16937	22934	N	N	N	1	CUSTOMER ISSUE	-
DMS_16938	22935	N	N	N	1	CUSTOMER ISSUE	-
DMS_16939	22936	N	N	N	1	CUSTOMER ISSUE	-

DMS_16940	22937	N	N	N	1	CUSTOMER ISSUE	-
DMS_16941	22938	N	N	N	1	CUSTOMER ISSUE	-
DMS_16942	22939	N	N	N	1	CUSTOMER ISSUE	-
DMS_16943	22940	N	N	N	1	CUSTOMER ISSUE	-
DMS_16944	22941	N	N	N	1	CUSTOMER ISSUE	-
DMS_16945	22942	N	N	N	1	CUSTOMER ISSUE	-
DMS_16946	22943	N	N	N	1	CUSTOMER ISSUE	-
DMS_16947	22944	N	N	N	1	CUSTOMER ISSUE	-
DMS_16948	22945	N	N	N	1	CUSTOMER ISSUE	-
DMS_16949	22946	N	N	N	1	CUSTOMER ISSUE	-
DMS_16950	22947	N	N	N	1	CUSTOMER ISSUE	-
DMS_16951	22948	N	N	N	1	CUSTOMER ISSUE	-
DMS_16952	22949	N	N	N	1	CUSTOMER ISSUE	-
DMS_16953	22950	N	N	N	1	CUSTOMER ISSUE	-
DMS_16954	22951	N	N	N	1	CUSTOMER ISSUE	-
DMS_16955	22952	N	N	N	1	CUSTOMER ISSUE	-
DMS_16956	22953	N	N	N	1	CUSTOMER ISSUE	-
DMS_16957	22954	N	N	N	1	CUSTOMER ISSUE	-
DMS_16958	22955	N	N	N	1	CUSTOMER ISSUE	-
DMS_16959	22956	N	N	N	1	CUSTOMER ISSUE	-
DMS_16960	22957	N	N	N	1	CUSTOMER ISSUE	-
DMS_16961	22958	N	N	N	1	CUSTOMER ISSUE	-
DMS_16962	22959	N	N	N	1	CUSTOMER ISSUE	-
DMS_16963	22960	N	N	N	1	CUSTOMER ISSUE	-
DMS_16964	22961	N	N	N	1	CUSTOMER ISSUE	-
DMS_16965	22962	N	N	N	1	CUSTOMER ISSUE	-
DMS_16966	22963	N	N	N	1	CUSTOMER ISSUE	-
DMS_16967	22964	N	N	N	1	CUSTOMER ISSUE	-
DMS_16968	22965	N	N	N	1	CUSTOMER ISSUE	-
DMS_16969	22966	N	N	N	1	CUSTOMER ISSUE	-
DMS_16970	22967	N	N	N	1	CUSTOMER ISSUE	-
DMS_16971	22968	N	N	N	1	CUSTOMER ISSUE	-
DMS_16972	22969	N	N	N	1	CUSTOMER ISSUE	-
DMS_16973	22970	N	N	N	1	CUSTOMER ISSUE	-
DMS_16974	22971	N	N	N	1	CUSTOMER ISSUE	-
DMS_16975	22972	N	N	N	1	CUSTOMER ISSUE	-
DMS_16976	22973	N	N	N	1	CUSTOMER ISSUE	-
DMS_16977	22974	N	N	N	1	CUSTOMER ISSUE	-
DMS_16978	22975	N	N	N	1	CUSTOMER ISSUE	-
DMS_16979	22976	N	N	N	1	CUSTOMER ISSUE	-
DMS_16980	22977	N	N	N	1	CUSTOMER ISSUE	-
DMS_16981	22978	N	N	N	1	CUSTOMER ISSUE	-
DMS_16982	22979	N	N	N	1	CUSTOMER ISSUE	-
DMS_16983	22980	N	N	N	1	CUSTOMER ISSUE	-
DMS_16984	22981	N	N	N	1	CUSTOMER ISSUE	-
DMS_16985	22982	N	N	N	1	CUSTOMER ISSUE	-
DMS_16986	22983	N	N	N	1	CUSTOMER ISSUE	-
DMS_16987	22984	N	N	N	1	CUSTOMER ISSUE	-
DMS_16988	22985	N	N	N	1	CUSTOMER ISSUE	-
DMS_16989	22986	N	N	N	1	CUSTOMER ISSUE	-
DMS_16990	22987	N	N	N	1	CUSTOMER ISSUE	-
DMS_16991	22988	N	N	N	1	CUSTOMER ISSUE	-
DMS_16992	22989	N	N	N	1	CUSTOMER ISSUE	-
DMS_16993	22990	N	N	N	1	CUSTOMER ISSUE	-
DMS_16994	22991	N	N	N	1	CUSTOMER ISSUE	-
DMS_16995	22992	N	N	N	1	CUSTOMER ISSUE	-
DMS_16996	22993	N	N	N	1	CUSTOMER ISSUE	-
DMS_16997	22994	N	N	N	1	CUSTOMER ISSUE	-
DMS_16998	22995	N	N	N	1	CUSTOMER ISSUE	-
DMS_16999	22996	N	N	N	1	CUSTOMER ISSUE	-
DMS_17000	22997	N	N	N	1	CUSTOMER ISSUE	-
DMS_17001	22998	N	N	N	1	CUSTOMER ISSUE	-
DMS_17002	22999	N	N	N	1	CUSTOMER ISSUE	-
DMS_17003	23000	N	N	N	1	CUSTOMER ISSUE	-
DMS_17004	23001	N	N	N	1	CUSTOMER ISSUE	-
DMS_17005	23002	N	N	N	1	CUSTOMER ISSUE	-
DMS_17006	23003	N	N	N	1	CUSTOMER ISSUE	-
DMS_17007	23004	N	N	N	1	CUSTOMER ISSUE	-
DMS_17008	23005	N	N	N	1	CUSTOMER ISSUE	-
DMS_17009	23006	N	N	N	1	CUSTOMER ISSUE	-
DMS_17010	23007	N	N	N	1	CUSTOMER ISSUE	-
DMS_17011	23008	N	N	N	1	CUSTOMER ISSUE	-
DMS_17012	23009	N	N	N	1	CUSTOMER ISSUE	-
DMS_17013	23010	N	N	N	1	CUSTOMER ISSUE	-
DMS_17014	23011	N	N	N	1	CUSTOMER ISSUE	-
DMS_17015	23012	N	N	N	1	CUSTOMER ISSUE	-
DMS_17016	23013	N	N	N	1	CUSTOMER ISSUE	-
DMS_17017	23014	N	N	N	1	CUSTOMER ISSUE	-
DMS_17018	23015	N	N	N	1	CUSTOMER ISSUE	-
DMS_17019	23016	N	N	N	1	CUSTOMER ISSUE	-

DMS_17020	23017	N	N	N	1	CUSTOMER ISSUE	-
DMS_17021	23018	N	N	N	1	CUSTOMER ISSUE	-
DMS_17022	23019	N	N	N	1	CUSTOMER ISSUE	-
DMS_17023	23020	N	N	N	1	CUSTOMER ISSUE	-
DMS_17024	23021	N	N	N	1	CUSTOMER ISSUE	-
DMS_17025	23022	N	N	N	1	CUSTOMER ISSUE	-
DMS_17026	23023	N	N	N	1	CUSTOMER ISSUE	-
DMS_17027	23024	N	N	N	1	CUSTOMER ISSUE	-
DMS_17028	23025	N	N	N	1	CUSTOMER ISSUE	-
DMS_17029	23026	N	N	N	1	CUSTOMER ISSUE	-
DMS_17030	23027	N	N	N	1	CUSTOMER ISSUE	-
DMS_17031	23028	N	N	N	1	CUSTOMER ISSUE	-
DMS_17032	23029	N	N	N	1	CUSTOMER ISSUE	-
DMS_17033	23030	N	N	N	1	CUSTOMER ISSUE	-
DMS_17034	23031	N	N	N	1	CUSTOMER ISSUE	-
DMS_17035	23032	N	N	N	1	CUSTOMER ISSUE	-
DMS_17036	23033	N	N	N	1	CUSTOMER ISSUE	-
DMS_17037	23034	N	N	N	1	CUSTOMER ISSUE	-
DMS_17038	23035	N	N	N	1	CUSTOMER ISSUE	-
DMS_17039	23036	N	N	N	1	CUSTOMER ISSUE	-
DMS_17040	23037	N	N	N	1	CUSTOMER ISSUE	-
DMS_17041	23038	N	N	N	1	CUSTOMER ISSUE	-
DMS_17042	23039	N	N	N	1	CUSTOMER ISSUE	-
DMS_17043	23040	N	N	N	1	CUSTOMER ISSUE	-
DMS_17044	23041	N	N	N	1	CUSTOMER ISSUE	-
DMS_17045	23042	N	N	N	1	CUSTOMER ISSUE	-
DMS_17046	23043	N	N	N	1	CUSTOMER ISSUE	-
DMS_17047	23044	N	N	N	1	CUSTOMER ISSUE	-
DMS_17048	23045	N	N	N	1	CUSTOMER ISSUE	-
DMS_17049	23046	N	N	N	1	CUSTOMER ISSUE	-
DMS_17050	23047	N	N	N	1	CUSTOMER ISSUE	-
DMS_17051	23048	N	N	N	1	CUSTOMER ISSUE	-
DMS_17052	23049	N	N	N	1	CUSTOMER ISSUE	-
DMS_17053	23050	N	N	N	1	CUSTOMER ISSUE	-
DMS_17054	23051	N	N	N	1	CUSTOMER ISSUE	-
DMS_17055	23052	N	N	N	1	CUSTOMER ISSUE	-
DMS_17056	23053	N	N	N	1	CUSTOMER ISSUE	-
DMS_17057	23054	N	N	N	1	CUSTOMER ISSUE	-
DMS_17058	23055	N	N	N	1	CUSTOMER ISSUE	-
DMS_17059	23056	N	N	N	1	CUSTOMER ISSUE	-
DMS_17060	23057	N	N	N	1	CUSTOMER ISSUE	-
DMS_17061	23058	N	N	N	1	CUSTOMER ISSUE	-
DMS_17062	23059	N	N	N	1	CUSTOMER ISSUE	-
DMS_17063	23060	N	N	N	1	CUSTOMER ISSUE	-
DMS_17064	23061	N	N	N	1	CUSTOMER ISSUE	-
DMS_17065	23062	N	N	N	1	CUSTOMER ISSUE	-
DMS_17066	23063	N	N	N	1	CUSTOMER ISSUE	-
DMS_17067	23064	N	N	N	1	CUSTOMER ISSUE	-
DMS_17068	23065	N	N	N	1	CUSTOMER ISSUE	-
DMS_17069	23066	N	N	N	1	CUSTOMER ISSUE	-
DMS_17070	23067	N	N	N	1	CUSTOMER ISSUE	-
DMS_17071	23068	N	N	N	1	CUSTOMER ISSUE	-
DMS_17072	23069	N	N	N	1	CUSTOMER ISSUE	-
DMS_17073	23070	N	N	N	1	CUSTOMER ISSUE	-
DMS_17074	23071	N	N	N	1	CUSTOMER ISSUE	-
DMS_17075	23072	N	N	N	1	CUSTOMER ISSUE	-
DMS_17076	23073	N	N	N	1	CUSTOMER ISSUE	-
DMS_17077	23074	N	N	N	1	CUSTOMER ISSUE	-
DMS_17078	23075	N	N	N	1	CUSTOMER ISSUE	-
DMS_17079	23076	N	N	N	1	CUSTOMER ISSUE	-
DMS_17080	23077	N	N	N	1	CUSTOMER ISSUE	-
DMS_17081	23078	N	N	N	1	CUSTOMER ISSUE	-
DMS_17082	23079	N	N	N	1	CUSTOMER ISSUE	-
DMS_17083	23080	N	N	N	1	CUSTOMER ISSUE	-
DMS_17084	23081	N	N	N	1	CUSTOMER ISSUE	-
DMS_17085	23082	N	N	N	1	CUSTOMER ISSUE	-
DMS_17086	23083	N	N	N	1	CUSTOMER ISSUE	-
DMS_17087	23084	N	N	N	1	CUSTOMER ISSUE	-
DMS_17088	23085	N	N	N	1	CUSTOMER ISSUE	-
DMS_17089	23086	N	N	N	1	CUSTOMER ISSUE	-
DMS_17090	23087	N	N	N	1	CUSTOMER ISSUE	-
DMS_17091	23088	N	N	N	1	CUSTOMER ISSUE	-
DMS_17092	23089	N	N	N	1	CUSTOMER ISSUE	-
DMS_17093	23090	N	N	N	1	CUSTOMER ISSUE	-
DMS_17095	23091	N	N	N	1	CUSTOMER ISSUE	-
DMS_17096	23092	N	N	N	1	CUSTOMER ISSUE	-
DMS_17097	23093	N	N	N	1	CUSTOMER ISSUE	-
DMS_17098	23094	N	N	N	1	CUSTOMER ISSUE	-
DMS_17099	23095	N	N	N	1	CUSTOMER ISSUE	-
DMS_17100	23096	N	N	N	1	CUSTOMER ISSUE	-

DMS_17101	23097	N	N	N	1	CUSTOMER ISSUE	-
DMS_17102	23098	N	N	N	1	CUSTOMER ISSUE	-
DMS_17103	23099	N	N	N	1	CUSTOMER ISSUE	-
DMS_17104	23100	N	N	N	1	CUSTOMER ISSUE	-
DMS_17105	23101	N	N	N	1	CUSTOMER ISSUE	-
DMS_17106	23102	N	N	N	1	CUSTOMER ISSUE	-
DMS_17107	23103	N	N	N	1	CUSTOMER ISSUE	-
DMS_17108	23104	N	N	N	1	CUSTOMER ISSUE	-
DMS_17109	23105	N	N	N	1	CUSTOMER ISSUE	-
DMS_17110	23106	N	N	N	1	CUSTOMER ISSUE	-
DMS_17111	23107	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17112	23108	N	N	N	1	CUSTOMER ISSUE	-
DMS_17113	23109	N	N	N	1	CUSTOMER ISSUE	-
DMS_17114	23110	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17115	23111	N	N	N	1	CUSTOMER ISSUE	-
DMS_17116	23112	N	N	N	1	CUSTOMER ISSUE	-
DMS_17117	23113	N	N	N	1	CUSTOMER ISSUE	-
DMS_17118	23114	N	N	N	1	CUSTOMER ISSUE	-
DMS_17119	23115	N	N	N	1	CUSTOMER ISSUE	-
DMS_17120	23116	N	N	N	1	CUSTOMER ISSUE	-
DMS_17121	23117	N	N	N	1	CUSTOMER ISSUE	-
DMS_17122	23118	N	N	N	1	CUSTOMER ISSUE	-
DMS_17123	23119	N	N	N	1	CUSTOMER ISSUE	-
DMS_17124	23120	N	N	N	1	CUSTOMER ISSUE	-
DMS_17125	23121	N	N	N	1	CUSTOMER ISSUE	-
DMS_17126	23122	N	N	N	1	CUSTOMER ISSUE	-
DMS_17127	23123	N	N	N	1	CUSTOMER ISSUE	-
DMS_17128	23124	N	N	N	1	CUSTOMER ISSUE	-
DMS_17129	23125	N	N	N	1	CUSTOMER ISSUE	-
DMS_17131	23126	N	N	N	1	CUSTOMER ISSUE	-
DMS_17132	23127	N	N	N	1	CUSTOMER ISSUE	-
DMS_17134	23128	N	N	N	1	CUSTOMER ISSUE	-
DMS_17135	23129	N	N	N	1	CUSTOMER ISSUE	-
DMS_17136	23130	N	N	N	1	CUSTOMER ISSUE	-
DMS_17137	23131	N	N	N	1	CUSTOMER ISSUE	-
DMS_17138	23132	N	N	N	1	CUSTOMER ISSUE	-
DMS_17139	23133	N	N	N	1	CUSTOMER ISSUE	-
DMS_17140	23134	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17141	23135	N	N	N	1	CUSTOMER ISSUE	-
DMS_17142	23136	N	N	N	1	CUSTOMER ISSUE	-
DMS_17143	23137	N	N	N	1	CUSTOMER ISSUE	-
DMS_17144	23138	N	N	N	1	CUSTOMER ISSUE	-
DMS_17145	23139	N	N	N	1	CUSTOMER ISSUE	-
DMS_17146	23140	N	N	N	1	CUSTOMER ISSUE	-
DMS_17147	23141	N	N	N	1	CUSTOMER ISSUE	-
DMS_17148	23142	N	N	N	1	CUSTOMER ISSUE	-
DMS_17150	23143	N	N	N	1	CUSTOMER ISSUE	-
DMS_17151	23144	N	N	N	1	CUSTOMER ISSUE	-
DMS_17152	23145	N	N	N	1	CUSTOMER ISSUE	-
DMS_17153	23146	N	N	N	1	CUSTOMER ISSUE	-
DMS_17154	23147	N	N	N	1	CUSTOMER ISSUE	-
DMS_17155	23148	N	N	N	1	CUSTOMER ISSUE	-
DMS_17156	23149	N	N	N	1	CUSTOMER ISSUE	-
DMS_17157	23150	N	N	N	1	CUSTOMER ISSUE	-
DMS_17158	23151	N	N	N	1	CUSTOMER ISSUE	-
DMS_17159	23152	N	N	N	1	CUSTOMER ISSUE	-
DMS_17160	23153	N	N	N	1	CUSTOMER ISSUE	-
DMS_17161	23154	N	N	N	1	CUSTOMER ISSUE	-
DMS_17162	23155	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_17163	23156	N	N	N	1	CUSTOMER ISSUE	-
DMS_17164	23157	N	N	N	1	CUSTOMER ISSUE	-
DMS_17165	23158	N	N	N	1	CUSTOMER ISSUE	-
DMS_17166	23159	N	N	N	1	CUSTOMER ISSUE	-
DMS_17167	23160	N	N	N	1	CUSTOMER ISSUE	-
DMS_17168	23161	N	N	N	1	CUSTOMER ISSUE	-
DMS_17169	23162	N	N	N	1	CUSTOMER ISSUE	-
DMS_17170	23163	N	N	N	1	CUSTOMER ISSUE	-
DMS_17171	23164	N	N	N	1	CUSTOMER ISSUE	-
DMS_17172	23165	N	N	N	1	CUSTOMER ISSUE	-
DMS_17173	23166	N	N	N	1	CUSTOMER ISSUE	-
DMS_17174	23167	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17175	23168	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17176	23169	N	N	N	1	CUSTOMER ISSUE	-
DMS_17177	23170	N	N	N	1	CUSTOMER ISSUE	-
DMS_17178	23171	N	N	N	1	CUSTOMER ISSUE	-
DMS_17179	23172	N	N	N	1	CUSTOMER ISSUE	-
DMS_17180	23173	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17181	23174	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_17183	23175	N	N	N	1	CUSTOMER ISSUE	-
DMS_17184	23176	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_17185	23177	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17186	23178	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17187	23179	N	N	N	1	CUSTOMER ISSUE	-
DMS_17188	23180	N	N	N	1	CUSTOMER ISSUE	-
DMS_17189	23181	N	N	N	1	CUSTOMER ISSUE	-
DMS_17190	23182	N	N	N	1	CUSTOMER ISSUE	-
DMS_17191	23183	N	N	N	1	CUSTOMER ISSUE	-
DMS_17192	23184	N	N	N	1	CUSTOMER ISSUE	-
DMS_17193	23185	N	N	N	1	CUSTOMER ISSUE	-
DMS_17194	23186	N	N	N	1	CUSTOMER ISSUE	-
DMS_17195	23187	N	N	N	1	CUSTOMER ISSUE	-
DMS_17196	23188	N	N	N	1	CUSTOMER ISSUE	-
DMS_17197	23189	N	N	N	1	CUSTOMER ISSUE	-
DMS_17199	23190	N	N	N	1	CUSTOMER ISSUE	-
DMS_17200	23191	N	N	N	1	CUSTOMER ISSUE	-
DMS_17201	23192	N	N	N	1	CUSTOMER ISSUE	-
DMS_17202	23193	N	N	N	1	CUSTOMER ISSUE	-
DMS_17203	23194	N	N	N	1	CUSTOMER ISSUE	-
DMS_17204	23195	N	N	N	1	CUSTOMER ISSUE	-
DMS_17205	23196	N	N	N	1	CUSTOMER ISSUE	-
DMS_17206	23197	N	N	N	1	CUSTOMER ISSUE	-
DMS_17207	23198	N	N	N	1	CUSTOMER ISSUE	-
DMS_17208	23199	N	N	N	1	CUSTOMER ISSUE	-
DMS_17209	23200	N	N	N	1	CUSTOMER ISSUE	-
DMS_17210	23201	N	N	N	1	CUSTOMER ISSUE	-
DMS_17211	23202	N	N	N	1	CUSTOMER ISSUE	-
DMS_17212	23203	N	N	N	1	CUSTOMER ISSUE	-
DMS_17213	23204	N	N	N	1	CUSTOMER ISSUE	-
DMS_17214	23205	N	N	N	1	CUSTOMER ISSUE	-
DMS_17215	23206	N	N	N	1	CUSTOMER ISSUE	-
DMS_17216	23207	N	N	N	1	CUSTOMER ISSUE	-
DMS_17217	23208	N	N	N	1	CUSTOMER ISSUE	-
DMS_17218	23209	N	N	N	1	CUSTOMER ISSUE	-
DMS_17219	23210	N	N	N	1	CUSTOMER ISSUE	-
DMS_17221	23211	N	N	N	1	CUSTOMER ISSUE	-
DMS_17222	23212	N	N	N	1	CUSTOMER ISSUE	-
DMS_17224	23213	N	N	N	1	CUSTOMER ISSUE	-
DMS_17225	23214	N	N	N	1	CUSTOMER ISSUE	-
DMS_17226	23215	N	N	N	1	CUSTOMER ISSUE	-
DMS_17227	23216	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17228	23217	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17229	23218	N	N	N	1	CUSTOMER ISSUE	-
DMS_17230	23219	N	N	N	1	CUSTOMER ISSUE	-
DMS_17231	23220	N	N	N	1	CUSTOMER ISSUE	-
DMS_17232	23221	N	N	N	1	CUSTOMER ISSUE	-
DMS_17233	23222	N	N	N	1	CUSTOMER ISSUE	-
DMS_17234	23223	N	N	N	1	CUSTOMER ISSUE	-
DMS_17235	23224	N	N	N	1	CUSTOMER ISSUE	-
DMS_17236	23225	N	N	N	1	CUSTOMER ISSUE	-
DMS_17237	23226	N	N	N	1	CUSTOMER ISSUE	-
DMS_17238	23227	N	N	N	1	CUSTOMER ISSUE	-
DMS_17239	23228	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17240	23229	N	N	N	1	CUSTOMER ISSUE	-
DMS_17241	23230	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17242	23231	N	N	N	1	CUSTOMER ISSUE	-
DMS_17243	23232	N	N	N	1	CUSTOMER ISSUE	-
DMS_17244	23233	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_17245	23234	N	N	N	1	CUSTOMER ISSUE	-
DMS_17246	23235	N	N	N	1	CUSTOMER ISSUE	-
DMS_17247	23236	N	N	N	1	CUSTOMER ISSUE	-
DMS_17248	23237	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17249	23238	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17250	23239	N	N	N	1	CUSTOMER ISSUE	-
DMS_17251	23240	N	N	N	1	CUSTOMER ISSUE	-
DMS_17252	23241	N	N	N	1	CUSTOMER ISSUE	-
DMS_17253	23242	N	N	N	1	CUSTOMER ISSUE	-
DMS_17255	23243	N	N	N	1	CUSTOMER ISSUE	-
DMS_17256	23244	N	N	N	1	CUSTOMER ISSUE	-
DMS_17257	23245	N	N	N	1	CUSTOMER ISSUE	-
DMS_17258	23246	N	N	N	1	CUSTOMER ISSUE	-
DMS_17259	23247	N	N	N	1	CUSTOMER ISSUE	-
DMS_17260	23248	N	N	N	1	CUSTOMER ISSUE	-
DMS_17261	23249	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17262	23250	N	N	N	1	CUSTOMER ISSUE	-
DMS_17263	23251	N	N	N	1	CUSTOMER ISSUE	-
DMS_17264	23252	N	N	N	1	CUSTOMER ISSUE	-
DMS_17265	23253	N	N	N	1	CUSTOMER ISSUE	-
DMS_17266	23254	N	N	N	1	CUSTOMER ISSUE	-
DMS_17268	23255	N	N	N	1	CUSTOMER ISSUE	-
DMS_17269	23256	N	N	N	1	CUSTOMER ISSUE	-

DMS_17270	23257	N	N	N	1	CUSTOMER ISSUE	-
DMS_17272	23258	N	N	N	1	CUSTOMER ISSUE	-
DMS_17273	23259	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17274	23260	N	N	N	1	CUSTOMER ISSUE	-
DMS_17275	23261	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17276	23262	N	N	N	1	CUSTOMER ISSUE	-
DMS_17277	23263	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17278	23264	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17279	23265	N	N	N	1	CUSTOMER ISSUE	-
DMS_17280	23266	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17281	23267	N	N	N	1	CUSTOMER ISSUE	-
DMS_17283	23268	N	N	N	1	CUSTOMER ISSUE	-
DMS_17284	23269	N	N	Y	1	TX - REPLACE	2500
DMS_17285	23270	N	N	N	1	CUSTOMER ISSUE	-
DMS_17286	23271	N	N	N	1	CUSTOMER ISSUE	-
DMS_17289	23272	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17291	23273	N	N	N	1	CUSTOMER ISSUE	-
DMS_17292	23274	N	N	N	1	CUSTOMER ISSUE	-
DMS_17293	23275	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17294	23276	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17295	23277	N	N	N	1	CUSTOMER ISSUE	-
DMS_17296	23278	N	N	N	1	CUSTOMER ISSUE	-
DMS_17297	23279	N	N	N	1	CUSTOMER ISSUE	-
DMS_17299	23280	N	N	N	1	CUSTOMER ISSUE	-
DMS_17300	23281	N	N	N	1	CUSTOMER ISSUE	-
DMS_17302	23282	N	N	N	1	CUSTOMER ISSUE	-
DMS_17303	23283	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17304	23284	N	N	N	1	CUSTOMER ISSUE	-
DMS_17305	23285	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17306	23286	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17307	23287	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17308	23288	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17309	23289	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17310	23290	N	N	N	1	CUSTOMER ISSUE	-
DMS_17311	23291	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_17312	23292	N	N	N	1	CUSTOMER ISSUE	-
DMS_17314	23293	N	N	N	1	CUSTOMER ISSUE	-
DMS_17315	23294	N	N	N	1	CUSTOMER ISSUE	-
DMS_17317	23295	N	N	N	1	CUSTOMER ISSUE	-
DMS_17319	23296	N	N	N	1	CUSTOMER ISSUE	-
DMS_17320	23297	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17321	23298	N	N	N	1	CUSTOMER ISSUE	-
DMS_17322	23299	N	N	N	1	CUSTOMER ISSUE	-
DMS_17323	23300	N	N	N	1	CUSTOMER ISSUE	-
DMS_17325	23301	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_17326	23302	N	N	N	1	CUSTOMER ISSUE	-
DMS_17327	23303	N	N	N	1	CUSTOMER ISSUE	-
DMS_17328	23304	N	N	N	1	CUSTOMER ISSUE	-
DMS_17329	23305	N	N	N	1	CUSTOMER ISSUE	-
DMS_17331	23306	N	N	N	1	CUSTOMER ISSUE	-
DMS_17332	23307	N	N	N	1	CUSTOMER ISSUE	-
DMS_17333	23308	N	N	N	1	CUSTOMER ISSUE	-
DMS_17334	23309	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17335	23310	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17336	23311	N	N	N	1	CUSTOMER ISSUE	-
DMS_17337	23312	N	N	N	1	CUSTOMER ISSUE	-
DMS_17338	23313	N	N	N	1	CUSTOMER ISSUE	-
DMS_17340	23314	N	N	N	1	CUSTOMER ISSUE	-
DMS_17341	23315	N	N	N	1	CUSTOMER ISSUE	-
DMS_17342	23316	N	N	N	1	CUSTOMER ISSUE	-
DMS_17343	23317	N	N	N	1	CUSTOMER ISSUE	-
DMS_17344	23318	N	N	N	1	CUSTOMER ISSUE	-
DMS_17346	23319	N	N	N	1	CUSTOMER ISSUE	-
DMS_17347	23320	N	N	N	1	CUSTOMER ISSUE	-
DMS_17348	23321	N	N	N	1	CUSTOMER ISSUE	-
DMS_17350	23322	N	N	N	1	CUSTOMER ISSUE	-
DMS_17351	23323	N	N	N	1	CUSTOMER ISSUE	-
DMS_17352	23324	N	N	N	1	CUSTOMER ISSUE	-
DMS_17354	23325	N	N	N	1	CUSTOMER ISSUE	-
DMS_17355	23326	N	N	N	1	CUSTOMER ISSUE	-
DMS_17357	23327	N	N	N	1	CUSTOMER ISSUE	-
DMS_17358	23328	N	N	N	1	CUSTOMER ISSUE	-
DMS_17359	23329	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17361	23330	N	N	N	1	CUSTOMER ISSUE	-
DMS_17362	23331	N	N	N	1	CUSTOMER ISSUE	-
DMS_17367	23332	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17368	23333	N	N	N	1	CUSTOMER ISSUE	-
DMS_17369	23334	N	N	N	1	CUSTOMER ISSUE	-
DMS_17370	23335	N	N	N	1	CUSTOMER ISSUE	-
DMS_17371	23336	N	N	N	1	CUSTOMER ISSUE	-

DMS_17373	23337	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17374	23338	N	N	N	1	CUSTOMER ISSUE	-
DMS_17375	23339	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_17376	23340	N	N	N	1	CUSTOMER ISSUE	-
DMS_17377	23341	N	N	N	1	CUSTOMER ISSUE	-
DMS_17378	23342	N	N	N	1	CUSTOMER ISSUE	-
DMS_17379	23343	N	N	N	1	CUSTOMER ISSUE	-
DMS_17380	23344	N	N	N	1	CUSTOMER ISSUE	-
DMS_17381	23345	N	N	N	1	CUSTOMER ISSUE	-
DMS_17382	23346	N	N	N	1	CUSTOMER ISSUE	-
DMS_17383	23347	N	N	N	1	CUSTOMER ISSUE	-
DMS_17384	23348	N	N	N	1	CUSTOMER ISSUE	-
DMS_17385	23349	N	N	N	1	CUSTOMER ISSUE	-
DMS_17386	23350	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17387	23351	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17388	23352	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17389	23353	N	N	N	1	CUSTOMER ISSUE	-
DMS_17390	23354	N	N	N	1	CUSTOMER ISSUE	-
DMS_17391	23355	N	N	N	1	CUSTOMER ISSUE	-
DMS_17392	23356	N	N	N	1	CUSTOMER ISSUE	-
DMS_17393	23357	N	N	N	1	CUSTOMER ISSUE	-
DMS_17394	23358	N	N	N	1	CUSTOMER ISSUE	-
DMS_17395	23359	N	N	N	1	CUSTOMER ISSUE	-
DMS_17396	23360	N	N	N	1	CUSTOMER ISSUE	-
DMS_17397	23361	N	N	N	1	CUSTOMER ISSUE	-
DMS_17398	23362	N	N	N	1	CUSTOMER ISSUE	-
DMS_17399	23363	N	N	N	1	CUSTOMER ISSUE	-
DMS_17400	23364	N	N	N	1	CUSTOMER ISSUE	-
DMS_17401	23365	N	N	N	1	CUSTOMER ISSUE	-
DMS_17402	23366	N	N	N	1	CUSTOMER ISSUE	-
DMS_17403	23367	N	N	N	1	CUSTOMER ISSUE	-
DMS_17404	23368	N	N	N	1	CUSTOMER ISSUE	-
DMS_17405	23369	N	N	N	1	CUSTOMER ISSUE	-
DMS_17406	23370	N	N	N	1	CUSTOMER ISSUE	-
DMS_17407	23371	N	N	N	1	CUSTOMER ISSUE	-
DMS_17408	23372	N	N	N	1	CUSTOMER ISSUE	-
DMS_17409	23373	N	N	N	1	CUSTOMER ISSUE	-
DMS_17410	23374	N	N	N	1	CUSTOMER ISSUE	-
DMS_17412	23375	N	N	N	1	CUSTOMER ISSUE	-
DMS_17413	23376	N	N	N	1	CUSTOMER ISSUE	-
DMS_17414	23377	N	N	N	1	CUSTOMER ISSUE	-
DMS_17415	23378	N	N	N	1	CUSTOMER ISSUE	-
DMS_17417	23379	N	N	N	1	CUSTOMER ISSUE	-
DMS_17418	23380	N	N	N	1	CUSTOMER ISSUE	-
DMS_17419	23381	N	N	N	1	CUSTOMER ISSUE	-
DMS_17420	23382	N	N	N	1	CUSTOMER ISSUE	-
DMS_17421	23383	N	N	N	1	CUSTOMER ISSUE	-
DMS_17422	23384	N	N	N	1	CUSTOMER ISSUE	-
DMS_17423	23385	N	N	N	1	CUSTOMER ISSUE	-
DMS_17424	23386	N	N	N	1	CUSTOMER ISSUE	-
DMS_17425	23387	N	N	N	1	CUSTOMER ISSUE	-
DMS_17426	23388	N	N	N	1	CUSTOMER ISSUE	-
DMS_17427	23389	N	N	N	1	CUSTOMER ISSUE	-
DMS_17428	23390	N	N	N	1	CUSTOMER ISSUE	-
DMS_17429	23391	N	N	N	1	CUSTOMER ISSUE	-
DMS_17430	23392	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17431	23393	N	N	N	1	CUSTOMER ISSUE	-
DMS_17432	23394	N	N	N	1	CUSTOMER ISSUE	-
DMS_17433	23395	N	N	N	1	CUSTOMER ISSUE	-
DMS_17434	23396	N	N	N	1	CUSTOMER ISSUE	-
DMS_17435	23397	N	N	N	1	CUSTOMER ISSUE	-
DMS_17436	23398	N	N	N	1	CUSTOMER ISSUE	-
DMS_17437	23399	N	N	N	1	CUSTOMER ISSUE	-
DMS_17438	23400	N	N	N	1	CUSTOMER ISSUE	-
DMS_17439	23401	N	N	N	1	CUSTOMER ISSUE	-
DMS_17440	23402	N	N	N	1	CUSTOMER ISSUE	-
DMS_17441	23403	N	N	N	1	CUSTOMER ISSUE	-
DMS_17442	23404	N	N	N	1	CUSTOMER ISSUE	-
DMS_17443	23405	N	N	N	1	CUSTOMER ISSUE	-
DMS_17444	23406	N	N	N	1	CUSTOMER ISSUE	-
DMS_17445	23407	N	N	N	1	CUSTOMER ISSUE	-
DMS_17446	23408	N	N	N	1	CUSTOMER ISSUE	-
DMS_17447	23409	N	N	N	1	CUSTOMER ISSUE	-
DMS_17448	23410	N	N	N	1	CUSTOMER ISSUE	-
DMS_17449	23411	N	N	N	1	CUSTOMER ISSUE	-
DMS_17450	23412	N	N	N	1	CUSTOMER ISSUE	-
DMS_17451	23413	N	N	N	1	CUSTOMER ISSUE	-
DMS_17452	23414	N	N	N	1	CUSTOMER ISSUE	-
DMS_17453	23415	N	N	N	1	CUSTOMER ISSUE	-
DMS_17454	23416	N	N	N	1	CUSTOMER ISSUE	-

DMS_17455	23417	N	N	N	1	CUSTOMER ISSUE	-
DMS_17456	23418	N	N	N	1	CUSTOMER ISSUE	-
DMS_17457	23419	N	N	N	1	CUSTOMER ISSUE	-
DMS_17458	23420	N	N	N	1	CUSTOMER ISSUE	-
DMS_17459	23421	N	N	N	1	CUSTOMER ISSUE	-
DMS_17460	23422	N	N	N	1	CUSTOMER ISSUE	-
DMS_17461	23423	N	N	N	1	CUSTOMER ISSUE	-
DMS_17462	23424	N	N	N	1	CUSTOMER ISSUE	-
DMS_17463	23425	N	N	N	1	CUSTOMER ISSUE	-
DMS_17464	23426	N	N	N	1	CUSTOMER ISSUE	-
DMS_17465	23427	N	N	N	1	CUSTOMER ISSUE	-
DMS_17466	23428	N	N	N	1	CUSTOMER ISSUE	-
DMS_17467	23429	N	N	N	1	CUSTOMER ISSUE	-
DMS_17468	23430	N	N	N	1	CUSTOMER ISSUE	-
DMS_17469	23431	N	N	N	1	CUSTOMER ISSUE	-
DMS_17470	23432	N	N	N	1	CUSTOMER ISSUE	-
DMS_17471	23433	N	N	N	1	CUSTOMER ISSUE	-
DMS_17472	23434	N	N	N	1	CUSTOMER ISSUE	-
DMS_17473	23435	N	N	N	1	CUSTOMER ISSUE	-
DMS_17474	23436	N	N	N	1	CUSTOMER ISSUE	-
DMS_17475	23437	N	N	N	1	CUSTOMER ISSUE	-
DMS_17476	23438	N	N	N	1	CUSTOMER ISSUE	-
DMS_17477	23439	N	N	N	1	CUSTOMER ISSUE	-
DMS_17478	23440	N	N	N	1	CUSTOMER ISSUE	-
DMS_17479	23441	N	N	N	1	CUSTOMER ISSUE	-
DMS_17480	23442	N	N	N	1	CUSTOMER ISSUE	-
DMS_17481	23443	N	N	N	1	CUSTOMER ISSUE	-
DMS_17482	23444	N	N	N	1	CUSTOMER ISSUE	-
DMS_17483	23445	N	N	N	1	CUSTOMER ISSUE	-
DMS_17484	23446	N	N	N	1	CUSTOMER ISSUE	-
DMS_17485	23447	N	N	N	1	CUSTOMER ISSUE	-
DMS_17486	23448	N	N	N	1	CUSTOMER ISSUE	-
DMS_17487	23449	N	N	N	1	CUSTOMER ISSUE	-
DMS_17488	23450	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17489	23451	N	N	N	1	CUSTOMER ISSUE	-
DMS_17491	23452	N	N	N	1	CUSTOMER ISSUE	-
DMS_17492	23453	N	N	N	1	CUSTOMER ISSUE	-
DMS_17493	23454	N	N	N	1	CUSTOMER ISSUE	-
DMS_17494	23455	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_17495	23456	N	N	N	1	CUSTOMER ISSUE	-
DMS_17496	23457	N	N	N	1	CUSTOMER ISSUE	-
DMS_17497	23458	N	N	N	1	CUSTOMER ISSUE	-
DMS_17498	23459	N	N	N	1	CUSTOMER ISSUE	-
DMS_17499	23460	N	N	N	1	CUSTOMER ISSUE	-
DMS_17500	23461	N	N	N	1	CUSTOMER ISSUE	-
DMS_17501	23462	N	N	N	1	CUSTOMER ISSUE	-
DMS_17502	23463	N	N	N	1	CUSTOMER ISSUE	-
DMS_17504	23464	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17507	23465	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_17508	23466	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17509	23467	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17510	23468	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17511	23469	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17513	23470	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17514	23471	N	N	N	1	CUSTOMER ISSUE	-
DMS_17529	23472	N	N	N	1	CUSTOMER ISSUE	-
DMS_17531	23473	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17534	23474	N	N	N	1	CUSTOMER ISSUE	-
DMS_17535	23475	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17536	23476	N	N	N	1	CUSTOMER ISSUE	-
DMS_17537	23477	N	N	N	1	CUSTOMER ISSUE	-
DMS_17538	23478	N	N	N	1	CUSTOMER ISSUE	-
DMS_17539	23479	N	N	N	1	CUSTOMER ISSUE	-
DMS_17540	23480	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17541	23481	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17542	23482	N	N	N	1	CUSTOMER ISSUE	-
DMS_17543	23483	N	N	N	1	CUSTOMER ISSUE	-
DMS_17544	23484	N	N	N	1	CUSTOMER ISSUE	-
DMS_17545	23485	N	N	N	1	CUSTOMER ISSUE	-
DMS_17546	23486	N	N	N	1	CUSTOMER ISSUE	-
DMS_17547	23487	N	N	N	1	CUSTOMER ISSUE	-
DMS_17548	23488	N	N	N	1	CUSTOMER ISSUE	-
DMS_17549	23489	N	N	N	1	CUSTOMER ISSUE	-
DMS_17550	23490	N	N	N	1	CUSTOMER ISSUE	-
DMS_17551	23491	N	N	N	1	CUSTOMER ISSUE	-
DMS_17552	23492	N	N	N	1	CUSTOMER ISSUE	-
DMS_17553	23493	N	N	N	1	CUSTOMER ISSUE	-
DMS_17554	23494	N	N	N	1	CUSTOMER ISSUE	-
DMS_17555	23495	N	N	N	1	CUSTOMER ISSUE	-
DMS_17556	23496	N	N	N	1	CUSTOMER ISSUE	-

DMS_17557	23497	N	N	N	1	CUSTOMER ISSUE	-
DMS_17558	23498	N	N	N	1	CUSTOMER ISSUE	-
DMS_17559	23499	N	N	N	1	CUSTOMER ISSUE	-
DMS_17560	23500	N	N	N	1	CUSTOMER ISSUE	-
DMS_17561	23501	N	N	N	1	CUSTOMER ISSUE	-
DMS_17562	23502	N	N	N	1	CUSTOMER ISSUE	-
DMS_17563	23503	N	N	N	1	CUSTOMER ISSUE	-
DMS_17564	23504	N	N	N	1	CUSTOMER ISSUE	-
DMS_17565	23505	N	N	N	1	CUSTOMER ISSUE	-
DMS_17566	23506	N	N	N	1	CUSTOMER ISSUE	-
DMS_17567	23507	N	N	N	1	CUSTOMER ISSUE	-
DMS_17568	23508	N	N	N	1	CUSTOMER ISSUE	-
DMS_17569	23509	N	N	N	1	CUSTOMER ISSUE	-
DMS_17570	23510	N	N	N	1	CUSTOMER ISSUE	-
DMS_17571	23511	N	N	N	1	CUSTOMER ISSUE	-
DMS_17572	23512	N	N	N	1	CUSTOMER ISSUE	-
DMS_17573	23513	N	N	N	1	CUSTOMER ISSUE	-
DMS_17574	23514	N	N	N	1	CUSTOMER ISSUE	-
DMS_17575	23515	N	N	N	1	CUSTOMER ISSUE	-
DMS_17576	23516	N	N	N	1	CUSTOMER ISSUE	-
DMS_17577	23517	N	N	N	1	CUSTOMER ISSUE	-
DMS_17578	23518	N	N	N	1	CUSTOMER ISSUE	-
DMS_17579	23519	N	N	N	1	CUSTOMER ISSUE	-
DMS_17580	23520	N	N	N	1	CUSTOMER ISSUE	-
DMS_17581	23521	N	N	N	1	CUSTOMER ISSUE	-
DMS_17582	23522	N	N	N	1	CUSTOMER ISSUE	-
DMS_17583	23523	N	N	N	1	CUSTOMER ISSUE	-
DMS_17584	23524	N	N	N	1	CUSTOMER ISSUE	-
DMS_17585	23525	N	N	N	1	CUSTOMER ISSUE	-
DMS_17586	23526	N	N	N	1	CUSTOMER ISSUE	-
DMS_17587	23527	N	N	N	1	CUSTOMER ISSUE	-
DMS_17588	23528	N	N	N	1	CUSTOMER ISSUE	-
DMS_17589	23529	N	N	N	1	CUSTOMER ISSUE	-
DMS_17590	23530	N	N	N	1	CUSTOMER ISSUE	-
DMS_17591	23531	N	N	N	1	CUSTOMER ISSUE	-
DMS_17592	23532	N	N	N	1	CUSTOMER ISSUE	-
DMS_17593	23533	N	N	N	1	CUSTOMER ISSUE	-
DMS_17594	23534	N	N	N	1	CUSTOMER ISSUE	-
DMS_17595	23535	N	N	N	1	CUSTOMER ISSUE	-
DMS_17596	23536	N	N	N	1	CUSTOMER ISSUE	-
DMS_17597	23537	N	N	N	1	CUSTOMER ISSUE	-
DMS_17598	23538	N	N	N	1	CUSTOMER ISSUE	-
DMS_17599	23539	N	N	N	1	CUSTOMER ISSUE	-
DMS_17600	23540	N	N	N	1	CUSTOMER ISSUE	-
DMS_17601	23541	N	N	N	1	CUSTOMER ISSUE	-
DMS_17602	23542	N	N	N	1	CUSTOMER ISSUE	-
DMS_17603	23543	N	N	N	1	CUSTOMER ISSUE	-
DMS_17604	23544	N	N	N	1	CUSTOMER ISSUE	-
DMS_17605	23545	N	N	N	1	CUSTOMER ISSUE	-
DMS_17606	23546	N	N	N	1	CUSTOMER ISSUE	-
DMS_17607	23547	N	N	N	1	CUSTOMER ISSUE	-
DMS_17608	23548	N	N	N	1	CUSTOMER ISSUE	-
DMS_17609	23549	N	N	N	1	CUSTOMER ISSUE	-
DMS_17610	23550	N	N	N	1	CUSTOMER ISSUE	-
DMS_17611	23551	N	N	N	1	CUSTOMER ISSUE	-
DMS_17612	23552	N	N	N	1	CUSTOMER ISSUE	-
DMS_17613	23553	N	N	N	1	CUSTOMER ISSUE	-
DMS_17614	23554	N	N	N	1	CUSTOMER ISSUE	-
DMS_17615	23555	N	N	N	1	CUSTOMER ISSUE	-
DMS_17616	23556	N	N	N	1	CUSTOMER ISSUE	-
DMS_17617	23557	N	N	N	1	CUSTOMER ISSUE	-
DMS_17618	23558	N	N	N	1	CUSTOMER ISSUE	-
DMS_17619	23559	N	N	N	1	CUSTOMER ISSUE	-
DMS_17620	23560	N	N	N	1	CUSTOMER ISSUE	-
DMS_17621	23561	N	N	N	1	CUSTOMER ISSUE	-
DMS_17622	23562	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17623	23563	N	N	N	1	CUSTOMER ISSUE	-
DMS_17624	23564	N	N	N	1	CUSTOMER ISSUE	-
DMS_17625	23565	N	N	N	1	CUSTOMER ISSUE	-
DMS_17626	23566	N	N	N	1	CUSTOMER ISSUE	-
DMS_17627	23567	N	N	N	1	CUSTOMER ISSUE	-
DMS_17628	23568	N	N	N	1	CUSTOMER ISSUE	-
DMS_17629	23569	N	N	N	1	CUSTOMER ISSUE	-
DMS_17630	23570	N	N	N	1	CUSTOMER ISSUE	-
DMS_17631	23571	N	N	N	1	CUSTOMER ISSUE	-
DMS_17632	23572	N	N	N	1	CUSTOMER ISSUE	-
DMS_17633	23573	N	N	N	1	CUSTOMER ISSUE	-
DMS_17634	23574	N	N	N	1	CUSTOMER ISSUE	-
DMS_17635	23575	N	N	N	1	CUSTOMER ISSUE	-
DMS_17636	23576	N	N	N	1	CUSTOMER ISSUE	-

DMS_17637	23577	N	N	N	1	CUSTOMER ISSUE	-
DMS_17638	23578	N	N	N	1	CUSTOMER ISSUE	-
DMS_17639	23579	N	N	N	1	CUSTOMER ISSUE	-
DMS_17640	23580	N	N	N	1	CUSTOMER ISSUE	-
DMS_17641	23581	N	N	N	1	CUSTOMER ISSUE	-
DMS_17643	23582	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_17644	23583	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_17645	23584	N	N	N	1	CUSTOMER ISSUE	-
DMS_17646	23585	N	N	N	1	CUSTOMER ISSUE	-
DMS_17647	23586	N	N	N	1	CUSTOMER ISSUE	-
DMS_17648	23587	N	N	N	1	CUSTOMER ISSUE	-
DMS_17649	23588	N	N	N	1	CUSTOMER ISSUE	-
DMS_17650	23589	N	N	N	1	CUSTOMER ISSUE	-
DMS_17651	23590	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_17652	23591	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_17653	23592	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_17654	23593	N	N	N	1	CUSTOMER ISSUE	-
DMS_17655	23594	N	N	N	2	CUSTOMER ISSUE	-
DMS_17656	23595	N	N	N	1	CUSTOMER ISSUE	-
DMS_17657	23596	N	N	N	1	CUSTOMER ISSUE	-
DMS_17658	23597	N	N	N	1	CUSTOMER ISSUE	-
DMS_17659	23598	N	N	N	1	CUSTOMER ISSUE	-
DMS_17660	23599	N	N	N	1	CUSTOMER ISSUE	-
DMS_17661	23600	N	N	N	1	CUSTOMER ISSUE	-
DMS_17662	23601	N	N	N	1	CUSTOMER ISSUE	-
DMS_17664	23602	N	N	N	1	CUSTOMER ISSUE	-
DMS_17665	23603	N	N	N	1	CUSTOMER ISSUE	-
DMS_17666	23604	N	N	N	1	CUSTOMER ISSUE	-
DMS_17667	23605	N	N	N	1	CUSTOMER ISSUE	-
DMS_17668	23606	N	N	N	1	CUSTOMER ISSUE	-
DMS_17669	23607	N	N	N	1	CUSTOMER ISSUE	-
DMS_17670	23608	N	N	N	1	CUSTOMER ISSUE	-
DMS_17672	23609	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_17673	23610	N	N	N	1	CUSTOMER ISSUE	-
DMS_17674	23611	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_17675	23612	N	N	N	1	CUSTOMER ISSUE	-
DMS_17676	23613	N	N	N	1	CUSTOMER ISSUE	-
DMS_17677	23614	N	N	N	1	CUSTOMER ISSUE	-
DMS_17678	23615	N	N	N	1	CUSTOMER ISSUE	-
DMS_17679	23616	N	N	N	1	CUSTOMER ISSUE	-
DMS_17680	23617	N	N	N	1	CUSTOMER ISSUE	-
DMS_17681	23618	N	N	N	1	CUSTOMER ISSUE	-
DMS_17682	23619	N	N	N	1	CUSTOMER ISSUE	-
DMS_17683	23620	N	N	N	1	CUSTOMER ISSUE	-
DMS_17684	23621	N	N	N	1	CUSTOMER ISSUE	-
DMS_17685	23622	N	N	N	1	CUSTOMER ISSUE	-
DMS_17686	23623	N	N	N	1	CUSTOMER ISSUE	-
DMS_17687	23624	N	N	N	1	CUSTOMER ISSUE	-
DMS_17688	23625	N	N	N	1	CUSTOMER ISSUE	-
DMS_17689	23626	N	N	N	1	CUSTOMER ISSUE	-
DMS_17690	23627	N	N	N	1	CUSTOMER ISSUE	-
DMS_17691	23628	N	N	N	1	CUSTOMER ISSUE	-
DMS_17693	23629	N	N	N	1	CUSTOMER ISSUE	-
DMS_17694	23630	N	N	N	1	CUSTOMER ISSUE	-
DMS_17695	23631	N	N	N	1	CUSTOMER ISSUE	-
DMS_17696	23632	N	N	N	1	CUSTOMER ISSUE	-
DMS_17697	23633	N	N	N	1	CUSTOMER ISSUE	-
DMS_17698	23634	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17700	23635	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_17702	23636	N	N	N	1	CUSTOMER ISSUE	-
DMS_17703	23637	N	N	N	1	CUSTOMER ISSUE	-
DMS_17704	23638	N	N	N	1	CUSTOMER ISSUE	-
DMS_17706	23639	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17707	23640	N	N	N	1	CUSTOMER ISSUE	-
DMS_17710	23641	N	N	N	1	CUSTOMER ISSUE	-
DMS_17711	23642	N	N	N	1	CUSTOMER ISSUE	-
DMS_17712	23643	N	N	N	1	CUSTOMER ISSUE	-
DMS_17713	23644	N	N	N	1	CUSTOMER ISSUE	-
DMS_17715	23645	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17716	23646	N	N	Y	1	TX - REPLACE	2500
DMS_17717	23647	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17718	23648	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17719	23649	N	N	N	1	CUSTOMER ISSUE	-
DMS_17720	23650	N	N	N	1	CUSTOMER ISSUE	-
DMS_17721	23651	N	N	N	1	CUSTOMER ISSUE	-
DMS_17722	23652	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17723	23653	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17724	23654	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17725	23655	N	N	N	1	CUSTOMER ISSUE	-
DMS_17726	23656	N	N	N	1	CUSTOMER ISSUE	-

DMS_17727	23657	N	N	N	1	CUSTOMER ISSUE	-
DMS_17728	23658	N	N	N	1	CUSTOMER ISSUE	-
DMS_17729	23659	N	N	N	1	CUSTOMER ISSUE	-
DMS_17730	23660	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_17731	23661	N	N	N	1	CUSTOMER ISSUE	-
DMS_17732	23662	N	N	N	1	CUSTOMER ISSUE	-
DMS_17733	23663	N	N	N	1	CUSTOMER ISSUE	-
DMS_17734	23664	N	N	N	1	CUSTOMER ISSUE	-
DMS_17735	23665	N	N	N	1	CUSTOMER ISSUE	-
DMS_17736	23666	N	N	N	1	CUSTOMER ISSUE	-
DMS_17737	23667	N	N	N	1	CUSTOMER ISSUE	-
DMS_17738	23668	N	N	N	1	CUSTOMER ISSUE	-
DMS_17739	23669	N	N	N	1	CUSTOMER ISSUE	-
DMS_17741	23670	N	N	N	1	CUSTOMER ISSUE	-
DMS_17742	23671	N	N	N	1	CUSTOMER ISSUE	-
DMS_17743	23672	N	N	N	1	CUSTOMER ISSUE	-
DMS_17744	23673	N	N	N	1	CUSTOMER ISSUE	-
DMS_17745	23674	N	N	N	1	CUSTOMER ISSUE	-
DMS_17746	23675	N	N	N	1	CUSTOMER ISSUE	-
DMS_17747	23676	N	N	N	1	CUSTOMER ISSUE	-
DMS_17748	23677	N	N	N	1	CUSTOMER ISSUE	-
DMS_17749	23678	N	N	N	1	CUSTOMER ISSUE	-
DMS_17750	23679	N	N	N	1	CUSTOMER ISSUE	-
DMS_17751	23680	N	N	N	1	CUSTOMER ISSUE	-
DMS_17752	23681	N	N	N	1	CUSTOMER ISSUE	-
DMS_17753	23682	N	N	N	1	CUSTOMER ISSUE	-
DMS_17754	23683	N	N	N	1	CUSTOMER ISSUE	-
DMS_17755	23684	N	N	N	1	CUSTOMER ISSUE	-
DMS_17756	23685	N	N	N	1	CUSTOMER ISSUE	-
DMS_17757	23686	N	N	N	1	CUSTOMER ISSUE	-
DMS_17758	23687	N	N	N	1	CUSTOMER ISSUE	-
DMS_17759	23688	N	N	N	1	CUSTOMER ISSUE	-
DMS_17760	23689	N	N	N	1	CUSTOMER ISSUE	-
DMS_17761	23690	N	N	N	1	CUSTOMER ISSUE	-
DMS_17762	23691	N	N	N	1	CUSTOMER ISSUE	-
DMS_17763	23692	N	N	N	1	CUSTOMER ISSUE	-
DMS_17764	23693	N	N	N	1	CUSTOMER ISSUE	-
DMS_17765	23694	N	N	N	1	CUSTOMER ISSUE	-
DMS_17766	23695	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17767	23696	N	N	N	1	CUSTOMER ISSUE	-
DMS_17768	23697	N	N	N	1	CUSTOMER ISSUE	-
DMS_17769	23698	N	N	N	1	CUSTOMER ISSUE	-
DMS_17770	23699	N	N	N	1	CUSTOMER ISSUE	-
DMS_17771	23700	N	N	N	1	CUSTOMER ISSUE	-
DMS_17772	23701	N	N	N	1	CUSTOMER ISSUE	-
DMS_17773	23702	N	N	N	1	CUSTOMER ISSUE	-
DMS_17776	23703	N	N	N	1	CUSTOMER ISSUE	-
DMS_17777	23704	N	N	N	1	CUSTOMER ISSUE	-
DMS_17778	23705	N	N	N	1	CUSTOMER ISSUE	-
DMS_17779	23706	N	N	N	1	CUSTOMER ISSUE	-
DMS_17780	23707	N	N	N	1	CUSTOMER ISSUE	-
DMS_17781	23708	N	N	N	1	CUSTOMER ISSUE	-
DMS_17782	23709	N	N	N	1	CUSTOMER ISSUE	-
DMS_17783	23710	N	N	N	1	CUSTOMER ISSUE	-
DMS_17784	23711	N	N	N	1	CUSTOMER ISSUE	-
DMS_17785	23712	N	N	N	1	CUSTOMER ISSUE	-
DMS_17786	23713	N	N	N	1	CUSTOMER ISSUE	-
DMS_17787	23714	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17788	23715	N	N	N	1	CUSTOMER ISSUE	-
DMS_17789	23716	N	N	N	1	CUSTOMER ISSUE	-
DMS_17790	23717	N	N	N	1	CUSTOMER ISSUE	-
DMS_17793	23718	N	N	N	1	CUSTOMER ISSUE	-
DMS_17794	23719	N	N	N	1	CUSTOMER ISSUE	-
DMS_17795	23720	N	N	N	1	CUSTOMER ISSUE	-
DMS_17796	23721	N	N	N	1	CUSTOMER ISSUE	-
DMS_17797	23722	N	N	N	1	CUSTOMER ISSUE	-
DMS_17798	23723	N	N	N	1	CUSTOMER ISSUE	-
DMS_17799	23724	N	N	N	1	CUSTOMER ISSUE	-
DMS_17800	23725	N	N	N	1	CUSTOMER ISSUE	-
DMS_17801	23726	N	N	N	1	CUSTOMER ISSUE	-
DMS_17802	23727	N	N	N	1	CUSTOMER ISSUE	-
DMS_17803	23728	N	N	N	1	CUSTOMER ISSUE	-
DMS_17804	23729	N	N	N	1	CUSTOMER ISSUE	-
DMS_17805	23730	N	N	N	1	CUSTOMER ISSUE	-
DMS_17806	23731	N	N	N	1	CUSTOMER ISSUE	-
DMS_17807	23732	N	N	N	1	CUSTOMER ISSUE	-
DMS_17808	23733	N	N	N	1	CUSTOMER ISSUE	-
DMS_17809	23734	N	N	N	1	CUSTOMER ISSUE	-
DMS_17810	23735	N	N	N	1	CUSTOMER ISSUE	-
DMS_17812	23736	N	N	N	1	CUSTOMER ISSUE	-

DMS_17813	23737	N	N	N	1	CUSTOMER ISSUE	-
DMS_17814	23738	N	N	N	1	CUSTOMER ISSUE	-
DMS_17815	23739	N	N	N	1	CUSTOMER ISSUE	-
DMS_17816	23740	N	N	N	1	CUSTOMER ISSUE	-
DMS_17817	23741	N	N	N	1	CUSTOMER ISSUE	-
DMS_17818	23742	N	N	N	1	CUSTOMER ISSUE	-
DMS_17819	23743	N	N	N	1	CUSTOMER ISSUE	-
DMS_17820	23744	N	N	N	1	CUSTOMER ISSUE	-
DMS_17821	23745	N	N	N	1	CUSTOMER ISSUE	-
DMS_17822	23746	N	N	N	1	CUSTOMER ISSUE	-
DMS_17823	23747	N	N	N	1	CUSTOMER ISSUE	-
DMS_17824	23748	N	N	N	1	CUSTOMER ISSUE	-
DMS_17825	23749	N	N	N	1	CUSTOMER ISSUE	-
DMS_17826	23750	N	N	N	1	CUSTOMER ISSUE	-
DMS_17827	23751	N	N	N	1	CUSTOMER ISSUE	-
DMS_17828	23752	N	N	N	1	CUSTOMER ISSUE	-
DMS_17830	23753	N	N	N	1	CUSTOMER ISSUE	-
DMS_17831	23754	N	N	N	1	CUSTOMER ISSUE	-
DMS_17832	23755	N	N	N	1	CUSTOMER ISSUE	-
DMS_17833	23756	N	N	N	1	CUSTOMER ISSUE	-
DMS_17834	23757	N	N	N	1	CUSTOMER ISSUE	-
DMS_17835	23758	N	N	N	1	CUSTOMER ISSUE	-
DMS_17836	23759	N	N	N	1	CUSTOMER ISSUE	-
DMS_17837	23760	N	N	N	1	CUSTOMER ISSUE	-
DMS_17838	23761	N	N	N	1	CUSTOMER ISSUE	-
DMS_17839	23762	N	N	N	1	CUSTOMER ISSUE	-
DMS_17840	23763	N	N	N	1	CUSTOMER ISSUE	-
DMS_17841	23764	N	N	N	1	CUSTOMER ISSUE	-
DMS_17842	23765	N	N	N	1	CUSTOMER ISSUE	-
DMS_17843	23766	N	N	N	1	CUSTOMER ISSUE	-
DMS_17844	23767	N	N	N	1	CUSTOMER ISSUE	-
DMS_17845	23768	N	N	N	1	CUSTOMER ISSUE	-
DMS_17846	23769	N	N	N	1	CUSTOMER ISSUE	-
DMS_17847	23770	N	N	N	1	CUSTOMER ISSUE	-
DMS_17848	23771	N	N	N	1	CUSTOMER ISSUE	-
DMS_17849	23772	N	N	N	1	CUSTOMER ISSUE	-
DMS_17850	23773	N	N	N	1	CUSTOMER ISSUE	-
DMS_17851	23774	N	N	N	1	CUSTOMER ISSUE	-
DMS_17852	23775	N	N	N	1	CUSTOMER ISSUE	-
DMS_17853	23776	N	N	N	1	CUSTOMER ISSUE	-
DMS_17854	23777	N	N	N	1	CUSTOMER ISSUE	-
DMS_17855	23778	N	N	N	1	CUSTOMER ISSUE	-
DMS_17856	23779	N	N	N	1	CUSTOMER ISSUE	-
DMS_17857	23780	N	N	N	1	CUSTOMER ISSUE	-
DMS_17858	23781	N	N	N	1	CUSTOMER ISSUE	-
DMS_17859	23782	N	N	N	1	CUSTOMER ISSUE	-
DMS_17860	23783	N	N	N	1	CUSTOMER ISSUE	-
DMS_17861	23784	N	N	N	1	CUSTOMER ISSUE	-
DMS_17862	23785	N	N	N	1	CUSTOMER ISSUE	-
DMS_17863	23786	N	N	N	1	CUSTOMER ISSUE	-
DMS_17864	23787	N	N	N	1	CUSTOMER ISSUE	-
DMS_17865	23788	N	N	N	1	CUSTOMER ISSUE	-
DMS_17866	23789	N	N	N	1	CUSTOMER ISSUE	-
DMS_17867	23790	N	N	N	1	CUSTOMER ISSUE	-
DMS_17868	23791	N	N	N	1	CUSTOMER ISSUE	-
DMS_17869	23792	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17870	23793	N	N	N	1	CUSTOMER ISSUE	-
DMS_17871	23794	N	N	N	1	CUSTOMER ISSUE	-
DMS_17872	23795	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17873	23796	N	N	N	1	CUSTOMER ISSUE	-
DMS_17874	23797	N	N	N	1	CUSTOMER ISSUE	-
DMS_17875	23798	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17876	23799	N	N	N	1	CUSTOMER ISSUE	-
DMS_17877	23800	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17878	23801	N	N	N	1	CUSTOMER ISSUE	-
DMS_17879	23802	N	N	N	1	CUSTOMER ISSUE	-
DMS_17880	23803	N	N	N	1	CUSTOMER ISSUE	-
DMS_17881	23804	N	N	N	1	CUSTOMER ISSUE	-
DMS_17882	23805	N	N	N	1	CUSTOMER ISSUE	-
DMS_17883	23806	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_17884	23807	N	N	N	1	CUSTOMER ISSUE	-
DMS_17885	23808	N	N	N	1	CUSTOMER ISSUE	-
DMS_17886	23809	N	N	N	1	CUSTOMER ISSUE	-
DMS_17887	23810	N	N	N	1	CUSTOMER ISSUE	-
DMS_17888	23811	N	N	N	1	CUSTOMER ISSUE	-
DMS_17889	23812	N	N	N	2	CUSTOMER ISSUE	-
DMS_17890	23813	N	N	N	1	CUSTOMER ISSUE	-
DMS_17891	23814	N	N	N	1	CUSTOMER ISSUE	-
DMS_17892	23815	N	N	N	1	CUSTOMER ISSUE	-
DMS_17893	23816	N	N	N	1	CUSTOMER ISSUE	-

DMS_17894	23817	N	N	N	1	CUSTOMER ISSUE	-
DMS_17895	23818	N	N	N	1	CUSTOMER ISSUE	-
DMS_17896	23819	N	N	N	1	CUSTOMER ISSUE	-
DMS_17897	23820	N	N	N	1	CUSTOMER ISSUE	-
DMS_17898	23821	N	N	N	1	CUSTOMER ISSUE	-
DMS_17899	23822	N	N	N	1	CUSTOMER ISSUE	-
DMS_17900	23823	N	N	N	1	CUSTOMER ISSUE	-
DMS_17901	23824	N	N	N	1	CUSTOMER ISSUE	-
DMS_17902	23825	N	N	N	1	CUSTOMER ISSUE	-
DMS_17903	23826	N	N	N	1	CUSTOMER ISSUE	-
DMS_17904	23827	N	N	N	1	CUSTOMER ISSUE	-
DMS_17905	23828	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17906	23829	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17907	23830	N	N	N	1	CUSTOMER ISSUE	-
DMS_17909	23831	N	N	N	1	CUSTOMER ISSUE	-
DMS_17910	23832	N	N	N	1	CUSTOMER ISSUE	-
DMS_17911	23833	N	N	N	1	CUSTOMER ISSUE	-
DMS_17912	23834	N	N	N	1	CUSTOMER ISSUE	-
DMS_17913	23835	N	N	N	1	CUSTOMER ISSUE	-
DMS_17914	23836	N	N	N	1	CUSTOMER ISSUE	-
DMS_17915	23837	N	N	N	1	CUSTOMER ISSUE	-
DMS_17916	23838	N	N	N	1	CUSTOMER ISSUE	-
DMS_17917	23839	N	N	N	1	CUSTOMER ISSUE	-
DMS_17918	23840	N	N	N	1	CUSTOMER ISSUE	-
DMS_17919	23841	N	N	N	1	CUSTOMER ISSUE	-
DMS_17920	23842	N	N	N	1	CUSTOMER ISSUE	-
DMS_17921	23843	N	N	N	1	CUSTOMER ISSUE	-
DMS_17922	23844	N	N	N	1	CUSTOMER ISSUE	-
DMS_17923	23845	N	N	N	1	CUSTOMER ISSUE	-
DMS_17924	23846	N	N	N	1	CUSTOMER ISSUE	-
DMS_17925	23847	N	N	N	1	CUSTOMER ISSUE	-
DMS_17926	23848	N	N	N	1	CUSTOMER ISSUE	-
DMS_17927	23849	N	N	N	1	CUSTOMER ISSUE	-
DMS_17928	23850	N	N	N	1	CUSTOMER ISSUE	-
DMS_17929	23851	N	N	N	1	CUSTOMER ISSUE	-
DMS_17930	23852	N	N	N	1	CUSTOMER ISSUE	-
DMS_17931	23853	N	N	N	1	CUSTOMER ISSUE	-
DMS_17932	23854	N	N	N	1	CUSTOMER ISSUE	-
DMS_17933	23855	N	N	N	1	CUSTOMER ISSUE	-
DMS_17934	23856	N	N	N	1	CUSTOMER ISSUE	-
DMS_17935	23857	N	N	N	1	CUSTOMER ISSUE	-
DMS_17936	23858	N	N	N	1	CUSTOMER ISSUE	-
DMS_17937	23859	N	N	N	1	CUSTOMER ISSUE	-
DMS_17938	23860	N	N	N	1	CUSTOMER ISSUE	-
DMS_17939	23861	N	N	N	1	CUSTOMER ISSUE	-
DMS_17940	23862	N	N	N	1	CUSTOMER ISSUE	-
DMS_17941	23863	N	N	N	1	CUSTOMER ISSUE	-
DMS_17942	23864	N	N	N	1	CUSTOMER ISSUE	-
DMS_17943	23865	N	N	N	1	CUSTOMER ISSUE	-
DMS_17944	23866	N	N	N	1	CUSTOMER ISSUE	-
DMS_17945	23867	N	N	N	1	CUSTOMER ISSUE	-
DMS_17946	23868	N	N	N	1	CUSTOMER ISSUE	-
DMS_17947	23869	N	N	N	1	CUSTOMER ISSUE	-
DMS_17948	23870	N	N	N	1	CUSTOMER ISSUE	-
DMS_17949	23871	N	N	N	1	CUSTOMER ISSUE	-
DMS_17950	23872	N	N	N	1	CUSTOMER ISSUE	-
DMS_17951	23873	N	N	N	1	CUSTOMER ISSUE	-
DMS_17952	23874	N	N	N	1	CUSTOMER ISSUE	-
DMS_17953	23875	N	N	N	1	CUSTOMER ISSUE	-
DMS_17954	23876	N	N	N	1	CUSTOMER ISSUE	-
DMS_17955	23877	N	N	N	1	CUSTOMER ISSUE	-
DMS_17956	23878	N	N	N	1	CUSTOMER ISSUE	-
DMS_17957	23879	N	N	N	1	CUSTOMER ISSUE	-
DMS_17958	23880	N	N	N	1	CUSTOMER ISSUE	-
DMS_17959	23881	N	N	N	1	CUSTOMER ISSUE	-
DMS_17960	23882	N	N	N	1	CUSTOMER ISSUE	-
DMS_17961	23883	N	N	N	1	CUSTOMER ISSUE	-
DMS_17962	23884	N	N	N	1	CUSTOMER ISSUE	-
DMS_17963	23885	N	N	N	1	CUSTOMER ISSUE	-
DMS_17964	23886	N	N	N	1	CUSTOMER ISSUE	-
DMS_17965	23887	N	N	N	1	CUSTOMER ISSUE	-
DMS_17966	23888	N	N	N	1	CUSTOMER ISSUE	-
DMS_17967	23889	N	N	N	1	CUSTOMER ISSUE	-
DMS_17968	23890	N	N	N	1	CUSTOMER ISSUE	-
DMS_17969	23891	N	N	N	1	CUSTOMER ISSUE	-
DMS_17970	23892	N	N	N	1	CUSTOMER ISSUE	-
DMS_17971	23893	N	N	N	1	CUSTOMER ISSUE	-
DMS_17972	23894	N	N	N	1	CUSTOMER ISSUE	-
DMS_17973	23895	N	N	N	1	CUSTOMER ISSUE	-
DMS_17974	23896	N	N	N	1	CUSTOMER ISSUE	-

DMS_17975	23897	N	N	N	1	CUSTOMER ISSUE	-
DMS_17976	23898	N	N	N	1	CUSTOMER ISSUE	-
DMS_17977	23899	N	N	N	1	CUSTOMER ISSUE	-
DMS_17978	23900	N	N	N	1	CUSTOMER ISSUE	-
DMS_17979	23901	N	N	N	1	CUSTOMER ISSUE	-
DMS_17980	23902	N	N	N	1	CUSTOMER ISSUE	-
DMS_17981	23903	N	N	N	1	CUSTOMER ISSUE	-
DMS_17982	23904	N	N	N	1	CUSTOMER ISSUE	-
DMS_17983	23905	N	N	N	1	CUSTOMER ISSUE	-
DMS_17984	23906	N	N	N	1	CUSTOMER ISSUE	-
DMS_17985	23907	N	N	N	1	CUSTOMER ISSUE	-
DMS_17987	23908	N	N	N	1	CUSTOMER ISSUE	-
DMS_17988	23909	N	N	N	1	CUSTOMER ISSUE	-
DMS_17989	23910	N	N	N	1	CUSTOMER ISSUE	-
DMS_17990	23911	N	N	N	1	CUSTOMER ISSUE	-
DMS_17991	23912	N	N	N	1	CUSTOMER ISSUE	-
DMS_17992	23913	N	N	N	1	CUSTOMER ISSUE	-
DMS_17993	23914	N	N	N	1	CUSTOMER ISSUE	-
DMS_17994	23915	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_17995	23916	N	N	N	1	CUSTOMER ISSUE	-
DMS_17996	23917	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_17997	23918	N	N	N	1	CUSTOMER ISSUE	-
DMS_17998	23919	N	N	N	1	CUSTOMER ISSUE	-
DMS_17999	23920	N	N	N	1	CUSTOMER ISSUE	-
DMS_18000	23921	N	N	N	1	CUSTOMER ISSUE	-
DMS_18001	23922	N	N	N	1	CUSTOMER ISSUE	-
DMS_18002	23923	N	N	N	1	CUSTOMER ISSUE	-
DMS_18003	23924	N	N	N	1	CUSTOMER ISSUE	-
DMS_18004	23925	N	N	N	1	CUSTOMER ISSUE	-
DMS_18005	23926	N	N	N	1	CUSTOMER ISSUE	-
DMS_18006	23927	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18007	23928	N	N	N	1	CUSTOMER ISSUE	-
DMS_18008	23929	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18009	23930	N	N	N	1	CUSTOMER ISSUE	-
DMS_18010	23931	N	N	N	1	CUSTOMER ISSUE	-
DMS_18011	23932	N	N	N	1	CUSTOMER ISSUE	-
DMS_18012	23933	N	N	N	1	CUSTOMER ISSUE	-
DMS_18013	23934	N	N	N	1	CUSTOMER ISSUE	-
DMS_18014	23935	N	N	N	1	CUSTOMER ISSUE	-
DMS_18015	23936	N	N	N	1	CUSTOMER ISSUE	-
DMS_18016	23937	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18017	23938	N	N	N	1	CUSTOMER ISSUE	-
DMS_18018	23939	N	N	N	1	CUSTOMER ISSUE	-
DMS_18019	23940	N	N	N	1	CUSTOMER ISSUE	-
DMS_18020	23941	N	N	N	1	CUSTOMER ISSUE	-
DMS_18021	23942	N	N	N	1	CUSTOMER ISSUE	-
DMS_18022	23943	N	N	N	1	CUSTOMER ISSUE	-
DMS_18023	23944	N	N	N	1	CUSTOMER ISSUE	-
DMS_18024	23945	N	N	N	1	CUSTOMER ISSUE	-
DMS_18025	23946	N	N	N	1	CUSTOMER ISSUE	-
DMS_18026	23947	N	N	N	1	CUSTOMER ISSUE	-
DMS_18027	23948	N	N	N	1	CUSTOMER ISSUE	-
DMS_18028	23949	N	N	N	1	CUSTOMER ISSUE	-
DMS_18029	23950	N	N	N	1	CUSTOMER ISSUE	-
DMS_18030	23951	N	N	N	1	CUSTOMER ISSUE	-
DMS_18031	23952	N	N	N	1	CUSTOMER ISSUE	-
DMS_18033	23953	N	N	N	1	CUSTOMER ISSUE	-
DMS_18034	23954	N	N	N	1	CUSTOMER ISSUE	-
DMS_18035	23955	N	N	N	1	CUSTOMER ISSUE	-
DMS_18036	23956	N	N	N	1	CUSTOMER ISSUE	-
DMS_18037	23957	N	N	N	1	CUSTOMER ISSUE	-
DMS_18038	23958	N	N	N	1	CUSTOMER ISSUE	-
DMS_18039	23959	N	N	N	1	CUSTOMER ISSUE	-
DMS_18040	23960	N	N	N	1	CUSTOMER ISSUE	-
DMS_18041	23961	N	N	N	1	CUSTOMER ISSUE	-
DMS_18042	23962	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18043	23963	N	N	N	1	CUSTOMER ISSUE	-
DMS_18044	23964	N	N	N	1	CUSTOMER ISSUE	-
DMS_18045	23965	N	N	N	1	CUSTOMER ISSUE	-
DMS_18046	23966	N	N	N	1	CUSTOMER ISSUE	-
DMS_18047	23967	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18048	23968	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_18049	23969	N	N	N	1	CUSTOMER ISSUE	-
DMS_18050	23970	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18051	23971	N	N	N	1	CUSTOMER ISSUE	-
DMS_18052	23972	N	N	N	1	CUSTOMER ISSUE	-
DMS_18053	23973	N	N	N	1	CUSTOMER ISSUE	-
DMS_18054	23974	N	N	N	1	CUSTOMER ISSUE	-
DMS_18056	23975	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18057	23976	N	N	N	1	CUSTOMER ISSUE	-

DMS_18058	23977	N	N	N	1	CUSTOMER ISSUE	-
DMS_18059	23978	N	N	N	1	CUSTOMER ISSUE	-
DMS_18060	23979	N	N	N	1	CUSTOMER ISSUE	-
DMS_18061	23980	N	N	N	1	CUSTOMER ISSUE	-
DMS_18062	23981	N	N	N	1	CUSTOMER ISSUE	-
DMS_18063	23982	N	N	N	1	CUSTOMER ISSUE	-
DMS_18064	23983	N	N	N	1	CUSTOMER ISSUE	-
DMS_18065	23984	N	N	N	1	CUSTOMER ISSUE	-
DMS_18066	23985	N	N	N	1	CUSTOMER ISSUE	-
DMS_18067	23986	N	N	N	1	CUSTOMER ISSUE	-
DMS_18068	23987	N	N	N	1	CUSTOMER ISSUE	-
DMS_18069	23988	N	N	N	1	CUSTOMER ISSUE	-
DMS_18070	23989	N	N	N	1	CUSTOMER ISSUE	-
DMS_18071	23990	N	N	N	1	CUSTOMER ISSUE	-
DMS_18072	23991	N	N	N	1	CUSTOMER ISSUE	-
DMS_18073	23992	N	N	N	1	CUSTOMER ISSUE	-
DMS_18074	23993	N	N	N	1	CUSTOMER ISSUE	-
DMS_18075	23994	N	N	N	1	CUSTOMER ISSUE	-
DMS_18076	23995	N	N	N	1	CUSTOMER ISSUE	-
DMS_18077	23996	N	N	N	1	CUSTOMER ISSUE	-
DMS_18078	23997	N	N	N	1	CUSTOMER ISSUE	-
DMS_18079	23998	N	N	N	1	CUSTOMER ISSUE	-
DMS_18080	23999	N	N	N	1	CUSTOMER ISSUE	-
DMS_18081	24000	N	N	N	1	CUSTOMER ISSUE	-
DMS_18082	24001	N	N	N	1	CUSTOMER ISSUE	-
DMS_18083	24002	N	N	N	1	CUSTOMER ISSUE	-
DMS_18084	24003	N	N	N	1	CUSTOMER ISSUE	-
DMS_18085	24004	N	N	N	1	CUSTOMER ISSUE	-
DMS_18086	24005	N	N	N	1	CUSTOMER ISSUE	-
DMS_18087	24006	N	N	N	1	CUSTOMER ISSUE	-
DMS_18088	24007	N	N	N	1	CUSTOMER ISSUE	-
DMS_18089	24008	N	N	N	1	CUSTOMER ISSUE	-
DMS_18090	24009	N	N	N	1	CUSTOMER ISSUE	-
DMS_18091	24010	N	N	N	1	CUSTOMER ISSUE	-
DMS_18092	24011	N	N	N	1	CUSTOMER ISSUE	-
DMS_18093	24012	N	N	N	1	CUSTOMER ISSUE	-
DMS_18094	24013	N	N	N	1	CUSTOMER ISSUE	-
DMS_18095	24014	N	N	N	1	CUSTOMER ISSUE	-
DMS_18096	24015	N	N	N	1	CUSTOMER ISSUE	-
DMS_18097	24016	N	N	N	1	CUSTOMER ISSUE	-
DMS_18098	24017	N	N	N	1	CUSTOMER ISSUE	-
DMS_18099	24018	N	N	N	1	CUSTOMER ISSUE	-
DMS_18100	24019	N	N	N	1	CUSTOMER ISSUE	-
DMS_18101	24020	N	N	N	1	CUSTOMER ISSUE	-
DMS_18102	24021	N	N	N	1	CUSTOMER ISSUE	-
DMS_18103	24022	N	N	N	1	CUSTOMER ISSUE	-
DMS_18104	24023	N	N	N	1	CUSTOMER ISSUE	-
DMS_18105	24024	N	N	N	1	CUSTOMER ISSUE	-
DMS_18106	24025	N	N	N	1	CUSTOMER ISSUE	-
DMS_18107	24026	N	N	N	1	CUSTOMER ISSUE	-
DMS_18108	24027	N	N	N	1	CUSTOMER ISSUE	-
DMS_18109	24028	N	N	N	1	CUSTOMER ISSUE	-
DMS_18110	24029	N	N	N	1	CUSTOMER ISSUE	-
DMS_18111	24030	N	N	N	1	CUSTOMER ISSUE	-
DMS_18112	24031	N	N	N	1	CUSTOMER ISSUE	-
DMS_18113	24032	N	N	N	1	CUSTOMER ISSUE	-
DMS_18114	24033	N	N	N	1	CUSTOMER ISSUE	-
DMS_18115	24034	N	N	N	1	CUSTOMER ISSUE	-
DMS_18116	24035	N	N	N	1	CUSTOMER ISSUE	-
DMS_18117	24036	N	N	N	1	CUSTOMER ISSUE	-
DMS_18118	24037	N	N	N	1	CUSTOMER ISSUE	-
DMS_18119	24038	N	N	N	1	CUSTOMER ISSUE	-
DMS_18120	24039	N	N	N	1	CUSTOMER ISSUE	-
DMS_18121	24040	N	N	N	1	CUSTOMER ISSUE	-
DMS_18122	24041	N	N	N	1	CUSTOMER ISSUE	-
DMS_18123	24042	N	N	N	1	CUSTOMER ISSUE	-
DMS_18124	24043	N	N	N	1	CUSTOMER ISSUE	-
DMS_18125	24044	N	N	N	1	CUSTOMER ISSUE	-
DMS_18126	24045	N	N	N	1	CUSTOMER ISSUE	-
DMS_18127	24046	N	N	N	1	CUSTOMER ISSUE	-
DMS_18128	24047	N	N	N	1	CUSTOMER ISSUE	-
DMS_18129	24048	N	N	N	1	CUSTOMER ISSUE	-
DMS_18130	24049	N	N	N	1	CUSTOMER ISSUE	-
DMS_18131	24050	N	N	N	1	CUSTOMER ISSUE	-
DMS_18132	24051	N	N	N	1	CUSTOMER ISSUE	-
DMS_18133	24052	N	N	N	1	CUSTOMER ISSUE	-
DMS_18134	24053	N	N	N	1	CUSTOMER ISSUE	-
DMS_18135	24054	N	N	N	1	CUSTOMER ISSUE	-
DMS_18136	24055	N	N	N	1	CUSTOMER ISSUE	-
DMS_18137	24056	N	N	N	1	CUSTOMER ISSUE	-

DMS_18138	24057	N	N	N	1	CUSTOMER ISSUE	-
DMS_18139	24058	N	N	N	1	CUSTOMER ISSUE	-
DMS_18140	24059	N	N	N	1	CUSTOMER ISSUE	-
DMS_18141	24060	N	N	N	1	CUSTOMER ISSUE	-
DMS_18142	24061	N	N	N	1	CUSTOMER ISSUE	-
DMS_18143	24062	N	N	N	1	CUSTOMER ISSUE	-
DMS_18144	24063	N	N	N	1	CUSTOMER ISSUE	-
DMS_18145	24064	N	N	N	1	CUSTOMER ISSUE	-
DMS_18146	24065	N	N	N	1	CUSTOMER ISSUE	-
DMS_18147	24066	N	N	N	1	CUSTOMER ISSUE	-
DMS_18148	24067	N	N	N	1	CUSTOMER ISSUE	-
DMS_18149	24068	N	N	N	1	CUSTOMER ISSUE	-
DMS_18150	24069	N	N	N	1	CUSTOMER ISSUE	-
DMS_18151	24070	N	N	N	1	CUSTOMER ISSUE	-
DMS_18152	24071	N	N	N	1	CUSTOMER ISSUE	-
DMS_18153	24072	N	N	N	1	CUSTOMER ISSUE	-
DMS_18154	24073	N	N	N	1	CUSTOMER ISSUE	-
DMS_18155	24074	N	N	N	1	CUSTOMER ISSUE	-
DMS_18156	24075	N	N	N	1	CUSTOMER ISSUE	-
DMS_18157	24076	N	N	N	1	CUSTOMER ISSUE	-
DMS_18158	24077	N	N	N	1	CUSTOMER ISSUE	-
DMS_18159	24078	N	N	N	1	CUSTOMER ISSUE	-
DMS_18160	24079	N	N	N	1	CUSTOMER ISSUE	-
DMS_18161	24080	N	N	N	1	CUSTOMER ISSUE	-
DMS_18162	24081	N	N	N	1	CUSTOMER ISSUE	-
DMS_18163	24082	N	N	N	1	CUSTOMER ISSUE	-
DMS_18164	24083	N	N	N	1	CUSTOMER ISSUE	-
DMS_18165	24084	N	N	N	1	CUSTOMER ISSUE	-
DMS_18166	24085	N	N	N	1	CUSTOMER ISSUE	-
DMS_18167	24086	N	N	N	1	CUSTOMER ISSUE	-
DMS_18168	24087	N	N	N	1	CUSTOMER ISSUE	-
DMS_18169	24088	N	N	N	1	CUSTOMER ISSUE	-
DMS_18170	24089	N	N	N	1	CUSTOMER ISSUE	-
DMS_18171	24090	N	N	N	1	CUSTOMER ISSUE	-
DMS_18172	24091	N	N	N	1	CUSTOMER ISSUE	-
DMS_18173	24092	N	N	N	1	CUSTOMER ISSUE	-
DMS_18174	24093	N	N	N	1	CUSTOMER ISSUE	-
DMS_18175	24094	N	N	N	1	CUSTOMER ISSUE	-
DMS_18176	24095	N	N	N	1	CUSTOMER ISSUE	-
DMS_18177	24096	N	N	N	1	CUSTOMER ISSUE	-
DMS_18178	24097	N	N	N	1	CUSTOMER ISSUE	-
DMS_18179	24098	N	N	N	1	CUSTOMER ISSUE	-
DMS_18180	24099	N	N	N	1	CUSTOMER ISSUE	-
DMS_18181	24100	N	N	N	1	CUSTOMER ISSUE	-
DMS_18182	24101	N	N	N	1	CUSTOMER ISSUE	-
DMS_18183	24102	N	N	N	1	CUSTOMER ISSUE	-
DMS_18184	24103	N	N	N	1	CUSTOMER ISSUE	-
DMS_18185	24104	N	N	N	1	CUSTOMER ISSUE	-
DMS_18186	24105	N	N	N	1	CUSTOMER ISSUE	-
DMS_18187	24106	N	N	N	1	CUSTOMER ISSUE	-
DMS_18188	24107	N	N	N	1	CUSTOMER ISSUE	-
DMS_18189	24108	N	N	N	1	CUSTOMER ISSUE	-
DMS_18190	24109	N	N	N	1	CUSTOMER ISSUE	-
DMS_18191	24110	N	N	N	1	CUSTOMER ISSUE	-
DMS_18192	24111	N	N	N	1	CUSTOMER ISSUE	-
DMS_18193	24112	N	N	N	1	CUSTOMER ISSUE	-
DMS_18194	24113	N	N	N	2	CUSTOMER ISSUE	-
DMS_18195	24114	N	N	N	1	CUSTOMER ISSUE	-
DMS_18196	24115	N	N	N	1	CUSTOMER ISSUE	-
DMS_18197	24116	N	N	N	1	CUSTOMER ISSUE	-
DMS_18198	24117	N	N	N	1	CUSTOMER ISSUE	-
DMS_18199	24118	N	N	N	1	CUSTOMER ISSUE	-
DMS_18200	24119	N	N	N	1	CUSTOMER ISSUE	-
DMS_18201	24120	N	N	N	1	CUSTOMER ISSUE	-
DMS_18202	24121	N	N	N	1	CUSTOMER ISSUE	-
DMS_18203	24122	N	N	N	1	CUSTOMER ISSUE	-
DMS_18204	24123	N	N	N	1	CUSTOMER ISSUE	-
DMS_18205	24124	N	N	N	1	CUSTOMER ISSUE	-
DMS_18206	24125	N	N	N	1	CUSTOMER ISSUE	-
DMS_18207	24126	N	N	N	1	CUSTOMER ISSUE	-
DMS_18208	24127	N	N	N	1	CUSTOMER ISSUE	-
DMS_18209	24128	N	N	N	1	CUSTOMER ISSUE	-
DMS_18210	24129	N	N	N	1	CUSTOMER ISSUE	-
DMS_18211	24130	N	N	N	1	CUSTOMER ISSUE	-
DMS_18212	24131	N	N	N	1	CUSTOMER ISSUE	-
DMS_18213	24132	N	N	N	1	CUSTOMER ISSUE	-
DMS_18214	24133	N	N	N	1	CUSTOMER ISSUE	-
DMS_18215	24134	N	N	N	1	CUSTOMER ISSUE	-
DMS_18216	24135	N	N	N	1	CUSTOMER ISSUE	-
DMS_18217	24136	N	N	N	1	CUSTOMER ISSUE	-

DMS_18218	24137	N	N	N	1	CUSTOMER ISSUE	-
DMS_18219	24138	N	N	N	1	CUSTOMER ISSUE	-
DMS_18220	24139	N	N	N	1	CUSTOMER ISSUE	-
DMS_18221	24140	N	N	N	1	CUSTOMER ISSUE	-
DMS_18222	24141	N	N	N	1	CUSTOMER ISSUE	-
DMS_18223	24142	N	N	N	1	CUSTOMER ISSUE	-
DMS_18224	24143	N	N	N	1	CUSTOMER ISSUE	-
DMS_18225	24144	N	N	N	1	CUSTOMER ISSUE	-
DMS_18226	24145	N	N	N	1	CUSTOMER ISSUE	-
DMS_18227	24146	N	N	N	1	CUSTOMER ISSUE	-
DMS_18228	24147	N	N	N	1	CUSTOMER ISSUE	-
DMS_18229	24148	N	N	N	1	CUSTOMER ISSUE	-
DMS_18230	24149	N	N	N	1	CUSTOMER ISSUE	-
DMS_18231	24150	N	N	N	1	CUSTOMER ISSUE	-
DMS_18232	24151	N	N	N	1	CUSTOMER ISSUE	-
DMS_18233	24152	N	N	N	1	CUSTOMER ISSUE	-
DMS_18234	24153	N	N	N	1	CUSTOMER ISSUE	-
DMS_18235	24154	N	N	N	1	CUSTOMER ISSUE	-
DMS_18236	24155	N	N	N	1	CUSTOMER ISSUE	-
DMS_18237	24156	N	N	N	1	CUSTOMER ISSUE	-
DMS_18238	24157	N	N	N	1	CUSTOMER ISSUE	-
DMS_18239	24158	N	N	N	1	CUSTOMER ISSUE	-
DMS_18240	24159	N	N	N	1	CUSTOMER ISSUE	-
DMS_18241	24160	N	N	N	1	CUSTOMER ISSUE	-
DMS_18242	24161	N	N	N	1	CUSTOMER ISSUE	-
DMS_18243	24162	N	N	N	1	CUSTOMER ISSUE	-
DMS_18244	24163	N	N	N	1	CUSTOMER ISSUE	-
DMS_18245	24164	N	N	N	1	CUSTOMER ISSUE	-
DMS_18246	24165	N	N	N	1	CUSTOMER ISSUE	-
DMS_18247	24166	N	N	N	1	CUSTOMER ISSUE	-
DMS_18248	24167	N	N	N	1	CUSTOMER ISSUE	-
DMS_18249	24168	N	N	N	1	CUSTOMER ISSUE	-
DMS_18250	24169	N	N	N	1	CUSTOMER ISSUE	-
DMS_18251	24170	N	N	N	1	CUSTOMER ISSUE	-
DMS_18252	24171	N	N	N	1	CUSTOMER ISSUE	-
DMS_18253	24172	N	N	N	1	CUSTOMER ISSUE	-
DMS_18254	24173	N	N	N	1	CUSTOMER ISSUE	-
DMS_18255	24174	N	N	N	1	CUSTOMER ISSUE	-
DMS_18256	24175	N	N	N	1	CUSTOMER ISSUE	-
DMS_18257	24176	N	N	N	1	CUSTOMER ISSUE	-
DMS_18258	24177	N	N	N	1	CUSTOMER ISSUE	-
DMS_18259	24178	N	N	N	1	CUSTOMER ISSUE	-
DMS_18260	24179	N	N	N	1	CUSTOMER ISSUE	-
DMS_18261	24180	N	N	N	1	CUSTOMER ISSUE	-
DMS_18262	24181	N	N	N	1	CUSTOMER ISSUE	-
DMS_18263	24182	N	N	N	1	CUSTOMER ISSUE	-
DMS_18264	24183	N	N	N	1	CUSTOMER ISSUE	-
DMS_18265	24184	N	N	N	1	CUSTOMER ISSUE	-
DMS_18266	24185	N	N	N	1	CUSTOMER ISSUE	-
DMS_18267	24186	N	N	N	1	CUSTOMER ISSUE	-
DMS_18268	24187	N	N	N	1	CUSTOMER ISSUE	-
DMS_18269	24188	N	N	N	1	CUSTOMER ISSUE	-
DMS_18270	24189	N	N	N	1	CUSTOMER ISSUE	-
DMS_18271	24190	N	N	N	1	CUSTOMER ISSUE	-
DMS_18272	24191	N	N	N	1	CUSTOMER ISSUE	-
DMS_18273	24192	N	N	N	1	CUSTOMER ISSUE	-
DMS_18274	24193	N	N	N	1	CUSTOMER ISSUE	-
DMS_18275	24194	N	N	N	1	CUSTOMER ISSUE	-
DMS_18276	24195	N	N	N	1	CUSTOMER ISSUE	-
DMS_18277	24196	N	N	N	1	CUSTOMER ISSUE	-
DMS_18278	24197	N	N	N	1	CUSTOMER ISSUE	-
DMS_18279	24198	N	N	N	1	CUSTOMER ISSUE	-
DMS_18280	24199	N	N	N	1	CUSTOMER ISSUE	-
DMS_18281	24200	N	N	N	1	CUSTOMER ISSUE	-
DMS_18282	24201	N	N	N	1	CUSTOMER ISSUE	-
DMS_18283	24202	N	N	N	1	CUSTOMER ISSUE	-
DMS_18284	24203	N	N	N	1	CUSTOMER ISSUE	-
DMS_18285	24204	N	N	N	1	CUSTOMER ISSUE	-
DMS_18286	24205	N	N	N	1	CUSTOMER ISSUE	-
DMS_18287	24206	N	N	N	1	CUSTOMER ISSUE	-
DMS_18288	24207	N	N	N	1	CUSTOMER ISSUE	-
DMS_18291	24208	N	N	N	1	CUSTOMER ISSUE	-
DMS_18292	24209	N	N	N	1	CUSTOMER ISSUE	-
DMS_18293	24210	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18294	24211	N	N	N	1	CUSTOMER ISSUE	-
DMS_18295	24212	N	N	N	1	CUSTOMER ISSUE	-
DMS_18296	24213	N	N	N	1	CUSTOMER ISSUE	-
DMS_18297	24214	N	N	N	1	CUSTOMER ISSUE	-
DMS_18298	24215	N	N	N	1	CUSTOMER ISSUE	-
DMS_18299	24216	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_18300	24217	N	N	N	1	CUSTOMER ISSUE	-
DMS_18301	24218	N	N	N	1	CUSTOMER ISSUE	-
DMS_18302	24219	N	N	N	1	CUSTOMER ISSUE	-
DMS_18303	24220	N	N	N	1	CUSTOMER ISSUE	-
DMS_18304	24221	N	N	N	1	CUSTOMER ISSUE	-
DMS_18305	24222	N	N	N	1	CUSTOMER ISSUE	-
DMS_18306	24223	N	N	N	1	CUSTOMER ISSUE	-
DMS_18308	24224	N	N	N	1	CUSTOMER ISSUE	-
DMS_18309	24225	N	N	N	1	CUSTOMER ISSUE	-
DMS_18310	24226	N	N	N	1	CUSTOMER ISSUE	-
DMS_18311	24227	N	N	N	1	CUSTOMER ISSUE	-
DMS_18312	24228	N	N	N	1	CUSTOMER ISSUE	-
DMS_18313	24229	N	N	N	1	CUSTOMER ISSUE	-
DMS_18314	24230	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18315	24231	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18316	24232	N	N	N	1	CUSTOMER ISSUE	-
DMS_18317	24233	N	N	N	1	CUSTOMER ISSUE	-
DMS_18318	24234	N	N	N	1	CUSTOMER ISSUE	-
DMS_18319	24235	N	N	N	1	CUSTOMER ISSUE	-
DMS_18320	24236	N	N	N	1	CUSTOMER ISSUE	-
DMS_18321	24237	N	N	N	1	CUSTOMER ISSUE	-
DMS_18322	24238	N	N	N	2	CUSTOMER ISSUE	-
DMS_18323	24239	N	N	N	1	CUSTOMER ISSUE	-
DMS_18324	24240	N	N	N	1	CUSTOMER ISSUE	-
DMS_18325	24241	N	N	N	1	CUSTOMER ISSUE	-
DMS_18326	24242	N	N	N	1	CUSTOMER ISSUE	-
DMS_18327	24243	N	N	N	1	CUSTOMER ISSUE	-
DMS_18328	24244	N	N	N	1	CUSTOMER ISSUE	-
DMS_18329	24245	N	N	N	1	CUSTOMER ISSUE	-
DMS_18330	24246	N	N	N	1	CUSTOMER ISSUE	-
DMS_18331	24247	N	N	N	2	CUSTOMER ISSUE	-
DMS_18332	24248	N	N	N	1	CUSTOMER ISSUE	-
DMS_18333	24249	N	N	N	1	CUSTOMER ISSUE	-
DMS_18334	24250	N	N	N	1	CUSTOMER ISSUE	-
DMS_18335	24251	N	N	N	1	CUSTOMER ISSUE	-
DMS_18336	24252	N	N	N	1	CUSTOMER ISSUE	-
DMS_18337	24253	N	N	N	1	CUSTOMER ISSUE	-
DMS_18338	24254	N	N	N	1	CUSTOMER ISSUE	-
DMS_18339	24255	N	N	N	1	CUSTOMER ISSUE	-
DMS_18340	24256	N	N	N	1	CUSTOMER ISSUE	-
DMS_18341	24257	N	N	N	1	CUSTOMER ISSUE	-
DMS_18342	24258	N	N	N	1	CUSTOMER ISSUE	-
DMS_18343	24259	N	N	N	1	CUSTOMER ISSUE	-
DMS_18344	24260	N	N	N	1	CUSTOMER ISSUE	-
DMS_18345	24261	N	N	N	1	CUSTOMER ISSUE	-
DMS_18346	24262	N	N	N	1	CUSTOMER ISSUE	-
DMS_18347	24263	N	N	N	1	CUSTOMER ISSUE	-
DMS_18348	24264	N	N	N	1	CUSTOMER ISSUE	-
DMS_18349	24265	N	N	N	1	CUSTOMER ISSUE	-
DMS_18350	24266	N	N	N	1	CUSTOMER ISSUE	-
DMS_18351	24267	N	N	N	1	CUSTOMER ISSUE	-
DMS_18352	24268	N	N	N	1	CUSTOMER ISSUE	-
DMS_18353	24269	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18354	24270	N	N	N	1	CUSTOMER ISSUE	-
DMS_18355	24271	N	N	N	1	CUSTOMER ISSUE	-
DMS_18356	24272	N	N	N	1	CUSTOMER ISSUE	-
DMS_18362	24273	N	N	N	1	CUSTOMER ISSUE	-
DMS_18363	24274	N	N	N	1	CUSTOMER ISSUE	-
DMS_18364	24275	N	N	N	1	CUSTOMER ISSUE	-
DMS_18365	24276	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18366	24277	N	N	N	1	CUSTOMER ISSUE	-
DMS_18367	24278	N	N	N	1	CUSTOMER ISSUE	-
DMS_18368	24279	N	N	N	1	CUSTOMER ISSUE	-
DMS_18369	24280	N	N	N	1	CUSTOMER ISSUE	-
DMS_18370	24281	N	N	N	1	CUSTOMER ISSUE	-
DMS_18371	24282	N	N	N	1	CUSTOMER ISSUE	-
DMS_18372	24283	N	N	N	1	CUSTOMER ISSUE	-
DMS_18373	24284	N	N	N	1	CUSTOMER ISSUE	-
DMS_18374	24285	N	N	N	1	CUSTOMER ISSUE	-
DMS_18375	24286	N	N	N	2	CUSTOMER ISSUE	-
DMS_18376	24287	N	N	N	1	CUSTOMER ISSUE	-
DMS_18377	24288	N	N	N	1	CUSTOMER ISSUE	-
DMS_18378	24289	N	N	N	1	CUSTOMER ISSUE	-
DMS_18379	24290	N	N	N	1	CUSTOMER ISSUE	-
DMS_18380	24291	N	N	N	1	CUSTOMER ISSUE	-
DMS_18381	24292	N	N	N	1	CUSTOMER ISSUE	-
DMS_18382	24293	N	N	N	1	CUSTOMER ISSUE	-
DMS_18383	24294	N	N	N	1	CUSTOMER ISSUE	-
DMS_18384	24295	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18385	24296	N	N	N	1	CUSTOMER ISSUE	-

DMS_18386	24297	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18387	24298	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18388	24299	N	N	N	1	CUSTOMER ISSUE	-
DMS_18389	24300	N	N	N	1	CUSTOMER ISSUE	-
DMS_18390	24301	N	N	N	1	CUSTOMER ISSUE	-
DMS_18391	24302	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18392	24303	N	N	N	1	CUSTOMER ISSUE	-
DMS_18393	24304	N	N	N	1	CUSTOMER ISSUE	-
DMS_18394	24305	N	N	N	1	CUSTOMER ISSUE	-
DMS_18395	24306	N	N	N	1	CUSTOMER ISSUE	-
DMS_18396	24307	N	N	N	1	CUSTOMER ISSUE	-
DMS_18397	24308	N	N	N	1	CUSTOMER ISSUE	-
DMS_18398	24309	N	N	N	1	CUSTOMER ISSUE	-
DMS_18399	24310	N	N	N	1	CUSTOMER ISSUE	-
DMS_18400	24311	N	N	N	1	CUSTOMER ISSUE	-
DMS_18401	24312	N	N	N	1	CUSTOMER ISSUE	-
DMS_18402	24313	N	N	N	1	CUSTOMER ISSUE	-
DMS_18403	24314	N	N	N	1	CUSTOMER ISSUE	-
DMS_18404	24315	N	N	N	2	CUSTOMER ISSUE	-
DMS_18405	24316	N	N	N	1	CUSTOMER ISSUE	-
DMS_18406	24317	N	N	N	1	CUSTOMER ISSUE	-
DMS_18407	24318	N	N	N	1	CUSTOMER ISSUE	-
DMS_18408	24319	N	N	N	1	CUSTOMER ISSUE	-
DMS_18409	24320	N	N	N	1	CUSTOMER ISSUE	-
DMS_18410	24321	N	N	N	1	CUSTOMER ISSUE	-
DMS_18411	24322	N	N	N	1	CUSTOMER ISSUE	-
DMS_18412	24323	N	N	N	1	CUSTOMER ISSUE	-
DMS_18413	24324	N	N	N	1	CUSTOMER ISSUE	-
DMS_18414	24325	N	N	N	1	CUSTOMER ISSUE	-
DMS_18415	24326	N	N	N	1	CUSTOMER ISSUE	-
DMS_18416	24327	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18417	24328	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_18418	24329	N	N	N	1	CUSTOMER ISSUE	-
DMS_18419	24330	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18420	24331	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18421	24332	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18422	24333	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18423	24334	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18425	24335	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18426	24336	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18427	24337	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18428	24338	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18429	24339	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18430	24340	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18431	24341	N	N	N	1	CUSTOMER ISSUE	-
DMS_18432	24342	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18433	24343	N	N	N	1	CUSTOMER ISSUE	-
DMS_18435	24344	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18439	24345	N	N	N	1	CUSTOMER ISSUE	-
DMS_18441	24346	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18442	24347	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18443	24348	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18444	24349	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18445	24350	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18447	24351	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18448	24352	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18449	24353	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18450	24354	N	N	N	1	CUSTOMER ISSUE	-
DMS_18451	24355	N	N	N	1	CUSTOMER ISSUE	-
DMS_18452	24356	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18454	24357	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18455	24358	N	N	N	1	CUSTOMER ISSUE	-
DMS_18456	24359	N	N	N	1	CUSTOMER ISSUE	-
DMS_18457	24360	N	N	N	1	CUSTOMER ISSUE	-
DMS_18458	24361	N	N	N	1	CUSTOMER ISSUE	-
DMS_18459	24362	N	N	N	1	CUSTOMER ISSUE	-
DMS_18460	24363	N	N	N	1	CUSTOMER ISSUE	-
DMS_18461	24364	N	N	N	1	CUSTOMER ISSUE	-
DMS_18462	24365	N	N	N	1	CUSTOMER ISSUE	-
DMS_18463	24366	N	N	N	1	CUSTOMER ISSUE	-
DMS_18464	24367	N	N	N	1	CUSTOMER ISSUE	-
DMS_18465	24368	N	N	N	1	CUSTOMER ISSUE	-
DMS_18466	24369	N	N	N	1	CUSTOMER ISSUE	-
DMS_18467	24370	N	N	N	1	CUSTOMER ISSUE	-
DMS_18468	24371	N	N	N	1	CUSTOMER ISSUE	-
DMS_18469	24372	N	N	N	1	CUSTOMER ISSUE	-
DMS_18470	24373	N	N	N	1	CUSTOMER ISSUE	-
DMS_18471	24374	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18472	24375	N	N	N	1	CUSTOMER ISSUE	-
DMS_18473	24376	N	N	N	1	CUSTOMER ISSUE	-

DMS_18474	24377	N	N	N	1	CUSTOMER ISSUE	-
DMS_18475	24378	N	N	N	1	CUSTOMER ISSUE	-
DMS_18476	24379	N	N	N	2	CUSTOMER ISSUE	-
DMS_18477	24380	N	N	N	1	CUSTOMER ISSUE	-
DMS_18478	24381	N	N	N	1	CUSTOMER ISSUE	-
DMS_18479	24382	N	N	N	1	CUSTOMER ISSUE	-
DMS_18480	24383	N	N	N	1	CUSTOMER ISSUE	-
DMS_18481	24384	N	N	N	1	CUSTOMER ISSUE	-
DMS_18482	24385	N	N	N	1	CUSTOMER ISSUE	-
DMS_18483	24386	N	N	N	1	CUSTOMER ISSUE	-
DMS_18484	24387	N	N	N	1	CUSTOMER ISSUE	-
DMS_18485	24388	N	N	N	1	CUSTOMER ISSUE	-
DMS_18486	24389	N	N	N	1	CUSTOMER ISSUE	-
DMS_18487	24390	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18488	24391	N	N	N	1	CUSTOMER ISSUE	-
DMS_18489	24392	N	N	N	1	CUSTOMER ISSUE	-
DMS_18490	24393	N	N	N	1	CUSTOMER ISSUE	-
DMS_18491	24394	N	N	N	1	CUSTOMER ISSUE	-
DMS_18492	24395	N	N	N	1	CUSTOMER ISSUE	-
DMS_18493	24396	N	N	N	1	CUSTOMER ISSUE	-
DMS_18494	24397	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18495	24398	N	N	N	1	CUSTOMER ISSUE	-
DMS_18496	24399	N	N	N	1	CUSTOMER ISSUE	-
DMS_18497	24400	N	N	N	1	CUSTOMER ISSUE	-
DMS_18498	24401	N	N	N	1	CUSTOMER ISSUE	-
DMS_18499	24402	N	N	N	1	CUSTOMER ISSUE	-
DMS_18500	24403	N	N	N	1	CUSTOMER ISSUE	-
DMS_18501	24404	N	N	N	1	CUSTOMER ISSUE	-
DMS_18502	24405	N	N	N	1	CUSTOMER ISSUE	-
DMS_18503	24406	N	N	N	1	CUSTOMER ISSUE	-
DMS_18504	24407	N	N	N	1	CUSTOMER ISSUE	-
DMS_18505	24408	N	N	N	1	CUSTOMER ISSUE	-
DMS_18506	24409	N	N	N	1	CUSTOMER ISSUE	-
DMS_18507	24410	N	N	N	1	CUSTOMER ISSUE	-
DMS_18508	24411	N	N	N	1	CUSTOMER ISSUE	-
DMS_18509	24412	N	N	N	1	CUSTOMER ISSUE	-
DMS_18510	24413	N	N	N	1	CUSTOMER ISSUE	-
DMS_18511	24414	N	N	N	1	CUSTOMER ISSUE	-
DMS_18512	24415	N	N	N	1	CUSTOMER ISSUE	-
DMS_18513	24416	N	N	N	1	CUSTOMER ISSUE	-
DMS_18514	24417	N	N	N	1	CUSTOMER ISSUE	-
DMS_18515	24418	N	N	N	1	CUSTOMER ISSUE	-
DMS_18516	24419	N	N	N	1	CUSTOMER ISSUE	-
DMS_18517	24420	N	N	N	1	CUSTOMER ISSUE	-
DMS_18518	24421	N	N	N	1	CUSTOMER ISSUE	-
DMS_18519	24422	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18520	24423	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18521	24424	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18522	24425	N	N	N	1	CUSTOMER ISSUE	-
DMS_18523	24426	N	N	N	1	CUSTOMER ISSUE	-
DMS_18524	24427	N	N	N	2	CUSTOMER ISSUE	-
DMS_18525	24428	N	N	N	1	CUSTOMER ISSUE	-
DMS_18526	24429	N	N	N	1	CUSTOMER ISSUE	-
DMS_18529	24430	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_18530	24431	N	N	N	1	CUSTOMER ISSUE	-
DMS_18531	24432	N	N	N	1	CUSTOMER ISSUE	-
DMS_18533	24433	N	N	N	1	CUSTOMER ISSUE	-
DMS_18534	24434	N	N	N	1	CUSTOMER ISSUE	-
DMS_18559	24435	N	N	N	1	CUSTOMER ISSUE	-
DMS_18560	24436	N	N	N	1	CUSTOMER ISSUE	-
DMS_18565	24437	N	N	N	3	CUSTOMER ISSUE	-
DMS_18566	24438	N	N	N	1	CUSTOMER ISSUE	-
DMS_18573	24439	N	N	N	1	CUSTOMER ISSUE	-
DMS_18574	24440	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18575	24441	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18581	24442	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18584	24443	N	N	N	1	CUSTOMER ISSUE	-
DMS_18589	24444	N	N	N	1	CUSTOMER ISSUE	-
DMS_18590	24445	N	N	N	1	CUSTOMER ISSUE	-
DMS_18591	24446	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_18595	24447	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_18602	24448	N	N	N	1	CUSTOMER ISSUE	-
DMS_18605	24449	N	N	N	1	CUSTOMER ISSUE	-
DMS_18606	24450	N	N	N	1	CUSTOMER ISSUE	-
DMS_18607	24451	N	N	N	1	CUSTOMER ISSUE	-
DMS_18612	24452	N	N	N	1	CUSTOMER ISSUE	-
DMS_18636	24453	N	N	N	1	CUSTOMER ISSUE	-
DMS_18645	24454	N	N	N	1	CUSTOMER ISSUE	-
DMS_18646	24455	N	N	N	1	CUSTOMER ISSUE	-
DMS_18648	24456	N	N	N	1	CUSTOMER ISSUE	-

DMS_18649	24457	N	N	N	1	CUSTOMER ISSUE	-
DMS_18650	24458	N	N	N	1	CUSTOMER ISSUE	-
DMS_18651	24459	N	N	N	1	CUSTOMER ISSUE	-
DMS_18652	24460	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_18653	24461	N	N	N	1	CUSTOMER ISSUE	-
DMS_18654	24462	N	N	N	1	CUSTOMER ISSUE	-
DMS_18655	24463	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18656	24464	N	N	N	1	CUSTOMER ISSUE	-
DMS_18657	24465	N	N	N	1	CUSTOMER ISSUE	-
DMS_18685	24466	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18686	24467	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18687	24468	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18688	24469	N	N	N	1	CUSTOMER ISSUE	-
DMS_18689	24470	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_18690	24471	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_18692	24472	N	N	N	1	CUSTOMER ISSUE	-
DMS_18693	24473	N	N	N	1	CUSTOMER ISSUE	-
DMS_18694	24474	N	N	N	1	CUSTOMER ISSUE	-
DMS_18695	24475	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_18696	24476	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_18697	24477	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_18698	24478	N	N	N	1	CUSTOMER ISSUE	-
DMS_18699	24479	N	N	N	1	CUSTOMER ISSUE	-
DMS_18700	24480	N	N	N	1	CUSTOMER ISSUE	-
DMS_18701	24481	N	N	N	1	CUSTOMER ISSUE	-
DMS_18702	24482	N	N	N	1	CUSTOMER ISSUE	-
DMS_18703	24483	N	N	N	1	CUSTOMER ISSUE	-
DMS_18704	24484	N	N	N	1	CUSTOMER ISSUE	-
DMS_18705	24485	N	N	N	1	CUSTOMER ISSUE	-
DMS_18706	24486	N	N	N	1	CUSTOMER ISSUE	-
DMS_18707	24487	N	N	N	1	CUSTOMER ISSUE	-
DMS_18708	24488	N	N	N	1	CUSTOMER ISSUE	-
DMS_18709	24489	N	N	N	1	CUSTOMER ISSUE	-
DMS_18710	24490	N	N	N	1	CUSTOMER ISSUE	-
DMS_18711	24491	N	N	N	1	CUSTOMER ISSUE	-
DMS_18712	24492	N	N	N	1	CUSTOMER ISSUE	-
DMS_18713	24493	N	N	N	1	CUSTOMER ISSUE	-
DMS_18715	24494	N	N	N	1	CUSTOMER ISSUE	-
DMS_18716	24495	N	N	N	1	CUSTOMER ISSUE	-
DMS_18717	24496	N	N	N	1	CUSTOMER ISSUE	-
DMS_18718	24497	N	N	N	1	CUSTOMER ISSUE	-
DMS_18720	24498	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18721	24499	N	N	N	1	CUSTOMER ISSUE	-
DMS_18722	24500	N	N	N	1	CUSTOMER ISSUE	-
DMS_18723	24501	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18724	24502	N	N	N	1	CUSTOMER ISSUE	-
DMS_18725	24503	N	N	N	1	CUSTOMER ISSUE	-
DMS_18726	24504	N	N	N	1	CUSTOMER ISSUE	-
DMS_18727	24505	N	N	N	1	CUSTOMER ISSUE	-
DMS_18728	24506	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18729	24507	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18730	24508	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18731	24509	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18732	24510	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18733	24511	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18734	24512	N	N	N	1	CUSTOMER ISSUE	-
DMS_18735	24513	N	N	N	1	CUSTOMER ISSUE	-
DMS_18736	24514	N	N	N	1	CUSTOMER ISSUE	-
DMS_18737	24515	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_18738	24516	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_18740	24517	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18741	24518	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18742	24519	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18743	24520	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18744	24521	N	N	N	1	CUSTOMER ISSUE	-
DMS_18745	24522	N	N	N	1	CUSTOMER ISSUE	-
DMS_18746	24523	N	N	N	1	CUSTOMER ISSUE	-
DMS_18747	24524	N	N	N	1	CUSTOMER ISSUE	-
DMS_18749	24525	N	N	N	1	CUSTOMER ISSUE	-
DMS_18751	24526	N	N	N	1	CUSTOMER ISSUE	-
DMS_18752	24527	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18753	24528	N	N	N	1	CUSTOMER ISSUE	-
DMS_18754	24529	N	N	N	1	CUSTOMER ISSUE	-
DMS_18755	24530	N	N	N	1	CUSTOMER ISSUE	-
DMS_18756	24531	N	N	N	1	CUSTOMER ISSUE	-
DMS_18757	24532	N	N	N	1	CUSTOMER ISSUE	-
DMS_18758	24533	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18759	24534	N	N	N	1	CUSTOMER ISSUE	-
DMS_18760	24535	N	N	N	1	CUSTOMER ISSUE	-
DMS_18761	24536	N	N	N	1	CUSTOMER ISSUE	-

DMS_18762	24537	N	N	N	1	CUSTOMER ISSUE	-
DMS_18765	24538	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18766	24539	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18767	24540	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18768	24541	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18769	24542	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18770	24543	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18771	24544	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18772	24545	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18773	24546	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18774	24547	N	N	N	1	CUSTOMER ISSUE	-
DMS_18775	24548	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18776	24549	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18777	24550	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18778	24551	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18779	24552	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18780	24553	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18781	24554	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18782	24555	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18783	24556	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18784	24557	N	N	N	1	CUSTOMER ISSUE	-
DMS_18785	24558	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18786	24559	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18787	24560	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_18788	24561	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18789	24562	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18790	24563	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18791	24564	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18792	24565	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18793	24566	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18794	24567	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18795	24568	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18796	24569	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18797	24570	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18798	24571	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18799	24572	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18800	24573	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18801	24574	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18802	24575	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18803	24576	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18804	24577	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18805	24578	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18806	24579	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18807	24580	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18808	24581	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18809	24582	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18810	24583	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18811	24584	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18812	24585	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18813	24586	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18814	24587	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18815	24588	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18816	24589	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18817	24590	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18818	24591	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18819	24592	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18820	24593	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18821	24594	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18822	24595	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18823	24596	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18824	24597	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_18825	24598	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18826	24599	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18827	24600	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18828	24601	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18829	24602	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18830	24603	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18831	24604	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_18832	24605	N	N	N	1	CUSTOMER ISSUE	-
DMS_18833	24606	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18834	24607	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18835	24608	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18836	24609	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18837	24610	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_18838	24611	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18839	24612	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18840	24613	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18841	24614	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18842	24615	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18843	24616	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_18844	24617	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18845	24618	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18846	24619	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18847	24620	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18848	24621	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18849	24622	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18850	24623	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18851	24624	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_18852	24625	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18853	24626	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18854	24627	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18855	24628	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18856	24629	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18857	24630	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18858	24631	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18859	24632	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18860	24633	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18861	24634	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18862	24635	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18863	24636	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18864	24637	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18865	24638	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18866	24639	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18867	24640	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18868	24641	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18870	24642	N	N	N	1	CUSTOMER ISSUE	-
DMS_18871	24643	N	N	N	1	CUSTOMER ISSUE	-
DMS_18877	24644	N	N	Y	3	DIST - TREE TRIMMING	945
DMS_18879	24645	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18881	24646	N	N	N	1	CUSTOMER ISSUE	-
DMS_18890	24647	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18892	24648	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18894	24649	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18896	24650	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18900	24651	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18901	24652	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18902	24653	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18903	24654	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18904	24655	N	N	N	1	CUSTOMER ISSUE	-
DMS_18905	24656	N	N	N	1	CUSTOMER ISSUE	-
DMS_18907	24657	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18912	24658	N	N	N	1	CUSTOMER ISSUE	-
DMS_18914	24659	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18916	24660	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18918	24661	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_18920	24662	N	N	N	1	CUSTOMER ISSUE	-
DMS_18921	24663	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18922	24664	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18923	24665	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18924	24666	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18925	24667	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18926	24668	N	N	N	1	CUSTOMER ISSUE	-
DMS_18927	24669	N	N	N	1	CUSTOMER ISSUE	-
DMS_18928	24670	N	N	N	1	CUSTOMER ISSUE	-
DMS_18929	24671	N	N	N	1	CUSTOMER ISSUE	-
DMS_18931	24672	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18933	24673	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18936	24674	N	N	N	1	CUSTOMER ISSUE	-
DMS_18937	24675	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18938	24676	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18939	24677	N	N	N	1	CUSTOMER ISSUE	-
DMS_18941	24678	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18942	24679	N	N	N	1	CUSTOMER ISSUE	-
DMS_18943	24680	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18944	24681	N	N	N	1	CUSTOMER ISSUE	-
DMS_18945	24682	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18946	24683	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18947	24684	N	N	N	1	CUSTOMER ISSUE	-
DMS_18948	24685	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18949	24686	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_18951	24687	N	N	N	1	CUSTOMER ISSUE	-
DMS_18954	24688	N	N	N	1	CUSTOMER ISSUE	-
DMS_18955	24689	N	N	N	1	CUSTOMER ISSUE	-
DMS_18956	24690	N	N	N	1	CUSTOMER ISSUE	-
DMS_18957	24691	N	N	N	1	CUSTOMER ISSUE	-
DMS_18958	24692	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18959	24693	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18960	24694	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18961	24695	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18962	24696	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_18963	24697	N	N	Y	1	TX - REPLACE	2500
DMS_18964	24698	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18965	24699	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18966	24700	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18967	24701	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18968	24702	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_18969	24703	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18970	24704	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18971	24705	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18972	24706	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18975	24707	N	N	N	1	CUSTOMER ISSUE	-
DMS_18976	24708	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_18977	24709	N	N	N	1	CUSTOMER ISSUE	-
DMS_18979	24710	N	N	N	1	CUSTOMER ISSUE	-
DMS_18980	24711	N	N	N	1	CUSTOMER ISSUE	-
DMS_18981	24712	N	N	N	1	CUSTOMER ISSUE	-
DMS_18982	24713	N	N	N	1	CUSTOMER ISSUE	-
DMS_18983	24714	N	N	N	1	CUSTOMER ISSUE	-
DMS_18984	24715	N	N	N	1	CUSTOMER ISSUE	-
DMS_18985	24716	N	N	N	1	CUSTOMER ISSUE	-
DMS_18986	24717	N	N	N	1	CUSTOMER ISSUE	-
DMS_18988	24718	N	N	N	1	CUSTOMER ISSUE	-
DMS_18989	24719	N	N	N	1	CUSTOMER ISSUE	-
DMS_18990	24720	N	N	N	1	CUSTOMER ISSUE	-
DMS_18991	24721	N	N	N	1	CUSTOMER ISSUE	-
DMS_18993	24722	N	N	N	1	CUSTOMER ISSUE	-
DMS_18994	24723	N	N	N	1	CUSTOMER ISSUE	-
DMS_18995	24724	N	N	N	1	CUSTOMER ISSUE	-
DMS_18996	24725	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_18997	24726	N	N	N	1	CUSTOMER ISSUE	-
DMS_18998	24727	N	N	N	1	CUSTOMER ISSUE	-
DMS_18999	24728	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19000	24729	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19001	24730	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
DMS_19002	24731	N	N	N	1	CUSTOMER ISSUE	-
DMS_19003	24732	N	N	N	1	CUSTOMER ISSUE	-
DMS_19005	24733	N	N	N	1	CUSTOMER ISSUE	-
DMS_19006	24734	N	N	N	1	CUSTOMER ISSUE	-
DMS_19007	24735	N	N	N	1	CUSTOMER ISSUE	-
DMS_19008	24736	N	N	N	1	CUSTOMER ISSUE	-
DMS_19009	24737	N	N	N	1	CUSTOMER ISSUE	-
DMS_19010	24738	N	N	N	1	CUSTOMER ISSUE	-
DMS_19011	24739	N	N	N	1	CUSTOMER ISSUE	-
DMS_19013	24740	N	N	N	1	CUSTOMER ISSUE	-
DMS_19014	24741	N	N	N	1	CUSTOMER ISSUE	-
DMS_19016	24742	N	N	N	1	CUSTOMER ISSUE	-
DMS_19017	24743	N	N	N	1	CUSTOMER ISSUE	-
DMS_19018	24744	N	N	N	1	CUSTOMER ISSUE	-
DMS_19019	24745	N	N	N	1	CUSTOMER ISSUE	-
DMS_19020	24746	N	N	N	1	CUSTOMER ISSUE	-
DMS_19021	24747	N	N	N	1	CUSTOMER ISSUE	-
DMS_19022	24748	N	N	N	1	CUSTOMER ISSUE	-
DMS_19023	24749	N	N	N	1	CUSTOMER ISSUE	-
DMS_19024	24750	N	N	N	1	CUSTOMER ISSUE	-
DMS_19025	24751	N	N	N	1	CUSTOMER ISSUE	-
DMS_19026	24752	N	N	N	1	CUSTOMER ISSUE	-
DMS_19027	24753	N	N	N	1	CUSTOMER ISSUE	-
DMS_19028	24754	N	N	N	1	CUSTOMER ISSUE	-
DMS_19029	24755	N	N	N	1	CUSTOMER ISSUE	-
DMS_19030	24756	N	N	N	1	CUSTOMER ISSUE	-
DMS_19031	24757	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19032	24758	N	N	N	1	CUSTOMER ISSUE	-
DMS_19033	24759	N	N	N	1	CUSTOMER ISSUE	-
DMS_19034	24760	N	N	N	1	CUSTOMER ISSUE	-
DMS_19035	24761	N	N	N	1	CUSTOMER ISSUE	-
DMS_19036	24762	N	N	N	1	CUSTOMER ISSUE	-
DMS_19038	24763	N	N	N	1	CUSTOMER ISSUE	-
DMS_19039	24764	N	N	N	1	CUSTOMER ISSUE	-
DMS_19040	24765	N	N	N	1	CUSTOMER ISSUE	-
DMS_19041	24766	N	N	N	1	CUSTOMER ISSUE	-
DMS_19042	24767	N	N	N	1	CUSTOMER ISSUE	-
DMS_19043	24768	N	N	N	1	CUSTOMER ISSUE	-
DMS_19044	24769	N	N	N	1	CUSTOMER ISSUE	-
DMS_19045	24770	N	N	N	1	CUSTOMER ISSUE	-
DMS_19046	24771	N	N	N	1	CUSTOMER ISSUE	-
DMS_19047	24772	N	N	N	1	CUSTOMER ISSUE	-
DMS_19048	24773	N	N	N	1	CUSTOMER ISSUE	-
DMS_19049	24774	N	N	N	1	CUSTOMER ISSUE	-
DMS_19050	24775	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19051	24776	N	N	N	1	CUSTOMER ISSUE	-

DMS_19052	24777	N	N	N	1	CUSTOMER ISSUE	-
DMS_19053	24778	N	N	N	1	CUSTOMER ISSUE	-
DMS_19054	24779	N	N	N	1	CUSTOMER ISSUE	-
DMS_19055	24780	N	N	N	1	CUSTOMER ISSUE	-
DMS_19056	24781	N	N	N	1	CUSTOMER ISSUE	-
DMS_19057	24782	N	N	N	1	CUSTOMER ISSUE	-
DMS_19058	24783	N	N	N	1	CUSTOMER ISSUE	-
DMS_19059	24784	N	N	N	1	CUSTOMER ISSUE	-
DMS_19060	24785	N	N	N	1	CUSTOMER ISSUE	-
DMS_19061	24786	N	N	N	1	CUSTOMER ISSUE	-
DMS_19062	24787	N	N	N	1	CUSTOMER ISSUE	-
DMS_19063	24788	N	N	N	1	CUSTOMER ISSUE	-
DMS_19064	24789	N	N	N	1	CUSTOMER ISSUE	-
DMS_19065	24790	N	N	N	1	CUSTOMER ISSUE	-
DMS_19066	24791	N	N	N	1	CUSTOMER ISSUE	-
DMS_19067	24792	N	N	N	1	CUSTOMER ISSUE	-
DMS_19068	24793	N	N	N	1	CUSTOMER ISSUE	-
DMS_19069	24794	N	N	N	1	CUSTOMER ISSUE	-
DMS_19070	24795	N	N	N	1	CUSTOMER ISSUE	-
DMS_19071	24796	N	N	N	1	CUSTOMER ISSUE	-
DMS_19072	24797	N	N	N	1	CUSTOMER ISSUE	-
DMS_19074	24798	N	N	N	1	CUSTOMER ISSUE	-
DMS_19075	24799	N	N	N	1	CUSTOMER ISSUE	-
DMS_19076	24800	N	N	N	1	CUSTOMER ISSUE	-
DMS_19077	24801	N	N	N	1	CUSTOMER ISSUE	-
DMS_19078	24802	N	N	N	1	CUSTOMER ISSUE	-
DMS_19079	24803	N	N	N	1	CUSTOMER ISSUE	-
DMS_19080	24804	N	N	N	1	CUSTOMER ISSUE	-
DMS_19081	24805	N	N	N	1	CUSTOMER ISSUE	-
DMS_19082	24806	N	N	N	1	CUSTOMER ISSUE	-
DMS_19083	24807	N	N	N	1	CUSTOMER ISSUE	-
DMS_19084	24808	N	N	N	1	CUSTOMER ISSUE	-
DMS_19085	24809	N	N	N	1	CUSTOMER ISSUE	-
DMS_19086	24810	N	N	N	1	CUSTOMER ISSUE	-
DMS_19087	24811	N	N	N	1	CUSTOMER ISSUE	-
DMS_19088	24812	N	N	N	1	CUSTOMER ISSUE	-
DMS_19089	24813	N	N	N	1	CUSTOMER ISSUE	-
DMS_19090	24814	N	N	N	1	CUSTOMER ISSUE	-
DMS_19091	24815	N	N	N	1	CUSTOMER ISSUE	-
DMS_19092	24816	N	N	N	1	CUSTOMER ISSUE	-
DMS_19093	24817	N	N	N	1	CUSTOMER ISSUE	-
DMS_19094	24818	N	N	N	1	CUSTOMER ISSUE	-
DMS_19095	24819	N	N	N	1	CUSTOMER ISSUE	-
DMS_19096	24820	N	N	N	1	CUSTOMER ISSUE	-
DMS_19098	24821	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19099	24822	N	N	N	1	CUSTOMER ISSUE	-
DMS_19101	24823	N	N	N	1	CUSTOMER ISSUE	-
DMS_19102	24824	N	N	N	1	CUSTOMER ISSUE	-
DMS_19103	24825	N	N	N	1	CUSTOMER ISSUE	-
DMS_19104	24826	N	N	N	1	CUSTOMER ISSUE	-
DMS_19105	24827	N	N	N	1	CUSTOMER ISSUE	-
DMS_19106	24828	N	N	N	1	CUSTOMER ISSUE	-
DMS_19107	24829	N	N	N	1	CUSTOMER ISSUE	-
DMS_19108	24830	N	N	N	1	CUSTOMER ISSUE	-
DMS_19109	24831	N	N	N	1	CUSTOMER ISSUE	-
DMS_19110	24832	N	N	N	1	CUSTOMER ISSUE	-
DMS_19111	24833	N	N	N	1	CUSTOMER ISSUE	-
DMS_19114	24834	N	N	N	1	CUSTOMER ISSUE	-
DMS_19115	24835	N	N	N	1	CUSTOMER ISSUE	-
DMS_19116	24836	N	N	N	1	CUSTOMER ISSUE	-
DMS_19117	24837	N	N	N	1	CUSTOMER ISSUE	-
DMS_19118	24838	N	N	N	1	CUSTOMER ISSUE	-
DMS_19119	24839	N	N	N	1	CUSTOMER ISSUE	-
DMS_19120	24840	N	N	N	1	CUSTOMER ISSUE	-
DMS_19121	24841	N	N	N	1	CUSTOMER ISSUE	-
DMS_19122	24842	N	N	N	1	CUSTOMER ISSUE	-
DMS_19123	24843	N	N	N	1	CUSTOMER ISSUE	-
DMS_19124	24844	N	N	N	1	CUSTOMER ISSUE	-
DMS_19125	24845	N	N	N	1	CUSTOMER ISSUE	-
DMS_19126	24846	N	N	N	1	CUSTOMER ISSUE	-
DMS_19127	24847	N	N	N	1	CUSTOMER ISSUE	-
DMS_19128	24848	N	N	N	1	CUSTOMER ISSUE	-
DMS_19129	24849	N	N	N	1	CUSTOMER ISSUE	-
DMS_19130	24850	N	N	N	1	CUSTOMER ISSUE	-
DMS_19131	24851	N	N	N	1	CUSTOMER ISSUE	-
DMS_19132	24852	N	N	Y	1	TX - REPLACE	2500
DMS_19133	24853	N	N	N	1	CUSTOMER ISSUE	-
DMS_19134	24854	N	N	N	1	CUSTOMER ISSUE	-
DMS_19135	24855	N	N	N	1	CUSTOMER ISSUE	-
DMS_19136	24856	N	N	N	1	CUSTOMER ISSUE	-

DMS_19137	24857	N	N	N	1	CUSTOMER ISSUE	-
DMS_19138	24858	N	N	N	1	CUSTOMER ISSUE	-
DMS_19139	24859	N	N	N	1	CUSTOMER ISSUE	-
DMS_19140	24860	N	N	N	1	CUSTOMER ISSUE	-
DMS_19141	24861	N	N	N	1	CUSTOMER ISSUE	-
DMS_19142	24862	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19143	24863	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19144	24864	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19145	24865	N	N	N	1	CUSTOMER ISSUE	-
DMS_19146	24866	N	N	N	1	CUSTOMER ISSUE	-
DMS_19147	24867	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_19148	24868	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_19150	24869	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_19153	24870	N	N	Y	1	DIST - CIRCUIT RETURN TO NORMAL CONFIG	472.5
DMS_19155	24871	N	N	N	1	CUSTOMER ISSUE	-
DMS_19156	24872	N	N	N	1	CUSTOMER ISSUE	-
DMS_19167	24873	N	N	N	1	CUSTOMER ISSUE	-
DMS_19169	24874	N	N	N	1	CUSTOMER ISSUE	-
DMS_19170	24875	N	N	N	1	CUSTOMER ISSUE	-
DMS_19172	24876	N	N	N	1	CUSTOMER ISSUE	-
DMS_19173	24877	N	N	N	1	CUSTOMER ISSUE	-
DMS_19174	24878	N	N	N	1	CUSTOMER ISSUE	-
DMS_19178	24879	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19180	24880	N	N	N	2	CUSTOMER ISSUE	-
DMS_19181	24881	N	N	N	1	CUSTOMER ISSUE	-
DMS_19182	24882	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19183	24883	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19184	24884	N	N	N	1	CUSTOMER ISSUE	-
DMS_19186	24885	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19188	24886	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19194	24887	N	N	N	1	CUSTOMER ISSUE	-
DMS_19195	24888	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19196	24889	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19200	24890	N	N	N	1	CUSTOMER ISSUE	-
DMS_19201	24891	N	N	N	1	CUSTOMER ISSUE	-
DMS_19202	24892	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19203	24893	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19204	24894	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19205	24895	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19206	24896	N	N	N	1	CUSTOMER ISSUE	-
DMS_19208	24897	N	N	N	1	CUSTOMER ISSUE	-
DMS_19209	24898	N	N	N	1	CUSTOMER ISSUE	-
DMS_19210	24899	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19211	24900	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19212	24901	N	N	N	2	CUSTOMER ISSUE	-
DMS_19213	24902	N	N	N	1	CUSTOMER ISSUE	-
DMS_19215	24903	N	N	N	1	CUSTOMER ISSUE	-
DMS_19219	24904	N	N	N	1	CUSTOMER ISSUE	-
DMS_19220	24905	N	N	N	1	CUSTOMER ISSUE	-
DMS_19222	24906	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19224	24907	N	N	N	1	CUSTOMER ISSUE	-
DMS_19227	24908	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19228	24909	N	N	N	1	CUSTOMER ISSUE	-
DMS_19229	24910	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19230	24911	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19231	24912	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19234	24913	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19236	24914	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19237	24915	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19238	24916	N	N	N	1	CUSTOMER ISSUE	-
DMS_19240	24917	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19241	24918	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19242	24919	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19243	24920	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19245	24921	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19246	24922	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19251	24923	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_19252	24924	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19257	24925	N	N	Y	1	TX - REPLACE	2500
DMS_19258	24926	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19259	24927	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19262	24928	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19263	24929	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19264	24930	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_19266	24931	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19267	24932	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19268	24933	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19269	24934	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19270	24935	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19271	24936	N	N	N	1	CUSTOMER ISSUE	-

DMS_19278	24937	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19279	24938	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19280	24939	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19281	24940	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19282	24941	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19283	24942	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19284	24943	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19285	24944	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19286	24945	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19287	24946	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19288	24947	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19289	24948	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19290	24949	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19291	24950	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19292	24951	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19293	24952	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19294	24953	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19295	24954	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19296	24955	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19297	24956	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19298	24957	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19299	24958	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19300	24959	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19301	24960	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19302	24961	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19303	24962	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19304	24963	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19305	24964	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19306	24965	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19307	24966	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19308	24967	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19309	24968	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19310	24969	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19311	24970	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19312	24971	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19313	24972	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19314	24973	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19315	24974	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19316	24975	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19317	24976	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19318	24977	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19319	24978	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19320	24979	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19321	24980	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19322	24981	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19323	24982	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19324	24983	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19325	24984	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19326	24985	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19327	24986	N	N	Y	1	TX - REPLACE	2500
DMS_19328	24987	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19329	24988	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19330	24989	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19331	24990	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19332	24991	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19333	24992	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19334	24993	N	N	N	1	CUSTOMER ISSUE	-
DMS_19335	24994	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19336	24995	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19337	24996	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19338	24997	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19339	24998	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19340	24999	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19342	25000	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19344	25001	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19347	25002	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19348	25003	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19349	25004	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19350	25005	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19351	25006	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19353	25007	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19354	25008	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19365	25009	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19366	25010	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19367	25011	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19368	25012	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19369	25013	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19370	25014	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19371	25015	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
DMS_19372	25016	N	N	Y	1	TX/SEC/SVC- REPLACE	3800

DMS_19373	25017	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19374	25018	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19375	25019	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19376	25020	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19377	25021	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19378	25022	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19379	25023	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19380	25024	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19382	25025	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19383	25026	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19384	25027	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19385	25028	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19386	25029	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19388	25030	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19389	25031	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19390	25032	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19391	25033	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19392	25034	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19393	25035	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19394	25036	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19395	25037	N	N	Y	1	TX - INSTALL	3000
DMS_19396	25038	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19397	25039	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19398	25040	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19399	25041	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19400	25042	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19401	25043	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19402	25044	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19404	25045	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19405	25046	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19407	25047	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19408	25048	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19409	25049	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19410	25050	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19411	25051	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19412	25052	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19413	25053	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19414	25054	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19415	25055	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19416	25056	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19417	25057	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19418	25058	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19420	25059	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19421	25060	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19422	25061	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19423	25062	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19424	25063	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19425	25064	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19428	25065	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19429	25066	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19430	25067	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19431	25068	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19432	25069	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19433	25070	N	N	N	1	CUSTOMER ISSUE	-
DMS_19434	25071	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_19435	25072	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_19436	25073	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19437	25074	N	N	N	1	CUSTOMER ISSUE	-
DMS_19438	25075	N	N	N	1	CUSTOMER ISSUE	-
DMS_19439	25076	N	N	N	1	CUSTOMER ISSUE	-
DMS_19440	25077	N	N	N	1	CUSTOMER ISSUE	-
DMS_19442	25078	N	N	N	1	CUSTOMER ISSUE	-
DMS_19443	25079	N	N	N	1	CUSTOMER ISSUE	-
DMS_19444	25080	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19445	25081	N	N	N	1	CUSTOMER ISSUE	-
DMS_19446	25082	N	N	N	1	CUSTOMER ISSUE	-
DMS_19447	25083	N	N	N	1	CUSTOMER ISSUE	-
DMS_19448	25084	N	N	N	1	CUSTOMER ISSUE	-
DMS_19449	25085	N	N	N	1	CUSTOMER ISSUE	-
DMS_19450	25086	N	N	N	1	CUSTOMER ISSUE	-
DMS_19451	25087	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19453	25088	N	N	N	1	CUSTOMER ISSUE	-
DMS_19454	25089	N	N	N	1	CUSTOMER ISSUE	-
DMS_19455	25090	N	N	N	1	CUSTOMER ISSUE	-
DMS_19456	25091	N	N	N	1	CUSTOMER ISSUE	-
DMS_19458	25092	N	N	N	1	CUSTOMER ISSUE	-
DMS_19459	25093	N	N	N	1	CUSTOMER ISSUE	-
DMS_19460	25094	N	N	N	1	CUSTOMER ISSUE	-
DMS_19461	25095	N	N	N	1	CUSTOMER ISSUE	-
DMS_19462	25096	N	N	N	1	CUSTOMER ISSUE	-

DMS_19463	25097	N	N	N	1	CUSTOMER ISSUE	-
DMS_19464	25098	N	N	N	1	CUSTOMER ISSUE	-
DMS_19465	25099	N	N	N	1	CUSTOMER ISSUE	-
DMS_19466	25100	N	N	N	1	CUSTOMER ISSUE	-
DMS_19467	25101	N	N	N	1	CUSTOMER ISSUE	-
DMS_19468	25102	N	N	N	1	CUSTOMER ISSUE	-
DMS_19469	25103	N	N	N	1	CUSTOMER ISSUE	-
DMS_19470	25104	N	N	N	1	CUSTOMER ISSUE	-
DMS_19471	25105	N	N	N	1	CUSTOMER ISSUE	-
DMS_19472	25106	N	N	N	1	CUSTOMER ISSUE	-
DMS_19473	25107	N	N	N	1	CUSTOMER ISSUE	-
DMS_19474	25108	N	N	N	1	CUSTOMER ISSUE	-
DMS_19475	25109	N	N	N	1	CUSTOMER ISSUE	-
DMS_19476	25110	N	N	N	1	CUSTOMER ISSUE	-
DMS_19477	25111	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19478	25112	N	N	N	1	CUSTOMER ISSUE	-
DMS_19479	25113	N	N	N	1	CUSTOMER ISSUE	-
DMS_19480	25114	N	N	N	1	CUSTOMER ISSUE	-
DMS_19481	25115	N	N	N	1	CUSTOMER ISSUE	-
DMS_19482	25116	N	N	N	1	CUSTOMER ISSUE	-
DMS_19483	25117	N	N	N	1	CUSTOMER ISSUE	-
DMS_19484	25118	N	N	N	1	CUSTOMER ISSUE	-
DMS_19485	25119	N	N	N	1	CUSTOMER ISSUE	-
DMS_19486	25120	N	N	N	1	CUSTOMER ISSUE	-
DMS_19487	25121	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19488	25122	N	N	N	1	CUSTOMER ISSUE	-
DMS_19489	25123	N	N	N	1	CUSTOMER ISSUE	-
DMS_19490	25124	N	N	N	1	CUSTOMER ISSUE	-
DMS_19491	25125	N	N	N	1	CUSTOMER ISSUE	-
DMS_19492	25126	N	N	N	1	CUSTOMER ISSUE	-
DMS_19493	25127	N	N	N	1	CUSTOMER ISSUE	-
DMS_19494	25128	N	N	N	1	CUSTOMER ISSUE	-
DMS_19495	25129	N	N	N	1	CUSTOMER ISSUE	-
DMS_19496	25130	N	N	N	1	CUSTOMER ISSUE	-
DMS_19497	25131	N	N	N	1	CUSTOMER ISSUE	-
DMS_19498	25132	N	N	N	1	CUSTOMER ISSUE	-
DMS_19499	25133	N	N	N	1	CUSTOMER ISSUE	-
DMS_19500	25134	N	N	N	1	CUSTOMER ISSUE	-
DMS_19501	25135	N	N	N	1	CUSTOMER ISSUE	-
DMS_19502	25136	N	N	N	1	CUSTOMER ISSUE	-
DMS_19503	25137	N	N	N	2	CUSTOMER ISSUE	-
DMS_19504	25138	N	N	N	1	CUSTOMER ISSUE	-
DMS_19505	25139	N	N	N	1	CUSTOMER ISSUE	-
DMS_19506	25140	N	N	N	1	CUSTOMER ISSUE	-
DMS_19507	25141	N	N	N	1	CUSTOMER ISSUE	-
DMS_19508	25142	N	N	N	1	CUSTOMER ISSUE	-
DMS_19509	25143	N	N	N	1	CUSTOMER ISSUE	-
DMS_19510	25144	N	N	N	1	CUSTOMER ISSUE	-
DMS_19511	25145	N	N	N	1	CUSTOMER ISSUE	-
DMS_19512	25146	N	N	N	1	CUSTOMER ISSUE	-
DMS_19513	25147	N	N	N	1	CUSTOMER ISSUE	-
DMS_19514	25148	N	N	N	1	CUSTOMER ISSUE	-
DMS_19515	25149	N	N	N	1	CUSTOMER ISSUE	-
DMS_19516	25150	N	N	N	1	CUSTOMER ISSUE	-
DMS_19517	25151	N	N	N	1	CUSTOMER ISSUE	-
DMS_19518	25152	N	N	N	1	CUSTOMER ISSUE	-
DMS_19519	25153	N	N	N	1	CUSTOMER ISSUE	-
DMS_19520	25154	N	N	N	1	CUSTOMER ISSUE	-
DMS_19521	25155	N	N	N	1	CUSTOMER ISSUE	-
DMS_19522	25156	N	N	N	1	CUSTOMER ISSUE	-
DMS_19523	25157	N	N	N	1	CUSTOMER ISSUE	-
DMS_19524	25158	N	N	N	1	CUSTOMER ISSUE	-
DMS_19525	25159	N	N	N	1	CUSTOMER ISSUE	-
DMS_19526	25160	N	N	N	1	CUSTOMER ISSUE	-
DMS_19527	25161	N	N	N	1	CUSTOMER ISSUE	-
DMS_19528	25162	N	N	N	1	CUSTOMER ISSUE	-
DMS_19529	25163	N	N	N	1	CUSTOMER ISSUE	-
DMS_19530	25164	N	N	N	1	CUSTOMER ISSUE	-
DMS_19531	25165	N	N	N	1	CUSTOMER ISSUE	-
DMS_19532	25166	N	N	N	1	CUSTOMER ISSUE	-
DMS_19533	25167	N	N	N	1	CUSTOMER ISSUE	-
DMS_19534	25168	N	N	N	1	CUSTOMER ISSUE	-
DMS_19535	25169	N	N	N	1	CUSTOMER ISSUE	-
DMS_19536	25170	N	N	N	1	CUSTOMER ISSUE	-
DMS_19537	25171	N	N	N	1	CUSTOMER ISSUE	-
DMS_19538	25172	N	N	N	1	CUSTOMER ISSUE	-
DMS_19539	25173	N	N	N	1	CUSTOMER ISSUE	-
DMS_19540	25174	N	N	N	1	CUSTOMER ISSUE	-
DMS_19541	25175	N	N	N	1	CUSTOMER ISSUE	-
DMS_19542	25176	N	N	N	1	CUSTOMER ISSUE	-

DMS_19543	25177	N	N	N	1	CUSTOMER ISSUE	-
DMS_19544	25178	N	N	N	1	CUSTOMER ISSUE	-
DMS_19545	25179	N	N	N	1	CUSTOMER ISSUE	-
DMS_19546	25180	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19547	25181	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19548	25182	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19549	25183	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19550	25184	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19553	25185	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19554	25186	N	N	N	1	CUSTOMER ISSUE	-
DMS_19555	25187	N	N	N	1	CUSTOMER ISSUE	-
DMS_19556	25188	N	N	N	1	CUSTOMER ISSUE	-
DMS_19558	25189	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19559	25190	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19561	25191	N	N	N	1	CUSTOMER ISSUE	-
DMS_19565	25192	N	N	N	1	CUSTOMER ISSUE	-
DMS_19566	25193	N	N	N	1	CUSTOMER ISSUE	-
DMS_19567	25194	N	N	N	1	CUSTOMER ISSUE	-
DMS_19569	25195	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19570	25196	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19571	25197	N	N	N	1	CUSTOMER ISSUE	-
DMS_19572	25198	N	N	N	1	CUSTOMER ISSUE	-
DMS_19574	25199	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_19578	25200	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19581	25201	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19586	25202	N	N	N	1	CUSTOMER ISSUE	-
DMS_19587	25203	N	N	N	1	CUSTOMER ISSUE	-
DMS_19588	25204	N	N	N	1	CUSTOMER ISSUE	-
DMS_19589	25205	N	N	N	1	CUSTOMER ISSUE	-
DMS_19592	25206	N	N	N	1	CUSTOMER ISSUE	-
DMS_19593	25207	N	N	N	1	CUSTOMER ISSUE	-
DMS_19594	25208	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_19595	25209	N	N	N	1	CUSTOMER ISSUE	-
DMS_19597	25210	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19600	25211	N	N	N	1	CUSTOMER ISSUE	-
DMS_19601	25212	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19602	25213	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19603	25214	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19604	25215	N	N	N	1	CUSTOMER ISSUE	-
DMS_19605	25216	N	N	N	1	CUSTOMER ISSUE	-
DMS_19606	25217	N	N	N	1	CUSTOMER ISSUE	-
DMS_19607	25218	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19608	25219	N	N	N	1	CUSTOMER ISSUE	-
DMS_19609	25220	N	N	N	1	CUSTOMER ISSUE	-
DMS_19610	25221	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
DMS_19613	25222	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19615	25223	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19616	25224	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19617	25225	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19618	25226	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19619	25227	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19620	25228	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_19621	25229	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19622	25230	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19623	25231	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19624	25232	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19625	25233	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19626	25234	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19627	25235	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19628	25236	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19629	25237	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19630	25238	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19631	25239	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19632	25240	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19633	25241	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19634	25242	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19640	25243	N	N	N	1	CUSTOMER ISSUE	-
DMS_19648	25244	N	N	N	1	CUSTOMER ISSUE	-
DMS_19649	25245	N	N	N	1	CUSTOMER ISSUE	-
DMS_19650	25246	N	N	N	1	CUSTOMER ISSUE	-
DMS_19651	25247	N	N	N	1	CUSTOMER ISSUE	-
DMS_19652	25248	N	N	N	1	CUSTOMER ISSUE	-
DMS_19653	25249	N	N	N	1	CUSTOMER ISSUE	-
DMS_19654	25250	N	N	N	1	CUSTOMER ISSUE	-
DMS_19655	25251	N	N	N	1	CUSTOMER ISSUE	-
DMS_19656	25252	N	N	N	1	CUSTOMER ISSUE	-
DMS_19657	25253	N	N	N	1	CUSTOMER ISSUE	-
DMS_19658	25254	N	N	N	1	CUSTOMER ISSUE	-
DMS_19659	25255	N	N	N	1	CUSTOMER ISSUE	-
DMS_19660	25256	N	N	N	1	CUSTOMER ISSUE	-

DMS_19661	25257	N	N	N	1	CUSTOMER ISSUE	-
DMS_19662	25258	N	N	N	1	CUSTOMER ISSUE	-
DMS_19663	25259	N	N	N	1	CUSTOMER ISSUE	-
DMS_19664	25260	N	N	N	1	CUSTOMER ISSUE	-
DMS_19665	25261	N	N	N	1	CUSTOMER ISSUE	-
DMS_19666	25262	N	N	N	1	CUSTOMER ISSUE	-
DMS_19667	25263	N	N	N	1	CUSTOMER ISSUE	-
DMS_19668	25264	N	N	N	1	CUSTOMER ISSUE	-
DMS_19670	25265	N	N	N	1	CUSTOMER ISSUE	-
DMS_19671	25266	N	N	N	1	CUSTOMER ISSUE	-
DMS_19672	25267	N	N	N	1	CUSTOMER ISSUE	-
DMS_19673	25268	N	N	N	1	CUSTOMER ISSUE	-
DMS_19674	25269	N	N	N	1	CUSTOMER ISSUE	-
DMS_19675	25270	N	N	N	1	CUSTOMER ISSUE	-
DMS_19676	25271	N	N	N	1	CUSTOMER ISSUE	-
DMS_19677	25272	N	N	N	1	CUSTOMER ISSUE	-
DMS_19678	25273	N	N	N	1	CUSTOMER ISSUE	-
DMS_19679	25274	N	N	N	1	CUSTOMER ISSUE	-
DMS_19680	25275	N	N	N	1	CUSTOMER ISSUE	-
DMS_19681	25276	N	N	N	1	CUSTOMER ISSUE	-
DMS_19682	25277	N	N	N	1	CUSTOMER ISSUE	-
DMS_19683	25278	N	N	N	1	CUSTOMER ISSUE	-
DMS_19684	25279	N	N	N	1	CUSTOMER ISSUE	-
DMS_19685	25280	N	N	N	1	CUSTOMER ISSUE	-
DMS_19686	25281	N	N	N	1	CUSTOMER ISSUE	-
DMS_19687	25282	N	N	N	1	CUSTOMER ISSUE	-
DMS_19688	25283	N	N	N	1	CUSTOMER ISSUE	-
DMS_19689	25284	N	N	N	1	CUSTOMER ISSUE	-
DMS_19690	25285	N	N	N	1	CUSTOMER ISSUE	-
DMS_19691	25286	N	N	N	1	CUSTOMER ISSUE	-
DMS_19692	25287	N	N	N	1	CUSTOMER ISSUE	-
DMS_19693	25288	N	N	N	1	CUSTOMER ISSUE	-
DMS_19694	25289	N	N	N	1	CUSTOMER ISSUE	-
DMS_19695	25290	N	N	N	1	CUSTOMER ISSUE	-
DMS_19696	25291	N	N	N	1	CUSTOMER ISSUE	-
DMS_19697	25292	N	N	N	1	CUSTOMER ISSUE	-
DMS_19699	25293	N	N	N	1	CUSTOMER ISSUE	-
DMS_19700	25294	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19701	25295	N	N	N	1	CUSTOMER ISSUE	-
DMS_19702	25296	N	N	N	1	CUSTOMER ISSUE	-
DMS_19703	25297	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19704	25298	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_19705	25299	N	N	N	1	CUSTOMER ISSUE	-
DMS_19706	25300	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19707	25301	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19708	25302	N	N	N	1	CUSTOMER ISSUE	-
DMS_19709	25303	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19710	25304	N	N	N	1	CUSTOMER ISSUE	-
DMS_19711	25305	N	N	N	1	CUSTOMER ISSUE	-
DMS_19712	25306	N	N	N	1	CUSTOMER ISSUE	-
DMS_19713	25307	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19714	25308	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19715	25309	N	N	N	1	CUSTOMER ISSUE	-
DMS_19716	25310	N	N	N	1	CUSTOMER ISSUE	-
DMS_19717	25311	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19718	25312	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19719	25313	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19720	25314	N	N	N	1	CUSTOMER ISSUE	-
DMS_19721	25315	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19722	25316	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19723	25317	N	N	N	1	CUSTOMER ISSUE	-
DMS_19724	25318	N	N	N	1	CUSTOMER ISSUE	-
DMS_19725	25319	N	N	N	1	CUSTOMER ISSUE	-
DMS_19726	25320	N	N	N	1	CUSTOMER ISSUE	-
DMS_19727	25321	N	N	N	1	CUSTOMER ISSUE	-
DMS_19728	25322	N	N	N	1	CUSTOMER ISSUE	-
DMS_19729	25323	N	N	N	1	CUSTOMER ISSUE	-
DMS_19730	25324	N	N	N	1	CUSTOMER ISSUE	-
DMS_19731	25325	N	N	N	1	CUSTOMER ISSUE	-
DMS_19732	25326	N	N	N	1	CUSTOMER ISSUE	-
DMS_19733	25327	N	N	N	1	CUSTOMER ISSUE	-
DMS_19734	25328	N	N	N	1	CUSTOMER ISSUE	-
DMS_19735	25329	N	N	N	1	CUSTOMER ISSUE	-
DMS_19736	25330	N	N	N	1	CUSTOMER ISSUE	-
DMS_19737	25331	N	N	N	1	CUSTOMER ISSUE	-
DMS_19738	25332	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19739	25333	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19740	25334	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19741	25335	N	N	N	1	CUSTOMER ISSUE	-
DMS_19742	25336	N	N	N	1	CUSTOMER ISSUE	-

DMS_19743	25337	N	N	N	1	CUSTOMER ISSUE	-
DMS_19744	25338	N	N	N	1	CUSTOMER ISSUE	-
DMS_19745	25339	N	N	N	1	CUSTOMER ISSUE	-
DMS_19746	25340	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19747	25341	N	N	N	1	CUSTOMER ISSUE	-
DMS_19748	25342	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19749	25343	N	N	N	1	CUSTOMER ISSUE	-
DMS_19750	25344	N	N	N	1	CUSTOMER ISSUE	-
DMS_19751	25345	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19752	25346	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19753	25347	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19754	25348	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19756	25349	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19758	25350	N	N	N	1	CUSTOMER ISSUE	-
DMS_19759	25351	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19760	25352	N	N	N	1	CUSTOMER ISSUE	-
DMS_19761	25353	N	N	N	1	CUSTOMER ISSUE	-
DMS_19762	25354	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19763	25355	N	N	N	1	CUSTOMER ISSUE	-
DMS_19764	25356	N	N	N	1	CUSTOMER ISSUE	-
DMS_19765	25357	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19766	25358	N	N	N	1	CUSTOMER ISSUE	-
DMS_19768	25359	N	N	N	1	CUSTOMER ISSUE	-
DMS_19769	25360	N	N	N	1	CUSTOMER ISSUE	-
DMS_19770	25361	N	N	N	1	CUSTOMER ISSUE	-
DMS_19778	25362	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19779	25363	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19780	25364	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19781	25365	N	N	N	1	CUSTOMER ISSUE	-
DMS_19782	25366	N	N	N	1	CUSTOMER ISSUE	-
DMS_19783	25367	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19784	25368	N	N	N	1	CUSTOMER ISSUE	-
DMS_19786	25369	N	N	N	1	CUSTOMER ISSUE	-
DMS_19788	25370	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19790	25371	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19793	25372	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19796	25373	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19797	25374	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19799	25375	N	N	N	1	CUSTOMER ISSUE	-
DMS_19800	25376	N	N	N	1	CUSTOMER ISSUE	-
DMS_19801	25377	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19802	25378	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19803	25379	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19804	25380	N	N	N	1	CUSTOMER ISSUE	-
DMS_19805	25381	N	N	N	1	CUSTOMER ISSUE	-
DMS_19806	25382	N	N	N	1	CUSTOMER ISSUE	-
DMS_19807	25383	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19808	25384	N	N	N	1	CUSTOMER ISSUE	-
DMS_19809	25385	N	N	N	1	CUSTOMER ISSUE	-
DMS_19810	25386	N	N	N	1	CUSTOMER ISSUE	-
DMS_19811	25387	N	N	N	1	CUSTOMER ISSUE	-
DMS_19812	25388	N	N	N	1	CUSTOMER ISSUE	-
DMS_19813	25389	N	N	N	1	CUSTOMER ISSUE	-
DMS_19814	25390	N	N	N	1	CUSTOMER ISSUE	-
DMS_19815	25391	N	N	N	1	CUSTOMER ISSUE	-
DMS_19816	25392	N	N	N	1	CUSTOMER ISSUE	-
DMS_19817	25393	N	N	N	1	CUSTOMER ISSUE	-
DMS_19818	25394	N	N	N	1	CUSTOMER ISSUE	-
DMS_19819	25395	N	N	N	1	CUSTOMER ISSUE	-
DMS_19822	25396	N	N	N	1	CUSTOMER ISSUE	-
DMS_19823	25397	N	N	N	1	CUSTOMER ISSUE	-
DMS_19824	25398	N	N	N	1	CUSTOMER ISSUE	-
DMS_19825	25399	N	N	N	1	CUSTOMER ISSUE	-
DMS_19826	25400	N	N	N	1	CUSTOMER ISSUE	-
DMS_19827	25401	N	N	N	1	CUSTOMER ISSUE	-
DMS_19828	25402	N	N	N	1	CUSTOMER ISSUE	-
DMS_19829	25403	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19830	25404	N	N	N	1	CUSTOMER ISSUE	-
DMS_19831	25405	N	N	N	1	CUSTOMER ISSUE	-
DMS_19832	25406	N	N	N	1	CUSTOMER ISSUE	-
DMS_19833	25407	N	N	N	1	CUSTOMER ISSUE	-
DMS_19834	25408	N	N	N	1	CUSTOMER ISSUE	-
DMS_19835	25409	N	N	N	1	CUSTOMER ISSUE	-
DMS_19836	25410	N	N	N	1	CUSTOMER ISSUE	-
DMS_19837	25411	N	N	N	1	CUSTOMER ISSUE	-
DMS_19838	25412	N	N	N	1	CUSTOMER ISSUE	-
DMS_19839	25413	N	N	N	1	CUSTOMER ISSUE	-
DMS_19840	25414	N	N	N	1	CUSTOMER ISSUE	-
DMS_19841	25415	N	N	N	1	CUSTOMER ISSUE	-
DMS_19842	25416	N	N	N	1	CUSTOMER ISSUE	-

DMS_19843	25417	N	N	N	1	CUSTOMER ISSUE	-
DMS_19844	25418	N	N	N	1	CUSTOMER ISSUE	-
DMS_19845	25419	N	N	N	1	CUSTOMER ISSUE	-
DMS_19846	25420	N	N	N	1	CUSTOMER ISSUE	-
DMS_19847	25421	N	N	N	1	CUSTOMER ISSUE	-
DMS_19848	25422	N	N	N	1	CUSTOMER ISSUE	-
DMS_19849	25423	N	N	N	1	CUSTOMER ISSUE	-
DMS_19850	25424	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19851	25425	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19852	25426	N	N	N	1	CUSTOMER ISSUE	-
DMS_19854	25427	N	N	N	1	CUSTOMER ISSUE	-
DMS_19855	25428	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19856	25429	N	N	N	1	CUSTOMER ISSUE	-
DMS_19857	25430	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19858	25431	N	N	N	1	CUSTOMER ISSUE	-
DMS_19860	25432	N	N	N	1	CUSTOMER ISSUE	-
DMS_19861	25433	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19862	25434	N	N	N	1	CUSTOMER ISSUE	-
DMS_19864	25435	N	N	N	1	CUSTOMER ISSUE	-
DMS_19865	25436	N	N	N	1	CUSTOMER ISSUE	-
DMS_19866	25437	N	N	N	1	CUSTOMER ISSUE	-
DMS_19867	25438	N	N	N	1	CUSTOMER ISSUE	-
DMS_19870	25439	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19871	25440	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19872	25441	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19873	25442	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19874	25443	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19875	25444	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_19876	25445	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19877	25446	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19878	25447	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19879	25448	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19880	25449	N	N	N	1	CUSTOMER ISSUE	-
DMS_19881	25450	N	N	N	1	CUSTOMER ISSUE	-
DMS_19882	25451	N	N	N	1	CUSTOMER ISSUE	-
DMS_19883	25452	N	N	N	1	CUSTOMER ISSUE	-
DMS_19884	25453	N	N	N	1	CUSTOMER ISSUE	-
DMS_19885	25454	N	N	N	1	CUSTOMER ISSUE	-
DMS_19887	25455	N	N	N	1	CUSTOMER ISSUE	-
DMS_19888	25456	N	N	Y	1	TX - REPLACE	2500
DMS_19889	25457	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19890	25458	N	N	N	1	CUSTOMER ISSUE	-
DMS_19892	25459	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19894	25460	N	N	N	1	CUSTOMER ISSUE	-
DMS_19895	25461	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_19896	25462	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_19897	25463	N	N	N	1	CUSTOMER ISSUE	-
DMS_19898	25464	N	N	N	1	CUSTOMER ISSUE	-
DMS_19899	25465	N	N	N	1	CUSTOMER ISSUE	-
DMS_19900	25466	N	N	N	1	CUSTOMER ISSUE	-
DMS_19901	25467	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19902	25468	N	N	N	1	CUSTOMER ISSUE	-
DMS_19903	25469	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_19904	25470	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19905	25471	N	N	N	1	CUSTOMER ISSUE	-
DMS_19906	25472	N	N	N	1	CUSTOMER ISSUE	-
DMS_19907	25473	N	N	N	1	CUSTOMER ISSUE	-
DMS_19908	25474	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19909	25475	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19910	25476	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19911	25477	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19912	25478	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19913	25479	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19914	25480	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19915	25481	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19916	25482	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19917	25483	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19918	25484	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19919	25485	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19920	25486	N	N	N	1	CUSTOMER ISSUE	-
DMS_19921	25487	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19922	25488	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19923	25489	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19924	25490	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19925	25491	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19926	25492	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19927	25493	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19928	25494	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19929	25495	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19930	25496	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_19931	25497	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19932	25498	N	N	N	1	CUSTOMER ISSUE	-
DMS_19933	25499	N	N	N	1	CUSTOMER ISSUE	-
DMS_19934	25500	N	N	N	1	CUSTOMER ISSUE	-
DMS_19935	25501	N	N	N	1	CUSTOMER ISSUE	-
DMS_19936	25502	N	N	N	1	CUSTOMER ISSUE	-
DMS_19937	25503	N	N	N	1	CUSTOMER ISSUE	-
DMS_19938	25504	N	N	N	1	CUSTOMER ISSUE	-
DMS_19939	25505	N	N	N	1	CUSTOMER ISSUE	-
DMS_19941	25506	N	N	N	1	CUSTOMER ISSUE	-
DMS_19942	25507	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19943	25508	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19944	25509	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19945	25510	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19946	25511	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19947	25512	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19948	25513	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19949	25514	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19950	25515	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19951	25516	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19952	25517	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19953	25518	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19954	25519	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19955	25520	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19956	25521	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19957	25522	N	N	N	1	CUSTOMER ISSUE	-
DMS_19958	25523	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19959	25524	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19960	25525	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19961	25526	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19962	25527	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19963	25528	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19964	25529	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_19965	25530	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19966	25531	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19967	25532	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19968	25533	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19969	25534	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19970	25535	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19971	25536	N	N	N	1	CUSTOMER ISSUE	-
DMS_19972	25537	N	N	N	1	CUSTOMER ISSUE	-
DMS_19973	25538	N	N	N	1	CUSTOMER ISSUE	-
DMS_19974	25539	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19975	25540	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19979	25541	N	N	N	1	CUSTOMER ISSUE	-
DMS_19981	25542	N	N	N	1	CUSTOMER ISSUE	-
DMS_19982	25543	N	N	N	1	CUSTOMER ISSUE	-
DMS_19983	25544	N	N	N	1	CUSTOMER ISSUE	-
DMS_19984	25545	N	N	N	1	CUSTOMER ISSUE	-
DMS_19985	25546	N	N	N	1	CUSTOMER ISSUE	-
DMS_19986	25547	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19987	25548	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_19988	25549	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19989	25550	N	N	N	1	CUSTOMER ISSUE	-
DMS_19990	25551	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_19991	25552	N	N	N	1	CUSTOMER ISSUE	-
DMS_19992	25553	N	N	N	1	CUSTOMER ISSUE	-
DMS_19993	25554	N	N	N	1	CUSTOMER ISSUE	-
DMS_19994	25555	N	N	N	1	CUSTOMER ISSUE	-
DMS_19998	25556	N	N	N	1	CUSTOMER ISSUE	-
DMS_20000	25557	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20001	25558	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20002	25559	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_20003	25560	N	N	N	1	CUSTOMER ISSUE	-
DMS_20006	25561	N	N	N	1	CUSTOMER ISSUE	-
DMS_20007	25562	N	N	N	1	CUSTOMER ISSUE	-
DMS_20008	25563	N	N	N	1	CUSTOMER ISSUE	-
DMS_20009	25564	N	N	N	1	CUSTOMER ISSUE	-
DMS_20010	25565	N	N	N	1	CUSTOMER ISSUE	-
DMS_20011	25566	N	N	N	1	CUSTOMER ISSUE	-
DMS_20012	25567	N	N	N	1	CUSTOMER ISSUE	-
DMS_20013	25568	N	N	N	1	CUSTOMER ISSUE	-
DMS_20014	25569	N	N	N	1	CUSTOMER ISSUE	-
DMS_20016	25570	N	N	N	1	CUSTOMER ISSUE	-
DMS_20019	25571	N	N	N	1	CUSTOMER ISSUE	-
DMS_20020	25572	N	N	N	1	CUSTOMER ISSUE	-
DMS_20021	25573	N	N	N	1	CUSTOMER ISSUE	-
DMS_20022	25574	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_20023	25575	N	N	N	1	CUSTOMER ISSUE	-
DMS_20026	25576	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_20027	25577	N	N	N	1	CUSTOMER ISSUE	-
DMS_20029	25578	N	N	N	1	CUSTOMER ISSUE	-
DMS_20030	25579	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_20031	25580	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20032	25581	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20033	25582	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_20035	25583	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20036	25584	N	N	N	1	CUSTOMER ISSUE	-
DMS_20037	25585	N	N	N	1	CUSTOMER ISSUE	-
DMS_20039	25586	N	N	N	1	CUSTOMER ISSUE	-
DMS_20040	25587	N	N	N	1	CUSTOMER ISSUE	-
DMS_20041	25588	N	N	N	1	CUSTOMER ISSUE	-
DMS_20042	25589	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_20043	25590	N	N	N	1	CUSTOMER ISSUE	-
DMS_20044	25591	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20045	25592	N	N	N	1	CUSTOMER ISSUE	-
DMS_20046	25593	N	N	N	1	CUSTOMER ISSUE	-
DMS_20047	25594	N	N	N	1	CUSTOMER ISSUE	-
DMS_20048	25595	N	N	N	1	CUSTOMER ISSUE	-
DMS_20049	25596	N	N	N	1	CUSTOMER ISSUE	-
DMS_20050	25597	N	N	N	1	CUSTOMER ISSUE	-
DMS_20051	25598	N	N	N	1	CUSTOMER ISSUE	-
DMS_20052	25599	N	N	N	1	CUSTOMER ISSUE	-
DMS_20053	25600	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20054	25601	N	N	N	1	CUSTOMER ISSUE	-
DMS_20057	25602	N	N	N	1	CUSTOMER ISSUE	-
DMS_20058	25603	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20059	25604	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20060	25605	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20061	25606	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20062	25607	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20064	25608	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20065	25609	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20066	25610	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20067	25611	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20068	25612	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20069	25613	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20070	25614	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_20071	25615	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20072	25616	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20073	25617	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20074	25618	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20075	25619	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20076	25620	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20077	25621	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20078	25622	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20079	25623	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20080	25624	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20081	25625	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20082	25626	N	N	N	1	CUSTOMER ISSUE	-
DMS_20083	25627	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20084	25628	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20085	25629	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20086	25630	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20087	25631	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20088	25632	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20089	25633	N	N	N	1	CUSTOMER ISSUE	-
DMS_20090	25634	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20091	25635	N	N	N	1	CUSTOMER ISSUE	-
DMS_20092	25636	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20093	25637	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20094	25638	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20095	25639	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20096	25640	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20097	25641	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20098	25642	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20099	25643	N	N	N	1	CUSTOMER ISSUE	-
DMS_20100	25644	N	N	N	1	CUSTOMER ISSUE	-
DMS_20102	25645	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20103	25646	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20104	25647	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20105	25648	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20106	25649	N	N	N	1	CUSTOMER ISSUE	-
DMS_20107	25650	N	N	N	1	CUSTOMER ISSUE	-
DMS_20108	25651	N	N	N	1	CUSTOMER ISSUE	-
DMS_20109	25652	N	N	N	1	CUSTOMER ISSUE	-
DMS_20110	25653	N	N	N	1	CUSTOMER ISSUE	-
DMS_20111	25654	N	N	N	1	CUSTOMER ISSUE	-
DMS_20112	25655	N	N	N	1	CUSTOMER ISSUE	-
DMS_20113	25656	N	N	N	1	CUSTOMER ISSUE	-

DMS_20114	25657	N	N	N	1	CUSTOMER ISSUE	-
DMS_20115	25658	N	N	N	1	CUSTOMER ISSUE	-
DMS_20116	25659	N	N	N	1	CUSTOMER ISSUE	-
DMS_20117	25660	N	N	N	1	CUSTOMER ISSUE	-
DMS_20118	25661	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20120	25662	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_20121	25663	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20122	25664	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20123	25665	N	N	N	1	CUSTOMER ISSUE	-
DMS_20124	25666	N	N	N	1	CUSTOMER ISSUE	-
DMS_20125	25667	N	N	N	1	CUSTOMER ISSUE	-
DMS_20126	25668	N	N	N	1	CUSTOMER ISSUE	-
DMS_20127	25669	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20128	25670	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20129	25671	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20130	25672	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20131	25673	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20132	25674	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20133	25675	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20134	25676	N	N	N	1	CUSTOMER ISSUE	-
DMS_20135	25677	N	N	N	1	CUSTOMER ISSUE	-
DMS_20136	25678	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20137	25679	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20138	25680	N	N	N	1	CUSTOMER ISSUE	-
DMS_20139	25681	N	N	N	1	CUSTOMER ISSUE	-
DMS_20140	25682	N	N	N	1	CUSTOMER ISSUE	-
DMS_20141	25683	N	N	N	1	CUSTOMER ISSUE	-
DMS_20142	25684	N	N	N	1	CUSTOMER ISSUE	-
DMS_20143	25685	N	N	N	1	CUSTOMER ISSUE	-
DMS_20144	25686	N	N	N	1	CUSTOMER ISSUE	-
DMS_20145	25687	N	N	N	1	CUSTOMER ISSUE	-
DMS_20146	25688	N	N	N	1	CUSTOMER ISSUE	-
DMS_20147	25689	N	N	N	1	CUSTOMER ISSUE	-
DMS_20148	25690	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20149	25691	N	N	N	1	CUSTOMER ISSUE	-
DMS_20150	25692	N	N	N	1	CUSTOMER ISSUE	-
DMS_20151	25693	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20152	25694	N	N	Y	1	TX - REPLACE	2500
DMS_20153	25695	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20154	25696	N	N	N	1	CUSTOMER ISSUE	-
DMS_20155	25697	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20156	25698	N	N	N	1	CUSTOMER ISSUE	-
DMS_20157	25699	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20158	25700	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20160	25701	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20161	25702	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20162	25703	N	N	N	1	CUSTOMER ISSUE	-
DMS_20163	25704	N	N	Y	3	DIST - REPLACE FUSE	708.75
DMS_20164	25705	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20165	25706	N	N	N	1	CUSTOMER ISSUE	-
DMS_20166	25707	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20167	25708	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20169	25709	N	N	N	1	CUSTOMER ISSUE	-
DMS_20170	25710	N	N	N	1	CUSTOMER ISSUE	-
DMS_20171	25711	N	N	N	1	CUSTOMER ISSUE	-
DMS_20172	25712	N	N	N	1	CUSTOMER ISSUE	-
DMS_20173	25713	N	N	N	1	CUSTOMER ISSUE	-
DMS_20174	25714	N	N	N	1	CUSTOMER ISSUE	-
DMS_20175	25715	N	N	N	1	CUSTOMER ISSUE	-
DMS_20176	25716	N	N	N	1	CUSTOMER ISSUE	-
DMS_20177	25717	N	N	N	1	CUSTOMER ISSUE	-
DMS_20178	25718	N	N	N	1	CUSTOMER ISSUE	-
DMS_20179	25719	N	N	N	1	CUSTOMER ISSUE	-
DMS_20180	25720	N	N	N	1	CUSTOMER ISSUE	-
DMS_20181	25721	N	N	N	1	CUSTOMER ISSUE	-
DMS_20182	25722	N	N	N	1	CUSTOMER ISSUE	-
DMS_20183	25723	N	N	N	1	CUSTOMER ISSUE	-
DMS_20184	25724	N	N	N	1	CUSTOMER ISSUE	-
DMS_20185	25725	N	N	N	1	CUSTOMER ISSUE	-
DMS_20186	25726	N	N	N	1	CUSTOMER ISSUE	-
DMS_20187	25727	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20188	25728	N	N	N	1	CUSTOMER ISSUE	-
DMS_20189	25729	N	N	N	1	CUSTOMER ISSUE	-
DMS_20190	25730	N	N	N	1	CUSTOMER ISSUE	-
DMS_20191	25731	N	N	N	1	CUSTOMER ISSUE	-
DMS_20192	25732	N	N	N	1	CUSTOMER ISSUE	-
DMS_20193	25733	N	N	N	1	CUSTOMER ISSUE	-
DMS_20194	25734	N	N	N	1	CUSTOMER ISSUE	-
DMS_20195	25735	N	N	N	1	CUSTOMER ISSUE	-
DMS_20196	25736	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_20198	25737	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20199	25738	N	N	N	1	CUSTOMER ISSUE	-
DMS_20200	25739	N	N	N	1	CUSTOMER ISSUE	-
DMS_20202	25740	N	N	N	1	CUSTOMER ISSUE	-
DMS_20203	25741	N	N	N	1	CUSTOMER ISSUE	-
DMS_20204	25742	N	N	N	1	CUSTOMER ISSUE	-
DMS_20205	25743	N	N	N	1	CUSTOMER ISSUE	-
DMS_20206	25744	N	N	N	1	CUSTOMER ISSUE	-
DMS_20207	25745	N	N	N	1	CUSTOMER ISSUE	-
DMS_20208	25746	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20209	25747	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20210	25748	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_20211	25749	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20212	25750	N	N	N	1	CUSTOMER ISSUE	-
DMS_20213	25751	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20215	25752	N	N	N	1	CUSTOMER ISSUE	-
DMS_20216	25753	N	N	N	1	CUSTOMER ISSUE	-
DMS_20217	25754	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20219	25755	N	N	N	1	CUSTOMER ISSUE	-
DMS_20220	25756	N	N	N	1	CUSTOMER ISSUE	-
DMS_20221	25757	N	N	N	1	CUSTOMER ISSUE	-
DMS_20222	25758	N	N	N	1	CUSTOMER ISSUE	-
DMS_20223	25759	N	N	N	1	CUSTOMER ISSUE	-
DMS_20224	25760	N	N	N	1	CUSTOMER ISSUE	-
DMS_20225	25761	N	N	N	1	CUSTOMER ISSUE	-
DMS_20226	25762	N	N	N	1	CUSTOMER ISSUE	-
DMS_20227	25763	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20228	25764	N	N	N	1	CUSTOMER ISSUE	-
DMS_20229	25765	N	N	N	1	CUSTOMER ISSUE	-
DMS_20230	25766	N	N	N	1	CUSTOMER ISSUE	-
DMS_20231	25767	N	N	N	1	CUSTOMER ISSUE	-
DMS_20232	25768	N	N	N	1	CUSTOMER ISSUE	-
DMS_20233	25769	N	N	N	1	CUSTOMER ISSUE	-
DMS_20234	25770	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20235	25771	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20237	25772	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20238	25773	N	N	N	1	CUSTOMER ISSUE	-
DMS_20239	25774	N	N	N	1	CUSTOMER ISSUE	-
DMS_20240	25775	N	N	N	1	CUSTOMER ISSUE	-
DMS_20241	25776	N	N	N	1	CUSTOMER ISSUE	-
DMS_20242	25777	N	N	N	1	CUSTOMER ISSUE	-
DMS_20243	25778	N	N	N	1	CUSTOMER ISSUE	-
DMS_20244	25779	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20245	25780	N	N	N	1	CUSTOMER ISSUE	-
DMS_20246	25781	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20247	25782	N	N	N	1	CUSTOMER ISSUE	-
DMS_20248	25783	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20249	25784	N	N	N	1	CUSTOMER ISSUE	-
DMS_20251	25785	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20252	25786	N	N	N	1	CUSTOMER ISSUE	-
DMS_20254	25787	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_20255	25788	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20256	25789	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20258	25790	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20259	25791	N	N	N	1	CUSTOMER ISSUE	-
DMS_20260	25792	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20261	25793	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20263	25794	N	N	N	1	CUSTOMER ISSUE	-
DMS_20264	25795	N	N	N	1	CUSTOMER ISSUE	-
DMS_20265	25796	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20266	25797	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20267	25798	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_20268	25799	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20269	25800	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20270	25801	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20271	25802	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20272	25803	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20273	25804	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20274	25805	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20275	25806	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20276	25807	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20277	25808	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20278	25809	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20279	25810	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20280	25811	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20281	25812	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20282	25813	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20283	25814	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20284	25815	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20285	25816	N	N	Y	1	DIST - REPLACE FUSE	708.75

DMS_20286	25817	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20287	25818	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20288	25819	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20289	25820	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20290	25821	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20291	25822	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20292	25823	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20293	25824	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20294	25825	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20295	25826	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20296	25827	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20297	25828	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20300	25829	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20302	25830	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20303	25831	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20304	25832	N	N	N	1	CUSTOMER ISSUE	-
DMS_20305	25833	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20306	25834	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20307	25835	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20308	25836	N	N	N	1	CUSTOMER ISSUE	-
DMS_20309	25837	N	N	N	1	CUSTOMER ISSUE	-
DMS_20310	25838	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20311	25839	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20312	25840	N	N	N	1	CUSTOMER ISSUE	-
DMS_20313	25841	N	N	N	1	CUSTOMER ISSUE	-
DMS_20314	25842	N	N	N	1	CUSTOMER ISSUE	-
DMS_20315	25843	N	N	N	1	CUSTOMER ISSUE	-
DMS_20316	25844	N	N	N	1	CUSTOMER ISSUE	-
DMS_20317	25845	N	N	N	1	CUSTOMER ISSUE	-
DMS_20318	25846	N	N	N	1	CUSTOMER ISSUE	-
DMS_20319	25847	N	N	N	1	CUSTOMER ISSUE	-
DMS_20320	25848	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20321	25849	N	N	N	1	CUSTOMER ISSUE	-
DMS_20322	25850	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20324	25851	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_20325	25852	N	N	N	1	CUSTOMER ISSUE	-
DMS_20326	25853	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20328	25854	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20329	25855	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20330	25856	N	N	N	1	CUSTOMER ISSUE	-
DMS_20331	25857	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20332	25858	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20333	25859	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20334	25860	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20335	25861	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20336	25862	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20337	25863	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20338	25864	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20339	25865	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20340	25866	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20341	25867	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20342	25868	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20343	25869	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20344	25870	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20345	25871	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20346	25872	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20347	25873	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20348	25874	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20349	25875	N	N	N	1	CUSTOMER ISSUE	-
DMS_20350	25876	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20352	25877	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20353	25878	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20354	25879	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20355	25880	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20356	25881	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20357	25882	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20358	25883	N	N	N	1	CUSTOMER ISSUE	-
DMS_20359	25884	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20360	25885	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20361	25886	N	N	N	1	CUSTOMER ISSUE	-
DMS_20362	25887	N	N	N	1	CUSTOMER ISSUE	-
DMS_20363	25888	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20364	25889	N	N	Y	3	DIST - REPLACE FUSE	708.75
DMS_20365	25890	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20366	25891	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_20367	25892	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20368	25893	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20369	25894	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20370	25895	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20371	25896	N	N	Y	1	DIST - REPLACE FUSE	708.75

DMS_20372	25897	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20373	25898	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20374	25899	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20375	25900	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20376	25901	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20377	25902	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20378	25903	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20379	25904	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20380	25905	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20381	25906	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20382	25907	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20383	25908	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20384	25909	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20385	25910	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20386	25911	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20387	25912	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20388	25913	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20389	25914	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20390	25915	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20391	25916	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20392	25917	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20393	25918	N	N	N	1	CUSTOMER ISSUE	-
DMS_20394	25919	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20395	25920	N	N	N	1	CUSTOMER ISSUE	-
DMS_20396	25921	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20397	25922	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20398	25923	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20399	25924	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20400	25925	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20401	25926	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20402	25927	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20403	25928	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20404	25929	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20405	25930	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20407	25931	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20408	25932	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20409	25933	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20410	25934	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20411	25935	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20412	25936	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20413	25937	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20414	25938	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20415	25939	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20416	25940	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20417	25941	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20418	25942	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20419	25943	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20420	25944	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20421	25945	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20422	25946	N	N	N	1	CUSTOMER ISSUE	-
DMS_20423	25947	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20424	25948	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20425	25949	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20426	25950	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20427	25951	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20428	25952	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20429	25953	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20430	25954	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20431	25955	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20432	25956	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20433	25957	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20434	25958	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20435	25959	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20436	25960	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20437	25961	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20438	25962	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20439	25963	N	N	N	1	CUSTOMER ISSUE	-
DMS_20440	25964	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_20441	25965	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20442	25966	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20443	25967	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20444	25968	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20445	25969	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20446	25970	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20447	25971	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20448	25972	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20449	25973	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20450	25974	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20451	25975	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20452	25976	N	N	Y	1	DIST - REPLACE FUSE	708.75

DMS_20453	25977	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20454	25978	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20455	25979	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20456	25980	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20457	25981	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20459	25982	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_20460	25983	N	N	N	1	CUSTOMER ISSUE	-
DMS_20461	25984	N	N	N	1	CUSTOMER ISSUE	-
DMS_20462	25985	N	N	N	1	CUSTOMER ISSUE	-
DMS_20463	25986	N	N	N	1	CUSTOMER ISSUE	-
DMS_20464	25987	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20465	25988	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20466	25989	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20467	25990	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20468	25991	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20469	25992	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20470	25993	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20471	25994	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20472	25995	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20473	25996	N	N	N	1	CUSTOMER ISSUE	-
DMS_20474	25997	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20475	25998	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20477	25999	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20478	26000	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20479	26001	N	N	N	1	CUSTOMER ISSUE	-
DMS_20480	26002	N	N	N	1	CUSTOMER ISSUE	-
DMS_20481	26003	N	N	N	2	CUSTOMER ISSUE	-
DMS_20482	26004	N	N	N	1	CUSTOMER ISSUE	-
DMS_20483	26005	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20484	26006	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20485	26007	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20486	26008	N	N	N	1	CUSTOMER ISSUE	-
DMS_20487	26009	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20488	26010	N	N	N	1	CUSTOMER ISSUE	-
DMS_20489	26011	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20491	26012	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20492	26013	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20493	26014	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20494	26015	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20495	26016	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20496	26017	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20497	26018	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20498	26019	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20499	26020	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20500	26021	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20501	26022	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20502	26023	N	N	N	1	CUSTOMER ISSUE	-
DMS_20503	26024	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20504	26025	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20506	26026	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20507	26027	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20508	26028	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20509	26029	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20510	26030	N	N	N	1	CUSTOMER ISSUE	-
DMS_20511	26031	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20512	26032	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20513	26033	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20514	26034	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20515	26035	N	N	Y	1	TX - REPLACE	2500
DMS_20516	26036	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20517	26037	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20518	26038	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20519	26039	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20521	26040	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20522	26041	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20523	26042	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20524	26043	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_20525	26044	N	N	N	1	CUSTOMER ISSUE	-
DMS_20526	26045	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20527	26046	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20528	26047	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20530	26048	N	N	N	1	CUSTOMER ISSUE	-
DMS_20531	26049	N	N	N	1	CUSTOMER ISSUE	-
DMS_20532	26050	N	N	N	1	CUSTOMER ISSUE	-
DMS_20533	26051	N	N	N	1	CUSTOMER ISSUE	-
DMS_20534	26052	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20535	26053	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20536	26054	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20538	26055	N	N	N	1	CUSTOMER ISSUE	-
DMS_20539	26056	N	N	N	1	CUSTOMER ISSUE	-

DMS_20540	26057	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20541	26058	N	N	N	1	CUSTOMER ISSUE	-
DMS_20542	26059	N	N	Y	1	TX - REPLACE	2500
DMS_20543	26060	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
DMS_20544	26061	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20545	26062	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20547	26063	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
DMS_20548	26064	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20550	26065	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20551	26066	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20552	26067	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20553	26068	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20554	26069	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20555	26070	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20556	26071	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20557	26072	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20558	26073	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20559	26074	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_20560	26075	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_20561	26076	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20562	26077	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20563	26078	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20564	26079	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20565	26080	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20566	26081	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20567	26082	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20568	26083	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20569	26084	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20570	26085	N	N	N	1	CUSTOMER ISSUE	-
DMS_20571	26086	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20572	26087	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20573	26088	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_20574	26089	N	N	N	1	CUSTOMER ISSUE	-
DMS_20575	26090	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20577	26091	N	N	N	1	CUSTOMER ISSUE	-
DMS_20578	26092	N	N	N	1	CUSTOMER ISSUE	-
DMS_20579	26093	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20580	26094	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20581	26095	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20582	26096	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20583	26097	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20584	26098	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20585	26099	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20586	26100	N	N	N	1	CUSTOMER ISSUE	-
DMS_20587	26101	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20588	26102	N	N	N	1	CUSTOMER ISSUE	-
DMS_20589	26103	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20590	26104	N	N	N	1	CUSTOMER ISSUE	-
DMS_20591	26105	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20592	26106	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20593	26107	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20594	26108	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20595	26109	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20596	26110	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20597	26111	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20598	26112	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20599	26113	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20600	26114	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20601	26115	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20602	26116	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20603	26117	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20604	26118	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20606	26119	N	N	N	1	CUSTOMER ISSUE	-
DMS_20607	26120	N	N	N	1	CUSTOMER ISSUE	-
DMS_20608	26121	N	N	N	1	CUSTOMER ISSUE	-
DMS_20610	26122	N	N	N	1	CUSTOMER ISSUE	-
DMS_20611	26123	N	N	N	1	CUSTOMER ISSUE	-
DMS_20612	26124	N	N	N	1	CUSTOMER ISSUE	-
DMS_20613	26125	N	N	N	1	CUSTOMER ISSUE	-
DMS_20614	26126	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20615	26127	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20616	26128	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20617	26129	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20618	26130	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20619	26131	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20620	26132	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20621	26133	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20622	26134	N	N	N	1	CUSTOMER ISSUE	-
DMS_20623	26135	N	N	N	1	CUSTOMER ISSUE	-
DMS_20624	26136	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_20625	26137	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20627	26138	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20630	26139	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20631	26140	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20632	26141	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20633	26142	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20634	26143	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20635	26144	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20636	26145	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20637	26146	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20638	26147	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20639	26148	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20640	26149	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20641	26150	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20642	26151	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20643	26152	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20644	26153	N	N	N	1	CUSTOMER ISSUE	-
DMS_20645	26154	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20646	26155	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20647	26156	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20648	26157	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20649	26158	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20650	26159	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20651	26160	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20652	26161	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20653	26162	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_20654	26163	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20655	26164	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20656	26165	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20657	26166	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20658	26167	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20659	26168	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20660	26169	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20661	26170	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20662	26171	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20663	26172	N	N	N	1	CUSTOMER ISSUE	-
DMS_20664	26173	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20665	26174	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20666	26175	N	N	N	1	CUSTOMER ISSUE	-
DMS_20667	26176	N	N	N	1	CUSTOMER ISSUE	-
DMS_20668	26177	N	N	N	1	CUSTOMER ISSUE	-
DMS_20669	26178	N	N	N	1	CUSTOMER ISSUE	-
DMS_20670	26179	N	N	N	1	CUSTOMER ISSUE	-
DMS_20671	26180	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20672	26181	N	N	N	1	CUSTOMER ISSUE	-
DMS_20673	26182	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20674	26183	N	N	N	1	CUSTOMER ISSUE	-
DMS_20675	26184	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20676	26185	N	N	N	1	CUSTOMER ISSUE	-
DMS_20677	26186	N	N	N	1	CUSTOMER ISSUE	-
DMS_20678	26187	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20679	26188	N	N	N	1	CUSTOMER ISSUE	-
DMS_20680	26189	N	N	N	1	CUSTOMER ISSUE	-
DMS_20681	26190	N	N	N	1	CUSTOMER ISSUE	-
DMS_20683	26191	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20684	26192	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20685	26193	N	N	N	1	CUSTOMER ISSUE	-
DMS_20686	26194	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20687	26195	N	N	N	1	CUSTOMER ISSUE	-
DMS_20688	26196	N	N	N	1	CUSTOMER ISSUE	-
DMS_20689	26197	N	N	N	1	CUSTOMER ISSUE	-
DMS_20690	26198	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20691	26199	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20692	26200	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20693	26201	N	N	N	1	CUSTOMER ISSUE	-
DMS_20694	26202	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20695	26203	N	N	N	1	CUSTOMER ISSUE	-
DMS_20696	26204	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20697	26205	N	N	N	1	CUSTOMER ISSUE	-
DMS_20698	26206	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20699	26207	N	N	N	1	CUSTOMER ISSUE	-
DMS_20700	26208	N	N	N	1	CUSTOMER ISSUE	-
DMS_20701	26209	N	N	N	1	CUSTOMER ISSUE	-
DMS_20702	26210	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20703	26211	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20704	26212	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20705	26213	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20706	26214	N	N	N	1	CUSTOMER ISSUE	-
DMS_20707	26215	N	N	N	1	CUSTOMER ISSUE	-
DMS_20708	26216	N	N	N	1	CUSTOMER ISSUE	-

DMS_20709	26217	N	N	N	1	CUSTOMER ISSUE	-
DMS_20710	26218	N	N	N	1	CUSTOMER ISSUE	-
DMS_20711	26219	N	N	N	1	CUSTOMER ISSUE	-
DMS_20712	26220	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20713	26221	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20714	26222	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20715	26223	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20716	26224	N	N	N	1	CUSTOMER ISSUE	-
DMS_20717	26225	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20718	26226	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20719	26227	N	N	N	1	CUSTOMER ISSUE	-
DMS_20720	26228	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20721	26229	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20722	26230	N	N	N	1	CUSTOMER ISSUE	-
DMS_20723	26231	N	N	N	1	CUSTOMER ISSUE	-
DMS_20724	26232	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20725	26233	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20726	26234	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20727	26235	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20728	26236	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20729	26237	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20730	26238	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20731	26239	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20732	26240	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20733	26241	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20734	26242	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20735	26243	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20736	26244	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20737	26245	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20738	26246	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20739	26247	N	N	N	1	CUSTOMER ISSUE	-
DMS_20740	26248	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20741	26249	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20742	26250	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20743	26251	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20744	26252	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20745	26253	N	N	Y	3	SEC/SVC - REPLACE	708.75
DMS_20746	26254	N	N	Y	3	SEC/SVC - REPLACE	708.75
DMS_20747	26255	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20748	26256	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20749	26257	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20750	26258	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20751	26259	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20752	26260	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20753	26261	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20754	26262	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20755	26263	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20756	26264	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20757	26265	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20758	26266	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20759	26267	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20760	26268	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20761	26269	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20762	26270	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20763	26271	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20764	26272	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20765	26273	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20766	26274	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20767	26275	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20768	26276	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20769	26277	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20770	26278	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20772	26279	N	N	N	1	CUSTOMER ISSUE	-
DMS_20773	26280	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20774	26281	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20775	26282	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20778	26283	N	N	N	1	CUSTOMER ISSUE	-
DMS_20779	26284	N	N	N	1	CUSTOMER ISSUE	-
DMS_20780	26285	N	N	N	1	CUSTOMER ISSUE	-
DMS_20781	26286	N	N	N	1	CUSTOMER ISSUE	-
DMS_20782	26287	N	N	N	1	CUSTOMER ISSUE	-
DMS_20783	26288	N	N	N	1	CUSTOMER ISSUE	-
DMS_20784	26289	N	N	N	1	CUSTOMER ISSUE	-
DMS_20785	26290	N	N	N	1	CUSTOMER ISSUE	-
DMS_20786	26291	N	N	N	1	CUSTOMER ISSUE	-
DMS_20787	26292	N	N	N	1	CUSTOMER ISSUE	-
DMS_20788	26293	N	N	N	1	CUSTOMER ISSUE	-
DMS_20791	26294	N	N	N	1	CUSTOMER ISSUE	-
DMS_20792	26295	N	N	N	1	CUSTOMER ISSUE	-
DMS_20796	26296	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_20797	26297	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20798	26298	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20799	26299	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20800	26300	N	N	N	1	CUSTOMER ISSUE	-
DMS_20801	26301	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20802	26302	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20803	26303	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20804	26304	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20805	26305	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20806	26306	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20807	26307	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20808	26308	N	N	N	1	CUSTOMER ISSUE	-
DMS_20809	26309	N	N	N	1	CUSTOMER ISSUE	-
DMS_20810	26310	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20811	26311	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20812	26312	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20813	26313	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20814	26314	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
DMS_20815	26315	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20816	26316	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20817	26317	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20818	26318	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20819	26319	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20820	26320	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20821	26321	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20822	26322	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20823	26323	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20824	26324	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20825	26325	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20826	26326	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20827	26327	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20828	26328	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20829	26329	N	N	N	1	CUSTOMER ISSUE	-
DMS_20830	26330	N	N	Y	1	TX - REPLACE	2500
DMS_20831	26331	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20832	26332	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20833	26333	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20834	26334	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20835	26335	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20836	26336	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20837	26337	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20838	26338	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20839	26339	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20840	26340	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20841	26341	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20842	26342	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20843	26343	N	N	Y	1	TX - REPLACE	2500
DMS_20844	26344	N	N	N	1	CUSTOMER ISSUE	-
DMS_20845	26345	N	N	N	1	CUSTOMER ISSUE	-
DMS_20846	26346	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20850	26347	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20851	26348	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20853	26349	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20856	26350	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20857	26351	N	N	N	1	CUSTOMER ISSUE	-
DMS_20858	26352	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20859	26353	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20860	26354	N	N	N	1	CUSTOMER ISSUE	-
DMS_20861	26355	N	N	N	1	CUSTOMER ISSUE	-
DMS_20862	26356	N	N	N	1	CUSTOMER ISSUE	-
DMS_20863	26357	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20864	26358	N	N	N	1	CUSTOMER ISSUE	-
DMS_20865	26359	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20866	26360	N	N	N	1	CUSTOMER ISSUE	-
DMS_20867	26361	N	N	N	1	CUSTOMER ISSUE	-
DMS_20868	26362	N	N	N	1	CUSTOMER ISSUE	-
DMS_20869	26363	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20870	26364	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20871	26365	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20872	26366	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20873	26367	N	N	N	1	CUSTOMER ISSUE	-
DMS_20874	26368	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20875	26369	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20876	26370	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20877	26371	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20878	26372	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20879	26373	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20880	26374	N	N	N	1	CUSTOMER ISSUE	-
DMS_20886	26375	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20889	26376	N	N	N	1	CUSTOMER ISSUE	-

DMS_20890	26377	N	N	N	1	CUSTOMER ISSUE	-
DMS_20891	26378	N	N	N	1	CUSTOMER ISSUE	-
DMS_20892	26379	N	N	N	1	CUSTOMER ISSUE	-
DMS_20893	26380	N	N	N	1	CUSTOMER ISSUE	-
DMS_20894	26381	N	N	N	1	CUSTOMER ISSUE	-
DMS_20895	26382	N	N	N	1	CUSTOMER ISSUE	-
DMS_20896	26383	N	N	N	1	CUSTOMER ISSUE	-
DMS_20897	26384	N	N	N	1	CUSTOMER ISSUE	-
DMS_20898	26385	N	N	N	1	CUSTOMER ISSUE	-
DMS_20899	26386	N	N	N	1	CUSTOMER ISSUE	-
DMS_20900	26387	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20901	26388	N	N	N	1	CUSTOMER ISSUE	-
DMS_20902	26389	N	N	N	1	CUSTOMER ISSUE	-
DMS_20903	26390	N	N	N	1	CUSTOMER ISSUE	-
DMS_20904	26391	N	N	N	1	CUSTOMER ISSUE	-
DMS_20905	26392	N	N	N	1	CUSTOMER ISSUE	-
DMS_20906	26393	N	N	N	1	CUSTOMER ISSUE	-
DMS_20907	26394	N	N	N	1	CUSTOMER ISSUE	-
DMS_20908	26395	N	N	N	1	CUSTOMER ISSUE	-
DMS_20909	26396	N	N	N	1	CUSTOMER ISSUE	-
DMS_20910	26397	N	N	N	1	CUSTOMER ISSUE	-
DMS_20911	26398	N	N	N	1	CUSTOMER ISSUE	-
DMS_20912	26399	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20913	26400	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20914	26401	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20915	26402	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20916	26403	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20917	26404	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20919	26405	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20920	26406	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_20921	26407	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20922	26408	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20923	26409	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20924	26410	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20925	26411	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20926	26412	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20927	26413	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20928	26414	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20929	26415	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20930	26416	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20931	26417	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20932	26418	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20933	26419	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20934	26420	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20935	26421	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20936	26422	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20937	26423	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_20938	26424	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20939	26425	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20940	26426	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20941	26427	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20942	26428	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_20943	26429	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20944	26430	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20945	26431	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20946	26432	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20947	26433	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20948	26434	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20949	26435	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20950	26436	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20951	26437	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20952	26438	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20953	26439	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20954	26440	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_20955	26441	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20956	26442	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20957	26443	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20958	26444	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20959	26445	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20960	26446	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20961	26447	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20962	26448	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20963	26449	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20964	26450	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20965	26451	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20966	26452	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20967	26453	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20968	26454	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20969	26455	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20970	26456	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_20971	26457	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20972	26458	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20973	26459	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20974	26460	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20975	26461	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20976	26462	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20977	26463	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20978	26464	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20979	26465	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20980	26466	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20981	26467	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20982	26468	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20983	26469	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20984	26470	N	N	N	1	CUSTOMER ISSUE	-
DMS_20985	26471	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20986	26472	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20987	26473	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20988	26474	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20989	26475	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20990	26476	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20991	26477	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20992	26478	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_20993	26479	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20994	26480	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20995	26481	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20996	26482	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20997	26483	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_20998	26484	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_20999	26485	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21000	26486	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21001	26487	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21002	26488	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21003	26489	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21004	26490	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21005	26491	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21006	26492	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21007	26493	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21008	26494	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21009	26495	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21010	26496	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21011	26497	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21012	26498	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21013	26499	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21014	26500	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21015	26501	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21016	26502	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21017	26503	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21018	26504	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21019	26505	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21020	26506	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21021	26507	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21022	26508	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21023	26509	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21024	26510	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21025	26511	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21026	26512	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21027	26513	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21028	26514	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21029	26515	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21030	26516	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21031	26517	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21032	26518	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21033	26519	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21034	26520	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21036	26521	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21037	26522	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21038	26523	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21039	26524	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21040	26525	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21041	26526	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21042	26527	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21043	26528	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21044	26529	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21045	26530	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_21046	26531	N	N	N	1	CUSTOMER ISSUE	-
DMS_21047	26532	N	N	N	1	CUSTOMER ISSUE	-
DMS_21048	26533	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21049	26534	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21050	26535	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21051	26536	N	N	N	1	CUSTOMER ISSUE	-

DMS_21052	26537	N	N	N	1	CUSTOMER ISSUE	-
DMS_21053	26538	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21054	26539	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21055	26540	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21056	26541	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21057	26542	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21058	26543	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21059	26544	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21060	26545	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21061	26546	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21062	26547	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21063	26548	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21064	26549	N	N	N	1	CUSTOMER ISSUE	-
DMS_21065	26550	N	N	N	1	CUSTOMER ISSUE	-
DMS_21066	26551	N	N	N	1	CUSTOMER ISSUE	-
DMS_21067	26552	N	N	N	2	CUSTOMER ISSUE	-
DMS_21068	26553	N	N	N	1	CUSTOMER ISSUE	-
DMS_21069	26554	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21070	26555	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21072	26556	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21073	26557	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21074	26558	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21075	26559	N	N	N	1	CUSTOMER ISSUE	-
DMS_21076	26560	N	N	N	1	CUSTOMER ISSUE	-
DMS_21077	26561	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21078	26562	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21079	26563	N	N	N	1	CUSTOMER ISSUE	-
DMS_21080	26564	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21081	26565	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21082	26566	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21083	26567	N	N	N	1	CUSTOMER ISSUE	-
DMS_21084	26568	N	N	N	1	CUSTOMER ISSUE	-
DMS_21085	26569	N	N	N	1	CUSTOMER ISSUE	-
DMS_21086	26570	N	N	N	1	CUSTOMER ISSUE	-
DMS_21087	26571	N	N	N	1	CUSTOMER ISSUE	-
DMS_21088	26572	N	N	N	1	CUSTOMER ISSUE	-
DMS_21089	26573	N	N	N	1	CUSTOMER ISSUE	-
DMS_21090	26574	N	N	N	1	CUSTOMER ISSUE	-
DMS_21091	26575	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21092	26576	N	N	N	1	CUSTOMER ISSUE	-
DMS_21093	26577	N	N	N	1	CUSTOMER ISSUE	-
DMS_21094	26578	N	N	N	1	CUSTOMER ISSUE	-
DMS_21095	26579	N	N	N	1	CUSTOMER ISSUE	-
DMS_21096	26580	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21097	26581	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21098	26582	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21099	26583	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21100	26584	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21101	26585	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21102	26586	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21103	26587	N	N	N	1	CUSTOMER ISSUE	-
DMS_21104	26588	N	N	N	1	CUSTOMER ISSUE	-
DMS_21105	26589	N	N	N	1	CUSTOMER ISSUE	-
DMS_21106	26590	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21107	26591	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21108	26592	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21109	26593	N	N	N	1	CUSTOMER ISSUE	-
DMS_21110	26594	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21111	26595	N	N	N	1	CUSTOMER ISSUE	-
DMS_21112	26596	N	N	N	1	CUSTOMER ISSUE	-
DMS_21113	26597	N	N	N	1	CUSTOMER ISSUE	-
DMS_21114	26598	N	N	N	1	CUSTOMER ISSUE	-
DMS_21115	26599	N	N	N	1	CUSTOMER ISSUE	-
DMS_21116	26600	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21117	26601	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21118	26602	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21119	26603	N	N	N	1	CUSTOMER ISSUE	-
DMS_21120	26604	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21121	26605	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21122	26606	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21123	26607	N	N	N	1	CUSTOMER ISSUE	-
DMS_21124	26608	N	N	N	1	CUSTOMER ISSUE	-
DMS_21125	26609	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21126	26610	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21127	26611	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21128	26612	N	N	N	1	CUSTOMER ISSUE	-
DMS_21129	26613	N	N	N	1	CUSTOMER ISSUE	-
DMS_21130	26614	N	N	N	1	CUSTOMER ISSUE	-
DMS_21131	26615	N	N	N	1	CUSTOMER ISSUE	-
DMS_21132	26616	N	N	N	1	CUSTOMER ISSUE	-

DMS_21133	26617	N	N	N	1	CUSTOMER ISSUE	-
DMS_21134	26618	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21136	26619	N	N	N	1	CUSTOMER ISSUE	-
DMS_21137	26620	N	N	N	1	CUSTOMER ISSUE	-
DMS_21138	26621	N	N	N	1	CUSTOMER ISSUE	-
DMS_21139	26622	N	N	N	1	CUSTOMER ISSUE	-
DMS_21140	26623	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21141	26624	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21142	26625	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21143	26626	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21144	26627	N	N	N	1	CUSTOMER ISSUE	-
DMS_21146	26628	N	N	N	1	CUSTOMER ISSUE	-
DMS_21147	26629	N	N	N	1	CUSTOMER ISSUE	-
DMS_21148	26630	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21149	26631	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21150	26632	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21151	26633	N	N	N	1	CUSTOMER ISSUE	-
DMS_21152	26634	N	N	N	1	CUSTOMER ISSUE	-
DMS_21153	26635	N	N	N	1	CUSTOMER ISSUE	-
DMS_21154	26636	N	N	N	1	CUSTOMER ISSUE	-
DMS_21155	26637	N	N	N	1	CUSTOMER ISSUE	-
DMS_21156	26638	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21157	26639	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21158	26640	N	N	N	1	CUSTOMER ISSUE	-
DMS_21159	26641	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21160	26642	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21161	26643	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21162	26644	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21163	26645	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21164	26646	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21165	26647	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21166	26648	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21167	26649	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21168	26650	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21169	26651	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21170	26652	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21171	26653	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21172	26654	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21173	26655	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21174	26656	N	N	N	1	CUSTOMER ISSUE	-
DMS_21175	26657	N	N	N	1	CUSTOMER ISSUE	-
DMS_21176	26658	N	N	N	1	CUSTOMER ISSUE	-
DMS_21177	26659	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21178	26660	N	N	N	1	CUSTOMER ISSUE	-
DMS_21179	26661	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21180	26662	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21181	26663	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21182	26664	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21183	26665	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21184	26666	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21185	26667	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21186	26668	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21187	26669	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21188	26670	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21189	26671	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21190	26672	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21191	26673	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21192	26674	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21193	26675	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21194	26676	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21195	26677	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21196	26678	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21197	26679	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21198	26680	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21199	26681	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21200	26682	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21201	26683	N	N	N	1	CUSTOMER ISSUE	-
DMS_21202	26684	N	N	N	1	CUSTOMER ISSUE	-
DMS_21203	26685	N	N	N	1	CUSTOMER ISSUE	-
DMS_21204	26686	N	N	N	1	CUSTOMER ISSUE	-
DMS_21205	26687	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21206	26688	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21207	26689	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21209	26690	N	N	N	1	CUSTOMER ISSUE	-
DMS_21210	26691	N	N	N	1	CUSTOMER ISSUE	-
DMS_21211	26692	N	N	N	1	CUSTOMER ISSUE	-
DMS_21212	26693	N	N	N	1	CUSTOMER ISSUE	-
DMS_21213	26694	N	N	N	1	CUSTOMER ISSUE	-
DMS_21214	26695	N	N	N	1	CUSTOMER ISSUE	-
DMS_21215	26696	N	N	N	1	CUSTOMER ISSUE	-

DMS_21216	26697	N	N	N	1	CUSTOMER ISSUE	-
DMS_21217	26698	N	N	N	1	CUSTOMER ISSUE	-
DMS_21218	26699	N	N	N	1	CUSTOMER ISSUE	-
DMS_21219	26700	N	N	N	1	CUSTOMER ISSUE	-
DMS_21220	26701	N	N	N	1	CUSTOMER ISSUE	-
DMS_21221	26702	N	N	N	1	CUSTOMER ISSUE	-
DMS_21222	26703	N	N	N	1	CUSTOMER ISSUE	-
DMS_21223	26704	N	N	N	1	CUSTOMER ISSUE	-
DMS_21224	26705	N	N	N	1	CUSTOMER ISSUE	-
DMS_21225	26706	N	N	N	1	CUSTOMER ISSUE	-
DMS_21226	26707	N	N	N	1	CUSTOMER ISSUE	-
DMS_21227	26708	N	N	N	1	CUSTOMER ISSUE	-
DMS_21228	26709	N	N	N	1	CUSTOMER ISSUE	-
DMS_21229	26710	N	N	N	1	CUSTOMER ISSUE	-
DMS_21230	26711	N	N	N	1	CUSTOMER ISSUE	-
DMS_21231	26712	N	N	N	1	CUSTOMER ISSUE	-
DMS_21232	26713	N	N	N	1	CUSTOMER ISSUE	-
DMS_21233	26714	N	N	N	1	CUSTOMER ISSUE	-
DMS_21234	26715	N	N	N	1	CUSTOMER ISSUE	-
DMS_21235	26716	N	N	N	1	CUSTOMER ISSUE	-
DMS_21236	26717	N	N	N	1	CUSTOMER ISSUE	-
DMS_21237	26718	N	N	N	1	CUSTOMER ISSUE	-
DMS_21238	26719	N	N	N	1	CUSTOMER ISSUE	-
DMS_21239	26720	N	N	N	1	CUSTOMER ISSUE	-
DMS_21240	26721	N	N	N	1	CUSTOMER ISSUE	-
DMS_21241	26722	N	N	N	1	CUSTOMER ISSUE	-
DMS_21242	26723	N	N	N	1	CUSTOMER ISSUE	-
DMS_21243	26724	N	N	N	1	CUSTOMER ISSUE	-
DMS_21244	26725	N	N	N	1	CUSTOMER ISSUE	-
DMS_21245	26726	N	N	N	1	CUSTOMER ISSUE	-
DMS_21246	26727	N	N	N	1	CUSTOMER ISSUE	-
DMS_21247	26728	N	N	N	1	CUSTOMER ISSUE	-
DMS_21248	26729	N	N	N	1	CUSTOMER ISSUE	-
DMS_21249	26730	N	N	N	1	CUSTOMER ISSUE	-
DMS_21250	26731	N	N	N	1	CUSTOMER ISSUE	-
DMS_21251	26732	N	N	N	1	CUSTOMER ISSUE	-
DMS_21252	26733	N	N	N	1	CUSTOMER ISSUE	-
DMS_21253	26734	N	N	N	1	CUSTOMER ISSUE	-
DMS_21254	26735	N	N	N	1	CUSTOMER ISSUE	-
DMS_21255	26736	N	N	N	1	CUSTOMER ISSUE	-
DMS_21256	26737	N	N	N	1	CUSTOMER ISSUE	-
DMS_21257	26738	N	N	N	1	CUSTOMER ISSUE	-
DMS_21258	26739	N	N	N	1	CUSTOMER ISSUE	-
DMS_21259	26740	N	N	N	1	CUSTOMER ISSUE	-
DMS_21260	26741	N	N	N	1	CUSTOMER ISSUE	-
DMS_21261	26742	N	N	N	1	CUSTOMER ISSUE	-
DMS_21262	26743	N	N	N	1	CUSTOMER ISSUE	-
DMS_21263	26744	N	N	N	1	CUSTOMER ISSUE	-
DMS_21264	26745	N	N	N	1	CUSTOMER ISSUE	-
DMS_21265	26746	N	N	N	1	CUSTOMER ISSUE	-
DMS_21266	26747	N	N	N	1	CUSTOMER ISSUE	-
DMS_21267	26748	N	N	N	1	CUSTOMER ISSUE	-
DMS_21268	26749	N	N	N	1	CUSTOMER ISSUE	-
DMS_21269	26750	N	N	N	1	CUSTOMER ISSUE	-
DMS_21270	26751	N	N	N	1	CUSTOMER ISSUE	-
DMS_21271	26752	N	N	N	1	CUSTOMER ISSUE	-
DMS_21272	26753	N	N	N	1	CUSTOMER ISSUE	-
DMS_21273	26754	N	N	N	1	CUSTOMER ISSUE	-
DMS_21274	26755	N	N	N	1	CUSTOMER ISSUE	-
DMS_21275	26756	N	N	N	1	CUSTOMER ISSUE	-
DMS_21276	26757	N	N	N	1	CUSTOMER ISSUE	-
DMS_21277	26758	N	N	N	1	CUSTOMER ISSUE	-
DMS_21278	26759	N	N	N	2	CUSTOMER ISSUE	-
DMS_21279	26760	N	N	N	1	CUSTOMER ISSUE	-
DMS_21280	26761	N	N	N	1	CUSTOMER ISSUE	-
DMS_21281	26762	N	N	N	1	CUSTOMER ISSUE	-
DMS_21282	26763	N	N	N	1	CUSTOMER ISSUE	-
DMS_21283	26764	N	N	N	1	CUSTOMER ISSUE	-
DMS_21284	26765	N	N	N	1	CUSTOMER ISSUE	-
DMS_21285	26766	N	N	N	1	CUSTOMER ISSUE	-
DMS_21286	26767	N	N	N	1	CUSTOMER ISSUE	-
DMS_21287	26768	N	N	N	1	CUSTOMER ISSUE	-
DMS_21288	26769	N	N	N	1	CUSTOMER ISSUE	-
DMS_21289	26770	N	N	N	1	CUSTOMER ISSUE	-
DMS_21290	26771	N	N	N	1	CUSTOMER ISSUE	-
DMS_21291	26772	N	N	N	1	CUSTOMER ISSUE	-
DMS_21292	26773	N	N	N	1	CUSTOMER ISSUE	-
DMS_21293	26774	N	N	N	1	CUSTOMER ISSUE	-
DMS_21294	26775	N	N	N	1	CUSTOMER ISSUE	-
DMS_21295	26776	N	N	N	1	CUSTOMER ISSUE	-

DMS_21296	26777	N	N	N	1	CUSTOMER ISSUE	-
DMS_21297	26778	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21298	26779	N	N	N	1	CUSTOMER ISSUE	-
DMS_21299	26780	N	N	N	1	CUSTOMER ISSUE	-
DMS_21300	26781	N	N	N	1	CUSTOMER ISSUE	-
DMS_21301	26782	N	N	N	1	CUSTOMER ISSUE	-
DMS_21302	26783	N	N	N	1	CUSTOMER ISSUE	-
DMS_21303	26784	N	N	N	1	CUSTOMER ISSUE	-
DMS_21304	26785	N	N	N	1	CUSTOMER ISSUE	-
DMS_21305	26786	N	N	N	1	CUSTOMER ISSUE	-
DMS_21306	26787	N	N	N	1	CUSTOMER ISSUE	-
DMS_21307	26788	N	N	N	1	CUSTOMER ISSUE	-
DMS_21308	26789	N	N	N	1	CUSTOMER ISSUE	-
DMS_21309	26790	N	N	N	1	CUSTOMER ISSUE	-
DMS_21310	26791	N	N	N	1	CUSTOMER ISSUE	-
DMS_21311	26792	N	N	N	1	CUSTOMER ISSUE	-
DMS_21312	26793	N	N	N	1	CUSTOMER ISSUE	-
DMS_21313	26794	N	N	N	1	CUSTOMER ISSUE	-
DMS_21314	26795	N	N	N	1	CUSTOMER ISSUE	-
DMS_21315	26796	N	N	N	1	CUSTOMER ISSUE	-
DMS_21316	26797	N	N	N	1	CUSTOMER ISSUE	-
DMS_21317	26798	N	N	N	1	CUSTOMER ISSUE	-
DMS_21318	26799	N	N	N	1	CUSTOMER ISSUE	-
DMS_21319	26800	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21320	26801	N	N	N	1	CUSTOMER ISSUE	-
DMS_21321	26802	N	N	N	1	CUSTOMER ISSUE	-
DMS_21322	26803	N	N	N	1	CUSTOMER ISSUE	-
DMS_21323	26804	N	N	N	1	CUSTOMER ISSUE	-
DMS_21324	26805	N	N	N	1	CUSTOMER ISSUE	-
DMS_21325	26806	N	N	N	1	CUSTOMER ISSUE	-
DMS_21326	26807	N	N	N	1	CUSTOMER ISSUE	-
DMS_21327	26808	N	N	N	1	CUSTOMER ISSUE	-
DMS_21328	26809	N	N	N	1	CUSTOMER ISSUE	-
DMS_21329	26810	N	N	N	1	CUSTOMER ISSUE	-
DMS_21330	26811	N	N	N	1	CUSTOMER ISSUE	-
DMS_21331	26812	N	N	N	1	CUSTOMER ISSUE	-
DMS_21332	26813	N	N	N	1	CUSTOMER ISSUE	-
DMS_21333	26814	N	N	N	1	CUSTOMER ISSUE	-
DMS_21334	26815	N	N	N	1	CUSTOMER ISSUE	-
DMS_21335	26816	N	N	N	1	CUSTOMER ISSUE	-
DMS_21336	26817	N	N	N	1	CUSTOMER ISSUE	-
DMS_21337	26818	N	N	N	1	CUSTOMER ISSUE	-
DMS_21338	26819	N	N	N	1	CUSTOMER ISSUE	-
DMS_21339	26820	N	N	N	1	CUSTOMER ISSUE	-
DMS_21340	26821	N	N	N	1	CUSTOMER ISSUE	-
DMS_21341	26822	N	N	N	1	CUSTOMER ISSUE	-
DMS_21342	26823	N	N	N	1	CUSTOMER ISSUE	-
DMS_21343	26824	N	N	N	1	CUSTOMER ISSUE	-
DMS_21344	26825	N	N	N	1	CUSTOMER ISSUE	-
DMS_21345	26826	N	N	N	1	CUSTOMER ISSUE	-
DMS_21346	26827	N	N	N	1	CUSTOMER ISSUE	-
DMS_21347	26828	N	N	N	1	CUSTOMER ISSUE	-
DMS_21348	26829	N	N	N	1	CUSTOMER ISSUE	-
DMS_21349	26830	N	N	N	1	CUSTOMER ISSUE	-
DMS_21350	26831	N	N	N	1	CUSTOMER ISSUE	-
DMS_21351	26832	N	N	N	1	CUSTOMER ISSUE	-
DMS_21352	26833	N	N	N	1	CUSTOMER ISSUE	-
DMS_21353	26834	N	N	N	1	CUSTOMER ISSUE	-
DMS_21354	26835	N	N	N	1	CUSTOMER ISSUE	-
DMS_21355	26836	N	N	N	1	CUSTOMER ISSUE	-
DMS_21356	26837	N	N	N	1	CUSTOMER ISSUE	-
DMS_21357	26838	N	N	N	1	CUSTOMER ISSUE	-
DMS_21358	26839	N	N	N	1	CUSTOMER ISSUE	-
DMS_21359	26840	N	N	N	1	CUSTOMER ISSUE	-
DMS_21360	26841	N	N	N	1	CUSTOMER ISSUE	-
DMS_21361	26842	N	N	N	2	CUSTOMER ISSUE	-
DMS_21362	26843	N	N	N	1	CUSTOMER ISSUE	-
DMS_21363	26844	N	N	N	1	CUSTOMER ISSUE	-
DMS_21365	26845	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_21366	26846	N	N	N	1	CUSTOMER ISSUE	-
DMS_21367	26847	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21368	26848	N	N	N	1	CUSTOMER ISSUE	-
DMS_21369	26849	N	N	N	1	CUSTOMER ISSUE	-
DMS_21370	26850	N	N	N	1	CUSTOMER ISSUE	-
DMS_21371	26851	N	N	N	1	CUSTOMER ISSUE	-
DMS_21372	26852	N	N	N	1	CUSTOMER ISSUE	-
DMS_21373	26853	N	N	N	1	CUSTOMER ISSUE	-
DMS_21374	26854	N	N	N	1	CUSTOMER ISSUE	-
DMS_21375	26855	N	N	N	1	CUSTOMER ISSUE	-
DMS_21376	26856	N	N	N	1	CUSTOMER ISSUE	-

DMS_21377	26857	N	N	N	1	CUSTOMER ISSUE	-
DMS_21378	26858	N	N	N	1	CUSTOMER ISSUE	-
DMS_21379	26859	N	N	N	1	CUSTOMER ISSUE	-
DMS_21380	26860	N	N	N	1	CUSTOMER ISSUE	-
DMS_21381	26861	N	N	N	1	CUSTOMER ISSUE	-
DMS_21382	26862	N	N	N	1	CUSTOMER ISSUE	-
DMS_21383	26863	N	N	N	1	CUSTOMER ISSUE	-
DMS_21384	26864	N	N	N	1	CUSTOMER ISSUE	-
DMS_21385	26865	N	N	N	1	CUSTOMER ISSUE	-
DMS_21386	26866	N	N	N	1	CUSTOMER ISSUE	-
DMS_21387	26867	N	N	N	1	CUSTOMER ISSUE	-
DMS_21388	26868	N	N	N	1	CUSTOMER ISSUE	-
DMS_21389	26869	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21390	26870	N	N	N	1	CUSTOMER ISSUE	-
DMS_21391	26871	N	N	N	1	CUSTOMER ISSUE	-
DMS_21392	26872	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21393	26873	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21394	26874	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21395	26875	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21396	26876	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21397	26877	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21398	26878	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21399	26879	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21400	26880	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21401	26881	N	N	N	1	CUSTOMER ISSUE	-
DMS_21402	26882	N	N	N	1	CUSTOMER ISSUE	-
DMS_21403	26883	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21404	26884	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21405	26885	N	N	N	1	CUSTOMER ISSUE	-
DMS_21406	26886	N	N	N	1	CUSTOMER ISSUE	-
DMS_21408	26887	N	N	N	1	CUSTOMER ISSUE	-
DMS_21409	26888	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21410	26889	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21411	26890	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21412	26891	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21413	26892	N	N	N	1	CUSTOMER ISSUE	-
DMS_21416	26893	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21418	26894	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21419	26895	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21420	26896	N	N	N	1	CUSTOMER ISSUE	-
DMS_21421	26897	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21422	26898	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21423	26899	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21424	26900	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21425	26901	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21426	26902	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21427	26903	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21428	26904	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21429	26905	N	N	N	1	CUSTOMER ISSUE	-
DMS_21433	26906	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21434	26907	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21435	26908	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21436	26909	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21437	26910	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21438	26911	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21439	26912	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21440	26913	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21441	26914	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21442	26915	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21443	26916	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21444	26917	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21445	26918	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21446	26919	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21447	26920	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21448	26921	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21450	26922	N	N	N	1	CUSTOMER ISSUE	-
DMS_21452	26923	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_21454	26924	N	N	N	1	CUSTOMER ISSUE	-
DMS_21455	26925	N	N	N	1	CUSTOMER ISSUE	-
DMS_21456	26926	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21457	26927	N	N	N	1	CUSTOMER ISSUE	-
DMS_21458	26928	N	N	N	1	CUSTOMER ISSUE	-
DMS_21459	26929	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21460	26930	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21461	26931	N	N	N	1	CUSTOMER ISSUE	-
DMS_21462	26932	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21463	26933	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21464	26934	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21465	26935	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21466	26936	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_21467	26937	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21468	26938	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21469	26939	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21470	26940	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21471	26941	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21473	26942	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21474	26943	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21475	26944	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21476	26945	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21477	26946	N	N	N	1	CUSTOMER ISSUE	-
DMS_21478	26947	N	N	N	1	CUSTOMER ISSUE	-
DMS_21479	26948	N	N	N	1	CUSTOMER ISSUE	-
DMS_21480	26949	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21481	26950	N	N	N	1	CUSTOMER ISSUE	-
DMS_21483	26951	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21484	26952	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21485	26953	N	N	N	1	CUSTOMER ISSUE	-
DMS_21486	26954	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21487	26955	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21488	26956	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21489	26957	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21490	26958	N	N	N	1	CUSTOMER ISSUE	-
DMS_21491	26959	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21492	26960	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21493	26961	N	N	N	1	CUSTOMER ISSUE	-
DMS_21494	26962	N	N	N	1	CUSTOMER ISSUE	-
DMS_21495	26963	N	N	N	1	CUSTOMER ISSUE	-
DMS_21496	26964	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21497	26965	N	N	N	1	CUSTOMER ISSUE	-
DMS_21499	26966	N	N	N	1	CUSTOMER ISSUE	-
DMS_21500	26967	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21501	26968	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21502	26969	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21503	26970	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21504	26971	N	N	N	1	CUSTOMER ISSUE	-
DMS_21505	26972	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21506	26973	N	N	N	1	CUSTOMER ISSUE	-
DMS_21507	26974	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21509	26975	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21510	26976	N	N	N	1	CUSTOMER ISSUE	-
DMS_21511	26977	N	N	N	1	CUSTOMER ISSUE	-
DMS_21512	26978	N	N	N	1	CUSTOMER ISSUE	-
DMS_21513	26979	N	N	N	1	CUSTOMER ISSUE	-
DMS_21514	26980	N	N	N	1	CUSTOMER ISSUE	-
DMS_21515	26981	N	N	N	1	CUSTOMER ISSUE	-
DMS_21516	26982	N	N	N	1	CUSTOMER ISSUE	-
DMS_21517	26983	N	N	N	1	CUSTOMER ISSUE	-
DMS_21518	26984	N	N	N	1	CUSTOMER ISSUE	-
DMS_21519	26985	N	N	N	1	CUSTOMER ISSUE	-
DMS_21520	26986	N	N	N	1	CUSTOMER ISSUE	-
DMS_21521	26987	N	N	N	1	CUSTOMER ISSUE	-
DMS_21522	26988	N	N	N	1	CUSTOMER ISSUE	-
DMS_21523	26989	N	N	N	1	CUSTOMER ISSUE	-
DMS_21524	26990	N	N	N	1	CUSTOMER ISSUE	-
DMS_21526	26991	N	N	N	1	CUSTOMER ISSUE	-
DMS_21527	26992	N	N	N	1	CUSTOMER ISSUE	-
DMS_21528	26993	N	N	N	1	CUSTOMER ISSUE	-
DMS_21529	26994	N	N	N	1	CUSTOMER ISSUE	-
DMS_21530	26995	N	N	N	1	CUSTOMER ISSUE	-
DMS_21531	26996	N	N	N	1	CUSTOMER ISSUE	-
DMS_21532	26997	N	N	N	1	CUSTOMER ISSUE	-
DMS_21533	26998	N	N	N	1	CUSTOMER ISSUE	-
DMS_21534	26999	N	N	N	1	CUSTOMER ISSUE	-
DMS_21535	27000	N	N	N	1	CUSTOMER ISSUE	-
DMS_21536	27001	N	N	N	1	CUSTOMER ISSUE	-
DMS_21537	27002	N	N	N	1	CUSTOMER ISSUE	-
DMS_21538	27003	N	N	N	1	CUSTOMER ISSUE	-
DMS_21539	27004	N	N	N	1	CUSTOMER ISSUE	-
DMS_21540	27005	N	N	N	1	CUSTOMER ISSUE	-
DMS_21541	27006	N	N	N	1	CUSTOMER ISSUE	-
DMS_21542	27007	N	N	N	1	CUSTOMER ISSUE	-
DMS_21543	27008	N	N	N	1	CUSTOMER ISSUE	-
DMS_21544	27009	N	N	N	1	CUSTOMER ISSUE	-
DMS_21545	27010	N	N	N	1	CUSTOMER ISSUE	-
DMS_21546	27011	N	N	N	1	CUSTOMER ISSUE	-
DMS_21547	27012	N	N	N	1	CUSTOMER ISSUE	-
DMS_21548	27013	N	N	N	1	CUSTOMER ISSUE	-
DMS_21549	27014	N	N	N	1	CUSTOMER ISSUE	-
DMS_21550	27015	N	N	N	1	CUSTOMER ISSUE	-
DMS_21551	27016	N	N	N	1	CUSTOMER ISSUE	-

DMS_21552	27017	N	N	N	1	CUSTOMER ISSUE	-
DMS_21553	27018	N	N	N	1	CUSTOMER ISSUE	-
DMS_21555	27019	N	N	N	1	CUSTOMER ISSUE	-
DMS_21556	27020	N	N	N	1	CUSTOMER ISSUE	-
DMS_21557	27021	N	N	N	1	CUSTOMER ISSUE	-
DMS_21558	27022	N	N	N	1	CUSTOMER ISSUE	-
DMS_21559	27023	N	N	N	1	CUSTOMER ISSUE	-
DMS_21560	27024	N	N	N	1	CUSTOMER ISSUE	-
DMS_21561	27025	N	N	N	1	CUSTOMER ISSUE	-
DMS_21562	27026	N	N	N	1	CUSTOMER ISSUE	-
DMS_21563	27027	N	N	N	1	CUSTOMER ISSUE	-
DMS_21564	27028	N	N	N	1	CUSTOMER ISSUE	-
DMS_21565	27029	N	N	N	1	CUSTOMER ISSUE	-
DMS_21566	27030	N	N	N	1	CUSTOMER ISSUE	-
DMS_21567	27031	N	N	N	1	CUSTOMER ISSUE	-
DMS_21568	27032	N	N	N	1	CUSTOMER ISSUE	-
DMS_21569	27033	N	N	N	1	CUSTOMER ISSUE	-
DMS_21570	27034	N	N	N	1	CUSTOMER ISSUE	-
DMS_21571	27035	N	N	N	1	CUSTOMER ISSUE	-
DMS_21572	27036	N	N	N	1	CUSTOMER ISSUE	-
DMS_21573	27037	N	N	N	1	CUSTOMER ISSUE	-
DMS_21574	27038	N	N	N	1	CUSTOMER ISSUE	-
DMS_21575	27039	N	N	N	1	CUSTOMER ISSUE	-
DMS_21576	27040	N	N	N	1	CUSTOMER ISSUE	-
DMS_21577	27041	N	N	N	1	CUSTOMER ISSUE	-
DMS_21578	27042	N	N	N	1	CUSTOMER ISSUE	-
DMS_21579	27043	N	N	N	1	CUSTOMER ISSUE	-
DMS_21580	27044	N	N	N	1	CUSTOMER ISSUE	-
DMS_21581	27045	N	N	N	1	CUSTOMER ISSUE	-
DMS_21582	27046	N	N	N	1	CUSTOMER ISSUE	-
DMS_21583	27047	N	N	N	1	CUSTOMER ISSUE	-
DMS_21584	27048	N	N	N	1	CUSTOMER ISSUE	-
DMS_21585	27049	N	N	N	1	CUSTOMER ISSUE	-
DMS_21586	27050	N	N	N	1	CUSTOMER ISSUE	-
DMS_21587	27051	N	N	N	1	CUSTOMER ISSUE	-
DMS_21588	27052	N	N	N	1	CUSTOMER ISSUE	-
DMS_21589	27053	N	N	N	1	CUSTOMER ISSUE	-
DMS_21590	27054	N	N	N	1	CUSTOMER ISSUE	-
DMS_21591	27055	N	N	N	1	CUSTOMER ISSUE	-
DMS_21592	27056	N	N	N	1	CUSTOMER ISSUE	-
DMS_21593	27057	N	N	N	1	CUSTOMER ISSUE	-
DMS_21594	27058	N	N	N	1	CUSTOMER ISSUE	-
DMS_21595	27059	N	N	N	1	CUSTOMER ISSUE	-
DMS_21596	27060	N	N	N	1	CUSTOMER ISSUE	-
DMS_21597	27061	N	N	N	1	CUSTOMER ISSUE	-
DMS_21598	27062	N	N	N	1	CUSTOMER ISSUE	-
DMS_21599	27063	N	N	N	1	CUSTOMER ISSUE	-
DMS_21600	27064	N	N	N	1	CUSTOMER ISSUE	-
DMS_21601	27065	N	N	N	1	CUSTOMER ISSUE	-
DMS_21602	27066	N	N	N	1	CUSTOMER ISSUE	-
DMS_21603	27067	N	N	N	1	CUSTOMER ISSUE	-
DMS_21605	27068	N	N	N	1	CUSTOMER ISSUE	-
DMS_21606	27069	N	N	N	1	CUSTOMER ISSUE	-
DMS_21607	27070	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21608	27071	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21609	27072	N	N	N	1	CUSTOMER ISSUE	-
DMS_21611	27073	N	N	N	1	CUSTOMER ISSUE	-
DMS_21612	27074	N	N	N	1	CUSTOMER ISSUE	-
DMS_21613	27075	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21614	27076	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21615	27077	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21616	27078	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21617	27079	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21618	27080	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21619	27081	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21620	27082	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21621	27083	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21624	27084	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21625	27085	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21626	27086	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21627	27087	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21628	27088	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21629	27089	N	N	N	1	CUSTOMER ISSUE	-
DMS_21630	27090	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21631	27091	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21632	27092	N	N	N	1	CUSTOMER ISSUE	-
DMS_21633	27093	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21634	27094	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21635	27095	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21636	27096	N	N	N	1	CUSTOMER ISSUE	-

DMS_21637	27097	N	N	N	1	CUSTOMER ISSUE	-
DMS_21638	27098	N	N	N	1	CUSTOMER ISSUE	-
DMS_21639	27099	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21640	27100	N	N	N	1	CUSTOMER ISSUE	-
DMS_21641	27101	N	N	N	1	CUSTOMER ISSUE	-
DMS_21646	27102	N	N	N	1	CUSTOMER ISSUE	-
DMS_21647	27103	N	N	N	1	CUSTOMER ISSUE	-
DMS_21648	27104	N	N	N	1	CUSTOMER ISSUE	-
DMS_21651	27105	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_21652	27106	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21653	27107	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_21661	27108	N	N	N	1	CUSTOMER ISSUE	-
DMS_21662	27109	N	N	N	1	CUSTOMER ISSUE	-
DMS_21663	27110	N	N	N	1	CUSTOMER ISSUE	-
DMS_21664	27111	N	N	N	1	CUSTOMER ISSUE	-
DMS_21665	27112	N	N	N	1	CUSTOMER ISSUE	-
DMS_21666	27113	N	N	N	1	CUSTOMER ISSUE	-
DMS_21667	27114	N	N	N	1	CUSTOMER ISSUE	-
DMS_21668	27115	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21669	27116	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21670	27117	N	N	N	1	CUSTOMER ISSUE	-
DMS_21671	27118	N	N	N	1	CUSTOMER ISSUE	-
DMS_21672	27119	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21673	27120	N	N	N	1	CUSTOMER ISSUE	-
DMS_21674	27121	N	N	N	1	CUSTOMER ISSUE	-
DMS_21675	27122	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21676	27123	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21677	27124	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21678	27125	N	N	N	1	CUSTOMER ISSUE	-
DMS_21679	27126	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21680	27127	N	N	N	1	CUSTOMER ISSUE	-
DMS_21681	27128	N	N	N	1	CUSTOMER ISSUE	-
DMS_21682	27129	N	N	N	1	CUSTOMER ISSUE	-
DMS_21683	27130	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21684	27131	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21685	27132	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21686	27133	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21687	27134	N	N	N	1	CUSTOMER ISSUE	-
DMS_21688	27135	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21689	27136	N	N	N	1	CUSTOMER ISSUE	-
DMS_21690	27137	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21691	27138	N	N	N	1	CUSTOMER ISSUE	-
DMS_21692	27139	N	N	N	1	CUSTOMER ISSUE	-
DMS_21693	27140	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21694	27141	N	N	N	1	CUSTOMER ISSUE	-
DMS_21695	27142	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21696	27143	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21697	27144	N	N	N	1	CUSTOMER ISSUE	-
DMS_21698	27145	N	N	N	1	CUSTOMER ISSUE	-
DMS_21699	27146	N	N	N	1	CUSTOMER ISSUE	-
DMS_21700	27147	N	N	N	1	CUSTOMER ISSUE	-
DMS_21701	27148	N	N	N	2	CUSTOMER ISSUE	-
DMS_21702	27149	N	N	N	1	CUSTOMER ISSUE	-
DMS_21703	27150	N	N	N	1	CUSTOMER ISSUE	-
DMS_21704	27151	N	N	N	1	CUSTOMER ISSUE	-
DMS_21705	27152	N	N	N	1	CUSTOMER ISSUE	-
DMS_21706	27153	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_21707	27154	N	N	N	1	CUSTOMER ISSUE	-
DMS_21708	27155	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21709	27156	N	N	Y	1	TX - REPLACE	2500
DMS_21710	27157	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21712	27158	N	N	N	1	CUSTOMER ISSUE	-
DMS_21713	27159	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21714	27160	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_21715	27161	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21716	27162	N	N	Y	1	SUB/TRANS - REPAIR	5000
DMS_21717	27163	N	N	N	1	CUSTOMER ISSUE	-
DMS_21718	27164	N	N	N	1	CUSTOMER ISSUE	-
DMS_21719	27165	N	N	N	1	CUSTOMER ISSUE	-
DMS_21720	27166	N	N	N	1	CUSTOMER ISSUE	-
DMS_21721	27167	N	N	N	1	CUSTOMER ISSUE	-
DMS_21722	27168	N	N	N	1	CUSTOMER ISSUE	-
DMS_21723	27169	N	N	N	1	CUSTOMER ISSUE	-
DMS_21724	27170	N	N	N	1	CUSTOMER ISSUE	-
DMS_21725	27171	N	N	N	1	CUSTOMER ISSUE	-
DMS_21726	27172	N	N	N	1	CUSTOMER ISSUE	-
DMS_21727	27173	N	N	N	1	CUSTOMER ISSUE	-
DMS_21728	27174	N	N	N	1	CUSTOMER ISSUE	-
DMS_21729	27175	N	N	N	1	CUSTOMER ISSUE	-
DMS_21730	27176	N	N	N	1	CUSTOMER ISSUE	-

DMS_21731	27177	N	N	N	1	CUSTOMER ISSUE	-
DMS_21732	27178	N	N	N	1	CUSTOMER ISSUE	-
DMS_21733	27179	N	N	N	1	CUSTOMER ISSUE	-
DMS_21734	27180	N	N	N	1	CUSTOMER ISSUE	-
DMS_21735	27181	N	N	N	1	CUSTOMER ISSUE	-
DMS_21736	27182	N	N	N	1	CUSTOMER ISSUE	-
DMS_21737	27183	N	N	N	1	CUSTOMER ISSUE	-
DMS_21738	27184	N	N	N	1	CUSTOMER ISSUE	-
DMS_21739	27185	N	N	N	1	CUSTOMER ISSUE	-
DMS_21740	27186	N	N	N	1	CUSTOMER ISSUE	-
DMS_21741	27187	N	N	N	1	CUSTOMER ISSUE	-
DMS_21742	27188	N	N	N	1	CUSTOMER ISSUE	-
DMS_21743	27189	N	N	N	1	CUSTOMER ISSUE	-
DMS_21744	27190	N	N	N	1	CUSTOMER ISSUE	-
DMS_21745	27191	N	N	N	1	CUSTOMER ISSUE	-
DMS_21746	27192	N	N	N	1	CUSTOMER ISSUE	-
DMS_21747	27193	N	N	N	1	CUSTOMER ISSUE	-
DMS_21748	27194	N	N	N	1	CUSTOMER ISSUE	-
DMS_21749	27195	N	N	N	1	CUSTOMER ISSUE	-
DMS_21750	27196	N	N	N	1	CUSTOMER ISSUE	-
DMS_21751	27197	N	N	N	1	CUSTOMER ISSUE	-
DMS_21752	27198	N	N	N	1	CUSTOMER ISSUE	-
DMS_21753	27199	N	N	N	1	CUSTOMER ISSUE	-
DMS_21754	27200	N	N	N	1	CUSTOMER ISSUE	-
DMS_21755	27201	N	N	N	1	CUSTOMER ISSUE	-
DMS_21756	27202	N	N	N	1	CUSTOMER ISSUE	-
DMS_21757	27203	N	N	N	1	CUSTOMER ISSUE	-
DMS_21758	27204	N	N	N	1	CUSTOMER ISSUE	-
DMS_21759	27205	N	N	N	1	CUSTOMER ISSUE	-
DMS_21760	27206	N	N	N	1	CUSTOMER ISSUE	-
DMS_21761	27207	N	N	N	1	CUSTOMER ISSUE	-
DMS_21762	27208	N	N	N	1	CUSTOMER ISSUE	-
DMS_21763	27209	N	N	N	1	CUSTOMER ISSUE	-
DMS_21764	27210	N	N	N	1	CUSTOMER ISSUE	-
DMS_21765	27211	N	N	N	1	CUSTOMER ISSUE	-
DMS_21766	27212	N	N	N	1	CUSTOMER ISSUE	-
DMS_21767	27213	N	N	N	1	CUSTOMER ISSUE	-
DMS_21768	27214	N	N	N	1	CUSTOMER ISSUE	-
DMS_21769	27215	N	N	N	1	CUSTOMER ISSUE	-
DMS_21770	27216	N	N	N	1	CUSTOMER ISSUE	-
DMS_21771	27217	N	N	N	1	CUSTOMER ISSUE	-
DMS_21772	27218	N	N	N	1	CUSTOMER ISSUE	-
DMS_21773	27219	N	N	N	1	CUSTOMER ISSUE	-
DMS_21774	27220	N	N	N	1	CUSTOMER ISSUE	-
DMS_21775	27221	N	N	N	1	CUSTOMER ISSUE	-
DMS_21776	27222	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21777	27223	N	N	N	1	CUSTOMER ISSUE	-
DMS_21778	27224	N	N	N	1	CUSTOMER ISSUE	-
DMS_21779	27225	N	N	N	1	CUSTOMER ISSUE	-
DMS_21780	27226	N	N	N	1	CUSTOMER ISSUE	-
DMS_21781	27227	N	N	N	1	CUSTOMER ISSUE	-
DMS_21782	27228	N	N	N	1	CUSTOMER ISSUE	-
DMS_21783	27229	N	N	N	1	CUSTOMER ISSUE	-
DMS_21788	27230	N	N	N	1	CUSTOMER ISSUE	-
DMS_21789	27231	N	N	N	1	CUSTOMER ISSUE	-
DMS_21790	27232	N	N	N	1	CUSTOMER ISSUE	-
DMS_21791	27233	N	N	N	1	CUSTOMER ISSUE	-
DMS_21792	27234	N	N	N	1	CUSTOMER ISSUE	-
DMS_21793	27235	N	N	N	1	CUSTOMER ISSUE	-
DMS_21794	27236	N	N	N	1	CUSTOMER ISSUE	-
DMS_21796	27237	N	N	N	1	CUSTOMER ISSUE	-
DMS_21797	27238	N	N	N	1	CUSTOMER ISSUE	-
DMS_21798	27239	N	N	N	1	CUSTOMER ISSUE	-
DMS_21800	27240	N	N	N	1	CUSTOMER ISSUE	-
DMS_21801	27241	N	N	N	1	CUSTOMER ISSUE	-
DMS_21802	27242	N	N	N	1	CUSTOMER ISSUE	-
DMS_21804	27243	N	N	N	1	CUSTOMER ISSUE	-
DMS_21805	27244	N	N	N	1	CUSTOMER ISSUE	-
DMS_21806	27245	N	N	N	1	CUSTOMER ISSUE	-
DMS_21808	27246	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21809	27247	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21810	27248	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21811	27249	N	N	N	1	CUSTOMER ISSUE	-
DMS_21813	27250	N	N	N	1	CUSTOMER ISSUE	-
DMS_21815	27251	N	N	N	1	CUSTOMER ISSUE	-
DMS_21817	27252	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21818	27253	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21819	27254	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21820	27255	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21821	27256	N	N	N	1	CUSTOMER ISSUE	-

DMS_21822	27257	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21830	27258	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21831	27259	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21833	27260	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21834	27261	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21835	27262	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21836	27263	N	N	N	1	CUSTOMER ISSUE	-
DMS_21837	27264	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21838	27265	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21839	27266	N	N	N	1	CUSTOMER ISSUE	-
DMS_21840	27267	N	N	N	1	CUSTOMER ISSUE	-
DMS_21841	27268	N	N	N	1	CUSTOMER ISSUE	-
DMS_21842	27269	N	N	N	1	CUSTOMER ISSUE	-
DMS_21843	27270	N	N	N	1	CUSTOMER ISSUE	-
DMS_21844	27271	N	N	N	1	CUSTOMER ISSUE	-
DMS_21845	27272	N	N	N	1	CUSTOMER ISSUE	-
DMS_21846	27273	N	N	N	1	CUSTOMER ISSUE	-
DMS_21847	27274	N	N	N	1	CUSTOMER ISSUE	-
DMS_21848	27275	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21849	27276	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21850	27277	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21851	27278	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21852	27279	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21853	27280	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21854	27281	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21855	27282	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21856	27283	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21857	27284	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21858	27285	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21859	27286	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21860	27287	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21861	27288	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21862	27289	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21863	27290	N	N	N	1	CUSTOMER ISSUE	-
DMS_21864	27291	N	N	N	1	CUSTOMER ISSUE	-
DMS_21865	27292	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21866	27293	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21867	27294	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21868	27295	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21869	27296	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21870	27297	N	N	N	1	CUSTOMER ISSUE	-
DMS_21871	27298	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_21872	27299	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21873	27300	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21874	27301	N	N	N	1	CUSTOMER ISSUE	-
DMS_21875	27302	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21876	27303	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21877	27304	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21878	27305	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21879	27306	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21880	27307	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21881	27308	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21882	27309	N	N	Y	1	TX - REPLACE	2500
DMS_21883	27310	N	N	N	1	CUSTOMER ISSUE	-
DMS_21884	27311	N	N	Y	1	TX - REPLACE	2500
DMS_21885	27312	N	N	N	1	CUSTOMER ISSUE	-
DMS_21886	27313	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_21888	27314	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_21889	27315	N	N	N	1	CUSTOMER ISSUE	-
DMS_21890	27316	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21891	27317	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21892	27318	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21893	27319	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21894	27320	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21895	27321	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21896	27322	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21897	27323	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21898	27324	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21899	27325	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21900	27326	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21901	27327	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21902	27328	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21903	27329	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21904	27330	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21905	27331	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21906	27332	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21907	27333	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21908	27334	N	N	N	1	CUSTOMER ISSUE	-
DMS_21909	27335	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21910	27336	N	N	N	1	CUSTOMER ISSUE	-

DMS_21911	27337	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21912	27338	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21913	27339	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21914	27340	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21915	27341	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21916	27342	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21917	27343	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21918	27344	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21919	27345	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21920	27346	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21921	27347	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21922	27348	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21923	27349	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21924	27350	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21925	27351	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21926	27352	N	N	N	1	CUSTOMER ISSUE	-
DMS_21927	27353	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21928	27354	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_21929	27355	N	N	N	1	CUSTOMER ISSUE	-
DMS_21930	27356	N	N	N	1	CUSTOMER ISSUE	-
DMS_21931	27357	N	N	N	1	CUSTOMER ISSUE	-
DMS_21932	27358	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21933	27359	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21934	27360	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21935	27361	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21936	27362	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21937	27363	N	N	N	1	CUSTOMER ISSUE	-
DMS_21938	27364	N	N	N	1	CUSTOMER ISSUE	-
DMS_21939	27365	N	N	N	1	CUSTOMER ISSUE	-
DMS_21940	27366	N	N	N	1	CUSTOMER ISSUE	-
DMS_21941	27367	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21942	27368	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21943	27369	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21944	27370	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21945	27371	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21946	27372	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21947	27373	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21948	27374	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21949	27375	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21950	27376	N	N	N	1	CUSTOMER ISSUE	-
DMS_21951	27377	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21952	27378	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21953	27379	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21954	27380	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21955	27381	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21956	27382	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21957	27383	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21958	27384	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21959	27385	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21960	27386	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21961	27387	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21962	27388	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21963	27389	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21964	27390	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21965	27391	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21966	27392	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21967	27393	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21968	27394	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21969	27395	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21970	27396	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21971	27397	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21972	27398	N	N	N	1	CUSTOMER ISSUE	-
DMS_21973	27399	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21974	27400	N	N	N	1	CUSTOMER ISSUE	-
DMS_21975	27401	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21976	27402	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21977	27403	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21978	27404	N	N	N	1	CUSTOMER ISSUE	-
DMS_21979	27405	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21980	27406	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21981	27407	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21982	27408	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21983	27409	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21984	27410	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21985	27411	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21986	27412	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21987	27413	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21988	27414	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21989	27415	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21990	27416	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_21991	27417	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21992	27418	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21993	27419	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21994	27420	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21995	27421	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21996	27422	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21997	27423	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_21998	27424	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_21999	27425	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22000	27426	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22001	27427	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22002	27428	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22003	27429	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22004	27430	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22005	27431	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22006	27432	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22007	27433	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22008	27434	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22009	27435	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22010	27436	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22011	27437	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22012	27438	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22013	27439	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22014	27440	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22015	27441	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22016	27442	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22017	27443	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22018	27444	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22019	27445	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22020	27446	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22021	27447	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22022	27448	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22023	27449	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22024	27450	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22025	27451	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22026	27452	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22027	27453	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22028	27454	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22029	27455	N	N	N	1	CUSTOMER ISSUE	-
DMS_22030	27456	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22031	27457	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22032	27458	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22033	27459	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22034	27460	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22035	27461	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22036	27462	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22037	27463	N	N	N	1	CUSTOMER ISSUE	-
DMS_22038	27464	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22039	27465	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22040	27466	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22041	27467	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22042	27468	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22043	27469	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22044	27470	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22045	27471	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22046	27472	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22047	27473	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22048	27474	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22049	27475	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22050	27476	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22051	27477	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22052	27478	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22053	27479	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22054	27480	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22055	27481	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22056	27482	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22057	27483	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22058	27484	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22059	27485	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22060	27486	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22061	27487	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22062	27488	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22063	27489	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22064	27490	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22065	27491	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22066	27492	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22067	27493	N	N	N	1	CUSTOMER ISSUE	-
DMS_22068	27494	N	N	N	1	CUSTOMER ISSUE	-
DMS_22069	27495	N	N	N	1	CUSTOMER ISSUE	-
DMS_22070	27496	N	N	N	1	CUSTOMER ISSUE	-

DMS_22071	27497	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22072	27498	N	N	N	1	CUSTOMER ISSUE	-
DMS_22073	27499	N	N	N	1	CUSTOMER ISSUE	-
DMS_22074	27500	N	N	N	1	CUSTOMER ISSUE	-
DMS_22075	27501	N	N	N	1	CUSTOMER ISSUE	-
DMS_22076	27502	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22077	27503	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22078	27504	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22079	27505	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22080	27506	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22081	27507	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22082	27508	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22083	27509	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22084	27510	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22085	27511	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22086	27512	N	N	N	1	CUSTOMER ISSUE	-
DMS_22087	27513	N	N	N	1	CUSTOMER ISSUE	-
DMS_22088	27514	N	N	N	1	CUSTOMER ISSUE	-
DMS_22089	27515	N	N	N	1	CUSTOMER ISSUE	-
DMS_22090	27516	N	N	N	1	CUSTOMER ISSUE	-
DMS_22091	27517	N	N	N	1	CUSTOMER ISSUE	-
DMS_22092	27518	N	N	N	1	CUSTOMER ISSUE	-
DMS_22093	27519	N	N	N	1	CUSTOMER ISSUE	-
DMS_22094	27520	N	N	N	1	CUSTOMER ISSUE	-
DMS_22095	27521	N	N	N	1	CUSTOMER ISSUE	-
DMS_22096	27522	N	N	N	1	CUSTOMER ISSUE	-
DMS_22097	27523	N	N	N	1	CUSTOMER ISSUE	-
DMS_22101	27524	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22102	27525	N	N	N	1	CUSTOMER ISSUE	-
DMS_22103	27526	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22104	27527	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22105	27528	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22106	27529	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22107	27530	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22108	27531	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22109	27532	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22110	27533	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22111	27534	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22112	27535	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22113	27536	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22114	27537	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22115	27538	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22116	27539	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22117	27540	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22118	27541	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22119	27542	N	N	N	1	CUSTOMER ISSUE	-
DMS_22120	27543	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22121	27544	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22122	27545	N	N	Y	1	TX - REPLACE	2500
DMS_22124	27546	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22125	27547	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22126	27548	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22127	27549	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22128	27550	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22129	27551	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22130	27552	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22132	27553	N	N	N	1	CUSTOMER ISSUE	-
DMS_22133	27554	N	N	N	1	CUSTOMER ISSUE	-
DMS_22134	27555	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22135	27556	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22136	27557	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22137	27558	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_22138	27559	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_22139	27560	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22140	27561	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22141	27562	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22142	27563	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22143	27564	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22144	27565	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22145	27566	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22146	27567	N	N	N	1	CUSTOMER ISSUE	-
DMS_22147	27568	N	N	N	1	CUSTOMER ISSUE	-
DMS_22148	27569	N	N	Y	1	TX - REPLACE	2500
DMS_22149	27570	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22150	27571	N	N	Y	1	TX - REPLACE	2500
DMS_22151	27572	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22152	27573	N	N	Y	1	TX - REPLACE	2500
DMS_22153	27574	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22154	27575	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22155	27576	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_22156	27577	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22157	27578	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22158	27579	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22159	27580	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22160	27581	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22161	27582	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22162	27583	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22163	27584	N	N	Y	3	SEC/SVC - REPAIR	472.5
DMS_22164	27585	N	N	N	1	CUSTOMER ISSUE	-
DMS_22165	27586	N	N	N	1	CUSTOMER ISSUE	-
DMS_22166	27587	N	N	N	1	CUSTOMER ISSUE	-
DMS_22168	27588	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22169	27589	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22170	27590	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22171	27591	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22173	27592	N	N	N	1	CUSTOMER ISSUE	-
DMS_22174	27593	N	N	N	1	CUSTOMER ISSUE	-
DMS_22175	27594	N	N	N	1	CUSTOMER ISSUE	-
DMS_22176	27595	N	N	N	1	CUSTOMER ISSUE	-
DMS_22177	27596	N	N	N	1	CUSTOMER ISSUE	-
DMS_22179	27597	N	N	N	1	CUSTOMER ISSUE	-
DMS_22180	27598	N	N	N	1	CUSTOMER ISSUE	-
DMS_22184	27599	N	N	N	1	CUSTOMER ISSUE	-
DMS_22187	27600	N	N	N	1	CUSTOMER ISSUE	-
DMS_22188	27601	N	N	N	1	CUSTOMER ISSUE	-
DMS_22189	27602	N	N	N	1	CUSTOMER ISSUE	-
DMS_22191	27603	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22193	27604	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22194	27605	N	N	N	1	CUSTOMER ISSUE	-
DMS_22195	27606	N	N	N	1	CUSTOMER ISSUE	-
DMS_22198	27607	N	N	N	1	CUSTOMER ISSUE	-
DMS_22199	27608	N	N	N	1	CUSTOMER ISSUE	-
DMS_22200	27609	N	N	N	1	CUSTOMER ISSUE	-
DMS_22201	27610	N	N	N	1	CUSTOMER ISSUE	-
DMS_22202	27611	N	N	N	1	CUSTOMER ISSUE	-
DMS_22203	27612	N	N	N	1	CUSTOMER ISSUE	-
DMS_22204	27613	N	N	N	1	CUSTOMER ISSUE	-
DMS_22205	27614	N	N	N	1	CUSTOMER ISSUE	-
DMS_22206	27615	N	N	N	1	CUSTOMER ISSUE	-
DMS_22207	27616	N	N	N	1	CUSTOMER ISSUE	-
DMS_22208	27617	N	N	N	1	CUSTOMER ISSUE	-
DMS_22209	27618	N	N	N	1	CUSTOMER ISSUE	-
DMS_22210	27619	N	N	N	1	CUSTOMER ISSUE	-
DMS_22211	27620	N	N	N	1	CUSTOMER ISSUE	-
DMS_22212	27621	N	N	N	1	CUSTOMER ISSUE	-
DMS_22213	27622	N	N	N	1	CUSTOMER ISSUE	-
DMS_22214	27623	N	N	N	1	CUSTOMER ISSUE	-
DMS_22215	27624	N	N	N	1	CUSTOMER ISSUE	-
DMS_22216	27625	N	N	N	1	CUSTOMER ISSUE	-
DMS_22217	27626	N	N	N	1	CUSTOMER ISSUE	-
DMS_22218	27627	N	N	N	1	CUSTOMER ISSUE	-
DMS_22219	27628	N	N	N	1	CUSTOMER ISSUE	-
DMS_22220	27629	N	N	N	1	CUSTOMER ISSUE	-
DMS_22221	27630	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22222	27631	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22225	27632	N	N	N	1	CUSTOMER ISSUE	-
DMS_22226	27633	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22227	27634	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22228	27635	N	N	N	1	CUSTOMER ISSUE	-
DMS_22229	27636	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22231	27637	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22232	27638	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22233	27639	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22236	27640	N	N	N	1	CUSTOMER ISSUE	-
DMS_22237	27641	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22238	27642	N	N	N	1	CUSTOMER ISSUE	-
DMS_22239	27643	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22240	27644	N	N	N	1	CUSTOMER ISSUE	-
DMS_22243	27645	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22244	27646	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22245	27647	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22246	27648	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22248	27649	N	N	N	1	CUSTOMER ISSUE	-
DMS_22250	27650	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22251	27651	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22252	27652	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22253	27653	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22254	27654	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22255	27655	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22256	27656	N	N	Y	1	DIST - REPLACE FUSE	708.75

DMS_22257	27657	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22258	27658	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22259	27659	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22260	27660	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22261	27661	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22262	27662	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22263	27663	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22264	27664	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22265	27665	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22266	27666	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22267	27667	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22268	27668	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22269	27669	N	N	Y	4	SEC/SVC - REPAIR	472.5
DMS_22270	27670	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22271	27671	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22272	27672	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22273	27673	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22274	27674	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22275	27675	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22276	27676	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22277	27677	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22278	27678	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22279	27679	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22280	27680	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22281	27681	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22282	27682	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22283	27683	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22284	27684	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22285	27685	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22286	27686	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22287	27687	N	N	N	1	CUSTOMER ISSUE	-
DMS_22288	27688	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22289	27689	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22290	27690	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22291	27691	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22292	27692	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22293	27693	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22294	27694	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22295	27695	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22296	27696	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22297	27697	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22298	27698	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22299	27699	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22300	27700	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22301	27701	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22302	27702	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22303	27703	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22304	27704	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22305	27705	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22306	27706	N	N	N	1	CUSTOMER ISSUE	-
DMS_22307	27707	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22308	27708	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22309	27709	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22310	27710	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22311	27711	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22312	27712	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22313	27713	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22314	27714	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_22315	27715	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22316	27716	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22317	27717	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22318	27718	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22319	27719	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22320	27720	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22321	27721	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22322	27722	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22323	27723	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22324	27724	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22325	27725	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22326	27726	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22327	27727	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22328	27728	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_22329	27729	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22330	27730	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22331	27731	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22332	27732	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22333	27733	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22334	27734	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22335	27735	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22336	27736	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_22337	27737	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22338	27738	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22339	27739	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22340	27740	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22341	27741	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22342	27742	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22343	27743	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22344	27744	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22345	27745	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22346	27746	N	N	N	1	CUSTOMER ISSUE	-
DMS_22347	27747	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22350	27748	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22352	27749	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22354	27750	N	N	N	1	CUSTOMER ISSUE	-
DMS_22355	27751	N	N	N	1	CUSTOMER ISSUE	-
DMS_22357	27752	N	N	N	1	CUSTOMER ISSUE	-
DMS_22358	27753	N	N	N	1	CUSTOMER ISSUE	-
DMS_22359	27754	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22360	27755	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22361	27756	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22362	27757	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22363	27758	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22364	27759	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22365	27760	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22366	27761	N	N	N	1	CUSTOMER ISSUE	-
DMS_22367	27762	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22368	27763	N	N	N	1	CUSTOMER ISSUE	-
DMS_22369	27764	N	N	N	1	CUSTOMER ISSUE	-
DMS_22370	27765	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22371	27766	N	N	N	1	CUSTOMER ISSUE	-
DMS_22372	27767	N	N	N	1	CUSTOMER ISSUE	-
DMS_22373	27768	N	N	N	1	CUSTOMER ISSUE	-
DMS_22374	27769	N	N	N	1	CUSTOMER ISSUE	-
DMS_22376	27770	N	N	N	1	CUSTOMER ISSUE	-
DMS_22377	27771	N	N	N	1	CUSTOMER ISSUE	-
DMS_22380	27772	N	N	N	1	CUSTOMER ISSUE	-
DMS_22381	27773	N	N	N	1	CUSTOMER ISSUE	-
DMS_22382	27774	N	N	N	1	CUSTOMER ISSUE	-
DMS_22384	27775	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22385	27776	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22386	27777	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22387	27778	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22388	27779	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22389	27780	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22390	27781	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22391	27782	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22392	27783	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22393	27784	N	N	N	1	CUSTOMER ISSUE	-
DMS_22394	27785	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22395	27786	N	N	N	1	CUSTOMER ISSUE	-
DMS_22396	27787	N	N	N	1	CUSTOMER ISSUE	-
DMS_22397	27788	N	N	N	1	CUSTOMER ISSUE	-
DMS_22398	27789	N	N	N	1	CUSTOMER ISSUE	-
DMS_22399	27790	N	N	N	1	CUSTOMER ISSUE	-
DMS_22401	27791	N	N	N	1	CUSTOMER ISSUE	-
DMS_22402	27792	N	N	N	1	CUSTOMER ISSUE	-
DMS_22403	27793	N	N	N	1	CUSTOMER ISSUE	-
DMS_22404	27794	N	N	N	1	CUSTOMER ISSUE	-
DMS_22405	27795	N	N	N	1	CUSTOMER ISSUE	-
DMS_22406	27796	N	N	N	1	CUSTOMER ISSUE	-
DMS_22407	27797	N	N	N	1	CUSTOMER ISSUE	-
DMS_22409	27798	N	N	N	1	CUSTOMER ISSUE	-
DMS_22411	27799	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22413	27800	N	N	N	1	CUSTOMER ISSUE	-
DMS_22414	27801	N	N	N	1	CUSTOMER ISSUE	-
DMS_22421	27802	N	N	N	1	CUSTOMER ISSUE	-
DMS_22425	27803	N	N	N	1	CUSTOMER ISSUE	-
DMS_22426	27804	N	N	N	1	CUSTOMER ISSUE	-
DMS_22427	27805	N	N	N	1	CUSTOMER ISSUE	-
DMS_22428	27806	N	N	N	1	CUSTOMER ISSUE	-
DMS_22429	27807	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
DMS_22430	27808	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22433	27809	N	N	N	1	CUSTOMER ISSUE	-
DMS_22434	27810	N	N	N	1	CUSTOMER ISSUE	-
DMS_22435	27811	N	N	N	1	CUSTOMER ISSUE	-
DMS_22436	27812	N	N	N	1	CUSTOMER ISSUE	-
DMS_22437	27813	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22438	27814	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22439	27815	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22440	27816	N	N	N	1	CUSTOMER ISSUE	-

DMS_22441	27817	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22442	27818	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22443	27819	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22444	27820	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22445	27821	N	N	N	1	CUSTOMER ISSUE	-
DMS_22446	27822	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22447	27823	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22448	27824	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22449	27825	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22450	27826	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22451	27827	N	N	N	1	CUSTOMER ISSUE	-
DMS_22452	27828	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22453	27829	N	N	N	1	CUSTOMER ISSUE	-
DMS_22454	27830	N	N	N	1	CUSTOMER ISSUE	-
DMS_22455	27831	N	N	N	1	CUSTOMER ISSUE	-
DMS_22456	27832	N	N	N	1	CUSTOMER ISSUE	-
DMS_22457	27833	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22458	27834	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22459	27835	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22460	27836	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22461	27837	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22462	27838	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22464	27839	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22465	27840	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22467	27841	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22469	27842	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22471	27843	N	N	N	1	CUSTOMER ISSUE	-
DMS_22472	27844	N	N	N	1	CUSTOMER ISSUE	-
DMS_22473	27845	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22474	27846	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22475	27847	N	N	N	1	CUSTOMER ISSUE	-
DMS_22476	27848	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22477	27849	N	N	N	1	CUSTOMER ISSUE	-
DMS_22478	27850	N	N	N	1	CUSTOMER ISSUE	-
DMS_22479	27851	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22480	27852	N	N	N	1	CUSTOMER ISSUE	-
DMS_22481	27853	N	N	N	1	CUSTOMER ISSUE	-
DMS_22485	27854	N	N	N	1	CUSTOMER ISSUE	-
DMS_22486	27855	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22487	27856	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22488	27857	N	N	Y	1	TX - REPLACE	2500
DMS_22490	27858	N	N	N	1	CUSTOMER ISSUE	-
DMS_22491	27859	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22492	27860	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22493	27861	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22494	27862	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22495	27863	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22496	27864	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22497	27865	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22498	27866	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22499	27867	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22500	27868	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22501	27869	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22502	27870	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22503	27871	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22504	27872	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22505	27873	N	N	N	1	CUSTOMER ISSUE	-
DMS_22506	27874	N	N	N	1	CUSTOMER ISSUE	-
DMS_22507	27875	N	N	N	1	CUSTOMER ISSUE	-
DMS_22508	27876	N	N	N	1	CUSTOMER ISSUE	-
DMS_22509	27877	N	N	N	1	CUSTOMER ISSUE	-
DMS_22510	27878	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22511	27879	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22512	27880	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_22513	27881	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22514	27882	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22515	27883	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22516	27884	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22517	27885	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22518	27886	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22519	27887	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22520	27888	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22521	27889	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22522	27890	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22523	27891	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22524	27892	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22525	27893	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22526	27894	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22527	27895	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22528	27896	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_22529	27897	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22530	27898	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22531	27899	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22532	27900	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22533	27901	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22534	27902	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22535	27903	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22536	27904	N	N	Y	1	TX - REPLACE	2500
DMS_22538	27905	N	N	N	1	CUSTOMER ISSUE	-
DMS_22540	27906	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22542	27907	N	N	N	1	CUSTOMER ISSUE	-
DMS_22543	27908	N	N	N	1	CUSTOMER ISSUE	-
DMS_22544	27909	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22545	27910	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22546	27911	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22547	27912	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22548	27913	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_22549	27914	N	N	Y	1	TX - REPLACE	2500
DMS_22550	27915	N	N	Y	1	TX - REPLACE	2500
DMS_22551	27916	N	N	N	1	CUSTOMER ISSUE	-
DMS_22552	27917	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22553	27918	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22554	27919	N	N	Y	1	TX - REPLACE	2500
DMS_22555	27920	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22556	27921	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22563	27922	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22564	27923	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22566	27924	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22567	27925	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22569	27926	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22570	27927	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_22571	27928	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22573	27929	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22577	27930	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22580	27931	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22583	27932	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22584	27933	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22585	27934	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22586	27935	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22590	27936	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22591	27937	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22593	27938	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_22594	27939	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22595	27940	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22596	27941	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22597	27942	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22598	27943	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22599	27944	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22600	27945	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22602	27946	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22603	27947	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22604	27948	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22605	27949	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22607	27950	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22608	27951	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22609	27952	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22610	27953	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22611	27954	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22613	27955	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22614	27956	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_22615	27957	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22618	27958	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22619	27959	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22621	27960	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22622	27961	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_22625	27962	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22626	27963	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22627	27964	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22628	27965	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22630	27966	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22631	27967	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_22635	27968	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22636	27969	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22637	27970	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22638	27971	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22639	27972	N	N	N	1	CUSTOMER ISSUE	-
DMS_22640	27973	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22642	27974	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22643	27975	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22646	27976	N	N	N	1	CUSTOMER ISSUE	-

DMS_22647	27977	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22648	27978	N	N	N	1	CUSTOMER ISSUE	-
DMS_22649	27979	N	N	N	1	CUSTOMER ISSUE	-
DMS_22650	27980	N	N	N	1	CUSTOMER ISSUE	-
DMS_22651	27981	N	N	N	1	CUSTOMER ISSUE	-
DMS_22652	27982	N	N	N	1	CUSTOMER ISSUE	-
DMS_22653	27983	N	N	N	1	CUSTOMER ISSUE	-
DMS_22654	27984	N	N	N	1	CUSTOMER ISSUE	-
DMS_22655	27985	N	N	N	1	CUSTOMER ISSUE	-
DMS_22656	27986	N	N	N	1	CUSTOMER ISSUE	-
DMS_22657	27987	N	N	N	1	CUSTOMER ISSUE	-
DMS_22658	27988	N	N	N	1	CUSTOMER ISSUE	-
DMS_22659	27989	N	N	N	1	CUSTOMER ISSUE	-
DMS_22660	27990	N	N	N	1	CUSTOMER ISSUE	-
DMS_22661	27991	N	N	N	1	CUSTOMER ISSUE	-
DMS_22662	27992	N	N	N	1	CUSTOMER ISSUE	-
DMS_22663	27993	N	N	N	1	CUSTOMER ISSUE	-
DMS_22664	27994	N	N	N	1	CUSTOMER ISSUE	-
DMS_22665	27995	N	N	N	1	CUSTOMER ISSUE	-
DMS_22666	27996	N	N	N	1	CUSTOMER ISSUE	-
DMS_22667	27997	N	N	N	1	CUSTOMER ISSUE	-
DMS_22668	27998	N	N	N	1	CUSTOMER ISSUE	-
DMS_22669	27999	N	N	N	1	CUSTOMER ISSUE	-
DMS_22670	28000	N	N	N	1	CUSTOMER ISSUE	-
DMS_22671	28001	N	N	N	1	CUSTOMER ISSUE	-
DMS_22672	28002	N	N	N	1	CUSTOMER ISSUE	-
DMS_22673	28003	N	N	N	1	CUSTOMER ISSUE	-
DMS_22674	28004	N	N	N	1	CUSTOMER ISSUE	-
DMS_22675	28005	N	N	N	1	CUSTOMER ISSUE	-
DMS_22676	28006	N	N	N	1	CUSTOMER ISSUE	-
DMS_22677	28007	N	N	N	1	CUSTOMER ISSUE	-
DMS_22678	28008	N	N	N	1	CUSTOMER ISSUE	-
DMS_22679	28009	N	N	N	1	CUSTOMER ISSUE	-
DMS_22680	28010	N	N	N	1	CUSTOMER ISSUE	-
DMS_22682	28011	N	N	N	1	CUSTOMER ISSUE	-
DMS_22683	28012	N	N	N	1	CUSTOMER ISSUE	-
DMS_22684	28013	N	N	N	1	CUSTOMER ISSUE	-
DMS_22685	28014	N	N	N	1	CUSTOMER ISSUE	-
DMS_22686	28015	N	N	N	1	CUSTOMER ISSUE	-
DMS_22687	28016	N	N	N	1	CUSTOMER ISSUE	-
DMS_22688	28017	N	N	N	1	CUSTOMER ISSUE	-
DMS_22689	28018	N	N	N	1	CUSTOMER ISSUE	-
DMS_22690	28019	N	N	N	1	CUSTOMER ISSUE	-
DMS_22691	28020	N	N	N	1	CUSTOMER ISSUE	-
DMS_22692	28021	N	N	N	1	CUSTOMER ISSUE	-
DMS_22693	28022	N	N	N	1	CUSTOMER ISSUE	-
DMS_22694	28023	N	N	N	1	CUSTOMER ISSUE	-
DMS_22695	28024	N	N	N	1	CUSTOMER ISSUE	-
DMS_22696	28025	N	N	N	1	CUSTOMER ISSUE	-
DMS_22697	28026	N	N	N	1	CUSTOMER ISSUE	-
DMS_22698	28027	N	N	N	1	CUSTOMER ISSUE	-
DMS_22699	28028	N	N	N	1	CUSTOMER ISSUE	-
DMS_22700	28029	N	N	N	1	CUSTOMER ISSUE	-
DMS_22701	28030	N	N	N	1	CUSTOMER ISSUE	-
DMS_22702	28031	N	N	N	1	CUSTOMER ISSUE	-
DMS_22703	28032	N	N	N	1	CUSTOMER ISSUE	-
DMS_22704	28033	N	N	N	1	CUSTOMER ISSUE	-
DMS_22705	28034	N	N	N	1	CUSTOMER ISSUE	-
DMS_22706	28035	N	N	N	1	CUSTOMER ISSUE	-
DMS_22708	28036	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_22709	28037	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22710	28038	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22711	28039	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22712	28040	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22713	28041	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22714	28042	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22715	28043	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22716	28044	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22717	28045	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22718	28046	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22720	28047	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22723	28048	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22724	28049	N	N	Y	1	TX - REPLACE	2500
DMS_22725	28050	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22726	28051	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22727	28052	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22728	28053	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22729	28054	N	N	Y	1	TX - INSTALL	3000
DMS_22731	28055	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22732	28056	N	N	Y	1	DIST - REPLACE FUSE	708.75

DMS_22733	28057	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22734	28058	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22736	28059	N	N	N	1	CUSTOMER ISSUE	-
DMS_22737	28060	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_22738	28061	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22739	28062	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22740	28063	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22741	28064	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22742	28065	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22743	28066	N	N	N	1	CUSTOMER ISSUE	-
DMS_22744	28067	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22745	28068	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22746	28069	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22747	28070	N	N	N	1	CUSTOMER ISSUE	-
DMS_22748	28071	N	N	N	1	CUSTOMER ISSUE	-
DMS_22749	28072	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22750	28073	N	N	N	1	CUSTOMER ISSUE	-
DMS_22751	28074	N	N	N	1	CUSTOMER ISSUE	-
DMS_22752	28075	N	N	N	1	CUSTOMER ISSUE	-
DMS_22753	28076	N	N	N	1	CUSTOMER ISSUE	-
DMS_22754	28077	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22755	28078	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
DMS_22757	28079	N	N	N	1	CUSTOMER ISSUE	-
DMS_22758	28080	N	N	Y	1	TX - REPLACE	2500
DMS_22760	28081	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22761	28082	N	N	N	1	CUSTOMER ISSUE	-
DMS_22762	28083	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_22763	28084	N	N	N	1	CUSTOMER ISSUE	-
DMS_22764	28085	N	N	N	1	CUSTOMER ISSUE	-
DMS_22765	28086	N	N	N	1	CUSTOMER ISSUE	-
DMS_22766	28087	N	N	N	1	CUSTOMER ISSUE	-
DMS_22767	28088	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22768	28089	N	N	N	1	CUSTOMER ISSUE	-
DMS_22769	28090	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_22770	28091	N	N	N	1	CUSTOMER ISSUE	-
DMS_22772	28092	N	N	N	1	CUSTOMER ISSUE	-
DMS_22773	28093	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22774	28094	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22775	28095	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22776	28096	N	N	N	1	CUSTOMER ISSUE	-
DMS_22777	28097	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22778	28098	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22779	28099	N	N	N	1	CUSTOMER ISSUE	-
DMS_22780	28100	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22781	28101	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22782	28102	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22783	28103	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22784	28104	N	N	N	1	CUSTOMER ISSUE	-
DMS_22785	28105	N	N	N	1	CUSTOMER ISSUE	-
DMS_22786	28106	N	N	Y	1	TX - REPLACE	2500
DMS_22787	28107	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22788	28108	N	N	N	1	CUSTOMER ISSUE	-
DMS_22789	28109	N	N	N	1	CUSTOMER ISSUE	-
DMS_22790	28110	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22791	28111	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22792	28112	N	N	Y	3	DIST - TREE TRIMMING	945
DMS_22794	28113	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22798	28114	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22799	28115	N	N	N	1	CUSTOMER ISSUE	-
DMS_22801	28116	N	N	N	1	CUSTOMER ISSUE	-
DMS_22803	28117	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22804	28118	N	N	N	1	CUSTOMER ISSUE	-
DMS_22805	28119	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22806	28120	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22807	28121	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22808	28122	N	N	N	1	CUSTOMER ISSUE	-
DMS_22809	28123	N	N	N	1	CUSTOMER ISSUE	-
DMS_22810	28124	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22812	28125	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22813	28126	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22814	28127	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22815	28128	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22816	28129	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22817	28130	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22818	28131	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22819	28132	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22820	28133	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22822	28134	N	N	N	1	CUSTOMER ISSUE	-
DMS_22823	28135	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22824	28136	N	N	N	1	CUSTOMER ISSUE	-

DMS_22825	28137	N	N	N	1	CUSTOMER ISSUE	-
DMS_22826	28138	N	N	N	1	CUSTOMER ISSUE	-
DMS_22827	28139	N	N	N	1	CUSTOMER ISSUE	-
DMS_22830	28140	N	N	N	1	CUSTOMER ISSUE	-
DMS_22831	28141	N	N	N	1	CUSTOMER ISSUE	-
DMS_22832	28142	N	N	N	1	CUSTOMER ISSUE	-
DMS_22834	28143	N	N	N	1	CUSTOMER ISSUE	-
DMS_22835	28144	N	N	N	1	CUSTOMER ISSUE	-
DMS_22836	28145	N	N	N	1	CUSTOMER ISSUE	-
DMS_22837	28146	N	N	N	1	CUSTOMER ISSUE	-
DMS_22838	28147	N	N	N	1	CUSTOMER ISSUE	-
DMS_22839	28148	N	N	N	1	CUSTOMER ISSUE	-
DMS_22840	28149	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22841	28150	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22842	28151	N	N	N	1	CUSTOMER ISSUE	-
DMS_22843	28152	N	N	N	1	CUSTOMER ISSUE	-
DMS_22844	28153	N	N	N	1	CUSTOMER ISSUE	-
DMS_22845	28154	N	N	N	1	CUSTOMER ISSUE	-
DMS_22846	28155	N	N	N	1	CUSTOMER ISSUE	-
DMS_22847	28156	N	N	N	1	CUSTOMER ISSUE	-
DMS_22848	28157	N	N	N	1	CUSTOMER ISSUE	-
DMS_22849	28158	N	N	N	1	CUSTOMER ISSUE	-
DMS_22850	28159	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22851	28160	N	N	N	1	CUSTOMER ISSUE	-
DMS_22852	28161	N	N	N	1	CUSTOMER ISSUE	-
DMS_22853	28162	N	N	N	1	CUSTOMER ISSUE	-
DMS_22854	28163	N	N	N	1	CUSTOMER ISSUE	-
DMS_22855	28164	N	N	N	1	CUSTOMER ISSUE	-
DMS_22856	28165	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22857	28166	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22858	28167	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22859	28168	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22860	28169	N	N	N	1	CUSTOMER ISSUE	-
DMS_22861	28170	N	N	N	1	CUSTOMER ISSUE	-
DMS_22862	28171	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22863	28172	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22864	28173	N	N	N	1	CUSTOMER ISSUE	-
DMS_22865	28174	N	N	N	1	CUSTOMER ISSUE	-
DMS_22866	28175	N	N	N	1	CUSTOMER ISSUE	-
DMS_22867	28176	N	N	N	1	CUSTOMER ISSUE	-
DMS_22868	28177	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22869	28178	N	N	N	1	CUSTOMER ISSUE	-
DMS_22870	28179	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22871	28180	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22872	28181	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22873	28182	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22874	28183	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22875	28184	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22876	28185	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22877	28186	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22878	28187	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22879	28188	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22880	28189	N	N	N	1	CUSTOMER ISSUE	-
DMS_22881	28190	N	N	N	1	CUSTOMER ISSUE	-
DMS_22882	28191	N	N	N	1	CUSTOMER ISSUE	-
DMS_22883	28192	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22884	28193	N	N	N	1	CUSTOMER ISSUE	-
DMS_22885	28194	N	N	N	1	CUSTOMER ISSUE	-
DMS_22886	28195	N	N	N	1	CUSTOMER ISSUE	-
DMS_22887	28196	N	N	N	1	CUSTOMER ISSUE	-
DMS_22888	28197	N	N	N	1	CUSTOMER ISSUE	-
DMS_22889	28198	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22890	28199	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22891	28200	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22892	28201	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22893	28202	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22894	28203	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22895	28204	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22896	28205	N	N	N	1	CUSTOMER ISSUE	-
DMS_22897	28206	N	N	N	1	CUSTOMER ISSUE	-
DMS_22898	28207	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22899	28208	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22900	28209	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22901	28210	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22902	28211	N	N	N	1	CUSTOMER ISSUE	-
DMS_22903	28212	N	N	N	1	CUSTOMER ISSUE	-
DMS_22904	28213	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22905	28214	N	N	N	1	CUSTOMER ISSUE	-
DMS_22906	28215	N	N	N	1	CUSTOMER ISSUE	-
DMS_22907	28216	N	N	N	1	CUSTOMER ISSUE	-

DMS_22908	28217	N	N	N	1	CUSTOMER ISSUE	-
DMS_22909	28218	N	N	N	1	CUSTOMER ISSUE	-
DMS_22910	28219	N	N	N	1	CUSTOMER ISSUE	-
DMS_22911	28220	N	N	N	1	CUSTOMER ISSUE	-
DMS_22912	28221	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22913	28222	N	N	N	1	CUSTOMER ISSUE	-
DMS_22914	28223	N	N	N	1	CUSTOMER ISSUE	-
DMS_22915	28224	N	N	N	1	CUSTOMER ISSUE	-
DMS_22916	28225	N	N	N	1	CUSTOMER ISSUE	-
DMS_22917	28226	N	N	N	1	CUSTOMER ISSUE	-
DMS_22918	28227	N	N	N	1	CUSTOMER ISSUE	-
DMS_22919	28228	N	N	N	1	CUSTOMER ISSUE	-
DMS_22920	28229	N	N	N	1	CUSTOMER ISSUE	-
DMS_22921	28230	N	N	N	1	CUSTOMER ISSUE	-
DMS_22922	28231	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22923	28232	N	N	N	1	CUSTOMER ISSUE	-
DMS_22924	28233	N	N	N	1	CUSTOMER ISSUE	-
DMS_22925	28234	N	N	N	1	CUSTOMER ISSUE	-
DMS_22926	28235	N	N	N	1	CUSTOMER ISSUE	-
DMS_22927	28236	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22928	28237	N	N	N	1	CUSTOMER ISSUE	-
DMS_22929	28238	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22930	28239	N	N	N	1	CUSTOMER ISSUE	-
DMS_22931	28240	N	N	N	1	CUSTOMER ISSUE	-
DMS_22932	28241	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22933	28242	N	N	N	1	CUSTOMER ISSUE	-
DMS_22934	28243	N	N	N	1	CUSTOMER ISSUE	-
DMS_22936	28244	N	N	N	1	CUSTOMER ISSUE	-
DMS_22937	28245	N	N	N	1	CUSTOMER ISSUE	-
DMS_22938	28246	N	N	N	1	CUSTOMER ISSUE	-
DMS_22939	28247	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22940	28248	N	N	N	1	CUSTOMER ISSUE	-
DMS_22944	28249	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22947	28250	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_22948	28251	N	N	N	1	CUSTOMER ISSUE	-
DMS_22949	28252	N	N	N	1	CUSTOMER ISSUE	-
DMS_22950	28253	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_22951	28254	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22952	28255	N	N	N	1	CUSTOMER ISSUE	-
DMS_22953	28256	N	N	N	1	CUSTOMER ISSUE	-
DMS_22954	28257	N	N	N	1	CUSTOMER ISSUE	-
DMS_22955	28258	N	N	N	1	CUSTOMER ISSUE	-
DMS_22956	28259	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_22957	28260	N	N	Y	1	TX - REPLACE	2500
DMS_22958	28261	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_22960	28262	N	N	N	1	CUSTOMER ISSUE	-
DMS_22961	28263	N	N	N	1	CUSTOMER ISSUE	-
DMS_22963	28264	N	N	N	1	CUSTOMER ISSUE	-
DMS_22964	28265	N	N	N	1	CUSTOMER ISSUE	-
DMS_22965	28266	N	N	N	1	CUSTOMER ISSUE	-
DMS_22966	28267	N	N	N	1	CUSTOMER ISSUE	-
DMS_22967	28268	N	N	N	1	CUSTOMER ISSUE	-
DMS_22968	28269	N	N	N	1	CUSTOMER ISSUE	-
DMS_22969	28270	N	N	N	1	CUSTOMER ISSUE	-
DMS_22970	28271	N	N	N	1	CUSTOMER ISSUE	-
DMS_22971	28272	N	N	N	1	CUSTOMER ISSUE	-
DMS_22972	28273	N	N	N	1	CUSTOMER ISSUE	-
DMS_22973	28274	N	N	N	1	CUSTOMER ISSUE	-
DMS_22974	28275	N	N	N	1	CUSTOMER ISSUE	-
DMS_22975	28276	N	N	N	1	CUSTOMER ISSUE	-
DMS_22976	28277	N	N	N	1	CUSTOMER ISSUE	-
DMS_22977	28278	N	N	N	1	CUSTOMER ISSUE	-
DMS_22978	28279	N	N	N	1	CUSTOMER ISSUE	-
DMS_22980	28280	N	N	N	1	CUSTOMER ISSUE	-
DMS_22981	28281	N	N	N	1	CUSTOMER ISSUE	-
DMS_22982	28282	N	N	N	1	CUSTOMER ISSUE	-
DMS_22983	28283	N	N	N	1	CUSTOMER ISSUE	-
DMS_22984	28284	N	N	N	1	CUSTOMER ISSUE	-
DMS_22985	28285	N	N	N	1	CUSTOMER ISSUE	-
DMS_22986	28286	N	N	N	1	CUSTOMER ISSUE	-
DMS_22987	28287	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22988	28288	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_22989	28289	N	N	N	1	CUSTOMER ISSUE	-
DMS_22990	28290	N	N	N	2	CUSTOMER ISSUE	-
DMS_22991	28291	N	N	N	1	CUSTOMER ISSUE	-
DMS_22992	28292	N	N	N	1	CUSTOMER ISSUE	-
DMS_22993	28293	N	N	N	2	CUSTOMER ISSUE	-
DMS_22994	28294	N	N	N	1	CUSTOMER ISSUE	-
DMS_22995	28295	N	N	N	1	CUSTOMER ISSUE	-
DMS_22996	28296	N	N	N	1	CUSTOMER ISSUE	-

DMS_22997	28297	N	N	N	1	CUSTOMER ISSUE	-
DMS_22999	28298	N	N	N	1	CUSTOMER ISSUE	-
DMS_23001	28299	N	N	N	1	CUSTOMER ISSUE	-
DMS_23002	28300	N	N	N	1	CUSTOMER ISSUE	-
DMS_23003	28301	N	N	N	1	CUSTOMER ISSUE	-
DMS_23004	28302	N	N	N	1	CUSTOMER ISSUE	-
DMS_23005	28303	N	N	N	1	CUSTOMER ISSUE	-
DMS_23006	28304	N	N	N	1	CUSTOMER ISSUE	-
DMS_23007	28305	N	N	N	1	CUSTOMER ISSUE	-
DMS_23008	28306	N	N	N	1	CUSTOMER ISSUE	-
DMS_23009	28307	N	N	N	1	CUSTOMER ISSUE	-
DMS_23010	28308	N	N	N	1	CUSTOMER ISSUE	-
DMS_23011	28309	N	N	N	1	CUSTOMER ISSUE	-
DMS_23012	28310	N	N	N	1	CUSTOMER ISSUE	-
DMS_23013	28311	N	N	N	1	CUSTOMER ISSUE	-
DMS_23014	28312	N	N	N	1	CUSTOMER ISSUE	-
DMS_23015	28313	N	N	N	1	CUSTOMER ISSUE	-
DMS_23016	28314	N	N	N	1	CUSTOMER ISSUE	-
DMS_23017	28315	N	N	N	1	CUSTOMER ISSUE	-
DMS_23018	28316	N	N	N	1	CUSTOMER ISSUE	-
DMS_23019	28317	N	N	N	1	CUSTOMER ISSUE	-
DMS_23023	28318	N	N	N	1	CUSTOMER ISSUE	-
DMS_23024	28319	N	N	N	1	CUSTOMER ISSUE	-
DMS_23025	28320	N	N	N	1	CUSTOMER ISSUE	-
DMS_23026	28321	N	N	N	1	CUSTOMER ISSUE	-
DMS_23027	28322	N	N	N	1	CUSTOMER ISSUE	-
DMS_23028	28323	N	N	N	1	CUSTOMER ISSUE	-
DMS_23029	28324	N	N	N	1	CUSTOMER ISSUE	-
DMS_23030	28325	N	N	N	1	CUSTOMER ISSUE	-
DMS_23031	28326	N	N	N	1	CUSTOMER ISSUE	-
DMS_23032	28327	N	N	N	1	CUSTOMER ISSUE	-
DMS_23033	28328	N	N	N	1	CUSTOMER ISSUE	-
DMS_23034	28329	N	N	N	1	CUSTOMER ISSUE	-
DMS_23035	28330	N	N	N	1	CUSTOMER ISSUE	-
DMS_23038	28331	N	N	N	1	CUSTOMER ISSUE	-
DMS_23043	28332	N	N	N	1	CUSTOMER ISSUE	-
DMS_23044	28333	N	N	N	1	CUSTOMER ISSUE	-
DMS_23045	28334	N	N	N	1	CUSTOMER ISSUE	-
DMS_23046	28335	N	N	N	1	CUSTOMER ISSUE	-
DMS_23047	28336	N	N	N	1	CUSTOMER ISSUE	-
DMS_23048	28337	N	N	N	1	CUSTOMER ISSUE	-
DMS_23049	28338	N	N	N	1	CUSTOMER ISSUE	-
DMS_23050	28339	N	N	N	1	CUSTOMER ISSUE	-
DMS_23051	28340	N	N	N	1	CUSTOMER ISSUE	-
DMS_23052	28341	N	N	N	1	CUSTOMER ISSUE	-
DMS_23053	28342	N	N	N	1	CUSTOMER ISSUE	-
DMS_23054	28343	N	N	N	1	CUSTOMER ISSUE	-
DMS_23055	28344	N	N	N	1	CUSTOMER ISSUE	-
DMS_23056	28345	N	N	N	1	CUSTOMER ISSUE	-
DMS_23057	28346	N	N	N	1	CUSTOMER ISSUE	-
DMS_23058	28347	N	N	N	1	CUSTOMER ISSUE	-
DMS_23059	28348	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_23060	28349	N	N	N	1	CUSTOMER ISSUE	-
DMS_23061	28350	N	N	N	1	CUSTOMER ISSUE	-
DMS_23062	28351	N	N	N	1	CUSTOMER ISSUE	-
DMS_23064	28352	N	N	N	1	CUSTOMER ISSUE	-
DMS_23065	28353	N	N	N	1	CUSTOMER ISSUE	-
DMS_23066	28354	N	N	N	1	CUSTOMER ISSUE	-
DMS_23068	28355	N	N	N	1	CUSTOMER ISSUE	-
DMS_23069	28356	N	N	N	1	CUSTOMER ISSUE	-
DMS_23070	28357	N	N	N	1	CUSTOMER ISSUE	-
DMS_23071	28358	N	N	N	1	CUSTOMER ISSUE	-
DMS_23072	28359	N	N	N	1	CUSTOMER ISSUE	-
DMS_23073	28360	N	N	N	1	CUSTOMER ISSUE	-
DMS_23074	28361	N	N	N	1	CUSTOMER ISSUE	-
DMS_23075	28362	N	N	N	1	CUSTOMER ISSUE	-
DMS_23076	28363	N	N	N	1	CUSTOMER ISSUE	-
DMS_23077	28364	N	N	N	1	CUSTOMER ISSUE	-
DMS_23078	28365	N	N	N	1	CUSTOMER ISSUE	-
DMS_23079	28366	N	N	N	1	CUSTOMER ISSUE	-
DMS_23080	28367	N	N	N	1	CUSTOMER ISSUE	-
DMS_23081	28368	N	N	N	1	CUSTOMER ISSUE	-
DMS_23082	28369	N	N	N	1	CUSTOMER ISSUE	-
DMS_23083	28370	N	N	N	1	CUSTOMER ISSUE	-
DMS_23084	28371	N	N	N	1	CUSTOMER ISSUE	-
DMS_23086	28372	N	N	N	1	CUSTOMER ISSUE	-
DMS_23088	28373	N	N	N	1	CUSTOMER ISSUE	-
DMS_23090	28374	N	N	N	1	CUSTOMER ISSUE	-
DMS_23091	28375	N	N	N	1	CUSTOMER ISSUE	-
DMS_23092	28376	N	N	N	1	CUSTOMER ISSUE	-

DMS_23093	28377	N	N	N	1	CUSTOMER ISSUE	-
DMS_23094	28378	N	N	N	1	CUSTOMER ISSUE	-
DMS_23097	28379	N	N	N	1	CUSTOMER ISSUE	-
DMS_23100	28380	N	N	N	1	CUSTOMER ISSUE	-
DMS_23104	28381	N	N	N	1	CUSTOMER ISSUE	-
DMS_23106	28382	N	N	N	1	CUSTOMER ISSUE	-
DMS_23107	28383	N	N	N	1	CUSTOMER ISSUE	-
DMS_23108	28384	N	N	N	1	CUSTOMER ISSUE	-
DMS_23111	28385	N	N	N	1	CUSTOMER ISSUE	-
DMS_23112	28386	N	N	N	1	CUSTOMER ISSUE	-
DMS_23113	28387	N	N	N	1	CUSTOMER ISSUE	-
DMS_23114	28388	N	N	N	1	CUSTOMER ISSUE	-
DMS_23115	28389	N	N	N	1	CUSTOMER ISSUE	-
DMS_23116	28390	N	N	N	1	CUSTOMER ISSUE	-
DMS_23117	28391	N	N	N	1	CUSTOMER ISSUE	-
DMS_23118	28392	N	N	N	1	CUSTOMER ISSUE	-
DMS_23119	28393	N	N	N	1	CUSTOMER ISSUE	-
DMS_23120	28394	N	N	N	1	CUSTOMER ISSUE	-
DMS_23121	28395	N	N	N	1	CUSTOMER ISSUE	-
DMS_23122	28396	N	N	N	1	CUSTOMER ISSUE	-
DMS_23123	28397	N	N	N	1	CUSTOMER ISSUE	-
DMS_23124	28398	N	N	N	1	CUSTOMER ISSUE	-
DMS_23125	28399	N	N	N	1	CUSTOMER ISSUE	-
DMS_23126	28400	N	N	N	1	CUSTOMER ISSUE	-
DMS_23127	28401	N	N	N	1	CUSTOMER ISSUE	-
DMS_23128	28402	N	N	N	1	CUSTOMER ISSUE	-
DMS_23129	28403	N	N	N	1	CUSTOMER ISSUE	-
DMS_23131	28404	N	N	N	1	CUSTOMER ISSUE	-
DMS_23132	28405	N	N	N	1	CUSTOMER ISSUE	-
DMS_23133	28406	N	N	N	1	CUSTOMER ISSUE	-
DMS_23134	28407	N	N	N	1	CUSTOMER ISSUE	-
DMS_23135	28408	N	N	N	1	CUSTOMER ISSUE	-
DMS_23137	28409	N	N	N	1	CUSTOMER ISSUE	-
DMS_23138	28410	N	N	N	1	CUSTOMER ISSUE	-
DMS_23140	28411	N	N	N	1	CUSTOMER ISSUE	-
DMS_23141	28412	N	N	N	1	CUSTOMER ISSUE	-
DMS_23142	28413	N	N	N	1	CUSTOMER ISSUE	-
DMS_23143	28414	N	N	N	1	CUSTOMER ISSUE	-
DMS_23144	28415	N	N	N	1	CUSTOMER ISSUE	-
DMS_23145	28416	N	N	N	1	CUSTOMER ISSUE	-
DMS_23146	28417	N	N	N	1	CUSTOMER ISSUE	-
DMS_23147	28418	N	N	N	1	CUSTOMER ISSUE	-
DMS_23148	28419	N	N	N	1	CUSTOMER ISSUE	-
DMS_23149	28420	N	N	N	1	CUSTOMER ISSUE	-
DMS_23150	28421	N	N	N	1	CUSTOMER ISSUE	-
DMS_23151	28422	N	N	N	1	CUSTOMER ISSUE	-
DMS_23152	28423	N	N	N	1	CUSTOMER ISSUE	-
DMS_23153	28424	N	N	N	1	CUSTOMER ISSUE	-
DMS_23154	28425	N	N	N	1	CUSTOMER ISSUE	-
DMS_23155	28426	N	N	N	1	CUSTOMER ISSUE	-
DMS_23156	28427	N	N	N	1	CUSTOMER ISSUE	-
DMS_23157	28428	N	N	N	1	CUSTOMER ISSUE	-
DMS_23158	28429	N	N	N	1	CUSTOMER ISSUE	-
DMS_23159	28430	N	N	N	1	CUSTOMER ISSUE	-
DMS_23160	28431	N	N	N	1	CUSTOMER ISSUE	-
DMS_23161	28432	N	N	N	1	CUSTOMER ISSUE	-
DMS_23162	28433	N	N	N	1	CUSTOMER ISSUE	-
DMS_23165	28434	N	N	N	1	CUSTOMER ISSUE	-
DMS_23166	28435	N	N	N	1	CUSTOMER ISSUE	-
DMS_23167	28436	N	N	N	1	CUSTOMER ISSUE	-
DMS_23169	28437	N	N	N	1	CUSTOMER ISSUE	-
DMS_23170	28438	N	N	N	1	CUSTOMER ISSUE	-
DMS_23171	28439	N	N	N	1	CUSTOMER ISSUE	-
DMS_23172	28440	N	N	N	1	CUSTOMER ISSUE	-
DMS_23174	28441	N	N	N	1	CUSTOMER ISSUE	-
DMS_23175	28442	N	N	N	1	CUSTOMER ISSUE	-
DMS_23176	28443	N	N	N	1	CUSTOMER ISSUE	-
DMS_23178	28444	N	N	N	1	CUSTOMER ISSUE	-
DMS_23181	28445	N	N	N	1	CUSTOMER ISSUE	-
DMS_23182	28446	N	N	N	1	CUSTOMER ISSUE	-
DMS_23183	28447	N	N	N	1	CUSTOMER ISSUE	-
DMS_23184	28448	N	N	N	1	CUSTOMER ISSUE	-
DMS_23185	28449	N	N	N	1	CUSTOMER ISSUE	-
DMS_23186	28450	N	N	N	1	CUSTOMER ISSUE	-
DMS_23187	28451	N	N	N	1	CUSTOMER ISSUE	-
DMS_23188	28452	N	N	N	1	CUSTOMER ISSUE	-
DMS_23189	28453	N	N	N	1	CUSTOMER ISSUE	-
DMS_23190	28454	N	N	N	1	CUSTOMER ISSUE	-
DMS_23191	28455	N	N	N	1	CUSTOMER ISSUE	-
DMS_23192	28456	N	N	N	1	CUSTOMER ISSUE	-

DMS_23193	28457	N	N	N	1	CUSTOMER ISSUE	-
DMS_23195	28458	N	N	N	1	CUSTOMER ISSUE	-
DMS_23196	28459	N	N	N	1	CUSTOMER ISSUE	-
DMS_23197	28460	N	N	N	1	CUSTOMER ISSUE	-
DMS_23198	28461	N	N	N	1	CUSTOMER ISSUE	-
DMS_23199	28462	N	N	N	1	CUSTOMER ISSUE	-
DMS_23200	28463	N	N	N	1	CUSTOMER ISSUE	-
DMS_23201	28464	N	N	N	1	CUSTOMER ISSUE	-
DMS_23202	28465	N	N	N	1	CUSTOMER ISSUE	-
DMS_23203	28466	N	N	N	1	CUSTOMER ISSUE	-
DMS_23204	28467	N	N	N	1	CUSTOMER ISSUE	-
DMS_23205	28468	N	N	N	1	CUSTOMER ISSUE	-
DMS_23206	28469	N	N	N	1	CUSTOMER ISSUE	-
DMS_23207	28470	N	N	N	1	CUSTOMER ISSUE	-
DMS_23208	28471	N	N	N	1	CUSTOMER ISSUE	-
DMS_23209	28472	N	N	N	1	CUSTOMER ISSUE	-
DMS_23210	28473	N	N	N	1	CUSTOMER ISSUE	-
DMS_23211	28474	N	N	N	1	CUSTOMER ISSUE	-
DMS_23212	28475	N	N	N	1	CUSTOMER ISSUE	-
DMS_23213	28476	N	N	N	1	CUSTOMER ISSUE	-
DMS_23214	28477	N	N	N	2	CUSTOMER ISSUE	-
DMS_23215	28478	N	N	N	1	CUSTOMER ISSUE	-
DMS_23216	28479	N	N	N	1	CUSTOMER ISSUE	-
DMS_23218	28480	N	N	N	1	CUSTOMER ISSUE	-
DMS_23219	28481	N	N	N	1	CUSTOMER ISSUE	-
DMS_23220	28482	N	N	N	1	CUSTOMER ISSUE	-
DMS_23221	28483	N	N	N	1	CUSTOMER ISSUE	-
DMS_23222	28484	N	N	N	1	CUSTOMER ISSUE	-
DMS_23224	28485	N	N	N	1	CUSTOMER ISSUE	-
DMS_23225	28486	N	N	N	1	CUSTOMER ISSUE	-
DMS_23226	28487	N	N	N	1	CUSTOMER ISSUE	-
DMS_23227	28488	N	N	N	1	CUSTOMER ISSUE	-
DMS_23228	28489	N	N	N	1	CUSTOMER ISSUE	-
DMS_23229	28490	N	N	N	1	CUSTOMER ISSUE	-
DMS_23230	28491	N	N	N	1	CUSTOMER ISSUE	-
DMS_23231	28492	N	N	N	1	CUSTOMER ISSUE	-
DMS_23232	28493	N	N	N	1	CUSTOMER ISSUE	-
DMS_23233	28494	N	N	N	1	CUSTOMER ISSUE	-
DMS_23234	28495	N	N	N	1	CUSTOMER ISSUE	-
DMS_23235	28496	N	N	N	1	CUSTOMER ISSUE	-
DMS_23236	28497	N	N	N	1	CUSTOMER ISSUE	-
DMS_23237	28498	N	N	N	1	CUSTOMER ISSUE	-
DMS_23239	28499	N	N	N	2	CUSTOMER ISSUE	-
DMS_23240	28500	N	N	N	1	CUSTOMER ISSUE	-
DMS_23241	28501	N	N	N	1	CUSTOMER ISSUE	-
DMS_23242	28502	N	N	N	1	CUSTOMER ISSUE	-
DMS_23243	28503	N	N	N	1	CUSTOMER ISSUE	-
DMS_23244	28504	N	N	N	1	CUSTOMER ISSUE	-
DMS_23245	28505	N	N	N	1	CUSTOMER ISSUE	-
DMS_23246	28506	N	N	N	1	CUSTOMER ISSUE	-
DMS_23247	28507	N	N	N	1	CUSTOMER ISSUE	-
DMS_23248	28508	N	N	N	1	CUSTOMER ISSUE	-
DMS_23249	28509	N	N	N	1	CUSTOMER ISSUE	-
DMS_23250	28510	N	N	N	1	CUSTOMER ISSUE	-
DMS_23251	28511	N	N	N	1	CUSTOMER ISSUE	-
DMS_23252	28512	N	N	N	1	CUSTOMER ISSUE	-
DMS_23255	28513	N	N	N	1	CUSTOMER ISSUE	-
DMS_23256	28514	N	N	N	1	CUSTOMER ISSUE	-
DMS_23258	28515	N	N	N	1	CUSTOMER ISSUE	-
DMS_23259	28516	N	N	N	1	CUSTOMER ISSUE	-
DMS_23260	28517	N	N	N	1	CUSTOMER ISSUE	-
DMS_23263	28518	N	N	N	1	CUSTOMER ISSUE	-
DMS_23264	28519	N	N	N	1	CUSTOMER ISSUE	-
DMS_23266	28520	N	N	N	1	CUSTOMER ISSUE	-
DMS_23267	28521	N	N	N	1	CUSTOMER ISSUE	-
DMS_23268	28522	N	N	N	1	CUSTOMER ISSUE	-
DMS_23269	28523	N	N	N	1	CUSTOMER ISSUE	-
DMS_23270	28524	N	N	N	1	CUSTOMER ISSUE	-
DMS_23271	28525	N	N	N	1	CUSTOMER ISSUE	-
DMS_23272	28526	N	N	N	1	CUSTOMER ISSUE	-
DMS_23273	28527	N	N	N	1	CUSTOMER ISSUE	-
DMS_23274	28528	N	N	N	1	CUSTOMER ISSUE	-
DMS_23275	28529	N	N	N	1	CUSTOMER ISSUE	-
DMS_23276	28530	N	N	N	1	CUSTOMER ISSUE	-
DMS_23277	28531	N	N	N	1	CUSTOMER ISSUE	-
DMS_23278	28532	N	N	N	1	CUSTOMER ISSUE	-
DMS_23279	28533	N	N	N	1	CUSTOMER ISSUE	-
DMS_23280	28534	N	N	N	1	CUSTOMER ISSUE	-
DMS_23281	28535	N	N	N	1	CUSTOMER ISSUE	-
DMS_23282	28536	N	N	N	1	CUSTOMER ISSUE	-

DMS_23283	28537	N	N	N	1	CUSTOMER ISSUE	-
DMS_23284	28538	N	N	N	1	CUSTOMER ISSUE	-
DMS_23285	28539	N	N	N	1	CUSTOMER ISSUE	-
DMS_23286	28540	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23287	28541	N	N	N	1	CUSTOMER ISSUE	-
DMS_23288	28542	N	N	N	1	CUSTOMER ISSUE	-
DMS_23289	28543	N	N	N	1	CUSTOMER ISSUE	-
DMS_23290	28544	N	N	N	1	CUSTOMER ISSUE	-
DMS_23291	28545	N	N	N	1	CUSTOMER ISSUE	-
DMS_23292	28546	N	N	N	1	CUSTOMER ISSUE	-
DMS_23299	28547	N	N	N	1	CUSTOMER ISSUE	-
DMS_23300	28548	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23302	28549	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_23303	28550	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_23304	28551	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_23306	28552	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23307	28553	N	N	N	1	CUSTOMER ISSUE	-
DMS_23309	28554	N	N	N	1	CUSTOMER ISSUE	-
DMS_23325	28555	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23327	28556	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23330	28557	N	N	N	1	CUSTOMER ISSUE	-
DMS_23331	28558	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23332	28559	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_23333	28560	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23334	28561	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23336	28562	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23337	28563	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23338	28564	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23339	28565	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23340	28566	N	N	N	1	CUSTOMER ISSUE	-
DMS_23341	28567	N	N	N	1	CUSTOMER ISSUE	-
DMS_23342	28568	N	N	N	1	CUSTOMER ISSUE	-
DMS_23344	28569	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23345	28570	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23346	28571	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23347	28572	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23348	28573	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23349	28574	N	N	N	1	CUSTOMER ISSUE	-
DMS_23350	28575	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23351	28576	N	N	N	1	CUSTOMER ISSUE	-
DMS_23352	28577	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23354	28578	N	N	N	1	CUSTOMER ISSUE	-
DMS_23355	28579	N	N	N	1	CUSTOMER ISSUE	-
DMS_23356	28580	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23357	28581	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23358	28582	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23359	28583	N	N	N	1	CUSTOMER ISSUE	-
DMS_23361	28584	N	N	N	1	CUSTOMER ISSUE	-
DMS_23363	28585	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23364	28586	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23365	28587	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23366	28588	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23367	28589	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23369	28590	N	N	N	1	CUSTOMER ISSUE	-
DMS_23370	28591	N	N	N	1	CUSTOMER ISSUE	-
DMS_23372	28592	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23373	28593	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_23374	28594	N	N	Y	1	DIST - CIRCUIT RETURN TO NORMAL CONFIG	472.5
DMS_23375	28595	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23376	28596	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23377	28597	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23378	28598	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23379	28599	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23380	28600	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23381	28601	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23382	28602	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23383	28603	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23384	28604	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23385	28605	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_23386	28606	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23388	28607	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_23390	28608	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23391	28609	N	N	N	1	CUSTOMER ISSUE	-
DMS_23392	28610	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23393	28611	N	N	N	1	CUSTOMER ISSUE	-
DMS_23394	28612	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23395	28613	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23396	28614	N	N	N	1	CUSTOMER ISSUE	-
DMS_23397	28615	N	N	N	1	CUSTOMER ISSUE	-
DMS_23398	28616	N	N	N	1	CUSTOMER ISSUE	-

DMS_23399	28617	N	N	N	1	CUSTOMER ISSUE	-
DMS_23400	28618	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23401	28619	N	N	N	1	CUSTOMER ISSUE	-
DMS_23402	28620	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23403	28621	N	N	N	1	CUSTOMER ISSUE	-
DMS_23404	28622	N	N	N	1	CUSTOMER ISSUE	-
DMS_23405	28623	N	N	N	1	CUSTOMER ISSUE	-
DMS_23408	28624	N	N	N	1	CUSTOMER ISSUE	-
DMS_23409	28625	N	N	N	1	CUSTOMER ISSUE	-
DMS_23410	28626	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23412	28627	N	N	N	1	CUSTOMER ISSUE	-
DMS_23413	28628	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23414	28629	N	N	N	1	CUSTOMER ISSUE	-
DMS_23415	28630	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_23416	28631	N	N	N	1	CUSTOMER ISSUE	-
DMS_23417	28632	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23418	28633	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23420	28634	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_23421	28635	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23422	28636	N	N	N	1	CUSTOMER ISSUE	-
DMS_23423	28637	N	N	N	1	CUSTOMER ISSUE	-
DMS_23426	28638	N	N	N	1	CUSTOMER ISSUE	-
DMS_23428	28639	N	N	N	1	CUSTOMER ISSUE	-
DMS_23429	28640	N	N	N	1	CUSTOMER ISSUE	-
DMS_23430	28641	N	N	N	1	CUSTOMER ISSUE	-
DMS_23431	28642	N	N	N	1	CUSTOMER ISSUE	-
DMS_23432	28643	N	N	N	1	CUSTOMER ISSUE	-
DMS_23433	28644	N	N	N	1	CUSTOMER ISSUE	-
DMS_23434	28645	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23436	28646	N	N	N	1	CUSTOMER ISSUE	-
DMS_23437	28647	N	N	N	1	CUSTOMER ISSUE	-
DMS_23438	28648	N	N	N	1	CUSTOMER ISSUE	-
DMS_23439	28649	N	N	N	1	CUSTOMER ISSUE	-
DMS_23440	28650	N	N	N	1	CUSTOMER ISSUE	-
DMS_23441	28651	N	N	N	1	CUSTOMER ISSUE	-
DMS_23442	28652	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23443	28653	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23444	28654	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23445	28655	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23446	28656	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23448	28657	N	N	N	1	CUSTOMER ISSUE	-
DMS_23449	28658	N	N	N	1	CUSTOMER ISSUE	-
DMS_23452	28659	N	N	N	1	CUSTOMER ISSUE	-
DMS_23453	28660	N	N	N	1	CUSTOMER ISSUE	-
DMS_23454	28661	N	N	N	1	CUSTOMER ISSUE	-
DMS_23455	28662	N	N	N	1	CUSTOMER ISSUE	-
DMS_23456	28663	N	N	N	1	CUSTOMER ISSUE	-
DMS_23457	28664	N	N	N	1	CUSTOMER ISSUE	-
DMS_23458	28665	N	N	N	1	CUSTOMER ISSUE	-
DMS_23459	28666	N	N	N	1	CUSTOMER ISSUE	-
DMS_23460	28667	N	N	N	1	CUSTOMER ISSUE	-
DMS_23461	28668	N	N	N	1	CUSTOMER ISSUE	-
DMS_23462	28669	N	N	N	1	CUSTOMER ISSUE	-
DMS_23463	28670	N	N	N	1	CUSTOMER ISSUE	-
DMS_23464	28671	N	N	N	1	CUSTOMER ISSUE	-
DMS_23465	28672	N	N	N	1	CUSTOMER ISSUE	-
DMS_23466	28673	N	N	N	1	CUSTOMER ISSUE	-
DMS_23467	28674	N	N	N	1	CUSTOMER ISSUE	-
DMS_23468	28675	N	N	N	1	CUSTOMER ISSUE	-
DMS_23469	28676	N	N	N	1	CUSTOMER ISSUE	-
DMS_23470	28677	N	N	N	1	CUSTOMER ISSUE	-
DMS_23471	28678	N	N	N	1	CUSTOMER ISSUE	-
DMS_23472	28679	N	N	N	1	CUSTOMER ISSUE	-
DMS_23473	28680	N	N	N	1	CUSTOMER ISSUE	-
DMS_23474	28681	N	N	N	1	CUSTOMER ISSUE	-
DMS_23475	28682	N	N	N	1	CUSTOMER ISSUE	-
DMS_23476	28683	N	N	N	1	CUSTOMER ISSUE	-
DMS_23477	28684	N	N	N	1	CUSTOMER ISSUE	-
DMS_23478	28685	N	N	N	2	CUSTOMER ISSUE	-
DMS_23479	28686	N	N	N	1	CUSTOMER ISSUE	-
DMS_23480	28687	N	N	N	1	CUSTOMER ISSUE	-
DMS_23481	28688	N	N	N	1	CUSTOMER ISSUE	-
DMS_23482	28689	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_23483	28690	N	N	N	1	CUSTOMER ISSUE	-
DMS_23484	28691	N	N	N	1	CUSTOMER ISSUE	-
DMS_23485	28692	N	N	N	1	CUSTOMER ISSUE	-
DMS_23486	28693	N	N	N	1	CUSTOMER ISSUE	-
DMS_23487	28694	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23488	28695	N	N	N	1	CUSTOMER ISSUE	-
DMS_23489	28696	N	N	N	1	CUSTOMER ISSUE	-

DMS_23490	28697	N	N	N	1	CUSTOMER ISSUE	-
DMS_23491	28698	N	N	N	1	CUSTOMER ISSUE	-
DMS_23492	28699	N	N	N	1	CUSTOMER ISSUE	-
DMS_23495	28700	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23496	28701	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23497	28702	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23498	28703	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23499	28704	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23500	28705	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23501	28706	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23504	28707	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23506	28708	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23507	28709	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23508	28710	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23509	28711	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23510	28712	N	N	N	1	CUSTOMER ISSUE	-
DMS_23511	28713	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23512	28714	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23514	28715	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23515	28716	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23516	28717	N	N	N	1	CUSTOMER ISSUE	-
DMS_23517	28718	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23518	28719	N	N	Y	1	DIST - CIRCUIT RETURN TO NORMAL CONFIG	472.5
DMS_23519	28720	N	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
DMS_23520	28721	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23522	28722	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23523	28723	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23524	28724	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23525	28725	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23526	28726	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23528	28727	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23529	28728	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23530	28729	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23532	28730	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23533	28731	N	N	N	1	CUSTOMER ISSUE	-
DMS_23534	28732	N	N	N	1	CUSTOMER ISSUE	-
DMS_23535	28733	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23537	28734	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23538	28735	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23540	28736	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23541	28737	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23542	28738	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23544	28739	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23545	28740	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23546	28741	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23547	28742	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23548	28743	N	N	N	1	CUSTOMER ISSUE	-
DMS_23549	28744	N	N	N	1	CUSTOMER ISSUE	-
DMS_23550	28745	N	N	N	1	CUSTOMER ISSUE	-
DMS_23551	28746	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23554	28747	N	N	Y	1	TX - REPLACE	2500
DMS_23555	28748	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23556	28749	N	N	Y	2	DIST - CHANGE SETTINGS	708.75
DMS_23557	28750	N	N	Y	1	TX - REPLACE	2500
DMS_23558	28751	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23560	28752	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23562	28753	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23563	28754	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23564	28755	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23567	28756	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23568	28757	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23569	28758	N	N	N	1	CUSTOMER ISSUE	-
DMS_23571	28759	N	N	N	1	CUSTOMER ISSUE	-
DMS_23572	28760	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23573	28761	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23574	28762	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23575	28763	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23578	28764	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23581	28765	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23582	28766	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23583	28767	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23584	28768	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23585	28769	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23586	28770	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23587	28771	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23588	28772	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23589	28773	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23590	28774	N	N	N	1	CUSTOMER ISSUE	-
DMS_23591	28775	N	N	N	1	CUSTOMER ISSUE	-
DMS_23592	28776	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_23593	28777	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23594	28778	N	N	N	1	CUSTOMER ISSUE	-
DMS_23595	28779	N	N	N	1	CUSTOMER ISSUE	-
DMS_23597	28780	N	N	N	1	CUSTOMER ISSUE	-
DMS_23598	28781	N	N	N	1	CUSTOMER ISSUE	-
DMS_23599	28782	N	N	N	1	CUSTOMER ISSUE	-
DMS_23600	28783	N	N	N	1	CUSTOMER ISSUE	-
DMS_23601	28784	N	N	N	1	CUSTOMER ISSUE	-
DMS_23602	28785	N	N	N	1	CUSTOMER ISSUE	-
DMS_23603	28786	N	N	N	1	CUSTOMER ISSUE	-
DMS_23604	28787	N	N	N	1	CUSTOMER ISSUE	-
DMS_23605	28788	N	N	N	1	CUSTOMER ISSUE	-
DMS_23606	28789	N	N	N	1	CUSTOMER ISSUE	-
DMS_23608	28790	N	N	N	1	CUSTOMER ISSUE	-
DMS_23609	28791	N	N	N	1	CUSTOMER ISSUE	-
DMS_23610	28792	N	N	N	1	CUSTOMER ISSUE	-
DMS_23611	28793	N	N	N	1	CUSTOMER ISSUE	-
DMS_23612	28794	N	N	N	1	CUSTOMER ISSUE	-
DMS_23613	28795	N	N	N	1	CUSTOMER ISSUE	-
DMS_23614	28796	N	N	N	1	CUSTOMER ISSUE	-
DMS_23615	28797	N	N	N	1	CUSTOMER ISSUE	-
DMS_23616	28798	N	N	N	1	CUSTOMER ISSUE	-
DMS_23618	28799	N	N	N	1	CUSTOMER ISSUE	-
DMS_23620	28800	N	N	N	1	CUSTOMER ISSUE	-
DMS_23621	28801	N	N	N	1	CUSTOMER ISSUE	-
DMS_23623	28802	N	N	N	2	CUSTOMER ISSUE	-
DMS_23624	28803	N	N	N	1	CUSTOMER ISSUE	-
DMS_23625	28804	N	N	N	1	CUSTOMER ISSUE	-
DMS_23626	28805	N	N	N	1	CUSTOMER ISSUE	-
DMS_23627	28806	N	N	N	1	CUSTOMER ISSUE	-
DMS_23628	28807	N	N	N	1	CUSTOMER ISSUE	-
DMS_23629	28808	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23631	28809	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23632	28810	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23633	28811	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23634	28812	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23635	28813	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23636	28814	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23637	28815	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23638	28816	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23639	28817	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23640	28818	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23641	28819	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23642	28820	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23643	28821	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23644	28822	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23645	28823	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23646	28824	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23647	28825	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23648	28826	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23649	28827	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23650	28828	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23651	28829	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23652	28830	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23653	28831	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23654	28832	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23655	28833	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23656	28834	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23657	28835	N	N	Y	3	SEC/SVC - REPAIR	472.5
DMS_23658	28836	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23659	28837	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23660	28838	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23661	28839	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23662	28840	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23663	28841	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23664	28842	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23665	28843	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23666	28844	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23667	28845	N	N	N	1	CUSTOMER ISSUE	-
DMS_23668	28846	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23669	28847	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23670	28848	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23671	28849	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23672	28850	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23673	28851	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23674	28852	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23675	28853	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23676	28854	N	N	N	1	CUSTOMER ISSUE	-
DMS_23677	28855	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23678	28856	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_23679	28857	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23680	28858	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23681	28859	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23682	28860	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23683	28861	N	N	N	1	CUSTOMER ISSUE	-
DMS_23684	28862	N	N	N	1	CUSTOMER ISSUE	-
DMS_23685	28863	N	N	N	1	CUSTOMER ISSUE	-
DMS_23686	28864	N	N	N	1	CUSTOMER ISSUE	-
DMS_23687	28865	N	N	N	1	CUSTOMER ISSUE	-
DMS_23688	28866	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23689	28867	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23690	28868	N	N	Y	3	SEC/SVC - REPAIR	472.5
DMS_23691	28869	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23692	28870	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23693	28871	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23694	28872	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23695	28873	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23696	28874	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23697	28875	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23698	28876	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23699	28877	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23700	28878	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23701	28879	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23702	28880	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23703	28881	N	N	N	1	CUSTOMER ISSUE	-
DMS_23704	28882	N	N	N	1	CUSTOMER ISSUE	-
DMS_23705	28883	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23707	28884	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23713	28885	N	N	N	1	CUSTOMER ISSUE	-
DMS_23714	28886	N	N	N	1	CUSTOMER ISSUE	-
DMS_23715	28887	N	N	N	1	CUSTOMER ISSUE	-
DMS_23717	28888	N	N	N	1	CUSTOMER ISSUE	-
DMS_23718	28889	N	N	N	1	CUSTOMER ISSUE	-
DMS_23719	28890	N	N	N	1	CUSTOMER ISSUE	-
DMS_23720	28891	N	N	N	1	CUSTOMER ISSUE	-
DMS_23722	28892	N	N	N	1	CUSTOMER ISSUE	-
DMS_23723	28893	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23725	28894	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_23727	28895	N	N	N	1	CUSTOMER ISSUE	-
DMS_23728	28896	N	N	N	1	CUSTOMER ISSUE	-
DMS_23729	28897	N	N	N	1	CUSTOMER ISSUE	-
DMS_23730	28898	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_23731	28899	N	N	N	1	CUSTOMER ISSUE	-
DMS_23732	28900	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23734	28901	N	N	N	1	CUSTOMER ISSUE	-
DMS_23736	28902	N	N	N	1	CUSTOMER ISSUE	-
DMS_23737	28903	N	N	N	1	CUSTOMER ISSUE	-
DMS_23738	28904	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_23739	28905	N	N	N	1	CUSTOMER ISSUE	-
DMS_23740	28906	N	N	N	1	CUSTOMER ISSUE	-
DMS_23741	28907	N	N	N	1	CUSTOMER ISSUE	-
DMS_23742	28908	N	N	N	1	CUSTOMER ISSUE	-
DMS_23743	28909	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_23744	28910	N	N	N	1	CUSTOMER ISSUE	-
DMS_23745	28911	N	N	N	1	CUSTOMER ISSUE	-
DMS_23746	28912	N	N	N	1	CUSTOMER ISSUE	-
DMS_23747	28913	N	N	N	1	CUSTOMER ISSUE	-
DMS_23748	28914	N	N	N	1	CUSTOMER ISSUE	-
DMS_23749	28915	N	N	N	1	CUSTOMER ISSUE	-
DMS_23750	28916	N	N	N	1	CUSTOMER ISSUE	-
DMS_23751	28917	N	N	N	1	CUSTOMER ISSUE	-
DMS_23752	28918	N	N	N	1	CUSTOMER ISSUE	-
DMS_23753	28919	N	N	N	1	CUSTOMER ISSUE	-
DMS_23755	28920	N	N	N	1	CUSTOMER ISSUE	-
DMS_23756	28921	N	N	N	1	CUSTOMER ISSUE	-
DMS_23757	28922	N	N	N	1	CUSTOMER ISSUE	-
DMS_23758	28923	N	N	N	1	CUSTOMER ISSUE	-
DMS_23760	28924	N	N	N	1	CUSTOMER ISSUE	-
DMS_23762	28925	N	N	N	1	CUSTOMER ISSUE	-
DMS_23763	28926	N	N	N	1	CUSTOMER ISSUE	-
DMS_23764	28927	N	N	N	1	CUSTOMER ISSUE	-
DMS_23765	28928	N	N	N	1	CUSTOMER ISSUE	-
DMS_23766	28929	N	N	N	1	CUSTOMER ISSUE	-
DMS_23767	28930	N	N	N	1	CUSTOMER ISSUE	-
DMS_23768	28931	N	N	N	1	CUSTOMER ISSUE	-
DMS_23769	28932	N	N	N	1	CUSTOMER ISSUE	-
DMS_23770	28933	N	N	N	1	CUSTOMER ISSUE	-
DMS_23771	28934	N	N	N	1	CUSTOMER ISSUE	-
DMS_23772	28935	N	N	N	1	CUSTOMER ISSUE	-
DMS_23773	28936	N	N	N	1	CUSTOMER ISSUE	-

DMS_23774	28937	N	N	N	1	CUSTOMER ISSUE	-
DMS_23775	28938	N	N	N	1	CUSTOMER ISSUE	-
DMS_23776	28939	N	N	N	1	CUSTOMER ISSUE	-
DMS_23777	28940	N	N	N	1	CUSTOMER ISSUE	-
DMS_23778	28941	N	N	N	1	CUSTOMER ISSUE	-
DMS_23779	28942	N	N	N	1	CUSTOMER ISSUE	-
DMS_23780	28943	N	N	N	1	CUSTOMER ISSUE	-
DMS_23782	28944	N	N	N	1	CUSTOMER ISSUE	-
DMS_23783	28945	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_23784	28946	N	N	N	1	CUSTOMER ISSUE	-
DMS_23785	28947	N	N	N	1	CUSTOMER ISSUE	-
DMS_23786	28948	N	N	N	1	CUSTOMER ISSUE	-
DMS_23787	28949	N	N	N	1	CUSTOMER ISSUE	-
DMS_23788	28950	N	N	N	1	CUSTOMER ISSUE	-
DMS_23789	28951	N	N	N	1	CUSTOMER ISSUE	-
DMS_23790	28952	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_23791	28953	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23792	28954	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23793	28955	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23794	28956	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_23795	28957	N	N	N	1	CUSTOMER ISSUE	-
DMS_23797	28958	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_23799	28959	N	N	N	1	CUSTOMER ISSUE	-
DMS_23800	28960	N	N	N	1	CUSTOMER ISSUE	-
DMS_23801	28961	N	N	N	1	CUSTOMER ISSUE	-
DMS_23802	28962	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23803	28963	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23804	28964	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23805	28965	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23806	28966	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23807	28967	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23808	28968	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23809	28969	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23810	28970	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23811	28971	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23812	28972	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23813	28973	N	N	N	1	CUSTOMER ISSUE	-
DMS_23814	28974	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23816	28975	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23817	28976	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23818	28977	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23819	28978	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23820	28979	N	N	N	1	CUSTOMER ISSUE	-
DMS_23821	28980	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23822	28981	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23823	28982	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23824	28983	N	N	N	1	CUSTOMER ISSUE	-
DMS_23825	28984	N	N	N	1	CUSTOMER ISSUE	-
DMS_23826	28985	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23827	28986	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23828	28987	N	N	N	1	CUSTOMER ISSUE	-
DMS_23829	28988	N	N	N	1	CUSTOMER ISSUE	-
DMS_23830	28989	N	N	N	1	CUSTOMER ISSUE	-
DMS_23831	28990	N	N	N	1	CUSTOMER ISSUE	-
DMS_23832	28991	N	N	N	1	CUSTOMER ISSUE	-
DMS_23833	28992	N	N	N	1	CUSTOMER ISSUE	-
DMS_23834	28993	N	N	N	1	CUSTOMER ISSUE	-
DMS_23835	28994	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_23836	28995	N	N	N	1	CUSTOMER ISSUE	-
DMS_23838	28996	N	N	N	1	CUSTOMER ISSUE	-
DMS_23839	28997	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23840	28998	N	N	N	1	CUSTOMER ISSUE	-
DMS_23841	28999	N	N	N	1	CUSTOMER ISSUE	-
DMS_23842	29000	N	N	N	1	CUSTOMER ISSUE	-
DMS_23843	29001	N	N	N	1	CUSTOMER ISSUE	-
DMS_23844	29002	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_23845	29003	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_23846	29004	N	N	N	1	CUSTOMER ISSUE	-
DMS_23847	29005	N	N	N	1	CUSTOMER ISSUE	-
DMS_23848	29006	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23849	29007	N	N	N	1	CUSTOMER ISSUE	-
DMS_23850	29008	N	N	N	1	CUSTOMER ISSUE	-
DMS_23851	29009	N	N	N	1	CUSTOMER ISSUE	-
DMS_23852	29010	N	N	N	1	CUSTOMER ISSUE	-
DMS_23853	29011	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23854	29012	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_23855	29013	N	N	N	1	CUSTOMER ISSUE	-
DMS_23856	29014	N	N	N	1	CUSTOMER ISSUE	-
DMS_23857	29015	N	N	Y	2	DIST - CHANGE SETTINGS	708.75
DMS_23859	29016	N	N	N	1	CUSTOMER ISSUE	-

DMS_23861	29017	N	N	N	1	CUSTOMER ISSUE	-
DMS_23862	29018	N	N	N	1	CUSTOMER ISSUE	-
DMS_23863	29019	N	N	N	1	CUSTOMER ISSUE	-
DMS_23864	29020	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23876	29021	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23877	29022	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23878	29023	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23879	29024	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23880	29025	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23881	29026	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23882	29027	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23883	29028	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23884	29029	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23885	29030	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23886	29031	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23887	29032	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23888	29033	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23889	29034	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23890	29035	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23891	29036	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23892	29037	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23893	29038	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23894	29039	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23895	29040	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23896	29041	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23897	29042	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23898	29043	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23899	29044	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23900	29045	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23901	29046	N	N	N	1	CUSTOMER ISSUE	-
DMS_23902	29047	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23903	29048	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23904	29049	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23905	29050	N	N	N	1	CUSTOMER ISSUE	-
DMS_23906	29051	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23907	29052	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23908	29053	N	N	N	1	CUSTOMER ISSUE	-
DMS_23909	29054	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23910	29055	N	N	N	1	CUSTOMER ISSUE	-
DMS_23911	29056	N	N	N	1	CUSTOMER ISSUE	-
DMS_23912	29057	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23913	29058	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23914	29059	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_23915	29060	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23916	29061	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23917	29062	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23918	29063	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23919	29064	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23920	29065	N	N	N	1	CUSTOMER ISSUE	-
DMS_23921	29066	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23922	29067	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23923	29068	N	N	N	1	CUSTOMER ISSUE	-
DMS_23924	29069	N	N	N	1	CUSTOMER ISSUE	-
DMS_23926	29070	N	N	N	1	CUSTOMER ISSUE	-
DMS_23927	29071	N	N	N	1	CUSTOMER ISSUE	-
DMS_23928	29072	N	N	N	1	CUSTOMER ISSUE	-
DMS_23929	29073	N	N	N	1	CUSTOMER ISSUE	-
DMS_23930	29074	N	N	N	1	CUSTOMER ISSUE	-
DMS_23931	29075	N	N	N	1	CUSTOMER ISSUE	-
DMS_23932	29076	N	N	N	1	CUSTOMER ISSUE	-
DMS_23933	29077	N	N	N	1	CUSTOMER ISSUE	-
DMS_23934	29078	N	N	N	1	CUSTOMER ISSUE	-
DMS_23935	29079	N	N	N	1	CUSTOMER ISSUE	-
DMS_23936	29080	N	N	N	1	CUSTOMER ISSUE	-
DMS_23937	29081	N	N	N	1	CUSTOMER ISSUE	-
DMS_23938	29082	N	N	N	1	CUSTOMER ISSUE	-
DMS_23939	29083	N	N	N	1	CUSTOMER ISSUE	-
DMS_23940	29084	N	N	N	1	CUSTOMER ISSUE	-
DMS_23941	29085	N	N	N	1	CUSTOMER ISSUE	-
DMS_23942	29086	N	N	N	1	CUSTOMER ISSUE	-
DMS_23943	29087	N	N	N	1	CUSTOMER ISSUE	-
DMS_23944	29088	N	N	N	1	CUSTOMER ISSUE	-
DMS_23945	29089	N	N	N	1	CUSTOMER ISSUE	-
DMS_23946	29090	N	N	N	1	CUSTOMER ISSUE	-
DMS_23947	29091	N	N	N	1	CUSTOMER ISSUE	-
DMS_23948	29092	N	N	N	1	CUSTOMER ISSUE	-
DMS_23949	29093	N	N	N	1	CUSTOMER ISSUE	-
DMS_23950	29094	N	N	N	1	CUSTOMER ISSUE	-
DMS_23951	29095	N	N	N	1	CUSTOMER ISSUE	-
DMS_23952	29096	N	N	N	1	CUSTOMER ISSUE	-

DMS_23953	29097	N	N	N	1	CUSTOMER ISSUE	-
DMS_23954	29098	N	N	N	1	CUSTOMER ISSUE	-
DMS_23955	29099	N	N	N	1	CUSTOMER ISSUE	-
DMS_23956	29100	N	N	N	1	CUSTOMER ISSUE	-
DMS_23957	29101	N	N	N	1	CUSTOMER ISSUE	-
DMS_23958	29102	N	N	N	1	CUSTOMER ISSUE	-
DMS_23959	29103	N	N	N	1	CUSTOMER ISSUE	-
DMS_23960	29104	N	N	N	1	CUSTOMER ISSUE	-
DMS_23961	29105	N	N	N	1	CUSTOMER ISSUE	-
DMS_23962	29106	N	N	N	1	CUSTOMER ISSUE	-
DMS_23963	29107	N	N	N	1	CUSTOMER ISSUE	-
DMS_23964	29108	N	N	N	1	CUSTOMER ISSUE	-
DMS_23965	29109	N	N	N	1	CUSTOMER ISSUE	-
DMS_23966	29110	N	N	N	1	CUSTOMER ISSUE	-
DMS_23967	29111	N	N	N	1	CUSTOMER ISSUE	-
DMS_23968	29112	N	N	N	1	CUSTOMER ISSUE	-
DMS_23969	29113	N	N	N	1	CUSTOMER ISSUE	-
DMS_23970	29114	N	N	N	1	CUSTOMER ISSUE	-
DMS_23971	29115	N	N	N	1	CUSTOMER ISSUE	-
DMS_23972	29116	N	N	N	1	CUSTOMER ISSUE	-
DMS_23973	29117	N	N	N	1	CUSTOMER ISSUE	-
DMS_23974	29118	N	N	N	1	CUSTOMER ISSUE	-
DMS_23975	29119	N	N	N	1	CUSTOMER ISSUE	-
DMS_23977	29120	N	N	N	1	CUSTOMER ISSUE	-
DMS_23978	29121	N	N	N	1	CUSTOMER ISSUE	-
DMS_23979	29122	N	N	N	1	CUSTOMER ISSUE	-
DMS_23980	29123	N	N	N	1	CUSTOMER ISSUE	-
DMS_23981	29124	N	N	N	1	CUSTOMER ISSUE	-
DMS_23982	29125	N	N	N	1	CUSTOMER ISSUE	-
DMS_23983	29126	N	N	N	1	CUSTOMER ISSUE	-
DMS_23984	29127	N	N	N	1	CUSTOMER ISSUE	-
DMS_23985	29128	N	N	N	1	CUSTOMER ISSUE	-
DMS_23986	29129	N	N	N	1	CUSTOMER ISSUE	-
DMS_23987	29130	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23988	29131	N	N	N	1	CUSTOMER ISSUE	-
DMS_23989	29132	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23990	29133	N	N	N	1	CUSTOMER ISSUE	-
DMS_23992	29134	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_23994	29135	N	N	N	1	CUSTOMER ISSUE	-
DMS_23995	29136	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23996	29137	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_23997	29138	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_23998	29139	N	N	N	1	CUSTOMER ISSUE	-
DMS_23999	29140	N	N	N	1	CUSTOMER ISSUE	-
DMS_24000	29141	N	N	N	1	CUSTOMER ISSUE	-
DMS_24001	29142	N	N	N	1	CUSTOMER ISSUE	-
DMS_24002	29143	N	N	N	1	CUSTOMER ISSUE	-
DMS_24003	29144	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24004	29145	N	N	N	1	CUSTOMER ISSUE	-
DMS_24005	29146	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24007	29147	N	N	N	1	CUSTOMER ISSUE	-
DMS_24008	29148	N	N	N	1	CUSTOMER ISSUE	-
DMS_24009	29149	N	N	N	1	CUSTOMER ISSUE	-
DMS_24010	29150	N	N	N	1	CUSTOMER ISSUE	-
DMS_24011	29151	N	N	N	1	CUSTOMER ISSUE	-
DMS_24012	29152	N	N	N	1	CUSTOMER ISSUE	-
DMS_24013	29153	N	N	N	1	CUSTOMER ISSUE	-
DMS_24014	29154	N	N	N	1	CUSTOMER ISSUE	-
DMS_24016	29155	N	N	N	1	CUSTOMER ISSUE	-
DMS_24017	29156	N	N	N	1	CUSTOMER ISSUE	-
DMS_24018	29157	N	N	N	1	CUSTOMER ISSUE	-
DMS_24019	29158	N	N	N	1	CUSTOMER ISSUE	-
DMS_24020	29159	N	N	N	1	CUSTOMER ISSUE	-
DMS_24021	29160	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24022	29161	N	N	N	1	CUSTOMER ISSUE	-
DMS_24023	29162	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24024	29163	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24025	29164	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24026	29165	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24027	29166	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24029	29167	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24030	29168	N	N	N	1	CUSTOMER ISSUE	-
DMS_24031	29169	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24032	29170	N	N	N	1	CUSTOMER ISSUE	-
DMS_24033	29171	N	N	N	1	CUSTOMER ISSUE	-
DMS_24034	29172	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24035	29173	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24036	29174	N	N	N	1	CUSTOMER ISSUE	-
DMS_24037	29175	N	N	N	1	CUSTOMER ISSUE	-
DMS_24039	29176	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_24040	29177	N	N	N	1	CUSTOMER ISSUE	-
DMS_24041	29178	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24043	29179	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24045	29180	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24046	29181	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24047	29182	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24048	29183	N	N	N	1	CUSTOMER ISSUE	-
DMS_24049	29184	N	N	N	1	CUSTOMER ISSUE	-
DMS_24050	29185	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24051	29186	N	N	N	1	CUSTOMER ISSUE	-
DMS_24052	29187	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24053	29188	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24054	29189	N	N	N	1	CUSTOMER ISSUE	-
DMS_24055	29190	N	N	N	1	CUSTOMER ISSUE	-
DMS_24056	29191	N	N	N	1	CUSTOMER ISSUE	-
DMS_24057	29192	N	N	N	1	CUSTOMER ISSUE	-
DMS_24058	29193	N	N	N	1	CUSTOMER ISSUE	-
DMS_24059	29194	N	N	N	1	CUSTOMER ISSUE	-
DMS_24060	29195	N	N	N	1	CUSTOMER ISSUE	-
DMS_24061	29196	N	N	N	1	CUSTOMER ISSUE	-
DMS_24062	29197	N	N	N	1	CUSTOMER ISSUE	-
DMS_24063	29198	N	N	N	1	CUSTOMER ISSUE	-
DMS_24064	29199	N	N	N	1	CUSTOMER ISSUE	-
DMS_24065	29200	N	N	N	1	CUSTOMER ISSUE	-
DMS_24066	29201	N	N	N	1	CUSTOMER ISSUE	-
DMS_24067	29202	N	N	N	1	CUSTOMER ISSUE	-
DMS_24068	29203	N	N	N	1	CUSTOMER ISSUE	-
DMS_24069	29204	N	N	N	1	CUSTOMER ISSUE	-
DMS_24070	29205	N	N	N	1	CUSTOMER ISSUE	-
DMS_24071	29206	N	N	N	1	CUSTOMER ISSUE	-
DMS_24072	29207	N	N	N	1	CUSTOMER ISSUE	-
DMS_24073	29208	N	N	N	1	CUSTOMER ISSUE	-
DMS_24074	29209	N	N	N	1	CUSTOMER ISSUE	-
DMS_24075	29210	N	N	N	1	CUSTOMER ISSUE	-
DMS_24076	29211	N	N	N	1	CUSTOMER ISSUE	-
DMS_24077	29212	N	N	N	1	CUSTOMER ISSUE	-
DMS_24078	29213	N	N	N	1	CUSTOMER ISSUE	-
DMS_24079	29214	N	N	N	1	CUSTOMER ISSUE	-
DMS_24080	29215	N	N	N	1	CUSTOMER ISSUE	-
DMS_24081	29216	N	N	N	1	CUSTOMER ISSUE	-
DMS_24082	29217	N	N	N	1	CUSTOMER ISSUE	-
DMS_24083	29218	N	N	N	1	CUSTOMER ISSUE	-
DMS_24084	29219	N	N	N	1	CUSTOMER ISSUE	-
DMS_24085	29220	N	N	N	1	CUSTOMER ISSUE	-
DMS_24086	29221	N	N	N	1	CUSTOMER ISSUE	-
DMS_24087	29222	N	N	N	1	CUSTOMER ISSUE	-
DMS_24088	29223	N	N	N	1	CUSTOMER ISSUE	-
DMS_24089	29224	N	N	N	1	CUSTOMER ISSUE	-
DMS_24090	29225	N	N	N	1	CUSTOMER ISSUE	-
DMS_24091	29226	N	N	N	1	CUSTOMER ISSUE	-
DMS_24092	29227	N	N	N	1	CUSTOMER ISSUE	-
DMS_24093	29228	N	N	N	1	CUSTOMER ISSUE	-
DMS_24094	29229	N	N	N	1	CUSTOMER ISSUE	-
DMS_24095	29230	N	N	N	1	CUSTOMER ISSUE	-
DMS_24096	29231	N	N	N	1	CUSTOMER ISSUE	-
DMS_24097	29232	N	N	N	1	CUSTOMER ISSUE	-
DMS_24098	29233	N	N	N	1	CUSTOMER ISSUE	-
DMS_24099	29234	N	N	N	1	CUSTOMER ISSUE	-
DMS_24100	29235	N	N	N	1	CUSTOMER ISSUE	-
DMS_24101	29236	N	N	N	1	CUSTOMER ISSUE	-
DMS_24102	29237	N	N	N	1	CUSTOMER ISSUE	-
DMS_24103	29238	N	N	N	1	CUSTOMER ISSUE	-
DMS_24104	29239	N	N	N	1	CUSTOMER ISSUE	-
DMS_24105	29240	N	N	N	1	CUSTOMER ISSUE	-
DMS_24106	29241	N	N	N	1	CUSTOMER ISSUE	-
DMS_24107	29242	N	N	N	1	CUSTOMER ISSUE	-
DMS_24108	29243	N	N	N	1	CUSTOMER ISSUE	-
DMS_24109	29244	N	N	N	1	CUSTOMER ISSUE	-
DMS_24110	29245	N	N	N	1	CUSTOMER ISSUE	-
DMS_24111	29246	N	N	N	1	CUSTOMER ISSUE	-
DMS_24112	29247	N	N	N	1	CUSTOMER ISSUE	-
DMS_24113	29248	N	N	N	1	CUSTOMER ISSUE	-
DMS_24114	29249	N	N	N	1	CUSTOMER ISSUE	-
DMS_24115	29250	N	N	N	1	CUSTOMER ISSUE	-
DMS_24116	29251	N	N	N	1	CUSTOMER ISSUE	-
DMS_24117	29252	N	N	N	1	CUSTOMER ISSUE	-
DMS_24118	29253	N	N	N	1	CUSTOMER ISSUE	-
DMS_24119	29254	N	N	N	1	CUSTOMER ISSUE	-
DMS_24120	29255	N	N	N	1	CUSTOMER ISSUE	-
DMS_24121	29256	N	N	N	1	CUSTOMER ISSUE	-

DMS_24122	29257	N	N	N	1	CUSTOMER ISSUE	-
DMS_24123	29258	N	N	N	1	CUSTOMER ISSUE	-
DMS_24124	29259	N	N	N	1	CUSTOMER ISSUE	-
DMS_24125	29260	N	N	N	1	CUSTOMER ISSUE	-
DMS_24126	29261	N	N	N	1	CUSTOMER ISSUE	-
DMS_24127	29262	N	N	N	1	CUSTOMER ISSUE	-
DMS_24128	29263	N	N	N	1	CUSTOMER ISSUE	-
DMS_24129	29264	N	N	N	1	CUSTOMER ISSUE	-
DMS_24130	29265	N	N	N	1	CUSTOMER ISSUE	-
DMS_24131	29266	N	N	N	1	CUSTOMER ISSUE	-
DMS_24132	29267	N	N	N	1	CUSTOMER ISSUE	-
DMS_24133	29268	N	N	N	1	CUSTOMER ISSUE	-
DMS_24134	29269	N	N	N	1	CUSTOMER ISSUE	-
DMS_24135	29270	N	N	N	1	CUSTOMER ISSUE	-
DMS_24136	29271	N	N	N	1	CUSTOMER ISSUE	-
DMS_24137	29272	N	N	N	1	CUSTOMER ISSUE	-
DMS_24138	29273	N	N	N	1	CUSTOMER ISSUE	-
DMS_24139	29274	N	N	N	1	CUSTOMER ISSUE	-
DMS_24140	29275	N	N	N	1	CUSTOMER ISSUE	-
DMS_24141	29276	N	N	N	1	CUSTOMER ISSUE	-
DMS_24142	29277	N	N	N	1	CUSTOMER ISSUE	-
DMS_24143	29278	N	N	N	1	CUSTOMER ISSUE	-
DMS_24144	29279	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24145	29280	N	N	N	1	CUSTOMER ISSUE	-
DMS_24146	29281	N	N	N	1	CUSTOMER ISSUE	-
DMS_24147	29282	N	N	N	1	CUSTOMER ISSUE	-
DMS_24148	29283	N	N	N	1	CUSTOMER ISSUE	-
DMS_24149	29284	N	N	N	1	CUSTOMER ISSUE	-
DMS_24150	29285	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_24151	29286	N	N	N	1	CUSTOMER ISSUE	-
DMS_24153	29287	N	N	N	1	CUSTOMER ISSUE	-
DMS_24154	29288	N	N	N	1	CUSTOMER ISSUE	-
DMS_24155	29289	N	N	N	1	CUSTOMER ISSUE	-
DMS_24156	29290	N	N	N	1	CUSTOMER ISSUE	-
DMS_24157	29291	N	N	N	1	CUSTOMER ISSUE	-
DMS_24158	29292	N	N	N	1	CUSTOMER ISSUE	-
DMS_24159	29293	N	N	N	1	CUSTOMER ISSUE	-
DMS_24160	29294	N	N	N	1	CUSTOMER ISSUE	-
DMS_24161	29295	N	N	N	1	CUSTOMER ISSUE	-
DMS_24162	29296	N	N	N	1	CUSTOMER ISSUE	-
DMS_24163	29297	N	N	N	1	CUSTOMER ISSUE	-
DMS_24164	29298	N	N	N	1	CUSTOMER ISSUE	-
DMS_24165	29299	N	N	N	1	CUSTOMER ISSUE	-
DMS_24166	29300	N	N	N	1	CUSTOMER ISSUE	-
DMS_24167	29301	N	N	N	1	CUSTOMER ISSUE	-
DMS_24168	29302	N	N	N	1	CUSTOMER ISSUE	-
DMS_24169	29303	N	N	N	1	CUSTOMER ISSUE	-
DMS_24170	29304	N	N	N	1	CUSTOMER ISSUE	-
DMS_24171	29305	N	N	N	1	CUSTOMER ISSUE	-
DMS_24172	29306	N	N	N	1	CUSTOMER ISSUE	-
DMS_24174	29307	N	N	N	1	CUSTOMER ISSUE	-
DMS_24175	29308	N	N	N	1	CUSTOMER ISSUE	-
DMS_24176	29309	N	N	N	1	CUSTOMER ISSUE	-
DMS_24177	29310	N	N	N	1	CUSTOMER ISSUE	-
DMS_24178	29311	N	N	N	1	CUSTOMER ISSUE	-
DMS_24179	29312	N	N	N	1	CUSTOMER ISSUE	-
DMS_24180	29313	N	N	N	1	CUSTOMER ISSUE	-
DMS_24181	29314	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_24182	29315	N	N	N	1	CUSTOMER ISSUE	-
DMS_24185	29316	N	N	N	1	CUSTOMER ISSUE	-
DMS_24186	29317	N	N	N	1	CUSTOMER ISSUE	-
DMS_24188	29318	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24189	29319	N	N	N	1	CUSTOMER ISSUE	-
DMS_24190	29320	N	N	N	1	CUSTOMER ISSUE	-
DMS_24191	29321	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24193	29322	N	N	N	1	CUSTOMER ISSUE	-
DMS_24194	29323	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24195	29324	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24196	29325	N	N	N	1	CUSTOMER ISSUE	-
DMS_24197	29326	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24198	29327	N	N	N	1	CUSTOMER ISSUE	-
DMS_24199	29328	N	N	N	1	CUSTOMER ISSUE	-
DMS_24200	29329	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_24201	29330	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24202	29331	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24203	29332	N	N	N	1	CUSTOMER ISSUE	-
DMS_24204	29333	N	N	N	1	CUSTOMER ISSUE	-
DMS_24205	29334	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24206	29335	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24207	29336	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_24213	29337	N	N	N	1	CUSTOMER ISSUE	-
DMS_24214	29338	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24215	29339	N	N	N	1	CUSTOMER ISSUE	-
DMS_24216	29340	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24217	29341	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24218	29342	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24219	29343	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24221	29344	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24223	29345	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24224	29346	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24225	29347	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24226	29348	N	N	N	1	CUSTOMER ISSUE	-
DMS_24227	29349	N	N	N	1	CUSTOMER ISSUE	-
DMS_24228	29350	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24229	29351	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24230	29352	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24231	29353	N	N	N	1	CUSTOMER ISSUE	-
DMS_24232	29354	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24233	29355	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24234	29356	N	N	N	1	CUSTOMER ISSUE	-
DMS_24237	29357	N	N	N	1	CUSTOMER ISSUE	-
DMS_24239	29358	N	N	N	1	CUSTOMER ISSUE	-
DMS_24240	29359	N	N	N	1	CUSTOMER ISSUE	-
DMS_24244	29360	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24245	29361	N	N	N	1	CUSTOMER ISSUE	-
DMS_24247	29362	N	N	N	1	CUSTOMER ISSUE	-
DMS_24248	29363	N	N	N	1	CUSTOMER ISSUE	-
DMS_24249	29364	N	N	N	1	CUSTOMER ISSUE	-
DMS_24250	29365	N	N	N	2	CUSTOMER ISSUE	-
DMS_24251	29366	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24252	29367	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24253	29368	N	N	N	1	CUSTOMER ISSUE	-
DMS_24254	29369	N	N	N	1	CUSTOMER ISSUE	-
DMS_24255	29370	N	N	N	1	CUSTOMER ISSUE	-
DMS_24256	29371	N	N	N	1	CUSTOMER ISSUE	-
DMS_24257	29372	N	N	N	1	CUSTOMER ISSUE	-
DMS_24258	29373	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24259	29374	N	N	N	1	CUSTOMER ISSUE	-
DMS_24260	29375	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24261	29376	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24262	29377	N	N	N	1	CUSTOMER ISSUE	-
DMS_24263	29378	N	N	N	1	CUSTOMER ISSUE	-
DMS_24265	29379	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24268	29380	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24269	29381	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24270	29382	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24271	29383	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24272	29384	N	N	N	1	CUSTOMER ISSUE	-
DMS_24273	29385	N	N	N	1	CUSTOMER ISSUE	-
DMS_24274	29386	N	N	N	1	CUSTOMER ISSUE	-
DMS_24276	29387	N	N	N	1	CUSTOMER ISSUE	-
DMS_24277	29388	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
DMS_24278	29389	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24279	29390	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24280	29391	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24281	29392	N	N	N	1	CUSTOMER ISSUE	-
DMS_24282	29393	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24283	29394	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24284	29395	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_24285	29396	N	N	N	1	CUSTOMER ISSUE	-
DMS_24286	29397	N	N	N	1	CUSTOMER ISSUE	-
DMS_24287	29398	N	N	N	1	CUSTOMER ISSUE	-
DMS_24288	29399	N	N	N	1	CUSTOMER ISSUE	-
DMS_24289	29400	N	N	N	1	CUSTOMER ISSUE	-
DMS_24290	29401	N	N	N	1	CUSTOMER ISSUE	-
DMS_24292	29402	N	N	N	1	CUSTOMER ISSUE	-
DMS_24293	29403	N	N	N	1	CUSTOMER ISSUE	-
DMS_24294	29404	N	N	N	1	CUSTOMER ISSUE	-
DMS_24295	29405	N	N	N	1	CUSTOMER ISSUE	-
DMS_24296	29406	N	N	N	1	CUSTOMER ISSUE	-
DMS_24297	29407	N	N	N	1	CUSTOMER ISSUE	-
DMS_24298	29408	N	N	N	1	CUSTOMER ISSUE	-
DMS_24299	29409	N	N	N	1	CUSTOMER ISSUE	-
DMS_24300	29410	N	N	N	1	CUSTOMER ISSUE	-
DMS_24301	29411	N	N	N	1	CUSTOMER ISSUE	-
DMS_24302	29412	N	N	N	1	CUSTOMER ISSUE	-
DMS_24303	29413	N	N	N	1	CUSTOMER ISSUE	-
DMS_24304	29414	N	N	N	1	CUSTOMER ISSUE	-
DMS_24305	29415	N	N	N	1	CUSTOMER ISSUE	-
DMS_24306	29416	N	N	N	1	CUSTOMER ISSUE	-

DMS_24307	29417	N	N	N	1	CUSTOMER ISSUE	-
DMS_24308	29418	N	N	N	1	CUSTOMER ISSUE	-
DMS_24309	29419	N	N	N	1	CUSTOMER ISSUE	-
DMS_24310	29420	N	N	N	1	CUSTOMER ISSUE	-
DMS_24311	29421	N	N	N	1	CUSTOMER ISSUE	-
DMS_24312	29422	N	N	N	1	CUSTOMER ISSUE	-
DMS_24313	29423	N	N	N	1	CUSTOMER ISSUE	-
DMS_24314	29424	N	N	N	1	CUSTOMER ISSUE	-
DMS_24315	29425	N	N	N	1	CUSTOMER ISSUE	-
DMS_24316	29426	N	N	N	1	CUSTOMER ISSUE	-
DMS_24317	29427	N	N	N	1	CUSTOMER ISSUE	-
DMS_24318	29428	N	N	N	1	CUSTOMER ISSUE	-
DMS_24319	29429	N	N	N	1	CUSTOMER ISSUE	-
DMS_24321	29430	N	N	N	1	CUSTOMER ISSUE	-
DMS_24322	29431	N	N	N	1	CUSTOMER ISSUE	-
DMS_24323	29432	N	N	N	1	CUSTOMER ISSUE	-
DMS_24324	29433	N	N	N	1	CUSTOMER ISSUE	-
DMS_24325	29434	N	N	N	1	CUSTOMER ISSUE	-
DMS_24326	29435	N	N	N	1	CUSTOMER ISSUE	-
DMS_24327	29436	N	N	N	1	CUSTOMER ISSUE	-
DMS_24328	29437	N	N	N	1	CUSTOMER ISSUE	-
DMS_24329	29438	N	N	N	1	CUSTOMER ISSUE	-
DMS_24330	29439	N	N	N	1	CUSTOMER ISSUE	-
DMS_24331	29440	N	N	N	1	CUSTOMER ISSUE	-
DMS_24332	29441	N	N	N	1	CUSTOMER ISSUE	-
DMS_24333	29442	N	N	N	1	CUSTOMER ISSUE	-
DMS_24334	29443	N	N	N	1	CUSTOMER ISSUE	-
DMS_24335	29444	N	N	N	1	CUSTOMER ISSUE	-
DMS_24336	29445	N	N	N	1	CUSTOMER ISSUE	-
DMS_24337	29446	N	N	N	1	CUSTOMER ISSUE	-
DMS_24338	29447	N	N	N	1	CUSTOMER ISSUE	-
DMS_24339	29448	N	N	N	1	CUSTOMER ISSUE	-
DMS_24340	29449	N	N	N	1	CUSTOMER ISSUE	-
DMS_24341	29450	N	N	N	1	CUSTOMER ISSUE	-
DMS_24342	29451	N	N	N	1	CUSTOMER ISSUE	-
DMS_24343	29452	N	N	N	1	CUSTOMER ISSUE	-
DMS_24345	29453	N	N	N	1	CUSTOMER ISSUE	-
DMS_24346	29454	N	N	N	1	CUSTOMER ISSUE	-
DMS_24347	29455	N	N	N	1	CUSTOMER ISSUE	-
DMS_24348	29456	N	N	N	1	CUSTOMER ISSUE	-
DMS_24349	29457	N	N	N	1	CUSTOMER ISSUE	-
DMS_24350	29458	N	N	N	1	CUSTOMER ISSUE	-
DMS_24351	29459	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24352	29460	N	N	N	1	CUSTOMER ISSUE	-
DMS_24353	29461	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24354	29462	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24355	29463	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24356	29464	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24357	29465	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24358	29466	N	N	N	1	CUSTOMER ISSUE	-
DMS_24359	29467	N	N	N	1	CUSTOMER ISSUE	-
DMS_24360	29468	N	N	N	1	CUSTOMER ISSUE	-
DMS_24361	29469	N	N	N	1	CUSTOMER ISSUE	-
DMS_24362	29470	N	N	N	1	CUSTOMER ISSUE	-
DMS_24363	29471	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_24364	29472	N	N	N	1	CUSTOMER ISSUE	-
DMS_24365	29473	N	N	N	1	CUSTOMER ISSUE	-
DMS_24366	29474	N	N	N	1	CUSTOMER ISSUE	-
DMS_24367	29475	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24368	29476	N	N	N	1	CUSTOMER ISSUE	-
DMS_24371	29477	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24376	29478	N	N	N	1	CUSTOMER ISSUE	-
DMS_24377	29479	N	N	N	1	CUSTOMER ISSUE	-
DMS_24378	29480	N	N	N	1	CUSTOMER ISSUE	-
DMS_24379	29481	N	N	N	1	CUSTOMER ISSUE	-
DMS_24380	29482	N	N	N	1	CUSTOMER ISSUE	-
DMS_24381	29483	N	N	N	1	CUSTOMER ISSUE	-
DMS_24382	29484	N	N	N	2	CUSTOMER ISSUE	-
DMS_24384	29485	N	N	N	1	CUSTOMER ISSUE	-
DMS_24385	29486	N	N	N	1	CUSTOMER ISSUE	-
DMS_24386	29487	N	N	N	1	CUSTOMER ISSUE	-
DMS_24387	29488	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24388	29489	N	N	N	1	CUSTOMER ISSUE	-
DMS_24391	29490	N	N	N	1	CUSTOMER ISSUE	-
DMS_24392	29491	N	N	N	1	CUSTOMER ISSUE	-
DMS_24393	29492	N	N	N	2	CUSTOMER ISSUE	-
DMS_24394	29493	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24396	29494	N	N	N	1	CUSTOMER ISSUE	-
DMS_24397	29495	N	N	N	1	CUSTOMER ISSUE	-
DMS_24405	29496	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_24406	29497	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24407	29498	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24408	29499	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24409	29500	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24410	29501	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24411	29502	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24413	29503	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24414	29504	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24415	29505	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24416	29506	N	N	N	1	CUSTOMER ISSUE	-
DMS_24420	29507	N	N	N	1	CUSTOMER ISSUE	-
DMS_24423	29508	N	N	N	1	CUSTOMER ISSUE	-
DMS_24424	29509	N	N	N	1	CUSTOMER ISSUE	-
DMS_24425	29510	N	N	N	1	CUSTOMER ISSUE	-
DMS_24426	29511	N	N	N	1	CUSTOMER ISSUE	-
DMS_24428	29512	N	N	N	1	CUSTOMER ISSUE	-
DMS_24429	29513	N	N	N	1	CUSTOMER ISSUE	-
DMS_24430	29514	N	N	N	1	CUSTOMER ISSUE	-
DMS_24431	29515	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24432	29516	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24433	29517	N	N	N	1	CUSTOMER ISSUE	-
DMS_24437	29518	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_24449	29519	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24450	29520	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24451	29521	N	N	N	1	CUSTOMER ISSUE	-
DMS_24452	29522	N	N	N	1	CUSTOMER ISSUE	-
DMS_24453	29523	N	N	N	1	CUSTOMER ISSUE	-
DMS_24458	29524	N	N	N	1	CUSTOMER ISSUE	-
DMS_24460	29525	N	N	N	1	CUSTOMER ISSUE	-
DMS_24461	29526	N	N	N	1	CUSTOMER ISSUE	-
DMS_24467	29527	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24468	29528	N	N	N	1	CUSTOMER ISSUE	-
DMS_24469	29529	N	N	N	1	CUSTOMER ISSUE	-
DMS_24471	29530	N	N	N	1	CUSTOMER ISSUE	-
DMS_24472	29531	N	N	N	1	CUSTOMER ISSUE	-
DMS_24473	29532	N	N	N	1	CUSTOMER ISSUE	-
DMS_24474	29533	N	N	N	1	CUSTOMER ISSUE	-
DMS_24475	29534	N	N	N	1	CUSTOMER ISSUE	-
DMS_24476	29535	N	N	N	1	CUSTOMER ISSUE	-
DMS_24477	29536	N	N	N	1	CUSTOMER ISSUE	-
DMS_24478	29537	N	N	N	1	CUSTOMER ISSUE	-
DMS_24479	29538	N	N	N	1	CUSTOMER ISSUE	-
DMS_24480	29539	N	N	N	1	CUSTOMER ISSUE	-
DMS_24481	29540	N	N	N	1	CUSTOMER ISSUE	-
DMS_24482	29541	N	N	N	1	CUSTOMER ISSUE	-
DMS_24483	29542	N	N	N	1	CUSTOMER ISSUE	-
DMS_24484	29543	N	N	N	1	CUSTOMER ISSUE	-
DMS_24485	29544	N	N	N	1	CUSTOMER ISSUE	-
DMS_24486	29545	N	N	N	1	CUSTOMER ISSUE	-
DMS_24487	29546	N	N	N	1	CUSTOMER ISSUE	-
DMS_24488	29547	N	N	N	1	CUSTOMER ISSUE	-
DMS_24489	29548	N	N	N	1	CUSTOMER ISSUE	-
DMS_24490	29549	N	N	N	1	CUSTOMER ISSUE	-
DMS_24491	29550	N	N	N	1	CUSTOMER ISSUE	-
DMS_24492	29551	N	N	N	1	CUSTOMER ISSUE	-
DMS_24493	29552	N	N	N	1	CUSTOMER ISSUE	-
DMS_24494	29553	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24495	29554	N	N	N	1	CUSTOMER ISSUE	-
DMS_24496	29555	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24497	29556	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24498	29557	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24499	29558	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24501	29559	N	N	N	1	CUSTOMER ISSUE	-
DMS_24502	29560	N	N	N	1	CUSTOMER ISSUE	-
DMS_24503	29561	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_24508	29562	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24509	29563	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24515	29564	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24519	29565	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24520	29566	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_24523	29567	N	N	N	1	CUSTOMER ISSUE	-
DMS_24525	29568	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24526	29569	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24530	29570	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24531	29571	N	N	N	1	CUSTOMER ISSUE	-
DMS_24535	29572	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24541	29573	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24543	29574	N	N	N	1	CUSTOMER ISSUE	-
DMS_24544	29575	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24545	29576	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_24547	29577	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24549	29578	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24553	29579	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24554	29580	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24555	29581	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24556	29582	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24558	29583	N	N	N	1	CUSTOMER ISSUE	-
DMS_24560	29584	N	N	N	1	CUSTOMER ISSUE	-
DMS_24561	29585	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24562	29586	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24563	29587	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24565	29588	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24567	29589	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24568	29590	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24569	29591	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24572	29592	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24573	29593	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24574	29594	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24575	29595	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24576	29596	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24577	29597	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24579	29598	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24581	29599	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24583	29600	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24584	29601	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24586	29602	N	N	N	1	CUSTOMER ISSUE	-
DMS_24595	29603	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24597	29604	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24598	29605	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24600	29606	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24601	29607	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24604	29608	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24605	29609	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24606	29610	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24607	29611	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24608	29612	N	N	N	1	CUSTOMER ISSUE	-
DMS_24609	29613	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24611	29614	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24613	29615	N	N	N	2	CUSTOMER ISSUE	-
DMS_24615	29616	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24616	29617	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24617	29618	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24620	29619	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24622	29620	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24624	29621	N	N	N	1	CUSTOMER ISSUE	-
DMS_24625	29622	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24627	29623	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24629	29624	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24630	29625	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24631	29626	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24633	29627	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24634	29628	N	N	N	1	CUSTOMER ISSUE	-
DMS_24637	29629	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24639	29630	N	N	N	1	CUSTOMER ISSUE	-
DMS_24641	29631	N	N	N	1	CUSTOMER ISSUE	-
DMS_24642	29632	N	N	N	1	CUSTOMER ISSUE	-
DMS_24643	29633	N	N	N	1	CUSTOMER ISSUE	-
DMS_24644	29634	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24647	29635	N	N	Y	1	TX - REPLACE	2500
DMS_24648	29636	N	N	Y	1	TX - REPLACE	2500
DMS_24649	29637	N	N	Y	1	TX - REPLACE	2500
DMS_24651	29638	N	N	N	1	CUSTOMER ISSUE	-
DMS_24655	29639	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24656	29640	N	N	N	1	CUSTOMER ISSUE	-
DMS_24658	29641	N	N	N	1	CUSTOMER ISSUE	-
DMS_24659	29642	N	N	N	1	CUSTOMER ISSUE	-
DMS_24660	29643	N	N	N	1	CUSTOMER ISSUE	-
DMS_24661	29644	N	N	N	1	CUSTOMER ISSUE	-
DMS_24662	29645	N	N	N	1	CUSTOMER ISSUE	-
DMS_24663	29646	N	N	N	1	CUSTOMER ISSUE	-
DMS_24664	29647	N	N	N	1	CUSTOMER ISSUE	-
DMS_24665	29648	N	N	N	1	CUSTOMER ISSUE	-
DMS_24666	29649	N	N	N	1	CUSTOMER ISSUE	-
DMS_24667	29650	N	N	N	1	CUSTOMER ISSUE	-
DMS_24668	29651	N	N	N	1	CUSTOMER ISSUE	-
DMS_24669	29652	N	N	N	1	CUSTOMER ISSUE	-
DMS_24670	29653	N	N	N	1	CUSTOMER ISSUE	-
DMS_24671	29654	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24672	29655	N	N	N	1	CUSTOMER ISSUE	-
DMS_24673	29656	N	N	N	1	CUSTOMER ISSUE	-

DMS_24674	29657	N	N	N	1	CUSTOMER ISSUE	-
DMS_24675	29658	N	N	N	1	CUSTOMER ISSUE	-
DMS_24676	29659	N	N	N	1	CUSTOMER ISSUE	-
DMS_24677	29660	N	N	N	1	CUSTOMER ISSUE	-
DMS_24678	29661	N	N	Y	1	TX - REPLACE	2500
DMS_24679	29662	N	N	Y	1	TX - REPLACE	2500
DMS_24680	29663	N	N	Y	1	TX - REPLACE	2500
DMS_24681	29664	N	N	Y	1	TX - REPLACE	2500
DMS_24682	29665	N	N	Y	1	TX - REPLACE	2500
DMS_24683	29666	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24684	29667	N	N	N	1	CUSTOMER ISSUE	-
DMS_24685	29668	N	N	N	1	CUSTOMER ISSUE	-
DMS_24690	29669	N	N	N	1	CUSTOMER ISSUE	-
DMS_24691	29670	N	N	N	1	CUSTOMER ISSUE	-
DMS_24692	29671	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24693	29672	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24694	29673	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24697	29674	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24698	29675	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24700	29676	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_24714	29677	N	N	N	1	CUSTOMER ISSUE	-
DMS_24715	29678	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24716	29679	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_24719	29680	N	N	N	1	CUSTOMER ISSUE	-
DMS_24720	29681	N	N	N	1	CUSTOMER ISSUE	-
DMS_24721	29682	N	N	N	1	CUSTOMER ISSUE	-
DMS_24722	29683	N	N	N	1	CUSTOMER ISSUE	-
DMS_24723	29684	N	N	N	1	CUSTOMER ISSUE	-
DMS_24725	29685	N	N	N	1	CUSTOMER ISSUE	-
DMS_24726	29686	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24727	29687	N	N	N	1	CUSTOMER ISSUE	-
DMS_24728	29688	N	N	N	1	CUSTOMER ISSUE	-
DMS_24729	29689	N	N	N	1	CUSTOMER ISSUE	-
DMS_24730	29690	N	N	N	1	CUSTOMER ISSUE	-
DMS_24731	29691	N	N	N	1	CUSTOMER ISSUE	-
DMS_24732	29692	N	N	N	1	CUSTOMER ISSUE	-
DMS_24733	29693	N	N	N	1	CUSTOMER ISSUE	-
DMS_24734	29694	N	N	N	1	CUSTOMER ISSUE	-
DMS_24735	29695	N	N	N	1	CUSTOMER ISSUE	-
DMS_24736	29696	N	N	N	1	CUSTOMER ISSUE	-
DMS_24737	29697	N	N	N	1	CUSTOMER ISSUE	-
DMS_24738	29698	N	N	N	1	CUSTOMER ISSUE	-
DMS_24739	29699	N	N	N	1	CUSTOMER ISSUE	-
DMS_24740	29700	N	N	N	1	CUSTOMER ISSUE	-
DMS_24741	29701	N	N	N	1	CUSTOMER ISSUE	-
DMS_24743	29702	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_24744	29703	N	N	N	1	CUSTOMER ISSUE	-
DMS_24745	29704	N	N	N	1	CUSTOMER ISSUE	-
DMS_24746	29705	N	N	N	1	CUSTOMER ISSUE	-
DMS_24747	29706	N	N	N	1	CUSTOMER ISSUE	-
DMS_24748	29707	N	N	N	1	CUSTOMER ISSUE	-
DMS_24749	29708	N	N	N	1	CUSTOMER ISSUE	-
DMS_24750	29709	N	N	N	1	CUSTOMER ISSUE	-
DMS_24751	29710	N	N	N	1	CUSTOMER ISSUE	-
DMS_24752	29711	N	N	N	1	CUSTOMER ISSUE	-
DMS_24753	29712	N	N	N	1	CUSTOMER ISSUE	-
DMS_24754	29713	N	N	N	1	CUSTOMER ISSUE	-
DMS_24755	29714	N	N	N	1	CUSTOMER ISSUE	-
DMS_24756	29715	N	N	N	1	CUSTOMER ISSUE	-
DMS_24757	29716	N	N	N	1	CUSTOMER ISSUE	-
DMS_24758	29717	N	N	N	1	CUSTOMER ISSUE	-
DMS_24759	29718	N	N	N	1	CUSTOMER ISSUE	-
DMS_24760	29719	N	N	N	1	CUSTOMER ISSUE	-
DMS_24761	29720	N	N	N	1	CUSTOMER ISSUE	-
DMS_24762	29721	N	N	N	1	CUSTOMER ISSUE	-
DMS_24763	29722	N	N	N	1	CUSTOMER ISSUE	-
DMS_24764	29723	N	N	N	1	CUSTOMER ISSUE	-
DMS_24765	29724	N	N	N	1	CUSTOMER ISSUE	-
DMS_24766	29725	N	N	N	1	CUSTOMER ISSUE	-
DMS_24767	29726	N	N	N	1	CUSTOMER ISSUE	-
DMS_24768	29727	N	N	N	1	CUSTOMER ISSUE	-
DMS_24769	29728	N	N	N	1	CUSTOMER ISSUE	-
DMS_24770	29729	N	N	N	1	CUSTOMER ISSUE	-
DMS_24771	29730	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24772	29731	N	N	N	1	CUSTOMER ISSUE	-
DMS_24773	29732	N	N	N	1	CUSTOMER ISSUE	-
DMS_24774	29733	N	N	Y	1	DIST - CIRCUIT RETURN TO NORMAL CONFIG	472.5
DMS_24779	29734	N	N	N	1	CUSTOMER ISSUE	-
DMS_24780	29735	N	N	N	1	CUSTOMER ISSUE	-
DMS_24781	29736	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_24782	29737	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24783	29738	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24785	29739	N	N	N	1	CUSTOMER ISSUE	-
DMS_24786	29740	N	N	N	1	CUSTOMER ISSUE	-
DMS_24787	29741	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24788	29742	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24789	29743	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24790	29744	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24791	29745	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24792	29746	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24793	29747	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24794	29748	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24795	29749	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24796	29750	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24797	29751	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_24798	29752	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24799	29753	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24800	29754	N	N	N	1	CUSTOMER ISSUE	-
DMS_24801	29755	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24802	29756	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24803	29757	N	N	N	2	CUSTOMER ISSUE	-
DMS_24804	29758	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24805	29759	N	N	N	1	CUSTOMER ISSUE	-
DMS_24806	29760	N	N	N	1	CUSTOMER ISSUE	-
DMS_24807	29761	N	N	N	1	CUSTOMER ISSUE	-
DMS_24808	29762	N	N	N	1	CUSTOMER ISSUE	-
DMS_24809	29763	N	N	N	1	CUSTOMER ISSUE	-
DMS_24810	29764	N	N	N	1	CUSTOMER ISSUE	-
DMS_24811	29765	N	N	N	1	CUSTOMER ISSUE	-
DMS_24812	29766	N	N	N	1	CUSTOMER ISSUE	-
DMS_24813	29767	N	N	N	1	CUSTOMER ISSUE	-
DMS_24818	29768	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24819	29769	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24823	29770	N	N	N	1	CUSTOMER ISSUE	-
DMS_24824	29771	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24825	29772	N	N	N	1	CUSTOMER ISSUE	-
DMS_24826	29773	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24827	29774	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24828	29775	N	N	N	1	CUSTOMER ISSUE	-
DMS_24829	29776	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24830	29777	N	N	N	1	CUSTOMER ISSUE	-
DMS_24831	29778	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24832	29779	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24833	29780	N	N	N	1	CUSTOMER ISSUE	-
DMS_24834	29781	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24835	29782	N	N	N	1	CUSTOMER ISSUE	-
DMS_24836	29783	N	N	N	1	CUSTOMER ISSUE	-
DMS_24837	29784	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24838	29785	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24839	29786	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24840	29787	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24841	29788	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24842	29789	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24843	29790	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24844	29791	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24845	29792	N	N	N	1	CUSTOMER ISSUE	-
DMS_24846	29793	N	N	N	1	CUSTOMER ISSUE	-
DMS_24847	29794	N	N	N	1	CUSTOMER ISSUE	-
DMS_24848	29795	N	N	N	1	CUSTOMER ISSUE	-
DMS_24849	29796	N	N	N	1	CUSTOMER ISSUE	-
DMS_24850	29797	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24851	29798	N	N	N	1	CUSTOMER ISSUE	-
DMS_24852	29799	N	N	N	1	CUSTOMER ISSUE	-
DMS_24853	29800	N	N	N	1	CUSTOMER ISSUE	-
DMS_24854	29801	N	N	N	1	CUSTOMER ISSUE	-
DMS_24855	29802	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24856	29803	N	N	N	1	CUSTOMER ISSUE	-
DMS_24857	29804	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24858	29805	N	N	N	1	CUSTOMER ISSUE	-
DMS_24859	29806	N	N	N	1	CUSTOMER ISSUE	-
DMS_24860	29807	N	N	N	1	CUSTOMER ISSUE	-
DMS_24861	29808	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24862	29809	N	N	N	1	CUSTOMER ISSUE	-
DMS_24863	29810	N	N	N	1	CUSTOMER ISSUE	-
DMS_24864	29811	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24865	29812	N	N	N	1	CUSTOMER ISSUE	-
DMS_24866	29813	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24867	29814	N	N	N	1	CUSTOMER ISSUE	-
DMS_24868	29815	N	N	N	1	CUSTOMER ISSUE	-
DMS_24869	29816	N	N	N	1	CUSTOMER ISSUE	-

DMS_24870	29817	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24871	29818	N	N	N	1	CUSTOMER ISSUE	-
DMS_24872	29819	N	N	N	1	CUSTOMER ISSUE	-
DMS_24873	29820	N	N	N	1	CUSTOMER ISSUE	-
DMS_24874	29821	N	N	N	1	CUSTOMER ISSUE	-
DMS_24875	29822	N	N	N	1	CUSTOMER ISSUE	-
DMS_24876	29823	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24877	29824	N	N	N	1	CUSTOMER ISSUE	-
DMS_24878	29825	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24879	29826	N	N	N	1	CUSTOMER ISSUE	-
DMS_24880	29827	N	N	N	1	CUSTOMER ISSUE	-
DMS_24881	29828	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24882	29829	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24883	29830	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24884	29831	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24885	29832	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24886	29833	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24887	29834	N	N	N	1	CUSTOMER ISSUE	-
DMS_24888	29835	N	N	N	1	CUSTOMER ISSUE	-
DMS_24889	29836	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24890	29837	N	N	N	1	CUSTOMER ISSUE	-
DMS_24891	29838	N	N	N	1	CUSTOMER ISSUE	-
DMS_24893	29839	N	N	N	1	CUSTOMER ISSUE	-
DMS_24894	29840	N	N	N	1	CUSTOMER ISSUE	-
DMS_24895	29841	N	N	N	1	CUSTOMER ISSUE	-
DMS_24896	29842	N	N	N	1	CUSTOMER ISSUE	-
DMS_24897	29843	N	N	N	1	CUSTOMER ISSUE	-
DMS_24898	29844	N	N	N	1	CUSTOMER ISSUE	-
DMS_24899	29845	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24900	29846	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24901	29847	N	N	N	1	CUSTOMER ISSUE	-
DMS_24902	29848	N	N	N	1	CUSTOMER ISSUE	-
DMS_24903	29849	N	N	N	1	CUSTOMER ISSUE	-
DMS_24905	29850	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24906	29851	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24907	29852	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24908	29853	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24909	29854	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24910	29855	N	N	N	1	CUSTOMER ISSUE	-
DMS_24911	29856	N	N	N	1	CUSTOMER ISSUE	-
DMS_24912	29857	N	N	N	1	CUSTOMER ISSUE	-
DMS_24913	29858	N	N	N	1	CUSTOMER ISSUE	-
DMS_24914	29859	N	N	N	1	CUSTOMER ISSUE	-
DMS_24915	29860	N	N	N	1	CUSTOMER ISSUE	-
DMS_24916	29861	N	N	N	1	CUSTOMER ISSUE	-
DMS_24918	29862	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24919	29863	N	N	N	1	CUSTOMER ISSUE	-
DMS_24920	29864	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24921	29865	N	N	N	1	CUSTOMER ISSUE	-
DMS_24922	29866	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24923	29867	N	N	N	1	CUSTOMER ISSUE	-
DMS_24924	29868	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24925	29869	N	N	N	1	CUSTOMER ISSUE	-
DMS_24926	29870	N	N	N	1	CUSTOMER ISSUE	-
DMS_24927	29871	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24928	29872	N	N	N	1	CUSTOMER ISSUE	-
DMS_24929	29873	N	N	N	1	CUSTOMER ISSUE	-
DMS_24930	29874	N	N	N	1	CUSTOMER ISSUE	-
DMS_24932	29875	N	N	N	1	CUSTOMER ISSUE	-
DMS_24934	29876	N	N	N	1	CUSTOMER ISSUE	-
DMS_24935	29877	N	N	N	1	CUSTOMER ISSUE	-
DMS_24936	29878	N	N	N	1	CUSTOMER ISSUE	-
DMS_24937	29879	N	N	N	1	CUSTOMER ISSUE	-
DMS_24939	29880	N	N	N	1	CUSTOMER ISSUE	-
DMS_24945	29881	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24946	29882	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_24947	29883	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24949	29884	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24951	29885	N	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
DMS_24956	29886	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_24958	29887	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_24959	29888	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24963	29889	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24965	29890	N	N	N	1	CUSTOMER ISSUE	-
DMS_24966	29891	N	N	N	1	CUSTOMER ISSUE	-
DMS_24967	29892	N	N	N	1	CUSTOMER ISSUE	-
DMS_24968	29893	N	N	N	1	CUSTOMER ISSUE	-
DMS_24969	29894	N	N	N	1	CUSTOMER ISSUE	-
DMS_24970	29895	N	N	N	1	CUSTOMER ISSUE	-
DMS_24971	29896	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_24972	29897	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_24975	29898	N	N	N	1	CUSTOMER ISSUE	-
DMS_24976	29899	N	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
DMS_24977	29900	N	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
DMS_24978	29901	N	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
DMS_24979	29902	N	N	N	1	CUSTOMER ISSUE	-
DMS_24980	29903	N	N	N	1	CUSTOMER ISSUE	-
DMS_24981	29904	N	N	N	1	CUSTOMER ISSUE	-
DMS_24982	29905	N	N	N	1	CUSTOMER ISSUE	-
DMS_24983	29906	N	N	N	1	CUSTOMER ISSUE	-
DMS_24984	29907	N	N	N	1	CUSTOMER ISSUE	-
DMS_24985	29908	N	N	N	1	CUSTOMER ISSUE	-
DMS_24988	29909	N	N	N	1	CUSTOMER ISSUE	-
DMS_24989	29910	N	N	N	1	CUSTOMER ISSUE	-
DMS_24990	29911	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_24991	29912	N	N	N	1	CUSTOMER ISSUE	-
DMS_24992	29913	N	N	N	1	CUSTOMER ISSUE	-
DMS_24993	29914	N	N	N	1	CUSTOMER ISSUE	-
DMS_24994	29915	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24996	29916	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24997	29917	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_24999	29918	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25003	29919	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25004	29920	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25005	29921	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25006	29922	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_25007	29923	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25008	29924	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25009	29925	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25010	29926	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25011	29927	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25012	29928	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25013	29929	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25014	29930	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25015	29931	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25016	29932	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_25017	29933	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_25018	29934	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25019	29935	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25020	29936	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25021	29937	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25022	29938	N	N	Y	1	TX - REPLACE	2500
DMS_25024	29939	N	N	Y	1	TX - REPLACE	2500
DMS_25025	29940	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25027	29941	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25028	29942	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25029	29943	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25030	29944	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25033	29945	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25034	29946	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25035	29947	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25036	29948	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25038	29949	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25039	29950	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25040	29951	N	N	N	1	CUSTOMER ISSUE	-
DMS_25041	29952	N	N	N	1	CUSTOMER ISSUE	-
DMS_25042	29953	N	N	N	1	CUSTOMER ISSUE	-
DMS_25043	29954	N	N	N	1	CUSTOMER ISSUE	-
DMS_25044	29955	N	N	N	1	CUSTOMER ISSUE	-
DMS_25045	29956	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25046	29957	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25047	29958	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25048	29959	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25049	29960	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25052	29961	N	N	N	1	CUSTOMER ISSUE	-
DMS_25054	29962	N	N	Y	1	TX - REPLACE	2500
DMS_25055	29963	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25056	29964	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25058	29965	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25059	29966	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_25060	29967	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25061	29968	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25062	29969	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25063	29970	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25065	29971	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25067	29972	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25068	29973	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_25069	29974	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25070	29975	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25071	29976	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_25072	29977	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25074	29978	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25075	29979	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25076	29980	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25077	29981	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25078	29982	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25079	29983	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25080	29984	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25081	29985	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25082	29986	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25083	29987	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25084	29988	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25085	29989	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25086	29990	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25087	29991	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25088	29992	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25089	29993	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25090	29994	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25091	29995	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25092	29996	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25093	29997	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25094	29998	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25095	29999	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25096	30000	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25097	30001	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25098	30002	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25099	30003	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25100	30004	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25101	30005	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25102	30006	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25103	30007	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25104	30008	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25105	30009	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25106	30010	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25107	30011	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25108	30012	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25109	30013	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25110	30014	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25111	30015	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25112	30016	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25113	30017	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25114	30018	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25115	30019	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25116	30020	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25117	30021	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25118	30022	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25119	30023	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25120	30024	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25121	30025	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25122	30026	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25123	30027	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25124	30028	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25125	30029	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25126	30030	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25127	30031	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25128	30032	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25129	30033	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25130	30034	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25131	30035	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25132	30036	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25133	30037	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25134	30038	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25135	30039	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25136	30040	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25137	30041	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25138	30042	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25139	30043	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25140	30044	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25141	30045	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25142	30046	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25143	30047	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25144	30048	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25145	30049	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25146	30050	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25147	30051	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25148	30052	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25149	30053	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
DMS_25150	30054	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25151	30055	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25152	30056	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_25153	30057	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25154	30058	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25155	30059	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25156	30060	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25157	30061	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25158	30062	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25159	30063	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25160	30064	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25161	30065	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25162	30066	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25163	30067	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25164	30068	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25165	30069	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25166	30070	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25167	30071	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25168	30072	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25169	30073	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25170	30074	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25171	30075	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25172	30076	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25173	30077	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25174	30078	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25175	30079	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25176	30080	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25177	30081	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25178	30082	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25179	30083	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25180	30084	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25181	30085	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25182	30086	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25183	30087	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25184	30088	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25185	30089	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25186	30090	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25187	30091	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25188	30092	N	N	N	1	CUSTOMER ISSUE	-
DMS_25189	30093	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25190	30094	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25191	30095	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25192	30096	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25193	30097	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25194	30098	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25195	30099	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25196	30100	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25197	30101	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25198	30102	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25199	30103	N	N	N	1	CUSTOMER ISSUE	-
DMS_25200	30104	N	N	N	1	CUSTOMER ISSUE	-
DMS_25201	30105	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25202	30106	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25203	30107	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25204	30108	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_25205	30109	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25206	30110	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25207	30111	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25208	30112	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25209	30113	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25210	30114	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25211	30115	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25212	30116	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25213	30117	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25214	30118	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25215	30119	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25216	30120	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25217	30121	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25218	30122	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25219	30123	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25220	30124	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25221	30125	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25222	30126	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25223	30127	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25224	30128	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25225	30129	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25226	30130	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25227	30131	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_25228	30132	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25229	30133	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25230	30134	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25231	30135	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25232	30136	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_25233	30137	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25234	30138	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25235	30139	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_25236	30140	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25237	30141	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25238	30142	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25239	30143	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25240	30144	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25241	30145	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25242	30146	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25243	30147	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25244	30148	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25245	30149	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25246	30150	N	N	N	1	CUSTOMER ISSUE	-
DMS_25247	30151	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25248	30152	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25249	30153	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25250	30154	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25251	30155	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25252	30156	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25253	30157	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25254	30158	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25255	30159	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25256	30160	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25257	30161	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25258	30162	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25259	30163	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25260	30164	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25261	30165	N	N	Y	3	SEC/SVC - REPAIR	472.5
DMS_25262	30166	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25263	30167	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25264	30168	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25265	30169	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25266	30170	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25267	30171	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25268	30172	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25269	30173	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25270	30174	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25271	30175	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25272	30176	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25273	30177	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25274	30178	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25275	30179	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25276	30180	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25277	30181	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25278	30182	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25279	30183	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25280	30184	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25281	30185	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25282	30186	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25283	30187	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25284	30188	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25285	30189	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25286	30190	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25287	30191	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25288	30192	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25289	30193	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25290	30194	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25291	30195	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25292	30196	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25293	30197	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25294	30198	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25295	30199	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25296	30200	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25297	30201	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25298	30202	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25299	30203	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25300	30204	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25301	30205	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25302	30206	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25303	30207	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25304	30208	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25305	30209	N	N	N	1	CUSTOMER ISSUE	-
DMS_25319	30210	N	N	N	1	CUSTOMER ISSUE	-
DMS_25320	30211	N	N	N	1	CUSTOMER ISSUE	-
DMS_25321	30212	N	N	N	1	CUSTOMER ISSUE	-
DMS_25323	30213	N	N	N	1	CUSTOMER ISSUE	-
DMS_25326	30214	N	N	N	1	CUSTOMER ISSUE	-
DMS_25327	30215	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25328	30216	N	N	N	1	CUSTOMER ISSUE	-

DMS_25329	30217	N	N	N	1	CUSTOMER ISSUE	-
DMS_25330	30218	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25331	30219	N	N	N	1	CUSTOMER ISSUE	-
DMS_25332	30220	N	N	N	1	CUSTOMER ISSUE	-
DMS_25333	30221	N	N	N	1	CUSTOMER ISSUE	-
DMS_25334	30222	N	N	N	1	CUSTOMER ISSUE	-
DMS_25335	30223	N	N	N	1	CUSTOMER ISSUE	-
DMS_25336	30224	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25337	30225	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25339	30226	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25340	30227	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25341	30228	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25342	30229	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25345	30230	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25346	30231	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25347	30232	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25348	30233	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25349	30234	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25350	30235	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25351	30236	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25352	30237	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25353	30238	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25354	30239	N	N	Y	1	TX - REPLACE	2500
DMS_25355	30240	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25356	30241	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25358	30242	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25359	30243	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25360	30244	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25361	30245	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25362	30246	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25363	30247	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25364	30248	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25365	30249	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25366	30250	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25367	30251	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25368	30252	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25369	30253	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25370	30254	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25371	30255	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25372	30256	N	N	Y	1	TX - REPLACE	2500
DMS_25374	30257	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25375	30258	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25376	30259	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25377	30260	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25378	30261	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25379	30262	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25380	30263	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25381	30264	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25382	30265	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25383	30266	N	N	Y	1	TX - REPLACE	2500
DMS_25384	30267	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25385	30268	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25386	30269	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25387	30270	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25388	30271	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25389	30272	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25390	30273	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25391	30274	N	N	N	1	CUSTOMER ISSUE	-
DMS_25392	30275	N	N	N	1	CUSTOMER ISSUE	-
DMS_25393	30276	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25394	30277	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25395	30278	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25396	30279	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25397	30280	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25398	30281	N	N	N	1	CUSTOMER ISSUE	-
DMS_25399	30282	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25400	30283	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25401	30284	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25402	30285	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25403	30286	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25404	30287	N	N	Y	3	SEC/SVC - REPAIR	472.5
DMS_25405	30288	N	N	N	1	CUSTOMER ISSUE	-
DMS_25406	30289	N	N	N	1	CUSTOMER ISSUE	-
DMS_25407	30290	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25408	30291	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25409	30292	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25410	30293	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25411	30294	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25412	30295	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25413	30296	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_25414	30297	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25415	30298	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25416	30299	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25417	30300	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25418	30301	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25419	30302	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25420	30303	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25421	30304	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25422	30305	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25423	30306	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25424	30307	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25425	30308	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25426	30309	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25427	30310	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25428	30311	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25429	30312	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25430	30313	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25431	30314	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25432	30315	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25433	30316	N	N	N	1	CUSTOMER ISSUE	-
DMS_25434	30317	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25435	30318	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_25436	30319	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25437	30320	N	N	N	1	CUSTOMER ISSUE	-
DMS_25438	30321	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25439	30322	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25440	30323	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25441	30324	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25443	30325	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25444	30326	N	N	N	1	CUSTOMER ISSUE	-
DMS_25445	30327	N	N	N	1	CUSTOMER ISSUE	-
DMS_25446	30328	N	N	N	1	CUSTOMER ISSUE	-
DMS_25447	30329	N	N	N	1	CUSTOMER ISSUE	-
DMS_25448	30330	N	N	N	1	CUSTOMER ISSUE	-
DMS_25449	30331	N	N	N	1	CUSTOMER ISSUE	-
DMS_25450	30332	N	N	N	1	CUSTOMER ISSUE	-
DMS_25451	30333	N	N	N	1	CUSTOMER ISSUE	-
DMS_25452	30334	N	N	N	1	CUSTOMER ISSUE	-
DMS_25453	30335	N	N	N	1	CUSTOMER ISSUE	-
DMS_25454	30336	N	N	N	1	CUSTOMER ISSUE	-
DMS_25455	30337	N	N	N	1	CUSTOMER ISSUE	-
DMS_25456	30338	N	N	N	1	CUSTOMER ISSUE	-
DMS_25457	30339	N	N	N	1	CUSTOMER ISSUE	-
DMS_25458	30340	N	N	N	1	CUSTOMER ISSUE	-
DMS_25459	30341	N	N	N	1	CUSTOMER ISSUE	-
DMS_25460	30342	N	N	N	1	CUSTOMER ISSUE	-
DMS_25461	30343	N	N	N	1	CUSTOMER ISSUE	-
DMS_25462	30344	N	N	N	1	CUSTOMER ISSUE	-
DMS_25463	30345	N	N	N	1	CUSTOMER ISSUE	-
DMS_25464	30346	N	N	N	1	CUSTOMER ISSUE	-
DMS_25465	30347	N	N	N	1	CUSTOMER ISSUE	-
DMS_25466	30348	N	N	N	1	CUSTOMER ISSUE	-
DMS_25467	30349	N	N	N	1	CUSTOMER ISSUE	-
DMS_25468	30350	N	N	N	1	CUSTOMER ISSUE	-
DMS_25469	30351	N	N	N	1	CUSTOMER ISSUE	-
DMS_25470	30352	N	N	N	1	CUSTOMER ISSUE	-
DMS_25471	30353	N	N	N	1	CUSTOMER ISSUE	-
DMS_25472	30354	N	N	N	1	CUSTOMER ISSUE	-
DMS_25473	30355	N	N	N	1	CUSTOMER ISSUE	-
DMS_25474	30356	N	N	N	1	CUSTOMER ISSUE	-
DMS_25475	30357	N	N	N	1	CUSTOMER ISSUE	-
DMS_25476	30358	N	N	N	1	CUSTOMER ISSUE	-
DMS_25477	30359	N	N	N	1	CUSTOMER ISSUE	-
DMS_25478	30360	N	N	N	1	CUSTOMER ISSUE	-
DMS_25479	30361	N	N	N	1	CUSTOMER ISSUE	-
DMS_25480	30362	N	N	N	1	CUSTOMER ISSUE	-
DMS_25481	30363	N	N	N	1	CUSTOMER ISSUE	-
DMS_25482	30364	N	N	N	1	CUSTOMER ISSUE	-
DMS_25483	30365	N	N	N	1	CUSTOMER ISSUE	-
DMS_25484	30366	N	N	N	1	CUSTOMER ISSUE	-
DMS_25485	30367	N	N	N	1	CUSTOMER ISSUE	-
DMS_25486	30368	N	N	N	1	CUSTOMER ISSUE	-
DMS_25487	30369	N	N	N	1	CUSTOMER ISSUE	-
DMS_25488	30370	N	N	N	1	CUSTOMER ISSUE	-
DMS_25489	30371	N	N	N	1	CUSTOMER ISSUE	-
DMS_25490	30372	N	N	N	1	CUSTOMER ISSUE	-
DMS_25491	30373	N	N	N	1	CUSTOMER ISSUE	-
DMS_25492	30374	N	N	N	1	CUSTOMER ISSUE	-
DMS_25493	30375	N	N	N	1	CUSTOMER ISSUE	-
DMS_25494	30376	N	N	N	1	CUSTOMER ISSUE	-

DMS_25495	30377	N	N	N	1	CUSTOMER ISSUE	-
DMS_25496	30378	N	N	N	1	CUSTOMER ISSUE	-
DMS_25497	30379	N	N	N	1	CUSTOMER ISSUE	-
DMS_25498	30380	N	N	N	1	CUSTOMER ISSUE	-
DMS_25499	30381	N	N	N	1	CUSTOMER ISSUE	-
DMS_25500	30382	N	N	N	1	CUSTOMER ISSUE	-
DMS_25501	30383	N	N	N	1	CUSTOMER ISSUE	-
DMS_25502	30384	N	N	N	1	CUSTOMER ISSUE	-
DMS_25503	30385	N	N	N	1	CUSTOMER ISSUE	-
DMS_25504	30386	N	N	N	1	CUSTOMER ISSUE	-
DMS_25505	30387	N	N	N	1	CUSTOMER ISSUE	-
DMS_25506	30388	N	N	N	1	CUSTOMER ISSUE	-
DMS_25507	30389	N	N	N	1	CUSTOMER ISSUE	-
DMS_25508	30390	N	N	N	1	CUSTOMER ISSUE	-
DMS_25509	30391	N	N	N	1	CUSTOMER ISSUE	-
DMS_25510	30392	N	N	N	1	CUSTOMER ISSUE	-
DMS_25511	30393	N	N	N	1	CUSTOMER ISSUE	-
DMS_25512	30394	N	N	N	1	CUSTOMER ISSUE	-
DMS_25513	30395	N	N	N	1	CUSTOMER ISSUE	-
DMS_25514	30396	N	N	N	1	CUSTOMER ISSUE	-
DMS_25515	30397	N	N	N	1	CUSTOMER ISSUE	-
DMS_25516	30398	N	N	N	1	CUSTOMER ISSUE	-
DMS_25517	30399	N	N	N	1	CUSTOMER ISSUE	-
DMS_25518	30400	N	N	N	1	CUSTOMER ISSUE	-
DMS_25519	30401	N	N	N	1	CUSTOMER ISSUE	-
DMS_25520	30402	N	N	N	1	CUSTOMER ISSUE	-
DMS_25521	30403	N	N	N	1	CUSTOMER ISSUE	-
DMS_25522	30404	N	N	N	1	CUSTOMER ISSUE	-
DMS_25523	30405	N	N	N	1	CUSTOMER ISSUE	-
DMS_25524	30406	N	N	N	1	CUSTOMER ISSUE	-
DMS_25525	30407	N	N	N	1	CUSTOMER ISSUE	-
DMS_25526	30408	N	N	N	1	CUSTOMER ISSUE	-
DMS_25527	30409	N	N	N	1	CUSTOMER ISSUE	-
DMS_25528	30410	N	N	N	1	CUSTOMER ISSUE	-
DMS_25529	30411	N	N	N	1	CUSTOMER ISSUE	-
DMS_25530	30412	N	N	N	1	CUSTOMER ISSUE	-
DMS_25531	30413	N	N	N	1	CUSTOMER ISSUE	-
DMS_25532	30414	N	N	N	1	CUSTOMER ISSUE	-
DMS_25533	30415	N	N	N	1	CUSTOMER ISSUE	-
DMS_25534	30416	N	N	N	1	CUSTOMER ISSUE	-
DMS_25535	30417	N	N	N	1	CUSTOMER ISSUE	-
DMS_25536	30418	N	N	N	1	CUSTOMER ISSUE	-
DMS_25537	30419	N	N	N	1	CUSTOMER ISSUE	-
DMS_25538	30420	N	N	N	1	CUSTOMER ISSUE	-
DMS_25539	30421	N	N	N	1	CUSTOMER ISSUE	-
DMS_25540	30422	N	N	N	1	CUSTOMER ISSUE	-
DMS_25541	30423	N	N	N	1	CUSTOMER ISSUE	-
DMS_25542	30424	N	N	N	1	CUSTOMER ISSUE	-
DMS_25543	30425	N	N	N	1	CUSTOMER ISSUE	-
DMS_25544	30426	N	N	N	1	CUSTOMER ISSUE	-
DMS_25545	30427	N	N	N	1	CUSTOMER ISSUE	-
DMS_25546	30428	N	N	N	1	CUSTOMER ISSUE	-
DMS_25547	30429	N	N	N	1	CUSTOMER ISSUE	-
DMS_25548	30430	N	N	N	1	CUSTOMER ISSUE	-
DMS_25549	30431	N	N	N	1	CUSTOMER ISSUE	-
DMS_25550	30432	N	N	N	1	CUSTOMER ISSUE	-
DMS_25551	30433	N	N	N	1	CUSTOMER ISSUE	-
DMS_25552	30434	N	N	N	1	CUSTOMER ISSUE	-
DMS_25553	30435	N	N	N	1	CUSTOMER ISSUE	-
DMS_25554	30436	N	N	N	1	CUSTOMER ISSUE	-
DMS_25555	30437	N	N	N	1	CUSTOMER ISSUE	-
DMS_25556	30438	N	N	N	1	CUSTOMER ISSUE	-
DMS_25557	30439	N	N	N	1	CUSTOMER ISSUE	-
DMS_25558	30440	N	N	N	1	CUSTOMER ISSUE	-
DMS_25559	30441	N	N	N	1	CUSTOMER ISSUE	-
DMS_25560	30442	N	N	N	1	CUSTOMER ISSUE	-
DMS_25561	30443	N	N	N	1	CUSTOMER ISSUE	-
DMS_25562	30444	N	N	N	1	CUSTOMER ISSUE	-
DMS_25563	30445	N	N	N	1	CUSTOMER ISSUE	-
DMS_25564	30446	N	N	N	1	CUSTOMER ISSUE	-
DMS_25565	30447	N	N	N	1	CUSTOMER ISSUE	-
DMS_25566	30448	N	N	N	1	CUSTOMER ISSUE	-
DMS_25567	30449	N	N	N	1	CUSTOMER ISSUE	-
DMS_25568	30450	N	N	N	1	CUSTOMER ISSUE	-
DMS_25569	30451	N	N	N	1	CUSTOMER ISSUE	-
DMS_25570	30452	N	N	N	1	CUSTOMER ISSUE	-
DMS_25571	30453	N	N	N	1	CUSTOMER ISSUE	-
DMS_25572	30454	N	N	N	1	CUSTOMER ISSUE	-
DMS_25573	30455	N	N	N	1	CUSTOMER ISSUE	-
DMS_25574	30456	N	N	N	1	CUSTOMER ISSUE	-

DMS_25575	30457	N	N	N	1	CUSTOMER ISSUE	-
DMS_25576	30458	N	N	N	1	CUSTOMER ISSUE	-
DMS_25577	30459	N	N	N	1	CUSTOMER ISSUE	-
DMS_25578	30460	N	N	N	1	CUSTOMER ISSUE	-
DMS_25579	30461	N	N	N	1	CUSTOMER ISSUE	-
DMS_25580	30462	N	N	N	1	CUSTOMER ISSUE	-
DMS_25581	30463	N	N	N	1	CUSTOMER ISSUE	-
DMS_25582	30464	N	N	N	1	CUSTOMER ISSUE	-
DMS_25583	30465	N	N	N	1	CUSTOMER ISSUE	-
DMS_25584	30466	N	N	N	1	CUSTOMER ISSUE	-
DMS_25585	30467	N	N	N	1	CUSTOMER ISSUE	-
DMS_25586	30468	N	N	N	1	CUSTOMER ISSUE	-
DMS_25587	30469	N	N	N	1	CUSTOMER ISSUE	-
DMS_25588	30470	N	N	N	1	CUSTOMER ISSUE	-
DMS_25589	30471	N	N	N	1	CUSTOMER ISSUE	-
DMS_25590	30472	N	N	N	1	CUSTOMER ISSUE	-
DMS_25591	30473	N	N	N	1	CUSTOMER ISSUE	-
DMS_25592	30474	N	N	N	1	CUSTOMER ISSUE	-
DMS_25593	30475	N	N	N	1	CUSTOMER ISSUE	-
DMS_25594	30476	N	N	N	1	CUSTOMER ISSUE	-
DMS_25595	30477	N	N	N	1	CUSTOMER ISSUE	-
DMS_25596	30478	N	N	N	1	CUSTOMER ISSUE	-
DMS_25597	30479	N	N	N	1	CUSTOMER ISSUE	-
DMS_25598	30480	N	N	N	1	CUSTOMER ISSUE	-
DMS_25599	30481	N	N	N	1	CUSTOMER ISSUE	-
DMS_25600	30482	N	N	N	1	CUSTOMER ISSUE	-
DMS_25601	30483	N	N	N	1	CUSTOMER ISSUE	-
DMS_25602	30484	N	N	N	1	CUSTOMER ISSUE	-
DMS_25603	30485	N	N	N	1	CUSTOMER ISSUE	-
DMS_25604	30486	N	N	N	1	CUSTOMER ISSUE	-
DMS_25605	30487	N	N	N	1	CUSTOMER ISSUE	-
DMS_25606	30488	N	N	N	1	CUSTOMER ISSUE	-
DMS_25607	30489	N	N	N	1	CUSTOMER ISSUE	-
DMS_25608	30490	N	N	N	1	CUSTOMER ISSUE	-
DMS_25609	30491	N	N	N	1	CUSTOMER ISSUE	-
DMS_25610	30492	N	N	N	1	CUSTOMER ISSUE	-
DMS_25611	30493	N	N	N	1	CUSTOMER ISSUE	-
DMS_25612	30494	N	N	N	1	CUSTOMER ISSUE	-
DMS_25613	30495	N	N	N	1	CUSTOMER ISSUE	-
DMS_25614	30496	N	N	N	1	CUSTOMER ISSUE	-
DMS_25615	30497	N	N	N	1	CUSTOMER ISSUE	-
DMS_25616	30498	N	N	N	1	CUSTOMER ISSUE	-
DMS_25617	30499	N	N	N	1	CUSTOMER ISSUE	-
DMS_25618	30500	N	N	N	1	CUSTOMER ISSUE	-
DMS_25619	30501	N	N	N	1	CUSTOMER ISSUE	-
DMS_25620	30502	N	N	N	1	CUSTOMER ISSUE	-
DMS_25621	30503	N	N	N	1	CUSTOMER ISSUE	-
DMS_25622	30504	N	N	N	1	CUSTOMER ISSUE	-
DMS_25623	30505	N	N	N	1	CUSTOMER ISSUE	-
DMS_25624	30506	N	N	N	1	CUSTOMER ISSUE	-
DMS_25625	30507	N	N	N	1	CUSTOMER ISSUE	-
DMS_25626	30508	N	N	N	1	CUSTOMER ISSUE	-
DMS_25627	30509	N	N	N	1	CUSTOMER ISSUE	-
DMS_25628	30510	N	N	N	1	CUSTOMER ISSUE	-
DMS_25629	30511	N	N	N	1	CUSTOMER ISSUE	-
DMS_25630	30512	N	N	N	1	CUSTOMER ISSUE	-
DMS_25631	30513	N	N	N	1	CUSTOMER ISSUE	-
DMS_25632	30514	N	N	N	1	CUSTOMER ISSUE	-
DMS_25633	30515	N	N	N	1	CUSTOMER ISSUE	-
DMS_25634	30516	N	N	N	1	CUSTOMER ISSUE	-
DMS_25635	30517	N	N	N	1	CUSTOMER ISSUE	-
DMS_25636	30518	N	N	N	1	CUSTOMER ISSUE	-
DMS_25637	30519	N	N	N	1	CUSTOMER ISSUE	-
DMS_25638	30520	N	N	N	1	CUSTOMER ISSUE	-
DMS_25639	30521	N	N	N	1	CUSTOMER ISSUE	-
DMS_25640	30522	N	N	N	1	CUSTOMER ISSUE	-
DMS_25641	30523	N	N	N	1	CUSTOMER ISSUE	-
DMS_25642	30524	N	N	N	1	CUSTOMER ISSUE	-
DMS_25643	30525	N	N	N	1	CUSTOMER ISSUE	-
DMS_25644	30526	N	N	N	1	CUSTOMER ISSUE	-
DMS_25645	30527	N	N	N	1	CUSTOMER ISSUE	-
DMS_25646	30528	N	N	N	1	CUSTOMER ISSUE	-
DMS_25647	30529	N	N	N	1	CUSTOMER ISSUE	-
DMS_25648	30530	N	N	N	1	CUSTOMER ISSUE	-
DMS_25649	30531	N	N	N	1	CUSTOMER ISSUE	-
DMS_25650	30532	N	N	N	1	CUSTOMER ISSUE	-
DMS_25651	30533	N	N	N	1	CUSTOMER ISSUE	-
DMS_25652	30534	N	N	N	1	CUSTOMER ISSUE	-
DMS_25653	30535	N	N	N	1	CUSTOMER ISSUE	-
DMS_25654	30536	N	N	N	1	CUSTOMER ISSUE	-

DMS_25655	30537	N	N	N	1	CUSTOMER ISSUE	-
DMS_25656	30538	N	N	N	1	CUSTOMER ISSUE	-
DMS_25657	30539	N	N	N	1	CUSTOMER ISSUE	-
DMS_25658	30540	N	N	N	1	CUSTOMER ISSUE	-
DMS_25659	30541	N	N	N	1	CUSTOMER ISSUE	-
DMS_25660	30542	N	N	N	1	CUSTOMER ISSUE	-
DMS_25661	30543	N	N	N	1	CUSTOMER ISSUE	-
DMS_25662	30544	N	N	N	1	CUSTOMER ISSUE	-
DMS_25663	30545	N	N	N	1	CUSTOMER ISSUE	-
DMS_25664	30546	N	N	N	1	CUSTOMER ISSUE	-
DMS_25665	30547	N	N	N	1	CUSTOMER ISSUE	-
DMS_25666	30548	N	N	N	1	CUSTOMER ISSUE	-
DMS_25667	30549	N	N	N	1	CUSTOMER ISSUE	-
DMS_25668	30550	N	N	N	1	CUSTOMER ISSUE	-
DMS_25669	30551	N	N	N	1	CUSTOMER ISSUE	-
DMS_25670	30552	N	N	N	1	CUSTOMER ISSUE	-
DMS_25671	30553	N	N	N	1	CUSTOMER ISSUE	-
DMS_25672	30554	N	N	N	1	CUSTOMER ISSUE	-
DMS_25673	30555	N	N	N	1	CUSTOMER ISSUE	-
DMS_25674	30556	N	N	N	1	CUSTOMER ISSUE	-
DMS_25675	30557	N	N	N	1	CUSTOMER ISSUE	-
DMS_25676	30558	N	N	N	1	CUSTOMER ISSUE	-
DMS_25677	30559	N	N	N	1	CUSTOMER ISSUE	-
DMS_25678	30560	N	N	N	1	CUSTOMER ISSUE	-
DMS_25679	30561	N	N	N	1	CUSTOMER ISSUE	-
DMS_25680	30562	N	N	N	1	CUSTOMER ISSUE	-
DMS_25681	30563	N	N	N	1	CUSTOMER ISSUE	-
DMS_25682	30564	N	N	N	1	CUSTOMER ISSUE	-
DMS_25683	30565	N	N	N	1	CUSTOMER ISSUE	-
DMS_25684	30566	N	N	N	1	CUSTOMER ISSUE	-
DMS_25685	30567	N	N	N	1	CUSTOMER ISSUE	-
DMS_25686	30568	N	N	N	1	CUSTOMER ISSUE	-
DMS_25687	30569	N	N	N	1	CUSTOMER ISSUE	-
DMS_25688	30570	N	N	N	1	CUSTOMER ISSUE	-
DMS_25689	30571	N	N	N	1	CUSTOMER ISSUE	-
DMS_25690	30572	N	N	N	1	CUSTOMER ISSUE	-
DMS_25691	30573	N	N	N	1	CUSTOMER ISSUE	-
DMS_25692	30574	N	N	N	1	CUSTOMER ISSUE	-
DMS_25693	30575	N	N	N	1	CUSTOMER ISSUE	-
DMS_25694	30576	N	N	N	1	CUSTOMER ISSUE	-
DMS_25695	30577	N	N	N	1	CUSTOMER ISSUE	-
DMS_25696	30578	N	N	N	1	CUSTOMER ISSUE	-
DMS_25697	30579	N	N	N	1	CUSTOMER ISSUE	-
DMS_25698	30580	N	N	N	1	CUSTOMER ISSUE	-
DMS_25699	30581	N	N	N	1	CUSTOMER ISSUE	-
DMS_25700	30582	N	N	N	1	CUSTOMER ISSUE	-
DMS_25701	30583	N	N	N	1	CUSTOMER ISSUE	-
DMS_25702	30584	N	N	N	1	CUSTOMER ISSUE	-
DMS_25703	30585	N	N	N	1	CUSTOMER ISSUE	-
DMS_25704	30586	N	N	N	1	CUSTOMER ISSUE	-
DMS_25705	30587	N	N	N	1	CUSTOMER ISSUE	-
DMS_25706	30588	N	N	N	1	CUSTOMER ISSUE	-
DMS_25707	30589	N	N	N	1	CUSTOMER ISSUE	-
DMS_25708	30590	N	N	N	1	CUSTOMER ISSUE	-
DMS_25709	30591	N	N	N	1	CUSTOMER ISSUE	-
DMS_25710	30592	N	N	N	1	CUSTOMER ISSUE	-
DMS_25711	30593	N	N	N	1	CUSTOMER ISSUE	-
DMS_25712	30594	N	N	N	1	CUSTOMER ISSUE	-
DMS_25713	30595	N	N	N	1	CUSTOMER ISSUE	-
DMS_25714	30596	N	N	N	1	CUSTOMER ISSUE	-
DMS_25715	30597	N	N	N	1	CUSTOMER ISSUE	-
DMS_25716	30598	N	N	N	1	CUSTOMER ISSUE	-
DMS_25717	30599	N	N	N	1	CUSTOMER ISSUE	-
DMS_25718	30600	N	N	N	1	CUSTOMER ISSUE	-
DMS_25719	30601	N	N	N	1	CUSTOMER ISSUE	-
DMS_25720	30602	N	N	N	1	CUSTOMER ISSUE	-
DMS_25721	30603	N	N	N	1	CUSTOMER ISSUE	-
DMS_25722	30604	N	N	N	1	CUSTOMER ISSUE	-
DMS_25723	30605	N	N	N	1	CUSTOMER ISSUE	-
DMS_25724	30606	N	N	N	1	CUSTOMER ISSUE	-
DMS_25725	30607	N	N	N	1	CUSTOMER ISSUE	-
DMS_25726	30608	N	N	N	1	CUSTOMER ISSUE	-
DMS_25727	30609	N	N	N	1	CUSTOMER ISSUE	-
DMS_25728	30610	N	N	N	1	CUSTOMER ISSUE	-
DMS_25729	30611	N	N	N	1	CUSTOMER ISSUE	-
DMS_25730	30612	N	N	N	1	CUSTOMER ISSUE	-
DMS_25731	30613	N	N	N	1	CUSTOMER ISSUE	-
DMS_25732	30614	N	N	N	1	CUSTOMER ISSUE	-
DMS_25733	30615	N	N	N	1	CUSTOMER ISSUE	-
DMS_25734	30616	N	N	N	1	CUSTOMER ISSUE	-

DMS_25735	30617	N	N	N	1	CUSTOMER ISSUE	-
DMS_25736	30618	N	N	N	1	CUSTOMER ISSUE	-
DMS_25737	30619	N	N	N	1	CUSTOMER ISSUE	-
DMS_25738	30620	N	N	N	1	CUSTOMER ISSUE	-
DMS_25739	30621	N	N	N	1	CUSTOMER ISSUE	-
DMS_25740	30622	N	N	N	1	CUSTOMER ISSUE	-
DMS_25741	30623	N	N	N	1	CUSTOMER ISSUE	-
DMS_25742	30624	N	N	N	1	CUSTOMER ISSUE	-
DMS_25743	30625	N	N	N	1	CUSTOMER ISSUE	-
DMS_25744	30626	N	N	N	1	CUSTOMER ISSUE	-
DMS_25745	30627	N	N	N	1	CUSTOMER ISSUE	-
DMS_25746	30628	N	N	N	1	CUSTOMER ISSUE	-
DMS_25747	30629	N	N	N	1	CUSTOMER ISSUE	-
DMS_25748	30630	N	N	N	1	CUSTOMER ISSUE	-
DMS_25749	30631	N	N	N	1	CUSTOMER ISSUE	-
DMS_25750	30632	N	N	N	1	CUSTOMER ISSUE	-
DMS_25751	30633	N	N	N	1	CUSTOMER ISSUE	-
DMS_25752	30634	N	N	N	1	CUSTOMER ISSUE	-
DMS_25753	30635	N	N	N	1	CUSTOMER ISSUE	-
DMS_25754	30636	N	N	N	1	CUSTOMER ISSUE	-
DMS_25755	30637	N	N	N	1	CUSTOMER ISSUE	-
DMS_25756	30638	N	N	N	1	CUSTOMER ISSUE	-
DMS_25757	30639	N	N	N	1	CUSTOMER ISSUE	-
DMS_25758	30640	N	N	N	1	CUSTOMER ISSUE	-
DMS_25759	30641	N	N	N	1	CUSTOMER ISSUE	-
DMS_25760	30642	N	N	N	1	CUSTOMER ISSUE	-
DMS_25761	30643	N	N	N	1	CUSTOMER ISSUE	-
DMS_25762	30644	N	N	N	1	CUSTOMER ISSUE	-
DMS_25763	30645	N	N	N	1	CUSTOMER ISSUE	-
DMS_25764	30646	N	N	N	1	CUSTOMER ISSUE	-
DMS_25765	30647	N	N	N	1	CUSTOMER ISSUE	-
DMS_25766	30648	N	N	N	1	CUSTOMER ISSUE	-
DMS_25767	30649	N	N	N	1	CUSTOMER ISSUE	-
DMS_25768	30650	N	N	N	1	CUSTOMER ISSUE	-
DMS_25769	30651	N	N	N	1	CUSTOMER ISSUE	-
DMS_25770	30652	N	N	N	1	CUSTOMER ISSUE	-
DMS_25771	30653	N	N	N	1	CUSTOMER ISSUE	-
DMS_25772	30654	N	N	N	1	CUSTOMER ISSUE	-
DMS_25773	30655	N	N	N	1	CUSTOMER ISSUE	-
DMS_25774	30656	N	N	N	1	CUSTOMER ISSUE	-
DMS_25775	30657	N	N	N	1	CUSTOMER ISSUE	-
DMS_25776	30658	N	N	N	1	CUSTOMER ISSUE	-
DMS_25777	30659	N	N	N	1	CUSTOMER ISSUE	-
DMS_25778	30660	N	N	N	1	CUSTOMER ISSUE	-
DMS_25779	30661	N	N	N	1	CUSTOMER ISSUE	-
DMS_25780	30662	N	N	N	1	CUSTOMER ISSUE	-
DMS_25781	30663	N	N	N	1	CUSTOMER ISSUE	-
DMS_25782	30664	N	N	N	1	CUSTOMER ISSUE	-
DMS_25783	30665	N	N	N	1	CUSTOMER ISSUE	-
DMS_25784	30666	N	N	N	1	CUSTOMER ISSUE	-
DMS_25785	30667	N	N	N	1	CUSTOMER ISSUE	-
DMS_25786	30668	N	N	N	1	CUSTOMER ISSUE	-
DMS_25787	30669	N	N	N	1	CUSTOMER ISSUE	-
DMS_25788	30670	N	N	N	1	CUSTOMER ISSUE	-
DMS_25789	30671	N	N	N	1	CUSTOMER ISSUE	-
DMS_25790	30672	N	N	N	1	CUSTOMER ISSUE	-
DMS_25791	30673	N	N	N	1	CUSTOMER ISSUE	-
DMS_25792	30674	N	N	N	1	CUSTOMER ISSUE	-
DMS_25793	30675	N	N	N	1	CUSTOMER ISSUE	-
DMS_25794	30676	N	N	N	1	CUSTOMER ISSUE	-
DMS_25795	30677	N	N	N	1	CUSTOMER ISSUE	-
DMS_25796	30678	N	N	N	1	CUSTOMER ISSUE	-
DMS_25797	30679	N	N	N	1	CUSTOMER ISSUE	-
DMS_25798	30680	N	N	N	1	CUSTOMER ISSUE	-
DMS_25799	30681	N	N	N	1	CUSTOMER ISSUE	-
DMS_25800	30682	N	N	N	1	CUSTOMER ISSUE	-
DMS_25801	30683	N	N	N	1	CUSTOMER ISSUE	-
DMS_25802	30684	N	N	N	1	CUSTOMER ISSUE	-
DMS_25803	30685	N	N	N	1	CUSTOMER ISSUE	-
DMS_25804	30686	N	N	N	1	CUSTOMER ISSUE	-
DMS_25805	30687	N	N	N	1	CUSTOMER ISSUE	-
DMS_25806	30688	N	N	N	1	CUSTOMER ISSUE	-
DMS_25807	30689	N	N	N	1	CUSTOMER ISSUE	-
DMS_25808	30690	N	N	N	1	CUSTOMER ISSUE	-
DMS_25809	30691	N	N	N	1	CUSTOMER ISSUE	-
DMS_25810	30692	N	N	N	1	CUSTOMER ISSUE	-
DMS_25811	30693	N	N	N	1	CUSTOMER ISSUE	-
DMS_25812	30694	N	N	N	1	CUSTOMER ISSUE	-
DMS_25813	30695	N	N	N	1	CUSTOMER ISSUE	-
DMS_25814	30696	N	N	N	1	CUSTOMER ISSUE	-

DMS_25815	30697	N	N	N	1	CUSTOMER ISSUE	-
DMS_25816	30698	N	N	N	1	CUSTOMER ISSUE	-
DMS_25817	30699	N	N	N	1	CUSTOMER ISSUE	-
DMS_25818	30700	N	N	N	1	CUSTOMER ISSUE	-
DMS_25819	30701	N	N	N	1	CUSTOMER ISSUE	-
DMS_25820	30702	N	N	N	1	CUSTOMER ISSUE	-
DMS_25821	30703	N	N	N	1	CUSTOMER ISSUE	-
DMS_25822	30704	N	N	N	1	CUSTOMER ISSUE	-
DMS_25823	30705	N	N	N	1	CUSTOMER ISSUE	-
DMS_25824	30706	N	N	N	1	CUSTOMER ISSUE	-
DMS_25825	30707	N	N	N	1	CUSTOMER ISSUE	-
DMS_25826	30708	N	N	N	1	CUSTOMER ISSUE	-
DMS_25827	30709	N	N	N	1	CUSTOMER ISSUE	-
DMS_25828	30710	N	N	N	1	CUSTOMER ISSUE	-
DMS_25829	30711	N	N	N	1	CUSTOMER ISSUE	-
DMS_25830	30712	N	N	N	1	CUSTOMER ISSUE	-
DMS_25831	30713	N	N	N	1	CUSTOMER ISSUE	-
DMS_25832	30714	N	N	N	1	CUSTOMER ISSUE	-
DMS_25833	30715	N	N	N	1	CUSTOMER ISSUE	-
DMS_25834	30716	N	N	N	1	CUSTOMER ISSUE	-
DMS_25835	30717	N	N	N	1	CUSTOMER ISSUE	-
DMS_25836	30718	N	N	N	1	CUSTOMER ISSUE	-
DMS_25837	30719	N	N	N	1	CUSTOMER ISSUE	-
DMS_25838	30720	N	N	N	1	CUSTOMER ISSUE	-
DMS_25839	30721	N	N	N	1	CUSTOMER ISSUE	-
DMS_25840	30722	N	N	N	1	CUSTOMER ISSUE	-
DMS_25841	30723	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_25843	30724	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25844	30725	N	N	N	1	CUSTOMER ISSUE	-
DMS_25845	30726	N	N	N	1	CUSTOMER ISSUE	-
DMS_25846	30727	N	N	N	1	CUSTOMER ISSUE	-
DMS_25847	30728	N	N	N	1	CUSTOMER ISSUE	-
DMS_25848	30729	N	N	N	1	CUSTOMER ISSUE	-
DMS_25849	30730	N	N	N	1	CUSTOMER ISSUE	-
DMS_25850	30731	N	N	N	1	CUSTOMER ISSUE	-
DMS_25851	30732	N	N	N	1	CUSTOMER ISSUE	-
DMS_25852	30733	N	N	N	1	CUSTOMER ISSUE	-
DMS_25853	30734	N	N	N	1	CUSTOMER ISSUE	-
DMS_25854	30735	N	N	N	1	CUSTOMER ISSUE	-
DMS_25855	30736	N	N	N	1	CUSTOMER ISSUE	-
DMS_25856	30737	N	N	N	1	CUSTOMER ISSUE	-
DMS_25857	30738	N	N	N	1	CUSTOMER ISSUE	-
DMS_25858	30739	N	N	N	1	CUSTOMER ISSUE	-
DMS_25859	30740	N	N	N	1	CUSTOMER ISSUE	-
DMS_25860	30741	N	N	N	1	CUSTOMER ISSUE	-
DMS_25861	30742	N	N	N	1	CUSTOMER ISSUE	-
DMS_25862	30743	N	N	N	1	CUSTOMER ISSUE	-
DMS_25863	30744	N	N	N	1	CUSTOMER ISSUE	-
DMS_25864	30745	N	N	N	1	CUSTOMER ISSUE	-
DMS_25865	30746	N	N	N	1	CUSTOMER ISSUE	-
DMS_25866	30747	N	N	N	1	CUSTOMER ISSUE	-
DMS_25867	30748	N	N	N	1	CUSTOMER ISSUE	-
DMS_25868	30749	N	N	N	1	CUSTOMER ISSUE	-
DMS_25869	30750	N	N	N	1	CUSTOMER ISSUE	-
DMS_25870	30751	N	N	N	1	CUSTOMER ISSUE	-
DMS_25871	30752	N	N	N	1	CUSTOMER ISSUE	-
DMS_25872	30753	N	N	N	1	CUSTOMER ISSUE	-
DMS_25873	30754	N	N	N	1	CUSTOMER ISSUE	-
DMS_25874	30755	N	N	N	1	CUSTOMER ISSUE	-
DMS_25875	30756	N	N	N	1	CUSTOMER ISSUE	-
DMS_25876	30757	N	N	N	1	CUSTOMER ISSUE	-
DMS_25877	30758	N	N	N	1	CUSTOMER ISSUE	-
DMS_25878	30759	N	N	N	1	CUSTOMER ISSUE	-
DMS_25879	30760	N	N	N	1	CUSTOMER ISSUE	-
DMS_25880	30761	N	N	N	1	CUSTOMER ISSUE	-
DMS_25881	30762	N	N	N	1	CUSTOMER ISSUE	-
DMS_25882	30763	N	N	N	1	CUSTOMER ISSUE	-
DMS_25883	30764	N	N	N	1	CUSTOMER ISSUE	-
DMS_25884	30765	N	N	N	1	CUSTOMER ISSUE	-
DMS_25885	30766	N	N	N	1	CUSTOMER ISSUE	-
DMS_25886	30767	N	N	N	1	CUSTOMER ISSUE	-
DMS_25887	30768	N	N	N	1	CUSTOMER ISSUE	-
DMS_25888	30769	N	N	N	1	CUSTOMER ISSUE	-
DMS_25890	30770	N	N	N	1	CUSTOMER ISSUE	-
DMS_25891	30771	N	N	N	1	CUSTOMER ISSUE	-
DMS_25892	30772	N	N	N	1	CUSTOMER ISSUE	-
DMS_25893	30773	N	N	N	1	CUSTOMER ISSUE	-
DMS_25894	30774	N	N	N	1	CUSTOMER ISSUE	-
DMS_25895	30775	N	N	N	1	CUSTOMER ISSUE	-
DMS_25896	30776	N	N	N	1	CUSTOMER ISSUE	-

DMS_25897	30777	N	N	N	1	CUSTOMER ISSUE	-
DMS_25898	30778	N	N	N	1	CUSTOMER ISSUE	-
DMS_25899	30779	N	N	N	1	CUSTOMER ISSUE	-
DMS_25900	30780	N	N	N	1	CUSTOMER ISSUE	-
DMS_25901	30781	N	N	N	1	CUSTOMER ISSUE	-
DMS_25902	30782	N	N	N	1	CUSTOMER ISSUE	-
DMS_25903	30783	N	N	N	1	CUSTOMER ISSUE	-
DMS_25904	30784	N	N	N	1	CUSTOMER ISSUE	-
DMS_25905	30785	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25906	30786	N	N	N	1	CUSTOMER ISSUE	-
DMS_25907	30787	N	N	N	1	CUSTOMER ISSUE	-
DMS_25908	30788	N	N	N	1	CUSTOMER ISSUE	-
DMS_25909	30789	N	N	N	1	CUSTOMER ISSUE	-
DMS_25910	30790	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25911	30791	N	N	N	1	CUSTOMER ISSUE	-
DMS_25912	30792	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25913	30793	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25914	30794	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25915	30795	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25916	30796	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25917	30797	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25918	30798	N	N	N	1	CUSTOMER ISSUE	-
DMS_25919	30799	N	N	N	1	CUSTOMER ISSUE	-
DMS_25920	30800	N	N	N	1	CUSTOMER ISSUE	-
DMS_25921	30801	N	N	N	1	CUSTOMER ISSUE	-
DMS_25922	30802	N	N	N	1	CUSTOMER ISSUE	-
DMS_25923	30803	N	N	N	1	CUSTOMER ISSUE	-
DMS_25924	30804	N	N	N	1	CUSTOMER ISSUE	-
DMS_25926	30805	N	N	N	1	CUSTOMER ISSUE	-
DMS_25927	30806	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25929	30807	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25930	30808	N	N	N	1	CUSTOMER ISSUE	-
DMS_25931	30809	N	N	N	1	CUSTOMER ISSUE	-
DMS_25932	30810	N	N	N	1	CUSTOMER ISSUE	-
DMS_25933	30811	N	N	N	1	CUSTOMER ISSUE	-
DMS_25934	30812	N	N	N	1	CUSTOMER ISSUE	-
DMS_25935	30813	N	N	N	1	CUSTOMER ISSUE	-
DMS_25936	30814	N	N	N	1	CUSTOMER ISSUE	-
DMS_25937	30815	N	N	N	1	CUSTOMER ISSUE	-
DMS_25938	30816	N	N	N	1	CUSTOMER ISSUE	-
DMS_25939	30817	N	N	N	1	CUSTOMER ISSUE	-
DMS_25940	30818	N	N	N	1	CUSTOMER ISSUE	-
DMS_25941	30819	N	N	N	1	CUSTOMER ISSUE	-
DMS_25942	30820	N	N	N	1	CUSTOMER ISSUE	-
DMS_25943	30821	N	N	N	1	CUSTOMER ISSUE	-
DMS_25944	30822	N	N	N	1	CUSTOMER ISSUE	-
DMS_25945	30823	N	N	N	1	CUSTOMER ISSUE	-
DMS_25946	30824	N	N	N	1	CUSTOMER ISSUE	-
DMS_25947	30825	N	N	N	1	CUSTOMER ISSUE	-
DMS_25948	30826	N	N	N	1	CUSTOMER ISSUE	-
DMS_25949	30827	N	N	N	1	CUSTOMER ISSUE	-
DMS_25950	30828	N	N	N	1	CUSTOMER ISSUE	-
DMS_25951	30829	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25952	30830	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25953	30831	N	N	N	1	CUSTOMER ISSUE	-
DMS_25954	30832	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25955	30833	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25956	30834	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25957	30835	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25958	30836	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25959	30837	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25960	30838	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25961	30839	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25962	30840	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25963	30841	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25964	30842	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25965	30843	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25966	30844	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_25967	30845	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25968	30846	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25969	30847	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25970	30848	N	N	N	1	CUSTOMER ISSUE	-
DMS_25971	30849	N	N	N	1	CUSTOMER ISSUE	-
DMS_25972	30850	N	N	N	1	CUSTOMER ISSUE	-
DMS_25974	30851	N	N	N	1	CUSTOMER ISSUE	-
DMS_25975	30852	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25976	30853	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25977	30854	N	N	N	1	CUSTOMER ISSUE	-
DMS_25978	30855	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25979	30856	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_25980	30857	N	N	N	1	CUSTOMER ISSUE	-
DMS_25981	30858	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_25982	30859	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_25983	30860	N	N	N	1	CUSTOMER ISSUE	-
DMS_25984	30861	N	N	N	1	CUSTOMER ISSUE	-
DMS_25986	30862	N	N	N	1	CUSTOMER ISSUE	-
DMS_25987	30863	N	N	N	1	CUSTOMER ISSUE	-
DMS_25988	30864	N	N	N	1	CUSTOMER ISSUE	-
DMS_25989	30865	N	N	N	1	CUSTOMER ISSUE	-
DMS_25990	30866	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_25998	30867	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_26000	30868	N	N	N	1	CUSTOMER ISSUE	-
DMS_26001	30869	N	N	N	1	CUSTOMER ISSUE	-
DMS_26002	30870	N	N	N	1	CUSTOMER ISSUE	-
DMS_26003	30871	N	N	N	1	CUSTOMER ISSUE	-
DMS_26004	30872	N	N	N	1	CUSTOMER ISSUE	-
DMS_26007	30873	N	N	N	1	CUSTOMER ISSUE	-
DMS_26008	30874	N	N	N	1	CUSTOMER ISSUE	-
DMS_26009	30875	N	N	N	1	CUSTOMER ISSUE	-
DMS_26010	30876	N	N	N	1	CUSTOMER ISSUE	-
DMS_26013	30877	N	N	N	1	CUSTOMER ISSUE	-
DMS_26015	30878	N	N	N	1	CUSTOMER ISSUE	-
DMS_26017	30879	N	N	N	1	CUSTOMER ISSUE	-
DMS_26018	30880	N	N	N	1	CUSTOMER ISSUE	-
DMS_26021	30881	N	N	N	1	CUSTOMER ISSUE	-
DMS_26022	30882	N	N	N	1	CUSTOMER ISSUE	-
DMS_26025	30883	N	N	N	1	CUSTOMER ISSUE	-
DMS_26026	30884	N	N	N	1	CUSTOMER ISSUE	-
DMS_26032	30885	N	N	N	1	CUSTOMER ISSUE	-
DMS_26033	30886	N	N	N	1	CUSTOMER ISSUE	-
DMS_26034	30887	N	N	N	1	CUSTOMER ISSUE	-
DMS_26036	30888	N	N	N	1	CUSTOMER ISSUE	-
DMS_26039	30889	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26040	30890	N	N	N	1	CUSTOMER ISSUE	-
DMS_26041	30891	N	N	N	1	CUSTOMER ISSUE	-
DMS_26042	30892	N	N	N	1	CUSTOMER ISSUE	-
DMS_26043	30893	N	N	N	1	CUSTOMER ISSUE	-
DMS_26044	30894	N	N	N	1	CUSTOMER ISSUE	-
DMS_26045	30895	N	N	N	1	CUSTOMER ISSUE	-
DMS_26046	30896	N	N	N	1	CUSTOMER ISSUE	-
DMS_26047	30897	N	N	N	1	CUSTOMER ISSUE	-
DMS_26048	30898	N	N	N	1	CUSTOMER ISSUE	-
DMS_26052	30899	N	N	N	1	CUSTOMER ISSUE	-
DMS_26053	30900	N	N	N	1	CUSTOMER ISSUE	-
DMS_26054	30901	N	N	N	1	CUSTOMER ISSUE	-
DMS_26055	30902	N	N	N	1	CUSTOMER ISSUE	-
DMS_26056	30903	N	N	N	1	CUSTOMER ISSUE	-
DMS_26057	30904	N	N	N	1	CUSTOMER ISSUE	-
DMS_26059	30905	N	N	N	1	CUSTOMER ISSUE	-
DMS_26060	30906	N	N	N	1	CUSTOMER ISSUE	-
DMS_26061	30907	N	N	N	1	CUSTOMER ISSUE	-
DMS_26062	30908	N	N	N	1	CUSTOMER ISSUE	-
DMS_26063	30909	N	N	N	1	CUSTOMER ISSUE	-
DMS_26064	30910	N	N	N	1	CUSTOMER ISSUE	-
DMS_26065	30911	N	N	N	1	CUSTOMER ISSUE	-
DMS_26066	30912	N	N	N	1	CUSTOMER ISSUE	-
DMS_26067	30913	N	N	N	1	CUSTOMER ISSUE	-
DMS_26068	30914	N	N	N	1	CUSTOMER ISSUE	-
DMS_26069	30915	N	N	N	1	CUSTOMER ISSUE	-
DMS_26071	30916	N	N	N	1	CUSTOMER ISSUE	-
DMS_26075	30917	N	N	N	1	CUSTOMER ISSUE	-
DMS_26078	30918	N	N	N	1	CUSTOMER ISSUE	-
DMS_26081	30919	N	N	N	1	CUSTOMER ISSUE	-
DMS_26082	30920	N	N	N	1	CUSTOMER ISSUE	-
DMS_26083	30921	N	N	N	1	CUSTOMER ISSUE	-
DMS_26084	30922	N	N	N	1	CUSTOMER ISSUE	-
DMS_26085	30923	N	N	N	1	CUSTOMER ISSUE	-
DMS_26086	30924	N	N	N	1	CUSTOMER ISSUE	-
DMS_26087	30925	N	N	N	1	CUSTOMER ISSUE	-
DMS_26088	30926	N	N	N	1	CUSTOMER ISSUE	-
DMS_26089	30927	N	N	N	1	CUSTOMER ISSUE	-
DMS_26090	30928	N	N	N	1	CUSTOMER ISSUE	-
DMS_26091	30929	N	N	N	1	CUSTOMER ISSUE	-
DMS_26092	30930	N	N	N	1	CUSTOMER ISSUE	-
DMS_26093	30931	N	N	N	1	CUSTOMER ISSUE	-
DMS_26094	30932	N	N	N	1	CUSTOMER ISSUE	-
DMS_26095	30933	N	N	N	1	CUSTOMER ISSUE	-
DMS_26096	30934	N	N	N	1	CUSTOMER ISSUE	-
DMS_26097	30935	N	N	N	1	CUSTOMER ISSUE	-
DMS_26098	30936	N	N	N	1	CUSTOMER ISSUE	-

DMS_26099	30937	N	N	N	1	CUSTOMER ISSUE	-
DMS_26101	30938	N	N	N	1	CUSTOMER ISSUE	-
DMS_26102	30939	N	N	N	1	CUSTOMER ISSUE	-
DMS_26104	30940	N	N	N	1	CUSTOMER ISSUE	-
DMS_26105	30941	N	N	N	1	CUSTOMER ISSUE	-
DMS_26106	30942	N	N	N	1	CUSTOMER ISSUE	-
DMS_26107	30943	N	N	N	1	CUSTOMER ISSUE	-
DMS_26108	30944	N	N	N	1	CUSTOMER ISSUE	-
DMS_26109	30945	N	N	N	1	CUSTOMER ISSUE	-
DMS_26110	30946	N	N	N	1	CUSTOMER ISSUE	-
DMS_26111	30947	N	N	N	1	CUSTOMER ISSUE	-
DMS_26112	30948	N	N	N	1	CUSTOMER ISSUE	-
DMS_26113	30949	N	N	N	1	CUSTOMER ISSUE	-
DMS_26115	30950	N	N	N	1	CUSTOMER ISSUE	-
DMS_26116	30951	N	N	N	1	CUSTOMER ISSUE	-
DMS_26117	30952	N	N	N	1	CUSTOMER ISSUE	-
DMS_26118	30953	N	N	N	1	CUSTOMER ISSUE	-
DMS_26119	30954	N	N	N	1	CUSTOMER ISSUE	-
DMS_26120	30955	N	N	N	1	CUSTOMER ISSUE	-
DMS_26121	30956	N	N	N	1	CUSTOMER ISSUE	-
DMS_26123	30957	N	N	N	1	CUSTOMER ISSUE	-
DMS_26124	30958	N	N	N	1	CUSTOMER ISSUE	-
DMS_26125	30959	N	N	N	1	CUSTOMER ISSUE	-
DMS_26126	30960	N	N	N	1	CUSTOMER ISSUE	-
DMS_26127	30961	N	N	N	1	CUSTOMER ISSUE	-
DMS_26128	30962	N	N	N	1	CUSTOMER ISSUE	-
DMS_26129	30963	N	N	N	1	CUSTOMER ISSUE	-
DMS_26130	30964	N	N	N	1	CUSTOMER ISSUE	-
DMS_26132	30965	N	N	N	1	CUSTOMER ISSUE	-
DMS_26133	30966	N	N	N	1	CUSTOMER ISSUE	-
DMS_26134	30967	N	N	N	1	CUSTOMER ISSUE	-
DMS_26135	30968	N	N	N	1	CUSTOMER ISSUE	-
DMS_26140	30969	N	N	N	1	CUSTOMER ISSUE	-
DMS_26141	30970	N	N	N	1	CUSTOMER ISSUE	-
DMS_26142	30971	N	N	N	1	CUSTOMER ISSUE	-
DMS_26143	30972	N	N	N	1	CUSTOMER ISSUE	-
DMS_26144	30973	N	N	N	1	CUSTOMER ISSUE	-
DMS_26145	30974	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26146	30975	N	N	N	1	CUSTOMER ISSUE	-
DMS_26147	30976	N	N	N	1	CUSTOMER ISSUE	-
DMS_26148	30977	N	N	N	1	CUSTOMER ISSUE	-
DMS_26151	30978	N	N	N	1	CUSTOMER ISSUE	-
DMS_26152	30979	N	N	N	1	CUSTOMER ISSUE	-
DMS_26153	30980	N	N	N	1	CUSTOMER ISSUE	-
DMS_26155	30981	N	N	N	1	CUSTOMER ISSUE	-
DMS_26156	30982	N	N	N	1	CUSTOMER ISSUE	-
DMS_26157	30983	N	N	N	1	CUSTOMER ISSUE	-
DMS_26158	30984	N	N	N	1	CUSTOMER ISSUE	-
DMS_26159	30985	N	N	N	1	CUSTOMER ISSUE	-
DMS_26160	30986	N	N	N	1	CUSTOMER ISSUE	-
DMS_26161	30987	N	N	N	1	CUSTOMER ISSUE	-
DMS_26162	30988	N	N	N	1	CUSTOMER ISSUE	-
DMS_26163	30989	N	N	N	1	CUSTOMER ISSUE	-
DMS_26164	30990	N	N	N	1	CUSTOMER ISSUE	-
DMS_26165	30991	N	N	N	1	CUSTOMER ISSUE	-
DMS_26166	30992	N	N	N	1	CUSTOMER ISSUE	-
DMS_26167	30993	N	N	N	1	CUSTOMER ISSUE	-
DMS_26168	30994	N	N	N	1	CUSTOMER ISSUE	-
DMS_26169	30995	N	N	N	1	CUSTOMER ISSUE	-
DMS_26170	30996	N	N	N	1	CUSTOMER ISSUE	-
DMS_26171	30997	N	N	N	1	CUSTOMER ISSUE	-
DMS_26172	30998	N	N	N	1	CUSTOMER ISSUE	-
DMS_26174	30999	N	N	N	1	CUSTOMER ISSUE	-
DMS_26176	31000	N	N	N	1	CUSTOMER ISSUE	-
DMS_26177	31001	N	N	N	1	CUSTOMER ISSUE	-
DMS_26178	31002	N	N	N	1	CUSTOMER ISSUE	-
DMS_26179	31003	N	N	N	1	CUSTOMER ISSUE	-
DMS_26180	31004	N	N	N	1	CUSTOMER ISSUE	-
DMS_26181	31005	N	N	N	1	CUSTOMER ISSUE	-
DMS_26182	31006	N	N	N	1	CUSTOMER ISSUE	-
DMS_26185	31007	N	N	N	1	CUSTOMER ISSUE	-
DMS_26186	31008	N	N	N	1	CUSTOMER ISSUE	-
DMS_26190	31009	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26194	31010	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26199	31011	N	N	N	1	CUSTOMER ISSUE	-
DMS_26201	31012	N	N	N	1	CUSTOMER ISSUE	-
DMS_26205	31013	N	N	N	1	CUSTOMER ISSUE	-
DMS_26206	31014	N	N	N	1	CUSTOMER ISSUE	-
DMS_26207	31015	N	N	N	1	CUSTOMER ISSUE	-
DMS_26208	31016	N	N	N	1	CUSTOMER ISSUE	-

DMS_26209	31017	N	N	N	1	CUSTOMER ISSUE	-
DMS_26210	31018	N	N	N	1	CUSTOMER ISSUE	-
DMS_26211	31019	N	N	N	1	CUSTOMER ISSUE	-
DMS_26213	31020	N	N	N	1	CUSTOMER ISSUE	-
DMS_26214	31021	N	N	N	1	CUSTOMER ISSUE	-
DMS_26215	31022	N	N	N	1	CUSTOMER ISSUE	-
DMS_26216	31023	N	N	N	1	CUSTOMER ISSUE	-
DMS_26217	31024	N	N	N	1	CUSTOMER ISSUE	-
DMS_26219	31025	N	N	N	1	CUSTOMER ISSUE	-
DMS_26220	31026	N	N	N	1	CUSTOMER ISSUE	-
DMS_26221	31027	N	N	N	1	CUSTOMER ISSUE	-
DMS_26222	31028	N	N	N	1	CUSTOMER ISSUE	-
DMS_26223	31029	N	N	N	1	CUSTOMER ISSUE	-
DMS_26225	31030	N	N	N	1	CUSTOMER ISSUE	-
DMS_26226	31031	N	N	N	1	CUSTOMER ISSUE	-
DMS_26227	31032	N	N	N	1	CUSTOMER ISSUE	-
DMS_26228	31033	N	N	N	1	CUSTOMER ISSUE	-
DMS_26229	31034	N	N	N	1	CUSTOMER ISSUE	-
DMS_26230	31035	N	N	N	1	CUSTOMER ISSUE	-
DMS_26232	31036	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26233	31037	N	N	N	1	CUSTOMER ISSUE	-
DMS_26234	31038	N	N	N	1	CUSTOMER ISSUE	-
DMS_26235	31039	N	N	N	1	CUSTOMER ISSUE	-
DMS_26236	31040	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26237	31041	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26238	31042	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_26239	31043	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_26240	31044	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_26242	31045	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26247	31046	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26254	31047	N	N	N	1	CUSTOMER ISSUE	-
DMS_26255	31048	N	N	N	1	CUSTOMER ISSUE	-
DMS_26256	31049	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26258	31050	N	N	N	1	CUSTOMER ISSUE	-
DMS_26259	31051	N	N	N	1	CUSTOMER ISSUE	-
DMS_26261	31052	N	N	N	1	CUSTOMER ISSUE	-
DMS_26262	31053	N	N	N	1	CUSTOMER ISSUE	-
DMS_26264	31054	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26266	31055	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26267	31056	N	N	N	1	CUSTOMER ISSUE	-
DMS_26268	31057	N	N	N	1	CUSTOMER ISSUE	-
DMS_26269	31058	N	N	N	1	CUSTOMER ISSUE	-
DMS_26270	31059	N	N	N	1	CUSTOMER ISSUE	-
DMS_26271	31060	N	N	N	1	CUSTOMER ISSUE	-
DMS_26272	31061	N	N	N	1	CUSTOMER ISSUE	-
DMS_26273	31062	N	N	N	1	CUSTOMER ISSUE	-
DMS_26274	31063	N	N	N	1	CUSTOMER ISSUE	-
DMS_26275	31064	N	N	N	1	CUSTOMER ISSUE	-
DMS_26276	31065	N	N	N	1	CUSTOMER ISSUE	-
DMS_26277	31066	N	N	N	1	CUSTOMER ISSUE	-
DMS_26278	31067	N	N	N	1	CUSTOMER ISSUE	-
DMS_26279	31068	N	N	N	1	CUSTOMER ISSUE	-
DMS_26280	31069	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26281	31070	N	N	N	1	CUSTOMER ISSUE	-
DMS_26285	31071	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26286	31072	N	N	N	1	CUSTOMER ISSUE	-
DMS_26290	31073	N	N	N	1	CUSTOMER ISSUE	-
DMS_26291	31074	N	N	N	1	CUSTOMER ISSUE	-
DMS_26294	31075	N	N	N	1	CUSTOMER ISSUE	-
DMS_26295	31076	N	N	N	1	CUSTOMER ISSUE	-
DMS_26296	31077	N	N	N	1	CUSTOMER ISSUE	-
DMS_26297	31078	N	N	N	1	CUSTOMER ISSUE	-
DMS_26299	31079	N	N	N	1	CUSTOMER ISSUE	-
DMS_26300	31080	N	N	N	1	CUSTOMER ISSUE	-
DMS_26301	31081	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_26302	31082	N	N	N	1	CUSTOMER ISSUE	-
DMS_26303	31083	N	N	N	1	CUSTOMER ISSUE	-
DMS_26304	31084	N	N	N	1	CUSTOMER ISSUE	-
DMS_26305	31085	N	N	N	1	CUSTOMER ISSUE	-
DMS_26306	31086	N	N	N	1	CUSTOMER ISSUE	-
DMS_26307	31087	N	N	N	1	CUSTOMER ISSUE	-
DMS_26308	31088	N	N	N	1	CUSTOMER ISSUE	-
DMS_26309	31089	N	N	N	1	CUSTOMER ISSUE	-
DMS_26310	31090	N	N	N	1	CUSTOMER ISSUE	-
DMS_26311	31091	N	N	N	1	CUSTOMER ISSUE	-
DMS_26312	31092	N	N	N	1	CUSTOMER ISSUE	-
DMS_26313	31093	N	N	N	1	CUSTOMER ISSUE	-
DMS_26314	31094	N	N	N	1	CUSTOMER ISSUE	-
DMS_26315	31095	N	N	N	1	CUSTOMER ISSUE	-
DMS_26316	31096	N	N	N	1	CUSTOMER ISSUE	-

DMS_26317	31097	N	N	N	1	CUSTOMER ISSUE	-
DMS_26318	31098	N	N	N	1	CUSTOMER ISSUE	-
DMS_26319	31099	N	N	N	1	CUSTOMER ISSUE	-
DMS_26320	31100	N	N	N	1	CUSTOMER ISSUE	-
DMS_26322	31101	N	N	N	1	CUSTOMER ISSUE	-
DMS_26323	31102	N	N	N	1	CUSTOMER ISSUE	-
DMS_26324	31103	N	N	N	1	CUSTOMER ISSUE	-
DMS_26325	31104	N	N	N	1	CUSTOMER ISSUE	-
DMS_26326	31105	N	N	N	1	CUSTOMER ISSUE	-
DMS_26327	31106	N	N	N	1	CUSTOMER ISSUE	-
DMS_26328	31107	N	N	N	1	CUSTOMER ISSUE	-
DMS_26329	31108	N	N	N	1	CUSTOMER ISSUE	-
DMS_26330	31109	N	N	N	1	CUSTOMER ISSUE	-
DMS_26331	31110	N	N	N	1	CUSTOMER ISSUE	-
DMS_26332	31111	N	N	N	1	CUSTOMER ISSUE	-
DMS_26334	31112	N	N	N	1	CUSTOMER ISSUE	-
DMS_26335	31113	N	N	N	1	CUSTOMER ISSUE	-
DMS_26336	31114	N	N	N	1	CUSTOMER ISSUE	-
DMS_26337	31115	N	N	N	1	CUSTOMER ISSUE	-
DMS_26338	31116	N	N	N	1	CUSTOMER ISSUE	-
DMS_26339	31117	N	N	N	1	CUSTOMER ISSUE	-
DMS_26340	31118	N	N	N	1	CUSTOMER ISSUE	-
DMS_26342	31119	N	N	N	1	CUSTOMER ISSUE	-
DMS_26343	31120	N	N	N	1	CUSTOMER ISSUE	-
DMS_26344	31121	N	N	N	1	CUSTOMER ISSUE	-
DMS_26345	31122	N	N	N	1	CUSTOMER ISSUE	-
DMS_26346	31123	N	N	N	1	CUSTOMER ISSUE	-
DMS_26347	31124	N	N	N	1	CUSTOMER ISSUE	-
DMS_26348	31125	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26349	31126	N	N	N	1	CUSTOMER ISSUE	-
DMS_26350	31127	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26352	31128	N	N	N	1	CUSTOMER ISSUE	-
DMS_26354	31129	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26355	31130	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26356	31131	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26357	31132	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26358	31133	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26359	31134	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26361	31135	N	N	N	1	CUSTOMER ISSUE	-
DMS_26362	31136	N	N	Y	1	TX - REPLACE	2500
DMS_26363	31137	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26364	31138	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26365	31139	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26368	31140	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26369	31141	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26370	31142	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26371	31143	N	N	Y	6	SEC/SVC - REPLACE	708.75
DMS_26372	31144	N	N	N	1	CUSTOMER ISSUE	-
DMS_26373	31145	N	N	N	1	CUSTOMER ISSUE	-
DMS_26375	31146	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26376	31147	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26377	31148	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_26379	31149	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26380	31150	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26381	31151	N	N	N	1	CUSTOMER ISSUE	-
DMS_26383	31152	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26384	31153	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26385	31154	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26386	31155	N	N	N	1	CUSTOMER ISSUE	-
DMS_26387	31156	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26388	31157	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26389	31158	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_26390	31159	N	N	N	1	CUSTOMER ISSUE	-
DMS_26392	31160	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26393	31161	N	N	N	1	CUSTOMER ISSUE	-
DMS_26394	31162	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26395	31163	N	N	N	1	CUSTOMER ISSUE	-
DMS_26396	31164	N	N	N	1	CUSTOMER ISSUE	-
DMS_26398	31165	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_26404	31166	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_26407	31167	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_26413	31168	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_26414	31169	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_26417	31170	N	N	N	1	CUSTOMER ISSUE	-
DMS_26427	31171	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_26432	31172	N	N	N	1	CUSTOMER ISSUE	-
DMS_26461	31173	N	N	N	1	CUSTOMER ISSUE	-
DMS_26493	31174	N	N	N	1	CUSTOMER ISSUE	-
DMS_26498	31175	N	N	N	1	CUSTOMER ISSUE	-
DMS_26532	31176	N	N	N	1	CUSTOMER ISSUE	-

DMS_26533	31177	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26534	31178	N	N	N	1	CUSTOMER ISSUE	-
DMS_26535	31179	N	N	N	1	CUSTOMER ISSUE	-
DMS_26536	31180	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26537	31181	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26538	31182	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26539	31183	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26540	31184	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26541	31185	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26542	31186	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26543	31187	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26544	31188	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26545	31189	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26546	31190	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26547	31191	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26548	31192	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26549	31193	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26550	31194	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26551	31195	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26552	31196	N	N	N	1	CUSTOMER ISSUE	-
DMS_26553	31197	N	N	N	1	CUSTOMER ISSUE	-
DMS_26554	31198	N	N	N	1	CUSTOMER ISSUE	-
DMS_26555	31199	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26556	31200	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26557	31201	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26558	31202	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26559	31203	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26560	31204	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26561	31205	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26562	31206	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26563	31207	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26564	31208	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26575	31209	N	N	N	1	CUSTOMER ISSUE	-
DMS_26576	31210	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26577	31211	N	N	N	1	CUSTOMER ISSUE	-
DMS_26579	31212	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26580	31213	N	N	N	1	CUSTOMER ISSUE	-
DMS_26581	31214	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26582	31215	N	N	N	1	CUSTOMER ISSUE	-
DMS_26583	31216	N	N	N	1	CUSTOMER ISSUE	-
DMS_26584	31217	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26585	31218	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26586	31219	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26587	31220	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26588	31221	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26589	31222	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26590	31223	N	N	N	1	CUSTOMER ISSUE	-
DMS_26591	31224	N	N	N	1	CUSTOMER ISSUE	-
DMS_26592	31225	N	N	N	1	CUSTOMER ISSUE	-
DMS_26593	31226	N	N	N	1	CUSTOMER ISSUE	-
DMS_26594	31227	N	N	N	1	CUSTOMER ISSUE	-
DMS_26595	31228	N	N	N	1	CUSTOMER ISSUE	-
DMS_26596	31229	N	N	N	1	CUSTOMER ISSUE	-
DMS_26597	31230	N	N	N	1	CUSTOMER ISSUE	-
DMS_26598	31231	N	N	N	1	CUSTOMER ISSUE	-
DMS_26599	31232	N	N	N	1	CUSTOMER ISSUE	-
DMS_26600	31233	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26601	31234	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26602	31235	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26603	31236	N	N	N	1	CUSTOMER ISSUE	-
DMS_26604	31237	N	N	N	1	CUSTOMER ISSUE	-
DMS_26605	31238	N	N	N	1	CUSTOMER ISSUE	-
DMS_26606	31239	N	N	N	1	CUSTOMER ISSUE	-
DMS_26607	31240	N	N	N	1	CUSTOMER ISSUE	-
DMS_26608	31241	N	N	N	1	CUSTOMER ISSUE	-
DMS_26609	31242	N	N	N	1	CUSTOMER ISSUE	-
DMS_26611	31243	N	N	N	1	CUSTOMER ISSUE	-
DMS_26612	31244	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26613	31245	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26614	31246	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26615	31247	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26616	31248	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26617	31249	N	N	Y	1	TX - REPLACE	2500
DMS_26619	31250	N	N	N	1	CUSTOMER ISSUE	-
DMS_26629	31251	N	N	N	1	CUSTOMER ISSUE	-
DMS_26630	31252	N	N	N	1	CUSTOMER ISSUE	-
DMS_26631	31253	N	N	N	1	CUSTOMER ISSUE	-
DMS_26633	31254	N	N	N	1	CUSTOMER ISSUE	-
DMS_26634	31255	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26635	31256	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_26636	31257	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_26637	31258	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26638	31259	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26639	31260	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26641	31261	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26643	31262	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26644	31263	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26645	31264	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26646	31265	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26647	31266	N	N	Y	1	TX - REPLACE	2500
DMS_26648	31267	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26649	31268	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26650	31269	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26651	31270	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26652	31271	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26653	31272	N	N	N	1	CUSTOMER ISSUE	-
DMS_26654	31273	N	N	N	1	CUSTOMER ISSUE	-
DMS_26655	31274	N	N	N	1	CUSTOMER ISSUE	-
DMS_26656	31275	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26657	31276	N	N	N	1	CUSTOMER ISSUE	-
DMS_26660	31277	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26661	31278	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26662	31279	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26663	31280	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26664	31281	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26665	31282	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26666	31283	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26669	31284	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26671	31285	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26672	31286	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26674	31287	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26675	31288	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26676	31289	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26677	31290	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26678	31291	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26679	31292	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26680	31293	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26684	31294	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26685	31295	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26686	31296	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26687	31297	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26688	31298	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26689	31299	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26690	31300	N	N	N	1	CUSTOMER ISSUE	-
DMS_26692	31301	N	N	N	1	CUSTOMER ISSUE	-
DMS_26693	31302	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26694	31303	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26695	31304	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26696	31305	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26697	31306	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26698	31307	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26699	31308	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26700	31309	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26701	31310	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26702	31311	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26703	31312	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26704	31313	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26705	31314	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26706	31315	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26707	31316	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26708	31317	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26709	31318	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26710	31319	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26711	31320	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26712	31321	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26713	31322	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26714	31323	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26715	31324	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26716	31325	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26717	31326	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26718	31327	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26719	31328	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26720	31329	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26721	31330	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26722	31331	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26723	31332	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26724	31333	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26725	31334	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26726	31335	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26727	31336	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_26728	31337	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26729	31338	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26730	31339	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26731	31340	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26732	31341	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26733	31342	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26734	31343	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26735	31344	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26736	31345	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26737	31346	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26738	31347	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26739	31348	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26740	31349	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26741	31350	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26742	31351	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26743	31352	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26745	31353	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26747	31354	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26749	31355	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26750	31356	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26754	31357	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26755	31358	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26759	31359	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26760	31360	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26762	31361	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26763	31362	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26764	31363	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26765	31364	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26766	31365	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26767	31366	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26768	31367	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26769	31368	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26770	31369	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26771	31370	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26772	31371	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26773	31372	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26774	31373	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26775	31374	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26776	31375	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26777	31376	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26778	31377	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26779	31378	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26780	31379	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26781	31380	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26782	31381	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26783	31382	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26784	31383	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26785	31384	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26786	31385	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26787	31386	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26788	31387	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26789	31388	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26790	31389	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26791	31390	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26792	31391	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26793	31392	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26794	31393	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26795	31394	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26796	31395	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26797	31396	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26798	31397	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26799	31398	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26800	31399	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26801	31400	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26802	31401	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26803	31402	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26804	31403	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26805	31404	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26806	31405	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26807	31406	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26808	31407	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26809	31408	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26810	31409	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26811	31410	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26812	31411	N	N	Y	1	TX - REPLACE	2500
DMS_26813	31412	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26814	31413	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26815	31414	N	N	Y	1	TX - REPLACE	2500
DMS_26816	31415	N	N	Y	1	TX - REPLACE	2500
DMS_26817	31416	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_26818	31417	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26819	31418	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26820	31419	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26821	31420	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26822	31421	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26823	31422	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26824	31423	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26825	31424	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26826	31425	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26828	31426	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26829	31427	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26830	31428	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26831	31429	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26832	31430	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26833	31431	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26834	31432	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26835	31433	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26836	31434	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26837	31435	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26838	31436	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26839	31437	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26840	31438	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26841	31439	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26842	31440	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26843	31441	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26844	31442	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26845	31443	N	N	Y	1	TX - REPLACE	2500
DMS_26846	31444	N	N	Y	1	TX - REPLACE	2500
DMS_26847	31445	N	N	Y	1	TX - REPLACE	2500
DMS_26848	31446	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26849	31447	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26850	31448	N	N	Y	1	TX - REPLACE	2500
DMS_26851	31449	N	N	Y	1	TX - REPLACE	2500
DMS_26852	31450	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26853	31451	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26854	31452	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26855	31453	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26856	31454	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26857	31455	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26858	31456	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26859	31457	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26860	31458	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26861	31459	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26862	31460	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26863	31461	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26864	31462	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26865	31463	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26866	31464	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26867	31465	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26868	31466	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26869	31467	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26870	31468	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26871	31469	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26872	31470	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26873	31471	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26874	31472	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26875	31473	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26876	31474	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26877	31475	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26878	31476	N	N	Y	1	TX - REPLACE	2500
DMS_26879	31477	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26880	31478	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26881	31479	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26882	31480	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26883	31481	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26884	31482	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26885	31483	N	N	Y	1	TX - REPLACE	2500
DMS_26886	31484	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26887	31485	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26888	31486	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26889	31487	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26890	31488	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26891	31489	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26892	31490	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26893	31491	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26894	31492	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26895	31493	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_26896	31494	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26897	31495	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_26898	31496	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_26899	31497	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26900	31498	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26901	31499	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26902	31500	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26903	31501	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26904	31502	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26905	31503	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26906	31504	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26907	31505	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26908	31506	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26909	31507	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26910	31508	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26911	31509	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26912	31510	N	N	Y	1	TX - REPLACE	2500
DMS_26913	31511	N	N	Y	1	TX - REPLACE	2500
DMS_26914	31512	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26915	31513	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26916	31514	N	N	Y	1	TX - REPLACE	2500
DMS_26917	31515	N	N	Y	1	TX - REPLACE	2500
DMS_26918	31516	N	N	Y	1	TX - REPLACE	2500
DMS_26919	31517	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26920	31518	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26921	31519	N	N	Y	1	TX - REPLACE	2500
DMS_26922	31520	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26923	31521	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26924	31522	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26925	31523	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26926	31524	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_26927	31525	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26928	31526	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26929	31527	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26930	31528	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26931	31529	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26932	31530	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26933	31531	N	N	Y	1	TX - REPLACE	2500
DMS_26934	31532	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26935	31533	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26936	31534	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26937	31535	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26938	31536	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26939	31537	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26940	31538	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26941	31539	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26942	31540	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26943	31541	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26944	31542	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26945	31543	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26946	31544	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26947	31545	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26948	31546	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26949	31547	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26950	31548	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26951	31549	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26952	31550	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26953	31551	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26954	31552	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26955	31553	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26956	31554	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26957	31555	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26958	31556	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26959	31557	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26960	31558	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26961	31559	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26962	31560	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26963	31561	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26964	31562	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26965	31563	N	N	Y	1	TX - REPLACE	2500
DMS_26966	31564	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26967	31565	N	N	Y	1	TX - REPLACE	2500
DMS_26968	31566	N	N	Y	1	TX - REPLACE	2500
DMS_26969	31567	N	N	Y	1	TX - REPLACE	2500
DMS_26970	31568	N	N	Y	1	TX - REPLACE	2500
DMS_26971	31569	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26972	31570	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26973	31571	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_26974	31572	N	N	Y	1	TX - REPLACE	2500
DMS_26975	31573	N	N	Y	1	TX - REPLACE	2500
DMS_26976	31574	N	N	Y	1	TX - REPLACE	2500
DMS_26977	31575	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26978	31576	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_26979	31577	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26981	31578	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26982	31579	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26983	31580	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_26984	31581	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26985	31582	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26986	31583	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26987	31584	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26989	31585	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26991	31586	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26993	31587	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26994	31588	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_26995	31589	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_26996	31590	N	N	Y	1	TX - REPLACE	2500
DMS_26997	31591	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_26998	31592	N	N	N	1	CUSTOMER ISSUE	-
DMS_26999	31593	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27000	31594	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27001	31595	N	N	N	1	CUSTOMER ISSUE	-
DMS_27002	31596	N	N	N	1	CUSTOMER ISSUE	-
DMS_27003	31597	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27004	31598	N	N	N	1	CUSTOMER ISSUE	-
DMS_27005	31599	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27006	31600	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27007	31601	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27008	31602	N	N	N	1	CUSTOMER ISSUE	-
DMS_27009	31603	N	N	N	1	CUSTOMER ISSUE	-
DMS_27011	31604	N	N	N	1	CUSTOMER ISSUE	-
DMS_27012	31605	N	N	N	1	CUSTOMER ISSUE	-
DMS_27013	31606	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27014	31607	N	N	N	1	CUSTOMER ISSUE	-
DMS_27015	31608	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27016	31609	N	N	N	1	CUSTOMER ISSUE	-
DMS_27017	31610	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27019	31611	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27020	31612	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27023	31613	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27024	31614	N	N	N	1	CUSTOMER ISSUE	-
DMS_27025	31615	N	N	N	1	CUSTOMER ISSUE	-
DMS_27026	31616	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27029	31617	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27031	31618	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27032	31619	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27033	31620	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27034	31621	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27035	31622	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27036	31623	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27037	31624	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27038	31625	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27040	31626	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27041	31627	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27044	31628	N	N	N	1	CUSTOMER ISSUE	-
DMS_27045	31629	N	N	N	1	CUSTOMER ISSUE	-
DMS_27046	31630	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27047	31631	N	N	N	1	CUSTOMER ISSUE	-
DMS_27048	31632	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27050	31633	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27051	31634	N	N	N	1	CUSTOMER ISSUE	-
DMS_27052	31635	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27053	31636	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27055	31637	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27056	31638	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_27058	31639	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27059	31640	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27060	31641	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27061	31642	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27062	31643	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27063	31644	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27064	31645	N	N	Y	1	TX - REPLACE	2500
DMS_27065	31646	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27066	31647	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27067	31648	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27068	31649	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27069	31650	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27071	31651	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27072	31652	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_27073	31653	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27074	31654	N	N	N	1	CUSTOMER ISSUE	-
DMS_27075	31655	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27077	31656	N	N	Y	1	DIST - TREE TRIMMING	945

DMS_27078	31657	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27079	31658	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27080	31659	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27081	31660	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27082	31661	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27083	31662	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27085	31663	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27086	31664	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27087	31665	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27088	31666	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27089	31667	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27090	31668	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27091	31669	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27092	31670	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27093	31671	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27094	31672	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27095	31673	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27096	31674	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27097	31675	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27098	31676	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_27099	31677	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27100	31678	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27101	31679	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_27102	31680	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27103	31681	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27104	31682	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27105	31683	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27106	31684	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27107	31685	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27108	31686	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27109	31687	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27110	31688	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27111	31689	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27112	31690	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27113	31691	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27114	31692	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27115	31693	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27116	31694	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_27117	31695	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27120	31696	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27121	31697	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27122	31698	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27123	31699	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27124	31700	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27125	31701	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27127	31702	N	N	N	1	CUSTOMER ISSUE	-
DMS_27128	31703	N	N	N	1	CUSTOMER ISSUE	-
DMS_27129	31704	N	N	N	1	CUSTOMER ISSUE	-
DMS_27130	31705	N	N	N	1	CUSTOMER ISSUE	-
DMS_27131	31706	N	N	N	1	CUSTOMER ISSUE	-
DMS_27132	31707	N	N	N	1	CUSTOMER ISSUE	-
DMS_27134	31708	N	N	N	2	CUSTOMER ISSUE	-
DMS_27135	31709	N	N	N	1	CUSTOMER ISSUE	-
DMS_27136	31710	N	N	N	1	CUSTOMER ISSUE	-
DMS_27137	31711	N	N	N	1	CUSTOMER ISSUE	-
DMS_27138	31712	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27139	31713	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27140	31714	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27141	31715	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27143	31716	N	N	N	1	CUSTOMER ISSUE	-
DMS_27144	31717	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27146	31718	N	N	N	1	CUSTOMER ISSUE	-
DMS_27147	31719	N	N	N	1	CUSTOMER ISSUE	-
DMS_27149	31720	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27150	31721	N	N	N	1	CUSTOMER ISSUE	-
DMS_27151	31722	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27152	31723	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27153	31724	N	N	N	1	CUSTOMER ISSUE	-
DMS_27154	31725	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27155	31726	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27156	31727	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27157	31728	N	N	N	1	CUSTOMER ISSUE	-
DMS_27158	31729	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_27159	31730	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27161	31731	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27162	31732	N	N	N	1	CUSTOMER ISSUE	-
DMS_27163	31733	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27164	31734	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27165	31735	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27166	31736	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_27167	31737	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27170	31738	N	N	N	1	CUSTOMER ISSUE	-
DMS_27171	31739	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27177	31740	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27178	31741	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27179	31742	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27180	31743	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27181	31744	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27182	31745	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27183	31746	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27184	31747	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27185	31748	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27186	31749	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27187	31750	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_27188	31751	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27189	31752	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27190	31753	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27191	31754	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27192	31755	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27193	31756	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27194	31757	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27195	31758	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27196	31759	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27197	31760	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27198	31761	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27199	31762	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27200	31763	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27201	31764	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27202	31765	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27203	31766	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27204	31767	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27205	31768	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27206	31769	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27207	31770	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27208	31771	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27209	31772	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27210	31773	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27211	31774	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27212	31775	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27213	31776	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27214	31777	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27215	31778	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27216	31779	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27217	31780	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27218	31781	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27219	31782	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27220	31783	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27221	31784	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27222	31785	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27223	31786	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27224	31787	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27225	31788	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27226	31789	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27227	31790	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27228	31791	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27229	31792	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27230	31793	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27231	31794	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27232	31795	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27233	31796	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27234	31797	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27235	31798	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27236	31799	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27237	31800	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27238	31801	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27239	31802	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27240	31803	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27241	31804	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27242	31805	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27243	31806	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27244	31807	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27245	31808	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27246	31809	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27247	31810	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27248	31811	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27249	31812	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27250	31813	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27251	31814	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27252	31815	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27253	31816	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_27254	31817	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27255	31818	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27256	31819	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27257	31820	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27258	31821	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27259	31822	N	N	N	1	CUSTOMER ISSUE	-
DMS_27260	31823	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27261	31824	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27262	31825	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27263	31826	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27264	31827	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27265	31828	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27266	31829	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27267	31830	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27268	31831	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27269	31832	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27270	31833	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27271	31834	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27272	31835	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27273	31836	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27274	31837	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27275	31838	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27276	31839	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27277	31840	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27278	31841	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27279	31842	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27280	31843	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27281	31844	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27282	31845	N	N	N	1	CUSTOMER ISSUE	-
DMS_27283	31846	N	N	N	1	CUSTOMER ISSUE	-
DMS_27284	31847	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27285	31848	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27286	31849	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27287	31850	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27288	31851	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27289	31852	N	N	N	1	CUSTOMER ISSUE	-
DMS_27290	31853	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27292	31854	N	N	N	1	CUSTOMER ISSUE	-
DMS_27293	31855	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27294	31856	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27295	31857	N	N	N	1	CUSTOMER ISSUE	-
DMS_27296	31858	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27297	31859	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27298	31860	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27299	31861	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27300	31862	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27301	31863	N	N	N	1	CUSTOMER ISSUE	-
DMS_27302	31864	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27303	31865	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27304	31866	N	N	N	1	CUSTOMER ISSUE	-
DMS_27305	31867	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27306	31868	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27307	31869	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27308	31870	N	N	N	1	CUSTOMER ISSUE	-
DMS_27309	31871	N	N	N	1	CUSTOMER ISSUE	-
DMS_27310	31872	N	N	N	1	CUSTOMER ISSUE	-
DMS_27311	31873	N	N	N	1	CUSTOMER ISSUE	-
DMS_27312	31874	N	N	N	1	CUSTOMER ISSUE	-
DMS_27313	31875	N	N	N	1	CUSTOMER ISSUE	-
DMS_27314	31876	N	N	N	1	CUSTOMER ISSUE	-
DMS_27315	31877	N	N	N	1	CUSTOMER ISSUE	-
DMS_27316	31878	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27317	31879	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27318	31880	N	N	N	1	CUSTOMER ISSUE	-
DMS_27319	31881	N	N	N	1	CUSTOMER ISSUE	-
DMS_27320	31882	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27321	31883	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27322	31884	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27323	31885	N	N	N	1	CUSTOMER ISSUE	-
DMS_27324	31886	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27325	31887	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27326	31888	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27327	31889	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27328	31890	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27329	31891	N	N	N	1	CUSTOMER ISSUE	-
DMS_27330	31892	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27331	31893	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27332	31894	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27333	31895	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27334	31896	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_27335	31897	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27336	31898	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27337	31899	N	N	N	1	CUSTOMER ISSUE	-
DMS_27338	31900	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_27339	31901	N	N	N	1	CUSTOMER ISSUE	-
DMS_27340	31902	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27341	31903	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27342	31904	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27343	31905	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27344	31906	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27345	31907	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27346	31908	N	N	N	1	CUSTOMER ISSUE	-
DMS_27347	31909	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27349	31910	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27350	31911	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27351	31912	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27352	31913	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27353	31914	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27354	31915	N	N	N	1	CUSTOMER ISSUE	-
DMS_27355	31916	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27356	31917	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27357	31918	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27358	31919	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27359	31920	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27360	31921	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27361	31922	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27362	31923	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27363	31924	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27364	31925	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27365	31926	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27369	31927	N	N	N	1	CUSTOMER ISSUE	-
DMS_27370	31928	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27371	31929	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27372	31930	N	N	N	1	CUSTOMER ISSUE	-
DMS_27373	31931	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27374	31932	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27375	31933	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27376	31934	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27377	31935	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27378	31936	N	N	N	1	CUSTOMER ISSUE	-
DMS_27379	31937	N	N	N	1	CUSTOMER ISSUE	-
DMS_27380	31938	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27381	31939	N	N	N	1	CUSTOMER ISSUE	-
DMS_27382	31940	N	N	N	1	CUSTOMER ISSUE	-
DMS_27384	31941	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27385	31942	N	N	N	1	CUSTOMER ISSUE	-
DMS_27386	31943	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27387	31944	N	N	N	1	CUSTOMER ISSUE	-
DMS_27388	31945	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27389	31946	N	N	N	1	CUSTOMER ISSUE	-
DMS_27390	31947	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27391	31948	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27392	31949	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27393	31950	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27394	31951	N	N	N	1	CUSTOMER ISSUE	-
DMS_27395	31952	N	N	N	1	CUSTOMER ISSUE	-
DMS_27396	31953	N	N	N	1	CUSTOMER ISSUE	-
DMS_27397	31954	N	N	N	1	CUSTOMER ISSUE	-
DMS_27398	31955	N	N	N	1	CUSTOMER ISSUE	-
DMS_27399	31956	N	N	N	1	CUSTOMER ISSUE	-
DMS_27400	31957	N	N	N	1	CUSTOMER ISSUE	-
DMS_27401	31958	N	N	N	1	CUSTOMER ISSUE	-
DMS_27402	31959	N	N	N	1	CUSTOMER ISSUE	-
DMS_27403	31960	N	N	N	1	CUSTOMER ISSUE	-
DMS_27404	31961	N	N	N	1	CUSTOMER ISSUE	-
DMS_27405	31962	N	N	N	1	CUSTOMER ISSUE	-
DMS_27406	31963	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27407	31964	N	N	N	1	CUSTOMER ISSUE	-
DMS_27408	31965	N	N	N	1	CUSTOMER ISSUE	-
DMS_27409	31966	N	N	N	1	CUSTOMER ISSUE	-
DMS_27410	31967	N	N	N	1	CUSTOMER ISSUE	-
DMS_27412	31968	N	N	N	1	CUSTOMER ISSUE	-
DMS_27413	31969	N	N	N	1	CUSTOMER ISSUE	-
DMS_27414	31970	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_27415	31971	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27416	31972	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27417	31973	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27418	31974	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27419	31975	N	N	N	1	CUSTOMER ISSUE	-
DMS_27420	31976	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_27421	31977	N	N	N	1	CUSTOMER ISSUE	-
DMS_27422	31978	N	N	N	1	CUSTOMER ISSUE	-
DMS_27423	31979	N	N	N	1	CUSTOMER ISSUE	-
DMS_27424	31980	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27425	31981	N	N	N	1	CUSTOMER ISSUE	-
DMS_27426	31982	N	N	N	1	CUSTOMER ISSUE	-
DMS_27427	31983	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27428	31984	N	N	N	1	CUSTOMER ISSUE	-
DMS_27429	31985	N	N	N	1	CUSTOMER ISSUE	-
DMS_27430	31986	N	N	N	1	CUSTOMER ISSUE	-
DMS_27431	31987	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27432	31988	N	N	N	1	CUSTOMER ISSUE	-
DMS_27433	31989	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27434	31990	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27435	31991	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27436	31992	N	N	N	1	CUSTOMER ISSUE	-
DMS_27437	31993	N	N	N	1	CUSTOMER ISSUE	-
DMS_27438	31994	N	N	Y	1	TX - REPLACE	2500
DMS_27439	31995	N	N	N	1	CUSTOMER ISSUE	-
DMS_27440	31996	N	N	Y	1	TX - REPLACE	2500
DMS_27441	31997	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27442	31998	N	N	N	1	CUSTOMER ISSUE	-
DMS_27443	31999	N	N	N	1	CUSTOMER ISSUE	-
DMS_27444	32000	N	N	N	1	CUSTOMER ISSUE	-
DMS_27445	32001	N	N	N	1	CUSTOMER ISSUE	-
DMS_27446	32002	N	N	N	1	CUSTOMER ISSUE	-
DMS_27447	32003	N	N	N	1	CUSTOMER ISSUE	-
DMS_27448	32004	N	N	Y	1	TX - REPLACE	2500
DMS_27449	32005	N	N	Y	1	TX - REPLACE	2500
DMS_27450	32006	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_27451	32007	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27452	32008	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_27453	32009	N	N	N	1	CUSTOMER ISSUE	-
DMS_27454	32010	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27455	32011	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27456	32012	N	N	N	1	CUSTOMER ISSUE	-
DMS_27457	32013	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27458	32014	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27459	32015	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27460	32016	N	N	N	1	CUSTOMER ISSUE	-
DMS_27461	32017	N	N	N	1	CUSTOMER ISSUE	-
DMS_27462	32018	N	N	N	1	CUSTOMER ISSUE	-
DMS_27463	32019	N	N	N	1	CUSTOMER ISSUE	-
DMS_27464	32020	N	N	N	1	CUSTOMER ISSUE	-
DMS_27465	32021	N	N	N	1	CUSTOMER ISSUE	-
DMS_27466	32022	N	N	N	1	CUSTOMER ISSUE	-
DMS_27467	32023	N	N	N	1	CUSTOMER ISSUE	-
DMS_27468	32024	N	N	N	1	CUSTOMER ISSUE	-
DMS_27469	32025	N	N	N	1	CUSTOMER ISSUE	-
DMS_27470	32026	N	N	N	1	CUSTOMER ISSUE	-
DMS_27471	32027	N	N	N	1	CUSTOMER ISSUE	-
DMS_27472	32028	N	N	N	1	CUSTOMER ISSUE	-
DMS_27473	32029	N	N	N	1	CUSTOMER ISSUE	-
DMS_27474	32030	N	N	N	1	CUSTOMER ISSUE	-
DMS_27475	32031	N	N	N	1	CUSTOMER ISSUE	-
DMS_27476	32032	N	N	N	1	CUSTOMER ISSUE	-
DMS_27477	32033	N	N	N	1	CUSTOMER ISSUE	-
DMS_27478	32034	N	N	N	1	CUSTOMER ISSUE	-
DMS_27479	32035	N	N	N	2	CUSTOMER ISSUE	-
DMS_27480	32036	N	N	N	1	CUSTOMER ISSUE	-
DMS_27481	32037	N	N	N	1	CUSTOMER ISSUE	-
DMS_27482	32038	N	N	N	1	CUSTOMER ISSUE	-
DMS_27483	32039	N	N	N	1	CUSTOMER ISSUE	-
DMS_27484	32040	N	N	N	1	CUSTOMER ISSUE	-
DMS_27485	32041	N	N	N	1	CUSTOMER ISSUE	-
DMS_27486	32042	N	N	N	1	CUSTOMER ISSUE	-
DMS_27487	32043	N	N	N	1	CUSTOMER ISSUE	-
DMS_27488	32044	N	N	N	1	CUSTOMER ISSUE	-
DMS_27489	32045	N	N	N	1	CUSTOMER ISSUE	-
DMS_27490	32046	N	N	N	1	CUSTOMER ISSUE	-
DMS_27491	32047	N	N	N	1	CUSTOMER ISSUE	-
DMS_27492	32048	N	N	N	1	CUSTOMER ISSUE	-
DMS_27493	32049	N	N	N	1	CUSTOMER ISSUE	-
DMS_27494	32050	N	N	N	1	CUSTOMER ISSUE	-
DMS_27495	32051	N	N	N	1	CUSTOMER ISSUE	-
DMS_27496	32052	N	N	N	1	CUSTOMER ISSUE	-
DMS_27497	32053	N	N	N	1	CUSTOMER ISSUE	-
DMS_27498	32054	N	N	N	1	CUSTOMER ISSUE	-
DMS_27499	32055	N	N	N	1	CUSTOMER ISSUE	-
DMS_27500	32056	N	N	N	1	CUSTOMER ISSUE	-

DMS_27501	32057	N	N	N	1	CUSTOMER ISSUE	-
DMS_27502	32058	N	N	N	1	CUSTOMER ISSUE	-
DMS_27503	32059	N	N	N	1	CUSTOMER ISSUE	-
DMS_27504	32060	N	N	N	1	CUSTOMER ISSUE	-
DMS_27505	32061	N	N	N	1	CUSTOMER ISSUE	-
DMS_27506	32062	N	N	N	1	CUSTOMER ISSUE	-
DMS_27507	32063	N	N	N	1	CUSTOMER ISSUE	-
DMS_27508	32064	N	N	N	1	CUSTOMER ISSUE	-
DMS_27509	32065	N	N	N	1	CUSTOMER ISSUE	-
DMS_27510	32066	N	N	N	1	CUSTOMER ISSUE	-
DMS_27511	32067	N	N	N	1	CUSTOMER ISSUE	-
DMS_27512	32068	N	N	N	1	CUSTOMER ISSUE	-
DMS_27513	32069	N	N	N	1	CUSTOMER ISSUE	-
DMS_27514	32070	N	N	N	1	CUSTOMER ISSUE	-
DMS_27515	32071	N	N	N	1	CUSTOMER ISSUE	-
DMS_27516	32072	N	N	N	1	CUSTOMER ISSUE	-
DMS_27517	32073	N	N	N	1	CUSTOMER ISSUE	-
DMS_27518	32074	N	N	N	2	CUSTOMER ISSUE	-
DMS_27519	32075	N	N	N	1	CUSTOMER ISSUE	-
DMS_27520	32076	N	N	N	1	CUSTOMER ISSUE	-
DMS_27521	32077	N	N	N	1	CUSTOMER ISSUE	-
DMS_27522	32078	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27523	32079	N	N	N	1	CUSTOMER ISSUE	-
DMS_27524	32080	N	N	N	1	CUSTOMER ISSUE	-
DMS_27525	32081	N	N	N	1	CUSTOMER ISSUE	-
DMS_27526	32082	N	N	N	1	CUSTOMER ISSUE	-
DMS_27527	32083	N	N	N	1	CUSTOMER ISSUE	-
DMS_27528	32084	N	N	N	1	CUSTOMER ISSUE	-
DMS_27529	32085	N	N	N	1	CUSTOMER ISSUE	-
DMS_27530	32086	N	N	N	1	CUSTOMER ISSUE	-
DMS_27531	32087	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27532	32088	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27533	32089	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27534	32090	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27535	32091	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27536	32092	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27537	32093	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_27538	32094	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27539	32095	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27540	32096	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27541	32097	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27542	32098	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27543	32099	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27544	32100	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27545	32101	N	N	N	1	CUSTOMER ISSUE	-
DMS_27546	32102	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27547	32103	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27548	32104	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27549	32105	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27550	32106	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27551	32107	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27552	32108	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27553	32109	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27554	32110	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27555	32111	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27556	32112	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27557	32113	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27558	32114	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27559	32115	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27560	32116	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27561	32117	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27562	32118	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27563	32119	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27564	32120	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27565	32121	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27566	32122	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27567	32123	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27568	32124	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27569	32125	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27570	32126	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27571	32127	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_27572	32128	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27573	32129	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27574	32130	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27575	32131	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27576	32132	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27577	32133	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27578	32134	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27579	32135	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27580	32136	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_27581	32137	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27582	32138	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27583	32139	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27584	32140	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27585	32141	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27586	32142	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27587	32143	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27588	32144	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27589	32145	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27590	32146	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27591	32147	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27592	32148	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27593	32149	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27594	32150	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27595	32151	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27596	32152	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27597	32153	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27598	32154	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27599	32155	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27600	32156	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27601	32157	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27602	32158	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27603	32159	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27604	32160	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27605	32161	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27606	32162	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27607	32163	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27608	32164	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27609	32165	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27610	32166	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27611	32167	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27612	32168	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27613	32169	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27614	32170	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27615	32171	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27616	32172	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27617	32173	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27618	32174	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27619	32175	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27620	32176	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27621	32177	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27622	32178	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27623	32179	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27624	32180	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27625	32181	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27626	32182	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27627	32183	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27628	32184	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27629	32185	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27630	32186	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27631	32187	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27632	32188	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27633	32189	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27634	32190	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27635	32191	N	N	N	1	CUSTOMER ISSUE	-
DMS_27636	32192	N	N	N	1	CUSTOMER ISSUE	-
DMS_27637	32193	N	N	N	1	CUSTOMER ISSUE	-
DMS_27638	32194	N	N	N	1	CUSTOMER ISSUE	-
DMS_27639	32195	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27640	32196	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27641	32197	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27642	32198	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27643	32199	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27644	32200	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27645	32201	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27646	32202	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27647	32203	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27649	32204	N	N	N	1	CUSTOMER ISSUE	-
DMS_27650	32205	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27651	32206	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27652	32207	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27653	32208	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27654	32209	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27655	32210	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27656	32211	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27657	32212	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27658	32213	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27659	32214	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27660	32215	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_27661	32216	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_27662	32217	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27663	32218	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27664	32219	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27665	32220	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27666	32221	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27667	32222	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27668	32223	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27669	32224	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27670	32225	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27671	32226	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27672	32227	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27673	32228	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27674	32229	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27675	32230	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27676	32231	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27677	32232	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27678	32233	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27679	32234	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27680	32235	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27681	32236	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27682	32237	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27683	32238	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27684	32239	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27685	32240	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27686	32241	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27687	32242	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27688	32243	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27689	32244	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27690	32245	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27691	32246	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27692	32247	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27693	32248	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27694	32249	N	N	N	1	CUSTOMER ISSUE	-
DMS_27695	32250	N	N	N	1	CUSTOMER ISSUE	-
DMS_27696	32251	N	N	N	1	CUSTOMER ISSUE	-
DMS_27697	32252	N	N	N	1	CUSTOMER ISSUE	-
DMS_27698	32253	N	N	N	1	CUSTOMER ISSUE	-
DMS_27699	32254	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27700	32255	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27701	32256	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_27702	32257	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27703	32258	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27704	32259	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27705	32260	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27706	32261	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27707	32262	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27708	32263	N	N	N	1	CUSTOMER ISSUE	-
DMS_27709	32264	N	N	N	1	CUSTOMER ISSUE	-
DMS_27710	32265	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27711	32266	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27712	32267	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27713	32268	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27714	32269	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27715	32270	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27716	32271	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27717	32272	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27718	32273	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27719	32274	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27720	32275	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27721	32276	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27722	32277	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27723	32278	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27724	32279	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27725	32280	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27726	32281	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27727	32282	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27728	32283	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27729	32284	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27730	32285	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27731	32286	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27732	32287	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27733	32288	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27734	32289	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27735	32290	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27736	32291	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27737	32292	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27738	32293	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27739	32294	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27740	32295	N	N	N	1	CUSTOMER ISSUE	-
DMS_27741	32296	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_27742	32297	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27743	32298	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27744	32299	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27745	32300	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27746	32301	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27747	32302	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27748	32303	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27749	32304	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27750	32305	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27751	32306	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27753	32307	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27754	32308	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27755	32309	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27756	32310	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27757	32311	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27758	32312	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27759	32313	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27760	32314	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27761	32315	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27762	32316	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27763	32317	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27764	32318	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27765	32319	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27766	32320	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27767	32321	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27768	32322	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27769	32323	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27770	32324	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27771	32325	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27772	32326	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27773	32327	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27774	32328	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27775	32329	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27776	32330	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27777	32331	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27778	32332	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27779	32333	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27780	32334	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27781	32335	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27782	32336	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27783	32337	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27784	32338	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27785	32339	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27786	32340	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27787	32341	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27788	32342	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27789	32343	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27790	32344	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27791	32345	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27792	32346	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27793	32347	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27794	32348	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27795	32349	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27796	32350	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27797	32351	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27798	32352	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27799	32353	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27800	32354	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27801	32355	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27802	32356	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27803	32357	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27804	32358	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_27805	32359	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27806	32360	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27807	32361	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27808	32362	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27809	32363	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27810	32364	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27811	32365	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27812	32366	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27813	32367	N	N	N	1	CUSTOMER ISSUE	-
DMS_27814	32368	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27815	32369	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27816	32370	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_27817	32371	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27818	32372	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27819	32373	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27820	32374	N	N	N	1	CUSTOMER ISSUE	-
DMS_27821	32375	N	N	N	1	CUSTOMER ISSUE	-
DMS_27822	32376	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_27823	32377	N	N	N	1	CUSTOMER ISSUE	-
DMS_27824	32378	N	N	N	1	CUSTOMER ISSUE	-
DMS_27825	32379	N	N	N	1	CUSTOMER ISSUE	-
DMS_27826	32380	N	N	N	1	CUSTOMER ISSUE	-
DMS_27827	32381	N	N	N	1	CUSTOMER ISSUE	-
DMS_27828	32382	N	N	N	1	CUSTOMER ISSUE	-
DMS_27829	32383	N	N	N	1	CUSTOMER ISSUE	-
DMS_27830	32384	N	N	N	1	CUSTOMER ISSUE	-
DMS_27831	32385	N	N	N	1	CUSTOMER ISSUE	-
DMS_27832	32386	N	N	N	1	CUSTOMER ISSUE	-
DMS_27833	32387	N	N	N	1	CUSTOMER ISSUE	-
DMS_27834	32388	N	N	N	1	CUSTOMER ISSUE	-
DMS_27835	32389	N	N	N	1	CUSTOMER ISSUE	-
DMS_27836	32390	N	N	N	1	CUSTOMER ISSUE	-
DMS_27837	32391	N	N	N	1	CUSTOMER ISSUE	-
DMS_27838	32392	N	N	N	2	CUSTOMER ISSUE	-
DMS_27839	32393	N	N	N	1	CUSTOMER ISSUE	-
DMS_27840	32394	N	N	N	1	CUSTOMER ISSUE	-
DMS_27841	32395	N	N	N	1	CUSTOMER ISSUE	-
DMS_27842	32396	N	N	N	1	CUSTOMER ISSUE	-
DMS_27843	32397	N	N	N	1	CUSTOMER ISSUE	-
DMS_27844	32398	N	N	N	1	CUSTOMER ISSUE	-
DMS_27845	32399	N	N	N	1	CUSTOMER ISSUE	-
DMS_27846	32400	N	N	N	1	CUSTOMER ISSUE	-
DMS_27847	32401	N	N	N	1	CUSTOMER ISSUE	-
DMS_27848	32402	N	N	N	1	CUSTOMER ISSUE	-
DMS_27849	32403	N	N	N	1	CUSTOMER ISSUE	-
DMS_27850	32404	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_27851	32405	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_27852	32406	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27853	32407	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27854	32408	N	N	Y	1	TX - REPLACE	2500
DMS_27855	32409	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27856	32410	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27857	32411	N	N	N	1	CUSTOMER ISSUE	-
DMS_27858	32412	N	N	N	1	CUSTOMER ISSUE	-
DMS_27859	32413	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27860	32414	N	N	N	1	CUSTOMER ISSUE	-
DMS_27861	32415	N	N	N	1	CUSTOMER ISSUE	-
DMS_27862	32416	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_27863	32417	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_27864	32418	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_27865	32419	N	N	N	1	CUSTOMER ISSUE	-
DMS_27866	32420	N	N	N	1	CUSTOMER ISSUE	-
DMS_27867	32421	N	N	N	1	CUSTOMER ISSUE	-
DMS_27868	32422	N	N	N	1	CUSTOMER ISSUE	-
DMS_27869	32423	N	N	N	1	CUSTOMER ISSUE	-
DMS_27870	32424	N	N	N	1	CUSTOMER ISSUE	-
DMS_27872	32425	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27873	32426	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27874	32427	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27875	32428	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27876	32429	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27877	32430	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27878	32431	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27879	32432	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27880	32433	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27881	32434	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27882	32435	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27883	32436	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27884	32437	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27885	32438	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27886	32439	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27887	32440	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27888	32441	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27889	32442	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27890	32443	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27891	32444	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27892	32445	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27893	32446	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27894	32447	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27895	32448	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27896	32449	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27897	32450	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27898	32451	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27899	32452	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27900	32453	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27901	32454	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_27902	32455	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27903	32456	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500

DMS_27904	32457	N	N	N	1	CUSTOMER ISSUE	-
DMS_27905	32458	N	N	N	1	CUSTOMER ISSUE	-
DMS_27906	32459	N	N	N	1	CUSTOMER ISSUE	-
DMS_27907	32460	N	N	N	1	CUSTOMER ISSUE	-
DMS_27909	32461	N	N	N	1	CUSTOMER ISSUE	-
DMS_27910	32462	N	N	N	1	CUSTOMER ISSUE	-
DMS_27911	32463	N	N	N	1	CUSTOMER ISSUE	-
DMS_27912	32464	N	N	N	1	CUSTOMER ISSUE	-
DMS_27913	32465	N	N	N	1	CUSTOMER ISSUE	-
DMS_27914	32466	N	N	N	1	CUSTOMER ISSUE	-
DMS_27915	32467	N	N	N	1	CUSTOMER ISSUE	-
DMS_27916	32468	N	N	N	1	CUSTOMER ISSUE	-
DMS_27917	32469	N	N	N	1	CUSTOMER ISSUE	-
DMS_27918	32470	N	N	N	1	CUSTOMER ISSUE	-
DMS_27919	32471	N	N	N	1	CUSTOMER ISSUE	-
DMS_27920	32472	N	N	N	1	CUSTOMER ISSUE	-
DMS_27921	32473	N	N	N	1	CUSTOMER ISSUE	-
DMS_27922	32474	N	N	N	1	CUSTOMER ISSUE	-
DMS_27923	32475	N	N	N	1	CUSTOMER ISSUE	-
DMS_27924	32476	N	N	N	1	CUSTOMER ISSUE	-
DMS_27925	32477	N	N	N	1	CUSTOMER ISSUE	-
DMS_27926	32478	N	N	N	1	CUSTOMER ISSUE	-
DMS_27927	32479	N	N	N	1	CUSTOMER ISSUE	-
DMS_27928	32480	N	N	N	1	CUSTOMER ISSUE	-
DMS_27929	32481	N	N	N	1	CUSTOMER ISSUE	-
DMS_27930	32482	N	N	N	1	CUSTOMER ISSUE	-
DMS_27931	32483	N	N	N	1	CUSTOMER ISSUE	-
DMS_27932	32484	N	N	N	1	CUSTOMER ISSUE	-
DMS_27933	32485	N	N	N	1	CUSTOMER ISSUE	-
DMS_27934	32486	N	N	N	1	CUSTOMER ISSUE	-
DMS_27935	32487	N	N	N	1	CUSTOMER ISSUE	-
DMS_27936	32488	N	N	N	1	CUSTOMER ISSUE	-
DMS_27937	32489	N	N	N	1	CUSTOMER ISSUE	-
DMS_27938	32490	N	N	N	1	CUSTOMER ISSUE	-
DMS_27939	32491	N	N	N	1	CUSTOMER ISSUE	-
DMS_27940	32492	N	N	N	1	CUSTOMER ISSUE	-
DMS_27941	32493	N	N	N	1	CUSTOMER ISSUE	-
DMS_27942	32494	N	N	N	1	CUSTOMER ISSUE	-
DMS_27943	32495	N	N	N	1	CUSTOMER ISSUE	-
DMS_27944	32496	N	N	N	1	CUSTOMER ISSUE	-
DMS_27945	32497	N	N	N	1	CUSTOMER ISSUE	-
DMS_27946	32498	N	N	N	1	CUSTOMER ISSUE	-
DMS_27947	32499	N	N	N	1	CUSTOMER ISSUE	-
DMS_27948	32500	N	N	N	1	CUSTOMER ISSUE	-
DMS_27949	32501	N	N	N	1	CUSTOMER ISSUE	-
DMS_27950	32502	N	N	N	1	CUSTOMER ISSUE	-
DMS_27951	32503	N	N	N	1	CUSTOMER ISSUE	-
DMS_27952	32504	N	N	N	1	CUSTOMER ISSUE	-
DMS_27953	32505	N	N	N	1	CUSTOMER ISSUE	-
DMS_27954	32506	N	N	N	1	CUSTOMER ISSUE	-
DMS_27955	32507	N	N	N	1	CUSTOMER ISSUE	-
DMS_27956	32508	N	N	N	1	CUSTOMER ISSUE	-
DMS_27957	32509	N	N	N	1	CUSTOMER ISSUE	-
DMS_27958	32510	N	N	N	1	CUSTOMER ISSUE	-
DMS_27959	32511	N	N	N	1	CUSTOMER ISSUE	-
DMS_27960	32512	N	N	N	1	CUSTOMER ISSUE	-
DMS_27961	32513	N	N	N	1	CUSTOMER ISSUE	-
DMS_27962	32514	N	N	N	1	CUSTOMER ISSUE	-
DMS_27963	32515	N	N	N	1	CUSTOMER ISSUE	-
DMS_27964	32516	N	N	N	1	CUSTOMER ISSUE	-
DMS_27965	32517	N	N	N	2	CUSTOMER ISSUE	-
DMS_27966	32518	N	N	N	1	CUSTOMER ISSUE	-
DMS_27967	32519	N	N	N	1	CUSTOMER ISSUE	-
DMS_27968	32520	N	N	N	1	CUSTOMER ISSUE	-
DMS_27969	32521	N	N	N	1	CUSTOMER ISSUE	-
DMS_27970	32522	N	N	N	1	CUSTOMER ISSUE	-
DMS_27971	32523	N	N	N	1	CUSTOMER ISSUE	-
DMS_27972	32524	N	N	N	1	CUSTOMER ISSUE	-
DMS_27973	32525	N	N	N	1	CUSTOMER ISSUE	-
DMS_27974	32526	N	N	N	1	CUSTOMER ISSUE	-
DMS_27975	32527	N	N	N	1	CUSTOMER ISSUE	-
DMS_27976	32528	N	N	N	1	CUSTOMER ISSUE	-
DMS_27977	32529	N	N	N	1	CUSTOMER ISSUE	-
DMS_27978	32530	N	N	N	1	CUSTOMER ISSUE	-
DMS_27979	32531	N	N	N	1	CUSTOMER ISSUE	-
DMS_27980	32532	N	N	N	2	CUSTOMER ISSUE	-
DMS_27981	32533	N	N	N	1	CUSTOMER ISSUE	-
DMS_27982	32534	N	N	N	1	CUSTOMER ISSUE	-
DMS_27983	32535	N	N	N	1	CUSTOMER ISSUE	-
DMS_27984	32536	N	N	N	1	CUSTOMER ISSUE	-

DMS_27985	32537	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_27986	32538	N	N	N	1	CUSTOMER ISSUE	-
DMS_27987	32539	N	N	N	1	CUSTOMER ISSUE	-
DMS_27992	32540	N	N	N	1	CUSTOMER ISSUE	-
DMS_27993	32541	N	N	N	1	CUSTOMER ISSUE	-
DMS_27994	32542	N	N	N	1	CUSTOMER ISSUE	-
DMS_27995	32543	N	N	N	1	CUSTOMER ISSUE	-
DMS_27996	32544	N	N	N	1	CUSTOMER ISSUE	-
DMS_27997	32545	N	N	N	1	CUSTOMER ISSUE	-
DMS_28002	32546	N	N	N	1	CUSTOMER ISSUE	-
DMS_28004	32547	N	N	N	1	CUSTOMER ISSUE	-
DMS_28005	32548	N	N	N	1	CUSTOMER ISSUE	-
DMS_28006	32549	N	N	N	1	CUSTOMER ISSUE	-
DMS_28007	32550	N	N	N	1	CUSTOMER ISSUE	-
DMS_28008	32551	N	N	N	1	CUSTOMER ISSUE	-
DMS_28009	32552	N	N	N	1	CUSTOMER ISSUE	-
DMS_28020	32553	N	N	N	1	CUSTOMER ISSUE	-
DMS_28021	32554	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28022	32555	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28023	32556	N	N	N	1	CUSTOMER ISSUE	-
DMS_28024	32557	N	N	N	1	CUSTOMER ISSUE	-
DMS_28025	32558	N	N	N	1	CUSTOMER ISSUE	-
DMS_28027	32559	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28028	32560	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28029	32561	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28030	32562	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28031	32563	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28032	32564	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28033	32565	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28034	32566	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28035	32567	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28036	32568	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28037	32569	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28038	32570	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28039	32571	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28040	32572	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28041	32573	N	N	N	1	CUSTOMER ISSUE	-
DMS_28042	32574	N	N	N	1	CUSTOMER ISSUE	-
DMS_28043	32575	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28044	32576	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28045	32577	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28046	32578	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28047	32579	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28048	32580	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28049	32581	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28050	32582	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28051	32583	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28052	32584	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28053	32585	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28054	32586	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28055	32587	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28056	32588	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28057	32589	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28058	32590	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28059	32591	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28060	32592	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28061	32593	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28062	32594	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28063	32595	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28064	32596	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28065	32597	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28066	32598	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28067	32599	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28068	32600	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28069	32601	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28070	32602	N	N	N	1	CUSTOMER ISSUE	-
DMS_28071	32603	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28072	32604	N	N	N	1	CUSTOMER ISSUE	-
DMS_28073	32605	N	N	N	1	CUSTOMER ISSUE	-
DMS_28074	32606	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28075	32607	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28076	32608	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28077	32609	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28078	32610	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28079	32611	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28080	32612	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28081	32613	N	N	N	1	CUSTOMER ISSUE	-
DMS_28082	32614	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28083	32615	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28084	32616	N	N	N	1	CUSTOMER ISSUE	-

DMS_28085	32617	N	N	N	1	CUSTOMER ISSUE	-
DMS_28086	32618	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28087	32619	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28088	32620	N	N	N	1	CUSTOMER ISSUE	-
DMS_28089	32621	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28090	32622	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28091	32623	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28092	32624	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28093	32625	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28094	32626	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28095	32627	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28096	32628	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28097	32629	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28098	32630	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28099	32631	N	N	N	1	CUSTOMER ISSUE	-
DMS_28100	32632	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28101	32633	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28102	32634	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28103	32635	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28104	32636	N	N	Y	2	TX - REPLACE	2500
DMS_28105	32637	N	N	Y	1	TX - REPLACE	2500
DMS_28106	32638	N	N	Y	1	TX - REPLACE	2500
DMS_28107	32639	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28108	32640	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28109	32641	N	N	Y	1	TX - REPLACE	2500
DMS_28110	32642	N	N	Y	1	TX - REPLACE	2500
DMS_28111	32643	N	N	N	1	CUSTOMER ISSUE	-
DMS_28112	32644	N	N	Y	1	TX - REPLACE	2500
DMS_28113	32645	N	N	Y	1	TX - REPLACE	2500
DMS_28114	32646	N	N	N	1	CUSTOMER ISSUE	-
DMS_28115	32647	N	N	N	1	CUSTOMER ISSUE	-
DMS_28116	32648	N	N	N	1	CUSTOMER ISSUE	-
DMS_28118	32649	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28119	32650	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28120	32651	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28121	32652	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28124	32653	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28126	32654	N	N	N	1	CUSTOMER ISSUE	-
DMS_28127	32655	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28128	32656	N	N	Y	1	TX - REPLACE	2500
DMS_28129	32657	N	N	N	1	CUSTOMER ISSUE	-
DMS_28130	32658	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28131	32659	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28132	32660	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28133	32661	N	N	N	1	CUSTOMER ISSUE	-
DMS_28134	32662	N	N	N	1	CUSTOMER ISSUE	-
DMS_28135	32663	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28136	32664	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28137	32665	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28138	32666	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28139	32667	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28140	32668	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28141	32669	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28142	32670	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28143	32671	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28144	32672	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_28145	32673	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28146	32674	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28147	32675	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28148	32676	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28149	32677	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28150	32678	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28151	32679	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28152	32680	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28153	32681	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28154	32682	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28155	32683	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28156	32684	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28157	32685	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28158	32686	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28159	32687	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28160	32688	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28161	32689	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28162	32690	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28163	32691	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28164	32692	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28165	32693	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28166	32694	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28167	32695	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28168	32696	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_28169	32697	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28170	32698	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28171	32699	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28172	32700	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28173	32701	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28174	32702	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28175	32703	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28176	32704	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28177	32705	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28178	32706	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28179	32707	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28180	32708	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28181	32709	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28182	32710	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28183	32711	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28184	32712	N	N	N	1	CUSTOMER ISSUE	-
DMS_28185	32713	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28186	32714	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28187	32715	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28188	32716	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28189	32717	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28190	32718	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28191	32719	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28192	32720	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28193	32721	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28194	32722	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28195	32723	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_28196	32724	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28197	32725	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28198	32726	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28199	32727	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28200	32728	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28201	32729	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28202	32730	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28203	32731	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28204	32732	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28205	32733	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28206	32734	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28207	32735	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28208	32736	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28214	32737	N	N	N	1	CUSTOMER ISSUE	-
DMS_28215	32738	N	N	Y	1	TX - REPLACE	2500
DMS_28216	32739	N	N	Y	1	TX - REPLACE	2500
DMS_28217	32740	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28218	32741	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28219	32742	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28220	32743	N	N	N	1	CUSTOMER ISSUE	-
DMS_28221	32744	N	N	N	1	CUSTOMER ISSUE	-
DMS_28222	32745	N	N	Y	1	TX - REPLACE	2500
DMS_28223	32746	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
DMS_28224	32747	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28225	32748	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28226	32749	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28227	32750	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28228	32751	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28229	32752	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28230	32753	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28231	32754	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28232	32755	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28233	32756	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28234	32757	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28235	32758	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28236	32759	N	N	N	1	CUSTOMER ISSUE	-
DMS_28237	32760	N	N	N	1	CUSTOMER ISSUE	-
DMS_28238	32761	N	N	N	1	CUSTOMER ISSUE	-
DMS_28239	32762	N	N	N	1	CUSTOMER ISSUE	-
DMS_28240	32763	N	N	N	1	CUSTOMER ISSUE	-
DMS_28241	32764	N	N	N	1	CUSTOMER ISSUE	-
DMS_28242	32765	N	N	N	1	CUSTOMER ISSUE	-
DMS_28243	32766	N	N	N	1	CUSTOMER ISSUE	-
DMS_28244	32767	N	N	N	1	CUSTOMER ISSUE	-
DMS_28245	32768	N	N	N	1	CUSTOMER ISSUE	-
DMS_28246	32769	N	N	N	1	CUSTOMER ISSUE	-
DMS_28247	32770	N	N	N	1	CUSTOMER ISSUE	-
DMS_28248	32771	N	N	N	1	CUSTOMER ISSUE	-
DMS_28249	32772	N	N	Y	1	TX - REPLACE	2500
DMS_28250	32773	N	N	N	1	CUSTOMER ISSUE	-
DMS_28251	32774	N	N	N	1	CUSTOMER ISSUE	-
DMS_28252	32775	N	N	N	1	CUSTOMER ISSUE	-
DMS_28253	32776	N	N	N	1	CUSTOMER ISSUE	-

DMS_28254	32777	N	N	N	1	CUSTOMER ISSUE	-
DMS_28255	32778	N	N	Y	1	TX - REPLACE	2500
DMS_28256	32779	N	N	Y	1	TX - REPLACE	2500
DMS_28257	32780	N	N	Y	1	TX - REPLACE	2500
DMS_28258	32781	N	N	Y	1	TX - REPLACE	2500
DMS_28259	32782	N	N	Y	1	TX - REPLACE	2500
DMS_28260	32783	N	N	Y	1	TX - REPLACE	2500
DMS_28261	32784	N	N	Y	1	TX - REPLACE	2500
DMS_28262	32785	N	N	Y	1	TX - REPLACE	2500
DMS_28263	32786	N	N	Y	1	TX - REPLACE	2500
DMS_28264	32787	N	N	Y	1	TX - REPLACE	2500
DMS_28265	32788	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28266	32789	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_28267	32790	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28268	32791	N	N	Y	1	TX - REPLACE	2500
DMS_28269	32792	N	N	Y	1	TX - REPLACE	2500
DMS_28270	32793	N	N	Y	1	TX - REPLACE	2500
DMS_28271	32794	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_28272	32795	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_28273	32796	N	N	Y	1	TX - REPLACE	2500
DMS_28274	32797	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_28275	32798	N	N	Y	1	TX - REPLACE	2500
DMS_28276	32799	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28277	32800	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28278	32801	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28279	32802	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28280	32803	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28281	32804	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28282	32805	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28283	32806	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28285	32807	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28286	32808	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28287	32809	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28288	32810	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28289	32811	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28290	32812	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28291	32813	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28292	32814	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28293	32815	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28294	32816	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28295	32817	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28296	32818	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28297	32819	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28298	32820	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28299	32821	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28300	32822	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28301	32823	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28302	32824	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28303	32825	N	N	Y	1	TX - REPLACE	2500
DMS_28304	32826	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28306	32827	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28307	32828	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28308	32829	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28309	32830	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28310	32831	N	N	N	1	CUSTOMER ISSUE	-
DMS_28311	32832	N	N	N	1	CUSTOMER ISSUE	-
DMS_28312	32833	N	N	N	1	CUSTOMER ISSUE	-
DMS_28313	32834	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28314	32835	N	N	N	1	CUSTOMER ISSUE	-
DMS_28315	32836	N	N	N	1	CUSTOMER ISSUE	-
DMS_28316	32837	N	N	N	1	CUSTOMER ISSUE	-
DMS_28317	32838	N	N	Y	1	TX - REPLACE	2500
DMS_28318	32839	N	N	Y	1	TX - REPLACE	2500
DMS_28319	32840	N	N	Y	1	TX - REPLACE	2500
DMS_28320	32841	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_28321	32842	N	N	N	1	CUSTOMER ISSUE	-
DMS_28322	32843	N	N	N	1	CUSTOMER ISSUE	-
DMS_28323	32844	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_28324	32845	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_28325	32846	N	N	N	1	CUSTOMER ISSUE	-
DMS_28326	32847	N	N	N	1	CUSTOMER ISSUE	-
DMS_28327	32848	N	N	N	1	CUSTOMER ISSUE	-
DMS_28328	32849	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28329	32850	N	N	N	1	CUSTOMER ISSUE	-
DMS_28331	32851	N	N	N	1	CUSTOMER ISSUE	-
DMS_28332	32852	N	N	N	1	CUSTOMER ISSUE	-
DMS_28334	32853	N	N	N	1	CUSTOMER ISSUE	-
DMS_28335	32854	N	N	N	1	CUSTOMER ISSUE	-
DMS_28336	32855	N	N	N	1	CUSTOMER ISSUE	-
DMS_28337	32856	N	N	N	1	CUSTOMER ISSUE	-

DMS_28338	32857	N	N	N	1	CUSTOMER ISSUE	-
DMS_28339	32858	N	N	N	1	CUSTOMER ISSUE	-
DMS_28340	32859	N	N	N	1	CUSTOMER ISSUE	-
DMS_28341	32860	N	N	N	1	CUSTOMER ISSUE	-
DMS_28342	32861	N	N	N	1	CUSTOMER ISSUE	-
DMS_28344	32862	N	N	N	1	CUSTOMER ISSUE	-
DMS_28345	32863	N	N	N	1	CUSTOMER ISSUE	-
DMS_28346	32864	N	N	N	1	CUSTOMER ISSUE	-
DMS_28347	32865	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28348	32866	N	N	N	1	CUSTOMER ISSUE	-
DMS_28349	32867	N	N	N	1	CUSTOMER ISSUE	-
DMS_28350	32868	N	N	N	1	CUSTOMER ISSUE	-
DMS_28351	32869	N	N	N	1	CUSTOMER ISSUE	-
DMS_28353	32870	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28354	32871	N	N	N	1	CUSTOMER ISSUE	-
DMS_28355	32872	N	N	N	1	CUSTOMER ISSUE	-
DMS_28356	32873	N	N	N	1	CUSTOMER ISSUE	-
DMS_28357	32874	N	N	N	1	CUSTOMER ISSUE	-
DMS_28358	32875	N	N	N	1	CUSTOMER ISSUE	-
DMS_28359	32876	N	N	N	1	CUSTOMER ISSUE	-
DMS_28360	32877	N	N	N	1	CUSTOMER ISSUE	-
DMS_28361	32878	N	N	N	1	CUSTOMER ISSUE	-
DMS_28364	32879	N	N	N	1	CUSTOMER ISSUE	-
DMS_28365	32880	N	N	N	1	CUSTOMER ISSUE	-
DMS_28366	32881	N	N	N	1	CUSTOMER ISSUE	-
DMS_28367	32882	N	N	N	1	CUSTOMER ISSUE	-
DMS_28368	32883	N	N	N	1	CUSTOMER ISSUE	-
DMS_28370	32884	N	N	N	1	CUSTOMER ISSUE	-
DMS_28371	32885	N	N	N	1	CUSTOMER ISSUE	-
DMS_28372	32886	N	N	N	1	CUSTOMER ISSUE	-
DMS_28373	32887	N	N	N	1	CUSTOMER ISSUE	-
DMS_28374	32888	N	N	N	1	CUSTOMER ISSUE	-
DMS_28375	32889	N	N	N	1	CUSTOMER ISSUE	-
DMS_28376	32890	N	N	N	1	CUSTOMER ISSUE	-
DMS_28377	32891	N	N	N	1	CUSTOMER ISSUE	-
DMS_28378	32892	N	N	N	1	CUSTOMER ISSUE	-
DMS_28379	32893	N	N	N	1	CUSTOMER ISSUE	-
DMS_28380	32894	N	N	N	1	CUSTOMER ISSUE	-
DMS_28381	32895	N	N	N	1	CUSTOMER ISSUE	-
DMS_28382	32896	N	N	N	1	CUSTOMER ISSUE	-
DMS_28383	32897	N	N	N	1	CUSTOMER ISSUE	-
DMS_28384	32898	N	N	N	1	CUSTOMER ISSUE	-
DMS_28385	32899	N	N	N	1	CUSTOMER ISSUE	-
DMS_28386	32900	N	N	N	1	CUSTOMER ISSUE	-
DMS_28387	32901	N	N	N	1	CUSTOMER ISSUE	-
DMS_28388	32902	N	N	N	1	CUSTOMER ISSUE	-
DMS_28389	32903	N	N	N	1	CUSTOMER ISSUE	-
DMS_28390	32904	N	N	N	1	CUSTOMER ISSUE	-
DMS_28391	32905	N	N	N	1	CUSTOMER ISSUE	-
DMS_28393	32906	N	N	N	1	CUSTOMER ISSUE	-
DMS_28394	32907	N	N	N	1	CUSTOMER ISSUE	-
DMS_28395	32908	N	N	N	1	CUSTOMER ISSUE	-
DMS_28396	32909	N	N	N	1	CUSTOMER ISSUE	-
DMS_28397	32910	N	N	N	1	CUSTOMER ISSUE	-
DMS_28398	32911	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28399	32912	N	N	N	1	CUSTOMER ISSUE	-
DMS_28400	32913	N	N	N	1	CUSTOMER ISSUE	-
DMS_28401	32914	N	N	N	1	CUSTOMER ISSUE	-
DMS_28402	32915	N	N	N	1	CUSTOMER ISSUE	-
DMS_28403	32916	N	N	N	1	CUSTOMER ISSUE	-
DMS_28404	32917	N	N	N	1	CUSTOMER ISSUE	-
DMS_28405	32918	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_28406	32919	N	N	N	1	CUSTOMER ISSUE	-
DMS_28407	32920	N	N	N	1	CUSTOMER ISSUE	-
DMS_28408	32921	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28409	32922	N	N	N	1	CUSTOMER ISSUE	-
DMS_28410	32923	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28411	32924	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28412	32925	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28413	32926	N	N	N	1	CUSTOMER ISSUE	-
DMS_28414	32927	N	N	N	1	CUSTOMER ISSUE	-
DMS_28415	32928	N	N	N	1	CUSTOMER ISSUE	-
DMS_28416	32929	N	N	N	1	CUSTOMER ISSUE	-
DMS_28417	32930	N	N	N	1	CUSTOMER ISSUE	-
DMS_28418	32931	N	N	N	1	CUSTOMER ISSUE	-
DMS_28420	32932	N	N	N	1	CUSTOMER ISSUE	-
DMS_28421	32933	N	N	N	1	CUSTOMER ISSUE	-
DMS_28422	32934	N	N	N	1	CUSTOMER ISSUE	-
DMS_28423	32935	N	N	N	1	CUSTOMER ISSUE	-
DMS_28424	32936	N	N	N	1	CUSTOMER ISSUE	-

DMS_28425	32937	N	N	N	1	CUSTOMER ISSUE	-
DMS_28426	32938	N	N	N	1	CUSTOMER ISSUE	-
DMS_28428	32939	N	N	N	1	CUSTOMER ISSUE	-
DMS_28429	32940	N	N	N	1	CUSTOMER ISSUE	-
DMS_28430	32941	N	N	N	1	CUSTOMER ISSUE	-
DMS_28432	32942	N	N	N	1	CUSTOMER ISSUE	-
DMS_28435	32943	N	N	N	1	CUSTOMER ISSUE	-
DMS_28436	32944	N	N	N	1	CUSTOMER ISSUE	-
DMS_28437	32945	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28442	32946	N	N	N	1	CUSTOMER ISSUE	-
DMS_28443	32947	N	N	N	1	CUSTOMER ISSUE	-
DMS_28444	32948	N	N	N	1	CUSTOMER ISSUE	-
DMS_28445	32949	N	N	N	1	CUSTOMER ISSUE	-
DMS_28446	32950	N	N	N	1	CUSTOMER ISSUE	-
DMS_28447	32951	N	N	N	1	CUSTOMER ISSUE	-
DMS_28448	32952	N	N	N	1	CUSTOMER ISSUE	-
DMS_28449	32953	N	N	N	1	CUSTOMER ISSUE	-
DMS_28450	32954	N	N	N	1	CUSTOMER ISSUE	-
DMS_28451	32955	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28452	32956	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28453	32957	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28454	32958	N	N	N	1	CUSTOMER ISSUE	-
DMS_28457	32959	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28458	32960	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28459	32961	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28460	32962	N	N	Y	1	TX - REPLACE	2500
DMS_28461	32963	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28462	32964	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28463	32965	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28464	32966	N	N	N	1	CUSTOMER ISSUE	-
DMS_28471	32967	N	N	N	1	CUSTOMER ISSUE	-
DMS_28477	32968	N	N	N	1	CUSTOMER ISSUE	-
DMS_28479	32969	N	N	N	1	CUSTOMER ISSUE	-
DMS_28483	32970	N	N	N	1	CUSTOMER ISSUE	-
DMS_28484	32971	N	N	N	1	CUSTOMER ISSUE	-
DMS_28485	32972	N	N	N	1	CUSTOMER ISSUE	-
DMS_28486	32973	N	N	N	1	CUSTOMER ISSUE	-
DMS_28487	32974	N	N	N	1	CUSTOMER ISSUE	-
DMS_28488	32975	N	N	N	1	CUSTOMER ISSUE	-
DMS_28492	32976	N	N	N	1	CUSTOMER ISSUE	-
DMS_28493	32977	N	N	N	1	CUSTOMER ISSUE	-
DMS_28496	32978	N	N	N	1	CUSTOMER ISSUE	-
DMS_28497	32979	N	N	N	1	CUSTOMER ISSUE	-
DMS_28498	32980	N	N	N	1	CUSTOMER ISSUE	-
DMS_28500	32981	N	N	N	1	CUSTOMER ISSUE	-
DMS_28501	32982	N	N	N	1	CUSTOMER ISSUE	-
DMS_28502	32983	N	N	N	1	CUSTOMER ISSUE	-
DMS_28503	32984	N	N	N	1	CUSTOMER ISSUE	-
DMS_28507	32985	N	N	N	1	CUSTOMER ISSUE	-
DMS_28523	32986	N	N	N	1	CUSTOMER ISSUE	-
DMS_28525	32987	N	N	N	1	CUSTOMER ISSUE	-
DMS_28528	32988	N	N	N	1	CUSTOMER ISSUE	-
DMS_28529	32989	N	N	N	1	CUSTOMER ISSUE	-
DMS_28531	32990	N	N	N	1	CUSTOMER ISSUE	-
DMS_28532	32991	N	N	N	1	CUSTOMER ISSUE	-
DMS_28533	32992	N	N	N	1	CUSTOMER ISSUE	-
DMS_28535	32993	N	N	N	1	CUSTOMER ISSUE	-
DMS_28536	32994	N	N	N	1	CUSTOMER ISSUE	-
DMS_28538	32995	N	N	N	1	CUSTOMER ISSUE	-
DMS_28539	32996	N	N	N	1	CUSTOMER ISSUE	-
DMS_28540	32997	N	N	N	1	CUSTOMER ISSUE	-
DMS_28555	32998	N	N	N	1	CUSTOMER ISSUE	-
DMS_28558	32999	N	N	N	1	CUSTOMER ISSUE	-
DMS_28559	33000	N	N	N	1	CUSTOMER ISSUE	-
DMS_28560	33001	N	N	N	1	CUSTOMER ISSUE	-
DMS_28561	33002	N	N	N	1	CUSTOMER ISSUE	-
DMS_28562	33003	N	N	N	1	CUSTOMER ISSUE	-
DMS_28563	33004	N	N	N	1	CUSTOMER ISSUE	-
DMS_28564	33005	N	N	N	1	CUSTOMER ISSUE	-
DMS_28566	33006	N	N	N	1	CUSTOMER ISSUE	-
DMS_28567	33007	N	N	N	1	CUSTOMER ISSUE	-
DMS_28568	33008	N	N	N	1	CUSTOMER ISSUE	-
DMS_28569	33009	N	N	N	1	CUSTOMER ISSUE	-
DMS_28570	33010	N	N	N	1	CUSTOMER ISSUE	-
DMS_28572	33011	N	N	N	1	CUSTOMER ISSUE	-
DMS_28573	33012	N	N	N	1	CUSTOMER ISSUE	-
DMS_28574	33013	N	N	N	1	CUSTOMER ISSUE	-
DMS_28576	33014	N	N	N	1	CUSTOMER ISSUE	-
DMS_28577	33015	N	N	N	1	CUSTOMER ISSUE	-
DMS_28578	33016	N	N	N	1	CUSTOMER ISSUE	-

DMS_28579	33017	N	N	N	1	CUSTOMER ISSUE	-
DMS_28580	33018	N	N	N	1	CUSTOMER ISSUE	-
DMS_28581	33019	N	N	N	1	CUSTOMER ISSUE	-
DMS_28583	33020	N	N	N	1	CUSTOMER ISSUE	-
DMS_28584	33021	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28585	33022	N	N	N	1	CUSTOMER ISSUE	-
DMS_28590	33023	N	N	N	1	CUSTOMER ISSUE	-
DMS_28591	33024	N	N	N	1	CUSTOMER ISSUE	-
DMS_28592	33025	N	N	N	1	CUSTOMER ISSUE	-
DMS_28593	33026	N	N	N	1	CUSTOMER ISSUE	-
DMS_28594	33027	N	N	N	1	CUSTOMER ISSUE	-
DMS_28595	33028	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28597	33029	N	N	N	1	CUSTOMER ISSUE	-
DMS_28598	33030	N	N	N	1	CUSTOMER ISSUE	-
DMS_28599	33031	N	N	N	1	CUSTOMER ISSUE	-
DMS_28600	33032	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28601	33033	N	N	N	1	CUSTOMER ISSUE	-
DMS_28602	33034	N	N	N	1	CUSTOMER ISSUE	-
DMS_28603	33035	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28605	33036	N	N	N	1	CUSTOMER ISSUE	-
DMS_28606	33037	N	N	N	1	CUSTOMER ISSUE	-
DMS_28607	33038	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28608	33039	N	N	N	1	CUSTOMER ISSUE	-
DMS_28609	33040	N	N	N	1	CUSTOMER ISSUE	-
DMS_28610	33041	N	N	N	1	CUSTOMER ISSUE	-
DMS_28611	33042	N	N	N	1	CUSTOMER ISSUE	-
DMS_28612	33043	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28613	33044	N	N	N	1	CUSTOMER ISSUE	-
DMS_28614	33045	N	N	N	1	CUSTOMER ISSUE	-
DMS_28615	33046	N	N	N	1	CUSTOMER ISSUE	-
DMS_28616	33047	N	N	N	1	CUSTOMER ISSUE	-
DMS_28617	33048	N	N	N	1	CUSTOMER ISSUE	-
DMS_28618	33049	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28620	33050	N	N	N	1	CUSTOMER ISSUE	-
DMS_28621	33051	N	N	N	1	CUSTOMER ISSUE	-
DMS_28622	33052	N	N	N	1	CUSTOMER ISSUE	-
DMS_28632	33053	N	N	N	1	CUSTOMER ISSUE	-
DMS_28633	33054	N	N	N	1	CUSTOMER ISSUE	-
DMS_28634	33055	N	N	N	1	CUSTOMER ISSUE	-
DMS_28635	33056	N	N	N	1	CUSTOMER ISSUE	-
DMS_28636	33057	N	N	N	1	CUSTOMER ISSUE	-
DMS_28638	33058	N	N	N	1	CUSTOMER ISSUE	-
DMS_28639	33059	N	N	N	1	CUSTOMER ISSUE	-
DMS_28644	33060	N	N	N	1	CUSTOMER ISSUE	-
DMS_28646	33061	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28647	33062	N	N	N	2	CUSTOMER ISSUE	-
DMS_28649	33063	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28650	33064	N	N	N	1	CUSTOMER ISSUE	-
DMS_28651	33065	N	N	N	1	CUSTOMER ISSUE	-
DMS_28652	33066	N	N	N	1	CUSTOMER ISSUE	-
DMS_28653	33067	N	N	N	1	CUSTOMER ISSUE	-
DMS_28654	33068	N	N	N	2	CUSTOMER ISSUE	-
DMS_28656	33069	N	N	N	1	CUSTOMER ISSUE	-
DMS_28662	33070	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28663	33071	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28664	33072	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28665	33073	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28666	33074	N	N	N	1	CUSTOMER ISSUE	-
DMS_28668	33075	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28675	33076	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28681	33077	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28682	33078	N	N	N	1	CUSTOMER ISSUE	-
DMS_28689	33079	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28698	33080	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28699	33081	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28700	33082	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28701	33083	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28702	33084	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28707	33085	N	N	N	1	CUSTOMER ISSUE	-
DMS_28708	33086	N	N	N	1	CUSTOMER ISSUE	-
DMS_28709	33087	N	N	N	1	CUSTOMER ISSUE	-
DMS_28710	33088	N	N	N	1	CUSTOMER ISSUE	-
DMS_28713	33089	N	N	N	1	CUSTOMER ISSUE	-
DMS_28714	33090	N	N	N	1	CUSTOMER ISSUE	-
DMS_28716	33091	N	N	N	1	CUSTOMER ISSUE	-
DMS_28717	33092	N	N	N	1	CUSTOMER ISSUE	-
DMS_28720	33093	N	N	N	1	CUSTOMER ISSUE	-
DMS_28721	33094	N	N	N	1	CUSTOMER ISSUE	-
DMS_28723	33095	N	N	N	1	CUSTOMER ISSUE	-
DMS_28724	33096	N	N	N	1	CUSTOMER ISSUE	-

DMS_28725	33097	N	N	N	1	CUSTOMER ISSUE	-
DMS_28734	33098	N	N	N	1	CUSTOMER ISSUE	-
DMS_28735	33099	N	N	N	1	CUSTOMER ISSUE	-
DMS_28736	33100	N	N	N	1	CUSTOMER ISSUE	-
DMS_28739	33101	N	N	N	1	CUSTOMER ISSUE	-
DMS_28740	33102	N	N	N	1	CUSTOMER ISSUE	-
DMS_28741	33103	N	N	N	1	CUSTOMER ISSUE	-
DMS_28743	33104	N	N	N	1	CUSTOMER ISSUE	-
DMS_28753	33105	N	N	N	1	CUSTOMER ISSUE	-
DMS_28754	33106	N	N	N	1	CUSTOMER ISSUE	-
DMS_28755	33107	N	N	N	1	CUSTOMER ISSUE	-
DMS_28756	33108	N	N	N	1	CUSTOMER ISSUE	-
DMS_28757	33109	N	N	N	1	CUSTOMER ISSUE	-
DMS_28758	33110	N	N	N	1	CUSTOMER ISSUE	-
DMS_28759	33111	N	N	N	1	CUSTOMER ISSUE	-
DMS_28764	33112	N	N	N	1	CUSTOMER ISSUE	-
DMS_28765	33113	N	N	N	1	CUSTOMER ISSUE	-
DMS_28766	33114	N	N	N	1	CUSTOMER ISSUE	-
DMS_28768	33115	N	N	N	1	CUSTOMER ISSUE	-
DMS_28769	33116	N	N	N	1	CUSTOMER ISSUE	-
DMS_28770	33117	N	N	N	1	CUSTOMER ISSUE	-
DMS_28771	33118	N	N	N	1	CUSTOMER ISSUE	-
DMS_28772	33119	N	N	N	1	CUSTOMER ISSUE	-
DMS_28773	33120	N	N	N	1	CUSTOMER ISSUE	-
DMS_28774	33121	N	N	N	1	CUSTOMER ISSUE	-
DMS_28775	33122	N	N	N	1	CUSTOMER ISSUE	-
DMS_28776	33123	N	N	N	1	CUSTOMER ISSUE	-
DMS_28777	33124	N	N	N	1	CUSTOMER ISSUE	-
DMS_28778	33125	N	N	N	1	CUSTOMER ISSUE	-
DMS_28779	33126	N	N	N	1	CUSTOMER ISSUE	-
DMS_28781	33127	N	N	N	1	CUSTOMER ISSUE	-
DMS_28782	33128	N	N	N	1	CUSTOMER ISSUE	-
DMS_28783	33129	N	N	N	1	CUSTOMER ISSUE	-
DMS_28808	33130	N	N	N	1	CUSTOMER ISSUE	-
DMS_28816	33131	N	N	N	1	CUSTOMER ISSUE	-
DMS_28840	33132	N	N	N	1	CUSTOMER ISSUE	-
DMS_28844	33133	N	N	N	1	CUSTOMER ISSUE	-
DMS_28845	33134	N	N	N	1	CUSTOMER ISSUE	-
DMS_28862	33135	N	N	N	1	CUSTOMER ISSUE	-
DMS_28864	33136	N	N	N	1	CUSTOMER ISSUE	-
DMS_28867	33137	N	N	N	1	CUSTOMER ISSUE	-
DMS_28870	33138	N	N	N	1	CUSTOMER ISSUE	-
DMS_28879	33139	N	N	N	1	CUSTOMER ISSUE	-
DMS_28881	33140	N	N	N	1	CUSTOMER ISSUE	-
DMS_28882	33141	N	N	N	1	CUSTOMER ISSUE	-
DMS_28883	33142	N	N	N	2	CUSTOMER ISSUE	-
DMS_28884	33143	N	N	N	1	CUSTOMER ISSUE	-
DMS_28885	33144	N	N	N	1	CUSTOMER ISSUE	-
DMS_28886	33145	N	N	N	1	CUSTOMER ISSUE	-
DMS_28889	33146	N	N	N	1	CUSTOMER ISSUE	-
DMS_28890	33147	N	N	N	1	CUSTOMER ISSUE	-
DMS_28892	33148	N	N	N	1	CUSTOMER ISSUE	-
DMS_28894	33149	N	N	N	1	CUSTOMER ISSUE	-
DMS_28895	33150	N	N	N	1	CUSTOMER ISSUE	-
DMS_28896	33151	N	N	N	1	CUSTOMER ISSUE	-
DMS_28907	33152	N	N	N	1	CUSTOMER ISSUE	-
DMS_28908	33153	N	N	N	1	CUSTOMER ISSUE	-
DMS_28909	33154	N	N	N	1	CUSTOMER ISSUE	-
DMS_28910	33155	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28913	33156	N	N	N	1	CUSTOMER ISSUE	-
DMS_28914	33157	N	N	N	1	CUSTOMER ISSUE	-
DMS_28915	33158	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28916	33159	N	N	N	1	CUSTOMER ISSUE	-
DMS_28917	33160	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28919	33161	N	N	N	1	CUSTOMER ISSUE	-
DMS_28920	33162	N	N	N	1	CUSTOMER ISSUE	-
DMS_28926	33163	N	N	N	1	CUSTOMER ISSUE	-
DMS_28927	33164	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28928	33165	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28929	33166	N	N	N	1	CUSTOMER ISSUE	-
DMS_28930	33167	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28931	33168	N	N	N	1	CUSTOMER ISSUE	-
DMS_28932	33169	N	N	N	1	CUSTOMER ISSUE	-
DMS_28933	33170	N	N	N	1	CUSTOMER ISSUE	-
DMS_28934	33171	N	N	N	1	CUSTOMER ISSUE	-
DMS_28935	33172	N	N	N	1	CUSTOMER ISSUE	-
DMS_28937	33173	N	N	N	1	CUSTOMER ISSUE	-
DMS_28938	33174	N	N	N	1	CUSTOMER ISSUE	-
DMS_28939	33175	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28940	33176	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_28941	33177	N	N	N	1	CUSTOMER ISSUE	-
DMS_28942	33178	N	N	N	1	CUSTOMER ISSUE	-
DMS_28943	33179	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28945	33180	N	N	N	1	CUSTOMER ISSUE	-
DMS_28946	33181	N	N	N	1	CUSTOMER ISSUE	-
DMS_28947	33182	N	N	N	1	CUSTOMER ISSUE	-
DMS_28948	33183	N	N	N	1	CUSTOMER ISSUE	-
DMS_28949	33184	N	N	N	1	CUSTOMER ISSUE	-
DMS_28951	33185	N	N	N	1	CUSTOMER ISSUE	-
DMS_28952	33186	N	N	N	1	CUSTOMER ISSUE	-
DMS_28953	33187	N	N	N	1	CUSTOMER ISSUE	-
DMS_28954	33188	N	N	N	1	CUSTOMER ISSUE	-
DMS_28955	33189	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28956	33190	N	N	N	2	CUSTOMER ISSUE	-
DMS_28958	33191	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_28960	33192	N	N	N	1	CUSTOMER ISSUE	-
DMS_28964	33193	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28966	33194	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28967	33195	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28971	33196	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28972	33197	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28973	33198	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28974	33199	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28975	33200	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28976	33201	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_28978	33202	N	N	N	1	CUSTOMER ISSUE	-
DMS_28980	33203	N	N	N	1	CUSTOMER ISSUE	-
DMS_28981	33204	N	N	N	1	CUSTOMER ISSUE	-
DMS_28982	33205	N	N	N	1	CUSTOMER ISSUE	-
DMS_28986	33206	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28987	33207	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_28988	33208	N	N	N	1	CUSTOMER ISSUE	-
DMS_28989	33209	N	N	N	1	CUSTOMER ISSUE	-
DMS_28990	33210	N	N	N	1	CUSTOMER ISSUE	-
DMS_28991	33211	N	N	N	1	CUSTOMER ISSUE	-
DMS_28992	33212	N	N	N	1	CUSTOMER ISSUE	-
DMS_28993	33213	N	N	N	1	CUSTOMER ISSUE	-
DMS_28994	33214	N	N	N	1	CUSTOMER ISSUE	-
DMS_28995	33215	N	N	N	1	CUSTOMER ISSUE	-
DMS_28996	33216	N	N	N	1	CUSTOMER ISSUE	-
DMS_28997	33217	N	N	N	1	CUSTOMER ISSUE	-
DMS_28998	33218	N	N	N	1	CUSTOMER ISSUE	-
DMS_28999	33219	N	N	N	1	CUSTOMER ISSUE	-
DMS_29000	33220	N	N	N	1	CUSTOMER ISSUE	-
DMS_29001	33221	N	N	N	1	CUSTOMER ISSUE	-
DMS_29004	33222	N	N	N	1	CUSTOMER ISSUE	-
DMS_29007	33223	N	N	N	1	CUSTOMER ISSUE	-
DMS_29009	33224	N	N	N	1	CUSTOMER ISSUE	-
DMS_29018	33225	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29019	33226	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29032	33227	N	N	N	1	CUSTOMER ISSUE	-
DMS_29039	33228	N	N	N	1	CUSTOMER ISSUE	-
DMS_29058	33229	N	N	N	1	CUSTOMER ISSUE	-
DMS_29059	33230	N	N	N	1	CUSTOMER ISSUE	-
DMS_29060	33231	N	N	N	1	CUSTOMER ISSUE	-
DMS_29061	33232	N	N	N	1	CUSTOMER ISSUE	-
DMS_29062	33233	N	N	N	1	CUSTOMER ISSUE	-
DMS_29063	33234	N	N	N	1	CUSTOMER ISSUE	-
DMS_29064	33235	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29065	33236	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29066	33237	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29068	33238	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29069	33239	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29071	33240	N	N	N	1	CUSTOMER ISSUE	-
DMS_29072	33241	N	N	N	1	CUSTOMER ISSUE	-
DMS_29073	33242	N	N	N	1	CUSTOMER ISSUE	-
DMS_29074	33243	N	N	N	1	CUSTOMER ISSUE	-
DMS_29075	33244	N	N	N	1	CUSTOMER ISSUE	-
DMS_29076	33245	N	N	N	1	CUSTOMER ISSUE	-
DMS_29077	33246	N	N	N	1	CUSTOMER ISSUE	-
DMS_29078	33247	N	N	N	1	CUSTOMER ISSUE	-
DMS_29080	33248	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29081	33249	N	N	N	1	CUSTOMER ISSUE	-
DMS_29083	33250	N	N	N	1	CUSTOMER ISSUE	-
DMS_29085	33251	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29086	33252	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29087	33253	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29089	33254	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29091	33255	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29093	33256	N	N	N	1	CUSTOMER ISSUE	-

DMS_29094	33257	N	N	N	1	CUSTOMER ISSUE	-
DMS_29095	33258	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29096	33259	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29098	33260	N	N	N	1	CUSTOMER ISSUE	-
DMS_29099	33261	N	N	N	1	CUSTOMER ISSUE	-
DMS_29100	33262	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29101	33263	N	N	N	1	CUSTOMER ISSUE	-
DMS_29102	33264	N	N	N	1	CUSTOMER ISSUE	-
DMS_29104	33265	N	N	N	1	CUSTOMER ISSUE	-
DMS_29106	33266	N	N	N	1	CUSTOMER ISSUE	-
DMS_29107	33267	N	N	N	1	CUSTOMER ISSUE	-
DMS_29108	33268	N	N	N	1	CUSTOMER ISSUE	-
DMS_29109	33269	N	N	N	1	CUSTOMER ISSUE	-
DMS_29110	33270	N	N	N	1	CUSTOMER ISSUE	-
DMS_29111	33271	N	N	N	1	CUSTOMER ISSUE	-
DMS_29112	33272	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29113	33273	N	N	N	1	CUSTOMER ISSUE	-
DMS_29114	33274	N	N	N	1	CUSTOMER ISSUE	-
DMS_29115	33275	N	N	N	1	CUSTOMER ISSUE	-
DMS_29116	33276	N	N	N	1	CUSTOMER ISSUE	-
DMS_29117	33277	N	N	N	1	CUSTOMER ISSUE	-
DMS_29118	33278	N	N	N	1	CUSTOMER ISSUE	-
DMS_29119	33279	N	N	N	1	CUSTOMER ISSUE	-
DMS_29120	33280	N	N	N	1	CUSTOMER ISSUE	-
DMS_29121	33281	N	N	N	1	CUSTOMER ISSUE	-
DMS_29122	33282	N	N	N	1	CUSTOMER ISSUE	-
DMS_29123	33283	N	N	N	1	CUSTOMER ISSUE	-
DMS_29130	33284	N	N	N	1	CUSTOMER ISSUE	-
DMS_29131	33285	N	N	N	1	CUSTOMER ISSUE	-
DMS_29132	33286	N	N	N	1	CUSTOMER ISSUE	-
DMS_29133	33287	N	N	N	1	CUSTOMER ISSUE	-
DMS_29134	33288	N	N	N	1	CUSTOMER ISSUE	-
DMS_29135	33289	N	N	N	1	CUSTOMER ISSUE	-
DMS_29136	33290	N	N	N	1	CUSTOMER ISSUE	-
DMS_29137	33291	N	N	N	1	CUSTOMER ISSUE	-
DMS_29140	33292	N	N	N	1	CUSTOMER ISSUE	-
DMS_29144	33293	N	N	N	1	CUSTOMER ISSUE	-
DMS_29145	33294	N	N	N	1	CUSTOMER ISSUE	-
DMS_29148	33295	N	N	N	1	CUSTOMER ISSUE	-
DMS_29151	33296	N	N	N	1	CUSTOMER ISSUE	-
DMS_29153	33297	N	N	N	1	CUSTOMER ISSUE	-
DMS_29154	33298	N	N	N	1	CUSTOMER ISSUE	-
DMS_29155	33299	N	N	N	1	CUSTOMER ISSUE	-
DMS_29156	33300	N	N	N	1	CUSTOMER ISSUE	-
DMS_29158	33301	N	N	N	1	CUSTOMER ISSUE	-
DMS_29159	33302	N	N	N	1	CUSTOMER ISSUE	-
DMS_29160	33303	N	N	N	1	CUSTOMER ISSUE	-
DMS_29161	33304	N	N	N	1	CUSTOMER ISSUE	-
DMS_29162	33305	N	N	N	1	CUSTOMER ISSUE	-
DMS_29164	33306	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29167	33307	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29168	33308	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29169	33309	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_29171	33310	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29172	33311	N	N	N	1	CUSTOMER ISSUE	-
DMS_29173	33312	N	N	N	1	CUSTOMER ISSUE	-
DMS_29174	33313	N	N	N	1	CUSTOMER ISSUE	-
DMS_29175	33314	N	N	N	1	CUSTOMER ISSUE	-
DMS_29176	33315	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29177	33316	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29178	33317	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29179	33318	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29180	33319	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29181	33320	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29182	33321	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29183	33322	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29184	33323	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29185	33324	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29186	33325	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29187	33326	N	N	N	1	CUSTOMER ISSUE	-
DMS_29188	33327	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29189	33328	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29190	33329	N	N	N	1	CUSTOMER ISSUE	-
DMS_29191	33330	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29192	33331	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29194	33332	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29195	33333	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29198	33334	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_29203	33335	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29205	33336	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_29206	33337	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29207	33338	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29210	33339	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29212	33340	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_29213	33341	N	N	N	1	CUSTOMER ISSUE	-
DMS_29214	33342	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29217	33343	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29219	33344	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_29225	33345	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29227	33346	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29228	33347	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29229	33348	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29234	33349	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29235	33350	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29237	33351	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29238	33352	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29239	33353	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29240	33354	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29241	33355	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29242	33356	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29243	33357	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29244	33358	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29249	33359	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29250	33360	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29252	33361	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29254	33362	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29255	33363	N	N	N	1	CUSTOMER ISSUE	-
DMS_29256	33364	N	N	N	1	CUSTOMER ISSUE	-
DMS_29257	33365	N	N	Y	1	TX - REPLACE	2500
DMS_29259	33366	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29260	33367	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29261	33368	N	N	Y	1	TX - REPLACE	2500
DMS_29262	33369	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29264	33370	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29265	33371	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_29266	33372	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29267	33373	N	N	N	1	CUSTOMER ISSUE	-
DMS_29268	33374	N	N	N	1	CUSTOMER ISSUE	-
DMS_29269	33375	N	N	N	1	CUSTOMER ISSUE	-
DMS_29270	33376	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29271	33377	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29272	33378	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29274	33379	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29275	33380	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29277	33381	N	N	N	1	CUSTOMER ISSUE	-
DMS_29280	33382	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29281	33383	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29284	33384	N	N	N	1	CUSTOMER ISSUE	-
DMS_29319	33385	N	N	N	1	CUSTOMER ISSUE	-
DMS_29322	33386	N	N	N	1	CUSTOMER ISSUE	-
DMS_29351	33387	N	N	N	1	CUSTOMER ISSUE	-
DMS_29361	33388	N	N	N	1	CUSTOMER ISSUE	-
DMS_29406	33389	N	N	N	1	CUSTOMER ISSUE	-
DMS_29418	33390	N	N	N	1	CUSTOMER ISSUE	-
DMS_29472	33391	N	N	N	1	CUSTOMER ISSUE	-
DMS_29473	33392	N	N	N	1	CUSTOMER ISSUE	-
DMS_29481	33393	N	N	N	1	CUSTOMER ISSUE	-
DMS_29482	33394	N	N	N	1	CUSTOMER ISSUE	-
DMS_29485	33395	N	N	N	1	CUSTOMER ISSUE	-
DMS_29488	33396	N	N	N	1	CUSTOMER ISSUE	-
DMS_29489	33397	N	N	N	1	CUSTOMER ISSUE	-
DMS_29490	33398	N	N	N	1	CUSTOMER ISSUE	-
DMS_29491	33399	N	N	N	1	CUSTOMER ISSUE	-
DMS_29492	33400	N	N	N	1	CUSTOMER ISSUE	-
DMS_29493	33401	N	N	N	1	CUSTOMER ISSUE	-
DMS_29494	33402	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29495	33403	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29496	33404	N	N	N	1	CUSTOMER ISSUE	-
DMS_29497	33405	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_29498	33406	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29499	33407	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29500	33408	N	N	N	1	CUSTOMER ISSUE	-
DMS_29501	33409	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29502	33410	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29503	33411	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29504	33412	N	N	N	1	CUSTOMER ISSUE	-
DMS_29505	33413	N	N	N	1	CUSTOMER ISSUE	-
DMS_29506	33414	N	N	N	1	CUSTOMER ISSUE	-
DMS_29507	33415	N	N	N	1	CUSTOMER ISSUE	-
DMS_29508	33416	N	N	N	1	CUSTOMER ISSUE	-

DMS_29509	33417	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29510	33418	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29512	33419	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29513	33420	N	N	N	1	CUSTOMER ISSUE	-
DMS_29515	33421	N	N	N	1	CUSTOMER ISSUE	-
DMS_29516	33422	N	N	Y	1	TX - REPLACE	2500
DMS_29518	33423	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29519	33424	N	N	N	1	CUSTOMER ISSUE	-
DMS_29520	33425	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29522	33426	N	N	N	1	CUSTOMER ISSUE	-
DMS_29523	33427	N	N	N	1	CUSTOMER ISSUE	-
DMS_29524	33428	N	N	N	1	CUSTOMER ISSUE	-
DMS_29525	33429	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29526	33430	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29527	33431	N	N	N	1	CUSTOMER ISSUE	-
DMS_29528	33432	N	N	N	1	CUSTOMER ISSUE	-
DMS_29529	33433	N	N	N	1	CUSTOMER ISSUE	-
DMS_29530	33434	N	N	N	1	CUSTOMER ISSUE	-
DMS_29531	33435	N	N	N	1	CUSTOMER ISSUE	-
DMS_29532	33436	N	N	N	1	CUSTOMER ISSUE	-
DMS_29533	33437	N	N	N	1	CUSTOMER ISSUE	-
DMS_29534	33438	N	N	N	1	CUSTOMER ISSUE	-
DMS_29535	33439	N	N	N	1	CUSTOMER ISSUE	-
DMS_29536	33440	N	N	N	1	CUSTOMER ISSUE	-
DMS_29537	33441	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29538	33442	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29539	33443	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29540	33444	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29541	33445	N	N	N	1	CUSTOMER ISSUE	-
DMS_29542	33446	N	N	N	1	CUSTOMER ISSUE	-
DMS_29543	33447	N	N	N	1	CUSTOMER ISSUE	-
DMS_29544	33448	N	N	N	1	CUSTOMER ISSUE	-
DMS_29545	33449	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29546	33450	N	N	N	1	CUSTOMER ISSUE	-
DMS_29547	33451	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29550	33452	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29551	33453	N	N	N	1	CUSTOMER ISSUE	-
DMS_29552	33454	N	N	N	1	CUSTOMER ISSUE	-
DMS_29553	33455	N	N	N	1	CUSTOMER ISSUE	-
DMS_29554	33456	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29556	33457	N	N	N	1	CUSTOMER ISSUE	-
DMS_29557	33458	N	N	N	1	CUSTOMER ISSUE	-
DMS_29558	33459	N	N	N	1	CUSTOMER ISSUE	-
DMS_29559	33460	N	N	N	1	CUSTOMER ISSUE	-
DMS_29560	33461	N	N	N	1	CUSTOMER ISSUE	-
DMS_29561	33462	N	N	N	1	CUSTOMER ISSUE	-
DMS_29562	33463	N	N	N	1	CUSTOMER ISSUE	-
DMS_29563	33464	N	N	N	1	CUSTOMER ISSUE	-
DMS_29564	33465	N	N	N	1	CUSTOMER ISSUE	-
DMS_29565	33466	N	N	N	1	CUSTOMER ISSUE	-
DMS_29566	33467	N	N	N	1	CUSTOMER ISSUE	-
DMS_29567	33468	N	N	N	1	CUSTOMER ISSUE	-
DMS_29569	33469	N	N	N	1	CUSTOMER ISSUE	-
DMS_29570	33470	N	N	N	1	CUSTOMER ISSUE	-
DMS_29572	33471	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_29573	33472	N	N	N	1	CUSTOMER ISSUE	-
DMS_29575	33473	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29576	33474	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29578	33475	N	N	N	1	CUSTOMER ISSUE	-
DMS_29579	33476	N	N	N	1	CUSTOMER ISSUE	-
DMS_29580	33477	N	N	N	1	CUSTOMER ISSUE	-
DMS_29581	33478	N	N	N	1	CUSTOMER ISSUE	-
DMS_29582	33479	N	N	N	1	CUSTOMER ISSUE	-
DMS_29583	33480	N	N	N	1	CUSTOMER ISSUE	-
DMS_29584	33481	N	N	N	1	CUSTOMER ISSUE	-
DMS_29585	33482	N	N	N	1	CUSTOMER ISSUE	-
DMS_29586	33483	N	N	N	1	CUSTOMER ISSUE	-
DMS_29587	33484	N	N	N	1	CUSTOMER ISSUE	-
DMS_29588	33485	N	N	N	1	CUSTOMER ISSUE	-
DMS_29589	33486	N	N	N	1	CUSTOMER ISSUE	-
DMS_29590	33487	N	N	N	1	CUSTOMER ISSUE	-
DMS_29591	33488	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29592	33489	N	N	N	1	CUSTOMER ISSUE	-
DMS_29593	33490	N	N	N	1	CUSTOMER ISSUE	-
DMS_29594	33491	N	N	N	1	CUSTOMER ISSUE	-
DMS_29595	33492	N	N	N	1	CUSTOMER ISSUE	-
DMS_29596	33493	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_29597	33494	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29598	33495	N	N	N	1	CUSTOMER ISSUE	-
DMS_29599	33496	N	N	N	1	CUSTOMER ISSUE	-

DMS_29600	33497	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29601	33498	N	N	N	1	CUSTOMER ISSUE	-
DMS_29602	33499	N	N	N	1	CUSTOMER ISSUE	-
DMS_29603	33500	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29604	33501	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29606	33502	N	N	N	1	CUSTOMER ISSUE	-
DMS_29607	33503	N	N	N	1	CUSTOMER ISSUE	-
DMS_29608	33504	N	N	N	1	CUSTOMER ISSUE	-
DMS_29609	33505	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29610	33506	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29611	33507	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29612	33508	N	N	N	1	CUSTOMER ISSUE	-
DMS_29613	33509	N	N	N	1	CUSTOMER ISSUE	-
DMS_29614	33510	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29615	33511	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29616	33512	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29617	33513	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29618	33514	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29619	33515	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29620	33516	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29621	33517	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29622	33518	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29623	33519	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29624	33520	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29625	33521	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29626	33522	N	N	N	1	CUSTOMER ISSUE	-
DMS_29627	33523	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29628	33524	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29629	33525	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29630	33526	N	N	N	1	CUSTOMER ISSUE	-
DMS_29631	33527	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29632	33528	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29633	33529	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29634	33530	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29635	33531	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29636	33532	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29637	33533	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29638	33534	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29639	33535	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29640	33536	N	N	N	1	CUSTOMER ISSUE	-
DMS_29641	33537	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29642	33538	N	N	N	1	CUSTOMER ISSUE	-
DMS_29644	33539	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29645	33540	N	N	N	1	CUSTOMER ISSUE	-
DMS_29646	33541	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29647	33542	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29648	33543	N	N	N	1	CUSTOMER ISSUE	-
DMS_29649	33544	N	N	N	1	CUSTOMER ISSUE	-
DMS_29650	33545	N	N	N	1	CUSTOMER ISSUE	-
DMS_29651	33546	N	N	N	1	CUSTOMER ISSUE	-
DMS_29652	33547	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29653	33548	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29654	33549	N	N	N	1	CUSTOMER ISSUE	-
DMS_29655	33550	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29656	33551	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29657	33552	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29658	33553	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29659	33554	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29661	33555	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29662	33556	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29663	33557	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29664	33558	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29665	33559	N	N	N	1	CUSTOMER ISSUE	-
DMS_29668	33560	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29669	33561	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29670	33562	N	N	N	1	CUSTOMER ISSUE	-
DMS_29671	33563	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29672	33564	N	N	N	1	CUSTOMER ISSUE	-
DMS_29673	33565	N	N	N	1	CUSTOMER ISSUE	-
DMS_29679	33566	N	N	N	1	CUSTOMER ISSUE	-
DMS_29680	33567	N	N	N	1	CUSTOMER ISSUE	-
DMS_29681	33568	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29682	33569	N	N	N	1	CUSTOMER ISSUE	-
DMS_29683	33570	N	N	N	1	CUSTOMER ISSUE	-
DMS_29684	33571	N	N	N	1	CUSTOMER ISSUE	-
DMS_29685	33572	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29686	33573	N	N	N	1	CUSTOMER ISSUE	-
DMS_29687	33574	N	N	Y	1	TX - REPLACE	2500
DMS_29688	33575	N	N	N	1	CUSTOMER ISSUE	-
DMS_29689	33576	N	N	N	1	CUSTOMER ISSUE	-

DMS_29690	33577	N	N	N	1	CUSTOMER ISSUE	-
DMS_29691	33578	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29692	33579	N	N	N	1	CUSTOMER ISSUE	-
DMS_29693	33580	N	N	N	1	CUSTOMER ISSUE	-
DMS_29694	33581	N	N	N	1	CUSTOMER ISSUE	-
DMS_29695	33582	N	N	N	1	CUSTOMER ISSUE	-
DMS_29696	33583	N	N	N	1	CUSTOMER ISSUE	-
DMS_29697	33584	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29698	33585	N	N	N	1	CUSTOMER ISSUE	-
DMS_29699	33586	N	N	N	1	CUSTOMER ISSUE	-
DMS_29700	33587	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29701	33588	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29702	33589	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29703	33590	N	N	N	1	CUSTOMER ISSUE	-
DMS_29705	33591	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29706	33592	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29707	33593	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29708	33594	N	N	N	1	CUSTOMER ISSUE	-
DMS_29710	33595	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29711	33596	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29713	33597	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29714	33598	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29715	33599	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29716	33600	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29717	33601	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29718	33602	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29719	33603	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29720	33604	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29721	33605	N	N	N	1	CUSTOMER ISSUE	-
DMS_29722	33606	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29723	33607	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29724	33608	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29725	33609	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29726	33610	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29727	33611	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29728	33612	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29729	33613	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29730	33614	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29731	33615	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29732	33616	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29733	33617	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29734	33618	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29735	33619	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29736	33620	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29737	33621	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29738	33622	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29739	33623	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29740	33624	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29741	33625	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29742	33626	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29743	33627	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29744	33628	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29745	33629	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29746	33630	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29747	33631	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29748	33632	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29749	33633	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29750	33634	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29751	33635	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29752	33636	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29753	33637	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29754	33638	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29755	33639	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29756	33640	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29757	33641	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29758	33642	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29759	33643	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29760	33644	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29761	33645	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29762	33646	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29763	33647	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29764	33648	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29765	33649	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29766	33650	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29767	33651	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29768	33652	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29769	33653	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29770	33654	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29771	33655	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29772	33656	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_29773	33657	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29774	33658	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29775	33659	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29776	33660	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29778	33661	N	N	N	1	CUSTOMER ISSUE	-
DMS_29779	33662	N	N	Y	1	TX - REPLACE	2500
DMS_29780	33663	N	N	N	1	CUSTOMER ISSUE	-
DMS_29781	33664	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29782	33665	N	N	N	1	CUSTOMER ISSUE	-
DMS_29783	33666	N	N	N	1	CUSTOMER ISSUE	-
DMS_29784	33667	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29785	33668	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29786	33669	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29787	33670	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29788	33671	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29789	33672	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29790	33673	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29793	33674	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29794	33675	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_29796	33676	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29797	33677	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29798	33678	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29799	33679	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29804	33680	N	N	N	1	CUSTOMER ISSUE	-
DMS_29809	33681	N	N	N	1	CUSTOMER ISSUE	-
DMS_29810	33682	N	N	N	1	CUSTOMER ISSUE	-
DMS_29811	33683	N	N	N	1	CUSTOMER ISSUE	-
DMS_29812	33684	N	N	N	1	CUSTOMER ISSUE	-
DMS_29813	33685	N	N	N	1	CUSTOMER ISSUE	-
DMS_29814	33686	N	N	N	1	CUSTOMER ISSUE	-
DMS_29815	33687	N	N	N	1	CUSTOMER ISSUE	-
DMS_29817	33688	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29818	33689	N	N	N	1	CUSTOMER ISSUE	-
DMS_29823	33690	N	N	N	1	CUSTOMER ISSUE	-
DMS_29824	33691	N	N	N	1	CUSTOMER ISSUE	-
DMS_29825	33692	N	N	N	1	CUSTOMER ISSUE	-
DMS_29826	33693	N	N	N	1	CUSTOMER ISSUE	-
DMS_29827	33694	N	N	N	1	CUSTOMER ISSUE	-
DMS_29829	33695	N	N	N	1	CUSTOMER ISSUE	-
DMS_29830	33696	N	N	N	1	CUSTOMER ISSUE	-
DMS_29831	33697	N	N	N	1	CUSTOMER ISSUE	-
DMS_29832	33698	N	N	N	1	CUSTOMER ISSUE	-
DMS_29833	33699	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29834	33700	N	N	N	1	CUSTOMER ISSUE	-
DMS_29835	33701	N	N	N	1	CUSTOMER ISSUE	-
DMS_29836	33702	N	N	N	1	CUSTOMER ISSUE	-
DMS_29837	33703	N	N	N	1	CUSTOMER ISSUE	-
DMS_29838	33704	N	N	N	1	CUSTOMER ISSUE	-
DMS_29839	33705	N	N	N	1	CUSTOMER ISSUE	-
DMS_29840	33706	N	N	N	1	CUSTOMER ISSUE	-
DMS_29841	33707	N	N	N	1	CUSTOMER ISSUE	-
DMS_29843	33708	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29845	33709	N	N	N	1	CUSTOMER ISSUE	-
DMS_29847	33710	N	N	N	1	CUSTOMER ISSUE	-
DMS_29849	33711	N	N	N	1	CUSTOMER ISSUE	-
DMS_29851	33712	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29852	33713	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29856	33714	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29858	33715	N	N	N	1	CUSTOMER ISSUE	-
DMS_29859	33716	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29860	33717	N	N	N	1	CUSTOMER ISSUE	-
DMS_29885	33718	N	N	N	1	CUSTOMER ISSUE	-
DMS_29886	33719	N	N	N	1	CUSTOMER ISSUE	-
DMS_29887	33720	N	N	N	1	CUSTOMER ISSUE	-
DMS_29889	33721	N	N	N	1	CUSTOMER ISSUE	-
DMS_29895	33722	N	N	N	1	CUSTOMER ISSUE	-
DMS_29896	33723	N	N	N	1	CUSTOMER ISSUE	-
DMS_29897	33724	N	N	N	1	CUSTOMER ISSUE	-
DMS_29898	33725	N	N	N	1	CUSTOMER ISSUE	-
DMS_29899	33726	N	N	N	1	CUSTOMER ISSUE	-
DMS_29900	33727	N	N	N	1	CUSTOMER ISSUE	-
DMS_29901	33728	N	N	N	1	CUSTOMER ISSUE	-
DMS_29902	33729	N	N	N	1	CUSTOMER ISSUE	-
DMS_29903	33730	N	N	N	1	CUSTOMER ISSUE	-
DMS_29904	33731	N	N	N	1	CUSTOMER ISSUE	-
DMS_29906	33732	N	N	N	1	CUSTOMER ISSUE	-
DMS_29907	33733	N	N	N	1	CUSTOMER ISSUE	-
DMS_29908	33734	N	N	N	1	CUSTOMER ISSUE	-
DMS_29909	33735	N	N	N	1	CUSTOMER ISSUE	-
DMS_29910	33736	N	N	N	1	CUSTOMER ISSUE	-

DMS_29911	33737	N	N	N	1	CUSTOMER ISSUE	-
DMS_29912	33738	N	N	N	1	CUSTOMER ISSUE	-
DMS_29913	33739	N	N	N	1	CUSTOMER ISSUE	-
DMS_29914	33740	N	N	Y	1	TX - REPLACE	2500
DMS_29916	33741	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29917	33742	N	N	N	1	CUSTOMER ISSUE	-
DMS_29918	33743	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29920	33744	N	N	N	1	CUSTOMER ISSUE	-
DMS_29921	33745	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29922	33746	N	N	N	1	CUSTOMER ISSUE	-
DMS_29923	33747	N	N	N	1	CUSTOMER ISSUE	-
DMS_29924	33748	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29925	33749	N	N	N	1	CUSTOMER ISSUE	-
DMS_29926	33750	N	N	N	1	CUSTOMER ISSUE	-
DMS_29927	33751	N	N	Y	1	TX - REPLACE	2500
DMS_29928	33752	N	N	Y	1	TX - REPLACE	2500
DMS_29929	33753	N	N	Y	1	TX - REPLACE	2500
DMS_29930	33754	N	N	N	1	CUSTOMER ISSUE	-
DMS_29931	33755	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29932	33756	N	N	N	1	CUSTOMER ISSUE	-
DMS_29933	33757	N	N	N	1	CUSTOMER ISSUE	-
DMS_29934	33758	N	N	N	1	CUSTOMER ISSUE	-
DMS_29935	33759	N	N	N	1	CUSTOMER ISSUE	-
DMS_29936	33760	N	N	N	1	CUSTOMER ISSUE	-
DMS_29937	33761	N	N	N	1	CUSTOMER ISSUE	-
DMS_29943	33762	N	N	N	1	CUSTOMER ISSUE	-
DMS_29944	33763	N	N	N	1	CUSTOMER ISSUE	-
DMS_29945	33764	N	N	N	1	CUSTOMER ISSUE	-
DMS_29946	33765	N	N	N	1	CUSTOMER ISSUE	-
DMS_29948	33766	N	N	N	1	CUSTOMER ISSUE	-
DMS_29949	33767	N	N	N	1	CUSTOMER ISSUE	-
DMS_29950	33768	N	N	N	1	CUSTOMER ISSUE	-
DMS_29951	33769	N	N	N	1	CUSTOMER ISSUE	-
DMS_29952	33770	N	N	N	1	CUSTOMER ISSUE	-
DMS_29953	33771	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29955	33772	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29958	33773	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_29960	33774	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29963	33775	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29967	33776	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29969	33777	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29970	33778	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29971	33779	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29979	33780	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_29982	33781	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_29985	33782	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29990	33783	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29994	33784	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_29996	33785	N	N	N	1	CUSTOMER ISSUE	-
DMS_29997	33786	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30001	33787	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30002	33788	N	N	N	1	CUSTOMER ISSUE	-
DMS_30003	33789	N	N	N	1	CUSTOMER ISSUE	-
DMS_30008	33790	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30009	33791	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_30011	33792	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30012	33793	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30014	33794	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30015	33795	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_30016	33796	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_30017	33797	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_30018	33798	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30021	33799	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30023	33800	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_30024	33801	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30027	33802	N	N	N	1	CUSTOMER ISSUE	-
DMS_30028	33803	N	N	N	1	CUSTOMER ISSUE	-
DMS_30029	33804	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_30030	33805	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_30033	33806	N	N	N	1	CUSTOMER ISSUE	-
DMS_30034	33807	N	N	N	1	CUSTOMER ISSUE	-
DMS_30035	33808	N	N	N	1	CUSTOMER ISSUE	-
DMS_30036	33809	N	N	N	1	CUSTOMER ISSUE	-
DMS_30037	33810	N	N	N	1	CUSTOMER ISSUE	-
DMS_30038	33811	N	N	N	1	CUSTOMER ISSUE	-
DMS_30039	33812	N	N	N	1	CUSTOMER ISSUE	-
DMS_30040	33813	N	N	N	1	CUSTOMER ISSUE	-
DMS_30041	33814	N	N	N	1	CUSTOMER ISSUE	-
DMS_30042	33815	N	N	N	1	CUSTOMER ISSUE	-
DMS_30043	33816	N	N	N	1	CUSTOMER ISSUE	-

DMS_30044	33817	N	N	N	1	CUSTOMER ISSUE	-
DMS_30045	33818	N	N	N	1	CUSTOMER ISSUE	-
DMS_30046	33819	N	N	N	1	CUSTOMER ISSUE	-
DMS_30047	33820	N	N	N	1	CUSTOMER ISSUE	-
DMS_30048	33821	N	N	N	1	CUSTOMER ISSUE	-
DMS_30049	33822	N	N	N	1	CUSTOMER ISSUE	-
DMS_30050	33823	N	N	N	1	CUSTOMER ISSUE	-
DMS_30051	33824	N	N	N	1	CUSTOMER ISSUE	-
DMS_30052	33825	N	N	N	1	CUSTOMER ISSUE	-
DMS_30053	33826	N	N	N	1	CUSTOMER ISSUE	-
DMS_30054	33827	N	N	N	1	CUSTOMER ISSUE	-
DMS_30055	33828	N	N	N	1	CUSTOMER ISSUE	-
DMS_30056	33829	N	N	N	1	CUSTOMER ISSUE	-
DMS_30057	33830	N	N	N	1	CUSTOMER ISSUE	-
DMS_30058	33831	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30059	33832	N	N	N	1	CUSTOMER ISSUE	-
DMS_30060	33833	N	N	N	1	CUSTOMER ISSUE	-
DMS_30061	33834	N	N	N	1	CUSTOMER ISSUE	-
DMS_30062	33835	N	N	N	1	CUSTOMER ISSUE	-
DMS_30063	33836	N	N	N	1	CUSTOMER ISSUE	-
DMS_30064	33837	N	N	N	1	CUSTOMER ISSUE	-
DMS_30065	33838	N	N	N	1	CUSTOMER ISSUE	-
DMS_30066	33839	N	N	N	1	CUSTOMER ISSUE	-
DMS_30067	33840	N	N	N	1	CUSTOMER ISSUE	-
DMS_30068	33841	N	N	N	1	CUSTOMER ISSUE	-
DMS_30069	33842	N	N	N	1	CUSTOMER ISSUE	-
DMS_30070	33843	N	N	N	1	CUSTOMER ISSUE	-
DMS_30071	33844	N	N	N	1	CUSTOMER ISSUE	-
DMS_30072	33845	N	N	N	1	CUSTOMER ISSUE	-
DMS_30073	33846	N	N	N	1	CUSTOMER ISSUE	-
DMS_30074	33847	N	N	N	1	CUSTOMER ISSUE	-
DMS_30075	33848	N	N	N	1	CUSTOMER ISSUE	-
DMS_30076	33849	N	N	N	1	CUSTOMER ISSUE	-
DMS_30077	33850	N	N	N	1	CUSTOMER ISSUE	-
DMS_30078	33851	N	N	N	1	CUSTOMER ISSUE	-
DMS_30079	33852	N	N	N	1	CUSTOMER ISSUE	-
DMS_30080	33853	N	N	N	1	CUSTOMER ISSUE	-
DMS_30081	33854	N	N	N	1	CUSTOMER ISSUE	-
DMS_30082	33855	N	N	N	1	CUSTOMER ISSUE	-
DMS_30083	33856	N	N	N	1	CUSTOMER ISSUE	-
DMS_30084	33857	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_30085	33858	N	N	N	1	CUSTOMER ISSUE	-
DMS_30087	33859	N	N	N	1	CUSTOMER ISSUE	-
DMS_30088	33860	N	N	N	1	CUSTOMER ISSUE	-
DMS_30090	33861	N	N	N	1	CUSTOMER ISSUE	-
DMS_30091	33862	N	N	N	1	CUSTOMER ISSUE	-
DMS_30093	33863	N	N	N	1	CUSTOMER ISSUE	-
DMS_30094	33864	N	N	N	1	CUSTOMER ISSUE	-
DMS_30096	33865	N	N	N	1	CUSTOMER ISSUE	-
DMS_30097	33866	N	N	N	1	CUSTOMER ISSUE	-
DMS_30098	33867	N	N	N	1	CUSTOMER ISSUE	-
DMS_30101	33868	N	N	N	1	CUSTOMER ISSUE	-
DMS_30102	33869	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30103	33870	N	N	N	1	CUSTOMER ISSUE	-
DMS_30104	33871	N	N	N	1	CUSTOMER ISSUE	-
DMS_30111	33872	N	N	N	1	CUSTOMER ISSUE	-
DMS_30112	33873	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30113	33874	N	N	N	1	CUSTOMER ISSUE	-
DMS_30114	33875	N	N	N	1	CUSTOMER ISSUE	-
DMS_30115	33876	N	N	N	1	CUSTOMER ISSUE	-
DMS_30117	33877	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_30120	33878	N	N	N	1	CUSTOMER ISSUE	-
DMS_30121	33879	N	N	N	1	CUSTOMER ISSUE	-
DMS_30122	33880	N	N	N	1	CUSTOMER ISSUE	-
DMS_30124	33881	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30125	33882	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30127	33883	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30128	33884	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30129	33885	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30130	33886	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30131	33887	N	N	N	1	CUSTOMER ISSUE	-
DMS_30132	33888	N	N	N	1	CUSTOMER ISSUE	-
DMS_30133	33889	N	N	N	1	CUSTOMER ISSUE	-
DMS_30134	33890	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30135	33891	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30136	33892	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30137	33893	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30138	33894	N	N	N	1	CUSTOMER ISSUE	-
DMS_30139	33895	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30140	33896	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_30141	33897	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30142	33898	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30143	33899	N	N	N	1	CUSTOMER ISSUE	-
DMS_30144	33900	N	N	N	1	CUSTOMER ISSUE	-
DMS_30145	33901	N	N	N	1	CUSTOMER ISSUE	-
DMS_30146	33902	N	N	N	1	CUSTOMER ISSUE	-
DMS_30147	33903	N	N	N	1	CUSTOMER ISSUE	-
DMS_30148	33904	N	N	N	1	CUSTOMER ISSUE	-
DMS_30149	33905	N	N	N	1	CUSTOMER ISSUE	-
DMS_30150	33906	N	N	N	1	CUSTOMER ISSUE	-
DMS_30151	33907	N	N	N	1	CUSTOMER ISSUE	-
DMS_30152	33908	N	N	N	1	CUSTOMER ISSUE	-
DMS_30154	33909	N	N	Y	3	SEC/SVC - REPLACE	708.75
DMS_30155	33910	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30156	33911	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30157	33912	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30158	33913	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30159	33914	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30160	33915	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30161	33916	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30162	33917	N	N	N	1	CUSTOMER ISSUE	-
DMS_30163	33918	N	N	N	1	CUSTOMER ISSUE	-
DMS_30164	33919	N	N	N	1	CUSTOMER ISSUE	-
DMS_30165	33920	N	N	N	1	CUSTOMER ISSUE	-
DMS_30166	33921	N	N	N	1	CUSTOMER ISSUE	-
DMS_30167	33922	N	N	N	1	CUSTOMER ISSUE	-
DMS_30168	33923	N	N	N	1	CUSTOMER ISSUE	-
DMS_30169	33924	N	N	N	1	CUSTOMER ISSUE	-
DMS_30170	33925	N	N	N	1	CUSTOMER ISSUE	-
DMS_30171	33926	N	N	N	1	CUSTOMER ISSUE	-
DMS_30172	33927	N	N	N	1	CUSTOMER ISSUE	-
DMS_30173	33928	N	N	N	1	CUSTOMER ISSUE	-
DMS_30174	33929	N	N	N	1	CUSTOMER ISSUE	-
DMS_30175	33930	N	N	N	1	CUSTOMER ISSUE	-
DMS_30176	33931	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30177	33932	N	N	N	1	CUSTOMER ISSUE	-
DMS_30178	33933	N	N	N	1	CUSTOMER ISSUE	-
DMS_30179	33934	N	N	N	1	CUSTOMER ISSUE	-
DMS_30180	33935	N	N	N	1	CUSTOMER ISSUE	-
DMS_30181	33936	N	N	N	1	CUSTOMER ISSUE	-
DMS_30182	33937	N	N	N	1	CUSTOMER ISSUE	-
DMS_30183	33938	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30184	33939	N	N	N	1	CUSTOMER ISSUE	-
DMS_30185	33940	N	N	N	1	CUSTOMER ISSUE	-
DMS_30186	33941	N	N	N	1	CUSTOMER ISSUE	-
DMS_30187	33942	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30188	33943	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30189	33944	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30190	33945	N	N	N	1	CUSTOMER ISSUE	-
DMS_30191	33946	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30192	33947	N	N	N	1	CUSTOMER ISSUE	-
DMS_30193	33948	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30194	33949	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30195	33950	N	N	N	1	CUSTOMER ISSUE	-
DMS_30196	33951	N	N	N	1	CUSTOMER ISSUE	-
DMS_30197	33952	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30198	33953	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30199	33954	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30200	33955	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30201	33956	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30202	33957	N	N	N	1	CUSTOMER ISSUE	-
DMS_30203	33958	N	N	N	1	CUSTOMER ISSUE	-
DMS_30205	33959	N	N	N	1	CUSTOMER ISSUE	-
DMS_30207	33960	N	N	N	1	CUSTOMER ISSUE	-
DMS_30208	33961	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30209	33962	N	N	N	1	CUSTOMER ISSUE	-
DMS_30210	33963	N	N	N	1	CUSTOMER ISSUE	-
DMS_30211	33964	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30212	33965	N	N	N	1	CUSTOMER ISSUE	-
DMS_30213	33966	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30214	33967	N	N	N	1	CUSTOMER ISSUE	-
DMS_30215	33968	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30216	33969	N	N	N	1	CUSTOMER ISSUE	-
DMS_30217	33970	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30218	33971	N	N	N	1	CUSTOMER ISSUE	-
DMS_30219	33972	N	N	N	1	CUSTOMER ISSUE	-
DMS_30220	33973	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30221	33974	N	N	N	1	CUSTOMER ISSUE	-
DMS_30222	33975	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30223	33976	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_30224	33977	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30225	33978	N	N	N	1	CUSTOMER ISSUE	-
DMS_30226	33979	N	N	N	1	CUSTOMER ISSUE	-
DMS_30227	33980	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30228	33981	N	N	N	1	CUSTOMER ISSUE	-
DMS_30229	33982	N	N	N	1	CUSTOMER ISSUE	-
DMS_30230	33983	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30231	33984	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30233	33985	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30234	33986	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30235	33987	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30236	33988	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30237	33989	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30238	33990	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30240	33991	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30241	33992	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30242	33993	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30243	33994	N	N	N	1	CUSTOMER ISSUE	-
DMS_30244	33995	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30246	33996	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30247	33997	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30249	33998	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30250	33999	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30251	34000	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30252	34001	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30253	34002	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30254	34003	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30255	34004	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30256	34005	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30257	34006	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30258	34007	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30259	34008	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30260	34009	N	N	N	1	CUSTOMER ISSUE	-
DMS_30261	34010	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30262	34011	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30263	34012	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30264	34013	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30265	34014	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30266	34015	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30267	34016	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30268	34017	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30269	34018	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30270	34019	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30271	34020	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30272	34021	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30273	34022	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30274	34023	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30275	34024	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30276	34025	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30277	34026	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30278	34027	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30279	34028	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30280	34029	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30281	34030	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30282	34031	N	N	N	1	CUSTOMER ISSUE	-
DMS_30283	34032	N	N	N	1	CUSTOMER ISSUE	-
DMS_30284	34033	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30285	34034	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30286	34035	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30287	34036	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30288	34037	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30289	34038	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30290	34039	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30291	34040	N	N	N	1	CUSTOMER ISSUE	-
DMS_30292	34041	N	N	N	1	CUSTOMER ISSUE	-
DMS_30294	34042	N	N	Y	1	TX - REPLACE	2500
DMS_30295	34043	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30298	34044	N	N	N	1	CUSTOMER ISSUE	-
DMS_30300	34045	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30301	34046	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30302	34047	N	N	N	1	CUSTOMER ISSUE	-
DMS_30304	34048	N	N	N	1	CUSTOMER ISSUE	-
DMS_30305	34049	N	N	N	1	CUSTOMER ISSUE	-
DMS_30307	34050	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30308	34051	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30309	34052	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30310	34053	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30313	34054	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30325	34055	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30328	34056	N	N	N	1	CUSTOMER ISSUE	-

DMS_30331	34057	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30332	34058	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30338	34059	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30339	34060	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30343	34061	N	N	N	1	CUSTOMER ISSUE	-
DMS_30344	34062	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_30345	34063	N	N	N	1	CUSTOMER ISSUE	-
DMS_30346	34064	N	N	N	1	CUSTOMER ISSUE	-
DMS_30348	34065	N	N	N	1	CUSTOMER ISSUE	-
DMS_30349	34066	N	N	N	1	CUSTOMER ISSUE	-
DMS_30350	34067	N	N	N	1	CUSTOMER ISSUE	-
DMS_30351	34068	N	N	N	1	CUSTOMER ISSUE	-
DMS_30352	34069	N	N	N	1	CUSTOMER ISSUE	-
DMS_30353	34070	N	N	N	1	CUSTOMER ISSUE	-
DMS_30354	34071	N	N	N	1	CUSTOMER ISSUE	-
DMS_30355	34072	N	N	N	1	CUSTOMER ISSUE	-
DMS_30356	34073	N	N	N	1	CUSTOMER ISSUE	-
DMS_30357	34074	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30358	34075	N	N	N	1	CUSTOMER ISSUE	-
DMS_30359	34076	N	N	N	1	CUSTOMER ISSUE	-
DMS_30360	34077	N	N	N	2	CUSTOMER ISSUE	-
DMS_30361	34078	N	N	N	1	CUSTOMER ISSUE	-
DMS_30363	34079	N	N	N	1	CUSTOMER ISSUE	-
DMS_30364	34080	N	N	N	1	CUSTOMER ISSUE	-
DMS_30365	34081	N	N	N	1	CUSTOMER ISSUE	-
DMS_30366	34082	N	N	N	1	CUSTOMER ISSUE	-
DMS_30367	34083	N	N	N	1	CUSTOMER ISSUE	-
DMS_30368	34084	N	N	N	1	CUSTOMER ISSUE	-
DMS_30369	34085	N	N	N	1	CUSTOMER ISSUE	-
DMS_30370	34086	N	N	N	1	CUSTOMER ISSUE	-
DMS_30371	34087	N	N	N	1	CUSTOMER ISSUE	-
DMS_30372	34088	N	N	N	1	CUSTOMER ISSUE	-
DMS_30373	34089	N	N	N	1	CUSTOMER ISSUE	-
DMS_30374	34090	N	N	N	1	CUSTOMER ISSUE	-
DMS_30375	34091	N	N	N	1	CUSTOMER ISSUE	-
DMS_30376	34092	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
DMS_30377	34093	N	N	N	1	CUSTOMER ISSUE	-
DMS_30378	34094	N	N	N	1	CUSTOMER ISSUE	-
DMS_30379	34095	N	N	N	1	CUSTOMER ISSUE	-
DMS_30380	34096	N	N	N	1	CUSTOMER ISSUE	-
DMS_30381	34097	N	N	N	1	CUSTOMER ISSUE	-
DMS_30382	34098	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_30383	34099	N	N	N	1	CUSTOMER ISSUE	-
DMS_30384	34100	N	N	N	1	CUSTOMER ISSUE	-
DMS_30387	34101	N	N	N	1	CUSTOMER ISSUE	-
DMS_30388	34102	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30389	34103	N	N	N	1	CUSTOMER ISSUE	-
DMS_30390	34104	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30391	34105	N	N	N	1	CUSTOMER ISSUE	-
DMS_30392	34106	N	N	N	1	CUSTOMER ISSUE	-
DMS_30394	34107	N	N	N	1	CUSTOMER ISSUE	-
DMS_30396	34108	N	N	N	1	CUSTOMER ISSUE	-
DMS_30397	34109	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_30398	34110	N	N	N	1	CUSTOMER ISSUE	-
DMS_30400	34111	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30401	34112	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30406	34113	N	N	N	1	CUSTOMER ISSUE	-
DMS_30407	34114	N	N	N	1	CUSTOMER ISSUE	-
DMS_30408	34115	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30410	34116	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30411	34117	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30412	34118	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30413	34119	N	N	N	1	CUSTOMER ISSUE	-
DMS_30414	34120	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30416	34121	N	N	N	1	CUSTOMER ISSUE	-
DMS_30417	34122	N	N	N	1	CUSTOMER ISSUE	-
DMS_30418	34123	N	N	N	1	CUSTOMER ISSUE	-
DMS_30419	34124	N	N	N	1	CUSTOMER ISSUE	-
DMS_30420	34125	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_30422	34126	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30423	34127	N	N	N	1	CUSTOMER ISSUE	-
DMS_30424	34128	N	N	N	1	CUSTOMER ISSUE	-
DMS_30425	34129	N	N	N	1	CUSTOMER ISSUE	-
DMS_30426	34130	N	N	N	1	CUSTOMER ISSUE	-
DMS_30427	34131	N	N	N	1	CUSTOMER ISSUE	-
DMS_30428	34132	N	N	N	1	CUSTOMER ISSUE	-
DMS_30429	34133	N	N	N	1	CUSTOMER ISSUE	-
DMS_30430	34134	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30431	34135	N	N	N	1	CUSTOMER ISSUE	-
DMS_30432	34136	N	N	N	1	CUSTOMER ISSUE	-

DMS_30433	34137	N	N	N	1	CUSTOMER ISSUE	-
DMS_30434	34138	N	N	N	1	CUSTOMER ISSUE	-
DMS_30435	34139	N	N	N	1	CUSTOMER ISSUE	-
DMS_30439	34140	N	N	N	1	CUSTOMER ISSUE	-
DMS_30440	34141	N	N	N	1	CUSTOMER ISSUE	-
DMS_30441	34142	N	N	N	1	CUSTOMER ISSUE	-
DMS_30442	34143	N	N	N	1	CUSTOMER ISSUE	-
DMS_30443	34144	N	N	N	1	CUSTOMER ISSUE	-
DMS_30444	34145	N	N	N	1	CUSTOMER ISSUE	-
DMS_30445	34146	N	N	N	1	CUSTOMER ISSUE	-
DMS_30446	34147	N	N	N	1	CUSTOMER ISSUE	-
DMS_30447	34148	N	N	N	1	CUSTOMER ISSUE	-
DMS_30448	34149	N	N	N	1	CUSTOMER ISSUE	-
DMS_30449	34150	N	N	N	1	CUSTOMER ISSUE	-
DMS_30450	34151	N	N	N	1	CUSTOMER ISSUE	-
DMS_30452	34152	N	N	N	1	CUSTOMER ISSUE	-
DMS_30453	34153	N	N	N	1	CUSTOMER ISSUE	-
DMS_30454	34154	N	N	N	1	CUSTOMER ISSUE	-
DMS_30455	34155	N	N	N	1	CUSTOMER ISSUE	-
DMS_30456	34156	N	N	N	1	CUSTOMER ISSUE	-
DMS_30457	34157	N	N	N	1	CUSTOMER ISSUE	-
DMS_30458	34158	N	N	N	1	CUSTOMER ISSUE	-
DMS_30459	34159	N	N	N	1	CUSTOMER ISSUE	-
DMS_30460	34160	N	N	N	1	CUSTOMER ISSUE	-
DMS_30461	34161	N	N	N	1	CUSTOMER ISSUE	-
DMS_30462	34162	N	N	N	1	CUSTOMER ISSUE	-
DMS_30464	34163	N	N	N	1	CUSTOMER ISSUE	-
DMS_30465	34164	N	N	N	1	CUSTOMER ISSUE	-
DMS_30466	34165	N	N	N	1	CUSTOMER ISSUE	-
DMS_30467	34166	N	N	N	1	CUSTOMER ISSUE	-
DMS_30468	34167	N	N	N	1	CUSTOMER ISSUE	-
DMS_30469	34168	N	N	N	1	CUSTOMER ISSUE	-
DMS_30470	34169	N	N	N	1	CUSTOMER ISSUE	-
DMS_30471	34170	N	N	N	1	CUSTOMER ISSUE	-
DMS_30472	34171	N	N	N	1	CUSTOMER ISSUE	-
DMS_30473	34172	N	N	N	1	CUSTOMER ISSUE	-
DMS_30475	34173	N	N	N	1	CUSTOMER ISSUE	-
DMS_30476	34174	N	N	N	1	CUSTOMER ISSUE	-
DMS_30477	34175	N	N	N	1	CUSTOMER ISSUE	-
DMS_30478	34176	N	N	N	1	CUSTOMER ISSUE	-
DMS_30479	34177	N	N	N	1	CUSTOMER ISSUE	-
DMS_30480	34178	N	N	N	1	CUSTOMER ISSUE	-
DMS_30481	34179	N	N	N	1	CUSTOMER ISSUE	-
DMS_30482	34180	N	N	N	1	CUSTOMER ISSUE	-
DMS_30483	34181	N	N	N	1	CUSTOMER ISSUE	-
DMS_30484	34182	N	N	N	1	CUSTOMER ISSUE	-
DMS_30485	34183	N	N	N	1	CUSTOMER ISSUE	-
DMS_30486	34184	N	N	N	1	CUSTOMER ISSUE	-
DMS_30487	34185	N	N	N	1	CUSTOMER ISSUE	-
DMS_30488	34186	N	N	N	1	CUSTOMER ISSUE	-
DMS_30489	34187	N	N	N	1	CUSTOMER ISSUE	-
DMS_30490	34188	N	N	N	1	CUSTOMER ISSUE	-
DMS_30491	34189	N	N	N	1	CUSTOMER ISSUE	-
DMS_30492	34190	N	N	N	1	CUSTOMER ISSUE	-
DMS_30493	34191	N	N	N	1	CUSTOMER ISSUE	-
DMS_30494	34192	N	N	N	1	CUSTOMER ISSUE	-
DMS_30495	34193	N	N	N	1	CUSTOMER ISSUE	-
DMS_30496	34194	N	N	N	1	CUSTOMER ISSUE	-
DMS_30497	34195	N	N	N	1	CUSTOMER ISSUE	-
DMS_30498	34196	N	N	N	1	CUSTOMER ISSUE	-
DMS_30499	34197	N	N	N	1	CUSTOMER ISSUE	-
DMS_30500	34198	N	N	N	1	CUSTOMER ISSUE	-
DMS_30501	34199	N	N	N	1	CUSTOMER ISSUE	-
DMS_30502	34200	N	N	N	1	CUSTOMER ISSUE	-
DMS_30503	34201	N	N	N	1	CUSTOMER ISSUE	-
DMS_30504	34202	N	N	N	1	CUSTOMER ISSUE	-
DMS_30505	34203	N	N	N	1	CUSTOMER ISSUE	-
DMS_30506	34204	N	N	N	1	CUSTOMER ISSUE	-
DMS_30507	34205	N	N	N	1	CUSTOMER ISSUE	-
DMS_30508	34206	N	N	N	1	CUSTOMER ISSUE	-
DMS_30509	34207	N	N	N	1	CUSTOMER ISSUE	-
DMS_30510	34208	N	N	N	1	CUSTOMER ISSUE	-
DMS_30511	34209	N	N	N	1	CUSTOMER ISSUE	-
DMS_30512	34210	N	N	N	1	CUSTOMER ISSUE	-
DMS_30513	34211	N	N	N	1	CUSTOMER ISSUE	-
DMS_30514	34212	N	N	N	1	CUSTOMER ISSUE	-
DMS_30515	34213	N	N	N	1	CUSTOMER ISSUE	-
DMS_30516	34214	N	N	N	1	CUSTOMER ISSUE	-
DMS_30517	34215	N	N	N	1	CUSTOMER ISSUE	-
DMS_30518	34216	N	N	N	1	CUSTOMER ISSUE	-

DMS_30519	34217	N	N	N	1	CUSTOMER ISSUE	-
DMS_30520	34218	N	N	N	1	CUSTOMER ISSUE	-
DMS_30521	34219	N	N	N	1	CUSTOMER ISSUE	-
DMS_30522	34220	N	N	N	1	CUSTOMER ISSUE	-
DMS_30523	34221	N	N	N	1	CUSTOMER ISSUE	-
DMS_30524	34222	N	N	N	1	CUSTOMER ISSUE	-
DMS_30525	34223	N	N	N	1	CUSTOMER ISSUE	-
DMS_30526	34224	N	N	N	1	CUSTOMER ISSUE	-
DMS_30527	34225	N	N	N	1	CUSTOMER ISSUE	-
DMS_30528	34226	N	N	N	1	CUSTOMER ISSUE	-
DMS_30529	34227	N	N	N	1	CUSTOMER ISSUE	-
DMS_30530	34228	N	N	N	1	CUSTOMER ISSUE	-
DMS_30531	34229	N	N	N	1	CUSTOMER ISSUE	-
DMS_30532	34230	N	N	N	1	CUSTOMER ISSUE	-
DMS_30533	34231	N	N	N	1	CUSTOMER ISSUE	-
DMS_30534	34232	N	N	N	1	CUSTOMER ISSUE	-
DMS_30535	34233	N	N	N	1	CUSTOMER ISSUE	-
DMS_30536	34234	N	N	N	1	CUSTOMER ISSUE	-
DMS_30537	34235	N	N	N	1	CUSTOMER ISSUE	-
DMS_30538	34236	N	N	N	1	CUSTOMER ISSUE	-
DMS_30539	34237	N	N	N	1	CUSTOMER ISSUE	-
DMS_30540	34238	N	N	N	1	CUSTOMER ISSUE	-
DMS_30541	34239	N	N	N	1	CUSTOMER ISSUE	-
DMS_30542	34240	N	N	N	1	CUSTOMER ISSUE	-
DMS_30543	34241	N	N	N	1	CUSTOMER ISSUE	-
DMS_30544	34242	N	N	N	1	CUSTOMER ISSUE	-
DMS_30545	34243	N	N	N	1	CUSTOMER ISSUE	-
DMS_30546	34244	N	N	N	1	CUSTOMER ISSUE	-
DMS_30547	34245	N	N	N	1	CUSTOMER ISSUE	-
DMS_30548	34246	N	N	N	1	CUSTOMER ISSUE	-
DMS_30549	34247	N	N	N	1	CUSTOMER ISSUE	-
DMS_30550	34248	N	N	N	1	CUSTOMER ISSUE	-
DMS_30551	34249	N	N	N	1	CUSTOMER ISSUE	-
DMS_30552	34250	N	N	N	1	CUSTOMER ISSUE	-
DMS_30553	34251	N	N	N	1	CUSTOMER ISSUE	-
DMS_30554	34252	N	N	N	1	CUSTOMER ISSUE	-
DMS_30555	34253	N	N	N	1	CUSTOMER ISSUE	-
DMS_30556	34254	N	N	N	1	CUSTOMER ISSUE	-
DMS_30557	34255	N	N	N	1	CUSTOMER ISSUE	-
DMS_30558	34256	N	N	N	1	CUSTOMER ISSUE	-
DMS_30559	34257	N	N	N	1	CUSTOMER ISSUE	-
DMS_30560	34258	N	N	N	1	CUSTOMER ISSUE	-
DMS_30561	34259	N	N	N	1	CUSTOMER ISSUE	-
DMS_30562	34260	N	N	N	1	CUSTOMER ISSUE	-
DMS_30563	34261	N	N	N	1	CUSTOMER ISSUE	-
DMS_30564	34262	N	N	N	1	CUSTOMER ISSUE	-
DMS_30565	34263	N	N	N	1	CUSTOMER ISSUE	-
DMS_30566	34264	N	N	N	1	CUSTOMER ISSUE	-
DMS_30567	34265	N	N	N	1	CUSTOMER ISSUE	-
DMS_30568	34266	N	N	N	1	CUSTOMER ISSUE	-
DMS_30569	34267	N	N	N	1	CUSTOMER ISSUE	-
DMS_30570	34268	N	N	N	1	CUSTOMER ISSUE	-
DMS_30571	34269	N	N	N	1	CUSTOMER ISSUE	-
DMS_30572	34270	N	N	N	1	CUSTOMER ISSUE	-
DMS_30573	34271	N	N	N	1	CUSTOMER ISSUE	-
DMS_30574	34272	N	N	N	1	CUSTOMER ISSUE	-
DMS_30575	34273	N	N	N	1	CUSTOMER ISSUE	-
DMS_30576	34274	N	N	N	1	CUSTOMER ISSUE	-
DMS_30580	34275	N	N	N	1	CUSTOMER ISSUE	-
DMS_30581	34276	N	N	N	1	CUSTOMER ISSUE	-
DMS_30582	34277	N	N	N	1	CUSTOMER ISSUE	-
DMS_30583	34278	N	N	N	1	CUSTOMER ISSUE	-
DMS_30584	34279	N	N	N	1	CUSTOMER ISSUE	-
DMS_30585	34280	N	N	N	1	CUSTOMER ISSUE	-
DMS_30586	34281	N	N	N	1	CUSTOMER ISSUE	-
DMS_30587	34282	N	N	N	1	CUSTOMER ISSUE	-
DMS_30588	34283	N	N	N	1	CUSTOMER ISSUE	-
DMS_30589	34284	N	N	N	1	CUSTOMER ISSUE	-
DMS_30590	34285	N	N	N	1	CUSTOMER ISSUE	-
DMS_30591	34286	N	N	N	1	CUSTOMER ISSUE	-
DMS_30592	34287	N	N	N	1	CUSTOMER ISSUE	-
DMS_30593	34288	N	N	N	1	CUSTOMER ISSUE	-
DMS_30594	34289	N	N	N	1	CUSTOMER ISSUE	-
DMS_30595	34290	N	N	N	1	CUSTOMER ISSUE	-
DMS_30596	34291	N	N	N	1	CUSTOMER ISSUE	-
DMS_30597	34292	N	N	N	1	CUSTOMER ISSUE	-
DMS_30598	34293	N	N	N	1	CUSTOMER ISSUE	-
DMS_30599	34294	N	N	N	1	CUSTOMER ISSUE	-
DMS_30600	34295	N	N	N	1	CUSTOMER ISSUE	-
DMS_30601	34296	N	N	N	1	CUSTOMER ISSUE	-

DMS_30602	34297	N	N	N	1	CUSTOMER ISSUE	-
DMS_30603	34298	N	N	N	1	CUSTOMER ISSUE	-
DMS_30604	34299	N	N	N	1	CUSTOMER ISSUE	-
DMS_30605	34300	N	N	N	1	CUSTOMER ISSUE	-
DMS_30606	34301	N	N	N	1	CUSTOMER ISSUE	-
DMS_30607	34302	N	N	N	1	CUSTOMER ISSUE	-
DMS_30608	34303	N	N	N	1	CUSTOMER ISSUE	-
DMS_30609	34304	N	N	N	1	CUSTOMER ISSUE	-
DMS_30610	34305	N	N	N	1	CUSTOMER ISSUE	-
DMS_30611	34306	N	N	N	1	CUSTOMER ISSUE	-
DMS_30612	34307	N	N	N	1	CUSTOMER ISSUE	-
DMS_30613	34308	N	N	N	1	CUSTOMER ISSUE	-
DMS_30614	34309	N	N	N	1	CUSTOMER ISSUE	-
DMS_30615	34310	N	N	N	1	CUSTOMER ISSUE	-
DMS_30616	34311	N	N	N	1	CUSTOMER ISSUE	-
DMS_30617	34312	N	N	N	1	CUSTOMER ISSUE	-
DMS_30618	34313	N	N	N	1	CUSTOMER ISSUE	-
DMS_30619	34314	N	N	N	1	CUSTOMER ISSUE	-
DMS_30620	34315	N	N	N	1	CUSTOMER ISSUE	-
DMS_30621	34316	N	N	N	1	CUSTOMER ISSUE	-
DMS_30622	34317	N	N	N	1	CUSTOMER ISSUE	-
DMS_30623	34318	N	N	N	1	CUSTOMER ISSUE	-
DMS_30626	34319	N	N	N	1	CUSTOMER ISSUE	-
DMS_30627	34320	N	N	N	1	CUSTOMER ISSUE	-
DMS_30628	34321	N	N	N	1	CUSTOMER ISSUE	-
DMS_30629	34322	N	N	N	1	CUSTOMER ISSUE	-
DMS_30630	34323	N	N	N	1	CUSTOMER ISSUE	-
DMS_30631	34324	N	N	N	1	CUSTOMER ISSUE	-
DMS_30632	34325	N	N	N	1	CUSTOMER ISSUE	-
DMS_30633	34326	N	N	N	1	CUSTOMER ISSUE	-
DMS_30634	34327	N	N	N	1	CUSTOMER ISSUE	-
DMS_30635	34328	N	N	N	1	CUSTOMER ISSUE	-
DMS_30636	34329	N	N	N	1	CUSTOMER ISSUE	-
DMS_30637	34330	N	N	N	1	CUSTOMER ISSUE	-
DMS_30640	34331	N	N	N	1	CUSTOMER ISSUE	-
DMS_30641	34332	N	N	N	1	CUSTOMER ISSUE	-
DMS_30642	34333	N	N	N	1	CUSTOMER ISSUE	-
DMS_30643	34334	N	N	N	1	CUSTOMER ISSUE	-
DMS_30644	34335	N	N	N	1	CUSTOMER ISSUE	-
DMS_30645	34336	N	N	N	1	CUSTOMER ISSUE	-
DMS_30646	34337	N	N	N	1	CUSTOMER ISSUE	-
DMS_30647	34338	N	N	N	1	CUSTOMER ISSUE	-
DMS_30648	34339	N	N	N	1	CUSTOMER ISSUE	-
DMS_30649	34340	N	N	N	1	CUSTOMER ISSUE	-
DMS_30650	34341	N	N	N	1	CUSTOMER ISSUE	-
DMS_30651	34342	N	N	N	1	CUSTOMER ISSUE	-
DMS_30652	34343	N	N	N	1	CUSTOMER ISSUE	-
DMS_30653	34344	N	N	N	1	CUSTOMER ISSUE	-
DMS_30656	34345	N	N	N	1	CUSTOMER ISSUE	-
DMS_30657	34346	N	N	N	1	CUSTOMER ISSUE	-
DMS_30658	34347	N	N	N	1	CUSTOMER ISSUE	-
DMS_30659	34348	N	N	N	1	CUSTOMER ISSUE	-
DMS_30660	34349	N	N	N	1	CUSTOMER ISSUE	-
DMS_30661	34350	N	N	N	1	CUSTOMER ISSUE	-
DMS_30662	34351	N	N	N	1	CUSTOMER ISSUE	-
DMS_30663	34352	N	N	N	1	CUSTOMER ISSUE	-
DMS_30664	34353	N	N	N	1	CUSTOMER ISSUE	-
DMS_30665	34354	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30666	34355	N	N	N	1	CUSTOMER ISSUE	-
DMS_30667	34356	N	N	N	1	CUSTOMER ISSUE	-
DMS_30668	34357	N	N	N	1	CUSTOMER ISSUE	-
DMS_30669	34358	N	N	N	1	CUSTOMER ISSUE	-
DMS_30670	34359	N	N	N	1	CUSTOMER ISSUE	-
DMS_30674	34360	N	N	N	1	CUSTOMER ISSUE	-
DMS_30675	34361	N	N	N	1	CUSTOMER ISSUE	-
DMS_30676	34362	N	N	N	1	CUSTOMER ISSUE	-
DMS_30677	34363	N	N	N	1	CUSTOMER ISSUE	-
DMS_30678	34364	N	N	N	1	CUSTOMER ISSUE	-
DMS_30679	34365	N	N	N	1	CUSTOMER ISSUE	-
DMS_30680	34366	N	N	N	1	CUSTOMER ISSUE	-
DMS_30681	34367	N	N	N	1	CUSTOMER ISSUE	-
DMS_30682	34368	N	N	N	1	CUSTOMER ISSUE	-
DMS_30685	34369	N	N	N	1	CUSTOMER ISSUE	-
DMS_30688	34370	N	N	N	1	CUSTOMER ISSUE	-
DMS_30689	34371	N	N	N	1	CUSTOMER ISSUE	-
DMS_30690	34372	N	N	N	1	CUSTOMER ISSUE	-
DMS_30691	34373	N	N	N	1	CUSTOMER ISSUE	-
DMS_30692	34374	N	N	N	1	CUSTOMER ISSUE	-
DMS_30693	34375	N	N	N	1	CUSTOMER ISSUE	-
DMS_30694	34376	N	N	N	1	CUSTOMER ISSUE	-

DMS_30695	34377	N	N	N	1	CUSTOMER ISSUE	-
DMS_30696	34378	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30698	34379	N	N	N	1	CUSTOMER ISSUE	-
DMS_30699	34380	N	N	N	1	CUSTOMER ISSUE	-
DMS_30701	34381	N	N	N	1	CUSTOMER ISSUE	-
DMS_30702	34382	N	N	N	1	CUSTOMER ISSUE	-
DMS_30704	34383	N	N	N	1	CUSTOMER ISSUE	-
DMS_30705	34384	N	N	N	1	CUSTOMER ISSUE	-
DMS_30706	34385	N	N	N	1	CUSTOMER ISSUE	-
DMS_30707	34386	N	N	N	1	CUSTOMER ISSUE	-
DMS_30708	34387	N	N	N	1	CUSTOMER ISSUE	-
DMS_30709	34388	N	N	N	1	CUSTOMER ISSUE	-
DMS_30710	34389	N	N	N	1	CUSTOMER ISSUE	-
DMS_30711	34390	N	N	N	1	CUSTOMER ISSUE	-
DMS_30712	34391	N	N	N	1	CUSTOMER ISSUE	-
DMS_30713	34392	N	N	N	1	CUSTOMER ISSUE	-
DMS_30714	34393	N	N	N	1	CUSTOMER ISSUE	-
DMS_30715	34394	N	N	N	1	CUSTOMER ISSUE	-
DMS_30716	34395	N	N	N	1	CUSTOMER ISSUE	-
DMS_30717	34396	N	N	N	1	CUSTOMER ISSUE	-
DMS_30718	34397	N	N	N	1	CUSTOMER ISSUE	-
DMS_30719	34398	N	N	N	1	CUSTOMER ISSUE	-
DMS_30720	34399	N	N	N	1	CUSTOMER ISSUE	-
DMS_30721	34400	N	N	N	1	CUSTOMER ISSUE	-
DMS_30722	34401	N	N	N	1	CUSTOMER ISSUE	-
DMS_30723	34402	N	N	N	1	CUSTOMER ISSUE	-
DMS_30724	34403	N	N	N	1	CUSTOMER ISSUE	-
DMS_30725	34404	N	N	N	1	CUSTOMER ISSUE	-
DMS_30726	34405	N	N	N	1	CUSTOMER ISSUE	-
DMS_30727	34406	N	N	N	1	CUSTOMER ISSUE	-
DMS_30728	34407	N	N	N	1	CUSTOMER ISSUE	-
DMS_30729	34408	N	N	N	1	CUSTOMER ISSUE	-
DMS_30730	34409	N	N	N	1	CUSTOMER ISSUE	-
DMS_30731	34410	N	N	N	1	CUSTOMER ISSUE	-
DMS_30732	34411	N	N	N	1	CUSTOMER ISSUE	-
DMS_30733	34412	N	N	N	1	CUSTOMER ISSUE	-
DMS_30734	34413	N	N	N	1	CUSTOMER ISSUE	-
DMS_30735	34414	N	N	N	1	CUSTOMER ISSUE	-
DMS_30736	34415	N	N	N	1	CUSTOMER ISSUE	-
DMS_30737	34416	N	N	N	1	CUSTOMER ISSUE	-
DMS_30738	34417	N	N	N	1	CUSTOMER ISSUE	-
DMS_30739	34418	N	N	N	1	CUSTOMER ISSUE	-
DMS_30740	34419	N	N	N	1	CUSTOMER ISSUE	-
DMS_30741	34420	N	N	N	1	CUSTOMER ISSUE	-
DMS_30742	34421	N	N	N	1	CUSTOMER ISSUE	-
DMS_30743	34422	N	N	N	1	CUSTOMER ISSUE	-
DMS_30744	34423	N	N	N	1	CUSTOMER ISSUE	-
DMS_30745	34424	N	N	N	1	CUSTOMER ISSUE	-
DMS_30746	34425	N	N	N	1	CUSTOMER ISSUE	-
DMS_30747	34426	N	N	N	1	CUSTOMER ISSUE	-
DMS_30748	34427	N	N	N	1	CUSTOMER ISSUE	-
DMS_30749	34428	N	N	N	1	CUSTOMER ISSUE	-
DMS_30750	34429	N	N	N	1	CUSTOMER ISSUE	-
DMS_30751	34430	N	N	N	1	CUSTOMER ISSUE	-
DMS_30752	34431	N	N	N	1	CUSTOMER ISSUE	-
DMS_30753	34432	N	N	N	1	CUSTOMER ISSUE	-
DMS_30754	34433	N	N	N	1	CUSTOMER ISSUE	-
DMS_30755	34434	N	N	N	1	CUSTOMER ISSUE	-
DMS_30756	34435	N	N	N	1	CUSTOMER ISSUE	-
DMS_30757	34436	N	N	N	1	CUSTOMER ISSUE	-
DMS_30758	34437	N	N	N	1	CUSTOMER ISSUE	-
DMS_30760	34438	N	N	N	1	CUSTOMER ISSUE	-
DMS_30762	34439	N	N	N	1	CUSTOMER ISSUE	-
DMS_30763	34440	N	N	N	1	CUSTOMER ISSUE	-
DMS_30764	34441	N	N	N	1	CUSTOMER ISSUE	-
DMS_30765	34442	N	N	N	1	CUSTOMER ISSUE	-
DMS_30766	34443	N	N	N	1	CUSTOMER ISSUE	-
DMS_30767	34444	N	N	N	1	CUSTOMER ISSUE	-
DMS_30768	34445	N	N	N	1	CUSTOMER ISSUE	-
DMS_30769	34446	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_30770	34447	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30773	34448	N	N	N	1	CUSTOMER ISSUE	-
DMS_30774	34449	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30776	34450	N	N	N	1	CUSTOMER ISSUE	-
DMS_30778	34451	N	N	N	1	CUSTOMER ISSUE	-
DMS_30779	34452	N	N	N	1	CUSTOMER ISSUE	-
DMS_30780	34453	N	N	N	1	CUSTOMER ISSUE	-
DMS_30781	34454	N	N	N	1	CUSTOMER ISSUE	-
DMS_30782	34455	N	N	N	1	CUSTOMER ISSUE	-
DMS_30783	34456	N	N	N	1	CUSTOMER ISSUE	-

DMS_30784	34457	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_30785	34458	N	N	N	1	CUSTOMER ISSUE	-
DMS_30789	34459	N	N	N	1	CUSTOMER ISSUE	-
DMS_30790	34460	N	N	N	1	CUSTOMER ISSUE	-
DMS_30791	34461	N	N	N	1	CUSTOMER ISSUE	-
DMS_30794	34462	N	N	N	1	CUSTOMER ISSUE	-
DMS_30795	34463	N	N	N	1	CUSTOMER ISSUE	-
DMS_30796	34464	N	N	N	1	CUSTOMER ISSUE	-
DMS_30798	34465	N	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
DMS_30799	34466	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_30806	34467	N	N	N	1	CUSTOMER ISSUE	-
DMS_30807	34468	N	N	N	1	CUSTOMER ISSUE	-
DMS_30810	34469	N	N	N	1	CUSTOMER ISSUE	-
DMS_30811	34470	N	N	N	1	CUSTOMER ISSUE	-
DMS_30812	34471	N	N	N	1	CUSTOMER ISSUE	-
DMS_30813	34472	N	N	N	1	CUSTOMER ISSUE	-
DMS_30814	34473	N	N	N	1	CUSTOMER ISSUE	-
DMS_30816	34474	N	N	N	1	CUSTOMER ISSUE	-
DMS_30817	34475	N	N	N	1	CUSTOMER ISSUE	-
DMS_30818	34476	N	N	N	1	CUSTOMER ISSUE	-
DMS_30819	34477	N	N	N	1	CUSTOMER ISSUE	-
DMS_30823	34478	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30825	34479	N	N	N	1	CUSTOMER ISSUE	-
DMS_30826	34480	N	N	N	1	CUSTOMER ISSUE	-
DMS_30827	34481	N	N	N	1	CUSTOMER ISSUE	-
DMS_30828	34482	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_30882	34483	N	N	N	1	CUSTOMER ISSUE	-
DMS_30883	34484	N	N	N	1	CUSTOMER ISSUE	-
DMS_30885	34485	N	N	N	1	CUSTOMER ISSUE	-
DMS_30886	34486	N	N	N	1	CUSTOMER ISSUE	-
DMS_30887	34487	N	N	N	1	CUSTOMER ISSUE	-
DMS_30888	34488	N	N	N	1	CUSTOMER ISSUE	-
DMS_30889	34489	N	N	N	1	CUSTOMER ISSUE	-
DMS_30890	34490	N	N	N	1	CUSTOMER ISSUE	-
DMS_30891	34491	N	N	N	1	CUSTOMER ISSUE	-
DMS_30892	34492	N	N	N	1	CUSTOMER ISSUE	-
DMS_30893	34493	N	N	N	1	CUSTOMER ISSUE	-
DMS_30894	34494	N	N	N	1	CUSTOMER ISSUE	-
DMS_30895	34495	N	N	N	1	CUSTOMER ISSUE	-
DMS_30896	34496	N	N	N	1	CUSTOMER ISSUE	-
DMS_30897	34497	N	N	N	1	CUSTOMER ISSUE	-
DMS_30898	34498	N	N	N	1	CUSTOMER ISSUE	-
DMS_30899	34499	N	N	N	1	CUSTOMER ISSUE	-
DMS_30900	34500	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_30902	34501	N	N	N	1	CUSTOMER ISSUE	-
DMS_30903	34502	N	N	N	1	CUSTOMER ISSUE	-
DMS_30904	34503	N	N	N	1	CUSTOMER ISSUE	-
DMS_30905	34504	N	N	N	1	CUSTOMER ISSUE	-
DMS_30906	34505	N	N	N	1	CUSTOMER ISSUE	-
DMS_30907	34506	N	N	N	1	CUSTOMER ISSUE	-
DMS_30908	34507	N	N	N	1	CUSTOMER ISSUE	-
DMS_30909	34508	N	N	N	1	CUSTOMER ISSUE	-
DMS_30910	34509	N	N	N	1	CUSTOMER ISSUE	-
DMS_30911	34510	N	N	N	1	CUSTOMER ISSUE	-
DMS_30912	34511	N	N	N	1	CUSTOMER ISSUE	-
DMS_30913	34512	N	N	N	1	CUSTOMER ISSUE	-
DMS_30916	34513	N	N	N	1	CUSTOMER ISSUE	-
DMS_30917	34514	N	N	N	1	CUSTOMER ISSUE	-
DMS_30918	34515	N	N	N	1	CUSTOMER ISSUE	-
DMS_30919	34516	N	N	N	1	CUSTOMER ISSUE	-
DMS_30920	34517	N	N	N	1	CUSTOMER ISSUE	-
DMS_30921	34518	N	N	N	1	CUSTOMER ISSUE	-
DMS_30922	34519	N	N	N	1	CUSTOMER ISSUE	-
DMS_30923	34520	N	N	N	1	CUSTOMER ISSUE	-
DMS_30924	34521	N	N	N	1	CUSTOMER ISSUE	-
DMS_30927	34522	N	N	N	1	CUSTOMER ISSUE	-
DMS_30928	34523	N	N	N	1	CUSTOMER ISSUE	-
DMS_30929	34524	N	N	N	1	CUSTOMER ISSUE	-
DMS_30930	34525	N	N	N	1	CUSTOMER ISSUE	-
DMS_30931	34526	N	N	N	1	CUSTOMER ISSUE	-
DMS_30932	34527	N	N	N	1	CUSTOMER ISSUE	-
DMS_30934	34528	N	N	N	1	CUSTOMER ISSUE	-
DMS_30936	34529	N	N	N	1	CUSTOMER ISSUE	-
DMS_30937	34530	N	N	N	1	CUSTOMER ISSUE	-
DMS_30938	34531	N	N	N	1	CUSTOMER ISSUE	-
DMS_30939	34532	N	N	N	1	CUSTOMER ISSUE	-
DMS_30940	34533	N	N	N	1	CUSTOMER ISSUE	-
DMS_30941	34534	N	N	N	1	CUSTOMER ISSUE	-
DMS_30942	34535	N	N	N	1	CUSTOMER ISSUE	-
DMS_30943	34536	N	N	N	1	CUSTOMER ISSUE	-

DMS_30944	34537	N	N	N	1	CUSTOMER ISSUE	-
DMS_30945	34538	N	N	N	1	CUSTOMER ISSUE	-
DMS_30946	34539	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30947	34540	N	N	N	1	CUSTOMER ISSUE	-
DMS_30948	34541	N	N	N	1	CUSTOMER ISSUE	-
DMS_30949	34542	N	N	N	1	CUSTOMER ISSUE	-
DMS_30950	34543	N	N	N	1	CUSTOMER ISSUE	-
DMS_30951	34544	N	N	N	1	CUSTOMER ISSUE	-
DMS_30952	34545	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30953	34546	N	N	N	1	CUSTOMER ISSUE	-
DMS_30954	34547	N	N	N	1	CUSTOMER ISSUE	-
DMS_30955	34548	N	N	N	1	CUSTOMER ISSUE	-
DMS_30956	34549	N	N	N	1	CUSTOMER ISSUE	-
DMS_30957	34550	N	N	N	1	CUSTOMER ISSUE	-
DMS_30958	34551	N	N	N	1	CUSTOMER ISSUE	-
DMS_30959	34552	N	N	N	1	CUSTOMER ISSUE	-
DMS_30960	34553	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30961	34554	N	N	N	1	CUSTOMER ISSUE	-
DMS_30962	34555	N	N	N	1	CUSTOMER ISSUE	-
DMS_30963	34556	N	N	N	1	CUSTOMER ISSUE	-
DMS_30964	34557	N	N	N	1	CUSTOMER ISSUE	-
DMS_30965	34558	N	N	N	1	CUSTOMER ISSUE	-
DMS_30966	34559	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30967	34560	N	N	N	1	CUSTOMER ISSUE	-
DMS_30968	34561	N	N	N	1	CUSTOMER ISSUE	-
DMS_30969	34562	N	N	N	1	CUSTOMER ISSUE	-
DMS_30970	34563	N	N	N	1	CUSTOMER ISSUE	-
DMS_30971	34564	N	N	N	1	CUSTOMER ISSUE	-
DMS_30972	34565	N	N	N	1	CUSTOMER ISSUE	-
DMS_30973	34566	N	N	N	1	CUSTOMER ISSUE	-
DMS_30974	34567	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30975	34568	N	N	N	1	CUSTOMER ISSUE	-
DMS_30976	34569	N	N	N	1	CUSTOMER ISSUE	-
DMS_30977	34570	N	N	N	1	CUSTOMER ISSUE	-
DMS_30978	34571	N	N	N	1	CUSTOMER ISSUE	-
DMS_30979	34572	N	N	N	1	CUSTOMER ISSUE	-
DMS_30980	34573	N	N	N	1	CUSTOMER ISSUE	-
DMS_30981	34574	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30982	34575	N	N	N	1	CUSTOMER ISSUE	-
DMS_30983	34576	N	N	N	1	CUSTOMER ISSUE	-
DMS_30984	34577	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30985	34578	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30986	34579	N	N	N	1	CUSTOMER ISSUE	-
DMS_30987	34580	N	N	N	1	CUSTOMER ISSUE	-
DMS_30988	34581	N	N	N	1	CUSTOMER ISSUE	-
DMS_30989	34582	N	N	N	1	CUSTOMER ISSUE	-
DMS_30990	34583	N	N	N	1	CUSTOMER ISSUE	-
DMS_30991	34584	N	N	N	1	CUSTOMER ISSUE	-
DMS_30992	34585	N	N	N	1	CUSTOMER ISSUE	-
DMS_30993	34586	N	N	N	1	CUSTOMER ISSUE	-
DMS_30994	34587	N	N	N	1	CUSTOMER ISSUE	-
DMS_30995	34588	N	N	N	1	CUSTOMER ISSUE	-
DMS_30996	34589	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_30997	34590	N	N	N	1	CUSTOMER ISSUE	-
DMS_30998	34591	N	N	N	1	CUSTOMER ISSUE	-
DMS_30999	34592	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_31000	34593	N	N	N	1	CUSTOMER ISSUE	-
DMS_31001	34594	N	N	N	1	CUSTOMER ISSUE	-
DMS_31002	34595	N	N	N	1	CUSTOMER ISSUE	-
DMS_31003	34596	N	N	N	1	CUSTOMER ISSUE	-
DMS_31004	34597	N	N	N	1	CUSTOMER ISSUE	-
DMS_31005	34598	N	N	N	1	CUSTOMER ISSUE	-
DMS_31006	34599	N	N	N	1	CUSTOMER ISSUE	-
DMS_31007	34600	N	N	N	1	CUSTOMER ISSUE	-
DMS_31008	34601	N	N	N	1	CUSTOMER ISSUE	-
DMS_31009	34602	N	N	N	1	CUSTOMER ISSUE	-
DMS_31010	34603	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_31011	34604	N	N	N	1	CUSTOMER ISSUE	-
DMS_31012	34605	N	N	N	1	CUSTOMER ISSUE	-
DMS_31013	34606	N	N	N	1	CUSTOMER ISSUE	-
DMS_31014	34607	N	N	N	1	CUSTOMER ISSUE	-
DMS_31015	34608	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_31016	34609	N	N	N	1	CUSTOMER ISSUE	-
DMS_31017	34610	N	N	N	1	CUSTOMER ISSUE	-
DMS_31018	34611	N	N	N	1	CUSTOMER ISSUE	-
DMS_31019	34612	N	N	N	1	CUSTOMER ISSUE	-
DMS_31021	34613	N	N	N	1	CUSTOMER ISSUE	-
DMS_31022	34614	N	N	N	1	CUSTOMER ISSUE	-
DMS_31023	34615	N	N	N	1	CUSTOMER ISSUE	-
DMS_31024	34616	N	N	N	1	CUSTOMER ISSUE	-

DMS_31025	34617	N	N	N	1	CUSTOMER ISSUE	-
DMS_31026	34618	N	N	N	1	CUSTOMER ISSUE	-
DMS_31027	34619	N	N	N	1	CUSTOMER ISSUE	-
DMS_31028	34620	N	N	N	1	CUSTOMER ISSUE	-
DMS_31029	34621	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_31030	34622	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_31031	34623	N	N	N	1	CUSTOMER ISSUE	-
DMS_31032	34624	N	N	N	1	CUSTOMER ISSUE	-
DMS_31033	34625	N	N	N	1	CUSTOMER ISSUE	-
DMS_31034	34626	N	N	N	1	CUSTOMER ISSUE	-
DMS_31035	34627	N	N	N	1	CUSTOMER ISSUE	-
DMS_31036	34628	N	N	N	1	CUSTOMER ISSUE	-
DMS_31037	34629	N	N	N	1	CUSTOMER ISSUE	-
DMS_31038	34630	N	N	N	1	CUSTOMER ISSUE	-
DMS_31039	34631	N	N	N	1	CUSTOMER ISSUE	-
DMS_31040	34632	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_31041	34633	N	N	N	1	CUSTOMER ISSUE	-
DMS_31042	34634	N	N	N	1	CUSTOMER ISSUE	-
DMS_31043	34635	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_31044	34636	N	N	N	1	CUSTOMER ISSUE	-
DMS_31046	34637	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_31047	34638	N	N	N	1	CUSTOMER ISSUE	-
DMS_31048	34639	N	N	N	1	CUSTOMER ISSUE	-
DMS_31049	34640	N	N	N	1	CUSTOMER ISSUE	-
DMS_31050	34641	N	N	N	1	CUSTOMER ISSUE	-
DMS_31051	34642	N	N	N	1	CUSTOMER ISSUE	-
DMS_31052	34643	N	N	N	1	CUSTOMER ISSUE	-
DMS_31053	34644	N	N	N	1	CUSTOMER ISSUE	-
DMS_31054	34645	N	N	N	1	CUSTOMER ISSUE	-
DMS_31055	34646	N	N	N	1	CUSTOMER ISSUE	-
DMS_31056	34647	N	N	N	1	CUSTOMER ISSUE	-
DMS_31057	34648	N	N	N	1	CUSTOMER ISSUE	-
DMS_31058	34649	N	N	N	1	CUSTOMER ISSUE	-
DMS_31059	34650	N	N	N	1	CUSTOMER ISSUE	-
DMS_31060	34651	N	N	N	1	CUSTOMER ISSUE	-
DMS_31061	34652	N	N	N	1	CUSTOMER ISSUE	-
DMS_31062	34653	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_31064	34654	N	N	N	1	CUSTOMER ISSUE	-
DMS_31065	34655	N	N	N	1	CUSTOMER ISSUE	-
DMS_31066	34656	N	N	N	1	CUSTOMER ISSUE	-
DMS_31067	34657	N	N	N	1	CUSTOMER ISSUE	-
DMS_31068	34658	N	N	N	1	CUSTOMER ISSUE	-
DMS_31069	34659	N	N	N	1	CUSTOMER ISSUE	-
DMS_31070	34660	N	N	N	1	CUSTOMER ISSUE	-
DMS_31071	34661	N	N	N	1	CUSTOMER ISSUE	-
DMS_31072	34662	N	N	N	1	CUSTOMER ISSUE	-
DMS_31073	34663	N	N	N	1	CUSTOMER ISSUE	-
DMS_31074	34664	N	N	N	1	CUSTOMER ISSUE	-
DMS_31076	34665	N	N	N	1	CUSTOMER ISSUE	-
DMS_31077	34666	N	N	N	1	CUSTOMER ISSUE	-
DMS_31078	34667	N	N	N	1	CUSTOMER ISSUE	-
DMS_31079	34668	N	N	N	1	CUSTOMER ISSUE	-
DMS_31080	34669	N	N	N	1	CUSTOMER ISSUE	-
DMS_31081	34670	N	N	N	1	CUSTOMER ISSUE	-
DMS_31082	34671	N	N	N	1	CUSTOMER ISSUE	-
DMS_31083	34672	N	N	N	1	CUSTOMER ISSUE	-
DMS_31084	34673	N	N	N	1	CUSTOMER ISSUE	-
DMS_31085	34674	N	N	N	1	CUSTOMER ISSUE	-
DMS_31086	34675	N	N	N	1	CUSTOMER ISSUE	-
DMS_31087	34676	N	N	N	1	CUSTOMER ISSUE	-
DMS_31088	34677	N	N	N	1	CUSTOMER ISSUE	-
DMS_31089	34678	N	N	N	1	CUSTOMER ISSUE	-
DMS_31090	34679	N	N	N	1	CUSTOMER ISSUE	-
DMS_31091	34680	N	N	N	1	CUSTOMER ISSUE	-
DMS_31092	34681	N	N	N	1	CUSTOMER ISSUE	-
DMS_31093	34682	N	N	N	1	CUSTOMER ISSUE	-
DMS_31094	34683	N	N	N	1	CUSTOMER ISSUE	-
DMS_31095	34684	N	N	N	1	CUSTOMER ISSUE	-
DMS_31096	34685	N	N	N	1	CUSTOMER ISSUE	-
DMS_31097	34686	N	N	N	1	CUSTOMER ISSUE	-
DMS_31098	34687	N	N	N	1	CUSTOMER ISSUE	-
DMS_31099	34688	N	N	N	1	CUSTOMER ISSUE	-
DMS_31100	34689	N	N	N	1	CUSTOMER ISSUE	-
DMS_31101	34690	N	N	N	1	CUSTOMER ISSUE	-
DMS_31102	34691	N	N	N	1	CUSTOMER ISSUE	-
DMS_31103	34692	N	N	N	1	CUSTOMER ISSUE	-
DMS_31104	34693	N	N	N	1	CUSTOMER ISSUE	-
DMS_31105	34694	N	N	N	1	CUSTOMER ISSUE	-
DMS_31106	34695	N	N	N	1	CUSTOMER ISSUE	-
DMS_31107	34696	N	N	N	1	CUSTOMER ISSUE	-

DMS_31108	34697	N	N	N	1	CUSTOMER ISSUE	-
DMS_31109	34698	N	N	N	1	CUSTOMER ISSUE	-
DMS_31110	34699	N	N	N	1	CUSTOMER ISSUE	-
DMS_31111	34700	N	N	N	1	CUSTOMER ISSUE	-
DMS_31112	34701	N	N	N	1	CUSTOMER ISSUE	-
DMS_31113	34702	N	N	N	1	CUSTOMER ISSUE	-
DMS_31114	34703	N	N	N	1	CUSTOMER ISSUE	-
DMS_31115	34704	N	N	N	1	CUSTOMER ISSUE	-
DMS_31116	34705	N	N	N	1	CUSTOMER ISSUE	-
DMS_31117	34706	N	N	N	1	CUSTOMER ISSUE	-
DMS_31118	34707	N	N	N	1	CUSTOMER ISSUE	-
DMS_31119	34708	N	N	N	1	CUSTOMER ISSUE	-
DMS_31120	34709	N	N	N	1	CUSTOMER ISSUE	-
DMS_31121	34710	N	N	N	1	CUSTOMER ISSUE	-
DMS_31122	34711	N	N	N	1	CUSTOMER ISSUE	-
DMS_31123	34712	N	N	N	1	CUSTOMER ISSUE	-
DMS_31124	34713	N	N	N	1	CUSTOMER ISSUE	-
DMS_31125	34714	N	N	N	1	CUSTOMER ISSUE	-
DMS_31126	34715	N	N	N	1	CUSTOMER ISSUE	-
DMS_31127	34716	N	N	N	1	CUSTOMER ISSUE	-
DMS_31128	34717	N	N	N	1	CUSTOMER ISSUE	-
DMS_31129	34718	N	N	N	1	CUSTOMER ISSUE	-
DMS_31130	34719	N	N	N	1	CUSTOMER ISSUE	-
DMS_31131	34720	N	N	N	1	CUSTOMER ISSUE	-
DMS_31132	34721	N	N	N	1	CUSTOMER ISSUE	-
DMS_31133	34722	N	N	N	1	CUSTOMER ISSUE	-
DMS_31134	34723	N	N	N	1	CUSTOMER ISSUE	-
DMS_31135	34724	N	N	N	1	CUSTOMER ISSUE	-
DMS_31136	34725	N	N	N	1	CUSTOMER ISSUE	-
DMS_31137	34726	N	N	N	1	CUSTOMER ISSUE	-
DMS_31138	34727	N	N	N	1	CUSTOMER ISSUE	-
DMS_31139	34728	N	N	N	1	CUSTOMER ISSUE	-
DMS_31140	34729	N	N	N	1	CUSTOMER ISSUE	-
DMS_31141	34730	N	N	N	1	CUSTOMER ISSUE	-
DMS_31142	34731	N	N	N	1	CUSTOMER ISSUE	-
DMS_31143	34732	N	N	N	1	CUSTOMER ISSUE	-
DMS_31144	34733	N	N	N	1	CUSTOMER ISSUE	-
DMS_31145	34734	N	N	N	1	CUSTOMER ISSUE	-
DMS_31146	34735	N	N	N	1	CUSTOMER ISSUE	-
DMS_31147	34736	N	N	N	1	CUSTOMER ISSUE	-
DMS_31148	34737	N	N	N	1	CUSTOMER ISSUE	-
DMS_31149	34738	N	N	N	1	CUSTOMER ISSUE	-
DMS_31150	34739	N	N	N	1	CUSTOMER ISSUE	-
DMS_31151	34740	N	N	N	1	CUSTOMER ISSUE	-
DMS_31152	34741	N	N	N	1	CUSTOMER ISSUE	-
DMS_31153	34742	N	N	N	1	CUSTOMER ISSUE	-
DMS_31154	34743	N	N	N	1	CUSTOMER ISSUE	-
DMS_31155	34744	N	N	N	1	CUSTOMER ISSUE	-
DMS_31156	34745	N	N	N	1	CUSTOMER ISSUE	-
DMS_31157	34746	N	N	N	1	CUSTOMER ISSUE	-
DMS_31158	34747	N	N	N	1	CUSTOMER ISSUE	-
DMS_31159	34748	N	N	N	1	CUSTOMER ISSUE	-
DMS_31162	34749	N	N	N	1	CUSTOMER ISSUE	-
DMS_31163	34750	N	N	N	1	CUSTOMER ISSUE	-
DMS_31164	34751	N	N	N	1	CUSTOMER ISSUE	-
DMS_31165	34752	N	N	N	1	CUSTOMER ISSUE	-
DMS_31174	34753	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_31175	34754	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_31176	34755	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_31177	34756	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_31178	34757	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_31179	34758	N	N	N	1	CUSTOMER ISSUE	-
DMS_31180	34759	N	N	N	1	CUSTOMER ISSUE	-
DMS_31181	34760	N	N	N	1	CUSTOMER ISSUE	-
DMS_31182	34761	N	N	N	1	CUSTOMER ISSUE	-
DMS_31183	34762	N	N	N	1	CUSTOMER ISSUE	-
DMS_31184	34763	N	N	N	1	CUSTOMER ISSUE	-
DMS_31185	34764	N	N	N	1	CUSTOMER ISSUE	-
DMS_31186	34765	N	N	N	1	CUSTOMER ISSUE	-
DMS_31187	34766	N	N	N	1	CUSTOMER ISSUE	-
DMS_31189	34767	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_31193	34768	N	N	N	1	CUSTOMER ISSUE	-
DMS_31194	34769	N	N	N	1	CUSTOMER ISSUE	-
DMS_31195	34770	N	N	N	1	CUSTOMER ISSUE	-
DMS_31196	34771	N	N	N	1	CUSTOMER ISSUE	-
DMS_31197	34772	N	N	N	1	CUSTOMER ISSUE	-
DMS_31198	34773	N	N	N	1	CUSTOMER ISSUE	-
DMS_31199	34774	N	N	N	1	CUSTOMER ISSUE	-
DMS_31200	34775	N	N	N	1	CUSTOMER ISSUE	-
DMS_31201	34776	N	N	N	1	CUSTOMER ISSUE	-

DMS_31202	34777	N	N	N	1	CUSTOMER ISSUE	-
DMS_31203	34778	N	N	N	1	CUSTOMER ISSUE	-
DMS_31204	34779	N	N	N	1	CUSTOMER ISSUE	-
DMS_31205	34780	N	N	N	1	CUSTOMER ISSUE	-
DMS_31206	34781	N	N	N	1	CUSTOMER ISSUE	-
DMS_31207	34782	N	N	N	1	CUSTOMER ISSUE	-
DMS_31208	34783	N	N	N	1	CUSTOMER ISSUE	-
DMS_31209	34784	N	N	N	1	CUSTOMER ISSUE	-
DMS_31210	34785	N	N	N	1	CUSTOMER ISSUE	-
DMS_31211	34786	N	N	N	1	CUSTOMER ISSUE	-
DMS_31212	34787	N	N	N	1	CUSTOMER ISSUE	-
DMS_31213	34788	N	N	N	1	CUSTOMER ISSUE	-
DMS_31214	34789	N	N	N	1	CUSTOMER ISSUE	-
DMS_31215	34790	N	N	N	1	CUSTOMER ISSUE	-
DMS_31216	34791	N	N	N	1	CUSTOMER ISSUE	-
DMS_31217	34792	N	N	N	1	CUSTOMER ISSUE	-
DMS_31218	34793	N	N	N	1	CUSTOMER ISSUE	-
DMS_31219	34794	N	N	N	1	CUSTOMER ISSUE	-
DMS_31220	34795	N	N	N	1	CUSTOMER ISSUE	-
DMS_31221	34796	N	N	N	1	CUSTOMER ISSUE	-
DMS_31222	34797	N	N	N	1	CUSTOMER ISSUE	-
DMS_31223	34798	N	N	N	1	CUSTOMER ISSUE	-
DMS_31224	34799	N	N	N	1	CUSTOMER ISSUE	-
DMS_31225	34800	N	N	N	1	CUSTOMER ISSUE	-
DMS_31226	34801	N	N	N	1	CUSTOMER ISSUE	-
DMS_31227	34802	N	N	N	1	CUSTOMER ISSUE	-
DMS_31228	34803	N	N	N	1	CUSTOMER ISSUE	-
DMS_31229	34804	N	N	N	1	CUSTOMER ISSUE	-
DMS_31230	34805	N	N	N	1	CUSTOMER ISSUE	-
DMS_31231	34806	N	N	N	1	CUSTOMER ISSUE	-
DMS_31232	34807	N	N	N	1	CUSTOMER ISSUE	-
DMS_31233	34808	N	N	N	1	CUSTOMER ISSUE	-
DMS_31234	34809	N	N	N	1	CUSTOMER ISSUE	-
DMS_31235	34810	N	N	N	1	CUSTOMER ISSUE	-
DMS_31236	34811	N	N	N	1	CUSTOMER ISSUE	-
DMS_31237	34812	N	N	N	1	CUSTOMER ISSUE	-
DMS_31238	34813	N	N	N	1	CUSTOMER ISSUE	-
DMS_31239	34814	N	N	N	1	CUSTOMER ISSUE	-
DMS_31240	34815	N	N	N	1	CUSTOMER ISSUE	-
DMS_31241	34816	N	N	N	1	CUSTOMER ISSUE	-
DMS_31242	34817	N	N	N	1	CUSTOMER ISSUE	-
DMS_31243	34818	N	N	N	1	CUSTOMER ISSUE	-
DMS_31244	34819	N	N	N	1	CUSTOMER ISSUE	-
DMS_31245	34820	N	N	N	1	CUSTOMER ISSUE	-
DMS_31246	34821	N	N	N	1	CUSTOMER ISSUE	-
DMS_31247	34822	N	N	N	1	CUSTOMER ISSUE	-
DMS_31248	34823	N	N	N	1	CUSTOMER ISSUE	-
DMS_31249	34824	N	N	N	1	CUSTOMER ISSUE	-
DMS_31250	34825	N	N	N	1	CUSTOMER ISSUE	-
DMS_31251	34826	N	N	N	1	CUSTOMER ISSUE	-
DMS_31252	34827	N	N	N	1	CUSTOMER ISSUE	-
DMS_31253	34828	N	N	N	1	CUSTOMER ISSUE	-
DMS_31254	34829	N	N	N	1	CUSTOMER ISSUE	-
DMS_31255	34830	N	N	N	1	CUSTOMER ISSUE	-
DMS_31256	34831	N	N	N	1	CUSTOMER ISSUE	-
DMS_31257	34832	N	N	N	1	CUSTOMER ISSUE	-
DMS_31258	34833	N	N	N	1	CUSTOMER ISSUE	-
DMS_31259	34834	N	N	N	1	CUSTOMER ISSUE	-
DMS_31260	34835	N	N	N	1	CUSTOMER ISSUE	-
DMS_31261	34836	N	N	N	1	CUSTOMER ISSUE	-
DMS_31262	34837	N	N	N	1	CUSTOMER ISSUE	-
DMS_31263	34838	N	N	N	1	CUSTOMER ISSUE	-
DMS_31264	34839	N	N	N	1	CUSTOMER ISSUE	-
DMS_31265	34840	N	N	N	1	CUSTOMER ISSUE	-
DMS_31266	34841	N	N	N	1	CUSTOMER ISSUE	-
DMS_31267	34842	N	N	N	1	CUSTOMER ISSUE	-
DMS_31268	34843	N	N	N	1	CUSTOMER ISSUE	-
DMS_31269	34844	N	N	N	1	CUSTOMER ISSUE	-
DMS_31270	34845	N	N	N	1	CUSTOMER ISSUE	-
DMS_31271	34846	N	N	N	1	CUSTOMER ISSUE	-
DMS_31272	34847	N	N	N	1	CUSTOMER ISSUE	-
DMS_31273	34848	N	N	N	1	CUSTOMER ISSUE	-
DMS_31274	34849	N	N	N	1	CUSTOMER ISSUE	-
DMS_31275	34850	N	N	N	1	CUSTOMER ISSUE	-
DMS_31276	34851	N	N	N	1	CUSTOMER ISSUE	-
DMS_31277	34852	N	N	N	1	CUSTOMER ISSUE	-
DMS_31278	34853	N	N	N	1	CUSTOMER ISSUE	-
DMS_31279	34854	N	N	N	1	CUSTOMER ISSUE	-
DMS_31280	34855	N	N	N	1	CUSTOMER ISSUE	-
DMS_31281	34856	N	N	N	1	CUSTOMER ISSUE	-

DMS_31283	34857	N	N	N	1	CUSTOMER ISSUE	-
DMS_31284	34858	N	N	N	1	CUSTOMER ISSUE	-
DMS_31285	34859	N	N	N	1	CUSTOMER ISSUE	-
DMS_31288	34860	N	N	N	1	CUSTOMER ISSUE	-
DMS_31289	34861	N	N	N	1	CUSTOMER ISSUE	-
DMS_31290	34862	N	N	N	1	CUSTOMER ISSUE	-
DMS_31291	34863	N	N	N	1	CUSTOMER ISSUE	-
DMS_31292	34864	N	N	N	1	CUSTOMER ISSUE	-
DMS_31294	34865	N	N	N	1	CUSTOMER ISSUE	-
DMS_31295	34866	N	N	N	1	CUSTOMER ISSUE	-
DMS_31296	34867	N	N	N	1	CUSTOMER ISSUE	-
DMS_31297	34868	N	N	N	1	CUSTOMER ISSUE	-
DMS_31298	34869	N	N	N	1	CUSTOMER ISSUE	-
DMS_31299	34870	N	N	N	1	CUSTOMER ISSUE	-
DMS_31300	34871	N	N	N	1	CUSTOMER ISSUE	-
DMS_31301	34872	N	N	N	1	CUSTOMER ISSUE	-
DMS_31302	34873	N	N	N	1	CUSTOMER ISSUE	-
DMS_31303	34874	N	N	N	1	CUSTOMER ISSUE	-
DMS_31304	34875	N	N	N	1	CUSTOMER ISSUE	-
DMS_31305	34876	N	N	N	1	CUSTOMER ISSUE	-
DMS_31306	34877	N	N	N	1	CUSTOMER ISSUE	-
DMS_31307	34878	N	N	N	1	CUSTOMER ISSUE	-
DMS_31308	34879	N	N	N	1	CUSTOMER ISSUE	-
DMS_31309	34880	N	N	N	1	CUSTOMER ISSUE	-
DMS_31310	34881	N	N	N	1	CUSTOMER ISSUE	-
DMS_31311	34882	N	N	N	1	CUSTOMER ISSUE	-
DMS_31312	34883	N	N	N	1	CUSTOMER ISSUE	-
DMS_31316	34884	N	N	N	1	CUSTOMER ISSUE	-
DMS_31317	34885	N	N	N	1	CUSTOMER ISSUE	-
DMS_31318	34886	N	N	N	1	CUSTOMER ISSUE	-
DMS_31322	34887	N	N	N	1	CUSTOMER ISSUE	-
DMS_31323	34888	N	N	N	1	CUSTOMER ISSUE	-
DMS_31324	34889	N	N	N	1	CUSTOMER ISSUE	-
DMS_31325	34890	N	N	N	1	CUSTOMER ISSUE	-
DMS_31326	34891	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_31327	34892	N	N	N	1	CUSTOMER ISSUE	-
DMS_31328	34893	N	N	N	1	CUSTOMER ISSUE	-
DMS_31329	34894	N	N	N	1	CUSTOMER ISSUE	-
DMS_31330	34895	N	N	N	1	CUSTOMER ISSUE	-
DMS_31331	34896	N	N	N	1	CUSTOMER ISSUE	-
DMS_31334	34897	N	N	N	2	CUSTOMER ISSUE	-
DMS_31336	34898	N	N	N	1	CUSTOMER ISSUE	-
DMS_31337	34899	N	N	N	1	CUSTOMER ISSUE	-
DMS_31338	34900	N	N	N	1	CUSTOMER ISSUE	-
DMS_31339	34901	N	N	N	1	CUSTOMER ISSUE	-
DMS_31340	34902	N	N	N	1	CUSTOMER ISSUE	-
DMS_31341	34903	N	N	N	1	CUSTOMER ISSUE	-
DMS_31342	34904	N	N	N	1	CUSTOMER ISSUE	-
DMS_31343	34905	N	N	N	1	CUSTOMER ISSUE	-
DMS_31344	34906	N	N	N	1	CUSTOMER ISSUE	-
DMS_31345	34907	N	N	N	1	CUSTOMER ISSUE	-
DMS_31346	34908	N	N	N	1	CUSTOMER ISSUE	-
DMS_31347	34909	N	N	N	1	CUSTOMER ISSUE	-
DMS_31348	34910	N	N	N	1	CUSTOMER ISSUE	-
DMS_31349	34911	N	N	N	1	CUSTOMER ISSUE	-
DMS_31351	34912	N	N	N	1	CUSTOMER ISSUE	-
DMS_31356	34913	N	N	N	1	CUSTOMER ISSUE	-
DMS_31358	34914	N	N	N	1	CUSTOMER ISSUE	-
DMS_31359	34915	N	N	N	1	CUSTOMER ISSUE	-
DMS_31360	34916	N	N	N	1	CUSTOMER ISSUE	-
DMS_31361	34917	N	N	N	1	CUSTOMER ISSUE	-
DMS_31362	34918	N	N	N	1	CUSTOMER ISSUE	-
DMS_31363	34919	N	N	N	1	CUSTOMER ISSUE	-
DMS_31364	34920	N	N	N	1	CUSTOMER ISSUE	-
DMS_31365	34921	N	N	N	1	CUSTOMER ISSUE	-
DMS_31366	34922	N	N	N	1	CUSTOMER ISSUE	-
DMS_31367	34923	N	N	N	1	CUSTOMER ISSUE	-
DMS_31368	34924	N	N	N	1	CUSTOMER ISSUE	-
DMS_31369	34925	N	N	N	1	CUSTOMER ISSUE	-
DMS_31371	34926	N	N	N	1	CUSTOMER ISSUE	-
DMS_31372	34927	N	N	N	1	CUSTOMER ISSUE	-
DMS_31373	34928	N	N	N	1	CUSTOMER ISSUE	-
DMS_31374	34929	N	N	N	1	CUSTOMER ISSUE	-
DMS_31375	34930	N	N	N	1	CUSTOMER ISSUE	-
DMS_31377	34931	N	N	N	1	CUSTOMER ISSUE	-
DMS_31393	34932	N	N	N	1	CUSTOMER ISSUE	-
DMS_31394	34933	N	N	N	1	CUSTOMER ISSUE	-
DMS_31395	34934	N	N	N	1	CUSTOMER ISSUE	-
DMS_31396	34935	N	N	N	1	CUSTOMER ISSUE	-
DMS_31397	34936	N	N	N	1	CUSTOMER ISSUE	-

DMS_31398	34937	N	N	N	1	CUSTOMER ISSUE	-
DMS_31399	34938	N	N	N	1	CUSTOMER ISSUE	-
DMS_31400	34939	N	N	N	1	CUSTOMER ISSUE	-
DMS_31401	34940	N	N	N	1	CUSTOMER ISSUE	-
DMS_31402	34941	N	N	N	1	CUSTOMER ISSUE	-
DMS_31403	34942	N	N	N	1	CUSTOMER ISSUE	-
DMS_31404	34943	N	N	N	1	CUSTOMER ISSUE	-
DMS_31406	34944	N	N	N	1	CUSTOMER ISSUE	-
DMS_31407	34945	N	N	N	1	CUSTOMER ISSUE	-
DMS_31408	34946	N	N	N	1	CUSTOMER ISSUE	-
DMS_31409	34947	N	N	N	1	CUSTOMER ISSUE	-
DMS_31410	34948	N	N	N	1	CUSTOMER ISSUE	-
DMS_31411	34949	N	N	N	1	CUSTOMER ISSUE	-
DMS_31412	34950	N	N	N	2	CUSTOMER ISSUE	-
DMS_31413	34951	N	N	N	1	CUSTOMER ISSUE	-
DMS_31414	34952	N	N	N	1	CUSTOMER ISSUE	-
DMS_31415	34953	N	N	N	1	CUSTOMER ISSUE	-
DMS_31416	34954	N	N	N	1	CUSTOMER ISSUE	-
DMS_31417	34955	N	N	N	1	CUSTOMER ISSUE	-
DMS_31418	34956	N	N	N	1	CUSTOMER ISSUE	-
DMS_31419	34957	N	N	N	1	CUSTOMER ISSUE	-
DMS_31420	34958	N	N	N	1	CUSTOMER ISSUE	-
DMS_31421	34959	N	N	N	1	CUSTOMER ISSUE	-
DMS_31422	34960	N	N	N	1	CUSTOMER ISSUE	-
DMS_31423	34961	N	N	N	1	CUSTOMER ISSUE	-
DMS_31424	34962	N	N	N	1	CUSTOMER ISSUE	-
DMS_31425	34963	N	N	N	1	CUSTOMER ISSUE	-
DMS_31426	34964	N	N	N	1	CUSTOMER ISSUE	-
DMS_31427	34965	N	N	N	1	CUSTOMER ISSUE	-
DMS_31428	34966	N	N	N	1	CUSTOMER ISSUE	-
DMS_31429	34967	N	N	N	1	CUSTOMER ISSUE	-
DMS_31430	34968	N	N	N	1	CUSTOMER ISSUE	-
DMS_31431	34969	N	N	N	1	CUSTOMER ISSUE	-
DMS_31432	34970	N	N	N	1	CUSTOMER ISSUE	-
DMS_31433	34971	N	N	N	1	CUSTOMER ISSUE	-
DMS_31434	34972	N	N	N	1	CUSTOMER ISSUE	-
DMS_31435	34973	N	N	N	1	CUSTOMER ISSUE	-
DMS_31436	34974	N	N	N	1	CUSTOMER ISSUE	-
DMS_31437	34975	N	N	N	1	CUSTOMER ISSUE	-
DMS_31438	34976	N	N	N	1	CUSTOMER ISSUE	-
DMS_31439	34977	N	N	N	1	CUSTOMER ISSUE	-
DMS_31440	34978	N	N	N	1	CUSTOMER ISSUE	-
DMS_31441	34979	N	N	N	1	CUSTOMER ISSUE	-
DMS_31442	34980	N	N	N	1	CUSTOMER ISSUE	-
DMS_31443	34981	N	N	N	1	CUSTOMER ISSUE	-
DMS_31444	34982	N	N	N	1	CUSTOMER ISSUE	-
DMS_31445	34983	N	N	N	1	CUSTOMER ISSUE	-
DMS_31446	34984	N	N	N	1	CUSTOMER ISSUE	-
DMS_31447	34985	N	N	N	1	CUSTOMER ISSUE	-
DMS_31448	34986	N	N	N	1	CUSTOMER ISSUE	-
DMS_31449	34987	N	N	N	1	CUSTOMER ISSUE	-
DMS_31450	34988	N	N	N	1	CUSTOMER ISSUE	-
DMS_31451	34989	N	N	N	1	CUSTOMER ISSUE	-
DMS_31452	34990	N	N	N	1	CUSTOMER ISSUE	-
DMS_31453	34991	N	N	N	1	CUSTOMER ISSUE	-
DMS_31454	34992	N	N	N	1	CUSTOMER ISSUE	-
DMS_31455	34993	N	N	N	1	CUSTOMER ISSUE	-
DMS_31456	34994	N	N	N	1	CUSTOMER ISSUE	-
DMS_31457	34995	N	N	N	1	CUSTOMER ISSUE	-
DMS_31458	34996	N	N	N	1	CUSTOMER ISSUE	-
DMS_31459	34997	N	N	N	1	CUSTOMER ISSUE	-
DMS_31460	34998	N	N	N	1	CUSTOMER ISSUE	-
DMS_31461	34999	N	N	N	1	CUSTOMER ISSUE	-
DMS_31462	35000	N	N	N	1	CUSTOMER ISSUE	-
DMS_31463	35001	N	N	N	1	CUSTOMER ISSUE	-
DMS_31464	35002	N	N	N	1	CUSTOMER ISSUE	-
DMS_31465	35003	N	N	N	1	CUSTOMER ISSUE	-
DMS_31466	35004	N	N	N	1	CUSTOMER ISSUE	-
DMS_31467	35005	N	N	N	1	CUSTOMER ISSUE	-
DMS_31468	35006	N	N	N	1	CUSTOMER ISSUE	-
DMS_31469	35007	N	N	N	1	CUSTOMER ISSUE	-
DMS_31470	35008	N	N	N	1	CUSTOMER ISSUE	-
DMS_31471	35009	N	N	N	1	CUSTOMER ISSUE	-
DMS_31472	35010	N	N	N	1	CUSTOMER ISSUE	-
DMS_31473	35011	N	N	N	1	CUSTOMER ISSUE	-
DMS_31474	35012	N	N	N	1	CUSTOMER ISSUE	-
DMS_31475	35013	N	N	N	1	CUSTOMER ISSUE	-
DMS_31476	35014	N	N	N	1	CUSTOMER ISSUE	-
DMS_31477	35015	N	N	N	1	CUSTOMER ISSUE	-
DMS_31478	35016	N	N	N	1	CUSTOMER ISSUE	-

DMS_31479	35017	N	N	N	1	CUSTOMER ISSUE	-
DMS_31480	35018	N	N	N	1	CUSTOMER ISSUE	-
DMS_31481	35019	N	N	N	1	CUSTOMER ISSUE	-
DMS_31482	35020	N	N	N	1	CUSTOMER ISSUE	-
DMS_31483	35021	N	N	N	1	CUSTOMER ISSUE	-
DMS_31484	35022	N	N	N	1	CUSTOMER ISSUE	-
DMS_31485	35023	N	N	N	1	CUSTOMER ISSUE	-
DMS_31488	35024	N	N	N	1	CUSTOMER ISSUE	-
DMS_31489	35025	N	N	N	1	CUSTOMER ISSUE	-
DMS_31490	35026	N	N	N	1	CUSTOMER ISSUE	-
DMS_31491	35027	N	N	N	1	CUSTOMER ISSUE	-
DMS_31492	35028	N	N	N	1	CUSTOMER ISSUE	-
DMS_31493	35029	N	N	N	1	CUSTOMER ISSUE	-
DMS_31494	35030	N	N	N	1	CUSTOMER ISSUE	-
DMS_31495	35031	N	N	N	1	CUSTOMER ISSUE	-
DMS_31496	35032	N	N	N	1	CUSTOMER ISSUE	-
DMS_31497	35033	N	N	N	1	CUSTOMER ISSUE	-
DMS_31498	35034	N	N	N	1	CUSTOMER ISSUE	-
DMS_31499	35035	N	N	N	1	CUSTOMER ISSUE	-
DMS_31500	35036	N	N	N	1	CUSTOMER ISSUE	-
DMS_31501	35037	N	N	N	1	CUSTOMER ISSUE	-
DMS_31502	35038	N	N	N	1	CUSTOMER ISSUE	-
DMS_31503	35039	N	N	N	1	CUSTOMER ISSUE	-
DMS_31504	35040	N	N	N	2	CUSTOMER ISSUE	-
DMS_31505	35041	N	N	N	1	CUSTOMER ISSUE	-
DMS_31506	35042	N	N	N	1	CUSTOMER ISSUE	-
DMS_31507	35043	N	N	N	1	CUSTOMER ISSUE	-
DMS_31508	35044	N	N	N	1	CUSTOMER ISSUE	-
DMS_31509	35045	N	N	N	1	CUSTOMER ISSUE	-
DMS_31510	35046	N	N	N	1	CUSTOMER ISSUE	-
DMS_31511	35047	N	N	N	1	CUSTOMER ISSUE	-
DMS_31512	35048	N	N	N	1	CUSTOMER ISSUE	-
DMS_31513	35049	N	N	N	1	CUSTOMER ISSUE	-
DMS_31514	35050	N	N	N	1	CUSTOMER ISSUE	-
DMS_31515	35051	N	N	N	1	CUSTOMER ISSUE	-
DMS_31516	35052	N	N	N	1	CUSTOMER ISSUE	-
DMS_31517	35053	N	N	N	1	CUSTOMER ISSUE	-
DMS_31518	35054	N	N	N	1	CUSTOMER ISSUE	-
DMS_31519	35055	N	N	N	1	CUSTOMER ISSUE	-
DMS_31520	35056	N	N	N	1	CUSTOMER ISSUE	-
DMS_31521	35057	N	N	N	1	CUSTOMER ISSUE	-
DMS_31522	35058	N	N	N	1	CUSTOMER ISSUE	-
DMS_31523	35059	N	N	N	1	CUSTOMER ISSUE	-
DMS_31525	35060	N	N	N	1	CUSTOMER ISSUE	-
DMS_31526	35061	N	N	N	1	CUSTOMER ISSUE	-
DMS_31527	35062	N	N	N	1	CUSTOMER ISSUE	-
DMS_31528	35063	N	N	N	1	CUSTOMER ISSUE	-
DMS_31529	35064	N	N	N	1	CUSTOMER ISSUE	-
DMS_31530	35065	N	N	N	1	CUSTOMER ISSUE	-
DMS_31531	35066	N	N	N	1	CUSTOMER ISSUE	-
DMS_31532	35067	N	N	N	1	CUSTOMER ISSUE	-
DMS_31533	35068	N	N	N	1	CUSTOMER ISSUE	-
DMS_31534	35069	N	N	N	1	CUSTOMER ISSUE	-
DMS_31535	35070	N	N	N	1	CUSTOMER ISSUE	-
DMS_31536	35071	N	N	N	1	CUSTOMER ISSUE	-
DMS_31537	35072	N	N	N	1	CUSTOMER ISSUE	-
DMS_31539	35073	N	N	N	1	CUSTOMER ISSUE	-
DMS_31540	35074	N	N	N	1	CUSTOMER ISSUE	-
DMS_31541	35075	N	N	N	1	CUSTOMER ISSUE	-
DMS_31542	35076	N	N	N	1	CUSTOMER ISSUE	-
DMS_31543	35077	N	N	N	1	CUSTOMER ISSUE	-
DMS_31544	35078	N	N	N	1	CUSTOMER ISSUE	-
DMS_31545	35079	N	N	N	1	CUSTOMER ISSUE	-
DMS_31546	35080	N	N	N	1	CUSTOMER ISSUE	-
DMS_31547	35081	N	N	N	1	CUSTOMER ISSUE	-
DMS_31548	35082	N	N	N	1	CUSTOMER ISSUE	-
DMS_31549	35083	N	N	N	1	CUSTOMER ISSUE	-
DMS_31550	35084	N	N	N	1	CUSTOMER ISSUE	-
DMS_31551	35085	N	N	N	1	CUSTOMER ISSUE	-
DMS_31552	35086	N	N	N	1	CUSTOMER ISSUE	-
DMS_31553	35087	N	N	N	1	CUSTOMER ISSUE	-
DMS_31554	35088	N	N	N	1	CUSTOMER ISSUE	-
DMS_31555	35089	N	N	N	1	CUSTOMER ISSUE	-
DMS_31556	35090	N	N	N	1	CUSTOMER ISSUE	-
DMS_31557	35091	N	N	N	1	CUSTOMER ISSUE	-
DMS_31558	35092	N	N	N	1	CUSTOMER ISSUE	-
DMS_31559	35093	N	N	N	1	CUSTOMER ISSUE	-
DMS_31560	35094	N	N	N	1	CUSTOMER ISSUE	-
DMS_31561	35095	N	N	N	1	CUSTOMER ISSUE	-
DMS_31562	35096	N	N	N	1	CUSTOMER ISSUE	-

DMS_31564	35097	N	N	N	1	CUSTOMER ISSUE	-
DMS_31565	35098	N	N	N	1	CUSTOMER ISSUE	-
DMS_31566	35099	N	N	N	1	CUSTOMER ISSUE	-
DMS_31567	35100	N	N	N	1	CUSTOMER ISSUE	-
DMS_31590	35101	N	N	N	1	CUSTOMER ISSUE	-
DMS_31591	35102	N	N	N	1	CUSTOMER ISSUE	-
DMS_31592	35103	N	N	N	1	CUSTOMER ISSUE	-
DMS_31594	35104	N	N	N	1	CUSTOMER ISSUE	-
DMS_31595	35105	N	N	N	1	CUSTOMER ISSUE	-
DMS_31596	35106	N	N	N	1	CUSTOMER ISSUE	-
DMS_31597	35107	N	N	N	1	CUSTOMER ISSUE	-
DMS_31598	35108	N	N	N	1	CUSTOMER ISSUE	-
DMS_31599	35109	N	N	N	1	CUSTOMER ISSUE	-
DMS_31600	35110	N	N	N	1	CUSTOMER ISSUE	-
DMS_31601	35111	N	N	N	1	CUSTOMER ISSUE	-
DMS_31602	35112	N	N	N	1	CUSTOMER ISSUE	-
DMS_31603	35113	N	N	N	1	CUSTOMER ISSUE	-
DMS_31604	35114	N	N	N	1	CUSTOMER ISSUE	-
DMS_31605	35115	N	N	N	1	CUSTOMER ISSUE	-
DMS_31606	35116	N	N	N	1	CUSTOMER ISSUE	-
DMS_31607	35117	N	N	N	1	CUSTOMER ISSUE	-
DMS_31608	35118	N	N	N	1	CUSTOMER ISSUE	-
DMS_31609	35119	N	N	N	1	CUSTOMER ISSUE	-
DMS_31610	35120	N	N	N	1	CUSTOMER ISSUE	-
DMS_31611	35121	N	N	N	1	CUSTOMER ISSUE	-
DMS_31612	35122	N	N	N	1	CUSTOMER ISSUE	-
DMS_31613	35123	N	N	N	1	CUSTOMER ISSUE	-
DMS_31614	35124	N	N	N	1	CUSTOMER ISSUE	-
DMS_31615	35125	N	N	N	1	CUSTOMER ISSUE	-
DMS_31616	35126	N	N	N	1	CUSTOMER ISSUE	-
DMS_31617	35127	N	N	N	1	CUSTOMER ISSUE	-
DMS_31618	35128	N	N	N	1	CUSTOMER ISSUE	-
DMS_31619	35129	N	N	N	1	CUSTOMER ISSUE	-
DMS_31620	35130	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_31621	35131	N	N	N	1	CUSTOMER ISSUE	-
DMS_31622	35132	N	N	N	1	CUSTOMER ISSUE	-
DMS_31623	35133	N	N	N	1	CUSTOMER ISSUE	-
DMS_31624	35134	N	N	N	1	CUSTOMER ISSUE	-
DMS_31625	35135	N	N	N	1	CUSTOMER ISSUE	-
DMS_31626	35136	N	N	N	1	CUSTOMER ISSUE	-
DMS_31627	35137	N	N	N	1	CUSTOMER ISSUE	-
DMS_31628	35138	N	N	N	1	CUSTOMER ISSUE	-
DMS_31629	35139	N	N	N	1	CUSTOMER ISSUE	-
DMS_31630	35140	N	N	N	1	CUSTOMER ISSUE	-
DMS_31631	35141	N	N	N	1	CUSTOMER ISSUE	-
DMS_31632	35142	N	N	N	1	CUSTOMER ISSUE	-
DMS_31633	35143	N	N	N	1	CUSTOMER ISSUE	-
DMS_31634	35144	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_31635	35145	N	N	N	1	CUSTOMER ISSUE	-
DMS_31636	35146	N	N	N	1	CUSTOMER ISSUE	-
DMS_31637	35147	N	N	N	1	CUSTOMER ISSUE	-
DMS_31638	35148	N	N	N	1	CUSTOMER ISSUE	-
DMS_31639	35149	N	N	N	2	CUSTOMER ISSUE	-
DMS_31640	35150	N	N	N	1	CUSTOMER ISSUE	-
DMS_31649	35151	N	N	N	1	CUSTOMER ISSUE	-
DMS_31650	35152	N	N	N	1	CUSTOMER ISSUE	-
DMS_31651	35153	N	N	N	1	CUSTOMER ISSUE	-
DMS_31652	35154	N	N	N	1	CUSTOMER ISSUE	-
DMS_31653	35155	N	N	N	1	CUSTOMER ISSUE	-
DMS_31654	35156	N	N	N	1	CUSTOMER ISSUE	-
DMS_31655	35157	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_31656	35158	N	N	N	1	CUSTOMER ISSUE	-
DMS_31657	35159	N	N	N	1	CUSTOMER ISSUE	-
DMS_31658	35160	N	N	N	1	CUSTOMER ISSUE	-
DMS_31659	35161	N	N	N	1	CUSTOMER ISSUE	-
DMS_31660	35162	N	N	N	1	CUSTOMER ISSUE	-
DMS_31661	35163	N	N	N	1	CUSTOMER ISSUE	-
DMS_31662	35164	N	N	N	1	CUSTOMER ISSUE	-
DMS_31663	35165	N	N	N	1	CUSTOMER ISSUE	-
DMS_31664	35166	N	N	N	1	CUSTOMER ISSUE	-
DMS_31665	35167	N	N	N	1	CUSTOMER ISSUE	-
DMS_31666	35168	N	N	N	1	CUSTOMER ISSUE	-
DMS_31667	35169	N	N	N	1	CUSTOMER ISSUE	-
DMS_31668	35170	N	N	N	1	CUSTOMER ISSUE	-
DMS_31669	35171	N	N	N	1	CUSTOMER ISSUE	-
DMS_31670	35172	N	N	N	1	CUSTOMER ISSUE	-
DMS_31671	35173	N	N	N	1	CUSTOMER ISSUE	-
DMS_31672	35174	N	N	N	1	CUSTOMER ISSUE	-
DMS_31673	35175	N	N	N	1	CUSTOMER ISSUE	-
DMS_31674	35176	N	N	N	1	CUSTOMER ISSUE	-

DMS_31675	35177	N	N	N	1	CUSTOMER ISSUE	-
DMS_31676	35178	N	N	N	1	CUSTOMER ISSUE	-
DMS_31677	35179	N	N	N	1	CUSTOMER ISSUE	-
DMS_31678	35180	N	N	N	1	CUSTOMER ISSUE	-
DMS_31679	35181	N	N	N	1	CUSTOMER ISSUE	-
DMS_31680	35182	N	N	N	1	CUSTOMER ISSUE	-
DMS_31681	35183	N	N	N	1	CUSTOMER ISSUE	-
DMS_31682	35184	N	N	N	1	CUSTOMER ISSUE	-
DMS_31683	35185	N	N	N	1	CUSTOMER ISSUE	-
DMS_31684	35186	N	N	N	1	CUSTOMER ISSUE	-
DMS_31685	35187	N	N	N	1	CUSTOMER ISSUE	-
DMS_31686	35188	N	N	N	1	CUSTOMER ISSUE	-
DMS_31687	35189	N	N	N	1	CUSTOMER ISSUE	-
DMS_31688	35190	N	N	N	1	CUSTOMER ISSUE	-
DMS_31689	35191	N	N	N	1	CUSTOMER ISSUE	-
DMS_31690	35192	N	N	N	1	CUSTOMER ISSUE	-
DMS_31691	35193	N	N	N	1	CUSTOMER ISSUE	-
DMS_31692	35194	N	N	N	1	CUSTOMER ISSUE	-
DMS_31693	35195	N	N	N	1	CUSTOMER ISSUE	-
DMS_31694	35196	N	N	N	1	CUSTOMER ISSUE	-
DMS_31695	35197	N	N	N	1	CUSTOMER ISSUE	-
DMS_31696	35198	N	N	N	1	CUSTOMER ISSUE	-
DMS_31697	35199	N	N	N	1	CUSTOMER ISSUE	-
DMS_31698	35200	N	N	N	1	CUSTOMER ISSUE	-
DMS_31699	35201	N	N	N	1	CUSTOMER ISSUE	-
DMS_31700	35202	N	N	N	1	CUSTOMER ISSUE	-
DMS_31701	35203	N	N	N	1	CUSTOMER ISSUE	-
DMS_31702	35204	N	N	N	1	CUSTOMER ISSUE	-
DMS_31703	35205	N	N	N	1	CUSTOMER ISSUE	-
DMS_31704	35206	N	N	N	1	CUSTOMER ISSUE	-
DMS_31705	35207	N	N	N	1	CUSTOMER ISSUE	-
DMS_31706	35208	N	N	N	1	CUSTOMER ISSUE	-
DMS_31707	35209	N	N	N	1	CUSTOMER ISSUE	-
DMS_31708	35210	N	N	N	1	CUSTOMER ISSUE	-
DMS_31709	35211	N	N	N	1	CUSTOMER ISSUE	-
DMS_31710	35212	N	N	N	1	CUSTOMER ISSUE	-
DMS_31711	35213	N	N	N	1	CUSTOMER ISSUE	-
DMS_31712	35214	N	N	N	1	CUSTOMER ISSUE	-
DMS_31713	35215	N	N	N	1	CUSTOMER ISSUE	-
DMS_31714	35216	N	N	N	1	CUSTOMER ISSUE	-
DMS_31715	35217	N	N	N	1	CUSTOMER ISSUE	-
DMS_31716	35218	N	N	N	1	CUSTOMER ISSUE	-
DMS_31717	35219	N	N	N	1	CUSTOMER ISSUE	-
DMS_31731	35220	N	N	N	1	CUSTOMER ISSUE	-
DMS_31733	35221	N	N	N	1	CUSTOMER ISSUE	-
DMS_31734	35222	N	N	N	1	CUSTOMER ISSUE	-
DMS_31735	35223	N	N	N	1	CUSTOMER ISSUE	-
DMS_31736	35224	N	N	N	1	CUSTOMER ISSUE	-
DMS_31737	35225	N	N	N	1	CUSTOMER ISSUE	-
DMS_31738	35226	N	N	N	1	CUSTOMER ISSUE	-
DMS_31739	35227	N	N	N	1	CUSTOMER ISSUE	-
DMS_31740	35228	N	N	N	1	CUSTOMER ISSUE	-
DMS_31741	35229	N	N	N	1	CUSTOMER ISSUE	-
DMS_31742	35230	N	N	N	1	CUSTOMER ISSUE	-
DMS_31743	35231	N	N	N	1	CUSTOMER ISSUE	-
DMS_31745	35232	N	N	N	1	CUSTOMER ISSUE	-
DMS_31746	35233	N	N	N	1	CUSTOMER ISSUE	-
DMS_31747	35234	N	N	N	1	CUSTOMER ISSUE	-
DMS_31749	35235	N	N	N	1	CUSTOMER ISSUE	-
DMS_31751	35236	N	N	N	1	CUSTOMER ISSUE	-
DMS_31753	35237	N	N	N	1	CUSTOMER ISSUE	-
DMS_31754	35238	N	N	N	1	CUSTOMER ISSUE	-
DMS_31755	35239	N	N	N	1	CUSTOMER ISSUE	-
DMS_31759	35240	N	N	N	1	CUSTOMER ISSUE	-
DMS_31760	35241	N	N	N	1	CUSTOMER ISSUE	-
DMS_31761	35242	N	N	N	1	CUSTOMER ISSUE	-
DMS_31762	35243	N	N	N	1	CUSTOMER ISSUE	-
DMS_31763	35244	N	N	N	1	CUSTOMER ISSUE	-
DMS_31764	35245	N	N	N	1	CUSTOMER ISSUE	-
DMS_31765	35246	N	N	N	1	CUSTOMER ISSUE	-
DMS_31766	35247	N	N	N	1	CUSTOMER ISSUE	-
DMS_31767	35248	N	N	N	1	CUSTOMER ISSUE	-
DMS_31768	35249	N	N	N	1	CUSTOMER ISSUE	-
DMS_31769	35250	N	N	N	1	CUSTOMER ISSUE	-
DMS_31770	35251	N	N	N	1	CUSTOMER ISSUE	-
DMS_31772	35252	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31773	35253	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_31774	35254	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_31775	35255	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_31776	35256	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_31777	35257	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31778	35258	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31779	35259	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31780	35260	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31781	35261	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31782	35262	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31783	35263	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31784	35264	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31785	35265	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31786	35266	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_31787	35267	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31788	35268	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31789	35269	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31790	35270	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31791	35271	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31792	35272	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31793	35273	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31794	35274	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31795	35275	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31796	35276	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31797	35277	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31798	35278	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31799	35279	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31800	35280	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31801	35281	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31802	35282	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31803	35283	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31804	35284	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31805	35285	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31806	35286	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_31825	35287	N	N	N	1	CUSTOMER ISSUE	-
DMS_32003	35288	N	N	N	1	CUSTOMER ISSUE	-
DMS_32005	35289	N	N	N	1	CUSTOMER ISSUE	-
DMS_32007	35290	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32008	35291	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32009	35292	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32011	35293	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32012	35294	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32013	35295	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_32020	35296	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_32022	35297	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_32025	35298	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32026	35299	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32027	35300	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32032	35301	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_32033	35302	N	N	N	1	CUSTOMER ISSUE	-
DMS_32034	35303	N	N	N	1	CUSTOMER ISSUE	-
DMS_32035	35304	N	N	N	1	CUSTOMER ISSUE	-
DMS_32036	35305	N	N	N	1	CUSTOMER ISSUE	-
DMS_32038	35306	N	N	N	1	CUSTOMER ISSUE	-
DMS_32039	35307	N	N	N	1	CUSTOMER ISSUE	-
DMS_32040	35308	N	N	N	1	CUSTOMER ISSUE	-
DMS_32041	35309	N	N	N	1	CUSTOMER ISSUE	-
DMS_32042	35310	N	N	N	1	CUSTOMER ISSUE	-
DMS_32043	35311	N	N	N	1	CUSTOMER ISSUE	-
DMS_32044	35312	N	N	N	1	CUSTOMER ISSUE	-
DMS_32045	35313	N	N	N	1	CUSTOMER ISSUE	-
DMS_32046	35314	N	N	N	1	CUSTOMER ISSUE	-
DMS_32047	35315	N	N	N	1	CUSTOMER ISSUE	-
DMS_32050	35316	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32052	35317	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_32053	35318	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_32054	35319	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_32055	35320	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_32069	35321	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32073	35322	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32074	35323	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32075	35324	N	N	N	1	CUSTOMER ISSUE	-
DMS_32076	35325	N	N	N	1	CUSTOMER ISSUE	-
DMS_32077	35326	N	N	N	1	CUSTOMER ISSUE	-
DMS_32079	35327	N	N	N	1	CUSTOMER ISSUE	-
DMS_32080	35328	N	N	N	1	CUSTOMER ISSUE	-
DMS_32081	35329	N	N	N	1	CUSTOMER ISSUE	-
DMS_32082	35330	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32083	35331	N	N	N	1	CUSTOMER ISSUE	-
DMS_32087	35332	N	N	Y	3	SEC/SVC - REPAIR	472.5
DMS_32088	35333	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32089	35334	N	N	N	1	CUSTOMER ISSUE	-
DMS_32090	35335	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32091	35336	N	N	N	1	CUSTOMER ISSUE	-

DMS_32094	35337	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32098	35338	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32099	35339	N	N	N	1	CUSTOMER ISSUE	-
DMS_32100	35340	N	N	N	1	CUSTOMER ISSUE	-
DMS_32101	35341	N	N	N	1	CUSTOMER ISSUE	-
DMS_32102	35342	N	N	N	1	CUSTOMER ISSUE	-
DMS_32104	35343	N	N	N	1	CUSTOMER ISSUE	-
DMS_32105	35344	N	N	N	1	CUSTOMER ISSUE	-
DMS_32106	35345	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32108	35346	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_32109	35347	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32110	35348	N	N	N	1	CUSTOMER ISSUE	-
DMS_32111	35349	N	N	N	1	CUSTOMER ISSUE	-
DMS_32112	35350	N	N	N	1	CUSTOMER ISSUE	-
DMS_32113	35351	N	N	N	1	CUSTOMER ISSUE	-
DMS_32114	35352	N	N	N	1	CUSTOMER ISSUE	-
DMS_32116	35353	N	N	N	1	CUSTOMER ISSUE	-
DMS_32117	35354	N	N	N	1	CUSTOMER ISSUE	-
DMS_32118	35355	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32119	35356	N	N	N	1	CUSTOMER ISSUE	-
DMS_32120	35357	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32121	35358	N	N	N	1	CUSTOMER ISSUE	-
DMS_32122	35359	N	N	N	1	CUSTOMER ISSUE	-
DMS_32124	35360	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32125	35361	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32126	35362	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32127	35363	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32128	35364	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32129	35365	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32130	35366	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32131	35367	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32132	35368	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32133	35369	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32134	35370	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32135	35371	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32136	35372	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32137	35373	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32138	35374	N	N	Y	3	DIST - REPLACE FUSE	708.75
DMS_32139	35375	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32140	35376	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32141	35377	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32142	35378	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32143	35379	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_32144	35380	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32145	35381	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32146	35382	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32147	35383	N	N	N	1	CUSTOMER ISSUE	-
DMS_32148	35384	N	N	N	1	CUSTOMER ISSUE	-
DMS_32149	35385	N	N	N	1	CUSTOMER ISSUE	-
DMS_32150	35386	N	N	N	1	CUSTOMER ISSUE	-
DMS_32151	35387	N	N	N	1	CUSTOMER ISSUE	-
DMS_32152	35388	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32153	35389	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32155	35390	N	N	N	1	CUSTOMER ISSUE	-
DMS_32156	35391	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32157	35392	N	N	N	1	CUSTOMER ISSUE	-
DMS_32160	35393	N	N	N	1	CUSTOMER ISSUE	-
DMS_32161	35394	N	N	N	1	CUSTOMER ISSUE	-
DMS_32163	35395	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32164	35396	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32165	35397	N	N	N	1	CUSTOMER ISSUE	-
DMS_32166	35398	N	N	N	1	CUSTOMER ISSUE	-
DMS_32168	35399	N	N	N	1	CUSTOMER ISSUE	-
DMS_32170	35400	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32171	35401	N	N	N	1	CUSTOMER ISSUE	-
DMS_32172	35402	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32173	35403	N	N	N	1	CUSTOMER ISSUE	-
DMS_32174	35404	N	N	N	1	CUSTOMER ISSUE	-
DMS_32175	35405	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32177	35406	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32178	35407	N	N	N	1	CUSTOMER ISSUE	-
DMS_32179	35408	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32180	35409	N	N	N	1	CUSTOMER ISSUE	-
DMS_32181	35410	N	N	N	1	CUSTOMER ISSUE	-
DMS_32182	35411	N	N	N	1	CUSTOMER ISSUE	-
DMS_32183	35412	N	N	N	1	CUSTOMER ISSUE	-
DMS_32184	35413	N	N	N	1	CUSTOMER ISSUE	-
DMS_32185	35414	N	N	N	1	CUSTOMER ISSUE	-
DMS_32187	35415	N	N	N	1	CUSTOMER ISSUE	-
DMS_32188	35416	N	N	N	1	CUSTOMER ISSUE	-

DMS_32189	35417	N	N	N	1	CUSTOMER ISSUE	-
DMS_32190	35418	N	N	N	1	CUSTOMER ISSUE	-
DMS_32197	35419	N	N	N	1	CUSTOMER ISSUE	-
DMS_32198	35420	N	N	N	1	CUSTOMER ISSUE	-
DMS_32199	35421	N	N	N	1	CUSTOMER ISSUE	-
DMS_32200	35422	N	N	N	1	CUSTOMER ISSUE	-
DMS_32201	35423	N	N	N	1	CUSTOMER ISSUE	-
DMS_32202	35424	N	N	N	1	CUSTOMER ISSUE	-
DMS_32203	35425	N	N	N	1	CUSTOMER ISSUE	-
DMS_32204	35426	N	N	N	1	CUSTOMER ISSUE	-
DMS_32206	35427	N	N	N	1	CUSTOMER ISSUE	-
DMS_32207	35428	N	N	N	1	CUSTOMER ISSUE	-
DMS_32208	35429	N	N	N	1	CUSTOMER ISSUE	-
DMS_32210	35430	N	N	N	1	CUSTOMER ISSUE	-
DMS_32211	35431	N	N	N	1	CUSTOMER ISSUE	-
DMS_32212	35432	N	N	N	1	CUSTOMER ISSUE	-
DMS_32213	35433	N	N	N	1	CUSTOMER ISSUE	-
DMS_32214	35434	N	N	N	1	CUSTOMER ISSUE	-
DMS_32215	35435	N	N	N	1	CUSTOMER ISSUE	-
DMS_32216	35436	N	N	N	1	CUSTOMER ISSUE	-
DMS_32217	35437	N	N	N	1	CUSTOMER ISSUE	-
DMS_32218	35438	N	N	N	1	CUSTOMER ISSUE	-
DMS_32219	35439	N	N	N	2	CUSTOMER ISSUE	-
DMS_32220	35440	N	N	N	1	CUSTOMER ISSUE	-
DMS_32221	35441	N	N	N	1	CUSTOMER ISSUE	-
DMS_32223	35442	N	N	N	1	CUSTOMER ISSUE	-
DMS_32224	35443	N	N	N	1	CUSTOMER ISSUE	-
DMS_32225	35444	N	N	N	1	CUSTOMER ISSUE	-
DMS_32226	35445	N	N	N	1	CUSTOMER ISSUE	-
DMS_32228	35446	N	N	N	1	CUSTOMER ISSUE	-
DMS_32230	35447	N	N	N	1	CUSTOMER ISSUE	-
DMS_32232	35448	N	N	N	1	CUSTOMER ISSUE	-
DMS_32233	35449	N	N	N	1	CUSTOMER ISSUE	-
DMS_32235	35450	N	N	N	1	CUSTOMER ISSUE	-
DMS_32236	35451	N	N	N	1	CUSTOMER ISSUE	-
DMS_32239	35452	N	N	N	1	CUSTOMER ISSUE	-
DMS_32240	35453	N	N	N	1	CUSTOMER ISSUE	-
DMS_32241	35454	N	N	N	1	CUSTOMER ISSUE	-
DMS_32242	35455	N	N	N	1	CUSTOMER ISSUE	-
DMS_32243	35456	N	N	N	1	CUSTOMER ISSUE	-
DMS_32244	35457	N	N	N	1	CUSTOMER ISSUE	-
DMS_32246	35458	N	N	N	1	CUSTOMER ISSUE	-
DMS_32247	35459	N	N	N	1	CUSTOMER ISSUE	-
DMS_32248	35460	N	N	N	1	CUSTOMER ISSUE	-
DMS_32250	35461	N	N	N	1	CUSTOMER ISSUE	-
DMS_32251	35462	N	N	N	1	CUSTOMER ISSUE	-
DMS_32252	35463	N	N	N	1	CUSTOMER ISSUE	-
DMS_32253	35464	N	N	N	1	CUSTOMER ISSUE	-
DMS_32255	35465	N	N	N	1	CUSTOMER ISSUE	-
DMS_32256	35466	N	N	N	1	CUSTOMER ISSUE	-
DMS_32259	35467	N	N	N	1	CUSTOMER ISSUE	-
DMS_32260	35468	N	N	N	1	CUSTOMER ISSUE	-
DMS_32263	35469	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32264	35470	N	N	N	1	CUSTOMER ISSUE	-
DMS_32265	35471	N	N	N	1	CUSTOMER ISSUE	-
DMS_32266	35472	N	N	N	1	CUSTOMER ISSUE	-
DMS_32267	35473	N	N	N	3	CUSTOMER ISSUE	-
DMS_32268	35474	N	N	N	1	CUSTOMER ISSUE	-
DMS_32269	35475	N	N	N	1	CUSTOMER ISSUE	-
DMS_32270	35476	N	N	N	1	CUSTOMER ISSUE	-
DMS_32271	35477	N	N	N	1	CUSTOMER ISSUE	-
DMS_32274	35478	N	N	N	1	CUSTOMER ISSUE	-
DMS_32275	35479	N	N	N	1	CUSTOMER ISSUE	-
DMS_32276	35480	N	N	N	1	CUSTOMER ISSUE	-
DMS_32277	35481	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32278	35482	N	N	N	1	CUSTOMER ISSUE	-
DMS_32279	35483	N	N	N	1	CUSTOMER ISSUE	-
DMS_32281	35484	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32282	35485	N	N	N	1	CUSTOMER ISSUE	-
DMS_32283	35486	N	N	N	1	CUSTOMER ISSUE	-
DMS_32284	35487	N	N	N	1	CUSTOMER ISSUE	-
DMS_32285	35488	N	N	N	1	CUSTOMER ISSUE	-
DMS_32286	35489	N	N	N	1	CUSTOMER ISSUE	-
DMS_32287	35490	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32288	35491	N	N	N	1	CUSTOMER ISSUE	-
DMS_32289	35492	N	N	N	1	CUSTOMER ISSUE	-
DMS_32290	35493	N	N	N	1	CUSTOMER ISSUE	-
DMS_32291	35494	N	N	N	1	CUSTOMER ISSUE	-
DMS_32292	35495	N	N	N	1	CUSTOMER ISSUE	-
DMS_32293	35496	N	N	N	1	CUSTOMER ISSUE	-

DMS_32294	35497	N	N	N	1	CUSTOMER ISSUE	-
DMS_32295	35498	N	N	N	1	CUSTOMER ISSUE	-
DMS_32296	35499	N	N	N	1	CUSTOMER ISSUE	-
DMS_32297	35500	N	N	N	1	CUSTOMER ISSUE	-
DMS_32298	35501	N	N	N	1	CUSTOMER ISSUE	-
DMS_32299	35502	N	N	N	1	CUSTOMER ISSUE	-
DMS_32300	35503	N	N	N	1	CUSTOMER ISSUE	-
DMS_32301	35504	N	N	N	1	CUSTOMER ISSUE	-
DMS_32302	35505	N	N	N	1	CUSTOMER ISSUE	-
DMS_32303	35506	N	N	N	1	CUSTOMER ISSUE	-
DMS_32304	35507	N	N	N	1	CUSTOMER ISSUE	-
DMS_32305	35508	N	N	N	1	CUSTOMER ISSUE	-
DMS_32306	35509	N	N	N	1	CUSTOMER ISSUE	-
DMS_32307	35510	N	N	N	1	CUSTOMER ISSUE	-
DMS_32308	35511	N	N	N	1	CUSTOMER ISSUE	-
DMS_32309	35512	N	N	N	1	CUSTOMER ISSUE	-
DMS_32310	35513	N	N	N	1	CUSTOMER ISSUE	-
DMS_32311	35514	N	N	N	1	CUSTOMER ISSUE	-
DMS_32312	35515	N	N	N	1	CUSTOMER ISSUE	-
DMS_32313	35516	N	N	N	1	CUSTOMER ISSUE	-
DMS_32314	35517	N	N	N	1	CUSTOMER ISSUE	-
DMS_32315	35518	N	N	N	1	CUSTOMER ISSUE	-
DMS_32316	35519	N	N	N	1	CUSTOMER ISSUE	-
DMS_32321	35520	N	N	N	1	CUSTOMER ISSUE	-
DMS_32322	35521	N	N	N	1	CUSTOMER ISSUE	-
DMS_32324	35522	N	N	N	1	CUSTOMER ISSUE	-
DMS_32325	35523	N	N	N	1	CUSTOMER ISSUE	-
DMS_32326	35524	N	N	N	1	CUSTOMER ISSUE	-
DMS_32327	35525	N	N	N	1	CUSTOMER ISSUE	-
DMS_32328	35526	N	N	N	1	CUSTOMER ISSUE	-
DMS_32329	35527	N	N	N	1	CUSTOMER ISSUE	-
DMS_32330	35528	N	N	N	1	CUSTOMER ISSUE	-
DMS_32331	35529	N	N	N	1	CUSTOMER ISSUE	-
DMS_32340	35530	N	N	N	1	CUSTOMER ISSUE	-
DMS_32341	35531	N	N	N	1	CUSTOMER ISSUE	-
DMS_32342	35532	N	N	N	1	CUSTOMER ISSUE	-
DMS_32343	35533	N	N	N	1	CUSTOMER ISSUE	-
DMS_32344	35534	N	N	N	1	CUSTOMER ISSUE	-
DMS_32345	35535	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32346	35536	N	N	N	1	CUSTOMER ISSUE	-
DMS_32347	35537	N	N	N	1	CUSTOMER ISSUE	-
DMS_32348	35538	N	N	N	1	CUSTOMER ISSUE	-
DMS_32349	35539	N	N	N	1	CUSTOMER ISSUE	-
DMS_32350	35540	N	N	N	1	CUSTOMER ISSUE	-
DMS_32351	35541	N	N	N	1	CUSTOMER ISSUE	-
DMS_32352	35542	N	N	N	1	CUSTOMER ISSUE	-
DMS_32353	35543	N	N	N	1	CUSTOMER ISSUE	-
DMS_32354	35544	N	N	N	1	CUSTOMER ISSUE	-
DMS_32355	35545	N	N	N	1	CUSTOMER ISSUE	-
DMS_32356	35546	N	N	N	1	CUSTOMER ISSUE	-
DMS_32357	35547	N	N	N	1	CUSTOMER ISSUE	-
DMS_32358	35548	N	N	N	1	CUSTOMER ISSUE	-
DMS_32359	35549	N	N	N	1	CUSTOMER ISSUE	-
DMS_32360	35550	N	N	N	1	CUSTOMER ISSUE	-
DMS_32362	35551	N	N	N	1	CUSTOMER ISSUE	-
DMS_32364	35552	N	N	N	1	CUSTOMER ISSUE	-
DMS_32369	35553	N	N	N	1	CUSTOMER ISSUE	-
DMS_32370	35554	N	N	N	1	CUSTOMER ISSUE	-
DMS_32371	35555	N	N	N	1	CUSTOMER ISSUE	-
DMS_32372	35556	N	N	N	1	CUSTOMER ISSUE	-
DMS_32373	35557	N	N	N	1	CUSTOMER ISSUE	-
DMS_32375	35558	N	N	N	1	CUSTOMER ISSUE	-
DMS_32376	35559	N	N	N	1	CUSTOMER ISSUE	-
DMS_32377	35560	N	N	N	1	CUSTOMER ISSUE	-
DMS_32378	35561	N	N	N	1	CUSTOMER ISSUE	-
DMS_32379	35562	N	N	N	1	CUSTOMER ISSUE	-
DMS_32380	35563	N	N	N	1	CUSTOMER ISSUE	-
DMS_32381	35564	N	N	N	1	CUSTOMER ISSUE	-
DMS_32382	35565	N	N	N	1	CUSTOMER ISSUE	-
DMS_32383	35566	N	N	N	1	CUSTOMER ISSUE	-
DMS_32384	35567	N	N	N	1	CUSTOMER ISSUE	-
DMS_32385	35568	N	N	N	1	CUSTOMER ISSUE	-
DMS_32386	35569	N	N	N	1	CUSTOMER ISSUE	-
DMS_32387	35570	N	N	N	1	CUSTOMER ISSUE	-
DMS_32416	35571	N	N	N	1	CUSTOMER ISSUE	-
DMS_32417	35572	N	N	N	1	CUSTOMER ISSUE	-
DMS_32418	35573	N	N	N	1	CUSTOMER ISSUE	-
DMS_32419	35574	N	N	N	1	CUSTOMER ISSUE	-
DMS_32420	35575	N	N	N	1	CUSTOMER ISSUE	-
DMS_32421	35576	N	N	N	1	CUSTOMER ISSUE	-

DMS_32422	35577	N	N	N	1	CUSTOMER ISSUE	-
DMS_32423	35578	N	N	N	1	CUSTOMER ISSUE	-
DMS_32424	35579	N	N	N	1	CUSTOMER ISSUE	-
DMS_32425	35580	N	N	N	1	CUSTOMER ISSUE	-
DMS_32426	35581	N	N	N	1	CUSTOMER ISSUE	-
DMS_32427	35582	N	N	N	1	CUSTOMER ISSUE	-
DMS_32428	35583	N	N	N	1	CUSTOMER ISSUE	-
DMS_32429	35584	N	N	N	1	CUSTOMER ISSUE	-
DMS_32430	35585	N	N	N	1	CUSTOMER ISSUE	-
DMS_32431	35586	N	N	N	1	CUSTOMER ISSUE	-
DMS_32432	35587	N	N	N	1	CUSTOMER ISSUE	-
DMS_32433	35588	N	N	N	1	CUSTOMER ISSUE	-
DMS_32434	35589	N	N	N	1	CUSTOMER ISSUE	-
DMS_32435	35590	N	N	N	1	CUSTOMER ISSUE	-
DMS_32436	35591	N	N	N	1	CUSTOMER ISSUE	-
DMS_32438	35592	N	N	N	1	CUSTOMER ISSUE	-
DMS_32439	35593	N	N	N	1	CUSTOMER ISSUE	-
DMS_32442	35594	N	N	N	1	CUSTOMER ISSUE	-
DMS_32443	35595	N	N	N	1	CUSTOMER ISSUE	-
DMS_32444	35596	N	N	N	1	CUSTOMER ISSUE	-
DMS_32445	35597	N	N	N	1	CUSTOMER ISSUE	-
DMS_32446	35598	N	N	N	1	CUSTOMER ISSUE	-
DMS_32447	35599	N	N	N	1	CUSTOMER ISSUE	-
DMS_32448	35600	N	N	N	1	CUSTOMER ISSUE	-
DMS_32449	35601	N	N	N	1	CUSTOMER ISSUE	-
DMS_32450	35602	N	N	N	1	CUSTOMER ISSUE	-
DMS_32451	35603	N	N	N	1	CUSTOMER ISSUE	-
DMS_32452	35604	N	N	N	1	CUSTOMER ISSUE	-
DMS_32454	35605	N	N	N	1	CUSTOMER ISSUE	-
DMS_32455	35606	N	N	N	1	CUSTOMER ISSUE	-
DMS_32456	35607	N	N	N	1	CUSTOMER ISSUE	-
DMS_32457	35608	N	N	N	1	CUSTOMER ISSUE	-
DMS_32458	35609	N	N	N	1	CUSTOMER ISSUE	-
DMS_32459	35610	N	N	N	1	CUSTOMER ISSUE	-
DMS_32461	35611	N	N	N	1	CUSTOMER ISSUE	-
DMS_32462	35612	N	N	N	1	CUSTOMER ISSUE	-
DMS_32463	35613	N	N	N	1	CUSTOMER ISSUE	-
DMS_32464	35614	N	N	N	1	CUSTOMER ISSUE	-
DMS_32465	35615	N	N	N	1	CUSTOMER ISSUE	-
DMS_32466	35616	N	N	N	1	CUSTOMER ISSUE	-
DMS_32467	35617	N	N	N	1	CUSTOMER ISSUE	-
DMS_32468	35618	N	N	N	1	CUSTOMER ISSUE	-
DMS_32469	35619	N	N	N	1	CUSTOMER ISSUE	-
DMS_32470	35620	N	N	N	1	CUSTOMER ISSUE	-
DMS_32471	35621	N	N	N	1	CUSTOMER ISSUE	-
DMS_32472	35622	N	N	N	1	CUSTOMER ISSUE	-
DMS_32474	35623	N	N	N	1	CUSTOMER ISSUE	-
DMS_32475	35624	N	N	N	1	CUSTOMER ISSUE	-
DMS_32477	35625	N	N	N	1	CUSTOMER ISSUE	-
DMS_32481	35626	N	N	N	1	CUSTOMER ISSUE	-
DMS_32482	35627	N	N	N	1	CUSTOMER ISSUE	-
DMS_32483	35628	N	N	N	1	CUSTOMER ISSUE	-
DMS_32484	35629	N	N	N	1	CUSTOMER ISSUE	-
DMS_32485	35630	N	N	N	1	CUSTOMER ISSUE	-
DMS_32487	35631	N	N	N	1	CUSTOMER ISSUE	-
DMS_32488	35632	N	N	N	1	CUSTOMER ISSUE	-
DMS_32489	35633	N	N	N	1	CUSTOMER ISSUE	-
DMS_32490	35634	N	N	N	1	CUSTOMER ISSUE	-
DMS_32491	35635	N	N	N	1	CUSTOMER ISSUE	-
DMS_32492	35636	N	N	N	1	CUSTOMER ISSUE	-
DMS_32493	35637	N	N	N	1	CUSTOMER ISSUE	-
DMS_32494	35638	N	N	N	1	CUSTOMER ISSUE	-
DMS_32495	35639	N	N	N	1	CUSTOMER ISSUE	-
DMS_32496	35640	N	N	N	1	CUSTOMER ISSUE	-
DMS_32497	35641	N	N	N	1	CUSTOMER ISSUE	-
DMS_32498	35642	N	N	N	1	CUSTOMER ISSUE	-
DMS_32499	35643	N	N	N	1	CUSTOMER ISSUE	-
DMS_32500	35644	N	N	N	1	CUSTOMER ISSUE	-
DMS_32501	35645	N	N	N	1	CUSTOMER ISSUE	-
DMS_32502	35646	N	N	N	1	CUSTOMER ISSUE	-
DMS_32503	35647	N	N	N	1	CUSTOMER ISSUE	-
DMS_32504	35648	N	N	N	1	CUSTOMER ISSUE	-
DMS_32505	35649	N	N	N	1	CUSTOMER ISSUE	-
DMS_32507	35650	N	N	N	1	CUSTOMER ISSUE	-
DMS_32508	35651	N	N	N	1	CUSTOMER ISSUE	-
DMS_32509	35652	N	N	N	1	CUSTOMER ISSUE	-
DMS_32510	35653	N	N	N	1	CUSTOMER ISSUE	-
DMS_32511	35654	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32512	35655	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32513	35656	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_32514	35657	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32516	35658	N	N	N	1	CUSTOMER ISSUE	-
DMS_32517	35659	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32518	35660	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_32519	35661	N	N	N	1	CUSTOMER ISSUE	-
DMS_32520	35662	N	N	N	1	CUSTOMER ISSUE	-
DMS_32566	35663	N	N	N	1	CUSTOMER ISSUE	-
DMS_32567	35664	N	N	N	1	CUSTOMER ISSUE	-
DMS_32568	35665	N	N	N	1	CUSTOMER ISSUE	-
DMS_32569	35666	N	N	N	1	CUSTOMER ISSUE	-
DMS_32570	35667	N	N	N	1	CUSTOMER ISSUE	-
DMS_32571	35668	N	N	N	1	CUSTOMER ISSUE	-
DMS_32572	35669	N	N	N	1	CUSTOMER ISSUE	-
DMS_32573	35670	N	N	N	1	CUSTOMER ISSUE	-
DMS_32574	35671	N	N	N	1	CUSTOMER ISSUE	-
DMS_32575	35672	N	N	N	1	CUSTOMER ISSUE	-
DMS_32576	35673	N	N	N	1	CUSTOMER ISSUE	-
DMS_32577	35674	N	N	N	1	CUSTOMER ISSUE	-
DMS_32581	35675	N	N	N	1	CUSTOMER ISSUE	-
DMS_32582	35676	N	N	N	1	CUSTOMER ISSUE	-
DMS_32583	35677	N	N	N	1	CUSTOMER ISSUE	-
DMS_32584	35678	N	N	N	1	CUSTOMER ISSUE	-
DMS_32585	35679	N	N	N	1	CUSTOMER ISSUE	-
DMS_32586	35680	N	N	N	1	CUSTOMER ISSUE	-
DMS_32587	35681	N	N	N	1	CUSTOMER ISSUE	-
DMS_32588	35682	N	N	N	1	CUSTOMER ISSUE	-
DMS_32589	35683	N	N	N	1	CUSTOMER ISSUE	-
DMS_32590	35684	N	N	N	1	CUSTOMER ISSUE	-
DMS_32591	35685	N	N	N	1	CUSTOMER ISSUE	-
DMS_32592	35686	N	N	N	1	CUSTOMER ISSUE	-
DMS_32593	35687	N	N	N	1	CUSTOMER ISSUE	-
DMS_32594	35688	N	N	N	1	CUSTOMER ISSUE	-
DMS_32595	35689	N	N	N	1	CUSTOMER ISSUE	-
DMS_32596	35690	N	N	N	1	CUSTOMER ISSUE	-
DMS_32597	35691	N	N	N	1	CUSTOMER ISSUE	-
DMS_32598	35692	N	N	N	1	CUSTOMER ISSUE	-
DMS_32599	35693	N	N	N	1	CUSTOMER ISSUE	-
DMS_32600	35694	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32601	35695	N	N	N	1	CUSTOMER ISSUE	-
DMS_32602	35696	N	N	N	1	CUSTOMER ISSUE	-
DMS_32603	35697	N	N	N	1	CUSTOMER ISSUE	-
DMS_32604	35698	N	N	N	1	CUSTOMER ISSUE	-
DMS_32605	35699	N	N	N	1	CUSTOMER ISSUE	-
DMS_32606	35700	N	N	N	1	CUSTOMER ISSUE	-
DMS_32607	35701	N	N	N	1	CUSTOMER ISSUE	-
DMS_32608	35702	N	N	N	1	CUSTOMER ISSUE	-
DMS_32609	35703	N	N	N	1	CUSTOMER ISSUE	-
DMS_32610	35704	N	N	N	1	CUSTOMER ISSUE	-
DMS_32611	35705	N	N	N	1	CUSTOMER ISSUE	-
DMS_32614	35706	N	N	N	1	CUSTOMER ISSUE	-
DMS_32631	35707	N	N	N	1	CUSTOMER ISSUE	-
DMS_32632	35708	N	N	N	1	CUSTOMER ISSUE	-
DMS_32633	35709	N	N	N	1	CUSTOMER ISSUE	-
DMS_32635	35710	N	N	N	1	CUSTOMER ISSUE	-
DMS_32636	35711	N	N	N	1	CUSTOMER ISSUE	-
DMS_32637	35712	N	N	N	1	CUSTOMER ISSUE	-
DMS_32638	35713	N	N	N	1	CUSTOMER ISSUE	-
DMS_32639	35714	N	N	N	1	CUSTOMER ISSUE	-
DMS_32640	35715	N	N	N	1	CUSTOMER ISSUE	-
DMS_32641	35716	N	N	N	1	CUSTOMER ISSUE	-
DMS_32642	35717	N	N	N	1	CUSTOMER ISSUE	-
DMS_32643	35718	N	N	N	1	CUSTOMER ISSUE	-
DMS_32644	35719	N	N	N	1	CUSTOMER ISSUE	-
DMS_32645	35720	N	N	N	1	CUSTOMER ISSUE	-
DMS_32646	35721	N	N	N	1	CUSTOMER ISSUE	-
DMS_32649	35722	N	N	N	1	CUSTOMER ISSUE	-
DMS_32650	35723	N	N	N	1	CUSTOMER ISSUE	-
DMS_32651	35724	N	N	N	1	CUSTOMER ISSUE	-
DMS_32652	35725	N	N	N	1	CUSTOMER ISSUE	-
DMS_32653	35726	N	N	N	1	CUSTOMER ISSUE	-
DMS_32654	35727	N	N	N	1	CUSTOMER ISSUE	-
DMS_32655	35728	N	N	N	1	CUSTOMER ISSUE	-
DMS_32656	35729	N	N	N	1	CUSTOMER ISSUE	-
DMS_32657	35730	N	N	N	1	CUSTOMER ISSUE	-
DMS_32658	35731	N	N	N	1	CUSTOMER ISSUE	-
DMS_32659	35732	N	N	N	1	CUSTOMER ISSUE	-
DMS_32660	35733	N	N	N	1	CUSTOMER ISSUE	-
DMS_32661	35734	N	N	N	1	CUSTOMER ISSUE	-
DMS_32662	35735	N	N	N	1	CUSTOMER ISSUE	-
DMS_32663	35736	N	N	N	1	CUSTOMER ISSUE	-

DMS_32664	35737	N	N	N	1	CUSTOMER ISSUE	-
DMS_32665	35738	N	N	N	1	CUSTOMER ISSUE	-
DMS_32666	35739	N	N	N	1	CUSTOMER ISSUE	-
DMS_32667	35740	N	N	N	1	CUSTOMER ISSUE	-
DMS_32668	35741	N	N	N	1	CUSTOMER ISSUE	-
DMS_32669	35742	N	N	N	1	CUSTOMER ISSUE	-
DMS_32670	35743	N	N	N	1	CUSTOMER ISSUE	-
DMS_32671	35744	N	N	N	1	CUSTOMER ISSUE	-
DMS_32678	35745	N	N	N	1	CUSTOMER ISSUE	-
DMS_32679	35746	N	N	N	1	CUSTOMER ISSUE	-
DMS_32680	35747	N	N	N	1	CUSTOMER ISSUE	-
DMS_32682	35748	N	N	N	1	CUSTOMER ISSUE	-
DMS_32683	35749	N	N	N	1	CUSTOMER ISSUE	-
DMS_32684	35750	N	N	N	1	CUSTOMER ISSUE	-
DMS_32685	35751	N	N	N	1	CUSTOMER ISSUE	-
DMS_32686	35752	N	N	N	2	CUSTOMER ISSUE	-
DMS_32687	35753	N	N	N	1	CUSTOMER ISSUE	-
DMS_32688	35754	N	N	N	1	CUSTOMER ISSUE	-
DMS_32689	35755	N	N	N	1	CUSTOMER ISSUE	-
DMS_32690	35756	N	N	N	1	CUSTOMER ISSUE	-
DMS_32691	35757	N	N	N	1	CUSTOMER ISSUE	-
DMS_32692	35758	N	N	N	1	CUSTOMER ISSUE	-
DMS_32693	35759	N	N	N	1	CUSTOMER ISSUE	-
DMS_32694	35760	N	N	N	1	CUSTOMER ISSUE	-
DMS_32696	35761	N	N	N	1	CUSTOMER ISSUE	-
DMS_32697	35762	N	N	N	1	CUSTOMER ISSUE	-
DMS_32698	35763	N	N	N	1	CUSTOMER ISSUE	-
DMS_32699	35764	N	N	N	1	CUSTOMER ISSUE	-
DMS_32700	35765	N	N	N	1	CUSTOMER ISSUE	-
DMS_32701	35766	N	N	N	1	CUSTOMER ISSUE	-
DMS_32702	35767	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32703	35768	N	N	N	1	CUSTOMER ISSUE	-
DMS_32705	35769	N	N	N	1	CUSTOMER ISSUE	-
DMS_32707	35770	N	N	N	1	CUSTOMER ISSUE	-
DMS_32708	35771	N	N	N	1	CUSTOMER ISSUE	-
DMS_32709	35772	N	N	N	1	CUSTOMER ISSUE	-
DMS_32710	35773	N	N	N	1	CUSTOMER ISSUE	-
DMS_32711	35774	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32712	35775	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_32713	35776	N	N	N	1	CUSTOMER ISSUE	-
DMS_32714	35777	N	N	N	1	CUSTOMER ISSUE	-
DMS_32715	35778	N	N	N	1	CUSTOMER ISSUE	-
DMS_32716	35779	N	N	N	1	CUSTOMER ISSUE	-
DMS_32717	35780	N	N	N	1	CUSTOMER ISSUE	-
DMS_32718	35781	N	N	N	1	CUSTOMER ISSUE	-
DMS_32719	35782	N	N	N	1	CUSTOMER ISSUE	-
DMS_32720	35783	N	N	N	1	CUSTOMER ISSUE	-
DMS_32721	35784	N	N	N	1	CUSTOMER ISSUE	-
DMS_32722	35785	N	N	N	1	CUSTOMER ISSUE	-
DMS_32723	35786	N	N	N	1	CUSTOMER ISSUE	-
DMS_32724	35787	N	N	N	1	CUSTOMER ISSUE	-
DMS_32725	35788	N	N	N	1	CUSTOMER ISSUE	-
DMS_32726	35789	N	N	N	1	CUSTOMER ISSUE	-
DMS_32727	35790	N	N	N	1	CUSTOMER ISSUE	-
DMS_32728	35791	N	N	N	1	CUSTOMER ISSUE	-
DMS_32729	35792	N	N	N	1	CUSTOMER ISSUE	-
DMS_32730	35793	N	N	N	1	CUSTOMER ISSUE	-
DMS_32732	35794	N	N	N	1	CUSTOMER ISSUE	-
DMS_32733	35795	N	N	N	1	CUSTOMER ISSUE	-
DMS_32734	35796	N	N	N	1	CUSTOMER ISSUE	-
DMS_32735	35797	N	N	N	1	CUSTOMER ISSUE	-
DMS_32736	35798	N	N	N	1	CUSTOMER ISSUE	-
DMS_32737	35799	N	N	N	1	CUSTOMER ISSUE	-
DMS_32738	35800	N	N	N	1	CUSTOMER ISSUE	-
DMS_32741	35801	N	N	N	1	CUSTOMER ISSUE	-
DMS_32742	35802	N	N	N	1	CUSTOMER ISSUE	-
DMS_32743	35803	N	N	N	1	CUSTOMER ISSUE	-
DMS_32745	35804	N	N	N	1	CUSTOMER ISSUE	-
DMS_32748	35805	N	N	N	1	CUSTOMER ISSUE	-
DMS_32749	35806	N	N	N	1	CUSTOMER ISSUE	-
DMS_32750	35807	N	N	N	1	CUSTOMER ISSUE	-
DMS_32751	35808	N	N	N	1	CUSTOMER ISSUE	-
DMS_32752	35809	N	N	N	1	CUSTOMER ISSUE	-
DMS_32753	35810	N	N	N	1	CUSTOMER ISSUE	-
DMS_32754	35811	N	N	N	1	CUSTOMER ISSUE	-
DMS_32755	35812	N	N	N	1	CUSTOMER ISSUE	-
DMS_32756	35813	N	N	N	1	CUSTOMER ISSUE	-
DMS_32757	35814	N	N	N	1	CUSTOMER ISSUE	-
DMS_32758	35815	N	N	N	1	CUSTOMER ISSUE	-
DMS_32759	35816	N	N	N	1	CUSTOMER ISSUE	-

DMS_32760	35817	N	N	N	1	CUSTOMER ISSUE	-
DMS_32761	35818	N	N	N	1	CUSTOMER ISSUE	-
DMS_32762	35819	N	N	N	1	CUSTOMER ISSUE	-
DMS_32763	35820	N	N	N	1	CUSTOMER ISSUE	-
DMS_32764	35821	N	N	N	1	CUSTOMER ISSUE	-
DMS_32765	35822	N	N	N	1	CUSTOMER ISSUE	-
DMS_32773	35823	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32774	35824	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32777	35825	N	N	N	1	CUSTOMER ISSUE	-
DMS_32778	35826	N	N	N	1	CUSTOMER ISSUE	-
DMS_32779	35827	N	N	N	1	CUSTOMER ISSUE	-
DMS_32780	35828	N	N	N	1	CUSTOMER ISSUE	-
DMS_32782	35829	N	N	N	1	CUSTOMER ISSUE	-
DMS_32783	35830	N	N	N	1	CUSTOMER ISSUE	-
DMS_32784	35831	N	N	N	1	CUSTOMER ISSUE	-
DMS_32785	35832	N	N	N	1	CUSTOMER ISSUE	-
DMS_32786	35833	N	N	N	1	CUSTOMER ISSUE	-
DMS_32787	35834	N	N	N	1	CUSTOMER ISSUE	-
DMS_32788	35835	N	N	N	1	CUSTOMER ISSUE	-
DMS_32789	35836	N	N	N	1	CUSTOMER ISSUE	-
DMS_32790	35837	N	N	N	1	CUSTOMER ISSUE	-
DMS_32791	35838	N	N	N	1	CUSTOMER ISSUE	-
DMS_32792	35839	N	N	N	1	CUSTOMER ISSUE	-
DMS_32795	35840	N	N	N	1	CUSTOMER ISSUE	-
DMS_32796	35841	N	N	N	1	CUSTOMER ISSUE	-
DMS_32797	35842	N	N	N	1	CUSTOMER ISSUE	-
DMS_32798	35843	N	N	N	1	CUSTOMER ISSUE	-
DMS_32799	35844	N	N	N	1	CUSTOMER ISSUE	-
DMS_32800	35845	N	N	N	1	CUSTOMER ISSUE	-
DMS_32801	35846	N	N	N	1	CUSTOMER ISSUE	-
DMS_32802	35847	N	N	N	1	CUSTOMER ISSUE	-
DMS_32803	35848	N	N	N	1	CUSTOMER ISSUE	-
DMS_32804	35849	N	N	N	1	CUSTOMER ISSUE	-
DMS_32810	35850	N	N	N	1	CUSTOMER ISSUE	-
DMS_32811	35851	N	N	N	1	CUSTOMER ISSUE	-
DMS_32812	35852	N	N	N	1	CUSTOMER ISSUE	-
DMS_32813	35853	N	N	N	1	CUSTOMER ISSUE	-
DMS_32814	35854	N	N	N	1	CUSTOMER ISSUE	-
DMS_32815	35855	N	N	N	1	CUSTOMER ISSUE	-
DMS_32817	35856	N	N	N	1	CUSTOMER ISSUE	-
DMS_32818	35857	N	N	N	1	CUSTOMER ISSUE	-
DMS_32819	35858	N	N	N	1	CUSTOMER ISSUE	-
DMS_32820	35859	N	N	N	1	CUSTOMER ISSUE	-
DMS_32821	35860	N	N	N	1	CUSTOMER ISSUE	-
DMS_32822	35861	N	N	N	1	CUSTOMER ISSUE	-
DMS_32823	35862	N	N	N	1	CUSTOMER ISSUE	-
DMS_32824	35863	N	N	N	1	CUSTOMER ISSUE	-
DMS_32825	35864	N	N	N	1	CUSTOMER ISSUE	-
DMS_32826	35865	N	N	N	1	CUSTOMER ISSUE	-
DMS_32827	35866	N	N	N	1	CUSTOMER ISSUE	-
DMS_32828	35867	N	N	N	1	CUSTOMER ISSUE	-
DMS_32829	35868	N	N	N	1	CUSTOMER ISSUE	-
DMS_32830	35869	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_32831	35870	N	N	N	1	CUSTOMER ISSUE	-
DMS_32832	35871	N	N	N	1	CUSTOMER ISSUE	-
DMS_32838	35872	N	N	N	1	CUSTOMER ISSUE	-
DMS_32839	35873	N	N	N	1	CUSTOMER ISSUE	-
DMS_32840	35874	N	N	N	1	CUSTOMER ISSUE	-
DMS_32841	35875	N	N	N	1	CUSTOMER ISSUE	-
DMS_32842	35876	N	N	N	1	CUSTOMER ISSUE	-
DMS_32843	35877	N	N	N	1	CUSTOMER ISSUE	-
DMS_32844	35878	N	N	N	1	CUSTOMER ISSUE	-
DMS_32845	35879	N	N	N	1	CUSTOMER ISSUE	-
DMS_32846	35880	N	N	N	1	CUSTOMER ISSUE	-
DMS_32847	35881	N	N	N	1	CUSTOMER ISSUE	-
DMS_32848	35882	N	N	N	1	CUSTOMER ISSUE	-
DMS_32849	35883	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_32850	35884	N	N	N	1	CUSTOMER ISSUE	-
DMS_32851	35885	N	N	N	1	CUSTOMER ISSUE	-
DMS_32852	35886	N	N	N	1	CUSTOMER ISSUE	-
DMS_32853	35887	N	N	N	1	CUSTOMER ISSUE	-
DMS_32854	35888	N	N	N	1	CUSTOMER ISSUE	-
DMS_32856	35889	N	N	N	2	CUSTOMER ISSUE	-
DMS_32857	35890	N	N	N	1	CUSTOMER ISSUE	-
DMS_32858	35891	N	N	N	1	CUSTOMER ISSUE	-
DMS_32859	35892	N	N	N	1	CUSTOMER ISSUE	-
DMS_32860	35893	N	N	N	1	CUSTOMER ISSUE	-
DMS_32861	35894	N	N	N	1	CUSTOMER ISSUE	-
DMS_32862	35895	N	N	N	1	CUSTOMER ISSUE	-
DMS_32863	35896	N	N	N	1	CUSTOMER ISSUE	-

DMS_32864	35897	N	N	N	1	CUSTOMER ISSUE	-
DMS_32865	35898	N	N	N	1	CUSTOMER ISSUE	-
DMS_32866	35899	N	N	N	1	CUSTOMER ISSUE	-
DMS_32867	35900	N	N	N	1	CUSTOMER ISSUE	-
DMS_32868	35901	N	N	N	1	CUSTOMER ISSUE	-
DMS_32869	35902	N	N	N	1	CUSTOMER ISSUE	-
DMS_32870	35903	N	N	N	1	CUSTOMER ISSUE	-
DMS_32871	35904	N	N	N	1	CUSTOMER ISSUE	-
DMS_32872	35905	N	N	N	1	CUSTOMER ISSUE	-
DMS_32873	35906	N	N	N	1	CUSTOMER ISSUE	-
DMS_32874	35907	N	N	N	1	CUSTOMER ISSUE	-
DMS_32875	35908	N	N	N	1	CUSTOMER ISSUE	-
DMS_32876	35909	N	N	N	1	CUSTOMER ISSUE	-
DMS_32877	35910	N	N	N	1	CUSTOMER ISSUE	-
DMS_32878	35911	N	N	N	1	CUSTOMER ISSUE	-
DMS_32879	35912	N	N	N	1	CUSTOMER ISSUE	-
DMS_32880	35913	N	N	N	1	CUSTOMER ISSUE	-
DMS_32881	35914	N	N	N	1	CUSTOMER ISSUE	-
DMS_32882	35915	N	N	N	1	CUSTOMER ISSUE	-
DMS_32883	35916	N	N	N	1	CUSTOMER ISSUE	-
DMS_32884	35917	N	N	N	1	CUSTOMER ISSUE	-
DMS_32885	35918	N	N	N	1	CUSTOMER ISSUE	-
DMS_32886	35919	N	N	N	1	CUSTOMER ISSUE	-
DMS_32887	35920	N	N	N	1	CUSTOMER ISSUE	-
DMS_32888	35921	N	N	N	1	CUSTOMER ISSUE	-
DMS_32889	35922	N	N	N	1	CUSTOMER ISSUE	-
DMS_32890	35923	N	N	N	1	CUSTOMER ISSUE	-
DMS_32891	35924	N	N	N	1	CUSTOMER ISSUE	-
DMS_32892	35925	N	N	N	1	CUSTOMER ISSUE	-
DMS_32893	35926	N	N	N	1	CUSTOMER ISSUE	-
DMS_32894	35927	N	N	N	1	CUSTOMER ISSUE	-
DMS_32895	35928	N	N	N	1	CUSTOMER ISSUE	-
DMS_32896	35929	N	N	N	1	CUSTOMER ISSUE	-
DMS_32897	35930	N	N	N	1	CUSTOMER ISSUE	-
DMS_32899	35931	N	N	N	1	CUSTOMER ISSUE	-
DMS_32900	35932	N	N	N	1	CUSTOMER ISSUE	-
DMS_32902	35933	N	N	N	1	CUSTOMER ISSUE	-
DMS_32904	35934	N	N	N	1	CUSTOMER ISSUE	-
DMS_32905	35935	N	N	N	1	CUSTOMER ISSUE	-
DMS_32906	35936	N	N	N	1	CUSTOMER ISSUE	-
DMS_32907	35937	N	N	N	1	CUSTOMER ISSUE	-
DMS_32908	35938	N	N	N	1	CUSTOMER ISSUE	-
DMS_32909	35939	N	N	N	1	CUSTOMER ISSUE	-
DMS_32910	35940	N	N	N	1	CUSTOMER ISSUE	-
DMS_32911	35941	N	N	N	1	CUSTOMER ISSUE	-
DMS_32912	35942	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32913	35943	N	N	N	1	CUSTOMER ISSUE	-
DMS_32914	35944	N	N	N	1	CUSTOMER ISSUE	-
DMS_32916	35945	N	N	N	1	CUSTOMER ISSUE	-
DMS_32918	35946	N	N	N	1	CUSTOMER ISSUE	-
DMS_32920	35947	N	N	N	1	CUSTOMER ISSUE	-
DMS_32921	35948	N	N	N	1	CUSTOMER ISSUE	-
DMS_32923	35949	N	N	N	1	CUSTOMER ISSUE	-
DMS_32924	35950	N	N	N	1	CUSTOMER ISSUE	-
DMS_32926	35951	N	N	N	1	CUSTOMER ISSUE	-
DMS_32927	35952	N	N	N	1	CUSTOMER ISSUE	-
DMS_32928	35953	N	N	N	1	CUSTOMER ISSUE	-
DMS_32929	35954	N	N	N	1	CUSTOMER ISSUE	-
DMS_32930	35955	N	N	N	1	CUSTOMER ISSUE	-
DMS_32932	35956	N	N	N	1	CUSTOMER ISSUE	-
DMS_32934	35957	N	N	N	1	CUSTOMER ISSUE	-
DMS_32935	35958	N	N	N	1	CUSTOMER ISSUE	-
DMS_32936	35959	N	N	N	1	CUSTOMER ISSUE	-
DMS_32937	35960	N	N	N	1	CUSTOMER ISSUE	-
DMS_32938	35961	N	N	N	1	CUSTOMER ISSUE	-
DMS_32939	35962	N	N	N	1	CUSTOMER ISSUE	-
DMS_32940	35963	N	N	N	1	CUSTOMER ISSUE	-
DMS_32941	35964	N	N	N	1	CUSTOMER ISSUE	-
DMS_32942	35965	N	N	N	1	CUSTOMER ISSUE	-
DMS_32943	35966	N	N	N	1	CUSTOMER ISSUE	-
DMS_32944	35967	N	N	N	1	CUSTOMER ISSUE	-
DMS_32945	35968	N	N	N	1	CUSTOMER ISSUE	-
DMS_32946	35969	N	N	N	1	CUSTOMER ISSUE	-
DMS_32947	35970	N	N	N	1	CUSTOMER ISSUE	-
DMS_32948	35971	N	N	N	1	CUSTOMER ISSUE	-
DMS_32949	35972	N	N	N	1	CUSTOMER ISSUE	-
DMS_32950	35973	N	N	N	1	CUSTOMER ISSUE	-
DMS_32951	35974	N	N	N	1	CUSTOMER ISSUE	-
DMS_32952	35975	N	N	N	1	CUSTOMER ISSUE	-
DMS_32953	35976	N	N	N	1	CUSTOMER ISSUE	-

DMS_32954	35977	N	N	N	1	CUSTOMER ISSUE	-
DMS_32955	35978	N	N	N	1	CUSTOMER ISSUE	-
DMS_32956	35979	N	N	N	1	CUSTOMER ISSUE	-
DMS_32957	35980	N	N	N	1	CUSTOMER ISSUE	-
DMS_32958	35981	N	N	N	1	CUSTOMER ISSUE	-
DMS_32959	35982	N	N	N	1	CUSTOMER ISSUE	-
DMS_32960	35983	N	N	N	1	CUSTOMER ISSUE	-
DMS_32961	35984	N	N	N	1	CUSTOMER ISSUE	-
DMS_32962	35985	N	N	N	1	CUSTOMER ISSUE	-
DMS_32963	35986	N	N	N	1	CUSTOMER ISSUE	-
DMS_32964	35987	N	N	N	1	CUSTOMER ISSUE	-
DMS_32965	35988	N	N	N	1	CUSTOMER ISSUE	-
DMS_32966	35989	N	N	N	1	CUSTOMER ISSUE	-
DMS_32967	35990	N	N	N	1	CUSTOMER ISSUE	-
DMS_32968	35991	N	N	N	1	CUSTOMER ISSUE	-
DMS_32969	35992	N	N	N	1	CUSTOMER ISSUE	-
DMS_32970	35993	N	N	N	2	CUSTOMER ISSUE	-
DMS_32971	35994	N	N	N	1	CUSTOMER ISSUE	-
DMS_32972	35995	N	N	N	1	CUSTOMER ISSUE	-
DMS_32973	35996	N	N	N	1	CUSTOMER ISSUE	-
DMS_32974	35997	N	N	N	1	CUSTOMER ISSUE	-
DMS_32975	35998	N	N	N	1	CUSTOMER ISSUE	-
DMS_32976	35999	N	N	N	1	CUSTOMER ISSUE	-
DMS_32977	36000	N	N	N	1	CUSTOMER ISSUE	-
DMS_32978	36001	N	N	N	1	CUSTOMER ISSUE	-
DMS_32979	36002	N	N	N	1	CUSTOMER ISSUE	-
DMS_32980	36003	N	N	N	1	CUSTOMER ISSUE	-
DMS_32981	36004	N	N	N	1	CUSTOMER ISSUE	-
DMS_32982	36005	N	N	N	1	CUSTOMER ISSUE	-
DMS_32983	36006	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_32984	36007	N	N	N	1	CUSTOMER ISSUE	-
DMS_32985	36008	N	N	N	1	CUSTOMER ISSUE	-
DMS_32986	36009	N	N	N	1	CUSTOMER ISSUE	-
DMS_32987	36010	N	N	N	1	CUSTOMER ISSUE	-
DMS_32988	36011	N	N	N	1	CUSTOMER ISSUE	-
DMS_32990	36012	N	N	N	1	CUSTOMER ISSUE	-
DMS_32991	36013	N	N	N	1	CUSTOMER ISSUE	-
DMS_32992	36014	N	N	N	1	CUSTOMER ISSUE	-
DMS_32993	36015	N	N	N	1	CUSTOMER ISSUE	-
DMS_32994	36016	N	N	N	1	CUSTOMER ISSUE	-
DMS_32995	36017	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_32996	36018	N	N	N	1	CUSTOMER ISSUE	-
DMS_32997	36019	N	N	N	1	CUSTOMER ISSUE	-
DMS_32998	36020	N	N	N	1	CUSTOMER ISSUE	-
DMS_32999	36021	N	N	N	1	CUSTOMER ISSUE	-
DMS_33000	36022	N	N	N	1	CUSTOMER ISSUE	-
DMS_33001	36023	N	N	N	1	CUSTOMER ISSUE	-
DMS_33002	36024	N	N	N	1	CUSTOMER ISSUE	-
DMS_33003	36025	N	N	N	1	CUSTOMER ISSUE	-
DMS_33004	36026	N	N	N	1	CUSTOMER ISSUE	-
DMS_33005	36027	N	N	N	1	CUSTOMER ISSUE	-
DMS_33011	36028	N	N	N	1	CUSTOMER ISSUE	-
DMS_33012	36029	N	N	N	1	CUSTOMER ISSUE	-
DMS_33019	36030	N	N	N	1	CUSTOMER ISSUE	-
DMS_33020	36031	N	N	N	1	CUSTOMER ISSUE	-
DMS_33021	36032	N	N	N	1	CUSTOMER ISSUE	-
DMS_33022	36033	N	N	N	1	CUSTOMER ISSUE	-
DMS_33023	36034	N	N	N	1	CUSTOMER ISSUE	-
DMS_33024	36035	N	N	N	1	CUSTOMER ISSUE	-
DMS_33025	36036	N	N	N	1	CUSTOMER ISSUE	-
DMS_33026	36037	N	N	N	1	CUSTOMER ISSUE	-
DMS_33027	36038	N	N	N	1	CUSTOMER ISSUE	-
DMS_33028	36039	N	N	N	1	CUSTOMER ISSUE	-
DMS_33029	36040	N	N	N	2	CUSTOMER ISSUE	-
DMS_33030	36041	N	N	N	1	CUSTOMER ISSUE	-
DMS_33031	36042	N	N	N	1	CUSTOMER ISSUE	-
DMS_33032	36043	N	N	N	1	CUSTOMER ISSUE	-
DMS_33033	36044	N	N	N	1	CUSTOMER ISSUE	-
DMS_33034	36045	N	N	N	1	CUSTOMER ISSUE	-
DMS_33035	36046	N	N	N	1	CUSTOMER ISSUE	-
DMS_33038	36047	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33039	36048	N	N	N	1	CUSTOMER ISSUE	-
DMS_33040	36049	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_33041	36050	N	N	N	1	CUSTOMER ISSUE	-
DMS_33042	36051	N	N	N	1	CUSTOMER ISSUE	-
DMS_33043	36052	N	N	N	1	CUSTOMER ISSUE	-
DMS_33044	36053	N	N	N	1	CUSTOMER ISSUE	-
DMS_33045	36054	N	N	N	1	CUSTOMER ISSUE	-
DMS_33046	36055	N	N	N	1	CUSTOMER ISSUE	-
DMS_33047	36056	N	N	N	1	CUSTOMER ISSUE	-

DMS_33048	36057	N	N	N	1	CUSTOMER ISSUE	-
DMS_33049	36058	N	N	N	1	CUSTOMER ISSUE	-
DMS_33050	36059	N	N	N	1	CUSTOMER ISSUE	-
DMS_33051	36060	N	N	N	1	CUSTOMER ISSUE	-
DMS_33052	36061	N	N	N	1	CUSTOMER ISSUE	-
DMS_33053	36062	N	N	N	1	CUSTOMER ISSUE	-
DMS_33054	36063	N	N	N	1	CUSTOMER ISSUE	-
DMS_33055	36064	N	N	N	1	CUSTOMER ISSUE	-
DMS_33056	36065	N	N	N	1	CUSTOMER ISSUE	-
DMS_33057	36066	N	N	Y	1	TX - REPLACE	2500
DMS_33058	36067	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33059	36068	N	N	N	1	CUSTOMER ISSUE	-
DMS_33060	36069	N	N	N	1	CUSTOMER ISSUE	-
DMS_33061	36070	N	N	N	1	CUSTOMER ISSUE	-
DMS_33062	36071	N	N	N	1	CUSTOMER ISSUE	-
DMS_33064	36072	N	N	N	1	CUSTOMER ISSUE	-
DMS_33065	36073	N	N	N	1	CUSTOMER ISSUE	-
DMS_33067	36074	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33068	36075	N	N	N	1	CUSTOMER ISSUE	-
DMS_33069	36076	N	N	N	1	CUSTOMER ISSUE	-
DMS_33070	36077	N	N	N	1	CUSTOMER ISSUE	-
DMS_33072	36078	N	N	N	1	CUSTOMER ISSUE	-
DMS_33075	36079	N	N	N	1	CUSTOMER ISSUE	-
DMS_33076	36080	N	N	N	1	CUSTOMER ISSUE	-
DMS_33077	36081	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33078	36082	N	N	N	1	CUSTOMER ISSUE	-
DMS_33079	36083	N	N	N	1	CUSTOMER ISSUE	-
DMS_33081	36084	N	N	N	1	CUSTOMER ISSUE	-
DMS_33082	36085	N	N	N	1	CUSTOMER ISSUE	-
DMS_33083	36086	N	N	N	1	CUSTOMER ISSUE	-
DMS_33084	36087	N	N	N	1	CUSTOMER ISSUE	-
DMS_33085	36088	N	N	N	1	CUSTOMER ISSUE	-
DMS_33087	36089	N	N	N	1	CUSTOMER ISSUE	-
DMS_33088	36090	N	N	N	1	CUSTOMER ISSUE	-
DMS_33089	36091	N	N	N	1	CUSTOMER ISSUE	-
DMS_33090	36092	N	N	N	1	CUSTOMER ISSUE	-
DMS_33091	36093	N	N	N	1	CUSTOMER ISSUE	-
DMS_33093	36094	N	N	N	1	CUSTOMER ISSUE	-
DMS_33094	36095	N	N	N	1	CUSTOMER ISSUE	-
DMS_33095	36096	N	N	N	1	CUSTOMER ISSUE	-
DMS_33096	36097	N	N	N	1	CUSTOMER ISSUE	-
DMS_33097	36098	N	N	N	1	CUSTOMER ISSUE	-
DMS_33098	36099	N	N	N	1	CUSTOMER ISSUE	-
DMS_33099	36100	N	N	N	1	CUSTOMER ISSUE	-
DMS_33100	36101	N	N	N	1	CUSTOMER ISSUE	-
DMS_33101	36102	N	N	N	1	CUSTOMER ISSUE	-
DMS_33102	36103	N	N	N	1	CUSTOMER ISSUE	-
DMS_33103	36104	N	N	N	1	CUSTOMER ISSUE	-
DMS_33104	36105	N	N	N	1	CUSTOMER ISSUE	-
DMS_33105	36106	N	N	N	1	CUSTOMER ISSUE	-
DMS_33107	36107	N	N	N	1	CUSTOMER ISSUE	-
DMS_33108	36108	N	N	N	1	CUSTOMER ISSUE	-
DMS_33109	36109	N	N	N	1	CUSTOMER ISSUE	-
DMS_33110	36110	N	N	N	1	CUSTOMER ISSUE	-
DMS_33111	36111	N	N	N	1	CUSTOMER ISSUE	-
DMS_33112	36112	N	N	N	1	CUSTOMER ISSUE	-
DMS_33113	36113	N	N	N	1	CUSTOMER ISSUE	-
DMS_33114	36114	N	N	N	1	CUSTOMER ISSUE	-
DMS_33115	36115	N	N	N	1	CUSTOMER ISSUE	-
DMS_33116	36116	N	N	N	1	CUSTOMER ISSUE	-
DMS_33117	36117	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33118	36118	N	N	N	1	CUSTOMER ISSUE	-
DMS_33119	36119	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_33120	36120	N	N	N	1	CUSTOMER ISSUE	-
DMS_33121	36121	N	N	N	1	CUSTOMER ISSUE	-
DMS_33122	36122	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33123	36123	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33124	36124	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33125	36125	N	N	N	1	CUSTOMER ISSUE	-
DMS_33126	36126	N	N	N	1	CUSTOMER ISSUE	-
DMS_33127	36127	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_33128	36128	N	N	N	1	CUSTOMER ISSUE	-
DMS_33129	36129	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33130	36130	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33131	36131	N	N	N	1	CUSTOMER ISSUE	-
DMS_33133	36132	N	N	N	1	CUSTOMER ISSUE	-
DMS_33134	36133	N	N	N	1	CUSTOMER ISSUE	-
DMS_33135	36134	N	N	N	1	CUSTOMER ISSUE	-
DMS_33136	36135	N	N	N	1	CUSTOMER ISSUE	-
DMS_33137	36136	N	N	N	1	CUSTOMER ISSUE	-

DMS_33138	36137	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33139	36138	N	N	N	1	CUSTOMER ISSUE	-
DMS_33140	36139	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33141	36140	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33143	36141	N	N	N	1	CUSTOMER ISSUE	-
DMS_33144	36142	N	N	N	1	CUSTOMER ISSUE	-
DMS_33145	36143	N	N	N	1	CUSTOMER ISSUE	-
DMS_33146	36144	N	N	N	1	CUSTOMER ISSUE	-
DMS_33147	36145	N	N	N	1	CUSTOMER ISSUE	-
DMS_33148	36146	N	N	N	1	CUSTOMER ISSUE	-
DMS_33149	36147	N	N	N	1	CUSTOMER ISSUE	-
DMS_33150	36148	N	N	N	1	CUSTOMER ISSUE	-
DMS_33151	36149	N	N	N	1	CUSTOMER ISSUE	-
DMS_33153	36150	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33155	36151	N	N	N	1	CUSTOMER ISSUE	-
DMS_33156	36152	N	N	N	1	CUSTOMER ISSUE	-
DMS_33161	36153	N	N	N	1	CUSTOMER ISSUE	-
DMS_33162	36154	N	N	N	1	CUSTOMER ISSUE	-
DMS_33165	36155	N	N	N	1	CUSTOMER ISSUE	-
DMS_33166	36156	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_33167	36157	N	N	N	1	CUSTOMER ISSUE	-
DMS_33168	36158	N	N	N	1	CUSTOMER ISSUE	-
DMS_33169	36159	N	N	N	1	CUSTOMER ISSUE	-
DMS_33170	36160	N	N	N	1	CUSTOMER ISSUE	-
DMS_33171	36161	N	N	N	1	CUSTOMER ISSUE	-
DMS_33172	36162	N	N	N	1	CUSTOMER ISSUE	-
DMS_33173	36163	N	N	N	1	CUSTOMER ISSUE	-
DMS_33174	36164	N	N	N	1	CUSTOMER ISSUE	-
DMS_33175	36165	N	N	N	1	CUSTOMER ISSUE	-
DMS_33176	36166	N	N	N	1	CUSTOMER ISSUE	-
DMS_33177	36167	N	N	N	1	CUSTOMER ISSUE	-
DMS_33178	36168	N	N	N	1	CUSTOMER ISSUE	-
DMS_33179	36169	N	N	N	2	CUSTOMER ISSUE	-
DMS_33180	36170	N	N	N	1	CUSTOMER ISSUE	-
DMS_33181	36171	N	N	N	1	CUSTOMER ISSUE	-
DMS_33182	36172	N	N	N	1	CUSTOMER ISSUE	-
DMS_33183	36173	N	N	N	1	CUSTOMER ISSUE	-
DMS_33184	36174	N	N	N	1	CUSTOMER ISSUE	-
DMS_33185	36175	N	N	N	1	CUSTOMER ISSUE	-
DMS_33186	36176	N	N	N	1	CUSTOMER ISSUE	-
DMS_33187	36177	N	N	N	1	CUSTOMER ISSUE	-
DMS_33188	36178	N	N	N	1	CUSTOMER ISSUE	-
DMS_33189	36179	N	N	N	1	CUSTOMER ISSUE	-
DMS_33190	36180	N	N	N	1	CUSTOMER ISSUE	-
DMS_33191	36181	N	N	N	1	CUSTOMER ISSUE	-
DMS_33192	36182	N	N	N	1	CUSTOMER ISSUE	-
DMS_33193	36183	N	N	N	1	CUSTOMER ISSUE	-
DMS_33194	36184	N	N	N	1	CUSTOMER ISSUE	-
DMS_33196	36185	N	N	N	1	CUSTOMER ISSUE	-
DMS_33197	36186	N	N	N	1	CUSTOMER ISSUE	-
DMS_33199	36187	N	N	N	1	CUSTOMER ISSUE	-
DMS_33200	36188	N	N	N	1	CUSTOMER ISSUE	-
DMS_33201	36189	N	N	N	1	CUSTOMER ISSUE	-
DMS_33202	36190	N	N	N	1	CUSTOMER ISSUE	-
DMS_33203	36191	N	N	N	1	CUSTOMER ISSUE	-
DMS_33204	36192	N	N	N	1	CUSTOMER ISSUE	-
DMS_33205	36193	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33207	36194	N	N	N	1	CUSTOMER ISSUE	-
DMS_33208	36195	N	N	N	1	CUSTOMER ISSUE	-
DMS_33209	36196	N	N	N	1	CUSTOMER ISSUE	-
DMS_33210	36197	N	N	N	1	CUSTOMER ISSUE	-
DMS_33211	36198	N	N	N	1	CUSTOMER ISSUE	-
DMS_33212	36199	N	N	N	1	CUSTOMER ISSUE	-
DMS_33213	36200	N	N	N	1	CUSTOMER ISSUE	-
DMS_33214	36201	N	N	N	1	CUSTOMER ISSUE	-
DMS_33215	36202	N	N	N	1	CUSTOMER ISSUE	-
DMS_33216	36203	N	N	N	1	CUSTOMER ISSUE	-
DMS_33217	36204	N	N	N	1	CUSTOMER ISSUE	-
DMS_33218	36205	N	N	N	1	CUSTOMER ISSUE	-
DMS_33219	36206	N	N	N	1	CUSTOMER ISSUE	-
DMS_33220	36207	N	N	N	1	CUSTOMER ISSUE	-
DMS_33221	36208	N	N	N	1	CUSTOMER ISSUE	-
DMS_33222	36209	N	N	N	1	CUSTOMER ISSUE	-
DMS_33223	36210	N	N	N	1	CUSTOMER ISSUE	-
DMS_33224	36211	N	N	N	1	CUSTOMER ISSUE	-
DMS_33225	36212	N	N	N	1	CUSTOMER ISSUE	-
DMS_33226	36213	N	N	N	2	CUSTOMER ISSUE	-
DMS_33227	36214	N	N	N	1	CUSTOMER ISSUE	-
DMS_33228	36215	N	N	N	1	CUSTOMER ISSUE	-
DMS_33229	36216	N	N	N	1	CUSTOMER ISSUE	-

DMS_33230	36217	N	N	N	1	CUSTOMER ISSUE	-
DMS_33231	36218	N	N	N	1	CUSTOMER ISSUE	-
DMS_33232	36219	N	N	N	1	CUSTOMER ISSUE	-
DMS_33233	36220	N	N	N	1	CUSTOMER ISSUE	-
DMS_33234	36221	N	N	N	1	CUSTOMER ISSUE	-
DMS_33235	36222	N	N	N	1	CUSTOMER ISSUE	-
DMS_33236	36223	N	N	N	1	CUSTOMER ISSUE	-
DMS_33237	36224	N	N	N	1	CUSTOMER ISSUE	-
DMS_33238	36225	N	N	N	1	CUSTOMER ISSUE	-
DMS_33239	36226	N	N	N	1	CUSTOMER ISSUE	-
DMS_33240	36227	N	N	N	1	CUSTOMER ISSUE	-
DMS_33241	36228	N	N	N	1	CUSTOMER ISSUE	-
DMS_33242	36229	N	N	N	1	CUSTOMER ISSUE	-
DMS_33243	36230	N	N	Y	1	TX - REPLACE	2500
DMS_33245	36231	N	N	N	1	CUSTOMER ISSUE	-
DMS_33246	36232	N	N	N	1	CUSTOMER ISSUE	-
DMS_33247	36233	N	N	N	1	CUSTOMER ISSUE	-
DMS_33248	36234	N	N	N	1	CUSTOMER ISSUE	-
DMS_33249	36235	N	N	N	1	CUSTOMER ISSUE	-
DMS_33250	36236	N	N	N	1	CUSTOMER ISSUE	-
DMS_33251	36237	N	N	N	1	CUSTOMER ISSUE	-
DMS_33252	36238	N	N	N	1	CUSTOMER ISSUE	-
DMS_33253	36239	N	N	N	1	CUSTOMER ISSUE	-
DMS_33254	36240	N	N	N	1	CUSTOMER ISSUE	-
DMS_33255	36241	N	N	N	1	CUSTOMER ISSUE	-
DMS_33256	36242	N	N	N	1	CUSTOMER ISSUE	-
DMS_33257	36243	N	N	N	1	CUSTOMER ISSUE	-
DMS_33258	36244	N	N	N	1	CUSTOMER ISSUE	-
DMS_33259	36245	N	N	N	1	CUSTOMER ISSUE	-
DMS_33260	36246	N	N	N	1	CUSTOMER ISSUE	-
DMS_33261	36247	N	N	N	1	CUSTOMER ISSUE	-
DMS_33263	36248	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33264	36249	N	N	N	1	CUSTOMER ISSUE	-
DMS_33265	36250	N	N	N	1	CUSTOMER ISSUE	-
DMS_33266	36251	N	N	N	1	CUSTOMER ISSUE	-
DMS_33267	36252	N	N	N	1	CUSTOMER ISSUE	-
DMS_33268	36253	N	N	N	1	CUSTOMER ISSUE	-
DMS_33269	36254	N	N	N	1	CUSTOMER ISSUE	-
DMS_33270	36255	N	N	N	1	CUSTOMER ISSUE	-
DMS_33271	36256	N	N	N	1	CUSTOMER ISSUE	-
DMS_33273	36257	N	N	N	1	CUSTOMER ISSUE	-
DMS_33274	36258	N	N	N	1	CUSTOMER ISSUE	-
DMS_33275	36259	N	N	N	1	CUSTOMER ISSUE	-
DMS_33276	36260	N	N	N	1	CUSTOMER ISSUE	-
DMS_33278	36261	N	N	N	1	CUSTOMER ISSUE	-
DMS_33279	36262	N	N	N	1	CUSTOMER ISSUE	-
DMS_33280	36263	N	N	N	1	CUSTOMER ISSUE	-
DMS_33281	36264	N	N	N	1	CUSTOMER ISSUE	-
DMS_33282	36265	N	N	N	1	CUSTOMER ISSUE	-
DMS_33283	36266	N	N	N	1	CUSTOMER ISSUE	-
DMS_33284	36267	N	N	N	1	CUSTOMER ISSUE	-
DMS_33285	36268	N	N	N	1	CUSTOMER ISSUE	-
DMS_33289	36269	N	N	N	1	CUSTOMER ISSUE	-
DMS_33291	36270	N	N	N	1	CUSTOMER ISSUE	-
DMS_33293	36271	N	N	N	1	CUSTOMER ISSUE	-
DMS_33296	36272	N	N	N	1	CUSTOMER ISSUE	-
DMS_33297	36273	N	N	N	1	CUSTOMER ISSUE	-
DMS_33298	36274	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33299	36275	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33300	36276	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33301	36277	N	N	N	1	CUSTOMER ISSUE	-
DMS_33302	36278	N	N	N	1	CUSTOMER ISSUE	-
DMS_33303	36279	N	N	N	1	CUSTOMER ISSUE	-
DMS_33304	36280	N	N	N	1	CUSTOMER ISSUE	-
DMS_33305	36281	N	N	N	1	CUSTOMER ISSUE	-
DMS_33306	36282	N	N	N	1	CUSTOMER ISSUE	-
DMS_33307	36283	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33308	36284	N	N	N	1	CUSTOMER ISSUE	-
DMS_33309	36285	N	N	N	1	CUSTOMER ISSUE	-
DMS_33310	36286	N	N	N	1	CUSTOMER ISSUE	-
DMS_33311	36287	N	N	N	1	CUSTOMER ISSUE	-
DMS_33312	36288	N	N	N	1	CUSTOMER ISSUE	-
DMS_33313	36289	N	N	N	1	CUSTOMER ISSUE	-
DMS_33315	36290	N	N	N	1	CUSTOMER ISSUE	-
DMS_33317	36291	N	N	N	1	CUSTOMER ISSUE	-
DMS_33318	36292	N	N	N	1	CUSTOMER ISSUE	-
DMS_33319	36293	N	N	N	1	CUSTOMER ISSUE	-
DMS_33320	36294	N	N	N	1	CUSTOMER ISSUE	-
DMS_33321	36295	N	N	N	1	CUSTOMER ISSUE	-
DMS_33322	36296	N	N	N	1	CUSTOMER ISSUE	-

DMS_33324	36297	N	N	N	1	CUSTOMER ISSUE	-
DMS_33325	36298	N	N	N	1	CUSTOMER ISSUE	-
DMS_33326	36299	N	N	N	1	CUSTOMER ISSUE	-
DMS_33327	36300	N	N	N	1	CUSTOMER ISSUE	-
DMS_33328	36301	N	N	N	1	CUSTOMER ISSUE	-
DMS_33329	36302	N	N	N	1	CUSTOMER ISSUE	-
DMS_33330	36303	N	N	N	1	CUSTOMER ISSUE	-
DMS_33332	36304	N	N	N	1	CUSTOMER ISSUE	-
DMS_33334	36305	N	N	N	1	CUSTOMER ISSUE	-
DMS_33335	36306	N	N	N	1	CUSTOMER ISSUE	-
DMS_33336	36307	N	N	N	1	CUSTOMER ISSUE	-
DMS_33337	36308	N	N	N	1	CUSTOMER ISSUE	-
DMS_33338	36309	N	N	N	1	CUSTOMER ISSUE	-
DMS_33339	36310	N	N	N	1	CUSTOMER ISSUE	-
DMS_33340	36311	N	N	N	1	CUSTOMER ISSUE	-
DMS_33341	36312	N	N	N	1	CUSTOMER ISSUE	-
DMS_33342	36313	N	N	N	1	CUSTOMER ISSUE	-
DMS_33343	36314	N	N	N	1	CUSTOMER ISSUE	-
DMS_33344	36315	N	N	N	1	CUSTOMER ISSUE	-
DMS_33345	36316	N	N	N	1	CUSTOMER ISSUE	-
DMS_33347	36317	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33350	36318	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33351	36319	N	N	N	1	CUSTOMER ISSUE	-
DMS_33352	36320	N	N	N	1	CUSTOMER ISSUE	-
DMS_33353	36321	N	N	N	1	CUSTOMER ISSUE	-
DMS_33355	36322	N	N	N	1	CUSTOMER ISSUE	-
DMS_33356	36323	N	N	N	1	CUSTOMER ISSUE	-
DMS_33358	36324	N	N	N	1	CUSTOMER ISSUE	-
DMS_33359	36325	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33360	36326	N	N	N	1	CUSTOMER ISSUE	-
DMS_33361	36327	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_33362	36328	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_33363	36329	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_33364	36330	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_33365	36331	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_33366	36332	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_33367	36333	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33368	36334	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33369	36335	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33370	36336	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33371	36337	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33372	36338	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33373	36339	N	N	N	1	CUSTOMER ISSUE	-
DMS_33374	36340	N	N	N	1	CUSTOMER ISSUE	-
DMS_33375	36341	N	N	N	1	CUSTOMER ISSUE	-
DMS_33376	36342	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_33377	36343	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_33378	36344	N	N	N	1	CUSTOMER ISSUE	-
DMS_33379	36345	N	N	N	1	CUSTOMER ISSUE	-
DMS_33381	36346	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33382	36347	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33384	36348	N	N	N	1	CUSTOMER ISSUE	-
DMS_33385	36349	N	N	N	1	CUSTOMER ISSUE	-
DMS_33386	36350	N	N	N	1	CUSTOMER ISSUE	-
DMS_33387	36351	N	N	N	1	CUSTOMER ISSUE	-
DMS_33389	36352	N	N	N	1	CUSTOMER ISSUE	-
DMS_33390	36353	N	N	N	1	CUSTOMER ISSUE	-
DMS_33391	36354	N	N	N	1	CUSTOMER ISSUE	-
DMS_33392	36355	N	N	N	1	CUSTOMER ISSUE	-
DMS_33393	36356	N	N	N	1	CUSTOMER ISSUE	-
DMS_33394	36357	N	N	N	1	CUSTOMER ISSUE	-
DMS_33395	36358	N	N	N	1	CUSTOMER ISSUE	-
DMS_33396	36359	N	N	N	1	CUSTOMER ISSUE	-
DMS_33397	36360	N	N	N	1	CUSTOMER ISSUE	-
DMS_33398	36361	N	N	N	1	CUSTOMER ISSUE	-
DMS_33399	36362	N	N	N	1	CUSTOMER ISSUE	-
DMS_33400	36363	N	N	N	1	CUSTOMER ISSUE	-
DMS_33401	36364	N	N	N	1	CUSTOMER ISSUE	-
DMS_33402	36365	N	N	N	1	CUSTOMER ISSUE	-
DMS_33403	36366	N	N	N	1	CUSTOMER ISSUE	-
DMS_33404	36367	N	N	N	1	CUSTOMER ISSUE	-
DMS_33405	36368	N	N	N	1	CUSTOMER ISSUE	-
DMS_33406	36369	N	N	N	1	CUSTOMER ISSUE	-
DMS_33407	36370	N	N	N	1	CUSTOMER ISSUE	-
DMS_33408	36371	N	N	N	1	CUSTOMER ISSUE	-
DMS_33409	36372	N	N	N	1	CUSTOMER ISSUE	-
DMS_33410	36373	N	N	N	1	CUSTOMER ISSUE	-
DMS_33414	36374	N	N	N	1	CUSTOMER ISSUE	-
DMS_33415	36375	N	N	N	1	CUSTOMER ISSUE	-
DMS_33416	36376	N	N	N	1	CUSTOMER ISSUE	-

DMS_33417	36377	N	N	N	1	CUSTOMER ISSUE	-
DMS_33418	36378	N	N	N	1	CUSTOMER ISSUE	-
DMS_33419	36379	N	N	N	1	CUSTOMER ISSUE	-
DMS_33420	36380	N	N	N	1	CUSTOMER ISSUE	-
DMS_33421	36381	N	N	N	1	CUSTOMER ISSUE	-
DMS_33422	36382	N	N	N	1	CUSTOMER ISSUE	-
DMS_33423	36383	N	N	N	1	CUSTOMER ISSUE	-
DMS_33424	36384	N	N	N	1	CUSTOMER ISSUE	-
DMS_33425	36385	N	N	N	1	CUSTOMER ISSUE	-
DMS_33426	36386	N	N	N	1	CUSTOMER ISSUE	-
DMS_33427	36387	N	N	N	1	CUSTOMER ISSUE	-
DMS_33428	36388	N	N	N	1	CUSTOMER ISSUE	-
DMS_33429	36389	N	N	N	1	CUSTOMER ISSUE	-
DMS_33430	36390	N	N	N	1	CUSTOMER ISSUE	-
DMS_33431	36391	N	N	N	1	CUSTOMER ISSUE	-
DMS_33432	36392	N	N	N	1	CUSTOMER ISSUE	-
DMS_33433	36393	N	N	N	1	CUSTOMER ISSUE	-
DMS_33434	36394	N	N	N	1	CUSTOMER ISSUE	-
DMS_33435	36395	N	N	N	1	CUSTOMER ISSUE	-
DMS_33436	36396	N	N	N	1	CUSTOMER ISSUE	-
DMS_33437	36397	N	N	N	1	CUSTOMER ISSUE	-
DMS_33438	36398	N	N	N	1	CUSTOMER ISSUE	-
DMS_33439	36399	N	N	N	1	CUSTOMER ISSUE	-
DMS_33440	36400	N	N	N	1	CUSTOMER ISSUE	-
DMS_33441	36401	N	N	N	1	CUSTOMER ISSUE	-
DMS_33442	36402	N	N	N	1	CUSTOMER ISSUE	-
DMS_33443	36403	N	N	N	1	CUSTOMER ISSUE	-
DMS_33444	36404	N	N	N	1	CUSTOMER ISSUE	-
DMS_33445	36405	N	N	N	1	CUSTOMER ISSUE	-
DMS_33446	36406	N	N	N	1	CUSTOMER ISSUE	-
DMS_33448	36407	N	N	N	1	CUSTOMER ISSUE	-
DMS_33488	36408	N	N	N	1	CUSTOMER ISSUE	-
DMS_33489	36409	N	N	N	1	CUSTOMER ISSUE	-
DMS_33490	36410	N	N	N	1	CUSTOMER ISSUE	-
DMS_33491	36411	N	N	N	1	CUSTOMER ISSUE	-
DMS_33492	36412	N	N	N	1	CUSTOMER ISSUE	-
DMS_33493	36413	N	N	N	1	CUSTOMER ISSUE	-
DMS_33494	36414	N	N	N	1	CUSTOMER ISSUE	-
DMS_33495	36415	N	N	N	1	CUSTOMER ISSUE	-
DMS_33496	36416	N	N	N	1	CUSTOMER ISSUE	-
DMS_33497	36417	N	N	N	1	CUSTOMER ISSUE	-
DMS_33498	36418	N	N	N	1	CUSTOMER ISSUE	-
DMS_33501	36419	N	N	N	1	CUSTOMER ISSUE	-
DMS_33502	36420	N	N	N	1	CUSTOMER ISSUE	-
DMS_33503	36421	N	N	N	1	CUSTOMER ISSUE	-
DMS_33504	36422	N	N	N	1	CUSTOMER ISSUE	-
DMS_33506	36423	N	N	N	1	CUSTOMER ISSUE	-
DMS_33507	36424	N	N	N	1	CUSTOMER ISSUE	-
DMS_33508	36425	N	N	N	1	CUSTOMER ISSUE	-
DMS_33509	36426	N	N	N	1	CUSTOMER ISSUE	-
DMS_33510	36427	N	N	N	1	CUSTOMER ISSUE	-
DMS_33511	36428	N	N	N	1	CUSTOMER ISSUE	-
DMS_33512	36429	N	N	N	1	CUSTOMER ISSUE	-
DMS_33513	36430	N	N	N	1	CUSTOMER ISSUE	-
DMS_33514	36431	N	N	N	1	CUSTOMER ISSUE	-
DMS_33515	36432	N	N	N	1	CUSTOMER ISSUE	-
DMS_33516	36433	N	N	N	1	CUSTOMER ISSUE	-
DMS_33517	36434	N	N	N	1	CUSTOMER ISSUE	-
DMS_33518	36435	N	N	N	1	CUSTOMER ISSUE	-
DMS_33519	36436	N	N	N	1	CUSTOMER ISSUE	-
DMS_33520	36437	N	N	N	1	CUSTOMER ISSUE	-
DMS_33521	36438	N	N	N	1	CUSTOMER ISSUE	-
DMS_33522	36439	N	N	N	1	CUSTOMER ISSUE	-
DMS_33523	36440	N	N	N	1	CUSTOMER ISSUE	-
DMS_33528	36441	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33529	36442	N	N	N	1	CUSTOMER ISSUE	-
DMS_33533	36443	N	N	N	1	CUSTOMER ISSUE	-
DMS_33534	36444	N	N	N	1	CUSTOMER ISSUE	-
DMS_33536	36445	N	N	N	1	CUSTOMER ISSUE	-
DMS_33537	36446	N	N	N	1	CUSTOMER ISSUE	-
DMS_33538	36447	N	N	N	1	CUSTOMER ISSUE	-
DMS_33542	36448	N	N	N	1	CUSTOMER ISSUE	-
DMS_33543	36449	N	N	N	1	CUSTOMER ISSUE	-
DMS_33544	36450	N	N	N	1	CUSTOMER ISSUE	-
DMS_33545	36451	N	N	N	1	CUSTOMER ISSUE	-
DMS_33546	36452	N	N	N	1	CUSTOMER ISSUE	-
DMS_33547	36453	N	N	N	1	CUSTOMER ISSUE	-
DMS_33548	36454	N	N	N	1	CUSTOMER ISSUE	-
DMS_33549	36455	N	N	N	1	CUSTOMER ISSUE	-
DMS_33550	36456	N	N	N	1	CUSTOMER ISSUE	-

DMS_33551	36457	N	N	N	1	CUSTOMER ISSUE	-
DMS_33552	36458	N	N	N	1	CUSTOMER ISSUE	-
DMS_33553	36459	N	N	N	1	CUSTOMER ISSUE	-
DMS_33554	36460	N	N	N	1	CUSTOMER ISSUE	-
DMS_33555	36461	N	N	N	1	CUSTOMER ISSUE	-
DMS_33556	36462	N	N	N	1	CUSTOMER ISSUE	-
DMS_33557	36463	N	N	N	1	CUSTOMER ISSUE	-
DMS_33558	36464	N	N	N	1	CUSTOMER ISSUE	-
DMS_33559	36465	N	N	N	1	CUSTOMER ISSUE	-
DMS_33560	36466	N	N	N	1	CUSTOMER ISSUE	-
DMS_33561	36467	N	N	N	1	CUSTOMER ISSUE	-
DMS_33562	36468	N	N	N	1	CUSTOMER ISSUE	-
DMS_33563	36469	N	N	N	1	CUSTOMER ISSUE	-
DMS_33564	36470	N	N	N	1	CUSTOMER ISSUE	-
DMS_33565	36471	N	N	N	1	CUSTOMER ISSUE	-
DMS_33566	36472	N	N	N	1	CUSTOMER ISSUE	-
DMS_33567	36473	N	N	N	1	CUSTOMER ISSUE	-
DMS_33568	36474	N	N	N	1	CUSTOMER ISSUE	-
DMS_33570	36475	N	N	N	1	CUSTOMER ISSUE	-
DMS_33571	36476	N	N	N	1	CUSTOMER ISSUE	-
DMS_33572	36477	N	N	N	1	CUSTOMER ISSUE	-
DMS_33573	36478	N	N	N	1	CUSTOMER ISSUE	-
DMS_33574	36479	N	N	N	1	CUSTOMER ISSUE	-
DMS_33575	36480	N	N	N	1	CUSTOMER ISSUE	-
DMS_33576	36481	N	N	N	1	CUSTOMER ISSUE	-
DMS_33577	36482	N	N	N	1	CUSTOMER ISSUE	-
DMS_33578	36483	N	N	N	1	CUSTOMER ISSUE	-
DMS_33579	36484	N	N	N	1	CUSTOMER ISSUE	-
DMS_33582	36485	N	N	N	1	CUSTOMER ISSUE	-
DMS_33583	36486	N	N	N	1	CUSTOMER ISSUE	-
DMS_33587	36487	N	N	N	1	CUSTOMER ISSUE	-
DMS_33588	36488	N	N	N	1	CUSTOMER ISSUE	-
DMS_33590	36489	N	N	N	1	CUSTOMER ISSUE	-
DMS_33591	36490	N	N	N	1	CUSTOMER ISSUE	-
DMS_33592	36491	N	N	N	1	CUSTOMER ISSUE	-
DMS_33593	36492	N	N	N	1	CUSTOMER ISSUE	-
DMS_33594	36493	N	N	N	1	CUSTOMER ISSUE	-
DMS_33595	36494	N	N	N	1	CUSTOMER ISSUE	-
DMS_33596	36495	N	N	N	1	CUSTOMER ISSUE	-
DMS_33597	36496	N	N	N	1	CUSTOMER ISSUE	-
DMS_33598	36497	N	N	N	1	CUSTOMER ISSUE	-
DMS_33599	36498	N	N	N	1	CUSTOMER ISSUE	-
DMS_33600	36499	N	N	N	1	CUSTOMER ISSUE	-
DMS_33601	36500	N	N	N	1	CUSTOMER ISSUE	-
DMS_33602	36501	N	N	N	1	CUSTOMER ISSUE	-
DMS_33603	36502	N	N	N	1	CUSTOMER ISSUE	-
DMS_33604	36503	N	N	N	1	CUSTOMER ISSUE	-
DMS_33605	36504	N	N	N	1	CUSTOMER ISSUE	-
DMS_33607	36505	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33609	36506	N	N	N	1	CUSTOMER ISSUE	-
DMS_33616	36507	N	N	N	1	CUSTOMER ISSUE	-
DMS_33617	36508	N	N	N	1	CUSTOMER ISSUE	-
DMS_33618	36509	N	N	N	1	CUSTOMER ISSUE	-
DMS_33619	36510	N	N	N	1	CUSTOMER ISSUE	-
DMS_33620	36511	N	N	N	1	CUSTOMER ISSUE	-
DMS_33621	36512	N	N	N	1	CUSTOMER ISSUE	-
DMS_33622	36513	N	N	N	1	CUSTOMER ISSUE	-
DMS_33623	36514	N	N	N	1	CUSTOMER ISSUE	-
DMS_33624	36515	N	N	N	1	CUSTOMER ISSUE	-
DMS_33625	36516	N	N	N	1	CUSTOMER ISSUE	-
DMS_33626	36517	N	N	N	1	CUSTOMER ISSUE	-
DMS_33627	36518	N	N	N	1	CUSTOMER ISSUE	-
DMS_33628	36519	N	N	N	1	CUSTOMER ISSUE	-
DMS_33629	36520	N	N	N	1	CUSTOMER ISSUE	-
DMS_33630	36521	N	N	N	1	CUSTOMER ISSUE	-
DMS_33631	36522	N	N	N	1	CUSTOMER ISSUE	-
DMS_33632	36523	N	N	N	1	CUSTOMER ISSUE	-
DMS_33633	36524	N	N	N	1	CUSTOMER ISSUE	-
DMS_33634	36525	N	N	N	1	CUSTOMER ISSUE	-
DMS_33635	36526	N	N	N	1	CUSTOMER ISSUE	-
DMS_33636	36527	N	N	N	1	CUSTOMER ISSUE	-
DMS_33638	36528	N	N	N	1	CUSTOMER ISSUE	-
DMS_33639	36529	N	N	N	1	CUSTOMER ISSUE	-
DMS_33640	36530	N	N	N	1	CUSTOMER ISSUE	-
DMS_33641	36531	N	N	N	1	CUSTOMER ISSUE	-
DMS_33642	36532	N	N	N	1	CUSTOMER ISSUE	-
DMS_33645	36533	N	N	N	1	CUSTOMER ISSUE	-
DMS_33646	36534	N	N	N	1	CUSTOMER ISSUE	-
DMS_33647	36535	N	N	N	1	CUSTOMER ISSUE	-
DMS_33648	36536	N	N	N	1	CUSTOMER ISSUE	-

DMS_33649	36537	N	N	N	1	CUSTOMER ISSUE	-
DMS_33650	36538	N	N	N	1	CUSTOMER ISSUE	-
DMS_33651	36539	N	N	N	1	CUSTOMER ISSUE	-
DMS_33652	36540	N	N	N	1	CUSTOMER ISSUE	-
DMS_33653	36541	N	N	N	1	CUSTOMER ISSUE	-
DMS_33655	36542	N	N	N	1	CUSTOMER ISSUE	-
DMS_33656	36543	N	N	N	1	CUSTOMER ISSUE	-
DMS_33657	36544	N	N	N	1	CUSTOMER ISSUE	-
DMS_33658	36545	N	N	N	1	CUSTOMER ISSUE	-
DMS_33659	36546	N	N	N	1	CUSTOMER ISSUE	-
DMS_33660	36547	N	N	N	1	CUSTOMER ISSUE	-
DMS_33661	36548	N	N	N	1	CUSTOMER ISSUE	-
DMS_33662	36549	N	N	N	1	CUSTOMER ISSUE	-
DMS_33663	36550	N	N	N	1	CUSTOMER ISSUE	-
DMS_33664	36551	N	N	N	1	CUSTOMER ISSUE	-
DMS_33665	36552	N	N	N	2	CUSTOMER ISSUE	-
DMS_33666	36553	N	N	N	1	CUSTOMER ISSUE	-
DMS_33667	36554	N	N	N	1	CUSTOMER ISSUE	-
DMS_33668	36555	N	N	N	1	CUSTOMER ISSUE	-
DMS_33669	36556	N	N	N	1	CUSTOMER ISSUE	-
DMS_33671	36557	N	N	N	1	CUSTOMER ISSUE	-
DMS_33673	36558	N	N	N	1	CUSTOMER ISSUE	-
DMS_33674	36559	N	N	N	1	CUSTOMER ISSUE	-
DMS_33675	36560	N	N	N	1	CUSTOMER ISSUE	-
DMS_33676	36561	N	N	N	1	CUSTOMER ISSUE	-
DMS_33681	36562	N	N	N	1	CUSTOMER ISSUE	-
DMS_33682	36563	N	N	N	1	CUSTOMER ISSUE	-
DMS_33683	36564	N	N	N	1	CUSTOMER ISSUE	-
DMS_33684	36565	N	N	N	1	CUSTOMER ISSUE	-
DMS_33685	36566	N	N	N	1	CUSTOMER ISSUE	-
DMS_33686	36567	N	N	N	1	CUSTOMER ISSUE	-
DMS_33687	36568	N	N	N	1	CUSTOMER ISSUE	-
DMS_33688	36569	N	N	N	1	CUSTOMER ISSUE	-
DMS_33689	36570	N	N	N	1	CUSTOMER ISSUE	-
DMS_33690	36571	N	N	N	1	CUSTOMER ISSUE	-
DMS_33691	36572	N	N	N	1	CUSTOMER ISSUE	-
DMS_33692	36573	N	N	N	1	CUSTOMER ISSUE	-
DMS_33693	36574	N	N	N	1	CUSTOMER ISSUE	-
DMS_33694	36575	N	N	N	1	CUSTOMER ISSUE	-
DMS_33696	36576	N	N	N	1	CUSTOMER ISSUE	-
DMS_33697	36577	N	N	N	1	CUSTOMER ISSUE	-
DMS_33698	36578	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_33699	36579	N	N	N	1	CUSTOMER ISSUE	-
DMS_33700	36580	N	N	N	1	CUSTOMER ISSUE	-
DMS_33701	36581	N	N	N	1	CUSTOMER ISSUE	-
DMS_33702	36582	N	N	N	1	CUSTOMER ISSUE	-
DMS_33703	36583	N	N	N	1	CUSTOMER ISSUE	-
DMS_33704	36584	N	N	N	1	CUSTOMER ISSUE	-
DMS_33707	36585	N	N	N	1	CUSTOMER ISSUE	-
DMS_33708	36586	N	N	N	1	CUSTOMER ISSUE	-
DMS_33710	36587	N	N	N	1	CUSTOMER ISSUE	-
DMS_33711	36588	N	N	N	1	CUSTOMER ISSUE	-
DMS_33712	36589	N	N	N	1	CUSTOMER ISSUE	-
DMS_33713	36590	N	N	N	1	CUSTOMER ISSUE	-
DMS_33714	36591	N	N	N	1	CUSTOMER ISSUE	-
DMS_33716	36592	N	N	N	1	CUSTOMER ISSUE	-
DMS_33720	36593	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33721	36594	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_33722	36595	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
DMS_33723	36596	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_33724	36597	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33725	36598	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33726	36599	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33727	36600	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33728	36601	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33729	36602	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33730	36603	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33731	36604	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33732	36605	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33733	36606	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33734	36607	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33735	36608	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33737	36609	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33738	36610	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33739	36611	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33740	36612	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33741	36613	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33742	36614	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33743	36615	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33744	36616	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_33745	36617	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33746	36618	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33747	36619	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33748	36620	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33749	36621	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33750	36622	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33751	36623	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33752	36624	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33753	36625	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33754	36626	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33755	36627	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_33756	36628	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33757	36629	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_33758	36630	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
DMS_33759	36631	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_33760	36632	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_33761	36633	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_33762	36634	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
DMS_33763	36635	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_33764	36636	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_33765	36637	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33766	36638	N	N	N	1	CUSTOMER ISSUE	-
DMS_33769	36639	N	N	N	1	CUSTOMER ISSUE	-
DMS_33771	36640	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33772	36641	N	N	N	2	CUSTOMER ISSUE	-
DMS_33773	36642	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33774	36643	N	N	N	1	CUSTOMER ISSUE	-
DMS_33775	36644	N	N	N	1	CUSTOMER ISSUE	-
DMS_33777	36645	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33778	36646	N	N	N	1	CUSTOMER ISSUE	-
DMS_33779	36647	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33780	36648	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33781	36649	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33782	36650	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33783	36651	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33785	36652	N	N	N	1	CUSTOMER ISSUE	-
DMS_33786	36653	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33787	36654	N	N	N	1	CUSTOMER ISSUE	-
DMS_33788	36655	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33790	36656	N	N	N	1	CUSTOMER ISSUE	-
DMS_33791	36657	N	N	N	1	CUSTOMER ISSUE	-
DMS_33792	36658	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33793	36659	N	N	N	1	CUSTOMER ISSUE	-
DMS_33794	36660	N	N	N	1	CUSTOMER ISSUE	-
DMS_33795	36661	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33799	36662	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33801	36663	N	N	N	1	CUSTOMER ISSUE	-
DMS_33802	36664	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_33803	36665	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_33804	36666	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33805	36667	N	N	Y	3	SEC/SVC - REPAIR	472.5
DMS_33806	36668	N	N	N	1	CUSTOMER ISSUE	-
DMS_33807	36669	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33808	36670	N	N	N	1	CUSTOMER ISSUE	-
DMS_33818	36671	N	N	N	1	CUSTOMER ISSUE	-
DMS_33820	36672	N	N	N	1	CUSTOMER ISSUE	-
DMS_33821	36673	N	N	N	1	CUSTOMER ISSUE	-
DMS_33822	36674	N	N	N	1	CUSTOMER ISSUE	-
DMS_33823	36675	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_33825	36676	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_33826	36677	N	N	N	1	CUSTOMER ISSUE	-
DMS_33827	36678	N	N	N	1	CUSTOMER ISSUE	-
DMS_33828	36679	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33829	36680	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33830	36681	N	N	N	1	CUSTOMER ISSUE	-
DMS_33831	36682	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33846	36683	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33848	36684	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33849	36685	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33850	36686	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33851	36687	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33852	36688	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33853	36689	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33854	36690	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_33855	36691	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33858	36692	N	N	N	1	CUSTOMER ISSUE	-
DMS_33859	36693	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33860	36694	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33863	36695	N	N	N	1	CUSTOMER ISSUE	-
DMS_33865	36696	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_33866	36697	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33867	36698	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33870	36699	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33871	36700	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33872	36701	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33873	36702	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33874	36703	N	N	N	1	CUSTOMER ISSUE	-
DMS_33875	36704	N	N	Y	1	TX - REPLACE	2500
DMS_33876	36705	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_33877	36706	N	N	N	1	CUSTOMER ISSUE	-
DMS_33878	36707	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33880	36708	N	N	N	1	CUSTOMER ISSUE	-
DMS_33881	36709	N	N	N	1	CUSTOMER ISSUE	-
DMS_33882	36710	N	N	N	1	CUSTOMER ISSUE	-
DMS_33883	36711	N	N	N	1	CUSTOMER ISSUE	-
DMS_33884	36712	N	N	N	1	CUSTOMER ISSUE	-
DMS_33885	36713	N	N	N	1	CUSTOMER ISSUE	-
DMS_33886	36714	N	N	N	1	CUSTOMER ISSUE	-
DMS_33887	36715	N	N	N	1	CUSTOMER ISSUE	-
DMS_33888	36716	N	N	N	1	CUSTOMER ISSUE	-
DMS_33889	36717	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33890	36718	N	N	N	1	CUSTOMER ISSUE	-
DMS_33891	36719	N	N	N	1	CUSTOMER ISSUE	-
DMS_33893	36720	N	N	N	1	CUSTOMER ISSUE	-
DMS_33894	36721	N	N	N	1	CUSTOMER ISSUE	-
DMS_33895	36722	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33896	36723	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33897	36724	N	N	N	1	CUSTOMER ISSUE	-
DMS_33898	36725	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33899	36726	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33900	36727	N	N	N	1	CUSTOMER ISSUE	-
DMS_33901	36728	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33902	36729	N	N	N	1	CUSTOMER ISSUE	-
DMS_33903	36730	N	N	N	1	CUSTOMER ISSUE	-
DMS_33904	36731	N	N	N	1	CUSTOMER ISSUE	-
DMS_33905	36732	N	N	N	1	CUSTOMER ISSUE	-
DMS_33906	36733	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33907	36734	N	N	N	1	CUSTOMER ISSUE	-
DMS_33908	36735	N	N	N	1	CUSTOMER ISSUE	-
DMS_33909	36736	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33910	36737	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33911	36738	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33913	36739	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33914	36740	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33915	36741	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33916	36742	N	N	N	1	CUSTOMER ISSUE	-
DMS_33917	36743	N	N	N	1	CUSTOMER ISSUE	-
DMS_33918	36744	N	N	N	2	CUSTOMER ISSUE	-
DMS_33919	36745	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33921	36746	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33922	36747	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33924	36748	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33926	36749	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_33927	36750	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33928	36751	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33931	36752	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33935	36753	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33936	36754	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33937	36755	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33939	36756	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33940	36757	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33941	36758	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33942	36759	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33944	36760	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33948	36761	N	N	N	1	CUSTOMER ISSUE	-
DMS_33950	36762	N	N	N	1	CUSTOMER ISSUE	-
DMS_33951	36763	N	N	N	1	CUSTOMER ISSUE	-
DMS_33957	36764	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33958	36765	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33959	36766	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33960	36767	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33961	36768	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33962	36769	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33963	36770	N	N	N	1	CUSTOMER ISSUE	-
DMS_33964	36771	N	N	N	1	CUSTOMER ISSUE	-
DMS_33965	36772	N	N	N	1	CUSTOMER ISSUE	-
DMS_33967	36773	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33968	36774	N	N	N	1	CUSTOMER ISSUE	-
DMS_33969	36775	N	N	N	1	CUSTOMER ISSUE	-
DMS_33971	36776	N	N	Y	1	DIST - TREE TRIMMING	945

DMS_33973	36777	N	N	N	1	CUSTOMER ISSUE	-
DMS_33974	36778	N	N	N	1	CUSTOMER ISSUE	-
DMS_33976	36779	N	N	N	1	CUSTOMER ISSUE	-
DMS_33977	36780	N	N	N	1	CUSTOMER ISSUE	-
DMS_33979	36781	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_33980	36782	N	N	N	1	CUSTOMER ISSUE	-
DMS_33981	36783	N	N	N	1	CUSTOMER ISSUE	-
DMS_33982	36784	N	N	N	1	CUSTOMER ISSUE	-
DMS_33983	36785	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_33984	36786	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_33985	36787	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_33986	36788	N	N	N	1	CUSTOMER ISSUE	-
DMS_33988	36789	N	N	Y	1	TX - REPLACE	2500
DMS_33989	36790	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_33991	36791	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_33992	36792	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_33993	36793	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_33994	36794	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_33995	36795	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_33996	36796	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_33997	36797	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_33998	36798	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_33999	36799	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34000	36800	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34001	36801	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34002	36802	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34003	36803	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34004	36804	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34005	36805	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34006	36806	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34007	36807	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34008	36808	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34009	36809	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34010	36810	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34011	36811	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34012	36812	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34013	36813	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34014	36814	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34015	36815	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34017	36816	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34018	36817	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34019	36818	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34029	36819	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34030	36820	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34031	36821	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34032	36822	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34034	36823	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34035	36824	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34036	36825	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34037	36826	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34038	36827	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34039	36828	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34040	36829	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34042	36830	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34044	36831	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34045	36832	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34046	36833	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34047	36834	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34048	36835	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34049	36836	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34050	36837	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34051	36838	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34052	36839	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34053	36840	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34054	36841	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34055	36842	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34056	36843	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34057	36844	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34058	36845	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34059	36846	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34060	36847	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34061	36848	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34062	36849	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34064	36850	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34065	36851	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34066	36852	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34067	36853	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34068	36854	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34069	36855	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34070	36856	N	N	Y	1	DIST - REPLACE FUSE	708.75

DMS_34071	36857	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_34072	36858	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_34073	36859	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_34074	36860	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_34075	36861	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_34076	36862	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_34077	36863	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_34078	36864	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_34079	36865	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_34080	36866	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_34081	36867	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_34082	36868	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_34083	36869	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_34084	36870	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_34085	36871	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_34087	36872	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_34088	36873	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_34091	36874	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_34092	36875	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_34093	36876	N	N	N	1	CUSTOMER ISSUE	-
DMS_34094	36877	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_34095	36878	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_34097	36879	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_34098	36880	N	N	N	1	CUSTOMER ISSUE	-
DMS_34105	36881	N	N	N	1	CUSTOMER ISSUE	-
DMS_34107	36882	N	N	N	1	CUSTOMER ISSUE	-
DMS_34108	36883	N	N	N	1	CUSTOMER ISSUE	-
DMS_34113	36884	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_34114	36885	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_34115	36886	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_34130	36887	N	N	N	1	CUSTOMER ISSUE	-
DMS_34131	36888	N	N	N	1	CUSTOMER ISSUE	-
DMS_34133	36889	N	N	N	1	CUSTOMER ISSUE	-
DMS_34135	36890	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_34140	36891	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_34157	36892	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34183	36893	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34184	36894	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34185	36895	N	N	N	1	CUSTOMER ISSUE	-
DMS_34186	36896	N	N	N	1	CUSTOMER ISSUE	-
DMS_34191	36897	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34193	36898	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_34195	36899	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34222	36900	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34227	36901	N	N	N	1	CUSTOMER ISSUE	-
DMS_34229	36902	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34233	36903	N	N	N	1	CUSTOMER ISSUE	-
DMS_34234	36904	N	N	N	1	CUSTOMER ISSUE	-
DMS_34253	36905	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34264	36906	N	N	N	1	CUSTOMER ISSUE	-
DMS_34265	36907	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_34279	36908	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34280	36909	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34281	36910	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34282	36911	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_34283	36912	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34285	36913	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34286	36914	N	N	N	1	CUSTOMER ISSUE	-
DMS_34298	36915	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34300	36916	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34301	36917	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_34302	36918	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34303	36919	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34304	36920	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_34305	36921	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34306	36922	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34307	36923	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34308	36924	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34309	36925	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34310	36926	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34313	36927	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34314	36928	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34315	36929	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34319	36930	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_34324	36931	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_34331	36932	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34337	36933	N	N	N	1	CUSTOMER ISSUE	-
DMS_34343	36934	N	N	N	1	CUSTOMER ISSUE	-
DMS_34434	36935	N	N	N	1	CUSTOMER ISSUE	-
DMS_34441	36936	N	N	Y	1	DIST - REPLACE FUSE	708.75

DMS_34451	36937	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34466	36938	N	N	N	1	CUSTOMER ISSUE	-
DMS_34468	36939	N	N	N	1	CUSTOMER ISSUE	-
DMS_34469	36940	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34473	36941	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_34532	36942	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_34586	36943	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_34593	36944	N	N	N	1	CUSTOMER ISSUE	-
DMS_34605	36945	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_34622	36946	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34627	36947	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34628	36948	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_34639	36949	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34640	36950	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_34641	36951	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34643	36952	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34644	36953	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34645	36954	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34646	36955	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34647	36956	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_34649	36957	N	N	N	1	CUSTOMER ISSUE	-
DMS_34676	36958	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34678	36959	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34679	36960	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34680	36961	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34681	36962	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34682	36963	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34684	36964	N	N	N	1	CUSTOMER ISSUE	-
DMS_34694	36965	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34700	36966	N	N	N	1	CUSTOMER ISSUE	-
DMS_34701	36967	N	N	N	1	CUSTOMER ISSUE	-
DMS_34712	36968	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34713	36969	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34715	36970	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_34716	36971	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34718	36972	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34722	36973	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_34725	36974	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34727	36975	N	N	N	1	CUSTOMER ISSUE	-
DMS_34728	36976	N	N	N	1	CUSTOMER ISSUE	-
DMS_34729	36977	N	N	N	1	CUSTOMER ISSUE	-
DMS_34734	36978	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34735	36979	N	N	N	1	CUSTOMER ISSUE	-
DMS_34741	36980	N	N	N	1	CUSTOMER ISSUE	-
DMS_34781	36981	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34806	36982	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34813	36983	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_34816	36984	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34845	36985	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_34861	36986	N	N	N	1	CUSTOMER ISSUE	-
DMS_34900	36987	N	N	N	1	CUSTOMER ISSUE	-
DMS_34901	36988	N	N	N	1	CUSTOMER ISSUE	-
DMS_34902	36989	N	N	N	1	CUSTOMER ISSUE	-
DMS_34904	36990	N	N	N	1	CUSTOMER ISSUE	-
DMS_34905	36991	N	N	N	1	CUSTOMER ISSUE	-
DMS_34906	36992	N	N	N	1	CUSTOMER ISSUE	-
DMS_34911	36993	N	N	N	1	CUSTOMER ISSUE	-
DMS_34912	36994	N	N	N	1	CUSTOMER ISSUE	-
DMS_34914	36995	N	N	N	1	CUSTOMER ISSUE	-
DMS_34915	36996	N	N	N	1	CUSTOMER ISSUE	-
DMS_34996	36997	N	N	N	1	CUSTOMER ISSUE	-
DMS_34997	36998	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_34998	36999	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_35003	37000	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_35006	37001	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35007	37002	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35035	37003	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_35036	37004	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_35056	37005	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35061	37006	N	N	N	1	CUSTOMER ISSUE	-
DMS_35064	37007	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35065	37008	N	N	N	1	CUSTOMER ISSUE	-
DMS_35066	37009	N	N	N	1	CUSTOMER ISSUE	-
DMS_35069	37010	N	N	N	1	CUSTOMER ISSUE	-
DMS_35073	37011	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_35076	37012	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_35085	37013	N	N	N	1	CUSTOMER ISSUE	-
DMS_35086	37014	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35087	37015	N	N	N	1	CUSTOMER ISSUE	-
DMS_35088	37016	N	N	N	1	CUSTOMER ISSUE	-

DMS_35089	37017	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35090	37018	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35092	37019	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35093	37020	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35095	37021	N	N	N	1	CUSTOMER ISSUE	-
DMS_35096	37022	N	N	N	1	CUSTOMER ISSUE	-
DMS_35100	37023	N	N	N	1	CUSTOMER ISSUE	-
DMS_35103	37024	N	N	N	1	CUSTOMER ISSUE	-
DMS_35133	37025	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35142	37026	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35146	37027	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35149	37028	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35150	37029	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35151	37030	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35152	37031	N	N	Y	1	SUB/TRANS - REPAIR	5000
DMS_35153	37032	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35159	37033	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35161	37034	N	N	N	1	CUSTOMER ISSUE	-
DMS_35170	37035	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35171	37036	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35172	37037	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35173	37038	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35174	37039	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35175	37040	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35176	37041	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35177	37042	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35179	37043	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35183	37044	N	N	N	1	CUSTOMER ISSUE	-
DMS_35188	37045	N	N	N	1	CUSTOMER ISSUE	-
DMS_35200	37046	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_35211	37047	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35233	37048	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_35238	37049	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_35246	37050	N	N	N	1	CUSTOMER ISSUE	-
DMS_35250	37051	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35251	37052	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_35252	37053	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35253	37054	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35254	37055	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35256	37056	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35257	37057	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35258	37058	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35259	37059	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35260	37060	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35261	37061	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35262	37062	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35263	37063	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35265	37064	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35267	37065	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35268	37066	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_35269	37067	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35270	37068	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35271	37069	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_35272	37070	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35273	37071	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35274	37072	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35275	37073	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35276	37074	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35277	37075	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35278	37076	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35279	37077	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35280	37078	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35281	37079	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35282	37080	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35283	37081	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35284	37082	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35285	37083	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35286	37084	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35287	37085	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35288	37086	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35289	37087	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35290	37088	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35291	37089	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35292	37090	N	N	N	1	CUSTOMER ISSUE	-
DMS_35293	37091	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35294	37092	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35295	37093	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35296	37094	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35298	37095	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35299	37096	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_35300	37097	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35301	37098	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35302	37099	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35307	37100	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35308	37101	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35309	37102	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35310	37103	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35311	37104	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35312	37105	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35313	37106	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35314	37107	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35315	37108	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35316	37109	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_35317	37110	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35318	37111	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35319	37112	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35320	37113	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35321	37114	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35322	37115	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35323	37116	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35324	37117	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35325	37118	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35326	37119	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35327	37120	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35329	37121	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35330	37122	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35331	37123	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35332	37124	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35333	37125	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35334	37126	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35335	37127	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35336	37128	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35338	37129	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35341	37130	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35344	37131	N	N	Y	4	DIST - TREE TRIMMING	945
DMS_35346	37132	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35347	37133	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35349	37134	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_35353	37135	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_35373	37136	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35374	37137	N	N	N	1	CUSTOMER ISSUE	-
DMS_35400	37138	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35401	37139	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35403	37140	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35404	37141	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35405	37142	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35406	37143	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35407	37144	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35408	37145	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35409	37146	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35410	37147	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35411	37148	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35412	37149	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35413	37150	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35416	37151	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_35417	37152	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35418	37153	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35419	37154	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35420	37155	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35421	37156	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35422	37157	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35423	37158	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35424	37159	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35425	37160	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35426	37161	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35427	37162	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35428	37163	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35429	37164	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35430	37165	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35431	37166	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35433	37167	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35434	37168	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35435	37169	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35436	37170	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35437	37171	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35438	37172	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35439	37173	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35440	37174	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35441	37175	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35442	37176	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_35443	37177	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35444	37178	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35445	37179	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35446	37180	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35447	37181	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35448	37182	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35449	37183	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35450	37184	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_35451	37185	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35452	37186	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35453	37187	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35454	37188	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35455	37189	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35456	37190	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35457	37191	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35458	37192	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35459	37193	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35460	37194	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35461	37195	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35462	37196	N	N	N	1	CUSTOMER ISSUE	-
DMS_35463	37197	N	N	N	1	CUSTOMER ISSUE	-
DMS_35464	37198	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35465	37199	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35466	37200	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35467	37201	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35468	37202	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35469	37203	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35470	37204	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35471	37205	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35472	37206	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35473	37207	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35474	37208	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35475	37209	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35476	37210	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35477	37211	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35478	37212	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35479	37213	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35480	37214	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35481	37215	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35482	37216	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35483	37217	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35485	37218	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35486	37219	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35487	37220	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35488	37221	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35489	37222	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35490	37223	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35491	37224	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35492	37225	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35493	37226	N	N	Y	3	SEC/SVC - REPAIR	472.5
DMS_35494	37227	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35495	37228	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35496	37229	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35497	37230	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35498	37231	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35499	37232	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35500	37233	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35501	37234	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35502	37235	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35503	37236	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35504	37237	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35505	37238	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35506	37239	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35507	37240	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35508	37241	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35509	37242	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35510	37243	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35511	37244	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35512	37245	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35513	37246	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35514	37247	N	N	Y	1	TX - REPLACE	2500
DMS_35515	37248	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35516	37249	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35517	37250	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35518	37251	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35519	37252	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35520	37253	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35521	37254	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35522	37255	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35523	37256	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_35524	37257	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35525	37258	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35526	37259	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35527	37260	N	N	N	1	CUSTOMER ISSUE	-
DMS_35528	37261	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35529	37262	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_35530	37263	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35531	37264	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35532	37265	N	N	N	1	CUSTOMER ISSUE	-
DMS_35533	37266	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35534	37267	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35535	37268	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35536	37269	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35537	37270	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35538	37271	N	N	N	1	CUSTOMER ISSUE	-
DMS_35539	37272	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35540	37273	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35541	37274	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35542	37275	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35543	37276	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35544	37277	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35545	37278	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35546	37279	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35547	37280	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35548	37281	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35549	37282	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35550	37283	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35551	37284	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35552	37285	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35553	37286	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35554	37287	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35555	37288	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35556	37289	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35557	37290	N	N	N	1	CUSTOMER ISSUE	-
DMS_35558	37291	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35559	37292	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35560	37293	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35561	37294	N	N	N	1	CUSTOMER ISSUE	-
DMS_35562	37295	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_35563	37296	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35564	37297	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35565	37298	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35566	37299	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35567	37300	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35568	37301	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35569	37302	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35570	37303	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35571	37304	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35572	37305	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35573	37306	N	N	Y	3	SEC/SVC - REPAIR	472.5
DMS_35574	37307	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35575	37308	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35576	37309	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35577	37310	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35578	37311	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35579	37312	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35580	37313	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35581	37314	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35582	37315	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35583	37316	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35584	37317	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35585	37318	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35586	37319	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35587	37320	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35588	37321	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35589	37322	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35590	37323	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35591	37324	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35592	37325	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_35593	37326	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35594	37327	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35595	37328	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35596	37329	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35597	37330	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35598	37331	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35599	37332	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35600	37333	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35601	37334	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35602	37335	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35603	37336	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_35604	37337	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35605	37338	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35606	37339	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35607	37340	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35608	37341	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35609	37342	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35610	37343	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35611	37344	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35612	37345	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35613	37346	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35614	37347	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35615	37348	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35616	37349	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35617	37350	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35618	37351	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35619	37352	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35620	37353	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35621	37354	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35622	37355	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35623	37356	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35624	37357	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35625	37358	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35626	37359	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35627	37360	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35628	37361	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35629	37362	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35630	37363	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35631	37364	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35632	37365	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35633	37366	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35634	37367	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35635	37368	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35636	37369	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35637	37370	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35638	37371	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35639	37372	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35640	37373	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35641	37374	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35642	37375	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35643	37376	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35644	37377	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35645	37378	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35646	37379	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35647	37380	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35648	37381	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35649	37382	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35650	37383	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35651	37384	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35652	37385	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35653	37386	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35654	37387	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35655	37388	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35656	37389	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35657	37390	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35658	37391	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35659	37392	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35660	37393	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35661	37394	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35662	37395	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35663	37396	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35664	37397	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35665	37398	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35666	37399	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35667	37400	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35668	37401	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35669	37402	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35670	37403	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35671	37404	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35672	37405	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35673	37406	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35674	37407	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35675	37408	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35676	37409	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35677	37410	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35678	37411	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35679	37412	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35680	37413	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35681	37414	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35682	37415	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35683	37416	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_35684	37417	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35685	37418	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35686	37419	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35687	37420	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35688	37421	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35689	37422	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35690	37423	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35691	37424	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_35692	37425	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35693	37426	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35694	37427	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35695	37428	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35696	37429	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35697	37430	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35698	37431	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35699	37432	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35700	37433	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35701	37434	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35702	37435	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35703	37436	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35704	37437	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35705	37438	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35706	37439	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35707	37440	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35708	37441	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35709	37442	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35710	37443	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35711	37444	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35712	37445	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35713	37446	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35714	37447	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35715	37448	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35716	37449	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35717	37450	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35718	37451	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35719	37452	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35720	37453	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35721	37454	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35722	37455	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35723	37456	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35724	37457	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35725	37458	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35726	37459	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35727	37460	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35728	37461	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35729	37462	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35730	37463	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35731	37464	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35732	37465	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35733	37466	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35734	37467	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35735	37468	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35736	37469	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35737	37470	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35738	37471	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35739	37472	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35740	37473	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35741	37474	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35742	37475	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35743	37476	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35744	37477	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35745	37478	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35746	37479	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35747	37480	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35748	37481	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35749	37482	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35750	37483	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35751	37484	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35752	37485	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35753	37486	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35754	37487	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35755	37488	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35756	37489	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35757	37490	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35758	37491	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35759	37492	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35760	37493	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35761	37494	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35762	37495	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35763	37496	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_35764	37497	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35765	37498	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35766	37499	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35767	37500	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35768	37501	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35769	37502	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_35770	37503	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35771	37504	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35772	37505	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35773	37506	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35774	37507	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35775	37508	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35776	37509	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35777	37510	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35778	37511	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35779	37512	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35780	37513	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35781	37514	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35782	37515	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35783	37516	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35784	37517	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35785	37518	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35786	37519	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35787	37520	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35788	37521	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35789	37522	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35790	37523	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35791	37524	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35792	37525	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35793	37526	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35794	37527	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35795	37528	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35796	37529	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35797	37530	N	N	N	1	CUSTOMER ISSUE	-
DMS_35798	37531	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35799	37532	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35800	37533	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35801	37534	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35802	37535	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35803	37536	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35804	37537	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35805	37538	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35806	37539	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35807	37540	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35808	37541	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35809	37542	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35810	37543	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35811	37544	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35812	37545	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35813	37546	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35814	37547	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35815	37548	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35816	37549	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35817	37550	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35818	37551	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35819	37552	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35820	37553	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35821	37554	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35822	37555	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35823	37556	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35824	37557	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35825	37558	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35826	37559	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35827	37560	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35828	37561	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35829	37562	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35830	37563	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35831	37564	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35832	37565	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35833	37566	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35834	37567	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35835	37568	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35836	37569	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35837	37570	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35839	37571	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35840	37572	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35841	37573	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35842	37574	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35843	37575	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35844	37576	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_35845	37577	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35846	37578	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35847	37579	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35848	37580	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35849	37581	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35850	37582	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35851	37583	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35852	37584	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35853	37585	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35854	37586	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35855	37587	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35856	37588	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35857	37589	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35858	37590	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35859	37591	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35860	37592	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35861	37593	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35862	37594	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35863	37595	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35864	37596	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35865	37597	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35866	37598	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35867	37599	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35868	37600	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35869	37601	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35870	37602	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35871	37603	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35872	37604	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35873	37605	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35874	37606	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35875	37607	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35876	37608	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35877	37609	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35878	37610	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35879	37611	N	N	N	1	CUSTOMER ISSUE	-
DMS_35880	37612	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35881	37613	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35882	37614	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35883	37615	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35884	37616	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35885	37617	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35886	37618	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35887	37619	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35888	37620	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35889	37621	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35890	37622	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35891	37623	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35892	37624	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35893	37625	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35894	37626	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35895	37627	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35896	37628	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35897	37629	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35898	37630	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35899	37631	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35900	37632	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35901	37633	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35902	37634	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35903	37635	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35904	37636	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35905	37637	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35906	37638	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35907	37639	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35908	37640	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35909	37641	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35910	37642	N	N	N	1	CUSTOMER ISSUE	-
DMS_35911	37643	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35912	37644	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35913	37645	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35914	37646	N	N	N	1	CUSTOMER ISSUE	-
DMS_35915	37647	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35916	37648	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35917	37649	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35918	37650	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35919	37651	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35920	37652	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35921	37653	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35922	37654	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35923	37655	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35924	37656	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_35925	37657	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35926	37658	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_35927	37659	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35928	37660	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35929	37661	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35930	37662	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35931	37663	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35932	37664	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35933	37665	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35934	37666	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35935	37667	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35936	37668	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35937	37669	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35938	37670	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35939	37671	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35940	37672	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35941	37673	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35942	37674	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35943	37675	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35944	37676	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35945	37677	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35946	37678	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35947	37679	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35948	37680	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35949	37681	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35950	37682	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35951	37683	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35952	37684	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35953	37685	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35954	37686	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35955	37687	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35956	37688	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35957	37689	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35958	37690	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35959	37691	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35960	37692	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35961	37693	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35962	37694	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35963	37695	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35964	37696	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35965	37697	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35966	37698	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35967	37699	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35968	37700	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35969	37701	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35970	37702	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35971	37703	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35972	37704	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35973	37705	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35974	37706	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35975	37707	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35976	37708	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35977	37709	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35978	37710	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35979	37711	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_35980	37712	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35981	37713	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35982	37714	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35983	37715	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35984	37716	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35985	37717	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35986	37718	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35987	37719	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35988	37720	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35989	37721	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35990	37722	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35991	37723	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35992	37724	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35993	37725	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35994	37726	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35995	37727	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35996	37728	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35997	37729	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35998	37730	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_35999	37731	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36000	37732	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36001	37733	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36002	37734	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36003	37735	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_36004	37736	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_36005	37737	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36006	37738	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36007	37739	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36008	37740	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36009	37741	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36010	37742	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36011	37743	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36012	37744	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36013	37745	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36014	37746	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36015	37747	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36016	37748	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36017	37749	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36018	37750	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36019	37751	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_36020	37752	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36021	37753	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36022	37754	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36023	37755	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36024	37756	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36025	37757	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36026	37758	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36027	37759	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36028	37760	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36029	37761	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36030	37762	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36031	37763	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36032	37764	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36033	37765	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36034	37766	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36035	37767	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36036	37768	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36037	37769	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36038	37770	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36039	37771	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36040	37772	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36041	37773	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36042	37774	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36043	37775	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36044	37776	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36045	37777	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36046	37778	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36047	37779	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36048	37780	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36049	37781	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36050	37782	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36051	37783	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36052	37784	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36053	37785	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36054	37786	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36055	37787	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36056	37788	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36057	37789	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36058	37790	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36059	37791	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36060	37792	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36061	37793	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36062	37794	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36063	37795	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36064	37796	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36065	37797	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36066	37798	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36067	37799	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36068	37800	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36069	37801	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36070	37802	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36071	37803	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36072	37804	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36073	37805	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_36074	37806	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36075	37807	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36076	37808	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36077	37809	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36078	37810	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36079	37811	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36080	37812	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36081	37813	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36082	37814	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36083	37815	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36084	37816	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_36085	37817	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36086	37818	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36087	37819	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36088	37820	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36089	37821	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36090	37822	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36091	37823	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36092	37824	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36093	37825	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36094	37826	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36095	37827	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36096	37828	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36097	37829	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36098	37830	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36099	37831	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36100	37832	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36101	37833	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36102	37834	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36103	37835	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36104	37836	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36105	37837	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36106	37838	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36107	37839	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36108	37840	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36109	37841	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36110	37842	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36111	37843	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36112	37844	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36113	37845	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36114	37846	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36115	37847	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36116	37848	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36117	37849	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36118	37850	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36119	37851	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36120	37852	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36121	37853	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36122	37854	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36123	37855	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36124	37856	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36125	37857	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36126	37858	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36127	37859	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36128	37860	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36129	37861	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36130	37862	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36131	37863	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36132	37864	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36133	37865	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36134	37866	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36135	37867	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36136	37868	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36137	37869	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36138	37870	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36139	37871	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36140	37872	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36141	37873	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36142	37874	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36143	37875	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36144	37876	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36145	37877	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36146	37878	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36147	37879	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36148	37880	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36149	37881	N	N	Y	3	SEC/SVC - REPAIR	472.5
DMS_36150	37882	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36151	37883	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36152	37884	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36153	37885	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36154	37886	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36155	37887	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36156	37888	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36157	37889	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36158	37890	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36159	37891	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36160	37892	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36161	37893	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36162	37894	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36163	37895	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36164	37896	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_36165	37897	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36166	37898	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36167	37899	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36168	37900	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36169	37901	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36170	37902	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36171	37903	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36172	37904	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36173	37905	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36174	37906	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36175	37907	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36176	37908	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36177	37909	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36178	37910	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36179	37911	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36180	37912	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36181	37913	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36182	37914	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36183	37915	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36184	37916	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36185	37917	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36186	37918	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36187	37919	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36188	37920	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36189	37921	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36190	37922	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36191	37923	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36192	37924	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36193	37925	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36194	37926	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36195	37927	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36196	37928	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36197	37929	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36198	37930	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36199	37931	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36200	37932	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36201	37933	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36202	37934	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36203	37935	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36204	37936	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36205	37937	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36206	37938	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36207	37939	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36208	37940	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36209	37941	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36210	37942	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36211	37943	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36212	37944	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36213	37945	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36214	37946	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36215	37947	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_36216	37948	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36217	37949	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36218	37950	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36219	37951	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36220	37952	N	N	N	1	CUSTOMER ISSUE	-
DMS_36221	37953	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36222	37954	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36223	37955	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36224	37956	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36225	37957	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36226	37958	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36227	37959	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36228	37960	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36229	37961	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36230	37962	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36231	37963	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36232	37964	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36233	37965	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36234	37966	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36235	37967	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36236	37968	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36237	37969	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36238	37970	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36239	37971	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36240	37972	N	N	Y	3	SEC/SVC - REPAIR	472.5
DMS_36241	37973	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36242	37974	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36243	37975	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36244	37976	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_36245	37977	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36246	37978	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36247	37979	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36248	37980	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36249	37981	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36250	37982	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36251	37983	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36252	37984	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36253	37985	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36254	37986	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36255	37987	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36256	37988	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36257	37989	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36258	37990	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36259	37991	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36260	37992	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36261	37993	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36262	37994	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36263	37995	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36264	37996	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36265	37997	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36266	37998	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36267	37999	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36268	38000	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36269	38001	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36270	38002	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36271	38003	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36272	38004	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36273	38005	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36274	38006	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36275	38007	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36276	38008	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36277	38009	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36278	38010	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36279	38011	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36280	38012	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36281	38013	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36282	38014	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_36283	38015	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36284	38016	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36285	38017	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36286	38018	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36287	38019	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36288	38020	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36289	38021	N	N	N	1	CUSTOMER ISSUE	-
DMS_36290	38022	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36291	38023	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36292	38024	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36293	38025	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_36294	38026	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36295	38027	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36296	38028	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36297	38029	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36298	38030	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36299	38031	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36300	38032	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36301	38033	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36302	38034	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36303	38035	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36304	38036	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36305	38037	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36306	38038	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36307	38039	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36308	38040	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36309	38041	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36310	38042	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36311	38043	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36312	38044	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36313	38045	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36314	38046	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36315	38047	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36316	38048	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36317	38049	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36318	38050	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36319	38051	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36320	38052	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36321	38053	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36322	38054	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36323	38055	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36324	38056	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_36325	38057	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36326	38058	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36327	38059	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36328	38060	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36329	38061	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36330	38062	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36331	38063	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36332	38064	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36333	38065	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36334	38066	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36335	38067	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36336	38068	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36337	38069	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36338	38070	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36339	38071	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36340	38072	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36341	38073	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36342	38074	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36343	38075	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36344	38076	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36345	38077	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36346	38078	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36347	38079	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36348	38080	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36349	38081	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36350	38082	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36351	38083	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36352	38084	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36353	38085	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36354	38086	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36355	38087	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36356	38088	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36357	38089	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36358	38090	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36359	38091	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36360	38092	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36361	38093	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36362	38094	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36363	38095	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36364	38096	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36365	38097	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36366	38098	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36367	38099	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36368	38100	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36369	38101	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36370	38102	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36371	38103	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36372	38104	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36373	38105	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36374	38106	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36375	38107	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36376	38108	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36377	38109	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36378	38110	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36379	38111	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36380	38112	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_36381	38113	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36382	38114	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_36383	38115	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36384	38116	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36385	38117	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36386	38118	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36387	38119	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36388	38120	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36389	38121	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36390	38122	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36391	38123	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36392	38124	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36393	38125	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36394	38126	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36395	38127	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36396	38128	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36397	38129	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36398	38130	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36399	38131	N	N	N	1	CUSTOMER ISSUE	-
DMS_36400	38132	N	N	N	1	CUSTOMER ISSUE	-
DMS_36401	38133	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36402	38134	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36403	38135	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36404	38136	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_36405	38137	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36406	38138	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36407	38139	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36408	38140	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36409	38141	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36410	38142	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36411	38143	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36412	38144	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36413	38145	N	N	N	2	CUSTOMER ISSUE	-
DMS_36414	38146	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36415	38147	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36416	38148	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36417	38149	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36418	38150	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36419	38151	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36420	38152	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36421	38153	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36422	38154	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36423	38155	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36424	38156	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36425	38157	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36426	38158	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36427	38159	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36428	38160	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36429	38161	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36430	38162	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36431	38163	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36432	38164	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36433	38165	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36434	38166	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36435	38167	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36436	38168	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36437	38169	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36438	38170	N	N	N	1	CUSTOMER ISSUE	-
DMS_36439	38171	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36440	38172	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36441	38173	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_36442	38174	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36443	38175	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36444	38176	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36445	38177	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36446	38178	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36447	38179	N	N	N	1	CUSTOMER ISSUE	-
DMS_36448	38180	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36449	38181	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36450	38182	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36451	38183	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36452	38184	N	N	N	1	CUSTOMER ISSUE	-
DMS_36453	38185	N	N	N	1	CUSTOMER ISSUE	-
DMS_36454	38186	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36455	38187	N	N	N	1	CUSTOMER ISSUE	-
DMS_36456	38188	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36457	38189	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36458	38190	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36459	38191	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36460	38192	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36461	38193	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36462	38194	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36463	38195	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36464	38196	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36465	38197	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36466	38198	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36467	38199	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36468	38200	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36469	38201	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36470	38202	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36471	38203	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36472	38204	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36473	38205	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36474	38206	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36475	38207	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36476	38208	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36477	38209	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36478	38210	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36479	38211	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36480	38212	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36481	38213	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36482	38214	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36483	38215	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36484	38216	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_36485	38217	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36486	38218	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36487	38219	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36488	38220	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36489	38221	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36490	38222	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36491	38223	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36492	38224	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36493	38225	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36494	38226	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36495	38227	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36496	38228	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36497	38229	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36498	38230	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36499	38231	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36500	38232	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36501	38233	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36502	38234	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36503	38235	N	N	N	1	CUSTOMER ISSUE	-
DMS_36504	38236	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36505	38237	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36506	38238	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36507	38239	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36508	38240	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36509	38241	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36510	38242	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36511	38243	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36512	38244	N	N	Y	1	TX - REPLACE	2500
DMS_36513	38245	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36514	38246	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36515	38247	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36516	38248	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36517	38249	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36518	38250	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36519	38251	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36520	38252	N	N	Y	1	TX - REPLACE	2500
DMS_36521	38253	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36522	38254	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36523	38255	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36524	38256	N	N	Y	1	TX - REPLACE	2500
DMS_36525	38257	N	N	Y	1	TX - REPLACE	2500
DMS_36526	38258	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36527	38259	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36528	38260	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36529	38261	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36530	38262	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36531	38263	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36532	38264	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36533	38265	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36534	38266	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36535	38267	N	N	N	1	CUSTOMER ISSUE	-
DMS_36536	38268	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36537	38269	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36538	38270	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36539	38271	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36540	38272	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36541	38273	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36542	38274	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36543	38275	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36544	38276	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36545	38277	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36546	38278	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36547	38279	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_36548	38280	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36549	38281	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36550	38282	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36551	38283	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36552	38284	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36553	38285	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36554	38286	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36555	38287	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36556	38288	N	N	N	1	CUSTOMER ISSUE	-
DMS_36557	38289	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36558	38290	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36559	38291	N	N	N	1	CUSTOMER ISSUE	-
DMS_36560	38292	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36561	38293	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36562	38294	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36563	38295	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36564	38296	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_36565	38297	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36566	38298	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36567	38299	N	N	N	1	CUSTOMER ISSUE	-
DMS_36568	38300	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36569	38301	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36570	38302	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36571	38303	N	N	Y	1	TX - REPLACE	2500
DMS_36572	38304	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_36573	38305	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36574	38306	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36575	38307	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36576	38308	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36577	38309	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36578	38310	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36579	38311	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36580	38312	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36581	38313	N	N	Y	1	TX - REPLACE	2500
DMS_36582	38314	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36583	38315	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36584	38316	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36587	38317	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36588	38318	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36589	38319	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36590	38320	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36591	38321	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36592	38322	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36593	38323	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36594	38324	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36595	38325	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36596	38326	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36597	38327	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36598	38328	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36599	38329	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36600	38330	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36601	38331	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36602	38332	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36603	38333	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36604	38334	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36605	38335	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36606	38336	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36607	38337	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36608	38338	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36609	38339	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36610	38340	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36611	38341	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36612	38342	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36613	38343	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36614	38344	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36615	38345	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36616	38346	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36617	38347	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36618	38348	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36619	38349	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36620	38350	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36621	38351	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36622	38352	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36623	38353	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36624	38354	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36625	38355	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36626	38356	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36627	38357	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36628	38358	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36629	38359	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36630	38360	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36631	38361	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36632	38362	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36633	38363	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36634	38364	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36635	38365	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36636	38366	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36637	38367	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36638	38368	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36639	38369	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36640	38370	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36641	38371	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36642	38372	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36643	38373	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36644	38374	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36645	38375	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36646	38376	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_36647	38377	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36648	38378	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36649	38379	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36650	38380	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36651	38381	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36652	38382	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36653	38383	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36654	38384	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36655	38385	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36656	38386	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36657	38387	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36658	38388	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36659	38389	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36660	38390	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36661	38391	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36662	38392	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36663	38393	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36664	38394	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36665	38395	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36666	38396	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36667	38397	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36668	38398	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_36669	38399	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36670	38400	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36671	38401	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36672	38402	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36673	38403	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36674	38404	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36675	38405	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36676	38406	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36677	38407	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36678	38408	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36679	38409	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36680	38410	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36681	38411	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36682	38412	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36683	38413	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36684	38414	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36685	38415	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36686	38416	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36687	38417	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36688	38418	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36689	38419	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36690	38420	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36691	38421	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36692	38422	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36693	38423	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36694	38424	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36695	38425	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36696	38426	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36697	38427	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36698	38428	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36699	38429	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36700	38430	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36701	38431	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36702	38432	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36703	38433	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36704	38434	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36705	38435	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36706	38436	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36707	38437	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36708	38438	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36709	38439	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36710	38440	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36711	38441	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36712	38442	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36713	38443	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36714	38444	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36715	38445	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36716	38446	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36717	38447	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36718	38448	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36719	38449	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36720	38450	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36721	38451	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36722	38452	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36723	38453	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36724	38454	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36725	38455	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36726	38456	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_36727	38457	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36728	38458	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36729	38459	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36730	38460	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36731	38461	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36732	38462	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36733	38463	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36734	38464	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36735	38465	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36736	38466	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36737	38467	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36738	38468	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36739	38469	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36740	38470	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36741	38471	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36742	38472	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36743	38473	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36744	38474	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36745	38475	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36746	38476	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36747	38477	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36748	38478	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36749	38479	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36750	38480	N	N	N	1	CUSTOMER ISSUE	-
DMS_36751	38481	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36752	38482	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36753	38483	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36754	38484	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36755	38485	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36756	38486	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36757	38487	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36758	38488	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36759	38489	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36760	38490	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36761	38491	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36762	38492	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36763	38493	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36764	38494	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36765	38495	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36766	38496	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36767	38497	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36768	38498	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36769	38499	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36770	38500	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36771	38501	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36772	38502	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36773	38503	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36774	38504	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36775	38505	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36776	38506	N	N	N	1	CUSTOMER ISSUE	-
DMS_36777	38507	N	N	N	1	CUSTOMER ISSUE	-
DMS_36778	38508	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36779	38509	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36780	38510	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36781	38511	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36782	38512	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36783	38513	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36784	38514	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36785	38515	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36786	38516	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36787	38517	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36788	38518	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36789	38519	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36791	38520	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36792	38521	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36793	38522	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36794	38523	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36795	38524	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36796	38525	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36797	38526	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36798	38527	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36799	38528	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36800	38529	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36801	38530	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36802	38531	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36803	38532	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36804	38533	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36805	38534	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36806	38535	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36807	38536	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_36808	38537	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36809	38538	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36810	38539	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36811	38540	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36812	38541	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36813	38542	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36814	38543	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36815	38544	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36816	38545	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36818	38546	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36819	38547	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36820	38548	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36821	38549	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36825	38550	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36826	38551	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36827	38552	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36828	38553	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36829	38554	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36830	38555	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36831	38556	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36832	38557	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36833	38558	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36834	38559	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36835	38560	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36836	38561	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36837	38562	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36838	38563	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36839	38564	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36840	38565	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36841	38566	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36842	38567	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36843	38568	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36844	38569	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36845	38570	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36846	38571	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36847	38572	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36848	38573	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36849	38574	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36850	38575	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36851	38576	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36852	38577	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36853	38578	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36854	38579	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36855	38580	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36856	38581	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36857	38582	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36858	38583	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36859	38584	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36860	38585	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36861	38586	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_36862	38587	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36863	38588	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36864	38589	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36865	38590	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36866	38591	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36867	38592	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36868	38593	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36869	38594	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36870	38595	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36871	38596	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36872	38597	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36873	38598	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36874	38599	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36875	38600	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36876	38601	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36877	38602	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36878	38603	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36879	38604	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36880	38605	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36881	38606	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36882	38607	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36883	38608	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36884	38609	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36885	38610	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36886	38611	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36887	38612	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36888	38613	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36889	38614	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36890	38615	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36891	38616	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_36892	38617	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36893	38618	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36894	38619	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36895	38620	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36896	38621	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36897	38622	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36898	38623	N	N	N	1	CUSTOMER ISSUE	-
DMS_36899	38624	N	N	Y	1	TX - REPLACE	2500
DMS_36900	38625	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36901	38626	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36902	38627	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36903	38628	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36904	38629	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36905	38630	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36906	38631	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36907	38632	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36908	38633	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36909	38634	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36910	38635	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36911	38636	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_36912	38637	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36913	38638	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36914	38639	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36915	38640	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36916	38641	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36917	38642	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36918	38643	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36919	38644	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36920	38645	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36921	38646	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36922	38647	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36923	38648	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36924	38649	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36925	38650	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36926	38651	N	N	Y	1	TX - REPLACE	2500
DMS_36927	38652	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36928	38653	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36929	38654	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36930	38655	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36931	38656	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36932	38657	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36933	38658	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36934	38659	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36935	38660	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36936	38661	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36937	38662	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36938	38663	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36939	38664	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36940	38665	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36941	38666	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36942	38667	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36943	38668	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36944	38669	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36945	38670	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36946	38671	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36947	38672	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36948	38673	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36949	38674	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36950	38675	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36951	38676	N	N	N	1	CUSTOMER ISSUE	-
DMS_36952	38677	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36953	38678	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36954	38679	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36955	38680	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36956	38681	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36957	38682	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36958	38683	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36959	38684	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36960	38685	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36961	38686	N	N	Y	2	TX/SEC/SVC- REPLACE	3800
DMS_36962	38687	N	N	Y	1	TX - REPLACE	2500
DMS_36963	38688	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36964	38689	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_36965	38690	N	N	Y	1	TX - REPLACE	2500
DMS_36966	38691	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36967	38692	N	N	Y	1	TX - REPLACE	2500
DMS_36968	38693	N	N	Y	1	TX - REPLACE	2500
DMS_36969	38694	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36970	38695	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36971	38696	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_36972	38697	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36973	38698	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36974	38699	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36975	38700	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_36976	38701	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36977	38702	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36978	38703	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36979	38704	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36980	38705	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36981	38706	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36982	38707	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36983	38708	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36984	38709	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36985	38710	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36986	38711	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36987	38712	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36988	38713	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36989	38714	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36990	38715	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36991	38716	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36992	38717	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36993	38718	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36994	38719	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36996	38720	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_36997	38721	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36998	38722	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_36999	38723	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37000	38724	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37001	38725	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37002	38726	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37003	38727	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37004	38728	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37005	38729	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37006	38730	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37007	38731	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37008	38732	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37009	38733	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37010	38734	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37011	38735	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37012	38736	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37013	38737	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37014	38738	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37015	38739	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37016	38740	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37017	38741	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37018	38742	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37019	38743	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37020	38744	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37021	38745	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37022	38746	N	N	N	1	CUSTOMER ISSUE	-
DMS_37023	38747	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37024	38748	N	N	N	1	CUSTOMER ISSUE	-
DMS_37025	38749	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37026	38750	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37027	38751	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37028	38752	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37029	38753	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37030	38754	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37031	38755	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37032	38756	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37033	38757	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37034	38758	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37035	38759	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37036	38760	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37037	38761	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37038	38762	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37039	38763	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_37040	38764	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37041	38765	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37042	38766	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37043	38767	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37044	38768	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37045	38769	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37046	38770	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37048	38771	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37049	38772	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37050	38773	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37051	38774	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37052	38775	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37053	38776	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_37054	38777	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37055	38778	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37056	38779	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37057	38780	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37058	38781	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37059	38782	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37060	38783	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37061	38784	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37062	38785	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37063	38786	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37064	38787	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37065	38788	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37066	38789	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37067	38790	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37068	38791	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37069	38792	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37070	38793	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37071	38794	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37072	38795	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37073	38796	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37074	38797	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37075	38798	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37076	38799	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37077	38800	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37078	38801	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37079	38802	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37080	38803	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37081	38804	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37082	38805	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37083	38806	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37084	38807	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37085	38808	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37086	38809	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37087	38810	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37088	38811	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37089	38812	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37090	38813	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37091	38814	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37092	38815	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37093	38816	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_37094	38817	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37095	38818	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37096	38819	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37097	38820	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37098	38821	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37099	38822	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37100	38823	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37101	38824	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37102	38825	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37103	38826	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37104	38827	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37105	38828	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37106	38829	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37107	38830	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37108	38831	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37109	38832	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37110	38833	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37111	38834	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37112	38835	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37113	38836	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37114	38837	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37115	38838	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37116	38839	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37117	38840	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37118	38841	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37119	38842	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37120	38843	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37121	38844	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37122	38845	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37123	38846	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37124	38847	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37125	38848	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37126	38849	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37127	38850	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37128	38851	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37129	38852	N	N	N	1	CUSTOMER ISSUE	-
DMS_37130	38853	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37131	38854	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37132	38855	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_37133	38856	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_37134	38857	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37135	38858	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37136	38859	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37137	38860	N	N	N	1	CUSTOMER ISSUE	-
DMS_37138	38861	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37139	38862	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37140	38863	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37141	38864	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37142	38865	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37143	38866	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37144	38867	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37145	38868	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37146	38869	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37147	38870	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37148	38871	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37149	38872	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37150	38873	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37151	38874	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37152	38875	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37153	38876	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37154	38877	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37155	38878	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37156	38879	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37157	38880	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37158	38881	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37159	38882	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37160	38883	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37161	38884	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37162	38885	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37163	38886	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37164	38887	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37165	38888	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37167	38889	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37168	38890	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37169	38891	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37170	38892	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37171	38893	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37172	38894	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37173	38895	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37174	38896	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37175	38897	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37176	38898	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37177	38899	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37178	38900	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37179	38901	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37180	38902	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37181	38903	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37182	38904	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37183	38905	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37184	38906	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37185	38907	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37186	38908	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37187	38909	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37188	38910	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37189	38911	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37190	38912	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37191	38913	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37192	38914	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37193	38915	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37194	38916	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37195	38917	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37196	38918	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37197	38919	N	N	N	1	CUSTOMER ISSUE	-
DMS_37198	38920	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37199	38921	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37200	38922	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37201	38923	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37202	38924	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37203	38925	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37204	38926	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37206	38927	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37207	38928	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37208	38929	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37209	38930	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37210	38931	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37211	38932	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37212	38933	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37213	38934	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37214	38935	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37215	38936	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_37216	38937	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37217	38938	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37218	38939	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_37219	38940	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37220	38941	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37221	38942	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37222	38943	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37223	38944	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37224	38945	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37225	38946	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37226	38947	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37227	38948	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37228	38949	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37229	38950	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37230	38951	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37231	38952	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37232	38953	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37233	38954	N	N	N	1	CUSTOMER ISSUE	-
DMS_37234	38955	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37235	38956	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37236	38957	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37237	38958	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37238	38959	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37239	38960	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37240	38961	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37241	38962	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37242	38963	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37243	38964	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37244	38965	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37245	38966	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37247	38967	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37248	38968	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37249	38969	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37250	38970	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37251	38971	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37252	38972	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37253	38973	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37254	38974	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37255	38975	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37256	38976	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37257	38977	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37258	38978	N	N	N	2	CUSTOMER ISSUE	-
DMS_37259	38979	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37260	38980	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37261	38981	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37262	38982	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37263	38983	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37264	38984	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37265	38985	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37266	38986	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37267	38987	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37268	38988	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37269	38989	N	N	N	1	CUSTOMER ISSUE	-
DMS_37270	38990	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37271	38991	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37272	38992	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37273	38993	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37274	38994	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37275	38995	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37276	38996	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37277	38997	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37278	38998	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37279	38999	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37280	39000	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37281	39001	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37282	39002	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37283	39003	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37284	39004	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37285	39005	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37286	39006	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37287	39007	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37288	39008	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37289	39009	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37290	39010	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37291	39011	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37292	39012	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37293	39013	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37295	39014	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37296	39015	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37297	39016	N	N	Y	1	DIST - REPLACE FUSE	708.75

DMS_37298	39017	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37299	39018	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37300	39019	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37301	39020	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37302	39021	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37303	39022	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37304	39023	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37305	39024	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37306	39025	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37307	39026	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37308	39027	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37309	39028	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37310	39029	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37311	39030	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37312	39031	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37313	39032	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37314	39033	N	N	N	1	CUSTOMER ISSUE	-
DMS_37315	39034	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37316	39035	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37317	39036	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37318	39037	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37319	39038	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37320	39039	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37321	39040	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37322	39041	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37323	39042	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37324	39043	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37325	39044	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37326	39045	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37327	39046	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37328	39047	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37329	39048	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37330	39049	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37331	39050	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37332	39051	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37333	39052	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37334	39053	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37335	39054	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37336	39055	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37337	39056	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37338	39057	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37339	39058	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37340	39059	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37341	39060	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37342	39061	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37343	39062	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37344	39063	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37345	39064	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37346	39065	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37347	39066	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37348	39067	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37349	39068	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37350	39069	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37351	39070	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37352	39071	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37353	39072	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37354	39073	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37355	39074	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37356	39075	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37357	39076	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37358	39077	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37359	39078	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37360	39079	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37361	39080	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37362	39081	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37363	39082	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37364	39083	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37365	39084	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37366	39085	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_37367	39086	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37368	39087	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37369	39088	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37370	39089	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37371	39090	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37372	39091	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37373	39092	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37374	39093	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37375	39094	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37376	39095	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37377	39096	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_37378	39097	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37379	39098	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37380	39099	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37381	39100	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37382	39101	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37383	39102	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37384	39103	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37385	39104	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37386	39105	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37387	39106	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37388	39107	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37389	39108	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37390	39109	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37391	39110	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37392	39111	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37393	39112	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37394	39113	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37395	39114	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37396	39115	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37397	39116	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37398	39117	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37399	39118	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37400	39119	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37401	39120	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37402	39121	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37403	39122	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37404	39123	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37405	39124	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37406	39125	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37407	39126	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37408	39127	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37409	39128	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37410	39129	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37411	39130	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37412	39131	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37413	39132	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37414	39133	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37415	39134	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37416	39135	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37417	39136	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37418	39137	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37419	39138	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37420	39139	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37421	39140	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37422	39141	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37423	39142	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37424	39143	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37425	39144	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37426	39145	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37427	39146	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37428	39147	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37429	39148	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37430	39149	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37431	39150	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37432	39151	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37433	39152	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37434	39153	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37435	39154	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37436	39155	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37437	39156	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37438	39157	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37439	39158	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37440	39159	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37441	39160	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37442	39161	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37443	39162	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37444	39163	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37445	39164	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37446	39165	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37447	39166	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37448	39167	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37449	39168	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37450	39169	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37451	39170	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37452	39171	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37453	39172	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37454	39173	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37455	39174	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37456	39175	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37457	39176	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_37458	39177	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37459	39178	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37460	39179	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37461	39180	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37462	39181	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37463	39182	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37464	39183	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37465	39184	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37466	39185	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_37467	39186	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37468	39187	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37469	39188	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37470	39189	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37471	39190	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37472	39191	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37473	39192	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37474	39193	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37475	39194	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37476	39195	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37477	39196	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37478	39197	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37479	39198	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37480	39199	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37481	39200	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37483	39201	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37484	39202	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37485	39203	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37486	39204	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37487	39205	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37488	39206	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37489	39207	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37490	39208	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37491	39209	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37492	39210	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37493	39211	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37494	39212	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37495	39213	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37496	39214	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37497	39215	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37498	39216	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37499	39217	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37500	39218	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37501	39219	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37502	39220	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37503	39221	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37504	39222	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37505	39223	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37507	39224	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37508	39225	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37509	39226	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37510	39227	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37511	39228	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37512	39229	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37513	39230	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37514	39231	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37515	39232	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37516	39233	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37517	39234	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37518	39235	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37519	39236	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37520	39237	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37521	39238	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37522	39239	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37523	39240	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37524	39241	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37525	39242	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37526	39243	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37527	39244	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37528	39245	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37529	39246	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37530	39247	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37531	39248	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37532	39249	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37533	39250	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37534	39251	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37535	39252	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37536	39253	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_37537	39254	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37538	39255	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37539	39256	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_37540	39257	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37541	39258	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37542	39259	N	N	N	1	CUSTOMER ISSUE	-
DMS_37543	39260	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37544	39261	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37545	39262	N	N	N	1	CUSTOMER ISSUE	-
DMS_37546	39263	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37547	39264	N	N	N	1	CUSTOMER ISSUE	-
DMS_37548	39265	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37549	39266	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37550	39267	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37551	39268	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37552	39269	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37553	39270	N	N	N	1	CUSTOMER ISSUE	-
DMS_37554	39271	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37555	39272	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37556	39273	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37557	39274	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37558	39275	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37559	39276	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37560	39277	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37561	39278	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37562	39279	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37563	39280	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37564	39281	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37565	39282	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37566	39283	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37567	39284	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37568	39285	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37569	39286	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37570	39287	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37571	39288	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37572	39289	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37573	39290	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37574	39291	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37575	39292	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37576	39293	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37577	39294	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37578	39295	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37579	39296	N	N	N	1	CUSTOMER ISSUE	-
DMS_37580	39297	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37581	39298	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37582	39299	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37583	39300	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37584	39301	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37585	39302	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37586	39303	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37587	39304	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37588	39305	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37589	39306	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37590	39307	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37591	39308	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37592	39309	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37593	39310	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_37594	39311	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37595	39312	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37596	39313	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37597	39314	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37598	39315	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37599	39316	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37600	39317	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37601	39318	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37602	39319	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37603	39320	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37604	39321	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37605	39322	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37606	39323	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37607	39324	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37608	39325	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37609	39326	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37610	39327	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37611	39328	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37612	39329	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37613	39330	N	N	N	1	CUSTOMER ISSUE	-
DMS_37614	39331	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37615	39332	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37616	39333	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37617	39334	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37618	39335	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37619	39336	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_37620	39337	N	N	N	1	CUSTOMER ISSUE	-
DMS_37621	39338	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37622	39339	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37623	39340	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37624	39341	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37625	39342	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37626	39343	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37627	39344	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37628	39345	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37629	39346	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37630	39347	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37631	39348	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37632	39349	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37633	39350	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37634	39351	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37635	39352	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37636	39353	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37637	39354	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37638	39355	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37639	39356	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37640	39357	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37641	39358	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37642	39359	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37643	39360	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37644	39361	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37645	39362	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37646	39363	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37647	39364	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37648	39365	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37649	39366	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37650	39367	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37651	39368	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37652	39369	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37653	39370	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37654	39371	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37655	39372	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37656	39373	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37657	39374	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37658	39375	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37659	39376	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37660	39377	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37661	39378	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37662	39379	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37663	39380	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37664	39381	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37665	39382	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37666	39383	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37667	39384	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37668	39385	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37669	39386	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37670	39387	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37671	39388	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37672	39389	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37673	39390	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37674	39391	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37675	39392	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37676	39393	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37677	39394	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37678	39395	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37679	39396	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37680	39397	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37681	39398	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37682	39399	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37683	39400	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37684	39401	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37685	39402	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37686	39403	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37687	39404	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37688	39405	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37689	39406	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37690	39407	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37691	39408	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37692	39409	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37693	39410	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37694	39411	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37695	39412	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37696	39413	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37697	39414	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37698	39415	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37699	39416	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_37700	39417	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37701	39418	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37702	39419	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37703	39420	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37704	39421	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37705	39422	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37706	39423	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37707	39424	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37708	39425	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37709	39426	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37710	39427	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37711	39428	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37712	39429	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37713	39430	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37714	39431	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37715	39432	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37716	39433	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37717	39434	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37718	39435	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37719	39436	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37720	39437	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37721	39438	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37722	39439	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37723	39440	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37724	39441	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37725	39442	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37726	39443	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37727	39444	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37728	39445	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37729	39446	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37730	39447	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37731	39448	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37732	39449	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37733	39450	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37734	39451	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37735	39452	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37736	39453	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37737	39454	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37738	39455	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37739	39456	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37740	39457	N	N	N	1	CUSTOMER ISSUE	-
DMS_37741	39458	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37742	39459	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37743	39460	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37744	39461	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37745	39462	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37746	39463	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37747	39464	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37748	39465	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37749	39466	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37750	39467	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37751	39468	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37752	39469	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37753	39470	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37754	39471	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37755	39472	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37756	39473	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37757	39474	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_37758	39475	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37759	39476	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37760	39477	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37761	39478	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37762	39479	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37763	39480	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37764	39481	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37765	39482	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37766	39483	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37767	39484	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37768	39485	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37769	39486	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37770	39487	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37771	39488	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37772	39489	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37773	39490	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37774	39491	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37775	39492	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37776	39493	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37777	39494	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37778	39495	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37779	39496	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_37780	39497	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37781	39498	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37782	39499	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37783	39500	N	N	N	1	CUSTOMER ISSUE	-
DMS_37784	39501	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37785	39502	N	N	N	1	CUSTOMER ISSUE	-
DMS_37786	39503	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37787	39504	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37788	39505	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37789	39506	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37790	39507	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37791	39508	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37792	39509	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37793	39510	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37794	39511	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37795	39512	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37796	39513	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37797	39514	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37798	39515	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37799	39516	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37800	39517	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37801	39518	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37802	39519	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37803	39520	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37804	39521	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37805	39522	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37806	39523	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37807	39524	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37808	39525	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37809	39526	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37810	39527	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37811	39528	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37812	39529	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37813	39530	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37814	39531	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37815	39532	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37816	39533	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37817	39534	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37818	39535	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37819	39536	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37820	39537	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37821	39538	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37822	39539	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_37823	39540	N	N	N	1	CUSTOMER ISSUE	-
DMS_37824	39541	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37825	39542	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_37826	39543	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37827	39544	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37828	39545	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37829	39546	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37830	39547	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37831	39548	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37832	39549	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37833	39550	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37834	39551	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37835	39552	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37836	39553	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37837	39554	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37838	39555	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37839	39556	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_37840	39557	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37841	39558	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37842	39559	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37843	39560	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37844	39561	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37845	39562	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37846	39563	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37847	39564	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37848	39565	N	N	N	1	CUSTOMER ISSUE	-
DMS_37849	39566	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37850	39567	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37851	39568	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37852	39569	N	N	N	1	CUSTOMER ISSUE	-
DMS_37853	39570	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37854	39571	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37855	39572	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37856	39573	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37857	39574	N	N	N	1	CUSTOMER ISSUE	-
DMS_37858	39575	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37859	39576	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_37860	39577	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37861	39578	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37862	39579	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_37863	39580	N	N	N	1	CUSTOMER ISSUE	-
DMS_37864	39581	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37866	39582	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37867	39583	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_37868	39584	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37869	39585	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37870	39586	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37871	39587	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37872	39588	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37873	39589	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37874	39590	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37875	39591	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37876	39592	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37877	39593	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37878	39594	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37879	39595	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37880	39596	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37881	39597	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37882	39598	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37883	39599	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37884	39600	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37885	39601	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37886	39602	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37887	39603	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37888	39604	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37889	39605	N	N	N	1	CUSTOMER ISSUE	-
DMS_37890	39606	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37891	39607	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37892	39608	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37893	39609	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37894	39610	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37895	39611	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37896	39612	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37897	39613	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37898	39614	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37899	39615	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37900	39616	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37901	39617	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37902	39618	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_37903	39619	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37904	39620	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37905	39621	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37906	39622	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37907	39623	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37908	39624	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37909	39625	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37910	39626	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37911	39627	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37912	39628	N	N	N	1	CUSTOMER ISSUE	-
DMS_37913	39629	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37914	39630	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37915	39631	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37916	39632	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37917	39633	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37918	39634	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37919	39635	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37920	39636	N	N	N	1	CUSTOMER ISSUE	-
DMS_37921	39637	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37922	39638	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37923	39639	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37924	39640	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37925	39641	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37926	39642	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37927	39643	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37928	39644	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37929	39645	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37930	39646	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37931	39647	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37932	39648	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37933	39649	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37934	39650	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37935	39651	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37936	39652	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37937	39653	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37938	39654	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37939	39655	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37940	39656	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_37941	39657	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37942	39658	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37943	39659	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37944	39660	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37945	39661	N	N	N	1	CUSTOMER ISSUE	-
DMS_37946	39662	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37947	39663	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37948	39664	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37949	39665	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37950	39666	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37951	39667	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37952	39668	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37953	39669	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37954	39670	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37955	39671	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37956	39672	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37957	39673	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37958	39674	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37959	39675	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37960	39676	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37961	39677	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37962	39678	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37963	39679	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37964	39680	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37965	39681	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37966	39682	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37967	39683	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37968	39684	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37969	39685	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37970	39686	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37971	39687	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37972	39688	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37973	39689	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37974	39690	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37975	39691	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37976	39692	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37977	39693	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37978	39694	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37979	39695	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37980	39696	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37981	39697	N	N	N	1	CUSTOMER ISSUE	-
DMS_37982	39698	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37983	39699	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37984	39700	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37985	39701	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37986	39702	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37987	39703	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37988	39704	N	N	N	1	CUSTOMER ISSUE	-
DMS_37989	39705	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37990	39706	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37991	39707	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37992	39708	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37993	39709	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37994	39710	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37995	39711	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37996	39712	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37997	39713	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37998	39714	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_37999	39715	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38000	39716	N	N	N	1	CUSTOMER ISSUE	-
DMS_38001	39717	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38002	39718	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38003	39719	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38004	39720	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38005	39721	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38006	39722	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38007	39723	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38008	39724	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38009	39725	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38010	39726	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38011	39727	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38012	39728	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38013	39729	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38014	39730	N	N	N	1	CUSTOMER ISSUE	-
DMS_38015	39731	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38016	39732	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38017	39733	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38018	39734	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38019	39735	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38020	39736	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_38021	39737	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38022	39738	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38023	39739	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38024	39740	N	N	N	1	CUSTOMER ISSUE	-
DMS_38025	39741	N	N	N	1	CUSTOMER ISSUE	-
DMS_38026	39742	N	N	N	1	CUSTOMER ISSUE	-
DMS_38027	39743	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38028	39744	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38029	39745	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38030	39746	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38031	39747	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38032	39748	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38033	39749	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38034	39750	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38035	39751	N	N	N	1	CUSTOMER ISSUE	-
DMS_38036	39752	N	N	N	1	CUSTOMER ISSUE	-
DMS_38037	39753	N	N	N	1	CUSTOMER ISSUE	-
DMS_38038	39754	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38039	39755	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38040	39756	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38041	39757	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38042	39758	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38043	39759	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38044	39760	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38045	39761	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38046	39762	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38047	39763	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38048	39764	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38049	39765	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38050	39766	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38051	39767	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38052	39768	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38053	39769	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38054	39770	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38055	39771	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38056	39772	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38057	39773	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38058	39774	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38059	39775	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38060	39776	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38061	39777	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38062	39778	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38063	39779	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38064	39780	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38065	39781	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38066	39782	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38067	39783	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38068	39784	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38069	39785	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38070	39786	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38071	39787	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38072	39788	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38073	39789	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38074	39790	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38075	39791	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38076	39792	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38077	39793	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38078	39794	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38079	39795	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38080	39796	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38081	39797	N	N	N	1	CUSTOMER ISSUE	-
DMS_38082	39798	N	N	N	1	CUSTOMER ISSUE	-
DMS_38083	39799	N	N	N	1	CUSTOMER ISSUE	-
DMS_38084	39800	N	N	N	1	CUSTOMER ISSUE	-
DMS_38085	39801	N	N	N	1	CUSTOMER ISSUE	-
DMS_38086	39802	N	N	N	1	CUSTOMER ISSUE	-
DMS_38087	39803	N	N	N	1	CUSTOMER ISSUE	-
DMS_38088	39804	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38089	39805	N	N	N	1	CUSTOMER ISSUE	-
DMS_38090	39806	N	N	N	1	CUSTOMER ISSUE	-
DMS_38091	39807	N	N	N	1	CUSTOMER ISSUE	-
DMS_38092	39808	N	N	N	1	CUSTOMER ISSUE	-
DMS_38093	39809	N	N	N	1	CUSTOMER ISSUE	-
DMS_38094	39810	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38095	39811	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38096	39812	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38097	39813	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38098	39814	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38099	39815	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38100	39816	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_38101	39817	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38102	39818	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38103	39819	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38104	39820	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38105	39821	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38106	39822	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38107	39823	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38108	39824	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38109	39825	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38110	39826	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38111	39827	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38112	39828	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38113	39829	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38114	39830	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38115	39831	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38116	39832	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38117	39833	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38118	39834	N	N	N	1	CUSTOMER ISSUE	-
DMS_38119	39835	N	N	N	1	CUSTOMER ISSUE	-
DMS_38120	39836	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38121	39837	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38122	39838	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38123	39839	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38124	39840	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38125	39841	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38126	39842	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38127	39843	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38128	39844	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38129	39845	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38130	39846	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38131	39847	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38132	39848	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38133	39849	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38134	39850	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38135	39851	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38136	39852	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38137	39853	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38138	39854	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38139	39855	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38140	39856	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38141	39857	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38142	39858	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38143	39859	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38144	39860	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38145	39861	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38146	39862	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38147	39863	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38148	39864	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38149	39865	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38150	39866	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38151	39867	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38152	39868	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_38153	39869	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38154	39870	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38155	39871	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38156	39872	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38157	39873	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_38158	39874	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38159	39875	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38160	39876	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38161	39877	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38162	39878	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38163	39879	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38164	39880	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38165	39881	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38166	39882	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38167	39883	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38168	39884	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38169	39885	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38170	39886	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38171	39887	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38172	39888	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38173	39889	N	N	N	1	CUSTOMER ISSUE	-
DMS_38174	39890	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38175	39891	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38176	39892	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38177	39893	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38178	39894	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38179	39895	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38180	39896	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_38181	39897	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38182	39898	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38183	39899	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38184	39900	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38185	39901	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38186	39902	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38187	39903	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38188	39904	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38189	39905	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38191	39906	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38192	39907	N	N	N	1	CUSTOMER ISSUE	-
DMS_38193	39908	N	N	N	1	CUSTOMER ISSUE	-
DMS_38194	39909	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38195	39910	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38196	39911	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38199	39912	N	N	N	1	CUSTOMER ISSUE	-
DMS_38207	39913	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38210	39914	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38211	39915	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38212	39916	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38213	39917	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38214	39918	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38215	39919	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38216	39920	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38217	39921	N	N	N	1	CUSTOMER ISSUE	-
DMS_38218	39922	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38219	39923	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38220	39924	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38221	39925	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38222	39926	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38223	39927	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38224	39928	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38225	39929	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38226	39930	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38227	39931	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38228	39932	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38229	39933	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38230	39934	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38231	39935	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38232	39936	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38233	39937	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38234	39938	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38235	39939	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38236	39940	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38237	39941	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_38238	39942	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38239	39943	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38240	39944	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38241	39945	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38242	39946	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38243	39947	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38244	39948	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38245	39949	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38246	39950	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38247	39951	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38248	39952	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38249	39953	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38250	39954	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38251	39955	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38252	39956	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38253	39957	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38254	39958	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38255	39959	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38256	39960	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38257	39961	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38258	39962	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38259	39963	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38260	39964	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38261	39965	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38262	39966	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38263	39967	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38264	39968	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38265	39969	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38266	39970	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38267	39971	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38268	39972	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38269	39973	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38270	39974	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_38271	39975	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38272	39976	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_38273	39977	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38274	39978	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38275	39979	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38276	39980	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38277	39981	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38278	39982	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38279	39983	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38280	39984	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38281	39985	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38282	39986	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38283	39987	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38284	39988	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38285	39989	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38286	39990	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38287	39991	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38288	39992	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38289	39993	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_38290	39994	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38291	39995	N	N	N	1	CUSTOMER ISSUE	-
DMS_38292	39996	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38293	39997	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38294	39998	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38295	39999	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38296	40000	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38297	40001	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38298	40002	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38299	40003	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38300	40004	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38301	40005	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38302	40006	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38303	40007	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38304	40008	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38305	40009	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38306	40010	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38307	40011	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38308	40012	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38309	40013	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38310	40014	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38311	40015	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38312	40016	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38313	40017	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38314	40018	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38315	40019	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38316	40020	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38317	40021	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38318	40022	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38319	40023	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38320	40024	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38321	40025	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38322	40026	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38323	40027	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38324	40028	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38325	40029	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38326	40030	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38327	40031	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38328	40032	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38329	40033	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38330	40034	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38331	40035	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38332	40036	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_38333	40037	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38334	40038	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38335	40039	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38336	40040	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38337	40041	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38338	40042	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38339	40043	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38340	40044	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38341	40045	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38342	40046	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38343	40047	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38344	40048	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38345	40049	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38346	40050	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38347	40051	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38348	40052	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38349	40053	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38350	40054	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38352	40055	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38353	40056	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_38354	40057	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38355	40058	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38356	40059	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38357	40060	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38358	40061	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38359	40062	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38360	40063	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38361	40064	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38362	40065	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38363	40066	N	N	N	1	CUSTOMER ISSUE	-
DMS_38364	40067	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38365	40068	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_38366	40069	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38367	40070	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38368	40071	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38369	40072	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38370	40073	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38371	40074	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38372	40075	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38373	40076	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38374	40077	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38375	40078	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38376	40079	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38377	40080	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38378	40081	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38379	40082	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38380	40083	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38381	40084	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38382	40085	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38383	40086	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38384	40087	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38385	40088	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38386	40089	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38387	40090	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38388	40091	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38389	40092	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38390	40093	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38391	40094	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38392	40095	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38393	40096	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38394	40097	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38395	40098	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38396	40099	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38397	40100	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38398	40101	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38399	40102	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38400	40103	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38402	40104	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38403	40105	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38404	40106	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38405	40107	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38406	40108	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38407	40109	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38408	40110	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38409	40111	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38410	40112	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38411	40113	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38412	40114	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38413	40115	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38414	40116	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38415	40117	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38416	40118	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38417	40119	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38418	40120	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38419	40121	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38420	40122	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38421	40123	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38422	40124	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38423	40125	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38424	40126	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38425	40127	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38426	40128	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38427	40129	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38428	40130	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38429	40131	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38430	40132	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38431	40133	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38432	40134	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38433	40135	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38434	40136	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_38435	40137	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38436	40138	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38437	40139	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38438	40140	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38439	40141	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38440	40142	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38441	40143	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38442	40144	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38443	40145	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38444	40146	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38445	40147	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38446	40148	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38447	40149	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38448	40150	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38449	40151	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38450	40152	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38451	40153	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38452	40154	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38453	40155	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38454	40156	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38455	40157	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38456	40158	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38457	40159	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38458	40160	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38459	40161	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38460	40162	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38461	40163	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38462	40164	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38463	40165	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38464	40166	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38465	40167	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38466	40168	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38467	40169	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38468	40170	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38469	40171	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38470	40172	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38471	40173	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_38472	40174	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38473	40175	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38474	40176	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38475	40177	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38476	40178	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38477	40179	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38478	40180	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38479	40181	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38480	40182	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38481	40183	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38482	40184	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38483	40185	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38484	40186	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38485	40187	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38486	40188	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38487	40189	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38488	40190	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38489	40191	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38490	40192	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38491	40193	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38492	40194	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38493	40195	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38494	40196	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38495	40197	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38496	40198	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38497	40199	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38498	40200	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38499	40201	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38500	40202	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38501	40203	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38502	40204	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38503	40205	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38504	40206	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38505	40207	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38506	40208	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38507	40209	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38508	40210	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38509	40211	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38510	40212	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38511	40213	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38512	40214	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38513	40215	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38514	40216	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_38515	40217	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38516	40218	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38517	40219	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38518	40220	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38519	40221	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38520	40222	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38521	40223	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38522	40224	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_38523	40225	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38524	40226	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38525	40227	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38526	40228	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38527	40229	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38528	40230	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38529	40231	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38530	40232	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38531	40233	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38532	40234	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38533	40235	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38534	40236	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38535	40237	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38536	40238	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38537	40239	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38538	40240	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38539	40241	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38540	40242	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38541	40243	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38542	40244	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38543	40245	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38544	40246	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38545	40247	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38546	40248	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38547	40249	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38548	40250	N	N	N	1	CUSTOMER ISSUE	-
DMS_38549	40251	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38550	40252	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38551	40253	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38552	40254	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38553	40255	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38554	40256	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38555	40257	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38556	40258	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38557	40259	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38558	40260	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38559	40261	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38560	40262	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38561	40263	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38562	40264	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38563	40265	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38564	40266	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38565	40267	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38566	40268	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38567	40269	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38568	40270	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38569	40271	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38570	40272	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38571	40273	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38572	40274	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38573	40275	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38574	40276	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38575	40277	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38576	40278	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38577	40279	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38578	40280	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38579	40281	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38580	40282	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38581	40283	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38582	40284	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38583	40285	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38584	40286	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38585	40287	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38586	40288	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38587	40289	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38588	40290	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38589	40291	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38590	40292	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38591	40293	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38592	40294	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38593	40295	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38594	40296	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_38595	40297	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38596	40298	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38597	40299	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38598	40300	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38599	40301	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38600	40302	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38601	40303	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38602	40304	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38603	40305	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38604	40306	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38605	40307	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38606	40308	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38607	40309	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38608	40310	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38609	40311	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38610	40312	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38611	40313	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38612	40314	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38613	40315	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38614	40316	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38615	40317	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38616	40318	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38617	40319	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38618	40320	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38619	40321	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38620	40322	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38621	40323	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38622	40324	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38623	40325	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38624	40326	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38625	40327	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38626	40328	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38627	40329	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38628	40330	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38629	40331	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38630	40332	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38631	40333	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38632	40334	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38633	40335	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38634	40336	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38635	40337	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38636	40338	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38637	40339	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38638	40340	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38639	40341	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38640	40342	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38641	40343	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38642	40344	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38643	40345	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38644	40346	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38645	40347	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38646	40348	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38647	40349	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38648	40350	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38649	40351	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38650	40352	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38651	40353	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38652	40354	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38653	40355	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38654	40356	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38655	40357	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38656	40358	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38657	40359	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38658	40360	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38659	40361	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38660	40362	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38661	40363	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38662	40364	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38663	40365	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38664	40366	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38665	40367	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38666	40368	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38667	40369	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38668	40370	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38669	40371	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38670	40372	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38671	40373	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38672	40374	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_38673	40375	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38674	40376	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_38675	40377	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38676	40378	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38677	40379	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38678	40380	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38679	40381	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38680	40382	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38681	40383	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38682	40384	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38683	40385	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38684	40386	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38685	40387	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38686	40388	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38687	40389	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38688	40390	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38689	40391	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38690	40392	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38691	40393	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38692	40394	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38693	40395	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38694	40396	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38695	40397	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38696	40398	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38697	40399	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38698	40400	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38699	40401	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38700	40402	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38701	40403	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38702	40404	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38703	40405	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38704	40406	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38705	40407	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38706	40408	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38707	40409	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38708	40410	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38709	40411	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38710	40412	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38711	40413	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38712	40414	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38713	40415	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38714	40416	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38715	40417	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38716	40418	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38717	40419	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38718	40420	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38719	40421	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38720	40422	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38721	40423	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38722	40424	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38723	40425	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38724	40426	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38725	40427	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38726	40428	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38727	40429	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38728	40430	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38729	40431	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38730	40432	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38731	40433	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38732	40434	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38733	40435	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38734	40436	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38735	40437	N	N	N	1	CUSTOMER ISSUE	-
DMS_38736	40438	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38737	40439	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38738	40440	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38739	40441	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38740	40442	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38741	40443	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38742	40444	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38743	40445	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38744	40446	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38745	40447	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38746	40448	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38747	40449	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38748	40450	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38749	40451	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38750	40452	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38751	40453	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38752	40454	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38753	40455	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38754	40456	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_38755	40457	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38756	40458	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38757	40459	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38758	40460	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38759	40461	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38760	40462	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38761	40463	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38762	40464	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_38763	40465	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38764	40466	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38765	40467	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38766	40468	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38767	40469	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38768	40470	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38769	40471	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38770	40472	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38771	40473	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38772	40474	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38773	40475	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38774	40476	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38775	40477	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38776	40478	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38778	40479	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38779	40480	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_38780	40481	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38781	40482	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38782	40483	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38783	40484	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38784	40485	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38785	40486	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38786	40487	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38787	40488	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38788	40489	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38789	40490	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38790	40491	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38791	40492	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38792	40493	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38793	40494	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38794	40495	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38795	40496	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38796	40497	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38797	40498	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38798	40499	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38799	40500	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38800	40501	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38801	40502	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38802	40503	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38803	40504	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38804	40505	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38805	40506	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38806	40507	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38807	40508	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38808	40509	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38809	40510	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38810	40511	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38811	40512	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38812	40513	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38813	40514	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38814	40515	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38815	40516	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38816	40517	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38817	40518	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38818	40519	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38819	40520	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38820	40521	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38821	40522	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38822	40523	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38823	40524	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38824	40525	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38825	40526	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38826	40527	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38827	40528	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38828	40529	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38829	40530	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38830	40531	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38831	40532	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38832	40533	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38833	40534	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38834	40535	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38835	40536	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_38836	40537	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38837	40538	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38838	40539	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38839	40540	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38840	40541	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38841	40542	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38842	40543	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38843	40544	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38844	40545	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38845	40546	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38846	40547	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38847	40548	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38848	40549	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38849	40550	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38850	40551	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38851	40552	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38852	40553	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38853	40554	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38854	40555	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38855	40556	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38856	40557	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38857	40558	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38858	40559	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38859	40560	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38860	40561	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38861	40562	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38862	40563	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38863	40564	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38864	40565	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38865	40566	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38866	40567	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38867	40568	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38868	40569	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38869	40570	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38870	40571	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38871	40572	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38872	40573	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38873	40574	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38874	40575	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38875	40576	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38876	40577	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38877	40578	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38878	40579	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38879	40580	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38880	40581	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38881	40582	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38882	40583	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38883	40584	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38884	40585	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38885	40586	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38886	40587	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38887	40588	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38888	40589	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38889	40590	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38890	40591	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38891	40592	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38892	40593	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38893	40594	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38894	40595	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38895	40596	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38896	40597	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38897	40598	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38898	40599	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38899	40600	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38900	40601	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38901	40602	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38902	40603	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38903	40604	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38904	40605	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38905	40606	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38906	40607	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38907	40608	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38908	40609	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38909	40610	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38910	40611	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38911	40612	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38912	40613	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38913	40614	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38914	40615	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38915	40616	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_38916	40617	N	N	N	1	CUSTOMER ISSUE	-
DMS_38918	40618	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38919	40619	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38920	40620	N	N	N	1	CUSTOMER ISSUE	-
DMS_38921	40621	N	N	N	1	CUSTOMER ISSUE	-
DMS_38922	40622	N	N	N	1	CUSTOMER ISSUE	-
DMS_38923	40623	N	N	N	1	CUSTOMER ISSUE	-
DMS_38924	40624	N	N	N	1	CUSTOMER ISSUE	-
DMS_38925	40625	N	N	N	1	CUSTOMER ISSUE	-
DMS_38926	40626	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38927	40627	N	N	N	1	CUSTOMER ISSUE	-
DMS_38928	40628	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38929	40629	N	N	N	1	CUSTOMER ISSUE	-
DMS_38930	40630	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38931	40631	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38932	40632	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38933	40633	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38934	40634	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38935	40635	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38936	40636	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38937	40637	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38938	40638	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38939	40639	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38940	40640	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38941	40641	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38942	40642	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38943	40643	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38944	40644	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38945	40645	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38946	40646	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38947	40647	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38948	40648	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38949	40649	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38950	40650	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38951	40651	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38952	40652	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38953	40653	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38954	40654	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38955	40655	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38956	40656	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38957	40657	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38958	40658	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38959	40659	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38960	40660	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38961	40661	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38962	40662	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38963	40663	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38964	40664	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38965	40665	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38966	40666	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38967	40667	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38968	40668	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38969	40669	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38970	40670	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38971	40671	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38972	40672	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38973	40673	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38974	40674	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38975	40675	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38976	40676	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38977	40677	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38978	40678	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38979	40679	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38980	40680	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38981	40681	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38982	40682	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38983	40683	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38984	40684	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38985	40685	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_38986	40686	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38987	40687	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38988	40688	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38989	40689	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38990	40690	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38991	40691	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38992	40692	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_38993	40693	N	N	N	1	CUSTOMER ISSUE	-
DMS_38994	40694	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38995	40695	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38996	40696	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_38997	40697	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38998	40698	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_38999	40699	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39000	40700	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39001	40701	N	N	N	1	CUSTOMER ISSUE	-
DMS_39002	40702	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39003	40703	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39004	40704	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39005	40705	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39006	40706	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39007	40707	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39008	40708	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39009	40709	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39010	40710	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39011	40711	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39012	40712	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39013	40713	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39014	40714	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39015	40715	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39016	40716	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39017	40717	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39018	40718	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39019	40719	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39020	40720	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39021	40721	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39022	40722	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39023	40723	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39024	40724	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39025	40725	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39026	40726	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39027	40727	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39028	40728	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39029	40729	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39030	40730	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39031	40731	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39032	40732	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39033	40733	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39034	40734	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39035	40735	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39036	40736	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39037	40737	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39038	40738	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39039	40739	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39040	40740	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39041	40741	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39042	40742	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39043	40743	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39044	40744	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39045	40745	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39046	40746	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39047	40747	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39048	40748	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39049	40749	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39050	40750	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39051	40751	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39052	40752	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39053	40753	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39054	40754	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39055	40755	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39056	40756	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39057	40757	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39058	40758	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39059	40759	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39060	40760	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39061	40761	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39062	40762	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39063	40763	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39064	40764	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39065	40765	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39066	40766	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39067	40767	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39068	40768	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39069	40769	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39070	40770	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39071	40771	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39072	40772	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39073	40773	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39074	40774	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39075	40775	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39076	40776	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_39077	40777	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39078	40778	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39079	40779	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39080	40780	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39081	40781	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39082	40782	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39083	40783	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39084	40784	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39085	40785	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39086	40786	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39087	40787	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39088	40788	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39089	40789	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39090	40790	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39091	40791	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39092	40792	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39093	40793	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39094	40794	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39095	40795	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39096	40796	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39097	40797	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39098	40798	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39099	40799	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39100	40800	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39101	40801	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39102	40802	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39103	40803	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39104	40804	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39105	40805	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39106	40806	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39107	40807	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39108	40808	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39109	40809	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39110	40810	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39111	40811	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39112	40812	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39113	40813	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39114	40814	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39115	40815	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39116	40816	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39117	40817	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39118	40818	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39119	40819	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39120	40820	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39121	40821	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39122	40822	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39123	40823	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39124	40824	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39125	40825	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39126	40826	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39127	40827	N	N	N	1	CUSTOMER ISSUE	-
DMS_39128	40828	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39129	40829	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39130	40830	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39131	40831	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39132	40832	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39133	40833	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39134	40834	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39135	40835	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39136	40836	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39137	40837	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39138	40838	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39139	40839	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39140	40840	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39141	40841	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39142	40842	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39143	40843	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39144	40844	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39145	40845	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39146	40846	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39147	40847	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39148	40848	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39149	40849	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39150	40850	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39151	40851	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39152	40852	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39153	40853	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39154	40854	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39155	40855	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39156	40856	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_39157	40857	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39158	40858	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39159	40859	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39160	40860	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39161	40861	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39162	40862	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39163	40863	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39164	40864	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39165	40865	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39166	40866	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39167	40867	N	N	N	1	CUSTOMER ISSUE	-
DMS_39168	40868	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39169	40869	N	N	N	1	CUSTOMER ISSUE	-
DMS_39170	40870	N	N	N	1	CUSTOMER ISSUE	-
DMS_39171	40871	N	N	N	1	CUSTOMER ISSUE	-
DMS_39172	40872	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39173	40873	N	N	N	1	CUSTOMER ISSUE	-
DMS_39174	40874	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39175	40875	N	N	N	1	CUSTOMER ISSUE	-
DMS_39176	40876	N	N	N	1	CUSTOMER ISSUE	-
DMS_39177	40877	N	N	N	1	CUSTOMER ISSUE	-
DMS_39178	40878	N	N	N	1	CUSTOMER ISSUE	-
DMS_39179	40879	N	N	N	1	CUSTOMER ISSUE	-
DMS_39180	40880	N	N	N	1	CUSTOMER ISSUE	-
DMS_39181	40881	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39182	40882	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39183	40883	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39184	40884	N	N	Y	1	TX - REPLACE	2500
DMS_39185	40885	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_39186	40886	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_39187	40887	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_39188	40888	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_39189	40889	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39190	40890	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39191	40891	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39192	40892	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39193	40893	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39194	40894	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39195	40895	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39196	40896	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39197	40897	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39198	40898	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39199	40899	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39200	40900	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39201	40901	N	N	N	1	CUSTOMER ISSUE	-
DMS_39202	40902	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39203	40903	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39204	40904	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39205	40905	N	N	N	1	CUSTOMER ISSUE	-
DMS_39206	40906	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39207	40907	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39208	40908	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39209	40909	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39210	40910	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39211	40911	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39212	40912	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39213	40913	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39214	40914	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39215	40915	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39216	40916	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39217	40917	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39218	40918	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39219	40919	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39220	40920	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39221	40921	N	N	N	1	CUSTOMER ISSUE	-
DMS_39222	40922	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39223	40923	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39224	40924	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39225	40925	N	N	N	1	CUSTOMER ISSUE	-
DMS_39226	40926	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39227	40927	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39228	40928	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39229	40929	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39230	40930	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39231	40931	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39232	40932	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39233	40933	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39234	40934	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39235	40935	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39236	40936	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_39237	40937	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39238	40938	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39239	40939	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39240	40940	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39241	40941	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39242	40942	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39243	40943	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39244	40944	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39245	40945	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39246	40946	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39247	40947	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39248	40948	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39249	40949	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39250	40950	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_39251	40951	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39252	40952	N	N	N	1	CUSTOMER ISSUE	-
DMS_39253	40953	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39254	40954	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39255	40955	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39256	40956	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39257	40957	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39258	40958	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39259	40959	N	N	N	1	CUSTOMER ISSUE	-
DMS_39260	40960	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39261	40961	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39262	40962	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39263	40963	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39264	40964	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39265	40965	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39266	40966	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39267	40967	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39268	40968	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39269	40969	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39270	40970	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39271	40971	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39272	40972	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39273	40973	N	N	N	1	CUSTOMER ISSUE	-
DMS_39274	40974	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_39275	40975	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_39276	40976	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39277	40977	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39278	40978	N	N	N	1	CUSTOMER ISSUE	-
DMS_39279	40979	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39280	40980	N	N	N	1	CUSTOMER ISSUE	-
DMS_39281	40981	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39282	40982	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_39283	40983	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39284	40984	N	N	N	1	CUSTOMER ISSUE	-
DMS_39285	40985	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39286	40986	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39287	40987	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39288	40988	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39289	40989	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39290	40990	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39291	40991	N	N	N	1	CUSTOMER ISSUE	-
DMS_39292	40992	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39293	40993	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39294	40994	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39295	40995	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39296	40996	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39297	40997	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39298	40998	N	N	N	1	CUSTOMER ISSUE	-
DMS_39299	40999	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39300	41000	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39301	41001	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39302	41002	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39303	41003	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39304	41004	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39305	41005	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39306	41006	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39307	41007	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39308	41008	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39309	41009	N	N	N	1	CUSTOMER ISSUE	-
DMS_39310	41010	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39311	41011	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39312	41012	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39313	41013	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39314	41014	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39315	41015	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39316	41016	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_39317	41017	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39318	41018	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39319	41019	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39320	41020	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39321	41021	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39322	41022	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39323	41023	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39324	41024	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39325	41025	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39326	41026	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39327	41027	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39328	41028	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39329	41029	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39330	41030	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39331	41031	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39332	41032	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39333	41033	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39334	41034	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39335	41035	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39336	41036	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39337	41037	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39338	41038	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39339	41039	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39340	41040	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39341	41041	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39342	41042	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39343	41043	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39344	41044	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39345	41045	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_39346	41046	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39347	41047	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39348	41048	N	N	N	1	CUSTOMER ISSUE	-
DMS_39349	41049	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39350	41050	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39351	41051	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39352	41052	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39353	41053	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39354	41054	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39355	41055	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39356	41056	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39357	41057	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39358	41058	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39359	41059	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39360	41060	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39361	41061	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39362	41062	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39363	41063	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39364	41064	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39365	41065	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39366	41066	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39367	41067	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39368	41068	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39369	41069	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39370	41070	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39371	41071	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39372	41072	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39373	41073	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39374	41074	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39375	41075	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39376	41076	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39377	41077	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39378	41078	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39379	41079	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39380	41080	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39381	41081	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39382	41082	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39383	41083	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39384	41084	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39385	41085	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39386	41086	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39387	41087	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39388	41088	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39389	41089	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39390	41090	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39391	41091	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39392	41092	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39393	41093	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39394	41094	N	N	N	1	CUSTOMER ISSUE	-
DMS_39395	41095	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39396	41096	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_39397	41097	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39398	41098	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39399	41099	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39400	41100	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39401	41101	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39402	41102	N	N	N	1	CUSTOMER ISSUE	-
DMS_39403	41103	N	N	N	1	CUSTOMER ISSUE	-
DMS_39404	41104	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39405	41105	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39406	41106	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39407	41107	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39408	41108	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39409	41109	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39410	41110	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39411	41111	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39412	41112	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39413	41113	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39414	41114	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39415	41115	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39416	41116	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39417	41117	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39418	41118	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39419	41119	N	N	N	1	CUSTOMER ISSUE	-
DMS_39420	41120	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39421	41121	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39422	41122	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39423	41123	N	N	N	1	CUSTOMER ISSUE	-
DMS_39424	41124	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39425	41125	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39426	41126	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39427	41127	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39428	41128	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39429	41129	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39430	41130	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39431	41131	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39432	41132	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39433	41133	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39434	41134	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39435	41135	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39436	41136	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_39437	41137	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_39438	41138	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_39439	41139	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39440	41140	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39441	41141	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39442	41142	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39443	41143	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39444	41144	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_39445	41145	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39446	41146	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39447	41147	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39448	41148	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39449	41149	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39450	41150	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39451	41151	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39452	41152	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39453	41153	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39454	41154	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39455	41155	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39456	41156	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39457	41157	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39458	41158	N	N	N	1	CUSTOMER ISSUE	-
DMS_39459	41159	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39460	41160	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39461	41161	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39462	41162	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39463	41163	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39464	41164	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39465	41165	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39466	41166	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39467	41167	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39469	41168	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39470	41169	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39471	41170	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39472	41171	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39473	41172	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39474	41173	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39475	41174	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39476	41175	N	N	N	1	CUSTOMER ISSUE	-
DMS_39477	41176	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_39478	41177	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39479	41178	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39480	41179	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39481	41180	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39482	41181	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39483	41182	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39484	41183	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39485	41184	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39486	41185	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39487	41186	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39488	41187	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39489	41188	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39490	41189	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39491	41190	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39492	41191	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39493	41192	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39494	41193	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39495	41194	N	N	N	1	CUSTOMER ISSUE	-
DMS_39496	41195	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39497	41196	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39498	41197	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39499	41198	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39500	41199	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39501	41200	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39502	41201	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39503	41202	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39504	41203	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39505	41204	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39506	41205	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39507	41206	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39508	41207	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39509	41208	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39510	41209	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39511	41210	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39512	41211	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39513	41212	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39514	41213	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39515	41214	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39516	41215	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39517	41216	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39518	41217	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39519	41218	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39520	41219	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39521	41220	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39522	41221	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39523	41222	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39524	41223	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39525	41224	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39526	41225	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39527	41226	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39528	41227	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39529	41228	N	N	N	1	CUSTOMER ISSUE	-
DMS_39530	41229	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39531	41230	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39532	41231	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39533	41232	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39534	41233	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39535	41234	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39536	41235	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39537	41236	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39538	41237	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39539	41238	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39540	41239	N	N	N	1	CUSTOMER ISSUE	-
DMS_39541	41240	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39542	41241	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39543	41242	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39544	41243	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39545	41244	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39546	41245	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39547	41246	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39548	41247	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39549	41248	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39550	41249	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39551	41250	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39552	41251	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_39554	41252	N	N	N	1	CUSTOMER ISSUE	-
DMS_39555	41253	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39556	41254	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39557	41255	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39558	41256	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_39559	41257	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39560	41258	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39561	41259	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39562	41260	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39563	41261	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39564	41262	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39565	41263	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39566	41264	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39567	41265	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39568	41266	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39569	41267	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39570	41268	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39571	41269	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_39572	41270	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39573	41271	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39574	41272	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39575	41273	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39581	41274	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_39582	41275	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39584	41276	N	N	N	1	CUSTOMER ISSUE	-
DMS_39592	41277	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39595	41278	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39596	41279	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39600	41280	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39601	41281	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_39602	41282	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39603	41283	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_39608	41284	N	N	N	1	CUSTOMER ISSUE	-
DMS_39611	41285	N	N	N	1	CUSTOMER ISSUE	-
DMS_39612	41286	N	N	N	1	CUSTOMER ISSUE	-
DMS_39613	41287	N	N	N	1	CUSTOMER ISSUE	-
DMS_39614	41288	N	N	N	1	CUSTOMER ISSUE	-
DMS_39615	41289	N	N	N	1	CUSTOMER ISSUE	-
DMS_39616	41290	N	N	N	1	CUSTOMER ISSUE	-
DMS_39617	41291	N	N	N	1	CUSTOMER ISSUE	-
DMS_39619	41292	N	N	N	1	CUSTOMER ISSUE	-
DMS_39620	41293	N	N	N	1	CUSTOMER ISSUE	-
DMS_39621	41294	N	N	N	1	CUSTOMER ISSUE	-
DMS_39622	41295	N	N	N	1	CUSTOMER ISSUE	-
DMS_39623	41296	N	N	N	1	CUSTOMER ISSUE	-
DMS_39624	41297	N	N	N	1	CUSTOMER ISSUE	-
DMS_39625	41298	N	N	N	1	CUSTOMER ISSUE	-
DMS_39626	41299	N	N	N	1	CUSTOMER ISSUE	-
DMS_39627	41300	N	N	N	1	CUSTOMER ISSUE	-
DMS_39628	41301	N	N	N	1	CUSTOMER ISSUE	-
DMS_39629	41302	N	N	N	1	CUSTOMER ISSUE	-
DMS_39630	41303	N	N	N	1	CUSTOMER ISSUE	-
DMS_39631	41304	N	N	N	1	CUSTOMER ISSUE	-
DMS_39632	41305	N	N	N	1	CUSTOMER ISSUE	-
DMS_39633	41306	N	N	N	1	CUSTOMER ISSUE	-
DMS_39634	41307	N	N	N	1	CUSTOMER ISSUE	-
DMS_39635	41308	N	N	N	1	CUSTOMER ISSUE	-
DMS_39636	41309	N	N	N	1	CUSTOMER ISSUE	-
DMS_39637	41310	N	N	N	1	CUSTOMER ISSUE	-
DMS_39638	41311	N	N	N	1	CUSTOMER ISSUE	-
DMS_39639	41312	N	N	N	1	CUSTOMER ISSUE	-
DMS_39640	41313	N	N	N	1	CUSTOMER ISSUE	-
DMS_39641	41314	N	N	N	1	CUSTOMER ISSUE	-
DMS_39642	41315	N	N	N	1	CUSTOMER ISSUE	-
DMS_39643	41316	N	N	N	1	CUSTOMER ISSUE	-
DMS_39644	41317	N	N	N	1	CUSTOMER ISSUE	-
DMS_39645	41318	N	N	N	1	CUSTOMER ISSUE	-
DMS_39646	41319	N	N	N	1	CUSTOMER ISSUE	-
DMS_39647	41320	N	N	N	1	CUSTOMER ISSUE	-
DMS_39648	41321	N	N	N	1	CUSTOMER ISSUE	-
DMS_39649	41322	N	N	N	1	CUSTOMER ISSUE	-
DMS_39650	41323	N	N	N	1	CUSTOMER ISSUE	-
DMS_39651	41324	N	N	N	1	CUSTOMER ISSUE	-
DMS_39652	41325	N	N	N	1	CUSTOMER ISSUE	-
DMS_39653	41326	N	N	N	1	CUSTOMER ISSUE	-
DMS_39654	41327	N	N	N	1	CUSTOMER ISSUE	-
DMS_39655	41328	N	N	N	1	CUSTOMER ISSUE	-
DMS_39656	41329	N	N	N	1	CUSTOMER ISSUE	-
DMS_39657	41330	N	N	N	1	CUSTOMER ISSUE	-
DMS_39658	41331	N	N	N	1	CUSTOMER ISSUE	-
DMS_39659	41332	N	N	N	1	CUSTOMER ISSUE	-
DMS_39661	41333	N	N	N	1	CUSTOMER ISSUE	-
DMS_39662	41334	N	N	N	1	CUSTOMER ISSUE	-
DMS_39663	41335	N	N	N	1	CUSTOMER ISSUE	-
DMS_39664	41336	N	N	N	1	CUSTOMER ISSUE	-

DMS_39665	41337	N	N	N	1	CUSTOMER ISSUE	-
DMS_39666	41338	N	N	N	1	CUSTOMER ISSUE	-
DMS_39667	41339	N	N	N	1	CUSTOMER ISSUE	-
DMS_39668	41340	N	N	N	2	CUSTOMER ISSUE	-
DMS_39669	41341	N	N	N	1	CUSTOMER ISSUE	-
DMS_39670	41342	N	N	N	1	CUSTOMER ISSUE	-
DMS_39672	41343	N	N	N	1	CUSTOMER ISSUE	-
DMS_39673	41344	N	N	N	1	CUSTOMER ISSUE	-
DMS_39674	41345	N	N	N	1	CUSTOMER ISSUE	-
DMS_39675	41346	N	N	N	1	CUSTOMER ISSUE	-
DMS_39676	41347	N	N	N	1	CUSTOMER ISSUE	-
DMS_39678	41348	N	N	N	1	CUSTOMER ISSUE	-
DMS_39679	41349	N	N	N	1	CUSTOMER ISSUE	-
DMS_39680	41350	N	N	N	1	CUSTOMER ISSUE	-
DMS_39681	41351	N	N	N	1	CUSTOMER ISSUE	-
DMS_39682	41352	N	N	N	1	CUSTOMER ISSUE	-
DMS_39683	41353	N	N	N	1	CUSTOMER ISSUE	-
DMS_39684	41354	N	N	N	1	CUSTOMER ISSUE	-
DMS_39685	41355	N	N	N	1	CUSTOMER ISSUE	-
DMS_39686	41356	N	N	N	1	CUSTOMER ISSUE	-
DMS_39687	41357	N	N	N	1	CUSTOMER ISSUE	-
DMS_39688	41358	N	N	N	1	CUSTOMER ISSUE	-
DMS_39689	41359	N	N	N	1	CUSTOMER ISSUE	-
DMS_39690	41360	N	N	N	1	CUSTOMER ISSUE	-
DMS_39692	41361	N	N	N	1	CUSTOMER ISSUE	-
DMS_39693	41362	N	N	N	1	CUSTOMER ISSUE	-
DMS_39694	41363	N	N	N	1	CUSTOMER ISSUE	-
DMS_39695	41364	N	N	N	1	CUSTOMER ISSUE	-
DMS_39696	41365	N	N	N	1	CUSTOMER ISSUE	-
DMS_39697	41366	N	N	N	1	CUSTOMER ISSUE	-
DMS_39698	41367	N	N	N	1	CUSTOMER ISSUE	-
DMS_39699	41368	N	N	N	1	CUSTOMER ISSUE	-
DMS_39700	41369	N	N	N	1	CUSTOMER ISSUE	-
DMS_39701	41370	N	N	N	1	CUSTOMER ISSUE	-
DMS_39702	41371	N	N	N	1	CUSTOMER ISSUE	-
DMS_39703	41372	N	N	N	1	CUSTOMER ISSUE	-
DMS_39704	41373	N	N	N	1	CUSTOMER ISSUE	-
DMS_39705	41374	N	N	N	1	CUSTOMER ISSUE	-
DMS_39706	41375	N	N	N	1	CUSTOMER ISSUE	-
DMS_39707	41376	N	N	N	1	CUSTOMER ISSUE	-
DMS_39708	41377	N	N	N	1	CUSTOMER ISSUE	-
DMS_39709	41378	N	N	N	1	CUSTOMER ISSUE	-
DMS_39710	41379	N	N	N	1	CUSTOMER ISSUE	-
DMS_39712	41380	N	N	N	1	CUSTOMER ISSUE	-
DMS_39713	41381	N	N	N	1	CUSTOMER ISSUE	-
DMS_39714	41382	N	N	N	1	CUSTOMER ISSUE	-
DMS_39715	41383	N	N	N	1	CUSTOMER ISSUE	-
DMS_39716	41384	N	N	N	1	CUSTOMER ISSUE	-
DMS_39717	41385	N	N	N	1	CUSTOMER ISSUE	-
DMS_39719	41386	N	N	N	1	CUSTOMER ISSUE	-
DMS_39720	41387	N	N	N	1	CUSTOMER ISSUE	-
DMS_39721	41388	N	N	N	1	CUSTOMER ISSUE	-
DMS_39723	41389	N	N	N	1	CUSTOMER ISSUE	-
DMS_39724	41390	N	N	N	1	CUSTOMER ISSUE	-
DMS_39725	41391	N	N	N	1	CUSTOMER ISSUE	-
DMS_39726	41392	N	N	N	1	CUSTOMER ISSUE	-
DMS_39727	41393	N	N	N	1	CUSTOMER ISSUE	-
DMS_39728	41394	N	N	N	1	CUSTOMER ISSUE	-
DMS_39729	41395	N	N	N	1	CUSTOMER ISSUE	-
DMS_39730	41396	N	N	N	1	CUSTOMER ISSUE	-
DMS_39731	41397	N	N	N	1	CUSTOMER ISSUE	-
DMS_39732	41398	N	N	N	1	CUSTOMER ISSUE	-
DMS_39733	41399	N	N	N	1	CUSTOMER ISSUE	-
DMS_39734	41400	N	N	N	1	CUSTOMER ISSUE	-
DMS_39735	41401	N	N	N	1	CUSTOMER ISSUE	-
DMS_39736	41402	N	N	N	1	CUSTOMER ISSUE	-
DMS_39737	41403	N	N	N	1	CUSTOMER ISSUE	-
DMS_39738	41404	N	N	N	1	CUSTOMER ISSUE	-
DMS_39739	41405	N	N	N	1	CUSTOMER ISSUE	-
DMS_39740	41406	N	N	N	1	CUSTOMER ISSUE	-
DMS_39741	41407	N	N	N	1	CUSTOMER ISSUE	-
DMS_39742	41408	N	N	N	1	CUSTOMER ISSUE	-
DMS_39743	41409	N	N	N	1	CUSTOMER ISSUE	-
DMS_39744	41410	N	N	N	1	CUSTOMER ISSUE	-
DMS_39745	41411	N	N	N	1	CUSTOMER ISSUE	-
DMS_39746	41412	N	N	N	1	CUSTOMER ISSUE	-
DMS_39747	41413	N	N	N	1	CUSTOMER ISSUE	-
DMS_39748	41414	N	N	N	1	CUSTOMER ISSUE	-
DMS_39749	41415	N	N	N	1	CUSTOMER ISSUE	-
DMS_39750	41416	N	N	N	1	CUSTOMER ISSUE	-

DMS_39751	41417	N	N	N	1	CUSTOMER ISSUE	-
DMS_39752	41418	N	N	N	1	CUSTOMER ISSUE	-
DMS_39753	41419	N	N	N	1	CUSTOMER ISSUE	-
DMS_39754	41420	N	N	N	1	CUSTOMER ISSUE	-
DMS_39755	41421	N	N	N	1	CUSTOMER ISSUE	-
DMS_39756	41422	N	N	N	1	CUSTOMER ISSUE	-
DMS_39757	41423	N	N	N	1	CUSTOMER ISSUE	-
DMS_39758	41424	N	N	N	1	CUSTOMER ISSUE	-
DMS_39759	41425	N	N	N	1	CUSTOMER ISSUE	-
DMS_39760	41426	N	N	N	1	CUSTOMER ISSUE	-
DMS_39761	41427	N	N	N	1	CUSTOMER ISSUE	-
DMS_39762	41428	N	N	N	1	CUSTOMER ISSUE	-
DMS_39763	41429	N	N	N	1	CUSTOMER ISSUE	-
DMS_39764	41430	N	N	N	1	CUSTOMER ISSUE	-
DMS_39765	41431	N	N	N	1	CUSTOMER ISSUE	-
DMS_39766	41432	N	N	N	1	CUSTOMER ISSUE	-
DMS_39767	41433	N	N	N	1	CUSTOMER ISSUE	-
DMS_39768	41434	N	N	N	1	CUSTOMER ISSUE	-
DMS_39769	41435	N	N	N	1	CUSTOMER ISSUE	-
DMS_39770	41436	N	N	N	1	CUSTOMER ISSUE	-
DMS_39771	41437	N	N	N	1	CUSTOMER ISSUE	-
DMS_39772	41438	N	N	N	1	CUSTOMER ISSUE	-
DMS_39773	41439	N	N	N	1	CUSTOMER ISSUE	-
DMS_39774	41440	N	N	N	1	CUSTOMER ISSUE	-
DMS_39775	41441	N	N	N	1	CUSTOMER ISSUE	-
DMS_39776	41442	N	N	N	1	CUSTOMER ISSUE	-
DMS_39777	41443	N	N	N	1	CUSTOMER ISSUE	-
DMS_39778	41444	N	N	N	1	CUSTOMER ISSUE	-
DMS_39779	41445	N	N	N	1	CUSTOMER ISSUE	-
DMS_39780	41446	N	N	N	1	CUSTOMER ISSUE	-
DMS_39781	41447	N	N	N	1	CUSTOMER ISSUE	-
DMS_39782	41448	N	N	N	1	CUSTOMER ISSUE	-
DMS_39783	41449	N	N	N	1	CUSTOMER ISSUE	-
DMS_39784	41450	N	N	N	1	CUSTOMER ISSUE	-
DMS_39785	41451	N	N	N	2	CUSTOMER ISSUE	-
DMS_39786	41452	N	N	N	1	CUSTOMER ISSUE	-
DMS_39787	41453	N	N	N	1	CUSTOMER ISSUE	-
DMS_39789	41454	N	N	N	2	CUSTOMER ISSUE	-
DMS_39790	41455	N	N	N	1	CUSTOMER ISSUE	-
DMS_39791	41456	N	N	N	1	CUSTOMER ISSUE	-
DMS_39792	41457	N	N	N	1	CUSTOMER ISSUE	-
DMS_39793	41458	N	N	N	1	CUSTOMER ISSUE	-
DMS_39794	41459	N	N	N	1	CUSTOMER ISSUE	-
DMS_39795	41460	N	N	N	1	CUSTOMER ISSUE	-
DMS_39796	41461	N	N	N	1	CUSTOMER ISSUE	-
DMS_39797	41462	N	N	N	1	CUSTOMER ISSUE	-
DMS_39798	41463	N	N	N	1	CUSTOMER ISSUE	-
DMS_39799	41464	N	N	N	1	CUSTOMER ISSUE	-
DMS_39800	41465	N	N	N	1	CUSTOMER ISSUE	-
DMS_39801	41466	N	N	N	1	CUSTOMER ISSUE	-
DMS_39802	41467	N	N	N	1	CUSTOMER ISSUE	-
DMS_39803	41468	N	N	N	1	CUSTOMER ISSUE	-
DMS_39804	41469	N	N	N	1	CUSTOMER ISSUE	-
DMS_39805	41470	N	N	N	1	CUSTOMER ISSUE	-
DMS_39806	41471	N	N	N	1	CUSTOMER ISSUE	-
DMS_39807	41472	N	N	N	1	CUSTOMER ISSUE	-
DMS_39808	41473	N	N	N	1	CUSTOMER ISSUE	-
DMS_39809	41474	N	N	N	2	CUSTOMER ISSUE	-
DMS_39810	41475	N	N	N	1	CUSTOMER ISSUE	-
DMS_39811	41476	N	N	N	1	CUSTOMER ISSUE	-
DMS_39812	41477	N	N	N	1	CUSTOMER ISSUE	-
DMS_39813	41478	N	N	N	1	CUSTOMER ISSUE	-
DMS_39814	41479	N	N	N	1	CUSTOMER ISSUE	-
DMS_39815	41480	N	N	N	1	CUSTOMER ISSUE	-
DMS_39816	41481	N	N	N	1	CUSTOMER ISSUE	-
DMS_39817	41482	N	N	N	1	CUSTOMER ISSUE	-
DMS_39818	41483	N	N	N	1	CUSTOMER ISSUE	-
DMS_39819	41484	N	N	N	1	CUSTOMER ISSUE	-
DMS_39820	41485	N	N	N	1	CUSTOMER ISSUE	-
DMS_39821	41486	N	N	N	1	CUSTOMER ISSUE	-
DMS_39822	41487	N	N	N	1	CUSTOMER ISSUE	-
DMS_39823	41488	N	N	N	1	CUSTOMER ISSUE	-
DMS_39824	41489	N	N	N	1	CUSTOMER ISSUE	-
DMS_39825	41490	N	N	N	1	CUSTOMER ISSUE	-
DMS_39826	41491	N	N	N	1	CUSTOMER ISSUE	-
DMS_39827	41492	N	N	N	1	CUSTOMER ISSUE	-
DMS_39828	41493	N	N	N	1	CUSTOMER ISSUE	-
DMS_39831	41494	N	N	N	1	CUSTOMER ISSUE	-
DMS_39832	41495	N	N	N	1	CUSTOMER ISSUE	-
DMS_39833	41496	N	N	N	1	CUSTOMER ISSUE	-

DMS_39834	41497	N	N	N	1	CUSTOMER ISSUE	-
DMS_39835	41498	N	N	N	1	CUSTOMER ISSUE	-
DMS_39836	41499	N	N	N	1	CUSTOMER ISSUE	-
DMS_39838	41500	N	N	N	1	CUSTOMER ISSUE	-
DMS_39839	41501	N	N	N	1	CUSTOMER ISSUE	-
DMS_39840	41502	N	N	N	1	CUSTOMER ISSUE	-
DMS_39841	41503	N	N	N	1	CUSTOMER ISSUE	-
DMS_39842	41504	N	N	N	1	CUSTOMER ISSUE	-
DMS_39843	41505	N	N	N	1	CUSTOMER ISSUE	-
DMS_39844	41506	N	N	N	1	CUSTOMER ISSUE	-
DMS_39845	41507	N	N	N	1	CUSTOMER ISSUE	-
DMS_39846	41508	N	N	N	1	CUSTOMER ISSUE	-
DMS_39847	41509	N	N	N	1	CUSTOMER ISSUE	-
DMS_39848	41510	N	N	N	1	CUSTOMER ISSUE	-
DMS_39849	41511	N	N	N	1	CUSTOMER ISSUE	-
DMS_39850	41512	N	N	N	1	CUSTOMER ISSUE	-
DMS_39851	41513	N	N	N	1	CUSTOMER ISSUE	-
DMS_39852	41514	N	N	N	1	CUSTOMER ISSUE	-
DMS_39853	41515	N	N	N	1	CUSTOMER ISSUE	-
DMS_39854	41516	N	N	N	1	CUSTOMER ISSUE	-
DMS_39855	41517	N	N	N	1	CUSTOMER ISSUE	-
DMS_39856	41518	N	N	N	1	CUSTOMER ISSUE	-
DMS_39857	41519	N	N	N	1	CUSTOMER ISSUE	-
DMS_39858	41520	N	N	N	1	CUSTOMER ISSUE	-
DMS_39859	41521	N	N	N	1	CUSTOMER ISSUE	-
DMS_39860	41522	N	N	N	1	CUSTOMER ISSUE	-
DMS_39861	41523	N	N	N	1	CUSTOMER ISSUE	-
DMS_39862	41524	N	N	N	1	CUSTOMER ISSUE	-
DMS_39863	41525	N	N	N	1	CUSTOMER ISSUE	-
DMS_39864	41526	N	N	N	1	CUSTOMER ISSUE	-
DMS_39865	41527	N	N	N	1	CUSTOMER ISSUE	-
DMS_39866	41528	N	N	N	1	CUSTOMER ISSUE	-
DMS_39867	41529	N	N	N	1	CUSTOMER ISSUE	-
DMS_39868	41530	N	N	N	1	CUSTOMER ISSUE	-
DMS_39869	41531	N	N	N	1	CUSTOMER ISSUE	-
DMS_39870	41532	N	N	N	1	CUSTOMER ISSUE	-
DMS_39871	41533	N	N	N	1	CUSTOMER ISSUE	-
DMS_39872	41534	N	N	N	1	CUSTOMER ISSUE	-
DMS_39873	41535	N	N	N	1	CUSTOMER ISSUE	-
DMS_39874	41536	N	N	N	1	CUSTOMER ISSUE	-
DMS_39875	41537	N	N	N	1	CUSTOMER ISSUE	-
DMS_39876	41538	N	N	N	1	CUSTOMER ISSUE	-
DMS_39877	41539	N	N	N	1	CUSTOMER ISSUE	-
DMS_39878	41540	N	N	N	1	CUSTOMER ISSUE	-
DMS_39879	41541	N	N	N	1	CUSTOMER ISSUE	-
DMS_39880	41542	N	N	N	1	CUSTOMER ISSUE	-
DMS_39881	41543	N	N	N	1	CUSTOMER ISSUE	-
DMS_39882	41544	N	N	N	1	CUSTOMER ISSUE	-
DMS_39883	41545	N	N	N	1	CUSTOMER ISSUE	-
DMS_39884	41546	N	N	N	1	CUSTOMER ISSUE	-
DMS_39885	41547	N	N	N	1	CUSTOMER ISSUE	-
DMS_39886	41548	N	N	N	1	CUSTOMER ISSUE	-
DMS_39887	41549	N	N	N	1	CUSTOMER ISSUE	-
DMS_39888	41550	N	N	N	1	CUSTOMER ISSUE	-
DMS_39889	41551	N	N	N	1	CUSTOMER ISSUE	-
DMS_39890	41552	N	N	N	1	CUSTOMER ISSUE	-
DMS_39891	41553	N	N	N	1	CUSTOMER ISSUE	-
DMS_39892	41554	N	N	N	1	CUSTOMER ISSUE	-
DMS_39893	41555	N	N	N	1	CUSTOMER ISSUE	-
DMS_39894	41556	N	N	N	1	CUSTOMER ISSUE	-
DMS_39895	41557	N	N	N	1	CUSTOMER ISSUE	-
DMS_39896	41558	N	N	N	1	CUSTOMER ISSUE	-
DMS_39897	41559	N	N	N	1	CUSTOMER ISSUE	-
DMS_39898	41560	N	N	N	1	CUSTOMER ISSUE	-
DMS_39899	41561	N	N	N	1	CUSTOMER ISSUE	-
DMS_39900	41562	N	N	N	1	CUSTOMER ISSUE	-
DMS_39901	41563	N	N	N	1	CUSTOMER ISSUE	-
DMS_39902	41564	N	N	N	1	CUSTOMER ISSUE	-
DMS_39903	41565	N	N	N	1	CUSTOMER ISSUE	-
DMS_39904	41566	N	N	N	1	CUSTOMER ISSUE	-
DMS_39905	41567	N	N	N	1	CUSTOMER ISSUE	-
DMS_39906	41568	N	N	N	1	CUSTOMER ISSUE	-
DMS_39907	41569	N	N	N	1	CUSTOMER ISSUE	-
DMS_39908	41570	N	N	N	1	CUSTOMER ISSUE	-
DMS_39909	41571	N	N	N	1	CUSTOMER ISSUE	-
DMS_39910	41572	N	N	N	1	CUSTOMER ISSUE	-
DMS_39911	41573	N	N	N	1	CUSTOMER ISSUE	-
DMS_39912	41574	N	N	N	1	CUSTOMER ISSUE	-
DMS_39913	41575	N	N	N	1	CUSTOMER ISSUE	-
DMS_39914	41576	N	N	N	1	CUSTOMER ISSUE	-

DMS_39915	41577	N	N	N	1	CUSTOMER ISSUE	-
DMS_39916	41578	N	N	N	1	CUSTOMER ISSUE	-
DMS_39917	41579	N	N	N	1	CUSTOMER ISSUE	-
DMS_39918	41580	N	N	N	1	CUSTOMER ISSUE	-
DMS_39919	41581	N	N	N	1	CUSTOMER ISSUE	-
DMS_39920	41582	N	N	N	1	CUSTOMER ISSUE	-
DMS_39921	41583	N	N	N	1	CUSTOMER ISSUE	-
DMS_39922	41584	N	N	N	1	CUSTOMER ISSUE	-
DMS_39923	41585	N	N	N	1	CUSTOMER ISSUE	-
DMS_39924	41586	N	N	N	1	CUSTOMER ISSUE	-
DMS_39925	41587	N	N	N	1	CUSTOMER ISSUE	-
DMS_39927	41588	N	N	N	1	CUSTOMER ISSUE	-
DMS_39928	41589	N	N	N	1	CUSTOMER ISSUE	-
DMS_39929	41590	N	N	N	1	CUSTOMER ISSUE	-
DMS_39930	41591	N	N	N	1	CUSTOMER ISSUE	-
DMS_39931	41592	N	N	N	1	CUSTOMER ISSUE	-
DMS_39932	41593	N	N	N	1	CUSTOMER ISSUE	-
DMS_39933	41594	N	N	N	1	CUSTOMER ISSUE	-
DMS_39934	41595	N	N	N	1	CUSTOMER ISSUE	-
DMS_39935	41596	N	N	N	1	CUSTOMER ISSUE	-
DMS_39936	41597	N	N	N	1	CUSTOMER ISSUE	-
DMS_39937	41598	N	N	N	1	CUSTOMER ISSUE	-
DMS_39938	41599	N	N	N	1	CUSTOMER ISSUE	-
DMS_39939	41600	N	N	N	1	CUSTOMER ISSUE	-
DMS_39940	41601	N	N	N	1	CUSTOMER ISSUE	-
DMS_39941	41602	N	N	N	1	CUSTOMER ISSUE	-
DMS_39942	41603	N	N	N	1	CUSTOMER ISSUE	-
DMS_39943	41604	N	N	N	1	CUSTOMER ISSUE	-
DMS_39944	41605	N	N	N	1	CUSTOMER ISSUE	-
DMS_39945	41606	N	N	N	1	CUSTOMER ISSUE	-
DMS_39946	41607	N	N	N	2	CUSTOMER ISSUE	-
DMS_39947	41608	N	N	N	1	CUSTOMER ISSUE	-
DMS_39948	41609	N	N	N	1	CUSTOMER ISSUE	-
DMS_39949	41610	N	N	N	1	CUSTOMER ISSUE	-
DMS_39950	41611	N	N	N	1	CUSTOMER ISSUE	-
DMS_39951	41612	N	N	N	1	CUSTOMER ISSUE	-
DMS_39952	41613	N	N	N	1	CUSTOMER ISSUE	-
DMS_39953	41614	N	N	N	1	CUSTOMER ISSUE	-
DMS_39954	41615	N	N	N	1	CUSTOMER ISSUE	-
DMS_39955	41616	N	N	N	1	CUSTOMER ISSUE	-
DMS_39956	41617	N	N	N	1	CUSTOMER ISSUE	-
DMS_39957	41618	N	N	N	1	CUSTOMER ISSUE	-
DMS_39958	41619	N	N	N	1	CUSTOMER ISSUE	-
DMS_39959	41620	N	N	N	1	CUSTOMER ISSUE	-
DMS_39960	41621	N	N	N	1	CUSTOMER ISSUE	-
DMS_39961	41622	N	N	N	1	CUSTOMER ISSUE	-
DMS_39962	41623	N	N	N	1	CUSTOMER ISSUE	-
DMS_39963	41624	N	N	N	1	CUSTOMER ISSUE	-
DMS_39964	41625	N	N	N	1	CUSTOMER ISSUE	-
DMS_39965	41626	N	N	N	1	CUSTOMER ISSUE	-
DMS_39966	41627	N	N	N	1	CUSTOMER ISSUE	-
DMS_39967	41628	N	N	N	1	CUSTOMER ISSUE	-
DMS_39968	41629	N	N	N	1	CUSTOMER ISSUE	-
DMS_39969	41630	N	N	N	1	CUSTOMER ISSUE	-
DMS_39970	41631	N	N	N	1	CUSTOMER ISSUE	-
DMS_39971	41632	N	N	N	1	CUSTOMER ISSUE	-
DMS_39972	41633	N	N	N	1	CUSTOMER ISSUE	-
DMS_39973	41634	N	N	N	1	CUSTOMER ISSUE	-
DMS_39974	41635	N	N	N	1	CUSTOMER ISSUE	-
DMS_39975	41636	N	N	N	1	CUSTOMER ISSUE	-
DMS_39976	41637	N	N	N	1	CUSTOMER ISSUE	-
DMS_39977	41638	N	N	N	1	CUSTOMER ISSUE	-
DMS_39978	41639	N	N	N	1	CUSTOMER ISSUE	-
DMS_39979	41640	N	N	N	1	CUSTOMER ISSUE	-
DMS_39980	41641	N	N	N	1	CUSTOMER ISSUE	-
DMS_39981	41642	N	N	N	1	CUSTOMER ISSUE	-
DMS_39982	41643	N	N	N	1	CUSTOMER ISSUE	-
DMS_39983	41644	N	N	N	1	CUSTOMER ISSUE	-
DMS_39984	41645	N	N	N	1	CUSTOMER ISSUE	-
DMS_39985	41646	N	N	N	1	CUSTOMER ISSUE	-
DMS_39986	41647	N	N	N	1	CUSTOMER ISSUE	-
DMS_39987	41648	N	N	N	1	CUSTOMER ISSUE	-
DMS_39988	41649	N	N	N	1	CUSTOMER ISSUE	-
DMS_39989	41650	N	N	N	1	CUSTOMER ISSUE	-
DMS_39990	41651	N	N	N	1	CUSTOMER ISSUE	-
DMS_39991	41652	N	N	N	1	CUSTOMER ISSUE	-
DMS_39992	41653	N	N	N	1	CUSTOMER ISSUE	-
DMS_39993	41654	N	N	N	1	CUSTOMER ISSUE	-
DMS_39994	41655	N	N	N	1	CUSTOMER ISSUE	-
DMS_39995	41656	N	N	N	1	CUSTOMER ISSUE	-

DMS_39996	41657	N	N	N	1	CUSTOMER ISSUE	-
DMS_39997	41658	N	N	N	1	CUSTOMER ISSUE	-
DMS_39998	41659	N	N	N	1	CUSTOMER ISSUE	-
DMS_39999	41660	N	N	N	1	CUSTOMER ISSUE	-
DMS_40000	41661	N	N	N	1	CUSTOMER ISSUE	-
DMS_40001	41662	N	N	N	1	CUSTOMER ISSUE	-
DMS_40002	41663	N	N	N	1	CUSTOMER ISSUE	-
DMS_40003	41664	N	N	N	1	CUSTOMER ISSUE	-
DMS_40004	41665	N	N	N	1	CUSTOMER ISSUE	-
DMS_40005	41666	N	N	N	1	CUSTOMER ISSUE	-
DMS_40006	41667	N	N	N	1	CUSTOMER ISSUE	-
DMS_40007	41668	N	N	N	1	CUSTOMER ISSUE	-
DMS_40008	41669	N	N	N	1	CUSTOMER ISSUE	-
DMS_40009	41670	N	N	N	1	CUSTOMER ISSUE	-
DMS_40010	41671	N	N	N	1	CUSTOMER ISSUE	-
DMS_40011	41672	N	N	N	1	CUSTOMER ISSUE	-
DMS_40012	41673	N	N	N	1	CUSTOMER ISSUE	-
DMS_40013	41674	N	N	N	1	CUSTOMER ISSUE	-
DMS_40014	41675	N	N	N	1	CUSTOMER ISSUE	-
DMS_40015	41676	N	N	N	1	CUSTOMER ISSUE	-
DMS_40016	41677	N	N	N	1	CUSTOMER ISSUE	-
DMS_40017	41678	N	N	N	1	CUSTOMER ISSUE	-
DMS_40018	41679	N	N	N	1	CUSTOMER ISSUE	-
DMS_40019	41680	N	N	N	1	CUSTOMER ISSUE	-
DMS_40020	41681	N	N	N	1	CUSTOMER ISSUE	-
DMS_40021	41682	N	N	N	1	CUSTOMER ISSUE	-
DMS_40022	41683	N	N	N	1	CUSTOMER ISSUE	-
DMS_40023	41684	N	N	N	1	CUSTOMER ISSUE	-
DMS_40024	41685	N	N	N	1	CUSTOMER ISSUE	-
DMS_40025	41686	N	N	N	1	CUSTOMER ISSUE	-
DMS_40026	41687	N	N	N	1	CUSTOMER ISSUE	-
DMS_40027	41688	N	N	N	1	CUSTOMER ISSUE	-
DMS_40028	41689	N	N	N	1	CUSTOMER ISSUE	-
DMS_40029	41690	N	N	N	1	CUSTOMER ISSUE	-
DMS_40030	41691	N	N	N	1	CUSTOMER ISSUE	-
DMS_40031	41692	N	N	N	1	CUSTOMER ISSUE	-
DMS_40032	41693	N	N	N	1	CUSTOMER ISSUE	-
DMS_40033	41694	N	N	N	1	CUSTOMER ISSUE	-
DMS_40034	41695	N	N	N	1	CUSTOMER ISSUE	-
DMS_40035	41696	N	N	N	1	CUSTOMER ISSUE	-
DMS_40036	41697	N	N	N	1	CUSTOMER ISSUE	-
DMS_40037	41698	N	N	N	1	CUSTOMER ISSUE	-
DMS_40038	41699	N	N	N	1	CUSTOMER ISSUE	-
DMS_40039	41700	N	N	N	1	CUSTOMER ISSUE	-
DMS_40040	41701	N	N	N	1	CUSTOMER ISSUE	-
DMS_40041	41702	N	N	N	1	CUSTOMER ISSUE	-
DMS_40042	41703	N	N	N	1	CUSTOMER ISSUE	-
DMS_40043	41704	N	N	N	1	CUSTOMER ISSUE	-
DMS_40044	41705	N	N	N	1	CUSTOMER ISSUE	-
DMS_40045	41706	N	N	N	1	CUSTOMER ISSUE	-
DMS_40046	41707	N	N	N	1	CUSTOMER ISSUE	-
DMS_40047	41708	N	N	N	1	CUSTOMER ISSUE	-
DMS_40048	41709	N	N	N	1	CUSTOMER ISSUE	-
DMS_40049	41710	N	N	N	1	CUSTOMER ISSUE	-
DMS_40050	41711	N	N	N	1	CUSTOMER ISSUE	-
DMS_40051	41712	N	N	N	1	CUSTOMER ISSUE	-
DMS_40052	41713	N	N	N	1	CUSTOMER ISSUE	-
DMS_40053	41714	N	N	N	1	CUSTOMER ISSUE	-
DMS_40054	41715	N	N	N	1	CUSTOMER ISSUE	-
DMS_40055	41716	N	N	N	1	CUSTOMER ISSUE	-
DMS_40056	41717	N	N	N	1	CUSTOMER ISSUE	-
DMS_40057	41718	N	N	N	1	CUSTOMER ISSUE	-
DMS_40058	41719	N	N	N	1	CUSTOMER ISSUE	-
DMS_40059	41720	N	N	N	1	CUSTOMER ISSUE	-
DMS_40060	41721	N	N	N	1	CUSTOMER ISSUE	-
DMS_40061	41722	N	N	N	1	CUSTOMER ISSUE	-
DMS_40062	41723	N	N	N	1	CUSTOMER ISSUE	-
DMS_40063	41724	N	N	N	1	CUSTOMER ISSUE	-
DMS_40064	41725	N	N	N	1	CUSTOMER ISSUE	-
DMS_40065	41726	N	N	N	1	CUSTOMER ISSUE	-
DMS_40067	41727	N	N	N	1	CUSTOMER ISSUE	-
DMS_40068	41728	N	N	N	2	CUSTOMER ISSUE	-
DMS_40069	41729	N	N	N	1	CUSTOMER ISSUE	-
DMS_40070	41730	N	N	N	1	CUSTOMER ISSUE	-
DMS_40071	41731	N	N	N	1	CUSTOMER ISSUE	-
DMS_40072	41732	N	N	N	1	CUSTOMER ISSUE	-
DMS_40073	41733	N	N	N	1	CUSTOMER ISSUE	-
DMS_40074	41734	N	N	N	1	CUSTOMER ISSUE	-
DMS_40075	41735	N	N	N	1	CUSTOMER ISSUE	-
DMS_40076	41736	N	N	N	1	CUSTOMER ISSUE	-

DMS_40077	41737	N	N	N	1	CUSTOMER ISSUE	-
DMS_40078	41738	N	N	N	1	CUSTOMER ISSUE	-
DMS_40079	41739	N	N	N	1	CUSTOMER ISSUE	-
DMS_40080	41740	N	N	N	1	CUSTOMER ISSUE	-
DMS_40081	41741	N	N	N	1	CUSTOMER ISSUE	-
DMS_40082	41742	N	N	N	1	CUSTOMER ISSUE	-
DMS_40083	41743	N	N	N	1	CUSTOMER ISSUE	-
DMS_40084	41744	N	N	N	1	CUSTOMER ISSUE	-
DMS_40085	41745	N	N	N	1	CUSTOMER ISSUE	-
DMS_40086	41746	N	N	N	1	CUSTOMER ISSUE	-
DMS_40087	41747	N	N	N	1	CUSTOMER ISSUE	-
DMS_40088	41748	N	N	N	1	CUSTOMER ISSUE	-
DMS_40089	41749	N	N	N	1	CUSTOMER ISSUE	-
DMS_40090	41750	N	N	N	1	CUSTOMER ISSUE	-
DMS_40091	41751	N	N	N	1	CUSTOMER ISSUE	-
DMS_40092	41752	N	N	N	1	CUSTOMER ISSUE	-
DMS_40093	41753	N	N	N	1	CUSTOMER ISSUE	-
DMS_40094	41754	N	N	N	1	CUSTOMER ISSUE	-
DMS_40095	41755	N	N	N	1	CUSTOMER ISSUE	-
DMS_40096	41756	N	N	N	1	CUSTOMER ISSUE	-
DMS_40097	41757	N	N	N	1	CUSTOMER ISSUE	-
DMS_40098	41758	N	N	N	1	CUSTOMER ISSUE	-
DMS_40099	41759	N	N	N	1	CUSTOMER ISSUE	-
DMS_40100	41760	N	N	N	1	CUSTOMER ISSUE	-
DMS_40101	41761	N	N	N	1	CUSTOMER ISSUE	-
DMS_40102	41762	N	N	N	1	CUSTOMER ISSUE	-
DMS_40103	41763	N	N	N	1	CUSTOMER ISSUE	-
DMS_40104	41764	N	N	N	1	CUSTOMER ISSUE	-
DMS_40105	41765	N	N	N	1	CUSTOMER ISSUE	-
DMS_40106	41766	N	N	N	1	CUSTOMER ISSUE	-
DMS_40107	41767	N	N	N	1	CUSTOMER ISSUE	-
DMS_40108	41768	N	N	N	1	CUSTOMER ISSUE	-
DMS_40109	41769	N	N	N	1	CUSTOMER ISSUE	-
DMS_40110	41770	N	N	N	1	CUSTOMER ISSUE	-
DMS_40111	41771	N	N	N	1	CUSTOMER ISSUE	-
DMS_40112	41772	N	N	N	1	CUSTOMER ISSUE	-
DMS_40113	41773	N	N	N	1	CUSTOMER ISSUE	-
DMS_40114	41774	N	N	N	1	CUSTOMER ISSUE	-
DMS_40115	41775	N	N	N	1	CUSTOMER ISSUE	-
DMS_40116	41776	N	N	N	1	CUSTOMER ISSUE	-
DMS_40118	41777	N	N	N	1	CUSTOMER ISSUE	-
DMS_40119	41778	N	N	N	1	CUSTOMER ISSUE	-
DMS_40120	41779	N	N	N	1	CUSTOMER ISSUE	-
DMS_40121	41780	N	N	N	1	CUSTOMER ISSUE	-
DMS_40122	41781	N	N	N	1	CUSTOMER ISSUE	-
DMS_40123	41782	N	N	N	1	CUSTOMER ISSUE	-
DMS_40124	41783	N	N	N	1	CUSTOMER ISSUE	-
DMS_40125	41784	N	N	N	1	CUSTOMER ISSUE	-
DMS_40126	41785	N	N	N	1	CUSTOMER ISSUE	-
DMS_40127	41786	N	N	N	1	CUSTOMER ISSUE	-
DMS_40128	41787	N	N	N	1	CUSTOMER ISSUE	-
DMS_40129	41788	N	N	N	1	CUSTOMER ISSUE	-
DMS_40130	41789	N	N	N	1	CUSTOMER ISSUE	-
DMS_40131	41790	N	N	N	1	CUSTOMER ISSUE	-
DMS_40132	41791	N	N	N	1	CUSTOMER ISSUE	-
DMS_40133	41792	N	N	N	1	CUSTOMER ISSUE	-
DMS_40134	41793	N	N	N	1	CUSTOMER ISSUE	-
DMS_40135	41794	N	N	N	1	CUSTOMER ISSUE	-
DMS_40136	41795	N	N	N	1	CUSTOMER ISSUE	-
DMS_40137	41796	N	N	N	1	CUSTOMER ISSUE	-
DMS_40138	41797	N	N	N	1	CUSTOMER ISSUE	-
DMS_40139	41798	N	N	N	1	CUSTOMER ISSUE	-
DMS_40140	41799	N	N	N	1	CUSTOMER ISSUE	-
DMS_40141	41800	N	N	N	1	CUSTOMER ISSUE	-
DMS_40142	41801	N	N	N	1	CUSTOMER ISSUE	-
DMS_40143	41802	N	N	N	1	CUSTOMER ISSUE	-
DMS_40144	41803	N	N	N	1	CUSTOMER ISSUE	-
DMS_40145	41804	N	N	N	1	CUSTOMER ISSUE	-
DMS_40146	41805	N	N	N	1	CUSTOMER ISSUE	-
DMS_40147	41806	N	N	N	1	CUSTOMER ISSUE	-
DMS_40148	41807	N	N	N	1	CUSTOMER ISSUE	-
DMS_40149	41808	N	N	N	1	CUSTOMER ISSUE	-
DMS_40150	41809	N	N	N	1	CUSTOMER ISSUE	-
DMS_40151	41810	N	N	N	1	CUSTOMER ISSUE	-
DMS_40152	41811	N	N	N	1	CUSTOMER ISSUE	-
DMS_40153	41812	N	N	N	1	CUSTOMER ISSUE	-
DMS_40154	41813	N	N	N	1	CUSTOMER ISSUE	-
DMS_40155	41814	N	N	N	1	CUSTOMER ISSUE	-
DMS_40156	41815	N	N	N	1	CUSTOMER ISSUE	-
DMS_40157	41816	N	N	N	1	CUSTOMER ISSUE	-

DMS_40158	41817	N	N	N	1	CUSTOMER ISSUE	-
DMS_40159	41818	N	N	N	1	CUSTOMER ISSUE	-
DMS_40160	41819	N	N	N	1	CUSTOMER ISSUE	-
DMS_40161	41820	N	N	N	1	CUSTOMER ISSUE	-
DMS_40162	41821	N	N	N	1	CUSTOMER ISSUE	-
DMS_40163	41822	N	N	N	1	CUSTOMER ISSUE	-
DMS_40164	41823	N	N	N	1	CUSTOMER ISSUE	-
DMS_40165	41824	N	N	N	1	CUSTOMER ISSUE	-
DMS_40166	41825	N	N	N	1	CUSTOMER ISSUE	-
DMS_40167	41826	N	N	N	1	CUSTOMER ISSUE	-
DMS_40168	41827	N	N	N	1	CUSTOMER ISSUE	-
DMS_40169	41828	N	N	N	1	CUSTOMER ISSUE	-
DMS_40170	41829	N	N	N	1	CUSTOMER ISSUE	-
DMS_40171	41830	N	N	N	1	CUSTOMER ISSUE	-
DMS_40172	41831	N	N	N	1	CUSTOMER ISSUE	-
DMS_40173	41832	N	N	N	1	CUSTOMER ISSUE	-
DMS_40174	41833	N	N	N	1	CUSTOMER ISSUE	-
DMS_40175	41834	N	N	N	1	CUSTOMER ISSUE	-
DMS_40176	41835	N	N	N	1	CUSTOMER ISSUE	-
DMS_40177	41836	N	N	N	1	CUSTOMER ISSUE	-
DMS_40178	41837	N	N	N	1	CUSTOMER ISSUE	-
DMS_40179	41838	N	N	N	1	CUSTOMER ISSUE	-
DMS_40180	41839	N	N	N	1	CUSTOMER ISSUE	-
DMS_40181	41840	N	N	N	1	CUSTOMER ISSUE	-
DMS_40182	41841	N	N	N	1	CUSTOMER ISSUE	-
DMS_40183	41842	N	N	N	1	CUSTOMER ISSUE	-
DMS_40184	41843	N	N	N	1	CUSTOMER ISSUE	-
DMS_40185	41844	N	N	N	1	CUSTOMER ISSUE	-
DMS_40187	41845	N	N	N	1	CUSTOMER ISSUE	-
DMS_40189	41846	N	N	N	1	CUSTOMER ISSUE	-
DMS_40190	41847	N	N	N	1	CUSTOMER ISSUE	-
DMS_40191	41848	N	N	N	1	CUSTOMER ISSUE	-
DMS_40192	41849	N	N	N	1	CUSTOMER ISSUE	-
DMS_40193	41850	N	N	N	1	CUSTOMER ISSUE	-
DMS_40194	41851	N	N	N	1	CUSTOMER ISSUE	-
DMS_40195	41852	N	N	N	1	CUSTOMER ISSUE	-
DMS_40196	41853	N	N	N	1	CUSTOMER ISSUE	-
DMS_40197	41854	N	N	N	1	CUSTOMER ISSUE	-
DMS_40198	41855	N	N	N	1	CUSTOMER ISSUE	-
DMS_40199	41856	N	N	N	1	CUSTOMER ISSUE	-
DMS_40200	41857	N	N	N	1	CUSTOMER ISSUE	-
DMS_40201	41858	N	N	N	1	CUSTOMER ISSUE	-
DMS_40202	41859	N	N	N	1	CUSTOMER ISSUE	-
DMS_40203	41860	N	N	N	1	CUSTOMER ISSUE	-
DMS_40204	41861	N	N	N	1	CUSTOMER ISSUE	-
DMS_40205	41862	N	N	N	1	CUSTOMER ISSUE	-
DMS_40206	41863	N	N	N	1	CUSTOMER ISSUE	-
DMS_40207	41864	N	N	N	1	CUSTOMER ISSUE	-
DMS_40208	41865	N	N	N	1	CUSTOMER ISSUE	-
DMS_40209	41866	N	N	N	1	CUSTOMER ISSUE	-
DMS_40210	41867	N	N	N	1	CUSTOMER ISSUE	-
DMS_40211	41868	N	N	N	1	CUSTOMER ISSUE	-
DMS_40212	41869	N	N	N	1	CUSTOMER ISSUE	-
DMS_40213	41870	N	N	N	1	CUSTOMER ISSUE	-
DMS_40214	41871	N	N	N	1	CUSTOMER ISSUE	-
DMS_40215	41872	N	N	N	1	CUSTOMER ISSUE	-
DMS_40216	41873	N	N	N	1	CUSTOMER ISSUE	-
DMS_40217	41874	N	N	N	1	CUSTOMER ISSUE	-
DMS_40218	41875	N	N	N	1	CUSTOMER ISSUE	-
DMS_40219	41876	N	N	N	1	CUSTOMER ISSUE	-
DMS_40220	41877	N	N	N	1	CUSTOMER ISSUE	-
DMS_40221	41878	N	N	N	1	CUSTOMER ISSUE	-
DMS_40222	41879	N	N	N	1	CUSTOMER ISSUE	-
DMS_40223	41880	N	N	N	1	CUSTOMER ISSUE	-
DMS_40224	41881	N	N	N	1	CUSTOMER ISSUE	-
DMS_40225	41882	N	N	N	1	CUSTOMER ISSUE	-
DMS_40226	41883	N	N	N	1	CUSTOMER ISSUE	-
DMS_40227	41884	N	N	N	1	CUSTOMER ISSUE	-
DMS_40228	41885	N	N	N	1	CUSTOMER ISSUE	-
DMS_40229	41886	N	N	N	1	CUSTOMER ISSUE	-
DMS_40230	41887	N	N	N	1	CUSTOMER ISSUE	-
DMS_40231	41888	N	N	N	1	CUSTOMER ISSUE	-
DMS_40232	41889	N	N	N	1	CUSTOMER ISSUE	-
DMS_40233	41890	N	N	N	1	CUSTOMER ISSUE	-
DMS_40234	41891	N	N	N	1	CUSTOMER ISSUE	-
DMS_40235	41892	N	N	N	1	CUSTOMER ISSUE	-
DMS_40236	41893	N	N	N	1	CUSTOMER ISSUE	-
DMS_40237	41894	N	N	N	1	CUSTOMER ISSUE	-
DMS_40238	41895	N	N	N	1	CUSTOMER ISSUE	-
DMS_40239	41896	N	N	N	1	CUSTOMER ISSUE	-

DMS_40240	41897	N	N	N	1	CUSTOMER ISSUE	-
DMS_40241	41898	N	N	N	1	CUSTOMER ISSUE	-
DMS_40242	41899	N	N	N	1	CUSTOMER ISSUE	-
DMS_40243	41900	N	N	N	1	CUSTOMER ISSUE	-
DMS_40244	41901	N	N	N	1	CUSTOMER ISSUE	-
DMS_40245	41902	N	N	N	1	CUSTOMER ISSUE	-
DMS_40246	41903	N	N	N	1	CUSTOMER ISSUE	-
DMS_40247	41904	N	N	N	1	CUSTOMER ISSUE	-
DMS_40248	41905	N	N	N	1	CUSTOMER ISSUE	-
DMS_40249	41906	N	N	N	1	CUSTOMER ISSUE	-
DMS_40250	41907	N	N	N	1	CUSTOMER ISSUE	-
DMS_40251	41908	N	N	N	1	CUSTOMER ISSUE	-
DMS_40252	41909	N	N	N	1	CUSTOMER ISSUE	-
DMS_40253	41910	N	N	N	1	CUSTOMER ISSUE	-
DMS_40254	41911	N	N	N	1	CUSTOMER ISSUE	-
DMS_40255	41912	N	N	N	1	CUSTOMER ISSUE	-
DMS_40256	41913	N	N	N	2	CUSTOMER ISSUE	-
DMS_40292	41914	N	N	N	1	CUSTOMER ISSUE	-
DMS_40293	41915	N	N	N	1	CUSTOMER ISSUE	-
DMS_40294	41916	N	N	N	1	CUSTOMER ISSUE	-
DMS_40295	41917	N	N	N	1	CUSTOMER ISSUE	-
DMS_40296	41918	N	N	N	1	CUSTOMER ISSUE	-
DMS_40298	41919	N	N	N	1	CUSTOMER ISSUE	-
DMS_40299	41920	N	N	N	1	CUSTOMER ISSUE	-
DMS_40300	41921	N	N	N	1	CUSTOMER ISSUE	-
DMS_40301	41922	N	N	N	1	CUSTOMER ISSUE	-
DMS_40302	41923	N	N	N	1	CUSTOMER ISSUE	-
DMS_40303	41924	N	N	N	1	CUSTOMER ISSUE	-
DMS_40304	41925	N	N	N	1	CUSTOMER ISSUE	-
DMS_40305	41926	N	N	N	1	CUSTOMER ISSUE	-
DMS_40306	41927	N	N	N	1	CUSTOMER ISSUE	-
DMS_40307	41928	N	N	N	1	CUSTOMER ISSUE	-
DMS_40318	41929	N	N	N	1	CUSTOMER ISSUE	-
DMS_40321	41930	N	N	N	1	CUSTOMER ISSUE	-
DMS_40322	41931	N	N	N	1	CUSTOMER ISSUE	-
DMS_40323	41932	N	N	N	1	CUSTOMER ISSUE	-
DMS_40324	41933	N	N	N	1	CUSTOMER ISSUE	-
DMS_40325	41934	N	N	N	1	CUSTOMER ISSUE	-
DMS_40326	41935	N	N	N	1	CUSTOMER ISSUE	-
DMS_40327	41936	N	N	N	1	CUSTOMER ISSUE	-
DMS_40328	41937	N	N	N	1	CUSTOMER ISSUE	-
DMS_40329	41938	N	N	N	1	CUSTOMER ISSUE	-
DMS_40330	41939	N	N	N	1	CUSTOMER ISSUE	-
DMS_40331	41940	N	N	N	1	CUSTOMER ISSUE	-
DMS_40332	41941	N	N	N	1	CUSTOMER ISSUE	-
DMS_40333	41942	N	N	N	1	CUSTOMER ISSUE	-
DMS_40334	41943	N	N	N	1	CUSTOMER ISSUE	-
DMS_40335	41944	N	N	N	1	CUSTOMER ISSUE	-
DMS_40336	41945	N	N	N	1	CUSTOMER ISSUE	-
DMS_40337	41946	N	N	N	1	CUSTOMER ISSUE	-
DMS_40338	41947	N	N	N	1	CUSTOMER ISSUE	-
DMS_40339	41948	N	N	N	1	CUSTOMER ISSUE	-
DMS_40340	41949	N	N	N	1	CUSTOMER ISSUE	-
DMS_40341	41950	N	N	N	1	CUSTOMER ISSUE	-
DMS_40342	41951	N	N	N	1	CUSTOMER ISSUE	-
DMS_40343	41952	N	N	N	1	CUSTOMER ISSUE	-
DMS_40344	41953	N	N	N	1	CUSTOMER ISSUE	-
DMS_40345	41954	N	N	N	1	CUSTOMER ISSUE	-
DMS_40346	41955	N	N	N	1	CUSTOMER ISSUE	-
DMS_40347	41956	N	N	N	1	CUSTOMER ISSUE	-
DMS_40348	41957	N	N	N	1	CUSTOMER ISSUE	-
DMS_40349	41958	N	N	N	1	CUSTOMER ISSUE	-
DMS_40350	41959	N	N	N	1	CUSTOMER ISSUE	-
DMS_40351	41960	N	N	N	1	CUSTOMER ISSUE	-
DMS_40352	41961	N	N	N	1	CUSTOMER ISSUE	-
DMS_40353	41962	N	N	N	1	CUSTOMER ISSUE	-
DMS_40354	41963	N	N	N	1	CUSTOMER ISSUE	-
DMS_40355	41964	N	N	N	1	CUSTOMER ISSUE	-
DMS_40356	41965	N	N	N	1	CUSTOMER ISSUE	-
DMS_40357	41966	N	N	N	1	CUSTOMER ISSUE	-
DMS_40358	41967	N	N	N	1	CUSTOMER ISSUE	-
DMS_40359	41968	N	N	N	1	CUSTOMER ISSUE	-
DMS_40360	41969	N	N	N	1	CUSTOMER ISSUE	-
DMS_40361	41970	N	N	N	1	CUSTOMER ISSUE	-
DMS_40362	41971	N	N	N	1	CUSTOMER ISSUE	-
DMS_40363	41972	N	N	N	1	CUSTOMER ISSUE	-
DMS_40364	41973	N	N	N	1	CUSTOMER ISSUE	-
DMS_40365	41974	N	N	N	1	CUSTOMER ISSUE	-
DMS_40366	41975	N	N	N	1	CUSTOMER ISSUE	-
DMS_40367	41976	N	N	N	1	CUSTOMER ISSUE	-

DMS_40368	41977	N	N	N	1	CUSTOMER ISSUE	-
DMS_40369	41978	N	N	N	1	CUSTOMER ISSUE	-
DMS_40370	41979	N	N	N	1	CUSTOMER ISSUE	-
DMS_40371	41980	N	N	N	1	CUSTOMER ISSUE	-
DMS_40372	41981	N	N	N	1	CUSTOMER ISSUE	-
DMS_40373	41982	N	N	N	1	CUSTOMER ISSUE	-
DMS_40374	41983	N	N	N	1	CUSTOMER ISSUE	-
DMS_40375	41984	N	N	N	1	CUSTOMER ISSUE	-
DMS_40376	41985	N	N	N	1	CUSTOMER ISSUE	-
DMS_40378	41986	N	N	N	1	CUSTOMER ISSUE	-
DMS_40379	41987	N	N	N	1	CUSTOMER ISSUE	-
DMS_40380	41988	N	N	N	1	CUSTOMER ISSUE	-
DMS_40381	41989	N	N	N	1	CUSTOMER ISSUE	-
DMS_40382	41990	N	N	N	1	CUSTOMER ISSUE	-
DMS_40383	41991	N	N	N	1	CUSTOMER ISSUE	-
DMS_40384	41992	N	N	N	1	CUSTOMER ISSUE	-
DMS_40385	41993	N	N	N	1	CUSTOMER ISSUE	-
DMS_40387	41994	N	N	N	1	CUSTOMER ISSUE	-
DMS_40388	41995	N	N	N	1	CUSTOMER ISSUE	-
DMS_40389	41996	N	N	N	1	CUSTOMER ISSUE	-
DMS_40390	41997	N	N	N	1	CUSTOMER ISSUE	-
DMS_40391	41998	N	N	N	1	CUSTOMER ISSUE	-
DMS_40392	41999	N	N	N	1	CUSTOMER ISSUE	-
DMS_40393	42000	N	N	N	1	CUSTOMER ISSUE	-
DMS_40394	42001	N	N	N	1	CUSTOMER ISSUE	-
DMS_40395	42002	N	N	N	1	CUSTOMER ISSUE	-
DMS_40396	42003	N	N	N	1	CUSTOMER ISSUE	-
DMS_40397	42004	N	N	N	1	CUSTOMER ISSUE	-
DMS_40398	42005	N	N	N	1	CUSTOMER ISSUE	-
DMS_40399	42006	N	N	N	1	CUSTOMER ISSUE	-
DMS_40400	42007	N	N	N	1	CUSTOMER ISSUE	-
DMS_40403	42008	N	N	N	1	CUSTOMER ISSUE	-
DMS_40404	42009	N	N	N	1	CUSTOMER ISSUE	-
DMS_40405	42010	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40406	42011	N	N	N	1	CUSTOMER ISSUE	-
DMS_40409	42012	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40411	42013	N	N	N	1	CUSTOMER ISSUE	-
DMS_40412	42014	N	N	N	1	CUSTOMER ISSUE	-
DMS_40413	42015	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40414	42016	N	N	N	1	CUSTOMER ISSUE	-
DMS_40416	42017	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40417	42018	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40418	42019	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40419	42020	N	N	N	1	CUSTOMER ISSUE	-
DMS_40420	42021	N	N	N	1	CUSTOMER ISSUE	-
DMS_40421	42022	N	N	N	1	CUSTOMER ISSUE	-
DMS_40422	42023	N	N	N	1	CUSTOMER ISSUE	-
DMS_40423	42024	N	N	N	1	CUSTOMER ISSUE	-
DMS_40424	42025	N	N	N	1	CUSTOMER ISSUE	-
DMS_40425	42026	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_40427	42027	N	N	N	1	CUSTOMER ISSUE	-
DMS_40428	42028	N	N	N	1	CUSTOMER ISSUE	-
DMS_40429	42029	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40430	42030	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40431	42031	N	N	N	2	CUSTOMER ISSUE	-
DMS_40432	42032	N	N	N	1	CUSTOMER ISSUE	-
DMS_40434	42033	N	N	N	1	CUSTOMER ISSUE	-
DMS_40435	42034	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40436	42035	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40437	42036	N	N	N	1	CUSTOMER ISSUE	-
DMS_40438	42037	N	N	N	1	CUSTOMER ISSUE	-
DMS_40439	42038	N	N	N	1	CUSTOMER ISSUE	-
DMS_40440	42039	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40441	42040	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40443	42041	N	N	N	1	CUSTOMER ISSUE	-
DMS_40444	42042	N	N	N	1	CUSTOMER ISSUE	-
DMS_40445	42043	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40446	42044	N	N	Y	1	TX - REPLACE	2500
DMS_40447	42045	N	N	N	1	CUSTOMER ISSUE	-
DMS_40448	42046	N	N	N	1	CUSTOMER ISSUE	-
DMS_40449	42047	N	N	N	1	CUSTOMER ISSUE	-
DMS_40450	42048	N	N	N	1	CUSTOMER ISSUE	-
DMS_40451	42049	N	N	N	1	CUSTOMER ISSUE	-
DMS_40452	42050	N	N	N	1	CUSTOMER ISSUE	-
DMS_40453	42051	N	N	N	1	CUSTOMER ISSUE	-
DMS_40454	42052	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40455	42053	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40456	42054	N	N	N	1	CUSTOMER ISSUE	-
DMS_40458	42055	N	N	N	1	CUSTOMER ISSUE	-
DMS_40459	42056	N	N	N	1	CUSTOMER ISSUE	-

DMS_40460	42057	N	N	N	1	CUSTOMER ISSUE	-
DMS_40461	42058	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40462	42059	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40463	42060	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40464	42061	N	N	N	1	CUSTOMER ISSUE	-
DMS_40466	42062	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40467	42063	N	N	N	1	CUSTOMER ISSUE	-
DMS_40468	42064	N	N	N	1	CUSTOMER ISSUE	-
DMS_40469	42065	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_40470	42066	N	N	N	1	CUSTOMER ISSUE	-
DMS_40471	42067	N	N	N	1	CUSTOMER ISSUE	-
DMS_40472	42068	N	N	N	1	CUSTOMER ISSUE	-
DMS_40473	42069	N	N	N	1	CUSTOMER ISSUE	-
DMS_40474	42070	N	N	N	1	CUSTOMER ISSUE	-
DMS_40475	42071	N	N	N	1	CUSTOMER ISSUE	-
DMS_40476	42072	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_40478	42073	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40479	42074	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40480	42075	N	N	N	1	CUSTOMER ISSUE	-
DMS_40481	42076	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40482	42077	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40483	42078	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40485	42079	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40486	42080	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40487	42081	N	N	N	1	CUSTOMER ISSUE	-
DMS_40489	42082	N	N	N	1	CUSTOMER ISSUE	-
DMS_40490	42083	N	N	N	1	CUSTOMER ISSUE	-
DMS_40491	42084	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40492	42085	N	N	N	1	CUSTOMER ISSUE	-
DMS_40493	42086	N	N	N	1	CUSTOMER ISSUE	-
DMS_40494	42087	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40495	42088	N	N	N	1	CUSTOMER ISSUE	-
DMS_40496	42089	N	N	N	1	CUSTOMER ISSUE	-
DMS_40497	42090	N	N	N	1	CUSTOMER ISSUE	-
DMS_40499	42091	N	N	N	1	CUSTOMER ISSUE	-
DMS_40500	42092	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40501	42093	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40503	42094	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40504	42095	N	N	N	1	CUSTOMER ISSUE	-
DMS_40505	42096	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40506	42097	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40507	42098	N	N	N	1	CUSTOMER ISSUE	-
DMS_40508	42099	N	N	N	1	CUSTOMER ISSUE	-
DMS_40510	42100	N	N	N	1	CUSTOMER ISSUE	-
DMS_40512	42101	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_40513	42102	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40514	42103	N	N	N	1	CUSTOMER ISSUE	-
DMS_40515	42104	N	N	N	1	CUSTOMER ISSUE	-
DMS_40516	42105	N	N	N	1	CUSTOMER ISSUE	-
DMS_40518	42106	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40521	42107	N	N	N	1	CUSTOMER ISSUE	-
DMS_40523	42108	N	N	N	1	CUSTOMER ISSUE	-
DMS_40527	42109	N	N	N	1	CUSTOMER ISSUE	-
DMS_40528	42110	N	N	N	1	CUSTOMER ISSUE	-
DMS_40529	42111	N	N	N	1	CUSTOMER ISSUE	-
DMS_40534	42112	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_40535	42113	N	N	N	1	CUSTOMER ISSUE	-
DMS_40536	42114	N	N	N	1	CUSTOMER ISSUE	-
DMS_40539	42115	N	N	N	1	CUSTOMER ISSUE	-
DMS_40540	42116	N	N	N	1	CUSTOMER ISSUE	-
DMS_40543	42117	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40544	42118	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40545	42119	N	N	N	1	CUSTOMER ISSUE	-
DMS_40546	42120	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40547	42121	N	N	N	2	CUSTOMER ISSUE	-
DMS_40548	42122	N	N	N	1	CUSTOMER ISSUE	-
DMS_40551	42123	N	N	N	1	CUSTOMER ISSUE	-
DMS_40552	42124	N	N	N	1	CUSTOMER ISSUE	-
DMS_40553	42125	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40554	42126	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40555	42127	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40558	42128	N	N	N	1	CUSTOMER ISSUE	-
DMS_40559	42129	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40560	42130	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40561	42131	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40563	42132	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40564	42133	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40565	42134	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40566	42135	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40567	42136	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_40568	42137	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_40569	42138	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40570	42139	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40571	42140	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40572	42141	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40574	42142	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40575	42143	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40576	42144	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40577	42145	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40578	42146	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40579	42147	N	N	N	1	CUSTOMER ISSUE	-
DMS_40580	42148	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40581	42149	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40582	42150	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40583	42151	N	N	N	1	CUSTOMER ISSUE	-
DMS_40584	42152	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40586	42153	N	N	N	1	CUSTOMER ISSUE	-
DMS_40587	42154	N	N	Y	1	TX - REPLACE	2500
DMS_40588	42155	N	N	N	1	CUSTOMER ISSUE	-
DMS_40589	42156	N	N	N	1	CUSTOMER ISSUE	-
DMS_40590	42157	N	N	N	1	CUSTOMER ISSUE	-
DMS_40593	42158	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40594	42159	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40595	42160	N	N	N	1	CUSTOMER ISSUE	-
DMS_40596	42161	N	N	N	1	CUSTOMER ISSUE	-
DMS_40597	42162	N	N	N	1	CUSTOMER ISSUE	-
DMS_40598	42163	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40599	42164	N	N	N	1	CUSTOMER ISSUE	-
DMS_40600	42165	N	N	N	1	CUSTOMER ISSUE	-
DMS_40601	42166	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40602	42167	N	N	N	1	CUSTOMER ISSUE	-
DMS_40605	42168	N	N	N	1	CUSTOMER ISSUE	-
DMS_40606	42169	N	N	N	1	CUSTOMER ISSUE	-
DMS_40608	42170	N	N	N	1	CUSTOMER ISSUE	-
DMS_40609	42171	N	N	N	1	CUSTOMER ISSUE	-
DMS_40610	42172	N	N	N	1	CUSTOMER ISSUE	-
DMS_40611	42173	N	N	N	1	CUSTOMER ISSUE	-
DMS_40612	42174	N	N	N	1	CUSTOMER ISSUE	-
DMS_40614	42175	N	N	N	1	CUSTOMER ISSUE	-
DMS_40617	42176	N	N	N	1	CUSTOMER ISSUE	-
DMS_40618	42177	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40620	42178	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40622	42179	N	N	N	1	CUSTOMER ISSUE	-
DMS_40623	42180	N	N	N	1	CUSTOMER ISSUE	-
DMS_40624	42181	N	N	N	1	CUSTOMER ISSUE	-
DMS_40627	42182	N	N	N	1	CUSTOMER ISSUE	-
DMS_40628	42183	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40629	42184	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40630	42185	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40631	42186	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40632	42187	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40634	42188	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40635	42189	N	N	N	1	CUSTOMER ISSUE	-
DMS_40636	42190	N	N	N	1	CUSTOMER ISSUE	-
DMS_40637	42191	N	N	N	1	CUSTOMER ISSUE	-
DMS_40638	42192	N	N	N	1	CUSTOMER ISSUE	-
DMS_40639	42193	N	N	N	1	CUSTOMER ISSUE	-
DMS_40640	42194	N	N	N	1	CUSTOMER ISSUE	-
DMS_40641	42195	N	N	N	1	CUSTOMER ISSUE	-
DMS_40642	42196	N	N	N	1	CUSTOMER ISSUE	-
DMS_40643	42197	N	N	N	1	CUSTOMER ISSUE	-
DMS_40644	42198	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40647	42199	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40648	42200	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40649	42201	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40650	42202	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40653	42203	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40654	42204	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40655	42205	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40656	42206	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40657	42207	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40658	42208	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40659	42209	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40660	42210	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40661	42211	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40662	42212	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40663	42213	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40664	42214	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40665	42215	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40666	42216	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_40667	42217	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40668	42218	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40669	42219	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40670	42220	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40671	42221	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40672	42222	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40673	42223	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40674	42224	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40675	42225	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_40676	42226	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40677	42227	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40678	42228	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40680	42229	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40681	42230	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40682	42231	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40683	42232	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_40684	42233	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40685	42234	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40686	42235	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40687	42236	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40688	42237	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40689	42238	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40690	42239	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40691	42240	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_40692	42241	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40693	42242	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40694	42243	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40695	42244	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40696	42245	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40697	42246	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40699	42247	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40700	42248	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40701	42249	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40702	42250	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40703	42251	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40704	42252	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40705	42253	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40706	42254	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40707	42255	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40709	42256	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40711	42257	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40712	42258	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40715	42259	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40716	42260	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_40717	42261	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40719	42262	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40720	42263	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40721	42264	N	N	N	1	CUSTOMER ISSUE	-
DMS_40722	42265	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40723	42266	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40724	42267	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40725	42268	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40726	42269	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40727	42270	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40728	42271	N	N	N	1	CUSTOMER ISSUE	-
DMS_40729	42272	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40731	42273	N	N	N	1	CUSTOMER ISSUE	-
DMS_40732	42274	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_40733	42275	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_40736	42276	N	N	N	1	CUSTOMER ISSUE	-
DMS_40737	42277	N	N	N	1	CUSTOMER ISSUE	-
DMS_40738	42278	N	N	N	1	CUSTOMER ISSUE	-
DMS_40739	42279	N	N	N	1	CUSTOMER ISSUE	-
DMS_40740	42280	N	N	N	1	CUSTOMER ISSUE	-
DMS_40741	42281	N	N	N	1	CUSTOMER ISSUE	-
DMS_40742	42282	N	N	N	1	CUSTOMER ISSUE	-
DMS_40743	42283	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40746	42284	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_40747	42285	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40749	42286	N	N	N	1	CUSTOMER ISSUE	-
DMS_40750	42287	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40753	42288	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40754	42289	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40755	42290	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40756	42291	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40771	42292	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40772	42293	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40773	42294	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40774	42295	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40775	42296	N	N	Y	2	SEC/SVC - REPLACE	708.75

DMS_40776	42297	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40777	42298	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40780	42299	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40783	42300	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40784	42301	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40786	42302	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40787	42303	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40788	42304	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40789	42305	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40790	42306	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40791	42307	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40792	42308	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40794	42309	N	N	Y	3	SEC/SVC - REPAIR	472.5
DMS_40795	42310	N	N	Y	1	TX - REPLACE	2500
DMS_40796	42311	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40797	42312	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40798	42313	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40799	42314	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40800	42315	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40802	42316	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40804	42317	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40805	42318	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40806	42319	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40807	42320	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40808	42321	N	N	Y	1	TX - REPLACE	2500
DMS_40809	42322	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40810	42323	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40811	42324	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40813	42325	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40814	42326	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40815	42327	N	N	N	1	CUSTOMER ISSUE	-
DMS_40816	42328	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40817	42329	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40818	42330	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40819	42331	N	N	N	1	CUSTOMER ISSUE	-
DMS_40822	42332	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40823	42333	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40824	42334	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40825	42335	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40826	42336	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40827	42337	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40828	42338	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40829	42339	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40830	42340	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40831	42341	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40832	42342	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40833	42343	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40834	42344	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40835	42345	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40836	42346	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40837	42347	N	N	N	2	CUSTOMER ISSUE	-
DMS_40838	42348	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40839	42349	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40840	42350	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_40841	42351	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40842	42352	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40843	42353	N	N	N	1	CUSTOMER ISSUE	-
DMS_40844	42354	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40845	42355	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40846	42356	N	N	N	1	CUSTOMER ISSUE	-
DMS_40847	42357	N	N	N	1	CUSTOMER ISSUE	-
DMS_40848	42358	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40850	42359	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40851	42360	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40852	42361	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40854	42362	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40855	42363	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40856	42364	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40857	42365	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40858	42366	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40859	42367	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40860	42368	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40861	42369	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40862	42370	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40863	42371	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40864	42372	N	N	N	1	CUSTOMER ISSUE	-
DMS_40865	42373	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40866	42374	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40867	42375	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40868	42376	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_40869	42377	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40870	42378	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40871	42379	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40872	42380	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40873	42381	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40874	42382	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40875	42383	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40878	42384	N	N	N	1	CUSTOMER ISSUE	-
DMS_40879	42385	N	N	N	1	CUSTOMER ISSUE	-
DMS_40880	42386	N	N	N	1	CUSTOMER ISSUE	-
DMS_40881	42387	N	N	N	1	CUSTOMER ISSUE	-
DMS_40882	42388	N	N	N	1	CUSTOMER ISSUE	-
DMS_40883	42389	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40885	42390	N	N	N	1	CUSTOMER ISSUE	-
DMS_40887	42391	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40888	42392	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40889	42393	N	N	N	1	CUSTOMER ISSUE	-
DMS_40891	42394	N	N	N	1	CUSTOMER ISSUE	-
DMS_40893	42395	N	N	N	1	CUSTOMER ISSUE	-
DMS_40894	42396	N	N	N	1	CUSTOMER ISSUE	-
DMS_40895	42397	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40896	42398	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40897	42399	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40898	42400	N	N	N	1	CUSTOMER ISSUE	-
DMS_40899	42401	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40900	42402	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40901	42403	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40902	42404	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40903	42405	N	N	N	1	CUSTOMER ISSUE	-
DMS_40904	42406	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40905	42407	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40906	42408	N	N	N	1	CUSTOMER ISSUE	-
DMS_40907	42409	N	N	N	1	CUSTOMER ISSUE	-
DMS_40908	42410	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40909	42411	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40910	42412	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40911	42413	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40913	42414	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40914	42415	N	N	N	1	CUSTOMER ISSUE	-
DMS_40915	42416	N	N	N	1	CUSTOMER ISSUE	-
DMS_40916	42417	N	N	N	1	CUSTOMER ISSUE	-
DMS_40919	42418	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_40922	42419	N	N	N	1	CUSTOMER ISSUE	-
DMS_40924	42420	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40925	42421	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40928	42422	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40930	42423	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40931	42424	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40932	42425	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40933	42426	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40934	42427	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40935	42428	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40936	42429	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40937	42430	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40938	42431	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40939	42432	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40940	42433	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40941	42434	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40942	42435	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40943	42436	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40944	42437	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40945	42438	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40946	42439	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40947	42440	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40948	42441	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40949	42442	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40950	42443	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40951	42444	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40952	42445	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40953	42446	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40954	42447	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40955	42448	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40956	42449	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40957	42450	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40958	42451	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40959	42452	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40960	42453	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40961	42454	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40962	42455	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40963	42456	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_40964	42457	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40965	42458	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40966	42459	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40967	42460	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40968	42461	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40969	42462	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40970	42463	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40971	42464	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40972	42465	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40973	42466	N	N	N	1	CUSTOMER ISSUE	-
DMS_40974	42467	N	N	N	1	CUSTOMER ISSUE	-
DMS_40975	42468	N	N	N	1	CUSTOMER ISSUE	-
DMS_40976	42469	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40977	42470	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40978	42471	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40981	42472	N	N	N	1	CUSTOMER ISSUE	-
DMS_40982	42473	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40984	42474	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40985	42475	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_40986	42476	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40987	42477	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40988	42478	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40989	42479	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40990	42480	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_40991	42481	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40992	42482	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40993	42483	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40994	42484	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40995	42485	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40996	42486	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_40997	42487	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_40998	42488	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_40999	42489	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41000	42490	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41001	42491	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41002	42492	N	N	N	1	CUSTOMER ISSUE	-
DMS_41003	42493	N	N	N	1	CUSTOMER ISSUE	-
DMS_41004	42494	N	N	N	1	CUSTOMER ISSUE	-
DMS_41005	42495	N	N	N	1	CUSTOMER ISSUE	-
DMS_41006	42496	N	N	N	1	CUSTOMER ISSUE	-
DMS_41007	42497	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41008	42498	N	N	N	1	CUSTOMER ISSUE	-
DMS_41010	42499	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41011	42500	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41012	42501	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41014	42502	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41015	42503	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41016	42504	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41017	42505	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41018	42506	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41019	42507	N	N	N	1	CUSTOMER ISSUE	-
DMS_41020	42508	N	N	N	1	CUSTOMER ISSUE	-
DMS_41021	42509	N	N	N	1	CUSTOMER ISSUE	-
DMS_41022	42510	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41023	42511	N	N	N	1	CUSTOMER ISSUE	-
DMS_41026	42512	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41027	42513	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41028	42514	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41029	42515	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41030	42516	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41031	42517	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41034	42518	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41035	42519	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41036	42520	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41039	42521	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41040	42522	N	N	N	1	CUSTOMER ISSUE	-
DMS_41041	42523	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_41043	42524	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41044	42525	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41045	42526	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41046	42527	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41047	42528	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41048	42529	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41049	42530	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41050	42531	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41052	42532	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41053	42533	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41054	42534	N	N	N	1	CUSTOMER ISSUE	-
DMS_41060	42535	N	N	N	1	CUSTOMER ISSUE	-
DMS_41065	42536	N	N	N	1	CUSTOMER ISSUE	-

DMS_41068	42537	N	N	N	1	CUSTOMER ISSUE	-
DMS_41069	42538	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41071	42539	N	N	N	1	CUSTOMER ISSUE	-
DMS_41072	42540	N	N	N	1	CUSTOMER ISSUE	-
DMS_41073	42541	N	N	N	1	CUSTOMER ISSUE	-
DMS_41074	42542	N	N	N	1	CUSTOMER ISSUE	-
DMS_41075	42543	N	N	N	1	CUSTOMER ISSUE	-
DMS_41076	42544	N	N	N	1	CUSTOMER ISSUE	-
DMS_41077	42545	N	N	N	1	CUSTOMER ISSUE	-
DMS_41078	42546	N	N	N	1	CUSTOMER ISSUE	-
DMS_41079	42547	N	N	N	1	CUSTOMER ISSUE	-
DMS_41082	42548	N	N	N	1	CUSTOMER ISSUE	-
DMS_41083	42549	N	N	N	1	CUSTOMER ISSUE	-
DMS_41084	42550	N	N	N	1	CUSTOMER ISSUE	-
DMS_41087	42551	N	N	N	1	CUSTOMER ISSUE	-
DMS_41088	42552	N	N	N	1	CUSTOMER ISSUE	-
DMS_41089	42553	N	N	N	1	CUSTOMER ISSUE	-
DMS_41090	42554	N	N	N	1	CUSTOMER ISSUE	-
DMS_41091	42555	N	N	N	1	CUSTOMER ISSUE	-
DMS_41092	42556	N	N	N	1	CUSTOMER ISSUE	-
DMS_41093	42557	N	N	N	1	CUSTOMER ISSUE	-
DMS_41094	42558	N	N	N	1	CUSTOMER ISSUE	-
DMS_41095	42559	N	N	N	1	CUSTOMER ISSUE	-
DMS_41096	42560	N	N	N	1	CUSTOMER ISSUE	-
DMS_41097	42561	N	N	N	1	CUSTOMER ISSUE	-
DMS_41098	42562	N	N	N	1	CUSTOMER ISSUE	-
DMS_41099	42563	N	N	N	1	CUSTOMER ISSUE	-
DMS_41100	42564	N	N	N	1	CUSTOMER ISSUE	-
DMS_41101	42565	N	N	N	1	CUSTOMER ISSUE	-
DMS_41102	42566	N	N	N	1	CUSTOMER ISSUE	-
DMS_41103	42567	N	N	N	1	CUSTOMER ISSUE	-
DMS_41104	42568	N	N	N	1	CUSTOMER ISSUE	-
DMS_41105	42569	N	N	N	1	CUSTOMER ISSUE	-
DMS_41106	42570	N	N	N	1	CUSTOMER ISSUE	-
DMS_41107	42571	N	N	N	1	CUSTOMER ISSUE	-
DMS_41108	42572	N	N	N	1	CUSTOMER ISSUE	-
DMS_41109	42573	N	N	N	1	CUSTOMER ISSUE	-
DMS_41110	42574	N	N	N	1	CUSTOMER ISSUE	-
DMS_41111	42575	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41112	42576	N	N	N	1	CUSTOMER ISSUE	-
DMS_41113	42577	N	N	N	1	CUSTOMER ISSUE	-
DMS_41114	42578	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41115	42579	N	N	N	1	CUSTOMER ISSUE	-
DMS_41117	42580	N	N	N	1	CUSTOMER ISSUE	-
DMS_41118	42581	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41119	42582	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41120	42583	N	N	N	1	CUSTOMER ISSUE	-
DMS_41121	42584	N	N	N	1	CUSTOMER ISSUE	-
DMS_41122	42585	N	N	N	1	CUSTOMER ISSUE	-
DMS_41123	42586	N	N	N	1	CUSTOMER ISSUE	-
DMS_41125	42587	N	N	N	1	CUSTOMER ISSUE	-
DMS_41126	42588	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41127	42589	N	N	N	1	CUSTOMER ISSUE	-
DMS_41128	42590	N	N	N	1	CUSTOMER ISSUE	-
DMS_41129	42591	N	N	N	1	CUSTOMER ISSUE	-
DMS_41130	42592	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41131	42593	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41133	42594	N	N	N	1	CUSTOMER ISSUE	-
DMS_41136	42595	N	N	N	1	CUSTOMER ISSUE	-
DMS_41137	42596	N	N	N	1	CUSTOMER ISSUE	-
DMS_41138	42597	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41139	42598	N	N	N	1	CUSTOMER ISSUE	-
DMS_41140	42599	N	N	N	1	CUSTOMER ISSUE	-
DMS_41141	42600	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41145	42601	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41157	42602	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41159	42603	N	N	N	1	CUSTOMER ISSUE	-
DMS_41161	42604	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41165	42605	N	N	N	1	CUSTOMER ISSUE	-
DMS_41166	42606	N	N	N	1	CUSTOMER ISSUE	-
DMS_41173	42607	N	N	Y	4	DIST - TREE TRIMMING	945
DMS_41176	42608	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41177	42609	N	N	N	1	CUSTOMER ISSUE	-
DMS_41181	42610	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41183	42611	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41184	42612	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41185	42613	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41189	42614	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41192	42615	N	N	N	1	CUSTOMER ISSUE	-
DMS_41193	42616	N	N	N	1	CUSTOMER ISSUE	-

DMS_41194	42617	N	N	N	1	CUSTOMER ISSUE	-
DMS_41195	42618	N	N	N	1	CUSTOMER ISSUE	-
DMS_41196	42619	N	N	N	1	CUSTOMER ISSUE	-
DMS_41197	42620	N	N	N	1	CUSTOMER ISSUE	-
DMS_41198	42621	N	N	N	1	CUSTOMER ISSUE	-
DMS_41200	42622	N	N	N	1	CUSTOMER ISSUE	-
DMS_41201	42623	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41203	42624	N	N	N	1	CUSTOMER ISSUE	-
DMS_41204	42625	N	N	N	1	CUSTOMER ISSUE	-
DMS_41205	42626	N	N	N	1	CUSTOMER ISSUE	-
DMS_41207	42627	N	N	N	1	CUSTOMER ISSUE	-
DMS_41208	42628	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41210	42629	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41212	42630	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41213	42631	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41214	42632	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41217	42633	N	N	N	1	CUSTOMER ISSUE	-
DMS_41218	42634	N	N	N	1	CUSTOMER ISSUE	-
DMS_41220	42635	N	N	N	1	CUSTOMER ISSUE	-
DMS_41221	42636	N	N	N	1	CUSTOMER ISSUE	-
DMS_41222	42637	N	N	N	1	CUSTOMER ISSUE	-
DMS_41223	42638	N	N	N	1	CUSTOMER ISSUE	-
DMS_41224	42639	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41225	42640	N	N	N	1	CUSTOMER ISSUE	-
DMS_41226	42641	N	N	N	1	CUSTOMER ISSUE	-
DMS_41227	42642	N	N	N	1	CUSTOMER ISSUE	-
DMS_41228	42643	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41229	42644	N	N	N	1	CUSTOMER ISSUE	-
DMS_41230	42645	N	N	N	1	CUSTOMER ISSUE	-
DMS_41231	42646	N	N	N	1	CUSTOMER ISSUE	-
DMS_41232	42647	N	N	N	1	CUSTOMER ISSUE	-
DMS_41233	42648	N	N	N	1	CUSTOMER ISSUE	-
DMS_41239	42649	N	N	N	1	CUSTOMER ISSUE	-
DMS_41240	42650	N	N	N	1	CUSTOMER ISSUE	-
DMS_41241	42651	N	N	N	1	CUSTOMER ISSUE	-
DMS_41242	42652	N	N	N	1	CUSTOMER ISSUE	-
DMS_41243	42653	N	N	N	1	CUSTOMER ISSUE	-
DMS_41244	42654	N	N	N	1	CUSTOMER ISSUE	-
DMS_41245	42655	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41246	42656	N	N	N	1	CUSTOMER ISSUE	-
DMS_41249	42657	N	N	N	1	CUSTOMER ISSUE	-
DMS_41250	42658	N	N	N	1	CUSTOMER ISSUE	-
DMS_41251	42659	N	N	N	1	CUSTOMER ISSUE	-
DMS_41252	42660	N	N	N	1	CUSTOMER ISSUE	-
DMS_41253	42661	N	N	N	1	CUSTOMER ISSUE	-
DMS_41255	42662	N	N	N	1	CUSTOMER ISSUE	-
DMS_41256	42663	N	N	N	2	CUSTOMER ISSUE	-
DMS_41257	42664	N	N	N	1	CUSTOMER ISSUE	-
DMS_41258	42665	N	N	N	1	CUSTOMER ISSUE	-
DMS_41259	42666	N	N	N	1	CUSTOMER ISSUE	-
DMS_41261	42667	N	N	N	1	CUSTOMER ISSUE	-
DMS_41262	42668	N	N	N	1	CUSTOMER ISSUE	-
DMS_41263	42669	N	N	N	1	CUSTOMER ISSUE	-
DMS_41264	42670	N	N	N	1	CUSTOMER ISSUE	-
DMS_41265	42671	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41266	42672	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_41267	42673	N	N	N	1	CUSTOMER ISSUE	-
DMS_41268	42674	N	N	N	1	CUSTOMER ISSUE	-
DMS_41269	42675	N	N	N	1	CUSTOMER ISSUE	-
DMS_41270	42676	N	N	N	1	CUSTOMER ISSUE	-
DMS_41271	42677	N	N	N	1	CUSTOMER ISSUE	-
DMS_41272	42678	N	N	N	1	CUSTOMER ISSUE	-
DMS_41273	42679	N	N	N	1	CUSTOMER ISSUE	-
DMS_41274	42680	N	N	N	1	CUSTOMER ISSUE	-
DMS_41275	42681	N	N	N	1	CUSTOMER ISSUE	-
DMS_41276	42682	N	N	N	1	CUSTOMER ISSUE	-
DMS_41277	42683	N	N	N	1	CUSTOMER ISSUE	-
DMS_41278	42684	N	N	N	1	CUSTOMER ISSUE	-
DMS_41279	42685	N	N	N	1	CUSTOMER ISSUE	-
DMS_41280	42686	N	N	N	1	CUSTOMER ISSUE	-
DMS_41281	42687	N	N	N	1	CUSTOMER ISSUE	-
DMS_41282	42688	N	N	N	1	CUSTOMER ISSUE	-
DMS_41283	42689	N	N	N	1	CUSTOMER ISSUE	-
DMS_41284	42690	N	N	N	1	CUSTOMER ISSUE	-
DMS_41285	42691	N	N	N	1	CUSTOMER ISSUE	-
DMS_41286	42692	N	N	N	1	CUSTOMER ISSUE	-
DMS_41287	42693	N	N	N	1	CUSTOMER ISSUE	-
DMS_41288	42694	N	N	N	1	CUSTOMER ISSUE	-
DMS_41289	42695	N	N	N	1	CUSTOMER ISSUE	-
DMS_41290	42696	N	N	N	1	CUSTOMER ISSUE	-

DMS_41291	42697	N	N	N	1	CUSTOMER ISSUE	-
DMS_41292	42698	N	N	N	1	CUSTOMER ISSUE	-
DMS_41293	42699	N	N	N	1	CUSTOMER ISSUE	-
DMS_41294	42700	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41295	42701	N	N	N	1	CUSTOMER ISSUE	-
DMS_41296	42702	N	N	N	1	CUSTOMER ISSUE	-
DMS_41297	42703	N	N	N	1	CUSTOMER ISSUE	-
DMS_41298	42704	N	N	N	1	CUSTOMER ISSUE	-
DMS_41299	42705	N	N	N	1	CUSTOMER ISSUE	-
DMS_41300	42706	N	N	N	1	CUSTOMER ISSUE	-
DMS_41301	42707	N	N	N	1	CUSTOMER ISSUE	-
DMS_41302	42708	N	N	N	1	CUSTOMER ISSUE	-
DMS_41303	42709	N	N	N	1	CUSTOMER ISSUE	-
DMS_41304	42710	N	N	N	1	CUSTOMER ISSUE	-
DMS_41305	42711	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41306	42712	N	N	N	1	CUSTOMER ISSUE	-
DMS_41307	42713	N	N	N	1	CUSTOMER ISSUE	-
DMS_41315	42714	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41316	42715	N	N	N	1	CUSTOMER ISSUE	-
DMS_41317	42716	N	N	N	1	CUSTOMER ISSUE	-
DMS_41318	42717	N	N	N	1	CUSTOMER ISSUE	-
DMS_41319	42718	N	N	N	1	CUSTOMER ISSUE	-
DMS_41320	42719	N	N	N	1	CUSTOMER ISSUE	-
DMS_41325	42720	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41326	42721	N	N	N	1	CUSTOMER ISSUE	-
DMS_41327	42722	N	N	N	1	CUSTOMER ISSUE	-
DMS_41328	42723	N	N	N	1	CUSTOMER ISSUE	-
DMS_41329	42724	N	N	N	1	CUSTOMER ISSUE	-
DMS_41330	42725	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41332	42726	N	N	N	1	CUSTOMER ISSUE	-
DMS_41333	42727	N	N	N	1	CUSTOMER ISSUE	-
DMS_41334	42728	N	N	N	1	CUSTOMER ISSUE	-
DMS_41335	42729	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41336	42730	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41337	42731	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41338	42732	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41339	42733	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41340	42734	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41341	42735	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41342	42736	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41343	42737	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41344	42738	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41346	42739	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41347	42740	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41348	42741	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41349	42742	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41350	42743	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41351	42744	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41352	42745	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41353	42746	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41354	42747	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41355	42748	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41356	42749	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41357	42750	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41358	42751	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41359	42752	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41360	42753	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41361	42754	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41362	42755	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41363	42756	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41364	42757	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41365	42758	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41366	42759	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41367	42760	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41368	42761	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41369	42762	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41370	42763	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41371	42764	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41372	42765	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41373	42766	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41374	42767	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41375	42768	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41378	42769	N	N	N	1	CUSTOMER ISSUE	-
DMS_41379	42770	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41380	42771	N	N	N	1	CUSTOMER ISSUE	-
DMS_41381	42772	N	N	N	1	CUSTOMER ISSUE	-
DMS_41382	42773	N	N	N	1	CUSTOMER ISSUE	-
DMS_41383	42774	N	N	N	1	CUSTOMER ISSUE	-
DMS_41385	42775	N	N	N	1	CUSTOMER ISSUE	-
DMS_41386	42776	N	N	N	1	CUSTOMER ISSUE	-

DMS_41387	42777	N	N	N	1	CUSTOMER ISSUE	-
DMS_41388	42778	N	N	N	1	CUSTOMER ISSUE	-
DMS_41389	42779	N	N	N	1	CUSTOMER ISSUE	-
DMS_41390	42780	N	N	N	1	CUSTOMER ISSUE	-
DMS_41391	42781	N	N	N	1	CUSTOMER ISSUE	-
DMS_41392	42782	N	N	N	1	CUSTOMER ISSUE	-
DMS_41393	42783	N	N	N	1	CUSTOMER ISSUE	-
DMS_41394	42784	N	N	N	1	CUSTOMER ISSUE	-
DMS_41395	42785	N	N	N	1	CUSTOMER ISSUE	-
DMS_41396	42786	N	N	N	1	CUSTOMER ISSUE	-
DMS_41397	42787	N	N	N	1	CUSTOMER ISSUE	-
DMS_41398	42788	N	N	N	1	CUSTOMER ISSUE	-
DMS_41399	42789	N	N	N	1	CUSTOMER ISSUE	-
DMS_41400	42790	N	N	N	1	CUSTOMER ISSUE	-
DMS_41401	42791	N	N	N	1	CUSTOMER ISSUE	-
DMS_41402	42792	N	N	N	1	CUSTOMER ISSUE	-
DMS_41403	42793	N	N	N	1	CUSTOMER ISSUE	-
DMS_41404	42794	N	N	N	1	CUSTOMER ISSUE	-
DMS_41405	42795	N	N	N	1	CUSTOMER ISSUE	-
DMS_41406	42796	N	N	N	1	CUSTOMER ISSUE	-
DMS_41407	42797	N	N	N	1	CUSTOMER ISSUE	-
DMS_41408	42798	N	N	N	1	CUSTOMER ISSUE	-
DMS_41409	42799	N	N	N	1	CUSTOMER ISSUE	-
DMS_41410	42800	N	N	N	1	CUSTOMER ISSUE	-
DMS_41412	42801	N	N	N	1	CUSTOMER ISSUE	-
DMS_41413	42802	N	N	N	1	CUSTOMER ISSUE	-
DMS_41414	42803	N	N	N	1	CUSTOMER ISSUE	-
DMS_41415	42804	N	N	N	1	CUSTOMER ISSUE	-
DMS_41416	42805	N	N	N	1	CUSTOMER ISSUE	-
DMS_41417	42806	N	N	N	1	CUSTOMER ISSUE	-
DMS_41418	42807	N	N	N	1	CUSTOMER ISSUE	-
DMS_41419	42808	N	N	N	1	CUSTOMER ISSUE	-
DMS_41420	42809	N	N	N	1	CUSTOMER ISSUE	-
DMS_41421	42810	N	N	N	1	CUSTOMER ISSUE	-
DMS_41422	42811	N	N	N	1	CUSTOMER ISSUE	-
DMS_41423	42812	N	N	N	1	CUSTOMER ISSUE	-
DMS_41424	42813	N	N	N	1	CUSTOMER ISSUE	-
DMS_41425	42814	N	N	N	1	CUSTOMER ISSUE	-
DMS_41426	42815	N	N	N	1	CUSTOMER ISSUE	-
DMS_41427	42816	N	N	N	1	CUSTOMER ISSUE	-
DMS_41428	42817	N	N	N	1	CUSTOMER ISSUE	-
DMS_41429	42818	N	N	N	1	CUSTOMER ISSUE	-
DMS_41430	42819	N	N	N	1	CUSTOMER ISSUE	-
DMS_41431	42820	N	N	N	1	CUSTOMER ISSUE	-
DMS_41432	42821	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41433	42822	N	N	N	1	CUSTOMER ISSUE	-
DMS_41434	42823	N	N	N	1	CUSTOMER ISSUE	-
DMS_41435	42824	N	N	N	1	CUSTOMER ISSUE	-
DMS_41436	42825	N	N	N	1	CUSTOMER ISSUE	-
DMS_41437	42826	N	N	N	1	CUSTOMER ISSUE	-
DMS_41438	42827	N	N	N	1	CUSTOMER ISSUE	-
DMS_41439	42828	N	N	N	1	CUSTOMER ISSUE	-
DMS_41440	42829	N	N	N	1	CUSTOMER ISSUE	-
DMS_41441	42830	N	N	N	1	CUSTOMER ISSUE	-
DMS_41442	42831	N	N	N	1	CUSTOMER ISSUE	-
DMS_41445	42832	N	N	N	1	CUSTOMER ISSUE	-
DMS_41446	42833	N	N	N	1	CUSTOMER ISSUE	-
DMS_41447	42834	N	N	N	1	CUSTOMER ISSUE	-
DMS_41448	42835	N	N	N	2	CUSTOMER ISSUE	-
DMS_41449	42836	N	N	N	1	CUSTOMER ISSUE	-
DMS_41450	42837	N	N	N	1	CUSTOMER ISSUE	-
DMS_41451	42838	N	N	N	1	CUSTOMER ISSUE	-
DMS_41452	42839	N	N	N	1	CUSTOMER ISSUE	-
DMS_41453	42840	N	N	N	1	CUSTOMER ISSUE	-
DMS_41457	42841	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41458	42842	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41459	42843	N	N	N	1	CUSTOMER ISSUE	-
DMS_41461	42844	N	N	N	1	CUSTOMER ISSUE	-
DMS_41462	42845	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41464	42846	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41465	42847	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41467	42848	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41468	42849	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41469	42850	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41470	42851	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41471	42852	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41472	42853	N	N	N	1	CUSTOMER ISSUE	-
DMS_41473	42854	N	N	N	1	CUSTOMER ISSUE	-
DMS_41474	42855	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41475	42856	N	N	Y	1	DIST - TREE TRIMMING	945

DMS_41476	42857	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41478	42858	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41479	42859	N	N	N	1	CUSTOMER ISSUE	-
DMS_41480	42860	N	N	Y	1	TX - REPLACE	2500
DMS_41481	42861	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41482	42862	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41483	42863	N	N	N	1	CUSTOMER ISSUE	-
DMS_41484	42864	N	N	N	1	CUSTOMER ISSUE	-
DMS_41485	42865	N	N	N	1	CUSTOMER ISSUE	-
DMS_41486	42866	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41487	42867	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41488	42868	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41489	42869	N	N	N	1	CUSTOMER ISSUE	-
DMS_41490	42870	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41491	42871	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41492	42872	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41493	42873	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41494	42874	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41495	42875	N	N	N	1	CUSTOMER ISSUE	-
DMS_41497	42876	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41498	42877	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41499	42878	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41500	42879	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41501	42880	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41502	42881	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41503	42882	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41504	42883	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41506	42884	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41507	42885	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41508	42886	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41509	42887	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41510	42888	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41511	42889	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41512	42890	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41513	42891	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41514	42892	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41515	42893	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41516	42894	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41517	42895	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41518	42896	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41519	42897	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41520	42898	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41521	42899	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41522	42900	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_41523	42901	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41524	42902	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41525	42903	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41526	42904	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41527	42905	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41528	42906	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41529	42907	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41530	42908	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_41531	42909	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41532	42910	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41533	42911	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41534	42912	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41535	42913	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41536	42914	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41537	42915	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41538	42916	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41539	42917	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41540	42918	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41541	42919	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41542	42920	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41543	42921	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41544	42922	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41545	42923	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41546	42924	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41547	42925	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41548	42926	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41549	42927	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41550	42928	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41551	42929	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41552	42930	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41553	42931	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41554	42932	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41555	42933	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41557	42934	N	N	Y	1	TX - REPLACE	2500
DMS_41558	42935	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41559	42936	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_41560	42937	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41561	42938	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41562	42939	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41563	42940	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41564	42941	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41565	42942	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41566	42943	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41567	42944	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41568	42945	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41569	42946	N	N	N	1	CUSTOMER ISSUE	-
DMS_41570	42947	N	N	N	1	CUSTOMER ISSUE	-
DMS_41571	42948	N	N	N	1	CUSTOMER ISSUE	-
DMS_41572	42949	N	N	N	1	CUSTOMER ISSUE	-
DMS_41573	42950	N	N	N	1	CUSTOMER ISSUE	-
DMS_41574	42951	N	N	N	1	CUSTOMER ISSUE	-
DMS_41575	42952	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41577	42953	N	N	N	1	CUSTOMER ISSUE	-
DMS_41578	42954	N	N	N	1	CUSTOMER ISSUE	-
DMS_41582	42955	N	N	N	1	CUSTOMER ISSUE	-
DMS_41583	42956	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41586	42957	N	N	N	1	CUSTOMER ISSUE	-
DMS_41589	42958	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41593	42959	N	N	N	1	CUSTOMER ISSUE	-
DMS_41594	42960	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41595	42961	N	N	N	1	CUSTOMER ISSUE	-
DMS_41596	42962	N	N	N	1	CUSTOMER ISSUE	-
DMS_41597	42963	N	N	N	1	CUSTOMER ISSUE	-
DMS_41598	42964	N	N	N	1	CUSTOMER ISSUE	-
DMS_41599	42965	N	N	N	1	CUSTOMER ISSUE	-
DMS_41600	42966	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_41601	42967	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_41605	42968	N	N	N	1	CUSTOMER ISSUE	-
DMS_41608	42969	N	N	N	2	CUSTOMER ISSUE	-
DMS_41609	42970	N	N	N	1	CUSTOMER ISSUE	-
DMS_41610	42971	N	N	N	1	CUSTOMER ISSUE	-
DMS_41611	42972	N	N	N	1	CUSTOMER ISSUE	-
DMS_41613	42973	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41614	42974	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41616	42975	N	N	N	1	CUSTOMER ISSUE	-
DMS_41618	42976	N	N	N	1	CUSTOMER ISSUE	-
DMS_41619	42977	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41620	42978	N	N	N	1	CUSTOMER ISSUE	-
DMS_41622	42979	N	N	N	1	CUSTOMER ISSUE	-
DMS_41623	42980	N	N	N	1	CUSTOMER ISSUE	-
DMS_41624	42981	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41625	42982	N	N	N	1	CUSTOMER ISSUE	-
DMS_41626	42983	N	N	N	1	CUSTOMER ISSUE	-
DMS_41627	42984	N	N	N	1	CUSTOMER ISSUE	-
DMS_41628	42985	N	N	N	1	CUSTOMER ISSUE	-
DMS_41629	42986	N	N	N	1	CUSTOMER ISSUE	-
DMS_41630	42987	N	N	N	1	CUSTOMER ISSUE	-
DMS_41631	42988	N	N	N	1	CUSTOMER ISSUE	-
DMS_41632	42989	N	N	N	1	CUSTOMER ISSUE	-
DMS_41633	42990	N	N	N	1	CUSTOMER ISSUE	-
DMS_41634	42991	N	N	N	1	CUSTOMER ISSUE	-
DMS_41635	42992	N	N	N	1	CUSTOMER ISSUE	-
DMS_41636	42993	N	N	N	1	CUSTOMER ISSUE	-
DMS_41637	42994	N	N	N	1	CUSTOMER ISSUE	-
DMS_41638	42995	N	N	N	1	CUSTOMER ISSUE	-
DMS_41639	42996	N	N	N	1	CUSTOMER ISSUE	-
DMS_41640	42997	N	N	N	1	CUSTOMER ISSUE	-
DMS_41641	42998	N	N	N	1	CUSTOMER ISSUE	-
DMS_41642	42999	N	N	N	1	CUSTOMER ISSUE	-
DMS_41643	43000	N	N	N	1	CUSTOMER ISSUE	-
DMS_41644	43001	N	N	N	1	CUSTOMER ISSUE	-
DMS_41645	43002	N	N	N	1	CUSTOMER ISSUE	-
DMS_41646	43003	N	N	N	1	CUSTOMER ISSUE	-
DMS_41647	43004	N	N	N	1	CUSTOMER ISSUE	-
DMS_41648	43005	N	N	N	1	CUSTOMER ISSUE	-
DMS_41650	43006	N	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
DMS_41651	43007	N	N	N	1	CUSTOMER ISSUE	-
DMS_41652	43008	N	N	N	1	CUSTOMER ISSUE	-
DMS_41653	43009	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41654	43010	N	N	N	1	CUSTOMER ISSUE	-
DMS_41657	43011	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41658	43012	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41660	43013	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41662	43014	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41663	43015	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41664	43016	N	N	Y	1	DIST - TREE TRIMMING	945

DMS_41665	43017	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41666	43018	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41667	43019	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41668	43020	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41669	43021	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41670	43022	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_41671	43023	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41672	43024	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41673	43025	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41674	43026	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41677	43027	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41678	43028	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41679	43029	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41680	43030	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41681	43031	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41682	43032	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41683	43033	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41684	43034	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41685	43035	N	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
DMS_41686	43036	N	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
DMS_41688	43037	N	N	N	1	CUSTOMER ISSUE	-
DMS_41689	43038	N	N	N	1	CUSTOMER ISSUE	-
DMS_41691	43039	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_41692	43040	N	N	N	1	CUSTOMER ISSUE	-
DMS_41693	43041	N	N	N	1	CUSTOMER ISSUE	-
DMS_41694	43042	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41695	43043	N	N	N	1	CUSTOMER ISSUE	-
DMS_41696	43044	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41697	43045	N	N	N	1	CUSTOMER ISSUE	-
DMS_41698	43046	N	N	N	1	CUSTOMER ISSUE	-
DMS_41699	43047	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41701	43048	N	N	N	1	CUSTOMER ISSUE	-
DMS_41702	43049	N	N	N	1	CUSTOMER ISSUE	-
DMS_41703	43050	N	N	N	1	CUSTOMER ISSUE	-
DMS_41704	43051	N	N	N	1	CUSTOMER ISSUE	-
DMS_41705	43052	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41706	43053	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41707	43054	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41708	43055	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41709	43056	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41710	43057	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41711	43058	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41712	43059	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41713	43060	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_41714	43061	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41715	43062	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41716	43063	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41717	43064	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41719	43065	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41720	43066	N	N	N	1	CUSTOMER ISSUE	-
DMS_41722	43067	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41723	43068	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41724	43069	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41725	43070	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41726	43071	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41727	43072	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41728	43073	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41729	43074	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41730	43075	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41731	43076	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41732	43077	N	N	N	1	CUSTOMER ISSUE	-
DMS_41733	43078	N	N	N	1	CUSTOMER ISSUE	-
DMS_41734	43079	N	N	N	1	CUSTOMER ISSUE	-
DMS_41735	43080	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41736	43081	N	N	N	1	CUSTOMER ISSUE	-
DMS_41737	43082	N	N	N	1	CUSTOMER ISSUE	-
DMS_41738	43083	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41739	43084	N	N	N	2	CUSTOMER ISSUE	-
DMS_41741	43085	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41743	43086	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41744	43087	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41746	43088	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41748	43089	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41749	43090	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41750	43091	N	N	N	1	CUSTOMER ISSUE	-
DMS_41751	43092	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41752	43093	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41753	43094	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41754	43095	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41755	43096	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_41756	43097	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41757	43098	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_41758	43099	N	N	N	1	CUSTOMER ISSUE	-
DMS_41759	43100	N	N	N	1	CUSTOMER ISSUE	-
DMS_41760	43101	N	N	N	1	CUSTOMER ISSUE	-
DMS_41761	43102	N	N	N	1	CUSTOMER ISSUE	-
DMS_41762	43103	N	N	N	1	CUSTOMER ISSUE	-
DMS_41764	43104	N	N	N	1	CUSTOMER ISSUE	-
DMS_41765	43105	N	N	N	1	CUSTOMER ISSUE	-
DMS_41766	43106	N	N	N	1	CUSTOMER ISSUE	-
DMS_41767	43107	N	N	N	2	CUSTOMER ISSUE	-
DMS_41769	43108	N	N	N	1	CUSTOMER ISSUE	-
DMS_41770	43109	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41772	43110	N	N	N	1	CUSTOMER ISSUE	-
DMS_41773	43111	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41774	43112	N	N	N	1	CUSTOMER ISSUE	-
DMS_41775	43113	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41776	43114	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41781	43115	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41782	43116	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41783	43117	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41784	43118	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41785	43119	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41786	43120	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41787	43121	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41788	43122	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41789	43123	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41790	43124	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41791	43125	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41792	43126	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41793	43127	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41794	43128	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41795	43129	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41796	43130	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41797	43131	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41798	43132	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41799	43133	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41800	43134	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41801	43135	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41802	43136	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41803	43137	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41804	43138	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41805	43139	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41806	43140	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41807	43141	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41808	43142	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41809	43143	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41810	43144	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41811	43145	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41812	43146	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41813	43147	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41814	43148	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41815	43149	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41816	43150	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41817	43151	N	N	N	1	CUSTOMER ISSUE	-
DMS_41819	43152	N	N	N	1	CUSTOMER ISSUE	-
DMS_41820	43153	N	N	N	1	CUSTOMER ISSUE	-
DMS_41821	43154	N	N	N	1	CUSTOMER ISSUE	-
DMS_41822	43155	N	N	N	1	CUSTOMER ISSUE	-
DMS_41823	43156	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41826	43157	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41827	43158	N	N	N	1	CUSTOMER ISSUE	-
DMS_41828	43159	N	N	N	1	CUSTOMER ISSUE	-
DMS_41829	43160	N	N	N	1	CUSTOMER ISSUE	-
DMS_41830	43161	N	N	N	1	CUSTOMER ISSUE	-
DMS_41831	43162	N	N	N	1	CUSTOMER ISSUE	-
DMS_41832	43163	N	N	N	1	CUSTOMER ISSUE	-
DMS_41833	43164	N	N	N	1	CUSTOMER ISSUE	-
DMS_41834	43165	N	N	N	1	CUSTOMER ISSUE	-
DMS_41836	43166	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41837	43167	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41838	43168	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41839	43169	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41842	43170	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41843	43171	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41844	43172	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41845	43173	N	N	N	1	CUSTOMER ISSUE	-
DMS_41847	43174	N	N	N	1	CUSTOMER ISSUE	-
DMS_41848	43175	N	N	Y	1	TX - REPLACE	2500
DMS_41849	43176	N	N	Y	1	DIST - REPLACE FUSE	708.75

DMS_41850	43177	N	N	N	1	CUSTOMER ISSUE	-
DMS_41851	43178	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_41852	43179	N	N	N	1	CUSTOMER ISSUE	-
DMS_41853	43180	N	N	N	1	CUSTOMER ISSUE	-
DMS_41858	43181	N	N	N	1	CUSTOMER ISSUE	-
DMS_41859	43182	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41860	43183	N	N	N	1	CUSTOMER ISSUE	-
DMS_41863	43184	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41864	43185	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41865	43186	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41867	43187	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41868	43188	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41869	43189	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41871	43190	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41872	43191	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41873	43192	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41874	43193	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41875	43194	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41876	43195	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41877	43196	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41878	43197	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41879	43198	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41880	43199	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41881	43200	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41883	43201	N	N	Y	3	DIST - TREE TRIMMING	945
DMS_41884	43202	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
DMS_41885	43203	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41886	43204	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41887	43205	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41888	43206	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41890	43207	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41891	43208	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41892	43209	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41894	43210	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41895	43211	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41896	43212	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41897	43213	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41898	43214	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41899	43215	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41903	43216	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41904	43217	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41905	43218	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41906	43219	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41907	43220	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41908	43221	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41909	43222	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41911	43223	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41913	43224	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41914	43225	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41915	43226	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41916	43227	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_41917	43228	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41918	43229	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41919	43230	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41920	43231	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41921	43232	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_41926	43233	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41928	43234	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41929	43235	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41932	43236	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_41936	43237	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41939	43238	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41940	43239	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41941	43240	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41942	43241	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41943	43242	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41944	43243	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41947	43244	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41948	43245	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41949	43246	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41950	43247	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41951	43248	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41952	43249	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41953	43250	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41954	43251	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41956	43252	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41957	43253	N	N	N	1	CUSTOMER ISSUE	-
DMS_41958	43254	N	N	N	1	CUSTOMER ISSUE	-
DMS_41959	43255	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_41960	43256	N	N	Y	1	DIST - TREE TRIMMING	945

DMS_41961	43257	N	N	N	1	CUSTOMER ISSUE	-
DMS_41962	43258	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_41964	43259	N	N	N	1	CUSTOMER ISSUE	-
DMS_41965	43260	N	N	N	1	CUSTOMER ISSUE	-
DMS_41966	43261	N	N	N	1	CUSTOMER ISSUE	-
DMS_41967	43262	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41968	43263	N	N	N	1	CUSTOMER ISSUE	-
DMS_41969	43264	N	N	N	1	CUSTOMER ISSUE	-
DMS_41970	43265	N	N	N	1	CUSTOMER ISSUE	-
DMS_41971	43266	N	N	N	1	CUSTOMER ISSUE	-
DMS_41972	43267	N	N	N	1	CUSTOMER ISSUE	-
DMS_41973	43268	N	N	N	1	CUSTOMER ISSUE	-
DMS_41974	43269	N	N	N	1	CUSTOMER ISSUE	-
DMS_41975	43270	N	N	N	1	CUSTOMER ISSUE	-
DMS_41976	43271	N	N	N	1	CUSTOMER ISSUE	-
DMS_41977	43272	N	N	Y	8	SEC/SVC - REPAIR	472.5
DMS_41978	43273	N	N	N	1	CUSTOMER ISSUE	-
DMS_41979	43274	N	N	N	1	CUSTOMER ISSUE	-
DMS_41980	43275	N	N	N	1	CUSTOMER ISSUE	-
DMS_41981	43276	N	N	N	1	CUSTOMER ISSUE	-
DMS_41982	43277	N	N	N	1	CUSTOMER ISSUE	-
DMS_41983	43278	N	N	N	1	CUSTOMER ISSUE	-
DMS_41984	43279	N	N	N	1	CUSTOMER ISSUE	-
DMS_41985	43280	N	N	N	1	CUSTOMER ISSUE	-
DMS_41986	43281	N	N	N	1	CUSTOMER ISSUE	-
DMS_41987	43282	N	N	N	1	CUSTOMER ISSUE	-
DMS_41989	43283	N	N	N	1	CUSTOMER ISSUE	-
DMS_41990	43284	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_41991	43285	N	N	N	1	CUSTOMER ISSUE	-
DMS_41992	43286	N	N	N	1	CUSTOMER ISSUE	-
DMS_41993	43287	N	N	N	1	CUSTOMER ISSUE	-
DMS_41994	43288	N	N	N	1	CUSTOMER ISSUE	-
DMS_41995	43289	N	N	Y	3	SEC/SVC - REPAIR	472.5
DMS_41996	43290	N	N	N	1	CUSTOMER ISSUE	-
DMS_41997	43291	N	N	N	1	CUSTOMER ISSUE	-
DMS_41998	43292	N	N	N	1	CUSTOMER ISSUE	-
DMS_41999	43293	N	N	N	1	CUSTOMER ISSUE	-
DMS_42000	43294	N	N	N	1	CUSTOMER ISSUE	-
DMS_42001	43295	N	N	N	1	CUSTOMER ISSUE	-
DMS_42002	43296	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_42003	43297	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42004	43298	N	N	N	1	CUSTOMER ISSUE	-
DMS_42005	43299	N	N	N	1	CUSTOMER ISSUE	-
DMS_42006	43300	N	N	N	1	CUSTOMER ISSUE	-
DMS_42007	43301	N	N	N	1	CUSTOMER ISSUE	-
DMS_42008	43302	N	N	N	1	CUSTOMER ISSUE	-
DMS_42010	43303	N	N	N	1	CUSTOMER ISSUE	-
DMS_42011	43304	N	N	N	1	CUSTOMER ISSUE	-
DMS_42012	43305	N	N	N	1	CUSTOMER ISSUE	-
DMS_42013	43306	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42014	43307	N	N	N	1	CUSTOMER ISSUE	-
DMS_42015	43308	N	N	N	1	CUSTOMER ISSUE	-
DMS_42016	43309	N	N	N	1	CUSTOMER ISSUE	-
DMS_42017	43310	N	N	N	1	CUSTOMER ISSUE	-
DMS_42018	43311	N	N	N	1	CUSTOMER ISSUE	-
DMS_42023	43312	N	N	N	1	CUSTOMER ISSUE	-
DMS_42024	43313	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42025	43314	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_42026	43315	N	N	N	1	CUSTOMER ISSUE	-
DMS_42048	43316	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42049	43317	N	N	N	1	CUSTOMER ISSUE	-
DMS_42050	43318	N	N	N	1	CUSTOMER ISSUE	-
DMS_42051	43319	N	N	N	1	CUSTOMER ISSUE	-
DMS_42052	43320	N	N	N	1	CUSTOMER ISSUE	-
DMS_42053	43321	N	N	N	1	CUSTOMER ISSUE	-
DMS_42054	43322	N	N	N	1	CUSTOMER ISSUE	-
DMS_42055	43323	N	N	N	1	CUSTOMER ISSUE	-
DMS_42056	43324	N	N	N	1	CUSTOMER ISSUE	-
DMS_42057	43325	N	N	N	1	CUSTOMER ISSUE	-
DMS_42058	43326	N	N	N	1	CUSTOMER ISSUE	-
DMS_42059	43327	N	N	N	1	CUSTOMER ISSUE	-
DMS_42060	43328	N	N	N	1	CUSTOMER ISSUE	-
DMS_42061	43329	N	N	N	1	CUSTOMER ISSUE	-
DMS_42062	43330	N	N	N	1	CUSTOMER ISSUE	-
DMS_42063	43331	N	N	N	1	CUSTOMER ISSUE	-
DMS_42064	43332	N	N	N	1	CUSTOMER ISSUE	-
DMS_42065	43333	N	N	N	1	CUSTOMER ISSUE	-
DMS_42066	43334	N	N	N	1	CUSTOMER ISSUE	-
DMS_42067	43335	N	N	N	1	CUSTOMER ISSUE	-
DMS_42068	43336	N	N	N	1	CUSTOMER ISSUE	-

DMS_42069	43337	N	N	N	1	CUSTOMER ISSUE	-
DMS_42070	43338	N	N	N	1	CUSTOMER ISSUE	-
DMS_42071	43339	N	N	N	1	CUSTOMER ISSUE	-
DMS_42072	43340	N	N	N	1	CUSTOMER ISSUE	-
DMS_42073	43341	N	N	N	1	CUSTOMER ISSUE	-
DMS_42074	43342	N	N	N	1	CUSTOMER ISSUE	-
DMS_42075	43343	N	N	N	1	CUSTOMER ISSUE	-
DMS_42076	43344	N	N	N	1	CUSTOMER ISSUE	-
DMS_42077	43345	N	N	N	1	CUSTOMER ISSUE	-
DMS_42078	43346	N	N	N	1	CUSTOMER ISSUE	-
DMS_42079	43347	N	N	N	1	CUSTOMER ISSUE	-
DMS_42080	43348	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42081	43349	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42082	43350	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42083	43351	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42084	43352	N	N	N	1	CUSTOMER ISSUE	-
DMS_42085	43353	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42086	43354	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42087	43355	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42088	43356	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42090	43357	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42091	43358	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42092	43359	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42093	43360	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42094	43361	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42095	43362	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42096	43363	N	N	N	1	CUSTOMER ISSUE	-
DMS_42097	43364	N	N	N	1	CUSTOMER ISSUE	-
DMS_42098	43365	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_42099	43366	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42100	43367	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42101	43368	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42102	43369	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42103	43370	N	N	N	1	CUSTOMER ISSUE	-
DMS_42104	43371	N	N	N	1	CUSTOMER ISSUE	-
DMS_42105	43372	N	N	N	1	CUSTOMER ISSUE	-
DMS_42106	43373	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42107	43374	N	N	N	1	CUSTOMER ISSUE	-
DMS_42108	43375	N	N	N	1	CUSTOMER ISSUE	-
DMS_42109	43376	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42111	43377	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42113	43378	N	N	N	1	CUSTOMER ISSUE	-
DMS_42114	43379	N	N	N	1	CUSTOMER ISSUE	-
DMS_42115	43380	N	N	N	1	CUSTOMER ISSUE	-
DMS_42116	43381	N	N	N	1	CUSTOMER ISSUE	-
DMS_42117	43382	N	N	N	1	CUSTOMER ISSUE	-
DMS_42118	43383	N	N	N	1	CUSTOMER ISSUE	-
DMS_42119	43384	N	N	N	1	CUSTOMER ISSUE	-
DMS_42120	43385	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42121	43386	N	N	N	1	CUSTOMER ISSUE	-
DMS_42122	43387	N	N	N	1	CUSTOMER ISSUE	-
DMS_42123	43388	N	N	N	1	CUSTOMER ISSUE	-
DMS_42124	43389	N	N	N	1	CUSTOMER ISSUE	-
DMS_42125	43390	N	N	N	1	CUSTOMER ISSUE	-
DMS_42126	43391	N	N	N	2	CUSTOMER ISSUE	-
DMS_42127	43392	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42128	43393	N	N	N	1	CUSTOMER ISSUE	-
DMS_42129	43394	N	N	N	1	CUSTOMER ISSUE	-
DMS_42130	43395	N	N	N	1	CUSTOMER ISSUE	-
DMS_42131	43396	N	N	N	1	CUSTOMER ISSUE	-
DMS_42132	43397	N	N	N	1	CUSTOMER ISSUE	-
DMS_42133	43398	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42134	43399	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42135	43400	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42136	43401	N	N	N	1	CUSTOMER ISSUE	-
DMS_42137	43402	N	N	N	1	CUSTOMER ISSUE	-
DMS_42138	43403	N	N	N	1	CUSTOMER ISSUE	-
DMS_42139	43404	N	N	N	1	CUSTOMER ISSUE	-
DMS_42140	43405	N	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
DMS_42141	43406	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42142	43407	N	N	N	1	CUSTOMER ISSUE	-
DMS_42143	43408	N	N	N	1	CUSTOMER ISSUE	-
DMS_42144	43409	N	N	N	1	CUSTOMER ISSUE	-
DMS_42145	43410	N	N	N	1	CUSTOMER ISSUE	-
DMS_42146	43411	N	N	N	1	CUSTOMER ISSUE	-
DMS_42148	43412	N	N	N	1	CUSTOMER ISSUE	-
DMS_42149	43413	N	N	Y	1	TX - REPLACE	2500
DMS_42150	43414	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42152	43415	N	N	N	1	CUSTOMER ISSUE	-
DMS_42153	43416	N	N	N	1	CUSTOMER ISSUE	-

DMS_42154	43417	N	N	N	1	CUSTOMER ISSUE	-
DMS_42155	43418	N	N	N	1	CUSTOMER ISSUE	-
DMS_42156	43419	N	N	N	1	CUSTOMER ISSUE	-
DMS_42157	43420	N	N	N	1	CUSTOMER ISSUE	-
DMS_42158	43421	N	N	N	1	CUSTOMER ISSUE	-
DMS_42160	43422	N	N	N	1	CUSTOMER ISSUE	-
DMS_42161	43423	N	N	N	1	CUSTOMER ISSUE	-
DMS_42162	43424	N	N	N	1	CUSTOMER ISSUE	-
DMS_42163	43425	N	N	N	1	CUSTOMER ISSUE	-
DMS_42164	43426	N	N	N	1	CUSTOMER ISSUE	-
DMS_42165	43427	N	N	N	1	CUSTOMER ISSUE	-
DMS_42166	43428	N	N	N	1	CUSTOMER ISSUE	-
DMS_42167	43429	N	N	N	1	CUSTOMER ISSUE	-
DMS_42168	43430	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42169	43431	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42170	43432	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42171	43433	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42173	43434	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42174	43435	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42175	43436	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42176	43437	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42177	43438	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42178	43439	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42179	43440	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42180	43441	N	N	N	1	CUSTOMER ISSUE	-
DMS_42181	43442	N	N	N	1	CUSTOMER ISSUE	-
DMS_42182	43443	N	N	N	1	CUSTOMER ISSUE	-
DMS_42184	43444	N	N	N	1	CUSTOMER ISSUE	-
DMS_42185	43445	N	N	N	1	CUSTOMER ISSUE	-
DMS_42186	43446	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42187	43447	N	N	N	1	CUSTOMER ISSUE	-
DMS_42188	43448	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42189	43449	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42190	43450	N	N	N	1	CUSTOMER ISSUE	-
DMS_42191	43451	N	N	N	1	CUSTOMER ISSUE	-
DMS_42192	43452	N	N	N	1	CUSTOMER ISSUE	-
DMS_42193	43453	N	N	N	1	CUSTOMER ISSUE	-
DMS_42194	43454	N	N	N	1	CUSTOMER ISSUE	-
DMS_42195	43455	N	N	N	1	CUSTOMER ISSUE	-
DMS_42196	43456	N	N	N	1	CUSTOMER ISSUE	-
DMS_42197	43457	N	N	N	1	CUSTOMER ISSUE	-
DMS_42198	43458	N	N	N	1	CUSTOMER ISSUE	-
DMS_42199	43459	N	N	N	1	CUSTOMER ISSUE	-
DMS_42200	43460	N	N	N	1	CUSTOMER ISSUE	-
DMS_42201	43461	N	N	N	1	CUSTOMER ISSUE	-
DMS_42202	43462	N	N	N	1	CUSTOMER ISSUE	-
DMS_42203	43463	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42204	43464	N	N	N	1	CUSTOMER ISSUE	-
DMS_42205	43465	N	N	N	1	CUSTOMER ISSUE	-
DMS_42206	43466	N	N	N	1	CUSTOMER ISSUE	-
DMS_42207	43467	N	N	N	1	CUSTOMER ISSUE	-
DMS_42208	43468	N	N	N	1	CUSTOMER ISSUE	-
DMS_42210	43469	N	N	N	1	CUSTOMER ISSUE	-
DMS_42211	43470	N	N	N	1	CUSTOMER ISSUE	-
DMS_42213	43471	N	N	N	1	CUSTOMER ISSUE	-
DMS_42214	43472	N	N	N	1	CUSTOMER ISSUE	-
DMS_42215	43473	N	N	N	1	CUSTOMER ISSUE	-
DMS_42216	43474	N	N	N	1	CUSTOMER ISSUE	-
DMS_42217	43475	N	N	N	1	CUSTOMER ISSUE	-
DMS_42218	43476	N	N	N	1	CUSTOMER ISSUE	-
DMS_42219	43477	N	N	N	1	CUSTOMER ISSUE	-
DMS_42220	43478	N	N	N	1	CUSTOMER ISSUE	-
DMS_42221	43479	N	N	N	1	CUSTOMER ISSUE	-
DMS_42222	43480	N	N	N	1	CUSTOMER ISSUE	-
DMS_42223	43481	N	N	N	1	CUSTOMER ISSUE	-
DMS_42224	43482	N	N	N	1	CUSTOMER ISSUE	-
DMS_42225	43483	N	N	N	1	CUSTOMER ISSUE	-
DMS_42226	43484	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_42227	43485	N	N	N	1	CUSTOMER ISSUE	-
DMS_42228	43486	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42229	43487	N	N	N	1	CUSTOMER ISSUE	-
DMS_42230	43488	N	N	N	1	CUSTOMER ISSUE	-
DMS_42231	43489	N	N	N	1	CUSTOMER ISSUE	-
DMS_42232	43490	N	N	N	1	CUSTOMER ISSUE	-
DMS_42233	43491	N	N	N	1	CUSTOMER ISSUE	-
DMS_42234	43492	N	N	N	1	CUSTOMER ISSUE	-
DMS_42235	43493	N	N	N	1	CUSTOMER ISSUE	-
DMS_42236	43494	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42237	43495	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42238	43496	N	N	N	1	CUSTOMER ISSUE	-

DMS_42239	43497	N	N	N	1	CUSTOMER ISSUE	-
DMS_42240	43498	N	N	N	1	CUSTOMER ISSUE	-
DMS_42241	43499	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42242	43500	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42243	43501	N	N	N	1	CUSTOMER ISSUE	-
DMS_42244	43502	N	N	N	1	CUSTOMER ISSUE	-
DMS_42245	43503	N	N	N	1	CUSTOMER ISSUE	-
DMS_42246	43504	N	N	N	1	CUSTOMER ISSUE	-
DMS_42247	43505	N	N	N	1	CUSTOMER ISSUE	-
DMS_42248	43506	N	N	N	1	CUSTOMER ISSUE	-
DMS_42250	43507	N	N	N	1	CUSTOMER ISSUE	-
DMS_42251	43508	N	N	N	1	CUSTOMER ISSUE	-
DMS_42252	43509	N	N	N	1	CUSTOMER ISSUE	-
DMS_42253	43510	N	N	N	2	CUSTOMER ISSUE	-
DMS_42254	43511	N	N	N	1	CUSTOMER ISSUE	-
DMS_42255	43512	N	N	N	1	CUSTOMER ISSUE	-
DMS_42256	43513	N	N	N	1	CUSTOMER ISSUE	-
DMS_42257	43514	N	N	N	1	CUSTOMER ISSUE	-
DMS_42258	43515	N	N	N	1	CUSTOMER ISSUE	-
DMS_42260	43516	N	N	N	1	CUSTOMER ISSUE	-
DMS_42261	43517	N	N	N	1	CUSTOMER ISSUE	-
DMS_42262	43518	N	N	N	1	CUSTOMER ISSUE	-
DMS_42263	43519	N	N	N	1	CUSTOMER ISSUE	-
DMS_42264	43520	N	N	N	1	CUSTOMER ISSUE	-
DMS_42265	43521	N	N	N	1	CUSTOMER ISSUE	-
DMS_42266	43522	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42268	43523	N	N	N	1	CUSTOMER ISSUE	-
DMS_42269	43524	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42270	43525	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42271	43526	N	N	N	1	CUSTOMER ISSUE	-
DMS_42272	43527	N	N	N	1	CUSTOMER ISSUE	-
DMS_42273	43528	N	N	N	1	CUSTOMER ISSUE	-
DMS_42274	43529	N	N	N	1	CUSTOMER ISSUE	-
DMS_42275	43530	N	N	N	1	CUSTOMER ISSUE	-
DMS_42276	43531	N	N	N	1	CUSTOMER ISSUE	-
DMS_42277	43532	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42278	43533	N	N	N	1	CUSTOMER ISSUE	-
DMS_42279	43534	N	N	N	1	CUSTOMER ISSUE	-
DMS_42280	43535	N	N	N	1	CUSTOMER ISSUE	-
DMS_42281	43536	N	N	N	1	CUSTOMER ISSUE	-
DMS_42282	43537	N	N	N	1	CUSTOMER ISSUE	-
DMS_42283	43538	N	N	N	1	CUSTOMER ISSUE	-
DMS_42285	43539	N	N	N	1	CUSTOMER ISSUE	-
DMS_42286	43540	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42287	43541	N	N	N	1	CUSTOMER ISSUE	-
DMS_42288	43542	N	N	N	1	CUSTOMER ISSUE	-
DMS_42289	43543	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42290	43544	N	N	N	1	CUSTOMER ISSUE	-
DMS_42291	43545	N	N	N	1	CUSTOMER ISSUE	-
DMS_42292	43546	N	N	N	1	CUSTOMER ISSUE	-
DMS_42293	43547	N	N	N	1	CUSTOMER ISSUE	-
DMS_42294	43548	N	N	N	1	CUSTOMER ISSUE	-
DMS_42295	43549	N	N	N	1	CUSTOMER ISSUE	-
DMS_42296	43550	N	N	N	1	CUSTOMER ISSUE	-
DMS_42297	43551	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42298	43552	N	N	N	1	CUSTOMER ISSUE	-
DMS_42299	43553	N	N	N	1	CUSTOMER ISSUE	-
DMS_42300	43554	N	N	N	1	CUSTOMER ISSUE	-
DMS_42302	43555	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42303	43556	N	N	N	1	CUSTOMER ISSUE	-
DMS_42304	43557	N	N	N	1	CUSTOMER ISSUE	-
DMS_42305	43558	N	N	N	1	CUSTOMER ISSUE	-
DMS_42307	43559	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42311	43560	N	N	N	1	CUSTOMER ISSUE	-
DMS_42314	43561	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500
DMS_42315	43562	N	N	N	1	CUSTOMER ISSUE	-
DMS_42316	43563	N	N	N	1	CUSTOMER ISSUE	-
DMS_42317	43564	N	N	N	1	CUSTOMER ISSUE	-
DMS_42318	43565	N	N	N	1	CUSTOMER ISSUE	-
DMS_42319	43566	N	N	N	1	CUSTOMER ISSUE	-
DMS_42320	43567	N	N	N	1	CUSTOMER ISSUE	-
DMS_42321	43568	N	N	N	1	CUSTOMER ISSUE	-
DMS_42323	43569	N	N	N	1	CUSTOMER ISSUE	-
DMS_42324	43570	N	N	N	1	CUSTOMER ISSUE	-
DMS_42325	43571	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42326	43572	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42329	43573	N	N	N	1	CUSTOMER ISSUE	-
DMS_42330	43574	N	N	N	1	CUSTOMER ISSUE	-
DMS_42331	43575	N	N	N	1	CUSTOMER ISSUE	-
DMS_42332	43576	N	N	Y	1	DIST - TREE TRIMMING	945

DMS_42334	43577	N	N	N	1	CUSTOMER ISSUE	-
DMS_42335	43578	N	N	N	1	CUSTOMER ISSUE	-
DMS_42336	43579	N	N	N	1	CUSTOMER ISSUE	-
DMS_42337	43580	N	N	N	1	CUSTOMER ISSUE	-
DMS_42338	43581	N	N	N	1	CUSTOMER ISSUE	-
DMS_42339	43582	N	N	N	1	CUSTOMER ISSUE	-
DMS_42340	43583	N	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
DMS_42341	43584	N	N	N	1	CUSTOMER ISSUE	-
DMS_42342	43585	N	N	N	1	CUSTOMER ISSUE	-
DMS_42343	43586	N	N	N	1	CUSTOMER ISSUE	-
DMS_42344	43587	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42345	43588	N	N	N	1	CUSTOMER ISSUE	-
DMS_42346	43589	N	N	N	1	CUSTOMER ISSUE	-
DMS_42347	43590	N	N	N	1	CUSTOMER ISSUE	-
DMS_42348	43591	N	N	N	1	CUSTOMER ISSUE	-
DMS_42349	43592	N	N	N	1	CUSTOMER ISSUE	-
DMS_42350	43593	N	N	N	1	CUSTOMER ISSUE	-
DMS_42351	43594	N	N	N	1	CUSTOMER ISSUE	-
DMS_42352	43595	N	N	N	1	CUSTOMER ISSUE	-
DMS_42353	43596	N	N	N	1	CUSTOMER ISSUE	-
DMS_42354	43597	N	N	N	1	CUSTOMER ISSUE	-
DMS_42355	43598	N	N	N	1	CUSTOMER ISSUE	-
DMS_42356	43599	N	N	N	1	CUSTOMER ISSUE	-
DMS_42357	43600	N	N	N	1	CUSTOMER ISSUE	-
DMS_42358	43601	N	N	N	1	CUSTOMER ISSUE	-
DMS_42359	43602	N	N	N	1	CUSTOMER ISSUE	-
DMS_42360	43603	N	N	N	1	CUSTOMER ISSUE	-
DMS_42362	43604	N	N	N	1	CUSTOMER ISSUE	-
DMS_42363	43605	N	N	N	1	CUSTOMER ISSUE	-
DMS_42364	43606	N	N	N	1	CUSTOMER ISSUE	-
DMS_42365	43607	N	N	N	1	CUSTOMER ISSUE	-
DMS_42366	43608	N	N	N	1	CUSTOMER ISSUE	-
DMS_42367	43609	N	N	N	1	CUSTOMER ISSUE	-
DMS_42368	43610	N	N	N	1	CUSTOMER ISSUE	-
DMS_42369	43611	N	N	N	1	CUSTOMER ISSUE	-
DMS_42370	43612	N	N	N	1	CUSTOMER ISSUE	-
DMS_42371	43613	N	N	N	1	CUSTOMER ISSUE	-
DMS_42372	43614	N	N	N	1	CUSTOMER ISSUE	-
DMS_42373	43615	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42374	43616	N	N	N	1	CUSTOMER ISSUE	-
DMS_42375	43617	N	N	N	1	CUSTOMER ISSUE	-
DMS_42376	43618	N	N	N	1	CUSTOMER ISSUE	-
DMS_42377	43619	N	N	N	1	CUSTOMER ISSUE	-
DMS_42378	43620	N	N	N	1	CUSTOMER ISSUE	-
DMS_42379	43621	N	N	N	1	CUSTOMER ISSUE	-
DMS_42380	43622	N	N	N	1	CUSTOMER ISSUE	-
DMS_42381	43623	N	N	N	1	CUSTOMER ISSUE	-
DMS_42382	43624	N	N	N	1	CUSTOMER ISSUE	-
DMS_42383	43625	N	N	N	1	CUSTOMER ISSUE	-
DMS_42384	43626	N	N	N	1	CUSTOMER ISSUE	-
DMS_42385	43627	N	N	N	1	CUSTOMER ISSUE	-
DMS_42386	43628	N	N	N	1	CUSTOMER ISSUE	-
DMS_42387	43629	N	N	N	1	CUSTOMER ISSUE	-
DMS_42388	43630	N	N	N	1	CUSTOMER ISSUE	-
DMS_42390	43631	N	N	N	1	CUSTOMER ISSUE	-
DMS_42391	43632	N	N	N	1	CUSTOMER ISSUE	-
DMS_42392	43633	N	N	N	1	CUSTOMER ISSUE	-
DMS_42394	43634	N	N	N	1	CUSTOMER ISSUE	-
DMS_42395	43635	N	N	N	1	CUSTOMER ISSUE	-
DMS_42396	43636	N	N	N	1	CUSTOMER ISSUE	-
DMS_42397	43637	N	N	N	1	CUSTOMER ISSUE	-
DMS_42398	43638	N	N	N	1	CUSTOMER ISSUE	-
DMS_42399	43639	N	N	N	1	CUSTOMER ISSUE	-
DMS_42400	43640	N	N	N	1	CUSTOMER ISSUE	-
DMS_42402	43641	N	N	N	1	CUSTOMER ISSUE	-
DMS_42403	43642	N	N	N	1	CUSTOMER ISSUE	-
DMS_42404	43643	N	N	N	1	CUSTOMER ISSUE	-
DMS_42405	43644	N	N	N	1	CUSTOMER ISSUE	-
DMS_42406	43645	N	N	N	1	CUSTOMER ISSUE	-
DMS_42407	43646	N	N	N	1	CUSTOMER ISSUE	-
DMS_42408	43647	N	N	N	1	CUSTOMER ISSUE	-
DMS_42409	43648	N	N	N	1	CUSTOMER ISSUE	-
DMS_42410	43649	N	N	N	1	CUSTOMER ISSUE	-
DMS_42411	43650	N	N	N	1	CUSTOMER ISSUE	-
DMS_42412	43651	N	N	N	1	CUSTOMER ISSUE	-
DMS_42413	43652	N	N	N	1	CUSTOMER ISSUE	-
DMS_42414	43653	N	N	N	1	CUSTOMER ISSUE	-
DMS_42415	43654	N	N	N	1	CUSTOMER ISSUE	-
DMS_42418	43655	N	N	N	1	CUSTOMER ISSUE	-
DMS_42420	43656	N	N	N	1	CUSTOMER ISSUE	-

DMS_42421	43657	N	N	N	1	CUSTOMER ISSUE	-
DMS_42422	43658	N	N	N	1	CUSTOMER ISSUE	-
DMS_42423	43659	N	N	N	1	CUSTOMER ISSUE	-
DMS_42424	43660	N	N	N	1	CUSTOMER ISSUE	-
DMS_42425	43661	N	N	N	1	CUSTOMER ISSUE	-
DMS_42426	43662	N	N	N	1	CUSTOMER ISSUE	-
DMS_42427	43663	N	N	N	1	CUSTOMER ISSUE	-
DMS_42428	43664	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42429	43665	N	N	N	1	CUSTOMER ISSUE	-
DMS_42430	43666	N	N	N	1	CUSTOMER ISSUE	-
DMS_42431	43667	N	N	N	1	CUSTOMER ISSUE	-
DMS_42432	43668	N	N	N	1	CUSTOMER ISSUE	-
DMS_42434	43669	N	N	N	1	CUSTOMER ISSUE	-
DMS_42435	43670	N	N	N	1	CUSTOMER ISSUE	-
DMS_42436	43671	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42437	43672	N	N	N	1	CUSTOMER ISSUE	-
DMS_42438	43673	N	N	N	1	CUSTOMER ISSUE	-
DMS_42439	43674	N	N	N	1	CUSTOMER ISSUE	-
DMS_42440	43675	N	N	N	1	CUSTOMER ISSUE	-
DMS_42441	43676	N	N	N	1	CUSTOMER ISSUE	-
DMS_42442	43677	N	N	N	1	CUSTOMER ISSUE	-
DMS_42443	43678	N	N	N	1	CUSTOMER ISSUE	-
DMS_42444	43679	N	N	N	1	CUSTOMER ISSUE	-
DMS_42445	43680	N	N	N	1	CUSTOMER ISSUE	-
DMS_42446	43681	N	N	N	1	CUSTOMER ISSUE	-
DMS_42447	43682	N	N	N	1	CUSTOMER ISSUE	-
DMS_42448	43683	N	N	N	1	CUSTOMER ISSUE	-
DMS_42449	43684	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42450	43685	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42452	43686	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42453	43687	N	N	N	1	CUSTOMER ISSUE	-
DMS_42455	43688	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42456	43689	N	N	N	1	CUSTOMER ISSUE	-
DMS_42458	43690	N	N	N	1	CUSTOMER ISSUE	-
DMS_42459	43691	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42460	43692	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_42466	43693	N	N	N	1	CUSTOMER ISSUE	-
DMS_42467	43694	N	N	N	1	CUSTOMER ISSUE	-
DMS_42468	43695	N	N	N	1	CUSTOMER ISSUE	-
DMS_42470	43696	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42471	43697	N	N	N	1	CUSTOMER ISSUE	-
DMS_42472	43698	N	N	N	1	CUSTOMER ISSUE	-
DMS_42473	43699	N	N	N	1	CUSTOMER ISSUE	-
DMS_42474	43700	N	N	N	1	CUSTOMER ISSUE	-
DMS_42475	43701	N	N	N	1	CUSTOMER ISSUE	-
DMS_42476	43702	N	N	N	1	CUSTOMER ISSUE	-
DMS_42477	43703	N	N	N	1	CUSTOMER ISSUE	-
DMS_42478	43704	N	N	N	1	CUSTOMER ISSUE	-
DMS_42479	43705	N	N	N	1	CUSTOMER ISSUE	-
DMS_42480	43706	N	N	N	1	CUSTOMER ISSUE	-
DMS_42481	43707	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42482	43708	N	N	N	1	CUSTOMER ISSUE	-
DMS_42484	43709	N	N	N	1	CUSTOMER ISSUE	-
DMS_42485	43710	N	N	N	1	CUSTOMER ISSUE	-
DMS_42486	43711	N	N	N	1	CUSTOMER ISSUE	-
DMS_42487	43712	N	N	N	1	CUSTOMER ISSUE	-
DMS_42488	43713	N	N	N	1	CUSTOMER ISSUE	-
DMS_42490	43714	N	N	N	1	CUSTOMER ISSUE	-
DMS_42491	43715	N	N	N	1	CUSTOMER ISSUE	-
DMS_42492	43716	N	N	N	1	CUSTOMER ISSUE	-
DMS_42493	43717	N	N	N	1	CUSTOMER ISSUE	-
DMS_42495	43718	N	N	N	1	CUSTOMER ISSUE	-
DMS_42496	43719	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42497	43720	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42498	43721	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42499	43722	N	N	N	1	CUSTOMER ISSUE	-
DMS_42500	43723	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42501	43724	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42502	43725	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42503	43726	N	N	N	1	CUSTOMER ISSUE	-
DMS_42504	43727	N	N	N	1	CUSTOMER ISSUE	-
DMS_42505	43728	N	N	N	1	CUSTOMER ISSUE	-
DMS_42506	43729	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42507	43730	N	N	N	1	CUSTOMER ISSUE	-
DMS_42508	43731	N	N	N	1	CUSTOMER ISSUE	-
DMS_42510	43732	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42511	43733	N	N	N	1	CUSTOMER ISSUE	-
DMS_42512	43734	N	N	N	1	CUSTOMER ISSUE	-
DMS_42515	43735	N	N	N	1	CUSTOMER ISSUE	-
DMS_42516	43736	N	N	N	1	CUSTOMER ISSUE	-

DMS_42517	43737	N	N	N	1	CUSTOMER ISSUE	-
DMS_42518	43738	N	N	N	1	CUSTOMER ISSUE	-
DMS_42519	43739	N	N	N	1	CUSTOMER ISSUE	-
DMS_42520	43740	N	N	N	1	CUSTOMER ISSUE	-
DMS_42521	43741	N	N	N	1	CUSTOMER ISSUE	-
DMS_42522	43742	N	N	N	1	CUSTOMER ISSUE	-
DMS_42523	43743	N	N	N	1	CUSTOMER ISSUE	-
DMS_42524	43744	N	N	N	1	CUSTOMER ISSUE	-
DMS_42525	43745	N	N	N	1	CUSTOMER ISSUE	-
DMS_42526	43746	N	N	N	1	CUSTOMER ISSUE	-
DMS_42527	43747	N	N	N	1	CUSTOMER ISSUE	-
DMS_42528	43748	N	N	N	1	CUSTOMER ISSUE	-
DMS_42529	43749	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42530	43750	N	N	N	1	CUSTOMER ISSUE	-
DMS_42531	43751	N	N	N	1	CUSTOMER ISSUE	-
DMS_42532	43752	N	N	N	1	CUSTOMER ISSUE	-
DMS_42533	43753	N	N	N	1	CUSTOMER ISSUE	-
DMS_42534	43754	N	N	N	1	CUSTOMER ISSUE	-
DMS_42535	43755	N	N	N	1	CUSTOMER ISSUE	-
DMS_42537	43756	N	N	N	1	CUSTOMER ISSUE	-
DMS_42538	43757	N	N	N	1	CUSTOMER ISSUE	-
DMS_42539	43758	N	N	N	1	CUSTOMER ISSUE	-
DMS_42540	43759	N	N	N	1	CUSTOMER ISSUE	-
DMS_42541	43760	N	N	N	1	CUSTOMER ISSUE	-
DMS_42542	43761	N	N	N	1	CUSTOMER ISSUE	-
DMS_42543	43762	N	N	N	1	CUSTOMER ISSUE	-
DMS_42544	43763	N	N	N	1	CUSTOMER ISSUE	-
DMS_42545	43764	N	N	N	1	CUSTOMER ISSUE	-
DMS_42546	43765	N	N	N	1	CUSTOMER ISSUE	-
DMS_42547	43766	N	N	N	1	CUSTOMER ISSUE	-
DMS_42548	43767	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_42549	43768	N	N	N	1	CUSTOMER ISSUE	-
DMS_42550	43769	N	N	N	1	CUSTOMER ISSUE	-
DMS_42551	43770	N	N	N	1	CUSTOMER ISSUE	-
DMS_42552	43771	N	N	N	1	CUSTOMER ISSUE	-
DMS_42553	43772	N	N	N	1	CUSTOMER ISSUE	-
DMS_42554	43773	N	N	N	1	CUSTOMER ISSUE	-
DMS_42556	43774	N	N	N	1	CUSTOMER ISSUE	-
DMS_42557	43775	N	N	N	1	CUSTOMER ISSUE	-
DMS_42558	43776	N	N	N	1	CUSTOMER ISSUE	-
DMS_42559	43777	N	N	N	1	CUSTOMER ISSUE	-
DMS_42560	43778	N	N	N	1	CUSTOMER ISSUE	-
DMS_42561	43779	N	N	N	1	CUSTOMER ISSUE	-
DMS_42562	43780	N	N	N	1	CUSTOMER ISSUE	-
DMS_42563	43781	N	N	N	1	CUSTOMER ISSUE	-
DMS_42564	43782	N	N	N	1	CUSTOMER ISSUE	-
DMS_42565	43783	N	N	N	1	CUSTOMER ISSUE	-
DMS_42566	43784	N	N	N	1	CUSTOMER ISSUE	-
DMS_42567	43785	N	N	N	1	CUSTOMER ISSUE	-
DMS_42568	43786	N	N	N	1	CUSTOMER ISSUE	-
DMS_42569	43787	N	N	N	1	CUSTOMER ISSUE	-
DMS_42570	43788	N	N	N	1	CUSTOMER ISSUE	-
DMS_42571	43789	N	N	N	1	CUSTOMER ISSUE	-
DMS_42572	43790	N	N	N	1	CUSTOMER ISSUE	-
DMS_42573	43791	N	N	N	1	CUSTOMER ISSUE	-
DMS_42574	43792	N	N	N	1	CUSTOMER ISSUE	-
DMS_42575	43793	N	N	N	1	CUSTOMER ISSUE	-
DMS_42576	43794	N	N	N	1	CUSTOMER ISSUE	-
DMS_42577	43795	N	N	N	1	CUSTOMER ISSUE	-
DMS_42578	43796	N	N	N	1	CUSTOMER ISSUE	-
DMS_42579	43797	N	N	N	1	CUSTOMER ISSUE	-
DMS_42580	43798	N	N	N	1	CUSTOMER ISSUE	-
DMS_42581	43799	N	N	N	1	CUSTOMER ISSUE	-
DMS_42582	43800	N	N	N	1	CUSTOMER ISSUE	-
DMS_42584	43801	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42585	43802	N	N	N	1	CUSTOMER ISSUE	-
DMS_42586	43803	N	N	N	1	CUSTOMER ISSUE	-
DMS_42588	43804	N	N	N	1	CUSTOMER ISSUE	-
DMS_42589	43805	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42590	43806	N	N	N	1	CUSTOMER ISSUE	-
DMS_42591	43807	N	N	N	1	CUSTOMER ISSUE	-
DMS_42593	43808	N	N	N	1	CUSTOMER ISSUE	-
DMS_42594	43809	N	N	N	1	CUSTOMER ISSUE	-
DMS_42595	43810	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42596	43811	N	N	N	1	CUSTOMER ISSUE	-
DMS_42597	43812	N	N	N	1	CUSTOMER ISSUE	-
DMS_42599	43813	N	N	N	1	CUSTOMER ISSUE	-
DMS_42601	43814	N	N	N	1	CUSTOMER ISSUE	-
DMS_42602	43815	N	N	N	1	CUSTOMER ISSUE	-
DMS_42603	43816	N	N	N	1	CUSTOMER ISSUE	-

DMS_42604	43817	N	N	N	1	CUSTOMER ISSUE	-
DMS_42605	43818	N	N	N	1	CUSTOMER ISSUE	-
DMS_42606	43819	N	N	N	1	CUSTOMER ISSUE	-
DMS_42607	43820	N	N	N	1	CUSTOMER ISSUE	-
DMS_42608	43821	N	N	N	1	CUSTOMER ISSUE	-
DMS_42609	43822	N	N	N	1	CUSTOMER ISSUE	-
DMS_42610	43823	N	N	N	1	CUSTOMER ISSUE	-
DMS_42611	43824	N	N	N	1	CUSTOMER ISSUE	-
DMS_42612	43825	N	N	N	1	CUSTOMER ISSUE	-
DMS_42613	43826	N	N	N	1	CUSTOMER ISSUE	-
DMS_42614	43827	N	N	N	1	CUSTOMER ISSUE	-
DMS_42615	43828	N	N	N	1	CUSTOMER ISSUE	-
DMS_42616	43829	N	N	N	1	CUSTOMER ISSUE	-
DMS_42617	43830	N	N	N	1	CUSTOMER ISSUE	-
DMS_42618	43831	N	N	N	1	CUSTOMER ISSUE	-
DMS_42619	43832	N	N	N	1	CUSTOMER ISSUE	-
DMS_42620	43833	N	N	N	1	CUSTOMER ISSUE	-
DMS_42621	43834	N	N	N	1	CUSTOMER ISSUE	-
DMS_42622	43835	N	N	N	1	CUSTOMER ISSUE	-
DMS_42623	43836	N	N	N	1	CUSTOMER ISSUE	-
DMS_42624	43837	N	N	N	1	CUSTOMER ISSUE	-
DMS_42625	43838	N	N	N	1	CUSTOMER ISSUE	-
DMS_42626	43839	N	N	N	1	CUSTOMER ISSUE	-
DMS_42627	43840	N	N	N	1	CUSTOMER ISSUE	-
DMS_42628	43841	N	N	N	1	CUSTOMER ISSUE	-
DMS_42629	43842	N	N	N	1	CUSTOMER ISSUE	-
DMS_42631	43843	N	N	N	1	CUSTOMER ISSUE	-
DMS_42633	43844	N	N	N	1	CUSTOMER ISSUE	-
DMS_42634	43845	N	N	N	1	CUSTOMER ISSUE	-
DMS_42635	43846	N	N	N	1	CUSTOMER ISSUE	-
DMS_42638	43847	N	N	N	1	CUSTOMER ISSUE	-
DMS_42639	43848	N	N	N	1	CUSTOMER ISSUE	-
DMS_42640	43849	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42643	43850	N	N	N	1	CUSTOMER ISSUE	-
DMS_42645	43851	N	N	N	1	CUSTOMER ISSUE	-
DMS_42646	43852	N	N	N	1	CUSTOMER ISSUE	-
DMS_42647	43853	N	N	N	1	CUSTOMER ISSUE	-
DMS_42648	43854	N	N	N	1	CUSTOMER ISSUE	-
DMS_42649	43855	N	N	N	1	CUSTOMER ISSUE	-
DMS_42650	43856	N	N	N	2	CUSTOMER ISSUE	-
DMS_42651	43857	N	N	N	1	CUSTOMER ISSUE	-
DMS_42652	43858	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42653	43859	N	N	N	1	CUSTOMER ISSUE	-
DMS_42655	43860	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42656	43861	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42657	43862	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42659	43863	N	N	N	1	CUSTOMER ISSUE	-
DMS_42660	43864	N	N	N	1	CUSTOMER ISSUE	-
DMS_42661	43865	N	N	Y	1	TX - REPLACE	2500
DMS_42662	43866	N	N	N	1	CUSTOMER ISSUE	-
DMS_42663	43867	N	N	N	1	CUSTOMER ISSUE	-
DMS_42665	43868	N	N	N	1	CUSTOMER ISSUE	-
DMS_42666	43869	N	N	N	1	CUSTOMER ISSUE	-
DMS_42667	43870	N	N	N	1	CUSTOMER ISSUE	-
DMS_42668	43871	N	N	N	1	CUSTOMER ISSUE	-
DMS_42669	43872	N	N	N	1	CUSTOMER ISSUE	-
DMS_42670	43873	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42671	43874	N	N	N	1	CUSTOMER ISSUE	-
DMS_42674	43875	N	N	N	1	CUSTOMER ISSUE	-
DMS_42675	43876	N	N	N	1	CUSTOMER ISSUE	-
DMS_42676	43877	N	N	N	1	CUSTOMER ISSUE	-
DMS_42677	43878	N	N	N	1	CUSTOMER ISSUE	-
DMS_42678	43879	N	N	N	1	CUSTOMER ISSUE	-
DMS_42679	43880	N	N	N	1	CUSTOMER ISSUE	-
DMS_42680	43881	N	N	N	1	CUSTOMER ISSUE	-
DMS_42681	43882	N	N	N	1	CUSTOMER ISSUE	-
DMS_42685	43883	N	N	N	1	CUSTOMER ISSUE	-
DMS_42686	43884	N	N	N	1	CUSTOMER ISSUE	-
DMS_42688	43885	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42689	43886	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42690	43887	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42691	43888	N	N	N	1	CUSTOMER ISSUE	-
DMS_42692	43889	N	N	N	1	CUSTOMER ISSUE	-
DMS_42693	43890	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42694	43891	N	N	N	1	CUSTOMER ISSUE	-
DMS_42695	43892	N	N	N	1	CUSTOMER ISSUE	-
DMS_42696	43893	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42697	43894	N	N	N	1	CUSTOMER ISSUE	-
DMS_42698	43895	N	N	N	1	CUSTOMER ISSUE	-
DMS_42699	43896	N	N	N	1	CUSTOMER ISSUE	-

DMS_42700	43897	N	N	N	1	CUSTOMER ISSUE	-
DMS_42701	43898	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42702	43899	N	N	N	1	CUSTOMER ISSUE	-
DMS_42703	43900	N	N	N	1	CUSTOMER ISSUE	-
DMS_42704	43901	N	N	N	1	CUSTOMER ISSUE	-
DMS_42705	43902	N	N	N	1	CUSTOMER ISSUE	-
DMS_42706	43903	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42707	43904	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42708	43905	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42709	43906	N	N	N	1	CUSTOMER ISSUE	-
DMS_42710	43907	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42711	43908	N	N	N	1	CUSTOMER ISSUE	-
DMS_42712	43909	N	N	N	1	CUSTOMER ISSUE	-
DMS_42713	43910	N	N	N	1	CUSTOMER ISSUE	-
DMS_42714	43911	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42715	43912	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42718	43913	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42720	43914	N	N	N	1	CUSTOMER ISSUE	-
DMS_42721	43915	N	N	N	1	CUSTOMER ISSUE	-
DMS_42722	43916	N	N	N	1	CUSTOMER ISSUE	-
DMS_42724	43917	N	N	N	1	CUSTOMER ISSUE	-
DMS_42727	43918	N	N	N	1	CUSTOMER ISSUE	-
DMS_42728	43919	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42729	43920	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42730	43921	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42731	43922	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42732	43923	N	N	N	1	CUSTOMER ISSUE	-
DMS_42733	43924	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_42735	43925	N	N	N	1	CUSTOMER ISSUE	-
DMS_42736	43926	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42737	43927	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_42738	43928	N	N	N	1	CUSTOMER ISSUE	-
DMS_42741	43929	N	N	N	1	CUSTOMER ISSUE	-
DMS_42742	43930	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_42746	43931	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42747	43932	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42748	43933	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42749	43934	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42750	43935	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42751	43936	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42752	43937	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42753	43938	N	N	N	1	CUSTOMER ISSUE	-
DMS_42755	43939	N	N	N	1	CUSTOMER ISSUE	-
DMS_42756	43940	N	N	N	1	CUSTOMER ISSUE	-
DMS_42758	43941	N	N	N	1	CUSTOMER ISSUE	-
DMS_42759	43942	N	N	N	1	CUSTOMER ISSUE	-
DMS_42760	43943	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42762	43944	N	N	N	1	CUSTOMER ISSUE	-
DMS_42763	43945	N	N	N	1	CUSTOMER ISSUE	-
DMS_42767	43946	N	N	N	1	CUSTOMER ISSUE	-
DMS_42768	43947	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42769	43948	N	N	N	1	CUSTOMER ISSUE	-
DMS_42770	43949	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42771	43950	N	N	N	1	CUSTOMER ISSUE	-
DMS_42772	43951	N	N	N	1	CUSTOMER ISSUE	-
DMS_42773	43952	N	N	N	1	CUSTOMER ISSUE	-
DMS_42774	43953	N	N	N	1	CUSTOMER ISSUE	-
DMS_42775	43954	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_42776	43955	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_42777	43956	N	N	N	1	CUSTOMER ISSUE	-
DMS_42778	43957	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_42780	43958	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42782	43959	N	N	N	1	CUSTOMER ISSUE	-
DMS_42783	43960	N	N	N	1	CUSTOMER ISSUE	-
DMS_42784	43961	N	N	N	1	CUSTOMER ISSUE	-
DMS_42785	43962	N	N	N	1	CUSTOMER ISSUE	-
DMS_42786	43963	N	N	N	1	CUSTOMER ISSUE	-
DMS_42787	43964	N	N	N	1	CUSTOMER ISSUE	-
DMS_42790	43965	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42791	43966	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42792	43967	N	N	N	1	CUSTOMER ISSUE	-
DMS_42793	43968	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42794	43969	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42795	43970	N	N	N	1	CUSTOMER ISSUE	-
DMS_42796	43971	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42797	43972	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42798	43973	N	N	N	1	CUSTOMER ISSUE	-
DMS_42799	43974	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42800	43975	N	N	N	1	CUSTOMER ISSUE	-
DMS_42801	43976	N	N	N	1	CUSTOMER ISSUE	-

DMS_42802	43977	N	N	N	1	CUSTOMER ISSUE	-
DMS_42803	43978	N	N	N	1	CUSTOMER ISSUE	-
DMS_42804	43979	N	N	N	1	CUSTOMER ISSUE	-
DMS_42805	43980	N	N	N	1	CUSTOMER ISSUE	-
DMS_42807	43981	N	N	N	1	CUSTOMER ISSUE	-
DMS_42808	43982	N	N	N	1	CUSTOMER ISSUE	-
DMS_42809	43983	N	N	N	1	CUSTOMER ISSUE	-
DMS_42810	43984	N	N	N	1	CUSTOMER ISSUE	-
DMS_42811	43985	N	N	N	1	CUSTOMER ISSUE	-
DMS_42812	43986	N	N	N	1	CUSTOMER ISSUE	-
DMS_42813	43987	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42815	43988	N	N	N	1	CUSTOMER ISSUE	-
DMS_42816	43989	N	N	N	1	CUSTOMER ISSUE	-
DMS_42817	43990	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42818	43991	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42819	43992	N	N	N	1	CUSTOMER ISSUE	-
DMS_42831	43993	N	N	N	1	CUSTOMER ISSUE	-
DMS_42832	43994	N	N	N	1	CUSTOMER ISSUE	-
DMS_42833	43995	N	N	N	1	CUSTOMER ISSUE	-
DMS_42834	43996	N	N	N	1	CUSTOMER ISSUE	-
DMS_42835	43997	N	N	N	1	CUSTOMER ISSUE	-
DMS_42836	43998	N	N	N	1	CUSTOMER ISSUE	-
DMS_42837	43999	N	N	N	1	CUSTOMER ISSUE	-
DMS_42838	44000	N	N	N	1	CUSTOMER ISSUE	-
DMS_42839	44001	N	N	N	1	CUSTOMER ISSUE	-
DMS_42840	44002	N	N	N	1	CUSTOMER ISSUE	-
DMS_42841	44003	N	N	N	1	CUSTOMER ISSUE	-
DMS_42842	44004	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42843	44005	N	N	Y	1	TX - REPLACE	2500
DMS_42844	44006	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42845	44007	N	N	N	1	CUSTOMER ISSUE	-
DMS_42846	44008	N	N	N	1	CUSTOMER ISSUE	-
DMS_42847	44009	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_42849	44010	N	N	Y	1	TX - REPLACE	2500
DMS_42850	44011	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42852	44012	N	N	Y	1	TX - REPLACE	2500
DMS_42853	44013	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42855	44014	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42856	44015	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42858	44016	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42859	44017	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42860	44018	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42862	44019	N	N	Y	1	TX - REPLACE	2500
DMS_42864	44020	N	N	Y	1	TX - REPLACE	2500
DMS_42865	44021	N	N	Y	1	TX - REPLACE	2500
DMS_42866	44022	N	N	N	1	CUSTOMER ISSUE	-
DMS_42867	44023	N	N	Y	1	TX - REPLACE	2500
DMS_42868	44024	N	N	Y	1	TX - REPLACE	2500
DMS_42869	44025	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_42870	44026	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42871	44027	N	N	Y	1	TX - REPLACE	2500
DMS_42872	44028	N	N	Y	1	TX - REPLACE	2500
DMS_42873	44029	N	N	Y	2	TX - REPLACE	2500
DMS_42874	44030	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42876	44031	N	N	Y	1	TX - REPLACE	2500
DMS_42878	44032	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42879	44033	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42880	44034	N	N	Y	1	TX - REPLACE	2500
DMS_42881	44035	N	N	Y	1	TX - REPLACE	2500
DMS_42882	44036	N	N	N	1	CUSTOMER ISSUE	-
DMS_42883	44037	N	N	N	1	CUSTOMER ISSUE	-
DMS_42884	44038	N	N	N	1	CUSTOMER ISSUE	-
DMS_42887	44039	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42888	44040	N	N	N	1	CUSTOMER ISSUE	-
DMS_42889	44041	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_42890	44042	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42892	44043	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42895	44044	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_42897	44045	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_42899	44046	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42901	44047	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_42902	44048	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_42903	44049	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42905	44050	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42906	44051	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_42908	44052	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42910	44053	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42911	44054	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42914	44055	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_42915	44056	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_42916	44057	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42917	44058	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42918	44059	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42921	44060	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42922	44061	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42923	44062	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42924	44063	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42925	44064	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42926	44065	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42927	44066	N	N	N	1	CUSTOMER ISSUE	-
DMS_42930	44067	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42935	44068	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_42936	44069	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42938	44070	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42939	44071	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42940	44072	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_42941	44073	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42942	44074	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42943	44075	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42944	44076	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42945	44077	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42947	44078	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42948	44079	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42949	44080	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42950	44081	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42952	44082	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42953	44083	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42954	44084	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42955	44085	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42956	44086	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42957	44087	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42960	44088	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42961	44089	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42962	44090	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42963	44091	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42965	44092	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42966	44093	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42968	44094	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42969	44095	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42972	44096	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42973	44097	N	N	N	1	CUSTOMER ISSUE	-
DMS_42974	44098	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42975	44099	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42976	44100	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42977	44101	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42978	44102	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_42979	44103	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42980	44104	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_42981	44105	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42982	44106	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42983	44107	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_42984	44108	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_42986	44109	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42988	44110	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42989	44111	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42990	44112	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_42996	44113	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42997	44114	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42998	44115	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_42999	44116	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43003	44117	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_43004	44118	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43006	44119	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43007	44120	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43008	44121	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43010	44122	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43011	44123	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43012	44124	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43013	44125	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43014	44126	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_43016	44127	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43017	44128	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43018	44129	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43023	44130	N	N	N	1	CUSTOMER ISSUE	-
DMS_43024	44131	N	N	N	1	CUSTOMER ISSUE	-
DMS_43025	44132	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43034	44133	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_43037	44134	N	N	Y	1	TX - REPLACE	2500
DMS_43040	44135	N	N	N	1	CUSTOMER ISSUE	-
DMS_43041	44136	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_43042	44137	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43043	44138	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43044	44139	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43045	44140	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43046	44141	N	N	N	1	CUSTOMER ISSUE	-
DMS_43047	44142	N	N	N	1	CUSTOMER ISSUE	-
DMS_43048	44143	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43049	44144	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43053	44145	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43054	44146	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43055	44147	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43058	44148	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43061	44149	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43064	44150	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43065	44151	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_43066	44152	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43072	44153	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43073	44154	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43074	44155	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43075	44156	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43076	44157	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43077	44158	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43078	44159	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43080	44160	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43081	44161	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43082	44162	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43083	44163	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43087	44164	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43089	44165	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43091	44166	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43092	44167	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43093	44168	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43094	44169	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43095	44170	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43096	44171	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_43097	44172	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43098	44173	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43099	44174	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43100	44175	N	N	N	1	CUSTOMER ISSUE	-
DMS_43101	44176	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_43102	44177	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43103	44178	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43104	44179	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_43106	44180	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43107	44181	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43109	44182	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43111	44183	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43112	44184	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43113	44185	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43114	44186	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43115	44187	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43122	44188	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_43123	44189	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43124	44190	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43125	44191	N	N	N	1	CUSTOMER ISSUE	-
DMS_43126	44192	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_43129	44193	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43138	44194	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43143	44195	N	N	N	1	CUSTOMER ISSUE	-
DMS_43148	44196	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43157	44197	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43167	44198	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43171	44199	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43174	44200	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43181	44201	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_43182	44202	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43184	44203	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43185	44204	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43186	44205	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43187	44206	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43188	44207	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43191	44208	N	N	N	1	CUSTOMER ISSUE	-
DMS_43192	44209	N	N	N	1	CUSTOMER ISSUE	-
DMS_43193	44210	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_43198	44211	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43199	44212	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43201	44213	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43202	44214	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43205	44215	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43206	44216	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_43207	44217	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43208	44218	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43210	44219	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43211	44220	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43212	44221	N	N	N	1	CUSTOMER ISSUE	-
DMS_43215	44222	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43216	44223	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43217	44224	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43222	44225	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43224	44226	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43225	44227	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43226	44228	N	N	N	1	CUSTOMER ISSUE	-
DMS_43227	44229	N	N	N	1	CUSTOMER ISSUE	-
DMS_43228	44230	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43229	44231	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43230	44232	N	N	N	1	CUSTOMER ISSUE	-
DMS_43231	44233	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43232	44234	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43233	44235	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43234	44236	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43235	44237	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43236	44238	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43237	44239	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43238	44240	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43239	44241	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43240	44242	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43241	44243	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43242	44244	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43243	44245	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43244	44246	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43245	44247	N	N	N	1	CUSTOMER ISSUE	-
DMS_43246	44248	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43247	44249	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_43248	44250	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43249	44251	N	N	N	1	CUSTOMER ISSUE	-
DMS_43250	44252	N	N	N	1	CUSTOMER ISSUE	-
DMS_43252	44253	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43253	44254	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43254	44255	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43255	44256	N	N	N	1	CUSTOMER ISSUE	-
DMS_43256	44257	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43257	44258	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_43259	44259	N	N	N	1	CUSTOMER ISSUE	-
DMS_43261	44260	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43262	44261	N	N	N	3	CUSTOMER ISSUE	-
DMS_43264	44262	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43265	44263	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43266	44264	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43267	44265	N	N	N	1	CUSTOMER ISSUE	-
DMS_43268	44266	N	N	N	1	CUSTOMER ISSUE	-
DMS_43269	44267	N	N	N	2	CUSTOMER ISSUE	-
DMS_43270	44268	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43271	44269	N	N	N	1	CUSTOMER ISSUE	-
DMS_43272	44270	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43273	44271	N	N	N	1	CUSTOMER ISSUE	-
DMS_43274	44272	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43275	44273	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43276	44274	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43278	44275	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43279	44276	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43281	44277	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43283	44278	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43285	44279	N	N	Y	4	SEC/SVC - REPAIR	472.5
DMS_43286	44280	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43288	44281	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43289	44282	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43292	44283	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43294	44284	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43295	44285	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43296	44286	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43299	44287	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43300	44288	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43301	44289	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43302	44290	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_43303	44291	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43304	44292	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43307	44293	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43308	44294	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43309	44295	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43310	44296	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_43311	44297	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_43313	44298	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43314	44299	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43315	44300	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43316	44301	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43317	44302	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43318	44303	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43320	44304	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43321	44305	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43322	44306	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_43323	44307	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43324	44308	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43325	44309	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43326	44310	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43328	44311	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43330	44312	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43331	44313	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43332	44314	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43333	44315	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43334	44316	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43335	44317	N	N	Y	3	DIST - TREE TRIMMING	945
DMS_43336	44318	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43337	44319	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43338	44320	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_43339	44321	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43340	44322	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43341	44323	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_43343	44324	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43344	44325	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43345	44326	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43346	44327	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43347	44328	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43348	44329	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43349	44330	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43350	44331	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43351	44332	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43352	44333	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43354	44334	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43355	44335	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43356	44336	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43357	44337	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43358	44338	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43359	44339	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43360	44340	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43361	44341	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43362	44342	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43363	44343	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43364	44344	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43365	44345	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43366	44346	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43367	44347	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43368	44348	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43369	44349	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43370	44350	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43371	44351	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43372	44352	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43373	44353	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43374	44354	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43375	44355	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43376	44356	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43377	44357	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43378	44358	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43379	44359	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43380	44360	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43381	44361	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43382	44362	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43383	44363	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43384	44364	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43385	44365	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43386	44366	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43387	44367	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43388	44368	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_43389	44369	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43390	44370	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43391	44371	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43392	44372	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43393	44373	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43394	44374	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_43395	44375	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43396	44376	N	N	Y	1	DIST - TREE TRIMMING	945

DMS_43397	44377	N	N	N	1	CUSTOMER ISSUE	-
DMS_43398	44378	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43399	44379	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43401	44380	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43402	44381	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43403	44382	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43404	44383	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43405	44384	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43406	44385	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43407	44386	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43408	44387	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43409	44388	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43410	44389	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43411	44390	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43412	44391	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_43413	44392	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43414	44393	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43415	44394	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43416	44395	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43417	44396	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43418	44397	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43419	44398	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43420	44399	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43421	44400	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43422	44401	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43423	44402	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43424	44403	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43425	44404	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43426	44405	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43427	44406	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43428	44407	N	N	N	1	CUSTOMER ISSUE	-
DMS_43429	44408	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43430	44409	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43431	44410	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43433	44411	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43434	44412	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_43435	44413	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_43436	44414	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43438	44415	N	N	N	1	CUSTOMER ISSUE	-
DMS_43440	44416	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43441	44417	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43442	44418	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43445	44419	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43450	44420	N	N	N	1	CUSTOMER ISSUE	-
DMS_43451	44421	N	N	Y	3	SEC/SVC - REPLACE	708.75
DMS_43452	44422	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43457	44423	N	N	N	1	CUSTOMER ISSUE	-
DMS_43458	44424	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43459	44425	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43461	44426	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43462	44427	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43463	44428	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43465	44429	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43468	44430	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43469	44431	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43470	44432	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43473	44433	N	N	N	1	CUSTOMER ISSUE	-
DMS_43474	44434	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43478	44435	N	N	N	1	CUSTOMER ISSUE	-
DMS_43479	44436	N	N	N	1	CUSTOMER ISSUE	-
DMS_43481	44437	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43482	44438	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_43484	44439	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43487	44440	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43488	44441	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43489	44442	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43490	44443	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43491	44444	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43493	44445	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43495	44446	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_43496	44447	N	N	N	1	CUSTOMER ISSUE	-
DMS_43497	44448	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43500	44449	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43502	44450	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43504	44451	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43506	44452	N	N	N	1	CUSTOMER ISSUE	-
DMS_43507	44453	N	N	N	1	CUSTOMER ISSUE	-
DMS_43508	44454	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43510	44455	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43511	44456	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_43512	44457	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43513	44458	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_43514	44459	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43517	44460	N	N	N	1	CUSTOMER ISSUE	-
DMS_43518	44461	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43520	44462	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43521	44463	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43522	44464	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43523	44465	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43525	44466	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43527	44467	N	N	N	1	CUSTOMER ISSUE	-
DMS_43528	44468	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43531	44469	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43533	44470	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43534	44471	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43535	44472	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43536	44473	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43537	44474	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43539	44475	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43542	44476	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43545	44477	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43546	44478	N	N	N	1	CUSTOMER ISSUE	-
DMS_43547	44479	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43548	44480	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_43551	44481	N	N	N	1	CUSTOMER ISSUE	-
DMS_43552	44482	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43553	44483	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43555	44484	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43557	44485	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43559	44486	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43560	44487	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_43562	44488	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43563	44489	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43564	44490	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43567	44491	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43568	44492	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43571	44493	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43580	44494	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43585	44495	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43586	44496	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43587	44497	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43588	44498	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43593	44499	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43597	44500	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43598	44501	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43601	44502	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43602	44503	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43603	44504	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43606	44505	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43607	44506	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43609	44507	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43610	44508	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43611	44509	N	N	N	1	CUSTOMER ISSUE	-
DMS_43612	44510	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43613	44511	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_43614	44512	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43615	44513	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43616	44514	N	N	N	1	CUSTOMER ISSUE	-
DMS_43617	44515	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43618	44516	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43619	44517	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43623	44518	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43624	44519	N	N	N	1	CUSTOMER ISSUE	-
DMS_43625	44520	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43626	44521	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43627	44522	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43629	44523	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43630	44524	N	N	N	1	CUSTOMER ISSUE	-
DMS_43635	44525	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43636	44526	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43638	44527	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43639	44528	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43641	44529	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43642	44530	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43643	44531	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43644	44532	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43645	44533	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43646	44534	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43648	44535	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43649	44536	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_43651	44537	N	N	Y	4	DIST - TREE TRIMMING	945
DMS_43653	44538	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43654	44539	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43655	44540	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43656	44541	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43657	44542	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43660	44543	N	N	N	1	CUSTOMER ISSUE	-
DMS_43661	44544	N	N	N	1	CUSTOMER ISSUE	-
DMS_43662	44545	N	N	N	1	CUSTOMER ISSUE	-
DMS_43663	44546	N	N	N	1	CUSTOMER ISSUE	-
DMS_43664	44547	N	N	N	1	CUSTOMER ISSUE	-
DMS_43665	44548	N	N	N	1	CUSTOMER ISSUE	-
DMS_43666	44549	N	N	N	1	CUSTOMER ISSUE	-
DMS_43669	44550	N	N	N	1	CUSTOMER ISSUE	-
DMS_43670	44551	N	N	N	1	CUSTOMER ISSUE	-
DMS_43671	44552	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43672	44553	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43673	44554	N	N	N	1	CUSTOMER ISSUE	-
DMS_43674	44555	N	N	N	1	CUSTOMER ISSUE	-
DMS_43678	44556	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_43681	44557	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_43682	44558	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43685	44559	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43688	44560	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43689	44561	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43690	44562	N	N	N	1	CUSTOMER ISSUE	-
DMS_43691	44563	N	N	N	1	CUSTOMER ISSUE	-
DMS_43694	44564	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43695	44565	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43698	44566	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43699	44567	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43700	44568	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43702	44569	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43704	44570	N	N	N	1	CUSTOMER ISSUE	-
DMS_43705	44571	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43706	44572	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43707	44573	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43710	44574	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43711	44575	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43712	44576	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43714	44577	N	N	N	1	CUSTOMER ISSUE	-
DMS_43717	44578	N	N	N	1	CUSTOMER ISSUE	-
DMS_43718	44579	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43719	44580	N	N	N	1	CUSTOMER ISSUE	-
DMS_43720	44581	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43721	44582	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43722	44583	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43723	44584	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43724	44585	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43725	44586	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43726	44587	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43727	44588	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43729	44589	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43730	44590	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43732	44591	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43734	44592	N	N	N	1	CUSTOMER ISSUE	-
DMS_43735	44593	N	N	N	1	CUSTOMER ISSUE	-
DMS_43736	44594	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_43743	44595	N	N	N	1	CUSTOMER ISSUE	-
DMS_43744	44596	N	N	N	1	CUSTOMER ISSUE	-
DMS_43748	44597	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43750	44598	N	N	N	1	CUSTOMER ISSUE	-
DMS_43751	44599	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43752	44600	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43753	44601	N	N	N	1	CUSTOMER ISSUE	-
DMS_43754	44602	N	N	Y	1	TX - REPLACE	2500
DMS_43756	44603	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43757	44604	N	N	N	1	CUSTOMER ISSUE	-
DMS_43758	44605	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43759	44606	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43761	44607	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43762	44608	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43763	44609	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43764	44610	N	N	N	1	CUSTOMER ISSUE	-
DMS_43765	44611	N	N	N	1	CUSTOMER ISSUE	-
DMS_43766	44612	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43767	44613	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_43768	44614	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43770	44615	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43771	44616	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_43772	44617	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43774	44618	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43775	44619	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43776	44620	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43777	44621	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43778	44622	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43779	44623	N	N	N	1	CUSTOMER ISSUE	-
DMS_43780	44624	N	N	N	1	CUSTOMER ISSUE	-
DMS_43781	44625	N	N	N	1	CUSTOMER ISSUE	-
DMS_43782	44626	N	N	N	1	CUSTOMER ISSUE	-
DMS_43784	44627	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43785	44628	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43786	44629	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43788	44630	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43792	44631	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43793	44632	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43794	44633	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43796	44634	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_43800	44635	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_43803	44636	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43805	44637	N	N	N	1	CUSTOMER ISSUE	-
DMS_43808	44638	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43809	44639	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_43810	44640	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43811	44641	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43813	44642	N	N	N	1	CUSTOMER ISSUE	-
DMS_43814	44643	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_43815	44644	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43816	44645	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43817	44646	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43818	44647	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43819	44648	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43820	44649	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43822	44650	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43824	44651	N	N	N	1	CUSTOMER ISSUE	-
DMS_43825	44652	N	N	N	1	CUSTOMER ISSUE	-
DMS_43826	44653	N	N	N	1	CUSTOMER ISSUE	-
DMS_43828	44654	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43834	44655	N	N	N	1	CUSTOMER ISSUE	-
DMS_43837	44656	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_43838	44657	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43839	44658	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43840	44659	N	N	Y	1	TX - REPLACE	2500
DMS_43842	44660	N	N	N	1	CUSTOMER ISSUE	-
DMS_43843	44661	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43844	44662	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43845	44663	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43846	44664	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43847	44665	N	N	N	1	CUSTOMER ISSUE	-
DMS_43848	44666	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_43849	44667	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43851	44668	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43852	44669	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43853	44670	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43854	44671	N	N	N	1	CUSTOMER ISSUE	-
DMS_43855	44672	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43856	44673	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_43857	44674	N	N	Y	1	TX - REPLACE	2500
DMS_43858	44675	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43859	44676	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43860	44677	N	N	N	1	CUSTOMER ISSUE	-
DMS_43861	44678	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43862	44679	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_43863	44680	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43865	44681	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43866	44682	N	N	N	1	CUSTOMER ISSUE	-
DMS_43867	44683	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43869	44684	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43871	44685	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43873	44686	N	N	N	1	CUSTOMER ISSUE	-
DMS_43874	44687	N	N	N	1	CUSTOMER ISSUE	-
DMS_43875	44688	N	N	N	1	CUSTOMER ISSUE	-
DMS_43876	44689	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43878	44690	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43879	44691	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43880	44692	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43881	44693	N	N	N	1	CUSTOMER ISSUE	-
DMS_43883	44694	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43884	44695	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43885	44696	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_43886	44697	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43887	44698	N	N	N	1	CUSTOMER ISSUE	-
DMS_43888	44699	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43889	44700	N	N	N	1	CUSTOMER ISSUE	-
DMS_43890	44701	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43891	44702	N	N	N	1	CUSTOMER ISSUE	-
DMS_43892	44703	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43894	44704	N	N	N	1	CUSTOMER ISSUE	-
DMS_43895	44705	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43896	44706	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43897	44707	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43898	44708	N	N	N	1	CUSTOMER ISSUE	-
DMS_43899	44709	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43900	44710	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43901	44711	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43902	44712	N	N	N	1	CUSTOMER ISSUE	-
DMS_43904	44713	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43905	44714	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43906	44715	N	N	N	1	CUSTOMER ISSUE	-
DMS_43908	44716	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43909	44717	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43915	44718	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43916	44719	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43917	44720	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43919	44721	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43922	44722	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43923	44723	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43924	44724	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43926	44725	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43927	44726	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43928	44727	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43929	44728	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43930	44729	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43931	44730	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43932	44731	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43933	44732	N	N	N	1	CUSTOMER ISSUE	-
DMS_43934	44733	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43935	44734	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43936	44735	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43937	44736	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43938	44737	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43939	44738	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43940	44739	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43941	44740	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43943	44741	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43944	44742	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43945	44743	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43946	44744	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43948	44745	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43950	44746	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43951	44747	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43952	44748	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43953	44749	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43954	44750	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43955	44751	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43956	44752	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43957	44753	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43962	44754	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43963	44755	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43964	44756	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43966	44757	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43967	44758	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43968	44759	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43969	44760	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43970	44761	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43971	44762	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43972	44763	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43973	44764	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43975	44765	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43976	44766	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43977	44767	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43978	44768	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43979	44769	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43980	44770	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43981	44771	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43982	44772	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43983	44773	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43984	44774	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43985	44775	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43987	44776	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_43988	44777	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43989	44778	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_43991	44779	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43993	44780	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43994	44781	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43995	44782	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43996	44783	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43997	44784	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_43998	44785	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_43999	44786	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44001	44787	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44003	44788	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44004	44789	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44005	44790	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44007	44791	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44008	44792	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44009	44793	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44010	44794	N	N	N	1	CUSTOMER ISSUE	-
DMS_44013	44795	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44014	44796	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44016	44797	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44018	44798	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44019	44799	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44022	44800	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44023	44801	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44024	44802	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44027	44803	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44028	44804	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44029	44805	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44031	44806	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44032	44807	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44033	44808	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44037	44809	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44038	44810	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44039	44811	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44042	44812	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44043	44813	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44044	44814	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44045	44815	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44046	44816	N	N	Y	1	TX - REPLACE	2500
DMS_44047	44817	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44048	44818	N	N	Y	1	TX - REPLACE	2500
DMS_44049	44819	N	N	Y	1	TX - REPLACE	2500
DMS_44050	44820	N	N	N	1	CUSTOMER ISSUE	-
DMS_44052	44821	N	N	Y	1	TX - REPLACE	2500
DMS_44054	44822	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44056	44823	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44057	44824	N	N	N	1	CUSTOMER ISSUE	-
DMS_44058	44825	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44059	44826	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44060	44827	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44061	44828	N	N	N	1	CUSTOMER ISSUE	-
DMS_44062	44829	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44063	44830	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44064	44831	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44065	44832	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44066	44833	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44069	44834	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44070	44835	N	N	Y	1	TX - REPLACE	2500
DMS_44072	44836	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44073	44837	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44074	44838	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44076	44839	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44077	44840	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44078	44841	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44079	44842	N	N	N	1	CUSTOMER ISSUE	-
DMS_44080	44843	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44081	44844	N	N	N	1	CUSTOMER ISSUE	-
DMS_44085	44845	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44086	44846	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44087	44847	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44088	44848	N	N	N	1	CUSTOMER ISSUE	-
DMS_44089	44849	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44091	44850	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44092	44851	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44093	44852	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44094	44853	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44096	44854	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44097	44855	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44102	44856	N	N	N	1	CUSTOMER ISSUE	-

DMS_44103	44857	N	N	N	1	CUSTOMER ISSUE	-
DMS_44104	44858	N	N	N	1	CUSTOMER ISSUE	-
DMS_44106	44859	N	N	N	1	CUSTOMER ISSUE	-
DMS_44108	44860	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44109	44861	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44112	44862	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44114	44863	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44115	44864	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44116	44865	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44118	44866	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44119	44867	N	N	N	2	CUSTOMER ISSUE	-
DMS_44120	44868	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44137	44869	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44138	44870	N	N	N	1	CUSTOMER ISSUE	-
DMS_44142	44871	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44147	44872	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_44148	44873	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44149	44874	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44150	44875	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44151	44876	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44152	44877	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44153	44878	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44155	44879	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44160	44880	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44161	44881	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44162	44882	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44163	44883	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44164	44884	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44170	44885	N	N	N	1	CUSTOMER ISSUE	-
DMS_44171	44886	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44175	44887	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44176	44888	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44185	44889	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44187	44890	N	N	N	1	CUSTOMER ISSUE	-
DMS_44188	44891	N	N	N	1	CUSTOMER ISSUE	-
DMS_44193	44892	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44194	44893	N	N	N	1	CUSTOMER ISSUE	-
DMS_44197	44894	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44198	44895	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44199	44896	N	N	N	1	CUSTOMER ISSUE	-
DMS_44200	44897	N	N	N	1	CUSTOMER ISSUE	-
DMS_44201	44898	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44204	44899	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44205	44900	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44206	44901	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44210	44902	N	N	N	1	CUSTOMER ISSUE	-
DMS_44213	44903	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44214	44904	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44215	44905	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44217	44906	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44220	44907	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44221	44908	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44223	44909	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44225	44910	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_44228	44911	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44229	44912	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44230	44913	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44234	44914	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44235	44915	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44236	44916	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44237	44917	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44238	44918	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44239	44919	N	N	N	1	CUSTOMER ISSUE	-
DMS_44241	44920	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44242	44921	N	N	N	1	CUSTOMER ISSUE	-
DMS_44243	44922	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44245	44923	N	N	N	1	CUSTOMER ISSUE	-
DMS_44246	44924	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44247	44925	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44248	44926	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44249	44927	N	N	N	1	CUSTOMER ISSUE	-
DMS_44250	44928	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44252	44929	N	N	N	1	CUSTOMER ISSUE	-
DMS_44253	44930	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44254	44931	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44255	44932	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44256	44933	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_44257	44934	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44258	44935	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44259	44936	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_44260	44937	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44261	44938	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44263	44939	N	N	N	1	CUSTOMER ISSUE	-
DMS_44264	44940	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44265	44941	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44266	44942	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44267	44943	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44268	44944	N	N	N	1	CUSTOMER ISSUE	-
DMS_44270	44945	N	N	N	1	CUSTOMER ISSUE	-
DMS_44272	44946	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44273	44947	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44274	44948	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44275	44949	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_44276	44950	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_44278	44951	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44280	44952	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44281	44953	N	N	N	1	CUSTOMER ISSUE	-
DMS_44282	44954	N	N	N	1	CUSTOMER ISSUE	-
DMS_44283	44955	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44284	44956	N	N	N	1	CUSTOMER ISSUE	-
DMS_44286	44957	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44288	44958	N	N	N	1	CUSTOMER ISSUE	-
DMS_44289	44959	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44292	44960	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44294	44961	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44299	44962	N	N	N	1	CUSTOMER ISSUE	-
DMS_44308	44963	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44315	44964	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44317	44965	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_44320	44966	N	N	N	1	CUSTOMER ISSUE	-
DMS_44321	44967	N	N	N	1	CUSTOMER ISSUE	-
DMS_44322	44968	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44323	44969	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44324	44970	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44325	44971	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44327	44972	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44328	44973	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44329	44974	N	N	N	1	CUSTOMER ISSUE	-
DMS_44330	44975	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44331	44976	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44332	44977	N	N	N	1	CUSTOMER ISSUE	-
DMS_44333	44978	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44334	44979	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44336	44980	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_44337	44981	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44338	44982	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44339	44983	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44340	44984	N	N	N	1	CUSTOMER ISSUE	-
DMS_44343	44985	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44344	44986	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44346	44987	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44348	44988	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44349	44989	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44352	44990	N	N	N	1	CUSTOMER ISSUE	-
DMS_44361	44991	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44362	44992	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44368	44993	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44369	44994	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_44373	44995	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_44375	44996	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44376	44997	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44377	44998	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44380	44999	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44382	45000	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44383	45001	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44384	45002	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44403	45003	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44418	45004	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44421	45005	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44422	45006	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_44423	45007	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44424	45008	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44426	45009	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44427	45010	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44428	45011	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44429	45012	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44430	45013	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44431	45014	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44436	45015	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44438	45016	N	N	Y	1	SEC/SVC - REPLACE	708.75

DMS_44440	45017	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44441	45018	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44444	45019	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44446	45020	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44447	45021	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44450	45022	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44451	45023	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44455	45024	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44456	45025	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_44458	45026	N	N	N	1	CUSTOMER ISSUE	-
DMS_44459	45027	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44463	45028	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44465	45029	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44466	45030	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44467	45031	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44468	45032	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44469	45033	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44470	45034	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_44471	45035	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44475	45036	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44476	45037	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44477	45038	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44478	45039	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44480	45040	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44486	45041	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44487	45042	N	N	N	1	CUSTOMER ISSUE	-
DMS_44488	45043	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44489	45044	N	N	N	1	CUSTOMER ISSUE	-
DMS_44490	45045	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44491	45046	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44492	45047	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44493	45048	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44494	45049	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44495	45050	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44496	45051	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44497	45052	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44498	45053	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44499	45054	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44500	45055	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44501	45056	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44502	45057	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44503	45058	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44505	45059	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44506	45060	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44507	45061	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44508	45062	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44509	45063	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44511	45064	N	N	N	1	CUSTOMER ISSUE	-
DMS_44512	45065	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44513	45066	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44517	45067	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44518	45068	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44520	45069	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44521	45070	N	N	N	1	CUSTOMER ISSUE	-
DMS_44522	45071	N	N	N	1	CUSTOMER ISSUE	-
DMS_44524	45072	N	N	N	1	CUSTOMER ISSUE	-
DMS_44525	45073	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44527	45074	N	N	N	1	CUSTOMER ISSUE	-
DMS_44530	45075	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44533	45076	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44534	45077	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44535	45078	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44537	45079	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_44539	45080	N	N	N	1	CUSTOMER ISSUE	-
DMS_44540	45081	N	N	N	1	CUSTOMER ISSUE	-
DMS_44541	45082	N	N	N	1	CUSTOMER ISSUE	-
DMS_44542	45083	N	N	N	1	CUSTOMER ISSUE	-
DMS_44545	45084	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44546	45085	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44547	45086	N	N	N	2	CUSTOMER ISSUE	-
DMS_44548	45087	N	N	N	1	CUSTOMER ISSUE	-
DMS_44549	45088	N	N	N	1	CUSTOMER ISSUE	-
DMS_44554	45089	N	N	N	1	CUSTOMER ISSUE	-
DMS_44555	45090	N	N	N	1	CUSTOMER ISSUE	-
DMS_44556	45091	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44557	45092	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_44558	45093	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44559	45094	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44560	45095	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_44561	45096	N	N	Y	1	SEC/SVC - REPAIR	472.5

DMS_44562	45097	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44563	45098	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_44564	45099	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44565	45100	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44573	45101	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44574	45102	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44578	45103	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44580	45104	N	N	N	1	CUSTOMER ISSUE	-
DMS_44582	45105	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44584	45106	N	N	N	1	CUSTOMER ISSUE	-
DMS_44586	45107	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44587	45108	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44588	45109	N	N	N	1	CUSTOMER ISSUE	-
DMS_44590	45110	N	N	N	1	CUSTOMER ISSUE	-
DMS_44592	45111	N	N	N	1	CUSTOMER ISSUE	-
DMS_44593	45112	N	N	N	1	CUSTOMER ISSUE	-
DMS_44596	45113	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44598	45114	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44599	45115	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44600	45116	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44601	45117	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44602	45118	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44604	45119	N	N	N	1	CUSTOMER ISSUE	-
DMS_44605	45120	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44606	45121	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44607	45122	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44608	45123	N	N	N	1	CUSTOMER ISSUE	-
DMS_44609	45124	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44610	45125	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44611	45126	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44612	45127	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44613	45128	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44614	45129	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44615	45130	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44617	45131	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44619	45132	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44620	45133	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44621	45134	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_44623	45135	N	N	N	1	CUSTOMER ISSUE	-
DMS_44624	45136	N	N	N	1	CUSTOMER ISSUE	-
DMS_44626	45137	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44628	45138	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44629	45139	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44630	45140	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44631	45141	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44632	45142	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44634	45143	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44635	45144	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44636	45145	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44637	45146	N	N	N	1	CUSTOMER ISSUE	-
DMS_44639	45147	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44642	45148	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44645	45149	N	N	N	1	CUSTOMER ISSUE	-
DMS_44647	45150	N	N	N	1	CUSTOMER ISSUE	-
DMS_44648	45151	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44649	45152	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_44651	45153	N	N	Y	3	DIST - TREE TRIMMING	945
DMS_44652	45154	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44653	45155	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44654	45156	N	N	N	1	CUSTOMER ISSUE	-
DMS_44656	45157	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44657	45158	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44659	45159	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44660	45160	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44661	45161	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44662	45162	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44663	45163	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44664	45164	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44665	45165	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44666	45166	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44672	45167	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44673	45168	N	N	N	1	CUSTOMER ISSUE	-
DMS_44674	45169	N	N	N	1	CUSTOMER ISSUE	-
DMS_44675	45170	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44678	45171	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44681	45172	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44682	45173	N	N	N	1	CUSTOMER ISSUE	-
DMS_44683	45174	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44685	45175	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44687	45176	N	N	Y	1	DIST - TREE TRIMMING	945

DMS_44689	45177	N	N	N	1	CUSTOMER ISSUE	-
DMS_44691	45178	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44692	45179	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44693	45180	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44694	45181	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44700	45182	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44701	45183	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44702	45184	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44705	45185	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44706	45186	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44707	45187	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44708	45188	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44709	45189	N	N	N	1	CUSTOMER ISSUE	-
DMS_44713	45190	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44714	45191	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44715	45192	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44716	45193	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44722	45194	N	N	N	1	CUSTOMER ISSUE	-
DMS_44723	45195	N	N	N	1	CUSTOMER ISSUE	-
DMS_44724	45196	N	N	N	1	CUSTOMER ISSUE	-
DMS_44725	45197	N	N	N	1	CUSTOMER ISSUE	-
DMS_44727	45198	N	N	N	1	CUSTOMER ISSUE	-
DMS_44728	45199	N	N	N	1	CUSTOMER ISSUE	-
DMS_44729	45200	N	N	N	1	CUSTOMER ISSUE	-
DMS_44730	45201	N	N	N	1	CUSTOMER ISSUE	-
DMS_44732	45202	N	N	N	1	CUSTOMER ISSUE	-
DMS_44734	45203	N	N	N	1	CUSTOMER ISSUE	-
DMS_44735	45204	N	N	N	1	CUSTOMER ISSUE	-
DMS_44736	45205	N	N	N	1	CUSTOMER ISSUE	-
DMS_44737	45206	N	N	N	1	CUSTOMER ISSUE	-
DMS_44738	45207	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44739	45208	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44740	45209	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44741	45210	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44742	45211	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44743	45212	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44744	45213	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44745	45214	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44746	45215	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44748	45216	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44749	45217	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44750	45218	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44751	45219	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44752	45220	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44753	45221	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44754	45222	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44755	45223	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44756	45224	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44758	45225	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44759	45226	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44760	45227	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44762	45228	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44764	45229	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44765	45230	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44766	45231	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44767	45232	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44768	45233	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44769	45234	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44770	45235	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44771	45236	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_44772	45237	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44773	45238	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44774	45239	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44775	45240	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44776	45241	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44777	45242	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44779	45243	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44781	45244	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44782	45245	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44784	45246	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44785	45247	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44786	45248	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44787	45249	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44788	45250	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44789	45251	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44790	45252	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44791	45253	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44792	45254	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44793	45255	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44794	45256	N	N	Y	1	DIST - TREE TRIMMING	945

DMS_44795	45257	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44796	45258	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44797	45259	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44798	45260	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44799	45261	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44800	45262	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44802	45263	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44803	45264	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44804	45265	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44805	45266	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44806	45267	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44807	45268	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44808	45269	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44809	45270	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44811	45271	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44812	45272	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44813	45273	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44814	45274	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44816	45275	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44817	45276	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44818	45277	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44819	45278	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44820	45279	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44821	45280	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_44822	45281	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44823	45282	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44824	45283	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44825	45284	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44826	45285	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44827	45286	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44828	45287	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44829	45288	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44830	45289	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44831	45290	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44832	45291	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44833	45292	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44834	45293	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44835	45294	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44836	45295	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44837	45296	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44838	45297	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44839	45298	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44840	45299	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44841	45300	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44842	45301	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44843	45302	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44844	45303	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_44845	45304	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44846	45305	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44847	45306	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44848	45307	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44849	45308	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44850	45309	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44851	45310	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44852	45311	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44853	45312	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44854	45313	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44855	45314	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44856	45315	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44857	45316	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44858	45317	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44859	45318	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44860	45319	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44861	45320	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44862	45321	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44863	45322	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44864	45323	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44865	45324	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44867	45325	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44868	45326	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44869	45327	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44870	45328	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44871	45329	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44872	45330	N	N	N	1	CUSTOMER ISSUE	-
DMS_44873	45331	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44874	45332	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44875	45333	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44876	45334	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44877	45335	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44878	45336	N	N	Y	1	DIST - TREE TRIMMING	945

DMS_44879	45337	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44880	45338	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44881	45339	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44882	45340	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44883	45341	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44884	45342	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44885	45343	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44886	45344	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44887	45345	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44888	45346	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44889	45347	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44890	45348	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44891	45349	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44892	45350	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44893	45351	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44894	45352	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44895	45353	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44896	45354	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44897	45355	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44898	45356	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44900	45357	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44901	45358	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44902	45359	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44903	45360	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44904	45361	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44905	45362	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44906	45363	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44907	45364	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44908	45365	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44909	45366	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44910	45367	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44911	45368	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44913	45369	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44914	45370	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44915	45371	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44916	45372	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44917	45373	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44918	45374	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44919	45375	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44920	45376	N	N	N	1	CUSTOMER ISSUE	-
DMS_44921	45377	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44922	45378	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44923	45379	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44924	45380	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44925	45381	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44926	45382	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44927	45383	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44928	45384	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44929	45385	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44930	45386	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44931	45387	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44932	45388	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44933	45389	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44934	45390	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44935	45391	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44936	45392	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44937	45393	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44938	45394	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44939	45395	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44940	45396	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44941	45397	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44942	45398	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44943	45399	N	N	N	1	CUSTOMER ISSUE	-
DMS_44945	45400	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_44946	45401	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44947	45402	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44948	45403	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44949	45404	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44950	45405	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44951	45406	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44952	45407	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44953	45408	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44954	45409	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44955	45410	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44956	45411	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44957	45412	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44958	45413	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44959	45414	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44960	45415	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44961	45416	N	N	Y	1	DIST - TREE TRIMMING	945

DMS_44962	45417	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44963	45418	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44964	45419	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44965	45420	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44966	45421	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44967	45422	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44968	45423	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44969	45424	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44970	45425	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44971	45426	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44972	45427	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44973	45428	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44974	45429	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44975	45430	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44976	45431	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44977	45432	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44978	45433	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44979	45434	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44980	45435	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44981	45436	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44982	45437	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44983	45438	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44984	45439	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44985	45440	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44986	45441	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44987	45442	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_44988	45443	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44989	45444	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44990	45445	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44991	45446	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44992	45447	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44993	45448	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44994	45449	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_44995	45450	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44996	45451	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44997	45452	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_44998	45453	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_44999	45454	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45000	45455	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45001	45456	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45002	45457	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45003	45458	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45005	45459	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45006	45460	N	N	N	1	CUSTOMER ISSUE	-
DMS_45007	45461	N	N	N	1	CUSTOMER ISSUE	-
DMS_45008	45462	N	N	N	1	CUSTOMER ISSUE	-
DMS_45009	45463	N	N	N	1	CUSTOMER ISSUE	-
DMS_45010	45464	N	N	N	1	CUSTOMER ISSUE	-
DMS_45011	45465	N	N	N	1	CUSTOMER ISSUE	-
DMS_45012	45466	N	N	N	1	CUSTOMER ISSUE	-
DMS_45013	45467	N	N	N	1	CUSTOMER ISSUE	-
DMS_45014	45468	N	N	N	1	CUSTOMER ISSUE	-
DMS_45015	45469	N	N	N	1	CUSTOMER ISSUE	-
DMS_45016	45470	N	N	N	1	CUSTOMER ISSUE	-
DMS_45017	45471	N	N	N	1	CUSTOMER ISSUE	-
DMS_45019	45472	N	N	N	1	CUSTOMER ISSUE	-
DMS_45020	45473	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45021	45474	N	N	N	1	CUSTOMER ISSUE	-
DMS_45022	45475	N	N	N	1	CUSTOMER ISSUE	-
DMS_45023	45476	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45024	45477	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45025	45478	N	N	N	1	CUSTOMER ISSUE	-
DMS_45026	45479	N	N	N	1	CUSTOMER ISSUE	-
DMS_45027	45480	N	N	N	1	CUSTOMER ISSUE	-
DMS_45028	45481	N	N	N	1	CUSTOMER ISSUE	-
DMS_45029	45482	N	N	N	1	CUSTOMER ISSUE	-
DMS_45030	45483	N	N	N	1	CUSTOMER ISSUE	-
DMS_45031	45484	N	N	N	1	CUSTOMER ISSUE	-
DMS_45032	45485	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45033	45486	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45034	45487	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45035	45488	N	N	N	1	CUSTOMER ISSUE	-
DMS_45036	45489	N	N	N	1	CUSTOMER ISSUE	-
DMS_45037	45490	N	N	N	1	CUSTOMER ISSUE	-
DMS_45038	45491	N	N	N	1	CUSTOMER ISSUE	-
DMS_45039	45492	N	N	N	1	CUSTOMER ISSUE	-
DMS_45040	45493	N	N	N	1	CUSTOMER ISSUE	-
DMS_45041	45494	N	N	N	1	CUSTOMER ISSUE	-
DMS_45042	45495	N	N	N	1	CUSTOMER ISSUE	-
DMS_45043	45496	N	N	N	1	CUSTOMER ISSUE	-

DMS_45044	45497	N	N	N	1	CUSTOMER ISSUE	-
DMS_45045	45498	N	N	N	1	CUSTOMER ISSUE	-
DMS_45046	45499	N	N	N	1	CUSTOMER ISSUE	-
DMS_45047	45500	N	N	N	1	CUSTOMER ISSUE	-
DMS_45048	45501	N	N	N	1	CUSTOMER ISSUE	-
DMS_45049	45502	N	N	N	1	CUSTOMER ISSUE	-
DMS_45050	45503	N	N	N	1	CUSTOMER ISSUE	-
DMS_45051	45504	N	N	N	1	CUSTOMER ISSUE	-
DMS_45052	45505	N	N	N	1	CUSTOMER ISSUE	-
DMS_45053	45506	N	N	N	1	CUSTOMER ISSUE	-
DMS_45054	45507	N	N	N	1	CUSTOMER ISSUE	-
DMS_45055	45508	N	N	N	1	CUSTOMER ISSUE	-
DMS_45056	45509	N	N	N	1	CUSTOMER ISSUE	-
DMS_45057	45510	N	N	N	1	CUSTOMER ISSUE	-
DMS_45058	45511	N	N	N	1	CUSTOMER ISSUE	-
DMS_45059	45512	N	N	N	1	CUSTOMER ISSUE	-
DMS_45060	45513	N	N	N	1	CUSTOMER ISSUE	-
DMS_45061	45514	N	N	N	1	CUSTOMER ISSUE	-
DMS_45062	45515	N	N	N	1	CUSTOMER ISSUE	-
DMS_45063	45516	N	N	N	1	CUSTOMER ISSUE	-
DMS_45064	45517	N	N	N	1	CUSTOMER ISSUE	-
DMS_45065	45518	N	N	N	1	CUSTOMER ISSUE	-
DMS_45066	45519	N	N	N	1	CUSTOMER ISSUE	-
DMS_45067	45520	N	N	N	1	CUSTOMER ISSUE	-
DMS_45068	45521	N	N	N	1	CUSTOMER ISSUE	-
DMS_45069	45522	N	N	N	1	CUSTOMER ISSUE	-
DMS_45070	45523	N	N	N	1	CUSTOMER ISSUE	-
DMS_45071	45524	N	N	N	1	CUSTOMER ISSUE	-
DMS_45072	45525	N	N	N	1	CUSTOMER ISSUE	-
DMS_45073	45526	N	N	N	1	CUSTOMER ISSUE	-
DMS_45074	45527	N	N	N	1	CUSTOMER ISSUE	-
DMS_45075	45528	N	N	N	1	CUSTOMER ISSUE	-
DMS_45076	45529	N	N	N	1	CUSTOMER ISSUE	-
DMS_45077	45530	N	N	N	1	CUSTOMER ISSUE	-
DMS_45078	45531	N	N	N	1	CUSTOMER ISSUE	-
DMS_45079	45532	N	N	N	1	CUSTOMER ISSUE	-
DMS_45080	45533	N	N	N	1	CUSTOMER ISSUE	-
DMS_45081	45534	N	N	N	1	CUSTOMER ISSUE	-
DMS_45082	45535	N	N	N	1	CUSTOMER ISSUE	-
DMS_45083	45536	N	N	N	1	CUSTOMER ISSUE	-
DMS_45084	45537	N	N	N	1	CUSTOMER ISSUE	-
DMS_45085	45538	N	N	N	1	CUSTOMER ISSUE	-
DMS_45086	45539	N	N	N	1	CUSTOMER ISSUE	-
DMS_45087	45540	N	N	N	1	CUSTOMER ISSUE	-
DMS_45088	45541	N	N	N	1	CUSTOMER ISSUE	-
DMS_45089	45542	N	N	N	1	CUSTOMER ISSUE	-
DMS_45090	45543	N	N	N	1	CUSTOMER ISSUE	-
DMS_45091	45544	N	N	N	1	CUSTOMER ISSUE	-
DMS_45092	45545	N	N	N	1	CUSTOMER ISSUE	-
DMS_45093	45546	N	N	N	1	CUSTOMER ISSUE	-
DMS_45094	45547	N	N	N	1	CUSTOMER ISSUE	-
DMS_45095	45548	N	N	N	1	CUSTOMER ISSUE	-
DMS_45096	45549	N	N	N	1	CUSTOMER ISSUE	-
DMS_45097	45550	N	N	N	1	CUSTOMER ISSUE	-
DMS_45098	45551	N	N	N	1	CUSTOMER ISSUE	-
DMS_45099	45552	N	N	N	1	CUSTOMER ISSUE	-
DMS_45100	45553	N	N	N	1	CUSTOMER ISSUE	-
DMS_45101	45554	N	N	N	1	CUSTOMER ISSUE	-
DMS_45102	45555	N	N	N	1	CUSTOMER ISSUE	-
DMS_45103	45556	N	N	N	1	CUSTOMER ISSUE	-
DMS_45104	45557	N	N	N	1	CUSTOMER ISSUE	-
DMS_45105	45558	N	N	N	1	CUSTOMER ISSUE	-
DMS_45106	45559	N	N	N	1	CUSTOMER ISSUE	-
DMS_45107	45560	N	N	N	1	CUSTOMER ISSUE	-
DMS_45108	45561	N	N	N	1	CUSTOMER ISSUE	-
DMS_45109	45562	N	N	N	1	CUSTOMER ISSUE	-
DMS_45110	45563	N	N	N	1	CUSTOMER ISSUE	-
DMS_45111	45564	N	N	N	1	CUSTOMER ISSUE	-
DMS_45112	45565	N	N	N	1	CUSTOMER ISSUE	-
DMS_45113	45566	N	N	N	1	CUSTOMER ISSUE	-
DMS_45114	45567	N	N	N	1	CUSTOMER ISSUE	-
DMS_45115	45568	N	N	N	1	CUSTOMER ISSUE	-
DMS_45116	45569	N	N	N	1	CUSTOMER ISSUE	-
DMS_45117	45570	N	N	N	1	CUSTOMER ISSUE	-
DMS_45118	45571	N	N	N	1	CUSTOMER ISSUE	-
DMS_45119	45572	N	N	N	1	CUSTOMER ISSUE	-
DMS_45120	45573	N	N	N	1	CUSTOMER ISSUE	-
DMS_45121	45574	N	N	N	1	CUSTOMER ISSUE	-
DMS_45122	45575	N	N	N	1	CUSTOMER ISSUE	-
DMS_45123	45576	N	N	N	1	CUSTOMER ISSUE	-

DMS_45124	45577	N	N	N	1	CUSTOMER ISSUE	-
DMS_45125	45578	N	N	N	1	CUSTOMER ISSUE	-
DMS_45126	45579	N	N	N	1	CUSTOMER ISSUE	-
DMS_45127	45580	N	N	N	1	CUSTOMER ISSUE	-
DMS_45128	45581	N	N	N	1	CUSTOMER ISSUE	-
DMS_45129	45582	N	N	N	1	CUSTOMER ISSUE	-
DMS_45130	45583	N	N	N	1	CUSTOMER ISSUE	-
DMS_45131	45584	N	N	N	1	CUSTOMER ISSUE	-
DMS_45132	45585	N	N	N	1	CUSTOMER ISSUE	-
DMS_45133	45586	N	N	N	1	CUSTOMER ISSUE	-
DMS_45134	45587	N	N	N	1	CUSTOMER ISSUE	-
DMS_45135	45588	N	N	N	1	CUSTOMER ISSUE	-
DMS_45136	45589	N	N	N	1	CUSTOMER ISSUE	-
DMS_45137	45590	N	N	N	1	CUSTOMER ISSUE	-
DMS_45138	45591	N	N	N	1	CUSTOMER ISSUE	-
DMS_45139	45592	N	N	N	1	CUSTOMER ISSUE	-
DMS_45140	45593	N	N	N	1	CUSTOMER ISSUE	-
DMS_45141	45594	N	N	N	1	CUSTOMER ISSUE	-
DMS_45142	45595	N	N	N	1	CUSTOMER ISSUE	-
DMS_45143	45596	N	N	N	1	CUSTOMER ISSUE	-
DMS_45144	45597	N	N	N	1	CUSTOMER ISSUE	-
DMS_45145	45598	N	N	N	2	CUSTOMER ISSUE	-
DMS_45146	45599	N	N	N	1	CUSTOMER ISSUE	-
DMS_45147	45600	N	N	N	1	CUSTOMER ISSUE	-
DMS_45148	45601	N	N	N	1	CUSTOMER ISSUE	-
DMS_45149	45602	N	N	N	1	CUSTOMER ISSUE	-
DMS_45150	45603	N	N	N	1	CUSTOMER ISSUE	-
DMS_45151	45604	N	N	N	1	CUSTOMER ISSUE	-
DMS_45152	45605	N	N	N	1	CUSTOMER ISSUE	-
DMS_45153	45606	N	N	N	1	CUSTOMER ISSUE	-
DMS_45154	45607	N	N	N	1	CUSTOMER ISSUE	-
DMS_45155	45608	N	N	N	1	CUSTOMER ISSUE	-
DMS_45156	45609	N	N	N	1	CUSTOMER ISSUE	-
DMS_45157	45610	N	N	N	1	CUSTOMER ISSUE	-
DMS_45158	45611	N	N	N	1	CUSTOMER ISSUE	-
DMS_45159	45612	N	N	N	1	CUSTOMER ISSUE	-
DMS_45160	45613	N	N	N	1	CUSTOMER ISSUE	-
DMS_45161	45614	N	N	N	1	CUSTOMER ISSUE	-
DMS_45162	45615	N	N	N	1	CUSTOMER ISSUE	-
DMS_45163	45616	N	N	N	1	CUSTOMER ISSUE	-
DMS_45164	45617	N	N	N	1	CUSTOMER ISSUE	-
DMS_45165	45618	N	N	N	1	CUSTOMER ISSUE	-
DMS_45166	45619	N	N	N	1	CUSTOMER ISSUE	-
DMS_45167	45620	N	N	N	1	CUSTOMER ISSUE	-
DMS_45168	45621	N	N	N	1	CUSTOMER ISSUE	-
DMS_45169	45622	N	N	N	1	CUSTOMER ISSUE	-
DMS_45170	45623	N	N	N	1	CUSTOMER ISSUE	-
DMS_45171	45624	N	N	N	1	CUSTOMER ISSUE	-
DMS_45172	45625	N	N	N	1	CUSTOMER ISSUE	-
DMS_45173	45626	N	N	N	1	CUSTOMER ISSUE	-
DMS_45174	45627	N	N	N	1	CUSTOMER ISSUE	-
DMS_45175	45628	N	N	N	1	CUSTOMER ISSUE	-
DMS_45176	45629	N	N	N	1	CUSTOMER ISSUE	-
DMS_45177	45630	N	N	N	1	CUSTOMER ISSUE	-
DMS_45178	45631	N	N	N	1	CUSTOMER ISSUE	-
DMS_45179	45632	N	N	N	1	CUSTOMER ISSUE	-
DMS_45180	45633	N	N	N	1	CUSTOMER ISSUE	-
DMS_45181	45634	N	N	N	1	CUSTOMER ISSUE	-
DMS_45183	45635	N	N	N	1	CUSTOMER ISSUE	-
DMS_45184	45636	N	N	N	1	CUSTOMER ISSUE	-
DMS_45185	45637	N	N	N	1	CUSTOMER ISSUE	-
DMS_45186	45638	N	N	N	1	CUSTOMER ISSUE	-
DMS_45187	45639	N	N	N	1	CUSTOMER ISSUE	-
DMS_45188	45640	N	N	N	1	CUSTOMER ISSUE	-
DMS_45189	45641	N	N	N	1	CUSTOMER ISSUE	-
DMS_45190	45642	N	N	N	1	CUSTOMER ISSUE	-
DMS_45191	45643	N	N	N	1	CUSTOMER ISSUE	-
DMS_45192	45644	N	N	N	1	CUSTOMER ISSUE	-
DMS_45193	45645	N	N	N	1	CUSTOMER ISSUE	-
DMS_45194	45646	N	N	N	1	CUSTOMER ISSUE	-
DMS_45195	45647	N	N	N	1	CUSTOMER ISSUE	-
DMS_45196	45648	N	N	N	1	CUSTOMER ISSUE	-
DMS_45197	45649	N	N	N	1	CUSTOMER ISSUE	-
DMS_45198	45650	N	N	N	1	CUSTOMER ISSUE	-
DMS_45199	45651	N	N	N	1	CUSTOMER ISSUE	-
DMS_45200	45652	N	N	N	1	CUSTOMER ISSUE	-
DMS_45201	45653	N	N	N	1	CUSTOMER ISSUE	-
DMS_45203	45654	N	N	N	1	CUSTOMER ISSUE	-
DMS_45204	45655	N	N	N	1	CUSTOMER ISSUE	-
DMS_45205	45656	N	N	N	1	CUSTOMER ISSUE	-

DMS_45206	45657	N	N	N	1	CUSTOMER ISSUE	-
DMS_45207	45658	N	N	N	1	CUSTOMER ISSUE	-
DMS_45208	45659	N	N	N	1	CUSTOMER ISSUE	-
DMS_45209	45660	N	N	N	1	CUSTOMER ISSUE	-
DMS_45210	45661	N	N	N	1	CUSTOMER ISSUE	-
DMS_45211	45662	N	N	N	1	CUSTOMER ISSUE	-
DMS_45212	45663	N	N	N	1	CUSTOMER ISSUE	-
DMS_45213	45664	N	N	N	1	CUSTOMER ISSUE	-
DMS_45214	45665	N	N	N	1	CUSTOMER ISSUE	-
DMS_45215	45666	N	N	N	1	CUSTOMER ISSUE	-
DMS_45216	45667	N	N	N	1	CUSTOMER ISSUE	-
DMS_45217	45668	N	N	N	1	CUSTOMER ISSUE	-
DMS_45218	45669	N	N	N	1	CUSTOMER ISSUE	-
DMS_45219	45670	N	N	N	1	CUSTOMER ISSUE	-
DMS_45220	45671	N	N	N	1	CUSTOMER ISSUE	-
DMS_45221	45672	N	N	N	1	CUSTOMER ISSUE	-
DMS_45222	45673	N	N	N	1	CUSTOMER ISSUE	-
DMS_45223	45674	N	N	N	1	CUSTOMER ISSUE	-
DMS_45224	45675	N	N	N	1	CUSTOMER ISSUE	-
DMS_45225	45676	N	N	N	1	CUSTOMER ISSUE	-
DMS_45226	45677	N	N	N	1	CUSTOMER ISSUE	-
DMS_45227	45678	N	N	N	1	CUSTOMER ISSUE	-
DMS_45228	45679	N	N	N	1	CUSTOMER ISSUE	-
DMS_45229	45680	N	N	N	1	CUSTOMER ISSUE	-
DMS_45230	45681	N	N	N	1	CUSTOMER ISSUE	-
DMS_45231	45682	N	N	N	1	CUSTOMER ISSUE	-
DMS_45232	45683	N	N	N	1	CUSTOMER ISSUE	-
DMS_45233	45684	N	N	N	1	CUSTOMER ISSUE	-
DMS_45234	45685	N	N	N	1	CUSTOMER ISSUE	-
DMS_45235	45686	N	N	N	1	CUSTOMER ISSUE	-
DMS_45236	45687	N	N	N	1	CUSTOMER ISSUE	-
DMS_45237	45688	N	N	N	1	CUSTOMER ISSUE	-
DMS_45238	45689	N	N	N	1	CUSTOMER ISSUE	-
DMS_45239	45690	N	N	N	1	CUSTOMER ISSUE	-
DMS_45240	45691	N	N	N	1	CUSTOMER ISSUE	-
DMS_45241	45692	N	N	N	1	CUSTOMER ISSUE	-
DMS_45242	45693	N	N	N	1	CUSTOMER ISSUE	-
DMS_45243	45694	N	N	N	1	CUSTOMER ISSUE	-
DMS_45244	45695	N	N	N	1	CUSTOMER ISSUE	-
DMS_45245	45696	N	N	N	1	CUSTOMER ISSUE	-
DMS_45246	45697	N	N	N	1	CUSTOMER ISSUE	-
DMS_45247	45698	N	N	N	1	CUSTOMER ISSUE	-
DMS_45248	45699	N	N	N	1	CUSTOMER ISSUE	-
DMS_45249	45700	N	N	N	1	CUSTOMER ISSUE	-
DMS_45250	45701	N	N	N	1	CUSTOMER ISSUE	-
DMS_45251	45702	N	N	N	1	CUSTOMER ISSUE	-
DMS_45252	45703	N	N	N	1	CUSTOMER ISSUE	-
DMS_45253	45704	N	N	N	1	CUSTOMER ISSUE	-
DMS_45254	45705	N	N	N	1	CUSTOMER ISSUE	-
DMS_45255	45706	N	N	N	1	CUSTOMER ISSUE	-
DMS_45256	45707	N	N	N	1	CUSTOMER ISSUE	-
DMS_45257	45708	N	N	N	1	CUSTOMER ISSUE	-
DMS_45258	45709	N	N	N	1	CUSTOMER ISSUE	-
DMS_45259	45710	N	N	N	1	CUSTOMER ISSUE	-
DMS_45260	45711	N	N	N	1	CUSTOMER ISSUE	-
DMS_45261	45712	N	N	N	1	CUSTOMER ISSUE	-
DMS_45262	45713	N	N	N	1	CUSTOMER ISSUE	-
DMS_45263	45714	N	N	N	1	CUSTOMER ISSUE	-
DMS_45264	45715	N	N	N	1	CUSTOMER ISSUE	-
DMS_45265	45716	N	N	N	1	CUSTOMER ISSUE	-
DMS_45266	45717	N	N	N	1	CUSTOMER ISSUE	-
DMS_45267	45718	N	N	N	1	CUSTOMER ISSUE	-
DMS_45268	45719	N	N	N	1	CUSTOMER ISSUE	-
DMS_45269	45720	N	N	N	1	CUSTOMER ISSUE	-
DMS_45270	45721	N	N	N	1	CUSTOMER ISSUE	-
DMS_45271	45722	N	N	N	1	CUSTOMER ISSUE	-
DMS_45272	45723	N	N	N	1	CUSTOMER ISSUE	-
DMS_45273	45724	N	N	N	1	CUSTOMER ISSUE	-
DMS_45274	45725	N	N	N	1	CUSTOMER ISSUE	-
DMS_45275	45726	N	N	N	1	CUSTOMER ISSUE	-
DMS_45276	45727	N	N	N	1	CUSTOMER ISSUE	-
DMS_45277	45728	N	N	N	1	CUSTOMER ISSUE	-
DMS_45278	45729	N	N	N	1	CUSTOMER ISSUE	-
DMS_45279	45730	N	N	N	1	CUSTOMER ISSUE	-
DMS_45280	45731	N	N	N	1	CUSTOMER ISSUE	-
DMS_45281	45732	N	N	N	1	CUSTOMER ISSUE	-
DMS_45282	45733	N	N	N	1	CUSTOMER ISSUE	-
DMS_45283	45734	N	N	N	1	CUSTOMER ISSUE	-
DMS_45284	45735	N	N	N	1	CUSTOMER ISSUE	-
DMS_45285	45736	N	N	N	1	CUSTOMER ISSUE	-

DMS_45286	45737	N	N	N	1	CUSTOMER ISSUE	-
DMS_45287	45738	N	N	N	2	CUSTOMER ISSUE	-
DMS_45288	45739	N	N	N	1	CUSTOMER ISSUE	-
DMS_45289	45740	N	N	N	1	CUSTOMER ISSUE	-
DMS_45290	45741	N	N	N	1	CUSTOMER ISSUE	-
DMS_45291	45742	N	N	N	1	CUSTOMER ISSUE	-
DMS_45292	45743	N	N	N	1	CUSTOMER ISSUE	-
DMS_45293	45744	N	N	N	1	CUSTOMER ISSUE	-
DMS_45294	45745	N	N	N	1	CUSTOMER ISSUE	-
DMS_45295	45746	N	N	N	1	CUSTOMER ISSUE	-
DMS_45296	45747	N	N	N	1	CUSTOMER ISSUE	-
DMS_45297	45748	N	N	N	1	CUSTOMER ISSUE	-
DMS_45298	45749	N	N	N	1	CUSTOMER ISSUE	-
DMS_45299	45750	N	N	N	1	CUSTOMER ISSUE	-
DMS_45300	45751	N	N	N	1	CUSTOMER ISSUE	-
DMS_45301	45752	N	N	N	1	CUSTOMER ISSUE	-
DMS_45302	45753	N	N	N	1	CUSTOMER ISSUE	-
DMS_45303	45754	N	N	N	1	CUSTOMER ISSUE	-
DMS_45304	45755	N	N	N	1	CUSTOMER ISSUE	-
DMS_45305	45756	N	N	N	1	CUSTOMER ISSUE	-
DMS_45306	45757	N	N	N	1	CUSTOMER ISSUE	-
DMS_45307	45758	N	N	N	1	CUSTOMER ISSUE	-
DMS_45308	45759	N	N	N	1	CUSTOMER ISSUE	-
DMS_45309	45760	N	N	N	1	CUSTOMER ISSUE	-
DMS_45310	45761	N	N	N	1	CUSTOMER ISSUE	-
DMS_45311	45762	N	N	N	1	CUSTOMER ISSUE	-
DMS_45312	45763	N	N	N	1	CUSTOMER ISSUE	-
DMS_45313	45764	N	N	N	1	CUSTOMER ISSUE	-
DMS_45314	45765	N	N	N	1	CUSTOMER ISSUE	-
DMS_45315	45766	N	N	N	1	CUSTOMER ISSUE	-
DMS_45316	45767	N	N	N	1	CUSTOMER ISSUE	-
DMS_45317	45768	N	N	N	1	CUSTOMER ISSUE	-
DMS_45318	45769	N	N	N	1	CUSTOMER ISSUE	-
DMS_45319	45770	N	N	N	1	CUSTOMER ISSUE	-
DMS_45320	45771	N	N	N	1	CUSTOMER ISSUE	-
DMS_45321	45772	N	N	N	1	CUSTOMER ISSUE	-
DMS_45322	45773	N	N	N	1	CUSTOMER ISSUE	-
DMS_45323	45774	N	N	N	1	CUSTOMER ISSUE	-
DMS_45324	45775	N	N	N	1	CUSTOMER ISSUE	-
DMS_45325	45776	N	N	N	1	CUSTOMER ISSUE	-
DMS_45326	45777	N	N	N	1	CUSTOMER ISSUE	-
DMS_45327	45778	N	N	N	1	CUSTOMER ISSUE	-
DMS_45328	45779	N	N	N	1	CUSTOMER ISSUE	-
DMS_45329	45780	N	N	N	1	CUSTOMER ISSUE	-
DMS_45330	45781	N	N	N	1	CUSTOMER ISSUE	-
DMS_45331	45782	N	N	N	1	CUSTOMER ISSUE	-
DMS_45332	45783	N	N	N	1	CUSTOMER ISSUE	-
DMS_45333	45784	N	N	N	1	CUSTOMER ISSUE	-
DMS_45334	45785	N	N	N	1	CUSTOMER ISSUE	-
DMS_45335	45786	N	N	N	1	CUSTOMER ISSUE	-
DMS_45336	45787	N	N	N	1	CUSTOMER ISSUE	-
DMS_45337	45788	N	N	N	1	CUSTOMER ISSUE	-
DMS_45338	45789	N	N	N	1	CUSTOMER ISSUE	-
DMS_45339	45790	N	N	N	1	CUSTOMER ISSUE	-
DMS_45340	45791	N	N	N	1	CUSTOMER ISSUE	-
DMS_45342	45792	N	N	N	1	CUSTOMER ISSUE	-
DMS_45343	45793	N	N	N	1	CUSTOMER ISSUE	-
DMS_45344	45794	N	N	N	1	CUSTOMER ISSUE	-
DMS_45345	45795	N	N	N	1	CUSTOMER ISSUE	-
DMS_45346	45796	N	N	N	1	CUSTOMER ISSUE	-
DMS_45347	45797	N	N	N	1	CUSTOMER ISSUE	-
DMS_45348	45798	N	N	N	1	CUSTOMER ISSUE	-
DMS_45349	45799	N	N	N	1	CUSTOMER ISSUE	-
DMS_45350	45800	N	N	N	1	CUSTOMER ISSUE	-
DMS_45351	45801	N	N	N	1	CUSTOMER ISSUE	-
DMS_45352	45802	N	N	N	1	CUSTOMER ISSUE	-
DMS_45353	45803	N	N	N	1	CUSTOMER ISSUE	-
DMS_45354	45804	N	N	N	1	CUSTOMER ISSUE	-
DMS_45355	45805	N	N	N	1	CUSTOMER ISSUE	-
DMS_45356	45806	N	N	N	1	CUSTOMER ISSUE	-
DMS_45357	45807	N	N	N	1	CUSTOMER ISSUE	-
DMS_45358	45808	N	N	N	1	CUSTOMER ISSUE	-
DMS_45359	45809	N	N	N	1	CUSTOMER ISSUE	-
DMS_45360	45810	N	N	N	2	CUSTOMER ISSUE	-
DMS_45361	45811	N	N	N	1	CUSTOMER ISSUE	-
DMS_45362	45812	N	N	N	1	CUSTOMER ISSUE	-
DMS_45363	45813	N	N	N	1	CUSTOMER ISSUE	-
DMS_45364	45814	N	N	N	1	CUSTOMER ISSUE	-
DMS_45365	45815	N	N	N	1	CUSTOMER ISSUE	-
DMS_45366	45816	N	N	N	1	CUSTOMER ISSUE	-

DMS_45367	45817	N	N	N	1	CUSTOMER ISSUE	-
DMS_45368	45818	N	N	N	1	CUSTOMER ISSUE	-
DMS_45369	45819	N	N	N	1	CUSTOMER ISSUE	-
DMS_45370	45820	N	N	N	1	CUSTOMER ISSUE	-
DMS_45371	45821	N	N	N	1	CUSTOMER ISSUE	-
DMS_45372	45822	N	N	N	1	CUSTOMER ISSUE	-
DMS_45373	45823	N	N	N	1	CUSTOMER ISSUE	-
DMS_45374	45824	N	N	N	1	CUSTOMER ISSUE	-
DMS_45375	45825	N	N	N	1	CUSTOMER ISSUE	-
DMS_45376	45826	N	N	N	1	CUSTOMER ISSUE	-
DMS_45377	45827	N	N	N	1	CUSTOMER ISSUE	-
DMS_45378	45828	N	N	N	1	CUSTOMER ISSUE	-
DMS_45379	45829	N	N	N	1	CUSTOMER ISSUE	-
DMS_45380	45830	N	N	N	1	CUSTOMER ISSUE	-
DMS_45381	45831	N	N	N	1	CUSTOMER ISSUE	-
DMS_45382	45832	N	N	N	1	CUSTOMER ISSUE	-
DMS_45383	45833	N	N	N	1	CUSTOMER ISSUE	-
DMS_45384	45834	N	N	N	1	CUSTOMER ISSUE	-
DMS_45385	45835	N	N	N	1	CUSTOMER ISSUE	-
DMS_45386	45836	N	N	N	1	CUSTOMER ISSUE	-
DMS_45387	45837	N	N	N	1	CUSTOMER ISSUE	-
DMS_45388	45838	N	N	N	1	CUSTOMER ISSUE	-
DMS_45389	45839	N	N	N	1	CUSTOMER ISSUE	-
DMS_45390	45840	N	N	N	1	CUSTOMER ISSUE	-
DMS_45391	45841	N	N	N	1	CUSTOMER ISSUE	-
DMS_45392	45842	N	N	N	1	CUSTOMER ISSUE	-
DMS_45393	45843	N	N	N	1	CUSTOMER ISSUE	-
DMS_45394	45844	N	N	N	1	CUSTOMER ISSUE	-
DMS_45395	45845	N	N	N	1	CUSTOMER ISSUE	-
DMS_45396	45846	N	N	N	1	CUSTOMER ISSUE	-
DMS_45397	45847	N	N	N	1	CUSTOMER ISSUE	-
DMS_45398	45848	N	N	N	1	CUSTOMER ISSUE	-
DMS_45399	45849	N	N	N	1	CUSTOMER ISSUE	-
DMS_45400	45850	N	N	N	1	CUSTOMER ISSUE	-
DMS_45401	45851	N	N	N	1	CUSTOMER ISSUE	-
DMS_45402	45852	N	N	N	1	CUSTOMER ISSUE	-
DMS_45403	45853	N	N	N	1	CUSTOMER ISSUE	-
DMS_45404	45854	N	N	N	1	CUSTOMER ISSUE	-
DMS_45405	45855	N	N	N	1	CUSTOMER ISSUE	-
DMS_45406	45856	N	N	N	1	CUSTOMER ISSUE	-
DMS_45407	45857	N	N	N	1	CUSTOMER ISSUE	-
DMS_45408	45858	N	N	N	1	CUSTOMER ISSUE	-
DMS_45409	45859	N	N	N	1	CUSTOMER ISSUE	-
DMS_45410	45860	N	N	N	1	CUSTOMER ISSUE	-
DMS_45411	45861	N	N	N	1	CUSTOMER ISSUE	-
DMS_45412	45862	N	N	N	1	CUSTOMER ISSUE	-
DMS_45413	45863	N	N	N	1	CUSTOMER ISSUE	-
DMS_45414	45864	N	N	N	1	CUSTOMER ISSUE	-
DMS_45415	45865	N	N	N	1	CUSTOMER ISSUE	-
DMS_45416	45866	N	N	N	1	CUSTOMER ISSUE	-
DMS_45417	45867	N	N	N	1	CUSTOMER ISSUE	-
DMS_45418	45868	N	N	N	1	CUSTOMER ISSUE	-
DMS_45419	45869	N	N	N	1	CUSTOMER ISSUE	-
DMS_45420	45870	N	N	N	1	CUSTOMER ISSUE	-
DMS_45421	45871	N	N	N	1	CUSTOMER ISSUE	-
DMS_45422	45872	N	N	N	1	CUSTOMER ISSUE	-
DMS_45423	45873	N	N	N	1	CUSTOMER ISSUE	-
DMS_45425	45874	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45426	45875	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45427	45876	N	N	N	1	CUSTOMER ISSUE	-
DMS_45428	45877	N	N	N	1	CUSTOMER ISSUE	-
DMS_45429	45878	N	N	N	1	CUSTOMER ISSUE	-
DMS_45430	45879	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45431	45880	N	N	N	1	CUSTOMER ISSUE	-
DMS_45432	45881	N	N	N	1	CUSTOMER ISSUE	-
DMS_45434	45882	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45435	45883	N	N	N	2	CUSTOMER ISSUE	-
DMS_45436	45884	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45437	45885	N	N	N	1	CUSTOMER ISSUE	-
DMS_45438	45886	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45439	45887	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45440	45888	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45441	45889	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45442	45890	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45443	45891	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45444	45892	N	N	N	1	CUSTOMER ISSUE	-
DMS_45449	45893	N	N	N	1	CUSTOMER ISSUE	-
DMS_45451	45894	N	N	N	1	CUSTOMER ISSUE	-
DMS_45453	45895	N	N	N	1	CUSTOMER ISSUE	-
DMS_45454	45896	N	N	Y	1	DIST - TREE TRIMMING	945

DMS_45455	45897	N	N	Y	1	TX - REPLACE	2500
DMS_45457	45898	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45459	45899	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45460	45900	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45461	45901	N	N	N	1	CUSTOMER ISSUE	-
DMS_45462	45902	N	N	N	1	CUSTOMER ISSUE	-
DMS_45463	45903	N	N	N	1	CUSTOMER ISSUE	-
DMS_45464	45904	N	N	N	1	CUSTOMER ISSUE	-
DMS_45465	45905	N	N	N	1	CUSTOMER ISSUE	-
DMS_45466	45906	N	N	N	1	CUSTOMER ISSUE	-
DMS_45467	45907	N	N	N	1	CUSTOMER ISSUE	-
DMS_45468	45908	N	N	N	1	CUSTOMER ISSUE	-
DMS_45469	45909	N	N	N	1	CUSTOMER ISSUE	-
DMS_45470	45910	N	N	N	1	CUSTOMER ISSUE	-
DMS_45471	45911	N	N	N	1	CUSTOMER ISSUE	-
DMS_45472	45912	N	N	N	1	CUSTOMER ISSUE	-
DMS_45473	45913	N	N	N	1	CUSTOMER ISSUE	-
DMS_45474	45914	N	N	N	1	CUSTOMER ISSUE	-
DMS_45475	45915	N	N	N	1	CUSTOMER ISSUE	-
DMS_45476	45916	N	N	N	1	CUSTOMER ISSUE	-
DMS_45477	45917	N	N	N	1	CUSTOMER ISSUE	-
DMS_45478	45918	N	N	N	1	CUSTOMER ISSUE	-
DMS_45479	45919	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45482	45920	N	N	Y	1	TX - REPLACE	2500
DMS_45483	45921	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45484	45922	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45492	45923	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45493	45924	N	N	N	1	CUSTOMER ISSUE	-
DMS_45494	45925	N	N	N	1	CUSTOMER ISSUE	-
DMS_45495	45926	N	N	N	1	CUSTOMER ISSUE	-
DMS_45496	45927	N	N	N	1	CUSTOMER ISSUE	-
DMS_45497	45928	N	N	N	1	CUSTOMER ISSUE	-
DMS_45498	45929	N	N	N	1	CUSTOMER ISSUE	-
DMS_45499	45930	N	N	N	1	CUSTOMER ISSUE	-
DMS_45500	45931	N	N	N	1	CUSTOMER ISSUE	-
DMS_45501	45932	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_45503	45933	N	N	N	1	CUSTOMER ISSUE	-
DMS_45504	45934	N	N	N	1	CUSTOMER ISSUE	-
DMS_45505	45935	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45506	45936	N	N	N	1	CUSTOMER ISSUE	-
DMS_45507	45937	N	N	N	1	CUSTOMER ISSUE	-
DMS_45508	45938	N	N	N	1	CUSTOMER ISSUE	-
DMS_45509	45939	N	N	N	1	CUSTOMER ISSUE	-
DMS_45511	45940	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45512	45941	N	N	N	1	CUSTOMER ISSUE	-
DMS_45513	45942	N	N	N	1	CUSTOMER ISSUE	-
DMS_45514	45943	N	N	N	1	CUSTOMER ISSUE	-
DMS_45515	45944	N	N	N	1	CUSTOMER ISSUE	-
DMS_45516	45945	N	N	N	1	CUSTOMER ISSUE	-
DMS_45517	45946	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45518	45947	N	N	N	1	CUSTOMER ISSUE	-
DMS_45520	45948	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45522	45949	N	N	N	1	CUSTOMER ISSUE	-
DMS_45523	45950	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45524	45951	N	N	N	1	CUSTOMER ISSUE	-
DMS_45525	45952	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45526	45953	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45528	45954	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45529	45955	N	N	N	1	CUSTOMER ISSUE	-
DMS_45531	45956	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45532	45957	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45533	45958	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45534	45959	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45535	45960	N	N	Y	1	TX - REPLACE	2500
DMS_45536	45961	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45538	45962	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45539	45963	N	N	Y	1	TX - REPLACE	2500
DMS_45540	45964	N	N	Y	1	TX - REPLACE	2500
DMS_45542	45965	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45543	45966	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45544	45967	N	N	N	1	CUSTOMER ISSUE	-
DMS_45546	45968	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45547	45969	N	N	N	1	CUSTOMER ISSUE	-
DMS_45548	45970	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_45549	45971	N	N	N	1	CUSTOMER ISSUE	-
DMS_45550	45972	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45551	45973	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45552	45974	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45553	45975	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45554	45976	N	N	Y	1	DIST - REPLACE FUSE	708.75

DMS_45555	45977	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45556	45978	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45557	45979	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45558	45980	N	N	N	1	CUSTOMER ISSUE	-
DMS_45559	45981	N	N	N	1	CUSTOMER ISSUE	-
DMS_45563	45982	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45564	45983	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45565	45984	N	N	Y	1	TX - REPLACE	2500
DMS_45566	45985	N	N	Y	1	TX - REPLACE	2500
DMS_45567	45986	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45568	45987	N	N	N	1	CUSTOMER ISSUE	-
DMS_45571	45988	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45572	45989	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45574	45990	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45575	45991	N	N	Y	1	TX - INSTALL	3000
DMS_45576	45992	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45577	45993	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45578	45994	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45579	45995	N	N	Y	1	TX - REPLACE	2500
DMS_45580	45996	N	N	Y	1	TX - REPLACE	2500
DMS_45581	45997	N	N	Y	2	DIST - REPLACE FUSE	708.75
DMS_45582	45998	N	N	Y	1	TX - REPLACE	2500
DMS_45583	45999	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45584	46000	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45585	46001	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45586	46002	N	N	N	1	CUSTOMER ISSUE	-
DMS_45587	46003	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45588	46004	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45589	46005	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45590	46006	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45591	46007	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45596	46008	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45597	46009	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45598	46010	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45599	46011	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45601	46012	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45602	46013	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45603	46014	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45604	46015	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45605	46016	N	N	N	1	CUSTOMER ISSUE	-
DMS_45606	46017	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45607	46018	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45608	46019	N	N	N	1	CUSTOMER ISSUE	-
DMS_45609	46020	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45610	46021	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45611	46022	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45612	46023	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45614	46024	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45615	46025	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45616	46026	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45617	46027	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45619	46028	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45620	46029	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45621	46030	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45622	46031	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45623	46032	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45624	46033	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45625	46034	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45626	46035	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45627	46036	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45628	46037	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45629	46038	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45630	46039	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45631	46040	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45632	46041	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45633	46042	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45634	46043	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45636	46044	N	N	N	1	CUSTOMER ISSUE	-
DMS_45637	46045	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45638	46046	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_45640	46047	N	N	N	1	CUSTOMER ISSUE	-
DMS_45641	46048	N	N	N	1	CUSTOMER ISSUE	-
DMS_45643	46049	N	N	N	1	CUSTOMER ISSUE	-
DMS_45644	46050	N	N	N	1	CUSTOMER ISSUE	-
DMS_45645	46051	N	N	N	1	CUSTOMER ISSUE	-
DMS_45647	46052	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45650	46053	N	N	N	1	CUSTOMER ISSUE	-
DMS_45652	46054	N	N	N	1	CUSTOMER ISSUE	-
DMS_45653	46055	N	N	N	1	CUSTOMER ISSUE	-
DMS_45654	46056	N	N	N	1	CUSTOMER ISSUE	-

DMS_45655	46057	N	N	N	1	CUSTOMER ISSUE	-
DMS_45656	46058	N	N	Y	1	TX - REPLACE	2500
DMS_45657	46059	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45658	46060	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45659	46061	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45660	46062	N	N	N	1	CUSTOMER ISSUE	-
DMS_45661	46063	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45663	46064	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45664	46065	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45665	46066	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45666	46067	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45667	46068	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45668	46069	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45669	46070	N	N	N	1	CUSTOMER ISSUE	-
DMS_45670	46071	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
DMS_45671	46072	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45672	46073	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45673	46074	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45675	46075	N	N	N	1	CUSTOMER ISSUE	-
DMS_45676	46076	N	N	N	1	CUSTOMER ISSUE	-
DMS_45677	46077	N	N	N	1	CUSTOMER ISSUE	-
DMS_45679	46078	N	N	N	1	CUSTOMER ISSUE	-
DMS_45680	46079	N	N	N	1	CUSTOMER ISSUE	-
DMS_45682	46080	N	N	N	1	CUSTOMER ISSUE	-
DMS_45683	46081	N	N	N	1	CUSTOMER ISSUE	-
DMS_45684	46082	N	N	N	1	CUSTOMER ISSUE	-
DMS_45685	46083	N	N	N	1	CUSTOMER ISSUE	-
DMS_45687	46084	N	N	N	1	CUSTOMER ISSUE	-
DMS_45688	46085	N	N	N	1	CUSTOMER ISSUE	-
DMS_45689	46086	N	N	N	1	CUSTOMER ISSUE	-
DMS_45690	46087	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45691	46088	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45692	46089	N	N	N	1	CUSTOMER ISSUE	-
DMS_45694	46090	N	N	N	1	CUSTOMER ISSUE	-
DMS_45695	46091	N	N	N	1	CUSTOMER ISSUE	-
DMS_45696	46092	N	N	N	1	CUSTOMER ISSUE	-
DMS_45697	46093	N	N	N	1	CUSTOMER ISSUE	-
DMS_45698	46094	N	N	N	1	CUSTOMER ISSUE	-
DMS_45699	46095	N	N	N	1	CUSTOMER ISSUE	-
DMS_45700	46096	N	N	N	1	CUSTOMER ISSUE	-
DMS_45701	46097	N	N	N	1	CUSTOMER ISSUE	-
DMS_45702	46098	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45703	46099	N	N	N	1	CUSTOMER ISSUE	-
DMS_45704	46100	N	N	N	1	CUSTOMER ISSUE	-
DMS_45705	46101	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45707	46102	N	N	N	1	CUSTOMER ISSUE	-
DMS_45710	46103	N	N	N	1	CUSTOMER ISSUE	-
DMS_45711	46104	N	N	N	1	CUSTOMER ISSUE	-
DMS_45712	46105	N	N	N	1	CUSTOMER ISSUE	-
DMS_45713	46106	N	N	N	1	CUSTOMER ISSUE	-
DMS_45714	46107	N	N	N	1	CUSTOMER ISSUE	-
DMS_45715	46108	N	N	N	1	CUSTOMER ISSUE	-
DMS_45716	46109	N	N	N	1	CUSTOMER ISSUE	-
DMS_45718	46110	N	N	N	1	CUSTOMER ISSUE	-
DMS_45719	46111	N	N	N	1	CUSTOMER ISSUE	-
DMS_45720	46112	N	N	N	1	CUSTOMER ISSUE	-
DMS_45721	46113	N	N	N	1	CUSTOMER ISSUE	-
DMS_45722	46114	N	N	N	1	CUSTOMER ISSUE	-
DMS_45725	46115	N	N	N	1	CUSTOMER ISSUE	-
DMS_45726	46116	N	N	N	1	CUSTOMER ISSUE	-
DMS_45727	46117	N	N	N	1	CUSTOMER ISSUE	-
DMS_45728	46118	N	N	N	1	CUSTOMER ISSUE	-
DMS_45729	46119	N	N	N	1	CUSTOMER ISSUE	-
DMS_45730	46120	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45732	46121	N	N	N	1	CUSTOMER ISSUE	-
DMS_45733	46122	N	N	N	1	CUSTOMER ISSUE	-
DMS_45734	46123	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45735	46124	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45737	46125	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45738	46126	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45739	46127	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45740	46128	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45741	46129	N	N	N	1	CUSTOMER ISSUE	-
DMS_45743	46130	N	N	N	1	CUSTOMER ISSUE	-
DMS_45745	46131	N	N	N	1	CUSTOMER ISSUE	-
DMS_45746	46132	N	N	N	1	CUSTOMER ISSUE	-
DMS_45747	46133	N	N	N	1	CUSTOMER ISSUE	-
DMS_45748	46134	N	N	N	1	CUSTOMER ISSUE	-
DMS_45749	46135	N	N	N	1	CUSTOMER ISSUE	-
DMS_45750	46136	N	N	N	1	CUSTOMER ISSUE	-

DMS_45751	46137	N	N	N	1	CUSTOMER ISSUE	-
DMS_45752	46138	N	N	N	1	CUSTOMER ISSUE	-
DMS_45753	46139	N	N	N	1	CUSTOMER ISSUE	-
DMS_45754	46140	N	N	N	1	CUSTOMER ISSUE	-
DMS_45755	46141	N	N	N	1	CUSTOMER ISSUE	-
DMS_45756	46142	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45757	46143	N	N	N	1	CUSTOMER ISSUE	-
DMS_45758	46144	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45760	46145	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45761	46146	N	N	N	1	CUSTOMER ISSUE	-
DMS_45762	46147	N	N	N	1	CUSTOMER ISSUE	-
DMS_45763	46148	N	N	N	1	CUSTOMER ISSUE	-
DMS_45764	46149	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45765	46150	N	N	N	1	CUSTOMER ISSUE	-
DMS_45766	46151	N	N	N	1	CUSTOMER ISSUE	-
DMS_45767	46152	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45768	46153	N	N	N	1	CUSTOMER ISSUE	-
DMS_45769	46154	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45770	46155	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45771	46156	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45772	46157	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45773	46158	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45774	46159	N	N	N	1	CUSTOMER ISSUE	-
DMS_45775	46160	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45776	46161	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45777	46162	N	N	N	1	CUSTOMER ISSUE	-
DMS_45778	46163	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45779	46164	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45780	46165	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45782	46166	N	N	N	1	CUSTOMER ISSUE	-
DMS_45783	46167	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45786	46168	N	N	N	1	CUSTOMER ISSUE	-
DMS_45787	46169	N	N	N	1	CUSTOMER ISSUE	-
DMS_45788	46170	N	N	N	1	CUSTOMER ISSUE	-
DMS_45789	46171	N	N	N	1	CUSTOMER ISSUE	-
DMS_45790	46172	N	N	N	1	CUSTOMER ISSUE	-
DMS_45791	46173	N	N	N	1	CUSTOMER ISSUE	-
DMS_45792	46174	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_45793	46175	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45794	46176	N	N	N	2	CUSTOMER ISSUE	-
DMS_45795	46177	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45796	46178	N	N	N	1	CUSTOMER ISSUE	-
DMS_45797	46179	N	N	N	1	CUSTOMER ISSUE	-
DMS_45798	46180	N	N	N	1	CUSTOMER ISSUE	-
DMS_45799	46181	N	N	N	1	CUSTOMER ISSUE	-
DMS_45800	46182	N	N	N	1	CUSTOMER ISSUE	-
DMS_45801	46183	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45803	46184	N	N	N	1	CUSTOMER ISSUE	-
DMS_45804	46185	N	N	N	1	CUSTOMER ISSUE	-
DMS_45805	46186	N	N	N	1	CUSTOMER ISSUE	-
DMS_45806	46187	N	N	N	1	CUSTOMER ISSUE	-
DMS_45807	46188	N	N	N	1	CUSTOMER ISSUE	-
DMS_45808	46189	N	N	N	1	CUSTOMER ISSUE	-
DMS_45810	46190	N	N	N	1	CUSTOMER ISSUE	-
DMS_45811	46191	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45812	46192	N	N	N	1	CUSTOMER ISSUE	-
DMS_45813	46193	N	N	N	1	CUSTOMER ISSUE	-
DMS_45814	46194	N	N	N	1	CUSTOMER ISSUE	-
DMS_45815	46195	N	N	N	1	CUSTOMER ISSUE	-
DMS_45816	46196	N	N	N	1	CUSTOMER ISSUE	-
DMS_45817	46197	N	N	N	1	CUSTOMER ISSUE	-
DMS_45818	46198	N	N	N	1	CUSTOMER ISSUE	-
DMS_45819	46199	N	N	N	1	CUSTOMER ISSUE	-
DMS_45820	46200	N	N	N	1	CUSTOMER ISSUE	-
DMS_45821	46201	N	N	N	1	CUSTOMER ISSUE	-
DMS_45822	46202	N	N	N	1	CUSTOMER ISSUE	-
DMS_45823	46203	N	N	N	1	CUSTOMER ISSUE	-
DMS_45824	46204	N	N	N	1	CUSTOMER ISSUE	-
DMS_45825	46205	N	N	N	1	CUSTOMER ISSUE	-
DMS_45826	46206	N	N	N	1	CUSTOMER ISSUE	-
DMS_45827	46207	N	N	N	1	CUSTOMER ISSUE	-
DMS_45828	46208	N	N	N	1	CUSTOMER ISSUE	-
DMS_45829	46209	N	N	N	1	CUSTOMER ISSUE	-
DMS_45830	46210	N	N	N	1	CUSTOMER ISSUE	-
DMS_45831	46211	N	N	N	1	CUSTOMER ISSUE	-
DMS_45832	46212	N	N	N	1	CUSTOMER ISSUE	-
DMS_45833	46213	N	N	N	1	CUSTOMER ISSUE	-
DMS_45834	46214	N	N	N	1	CUSTOMER ISSUE	-
DMS_45835	46215	N	N	N	1	CUSTOMER ISSUE	-
DMS_45836	46216	N	N	N	1	CUSTOMER ISSUE	-

DMS_45837	46217	N	N	N	1	CUSTOMER ISSUE	-
DMS_45838	46218	N	N	N	1	CUSTOMER ISSUE	-
DMS_45839	46219	N	N	N	1	CUSTOMER ISSUE	-
DMS_45840	46220	N	N	N	1	CUSTOMER ISSUE	-
DMS_45841	46221	N	N	N	1	CUSTOMER ISSUE	-
DMS_45842	46222	N	N	N	1	CUSTOMER ISSUE	-
DMS_45843	46223	N	N	N	1	CUSTOMER ISSUE	-
DMS_45844	46224	N	N	N	1	CUSTOMER ISSUE	-
DMS_45845	46225	N	N	N	1	CUSTOMER ISSUE	-
DMS_45846	46226	N	N	N	1	CUSTOMER ISSUE	-
DMS_45847	46227	N	N	N	1	CUSTOMER ISSUE	-
DMS_45848	46228	N	N	N	1	CUSTOMER ISSUE	-
DMS_45849	46229	N	N	N	1	CUSTOMER ISSUE	-
DMS_45850	46230	N	N	N	1	CUSTOMER ISSUE	-
DMS_45851	46231	N	N	N	1	CUSTOMER ISSUE	-
DMS_45852	46232	N	N	N	1	CUSTOMER ISSUE	-
DMS_45853	46233	N	N	N	1	CUSTOMER ISSUE	-
DMS_45854	46234	N	N	N	1	CUSTOMER ISSUE	-
DMS_45855	46235	N	N	N	1	CUSTOMER ISSUE	-
DMS_45856	46236	N	N	N	1	CUSTOMER ISSUE	-
DMS_45857	46237	N	N	N	1	CUSTOMER ISSUE	-
DMS_45858	46238	N	N	N	1	CUSTOMER ISSUE	-
DMS_45859	46239	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45860	46240	N	N	N	1	CUSTOMER ISSUE	-
DMS_45861	46241	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45862	46242	N	N	N	1	CUSTOMER ISSUE	-
DMS_45863	46243	N	N	N	1	CUSTOMER ISSUE	-
DMS_45864	46244	N	N	N	1	CUSTOMER ISSUE	-
DMS_45865	46245	N	N	Y	1	TX - REPLACE	2500
DMS_45866	46246	N	N	N	1	CUSTOMER ISSUE	-
DMS_45867	46247	N	N	N	1	CUSTOMER ISSUE	-
DMS_45869	46248	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45870	46249	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45872	46250	N	N	N	1	CUSTOMER ISSUE	-
DMS_45873	46251	N	N	N	1	CUSTOMER ISSUE	-
DMS_45874	46252	N	N	N	1	CUSTOMER ISSUE	-
DMS_45875	46253	N	N	N	1	CUSTOMER ISSUE	-
DMS_45876	46254	N	N	N	1	CUSTOMER ISSUE	-
DMS_45877	46255	N	N	N	1	CUSTOMER ISSUE	-
DMS_45878	46256	N	N	N	1	CUSTOMER ISSUE	-
DMS_45879	46257	N	N	N	1	CUSTOMER ISSUE	-
DMS_45880	46258	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_45881	46259	N	N	N	1	CUSTOMER ISSUE	-
DMS_45882	46260	N	N	N	1	CUSTOMER ISSUE	-
DMS_45883	46261	N	N	N	1	CUSTOMER ISSUE	-
DMS_45884	46262	N	N	N	1	CUSTOMER ISSUE	-
DMS_45885	46263	N	N	N	1	CUSTOMER ISSUE	-
DMS_45886	46264	N	N	N	1	CUSTOMER ISSUE	-
DMS_45887	46265	N	N	N	1	CUSTOMER ISSUE	-
DMS_45888	46266	N	N	N	1	CUSTOMER ISSUE	-
DMS_45890	46267	N	N	N	1	CUSTOMER ISSUE	-
DMS_45891	46268	N	N	N	1	CUSTOMER ISSUE	-
DMS_45892	46269	N	N	N	1	CUSTOMER ISSUE	-
DMS_45893	46270	N	N	N	1	CUSTOMER ISSUE	-
DMS_45894	46271	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_45895	46272	N	N	N	1	CUSTOMER ISSUE	-
DMS_45896	46273	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_45897	46274	N	N	N	1	CUSTOMER ISSUE	-
DMS_45898	46275	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45899	46276	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45900	46277	N	N	N	1	CUSTOMER ISSUE	-
DMS_45902	46278	N	N	N	1	CUSTOMER ISSUE	-
DMS_45903	46279	N	N	N	1	CUSTOMER ISSUE	-
DMS_45904	46280	N	N	N	1	CUSTOMER ISSUE	-
DMS_45905	46281	N	N	N	1	CUSTOMER ISSUE	-
DMS_45906	46282	N	N	N	1	CUSTOMER ISSUE	-
DMS_45907	46283	N	N	N	1	CUSTOMER ISSUE	-
DMS_45908	46284	N	N	N	1	CUSTOMER ISSUE	-
DMS_45909	46285	N	N	N	1	CUSTOMER ISSUE	-
DMS_45910	46286	N	N	N	1	CUSTOMER ISSUE	-
DMS_45911	46287	N	N	N	1	CUSTOMER ISSUE	-
DMS_45913	46288	N	N	N	1	CUSTOMER ISSUE	-
DMS_45914	46289	N	N	N	1	CUSTOMER ISSUE	-
DMS_45915	46290	N	N	N	1	CUSTOMER ISSUE	-
DMS_45918	46291	N	N	N	1	CUSTOMER ISSUE	-
DMS_45919	46292	N	N	N	1	CUSTOMER ISSUE	-
DMS_45922	46293	N	N	N	1	CUSTOMER ISSUE	-
DMS_45923	46294	N	N	N	1	CUSTOMER ISSUE	-
DMS_45924	46295	N	N	N	1	CUSTOMER ISSUE	-
DMS_45925	46296	N	N	N	1	CUSTOMER ISSUE	-

DMS_45926	46297	N	N	N	2	CUSTOMER ISSUE	-
DMS_45927	46298	N	N	N	1	CUSTOMER ISSUE	-
DMS_45928	46299	N	N	N	1	CUSTOMER ISSUE	-
DMS_45930	46300	N	N	N	1	CUSTOMER ISSUE	-
DMS_45931	46301	N	N	N	1	CUSTOMER ISSUE	-
DMS_45932	46302	N	N	N	1	CUSTOMER ISSUE	-
DMS_45933	46303	N	N	N	1	CUSTOMER ISSUE	-
DMS_45934	46304	N	N	N	1	CUSTOMER ISSUE	-
DMS_45935	46305	N	N	N	1	CUSTOMER ISSUE	-
DMS_45936	46306	N	N	N	1	CUSTOMER ISSUE	-
DMS_45937	46307	N	N	N	1	CUSTOMER ISSUE	-
DMS_45938	46308	N	N	N	1	CUSTOMER ISSUE	-
DMS_45939	46309	N	N	N	1	CUSTOMER ISSUE	-
DMS_45940	46310	N	N	N	1	CUSTOMER ISSUE	-
DMS_45941	46311	N	N	N	1	CUSTOMER ISSUE	-
DMS_45942	46312	N	N	N	1	CUSTOMER ISSUE	-
DMS_45943	46313	N	N	N	1	CUSTOMER ISSUE	-
DMS_45944	46314	N	N	N	1	CUSTOMER ISSUE	-
DMS_45945	46315	N	N	N	1	CUSTOMER ISSUE	-
DMS_45946	46316	N	N	N	1	CUSTOMER ISSUE	-
DMS_45947	46317	N	N	N	1	CUSTOMER ISSUE	-
DMS_45948	46318	N	N	N	1	CUSTOMER ISSUE	-
DMS_45949	46319	N	N	N	1	CUSTOMER ISSUE	-
DMS_45950	46320	N	N	N	1	CUSTOMER ISSUE	-
DMS_45952	46321	N	N	N	1	CUSTOMER ISSUE	-
DMS_45953	46322	N	N	N	1	CUSTOMER ISSUE	-
DMS_45954	46323	N	N	N	1	CUSTOMER ISSUE	-
DMS_45955	46324	N	N	N	1	CUSTOMER ISSUE	-
DMS_45956	46325	N	N	N	1	CUSTOMER ISSUE	-
DMS_45959	46326	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45962	46327	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45963	46328	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45964	46329	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45965	46330	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45967	46331	N	N	Y	2	DIST - TREE TRIMMING	945
DMS_45969	46332	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45970	46333	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45971	46334	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45972	46335	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45973	46336	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45974	46337	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45975	46338	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45976	46339	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_45978	46340	N	N	N	1	CUSTOMER ISSUE	-
DMS_45979	46341	N	N	N	1	CUSTOMER ISSUE	-
DMS_45980	46342	N	N	N	1	CUSTOMER ISSUE	-
DMS_45984	46343	N	N	N	1	CUSTOMER ISSUE	-
DMS_45985	46344	N	N	N	1	CUSTOMER ISSUE	-
DMS_45987	46345	N	N	N	1	CUSTOMER ISSUE	-
DMS_45989	46346	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_45990	46347	N	N	N	1	CUSTOMER ISSUE	-
DMS_45991	46348	N	N	N	1	CUSTOMER ISSUE	-
DMS_45992	46349	N	N	N	1	CUSTOMER ISSUE	-
DMS_45993	46350	N	N	N	1	CUSTOMER ISSUE	-
DMS_45994	46351	N	N	N	1	CUSTOMER ISSUE	-
DMS_45995	46352	N	N	N	1	CUSTOMER ISSUE	-
DMS_45996	46353	N	N	N	1	CUSTOMER ISSUE	-
DMS_45997	46354	N	N	N	1	CUSTOMER ISSUE	-
DMS_45998	46355	N	N	N	1	CUSTOMER ISSUE	-
DMS_45999	46356	N	N	N	1	CUSTOMER ISSUE	-
DMS_46000	46357	N	N	N	1	CUSTOMER ISSUE	-
DMS_46001	46358	N	N	N	1	CUSTOMER ISSUE	-
DMS_46002	46359	N	N	N	1	CUSTOMER ISSUE	-
DMS_46003	46360	N	N	N	1	CUSTOMER ISSUE	-
DMS_46004	46361	N	N	N	1	CUSTOMER ISSUE	-
DMS_46005	46362	N	N	N	1	CUSTOMER ISSUE	-
DMS_46006	46363	N	N	N	1	CUSTOMER ISSUE	-
DMS_46007	46364	N	N	N	1	CUSTOMER ISSUE	-
DMS_46008	46365	N	N	N	1	CUSTOMER ISSUE	-
DMS_46009	46366	N	N	N	1	CUSTOMER ISSUE	-
DMS_46010	46367	N	N	N	1	CUSTOMER ISSUE	-
DMS_46012	46368	N	N	N	1	CUSTOMER ISSUE	-
DMS_46013	46369	N	N	N	1	CUSTOMER ISSUE	-
DMS_46014	46370	N	N	N	1	CUSTOMER ISSUE	-
DMS_46015	46371	N	N	N	1	CUSTOMER ISSUE	-
DMS_46016	46372	N	N	N	1	CUSTOMER ISSUE	-
DMS_46017	46373	N	N	N	1	CUSTOMER ISSUE	-
DMS_46018	46374	N	N	N	1	CUSTOMER ISSUE	-
DMS_46019	46375	N	N	N	1	CUSTOMER ISSUE	-
DMS_46020	46376	N	N	N	1	CUSTOMER ISSUE	-

DMS_46021	46377	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46022	46378	N	N	N	1	CUSTOMER ISSUE	-
DMS_46023	46379	N	N	N	1	CUSTOMER ISSUE	-
DMS_46024	46380	N	N	N	1	CUSTOMER ISSUE	-
DMS_46025	46381	N	N	N	1	CUSTOMER ISSUE	-
DMS_46026	46382	N	N	N	1	CUSTOMER ISSUE	-
DMS_46027	46383	N	N	N	1	CUSTOMER ISSUE	-
DMS_46028	46384	N	N	N	1	CUSTOMER ISSUE	-
DMS_46029	46385	N	N	N	1	CUSTOMER ISSUE	-
DMS_46031	46386	N	N	N	1	CUSTOMER ISSUE	-
DMS_46032	46387	N	N	N	1	CUSTOMER ISSUE	-
DMS_46033	46388	N	N	N	1	CUSTOMER ISSUE	-
DMS_46034	46389	N	N	N	1	CUSTOMER ISSUE	-
DMS_46035	46390	N	N	N	1	CUSTOMER ISSUE	-
DMS_46036	46391	N	N	N	1	CUSTOMER ISSUE	-
DMS_46037	46392	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46038	46393	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46039	46394	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46040	46395	N	N	N	1	CUSTOMER ISSUE	-
DMS_46041	46396	N	N	N	1	CUSTOMER ISSUE	-
DMS_46042	46397	N	N	N	1	CUSTOMER ISSUE	-
DMS_46043	46398	N	N	N	1	CUSTOMER ISSUE	-
DMS_46044	46399	N	N	N	1	CUSTOMER ISSUE	-
DMS_46045	46400	N	N	N	1	CUSTOMER ISSUE	-
DMS_46046	46401	N	N	N	1	CUSTOMER ISSUE	-
DMS_46047	46402	N	N	N	1	CUSTOMER ISSUE	-
DMS_46048	46403	N	N	N	1	CUSTOMER ISSUE	-
DMS_46049	46404	N	N	N	1	CUSTOMER ISSUE	-
DMS_46050	46405	N	N	N	1	CUSTOMER ISSUE	-
DMS_46051	46406	N	N	N	1	CUSTOMER ISSUE	-
DMS_46052	46407	N	N	N	1	CUSTOMER ISSUE	-
DMS_46053	46408	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46054	46409	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46055	46410	N	N	N	1	CUSTOMER ISSUE	-
DMS_46056	46411	N	N	N	1	CUSTOMER ISSUE	-
DMS_46057	46412	N	N	N	1	CUSTOMER ISSUE	-
DMS_46058	46413	N	N	N	1	CUSTOMER ISSUE	-
DMS_46059	46414	N	N	N	1	CUSTOMER ISSUE	-
DMS_46060	46415	N	N	N	1	CUSTOMER ISSUE	-
DMS_46061	46416	N	N	N	1	CUSTOMER ISSUE	-
DMS_46062	46417	N	N	N	1	CUSTOMER ISSUE	-
DMS_46063	46418	N	N	N	1	CUSTOMER ISSUE	-
DMS_46064	46419	N	N	N	1	CUSTOMER ISSUE	-
DMS_46065	46420	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46066	46421	N	N	N	1	CUSTOMER ISSUE	-
DMS_46067	46422	N	N	N	1	CUSTOMER ISSUE	-
DMS_46068	46423	N	N	N	1	CUSTOMER ISSUE	-
DMS_46069	46424	N	N	N	1	CUSTOMER ISSUE	-
DMS_46070	46425	N	N	N	1	CUSTOMER ISSUE	-
DMS_46071	46426	N	N	N	1	CUSTOMER ISSUE	-
DMS_46072	46427	N	N	N	1	CUSTOMER ISSUE	-
DMS_46073	46428	N	N	N	1	CUSTOMER ISSUE	-
DMS_46074	46429	N	N	N	1	CUSTOMER ISSUE	-
DMS_46075	46430	N	N	N	1	CUSTOMER ISSUE	-
DMS_46076	46431	N	N	N	1	CUSTOMER ISSUE	-
DMS_46077	46432	N	N	N	1	CUSTOMER ISSUE	-
DMS_46078	46433	N	N	N	1	CUSTOMER ISSUE	-
DMS_46079	46434	N	N	N	1	CUSTOMER ISSUE	-
DMS_46080	46435	N	N	N	1	CUSTOMER ISSUE	-
DMS_46082	46436	N	N	N	1	CUSTOMER ISSUE	-
DMS_46083	46437	N	N	N	1	CUSTOMER ISSUE	-
DMS_46084	46438	N	N	N	1	CUSTOMER ISSUE	-
DMS_46085	46439	N	N	N	1	CUSTOMER ISSUE	-
DMS_46086	46440	N	N	N	1	CUSTOMER ISSUE	-
DMS_46087	46441	N	N	N	1	CUSTOMER ISSUE	-
DMS_46088	46442	N	N	N	1	CUSTOMER ISSUE	-
DMS_46089	46443	N	N	N	1	CUSTOMER ISSUE	-
DMS_46090	46444	N	N	N	1	CUSTOMER ISSUE	-
DMS_46091	46445	N	N	N	1	CUSTOMER ISSUE	-
DMS_46092	46446	N	N	N	1	CUSTOMER ISSUE	-
DMS_46093	46447	N	N	N	1	CUSTOMER ISSUE	-
DMS_46094	46448	N	N	N	1	CUSTOMER ISSUE	-
DMS_46095	46449	N	N	N	1	CUSTOMER ISSUE	-
DMS_46096	46450	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46097	46451	N	N	N	1	CUSTOMER ISSUE	-
DMS_46098	46452	N	N	N	1	CUSTOMER ISSUE	-
DMS_46099	46453	N	N	N	1	CUSTOMER ISSUE	-
DMS_46100	46454	N	N	N	1	CUSTOMER ISSUE	-
DMS_46101	46455	N	N	N	1	CUSTOMER ISSUE	-
DMS_46102	46456	N	N	N	1	CUSTOMER ISSUE	-

DMS_46103	46457	N	N	N	1	CUSTOMER ISSUE	-
DMS_46104	46458	N	N	N	1	CUSTOMER ISSUE	-
DMS_46105	46459	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46106	46460	N	N	N	1	CUSTOMER ISSUE	-
DMS_46107	46461	N	N	N	1	CUSTOMER ISSUE	-
DMS_46108	46462	N	N	N	1	CUSTOMER ISSUE	-
DMS_46109	46463	N	N	N	1	CUSTOMER ISSUE	-
DMS_46110	46464	N	N	N	1	CUSTOMER ISSUE	-
DMS_46111	46465	N	N	N	1	CUSTOMER ISSUE	-
DMS_46112	46466	N	N	N	1	CUSTOMER ISSUE	-
DMS_46113	46467	N	N	N	1	CUSTOMER ISSUE	-
DMS_46114	46468	N	N	N	1	CUSTOMER ISSUE	-
DMS_46115	46469	N	N	N	1	CUSTOMER ISSUE	-
DMS_46116	46470	N	N	N	1	CUSTOMER ISSUE	-
DMS_46117	46471	N	N	N	1	CUSTOMER ISSUE	-
DMS_46118	46472	N	N	N	1	CUSTOMER ISSUE	-
DMS_46119	46473	N	N	N	1	CUSTOMER ISSUE	-
DMS_46120	46474	N	N	N	1	CUSTOMER ISSUE	-
DMS_46121	46475	N	N	N	1	CUSTOMER ISSUE	-
DMS_46122	46476	N	N	N	1	CUSTOMER ISSUE	-
DMS_46123	46477	N	N	N	1	CUSTOMER ISSUE	-
DMS_46124	46478	N	N	N	1	CUSTOMER ISSUE	-
DMS_46125	46479	N	N	N	1	CUSTOMER ISSUE	-
DMS_46126	46480	N	N	N	1	CUSTOMER ISSUE	-
DMS_46127	46481	N	N	N	1	CUSTOMER ISSUE	-
DMS_46128	46482	N	N	N	1	CUSTOMER ISSUE	-
DMS_46129	46483	N	N	N	1	CUSTOMER ISSUE	-
DMS_46130	46484	N	N	N	1	CUSTOMER ISSUE	-
DMS_46131	46485	N	N	N	1	CUSTOMER ISSUE	-
DMS_46132	46486	N	N	N	1	CUSTOMER ISSUE	-
DMS_46133	46487	N	N	N	1	CUSTOMER ISSUE	-
DMS_46135	46488	N	N	N	1	CUSTOMER ISSUE	-
DMS_46136	46489	N	N	N	1	CUSTOMER ISSUE	-
DMS_46137	46490	N	N	N	1	CUSTOMER ISSUE	-
DMS_46138	46491	N	N	N	1	CUSTOMER ISSUE	-
DMS_46140	46492	N	N	N	1	CUSTOMER ISSUE	-
DMS_46141	46493	N	N	N	1	CUSTOMER ISSUE	-
DMS_46142	46494	N	N	N	1	CUSTOMER ISSUE	-
DMS_46143	46495	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46144	46496	N	N	N	1	CUSTOMER ISSUE	-
DMS_46145	46497	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_46146	46498	N	N	N	1	CUSTOMER ISSUE	-
DMS_46147	46499	N	N	N	1	CUSTOMER ISSUE	-
DMS_46148	46500	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46149	46501	N	N	N	1	CUSTOMER ISSUE	-
DMS_46150	46502	N	N	N	1	CUSTOMER ISSUE	-
DMS_46151	46503	N	N	N	1	CUSTOMER ISSUE	-
DMS_46152	46504	N	N	N	1	CUSTOMER ISSUE	-
DMS_46153	46505	N	N	N	1	CUSTOMER ISSUE	-
DMS_46154	46506	N	N	N	1	CUSTOMER ISSUE	-
DMS_46155	46507	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46156	46508	N	N	N	1	CUSTOMER ISSUE	-
DMS_46157	46509	N	N	N	1	CUSTOMER ISSUE	-
DMS_46158	46510	N	N	N	1	CUSTOMER ISSUE	-
DMS_46159	46511	N	N	N	1	CUSTOMER ISSUE	-
DMS_46160	46512	N	N	N	1	CUSTOMER ISSUE	-
DMS_46161	46513	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46162	46514	N	N	N	1	CUSTOMER ISSUE	-
DMS_46163	46515	N	N	N	1	CUSTOMER ISSUE	-
DMS_46164	46516	N	N	N	1	CUSTOMER ISSUE	-
DMS_46165	46517	N	N	N	1	CUSTOMER ISSUE	-
DMS_46166	46518	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_46167	46519	N	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
DMS_46168	46520	N	N	N	1	CUSTOMER ISSUE	-
DMS_46169	46521	N	N	N	1	CUSTOMER ISSUE	-
DMS_46170	46522	N	N	N	1	CUSTOMER ISSUE	-
DMS_46171	46523	N	N	N	1	CUSTOMER ISSUE	-
DMS_46172	46524	N	N	N	1	CUSTOMER ISSUE	-
DMS_46173	46525	N	N	N	1	CUSTOMER ISSUE	-
DMS_46174	46526	N	N	N	1	CUSTOMER ISSUE	-
DMS_46175	46527	N	N	N	1	CUSTOMER ISSUE	-
DMS_46176	46528	N	N	N	1	CUSTOMER ISSUE	-
DMS_46177	46529	N	N	N	1	CUSTOMER ISSUE	-
DMS_46178	46530	N	N	N	1	CUSTOMER ISSUE	-
DMS_46179	46531	N	N	N	1	CUSTOMER ISSUE	-
DMS_46180	46532	N	N	N	1	CUSTOMER ISSUE	-
DMS_46181	46533	N	N	N	1	CUSTOMER ISSUE	-
DMS_46182	46534	N	N	N	1	CUSTOMER ISSUE	-
DMS_46183	46535	N	N	N	1	CUSTOMER ISSUE	-
DMS_46184	46536	N	N	N	1	CUSTOMER ISSUE	-

DMS_46185	46537	N	N	N	1	CUSTOMER ISSUE	-
DMS_46186	46538	N	N	N	1	CUSTOMER ISSUE	-
DMS_46187	46539	N	N	N	1	CUSTOMER ISSUE	-
DMS_46188	46540	N	N	N	1	CUSTOMER ISSUE	-
DMS_46189	46541	N	N	N	1	CUSTOMER ISSUE	-
DMS_46190	46542	N	N	N	1	CUSTOMER ISSUE	-
DMS_46191	46543	N	N	N	1	CUSTOMER ISSUE	-
DMS_46192	46544	N	N	N	1	CUSTOMER ISSUE	-
DMS_46193	46545	N	N	N	1	CUSTOMER ISSUE	-
DMS_46194	46546	N	N	N	1	CUSTOMER ISSUE	-
DMS_46195	46547	N	N	N	1	CUSTOMER ISSUE	-
DMS_46196	46548	N	N	N	1	CUSTOMER ISSUE	-
DMS_46197	46549	N	N	N	1	CUSTOMER ISSUE	-
DMS_46198	46550	N	N	N	1	CUSTOMER ISSUE	-
DMS_46199	46551	N	N	N	1	CUSTOMER ISSUE	-
DMS_46200	46552	N	N	N	1	CUSTOMER ISSUE	-
DMS_46201	46553	N	N	N	1	CUSTOMER ISSUE	-
DMS_46202	46554	N	N	N	1	CUSTOMER ISSUE	-
DMS_46203	46555	N	N	N	1	CUSTOMER ISSUE	-
DMS_46204	46556	N	N	N	1	CUSTOMER ISSUE	-
DMS_46205	46557	N	N	N	1	CUSTOMER ISSUE	-
DMS_46206	46558	N	N	N	1	CUSTOMER ISSUE	-
DMS_46207	46559	N	N	N	1	CUSTOMER ISSUE	-
DMS_46208	46560	N	N	N	1	CUSTOMER ISSUE	-
DMS_46209	46561	N	N	N	1	CUSTOMER ISSUE	-
DMS_46210	46562	N	N	N	1	CUSTOMER ISSUE	-
DMS_46211	46563	N	N	N	1	CUSTOMER ISSUE	-
DMS_46212	46564	N	N	N	1	CUSTOMER ISSUE	-
DMS_46213	46565	N	N	N	1	CUSTOMER ISSUE	-
DMS_46214	46566	N	N	N	1	CUSTOMER ISSUE	-
DMS_46215	46567	N	N	N	1	CUSTOMER ISSUE	-
DMS_46216	46568	N	N	N	1	CUSTOMER ISSUE	-
DMS_46217	46569	N	N	N	1	CUSTOMER ISSUE	-
DMS_46218	46570	N	N	N	1	CUSTOMER ISSUE	-
DMS_46219	46571	N	N	N	1	CUSTOMER ISSUE	-
DMS_46221	46572	N	N	N	1	CUSTOMER ISSUE	-
DMS_46224	46573	N	N	N	1	CUSTOMER ISSUE	-
DMS_46225	46574	N	N	N	1	CUSTOMER ISSUE	-
DMS_46226	46575	N	N	N	1	CUSTOMER ISSUE	-
DMS_46227	46576	N	N	N	1	CUSTOMER ISSUE	-
DMS_46228	46577	N	N	N	1	CUSTOMER ISSUE	-
DMS_46229	46578	N	N	N	1	CUSTOMER ISSUE	-
DMS_46230	46579	N	N	N	1	CUSTOMER ISSUE	-
DMS_46231	46580	N	N	N	1	CUSTOMER ISSUE	-
DMS_46232	46581	N	N	N	1	CUSTOMER ISSUE	-
DMS_46233	46582	N	N	N	1	CUSTOMER ISSUE	-
DMS_46234	46583	N	N	N	1	CUSTOMER ISSUE	-
DMS_46235	46584	N	N	N	1	CUSTOMER ISSUE	-
DMS_46236	46585	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46237	46586	N	N	N	1	CUSTOMER ISSUE	-
DMS_46238	46587	N	N	N	1	CUSTOMER ISSUE	-
DMS_46243	46588	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_46246	46589	N	N	N	1	CUSTOMER ISSUE	-
DMS_46247	46590	N	N	N	1	CUSTOMER ISSUE	-
DMS_46249	46591	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_46251	46592	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_46255	46593	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46258	46594	N	N	N	1	CUSTOMER ISSUE	-
DMS_46259	46595	N	N	N	1	CUSTOMER ISSUE	-
DMS_46260	46596	N	N	N	1	CUSTOMER ISSUE	-
DMS_46261	46597	N	N	Y	1	TX - REPLACE	2500
DMS_46262	46598	N	N	N	1	CUSTOMER ISSUE	-
DMS_46263	46599	N	N	N	1	CUSTOMER ISSUE	-
DMS_46264	46600	N	N	N	1	CUSTOMER ISSUE	-
DMS_46265	46601	N	N	N	1	CUSTOMER ISSUE	-
DMS_46266	46602	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_46267	46603	N	N	N	1	CUSTOMER ISSUE	-
DMS_46268	46604	N	N	N	1	CUSTOMER ISSUE	-
DMS_46269	46605	N	N	N	1	CUSTOMER ISSUE	-
DMS_46270	46606	N	N	N	1	CUSTOMER ISSUE	-
DMS_46271	46607	N	N	N	1	CUSTOMER ISSUE	-
DMS_46272	46608	N	N	N	1	CUSTOMER ISSUE	-
DMS_46273	46609	N	N	N	1	CUSTOMER ISSUE	-
DMS_46274	46610	N	N	N	1	CUSTOMER ISSUE	-
DMS_46275	46611	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_46276	46612	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46277	46613	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46278	46614	N	N	N	1	CUSTOMER ISSUE	-
DMS_46279	46615	N	N	N	1	CUSTOMER ISSUE	-
DMS_46280	46616	N	N	N	1	CUSTOMER ISSUE	-

DMS_46281	46617	N	N	N	1	CUSTOMER ISSUE	-
DMS_46282	46618	N	N	N	1	CUSTOMER ISSUE	-
DMS_46283	46619	N	N	N	1	CUSTOMER ISSUE	-
DMS_46284	46620	N	N	N	1	CUSTOMER ISSUE	-
DMS_46285	46621	N	N	N	1	CUSTOMER ISSUE	-
DMS_46286	46622	N	N	N	1	CUSTOMER ISSUE	-
DMS_46287	46623	N	N	N	1	CUSTOMER ISSUE	-
DMS_46288	46624	N	N	N	1	CUSTOMER ISSUE	-
DMS_46290	46625	N	N	N	1	CUSTOMER ISSUE	-
DMS_46291	46626	N	N	N	1	CUSTOMER ISSUE	-
DMS_46292	46627	N	N	N	1	CUSTOMER ISSUE	-
DMS_46294	46628	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46295	46629	N	N	Y	1	TX/SEC/SVC- REPLACE	3800
DMS_46296	46630	N	N	N	1	CUSTOMER ISSUE	-
DMS_46298	46631	N	N	N	1	CUSTOMER ISSUE	-
DMS_46299	46632	N	N	N	1	CUSTOMER ISSUE	-
DMS_46300	46633	N	N	N	1	CUSTOMER ISSUE	-
DMS_46301	46634	N	N	N	1	CUSTOMER ISSUE	-
DMS_46302	46635	N	N	N	1	CUSTOMER ISSUE	-
DMS_46303	46636	N	N	N	1	CUSTOMER ISSUE	-
DMS_46304	46637	N	N	N	1	CUSTOMER ISSUE	-
DMS_46305	46638	N	N	N	1	CUSTOMER ISSUE	-
DMS_46306	46639	N	N	N	1	CUSTOMER ISSUE	-
DMS_46308	46640	N	N	N	1	CUSTOMER ISSUE	-
DMS_46309	46641	N	N	N	1	CUSTOMER ISSUE	-
DMS_46310	46642	N	N	N	1	CUSTOMER ISSUE	-
DMS_46311	46643	N	N	N	1	CUSTOMER ISSUE	-
DMS_46313	46644	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46314	46645	N	N	N	1	CUSTOMER ISSUE	-
DMS_46315	46646	N	N	N	1	CUSTOMER ISSUE	-
DMS_46316	46647	N	N	N	1	CUSTOMER ISSUE	-
DMS_46317	46648	N	N	N	1	CUSTOMER ISSUE	-
DMS_46318	46649	N	N	N	1	CUSTOMER ISSUE	-
DMS_46320	46650	N	N	N	1	CUSTOMER ISSUE	-
DMS_46321	46651	N	N	N	1	CUSTOMER ISSUE	-
DMS_46323	46652	N	N	N	1	CUSTOMER ISSUE	-
DMS_46325	46653	N	N	N	1	CUSTOMER ISSUE	-
DMS_46330	46654	N	N	N	1	CUSTOMER ISSUE	-
DMS_46331	46655	N	N	N	1	CUSTOMER ISSUE	-
DMS_46332	46656	N	N	N	1	CUSTOMER ISSUE	-
DMS_46333	46657	N	N	N	1	CUSTOMER ISSUE	-
DMS_46334	46658	N	N	N	1	CUSTOMER ISSUE	-
DMS_46338	46659	N	N	N	1	CUSTOMER ISSUE	-
DMS_46339	46660	N	N	N	1	CUSTOMER ISSUE	-
DMS_46340	46661	N	N	N	2	CUSTOMER ISSUE	-
DMS_46341	46662	N	N	N	1	CUSTOMER ISSUE	-
DMS_46342	46663	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_46343	46664	N	N	N	1	CUSTOMER ISSUE	-
DMS_46344	46665	N	N	N	1	CUSTOMER ISSUE	-
DMS_46345	46666	N	N	N	1	CUSTOMER ISSUE	-
DMS_46346	46667	N	N	N	1	CUSTOMER ISSUE	-
DMS_46350	46668	N	N	N	1	CUSTOMER ISSUE	-
DMS_46351	46669	N	N	N	1	CUSTOMER ISSUE	-
DMS_46352	46670	N	N	N	1	CUSTOMER ISSUE	-
DMS_46353	46671	N	N	N	1	CUSTOMER ISSUE	-
DMS_46354	46672	N	N	N	1	CUSTOMER ISSUE	-
DMS_46355	46673	N	N	N	1	CUSTOMER ISSUE	-
DMS_46356	46674	N	N	N	1	CUSTOMER ISSUE	-
DMS_46357	46675	N	N	N	1	CUSTOMER ISSUE	-
DMS_46358	46676	N	N	N	1	CUSTOMER ISSUE	-
DMS_46359	46677	N	N	N	2	CUSTOMER ISSUE	-
DMS_46361	46678	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_46362	46679	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46363	46680	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46365	46681	N	N	N	1	CUSTOMER ISSUE	-
DMS_46366	46682	N	N	N	1	CUSTOMER ISSUE	-
DMS_46367	46683	N	N	N	1	CUSTOMER ISSUE	-
DMS_46368	46684	N	N	N	1	CUSTOMER ISSUE	-
DMS_46369	46685	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46372	46686	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46373	46687	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_46374	46688	N	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
DMS_46375	46689	N	N	N	1	CUSTOMER ISSUE	-
DMS_46376	46690	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_46377	46691	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46378	46692	N	N	N	1	CUSTOMER ISSUE	-
DMS_46381	46693	N	N	N	1	CUSTOMER ISSUE	-
DMS_46390	46694	N	N	N	1	CUSTOMER ISSUE	-
DMS_46391	46695	N	N	N	1	CUSTOMER ISSUE	-
DMS_46392	46696	N	N	N	1	CUSTOMER ISSUE	-

DMS_46393	46697	N	N	N	1	CUSTOMER ISSUE	-
DMS_46394	46698	N	N	N	1	CUSTOMER ISSUE	-
DMS_46396	46699	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46397	46700	N	N	N	1	CUSTOMER ISSUE	-
DMS_46398	46701	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_46399	46702	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46400	46703	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46401	46704	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46402	46705	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46403	46706	N	N	N	1	CUSTOMER ISSUE	-
DMS_46404	46707	N	N	N	1	CUSTOMER ISSUE	-
DMS_46405	46708	N	N	Y	1	SUB/TRANS - REPAIR	5000
DMS_46406	46709	N	N	N	1	CUSTOMER ISSUE	-
DMS_46409	46710	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46410	46711	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46411	46712	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46412	46713	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46413	46714	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46414	46715	N	N	N	1	CUSTOMER ISSUE	-
DMS_46415	46716	N	N	N	1	CUSTOMER ISSUE	-
DMS_46416	46717	N	N	N	1	CUSTOMER ISSUE	-
DMS_46417	46718	N	N	N	1	CUSTOMER ISSUE	-
DMS_46418	46719	N	N	N	1	CUSTOMER ISSUE	-
DMS_46419	46720	N	N	N	1	CUSTOMER ISSUE	-
DMS_46420	46721	N	N	N	1	CUSTOMER ISSUE	-
DMS_46421	46722	N	N	N	1	CUSTOMER ISSUE	-
DMS_46422	46723	N	N	N	1	CUSTOMER ISSUE	-
DMS_46423	46724	N	N	N	1	CUSTOMER ISSUE	-
DMS_46424	46725	N	N	N	1	CUSTOMER ISSUE	-
DMS_46425	46726	N	N	N	1	CUSTOMER ISSUE	-
DMS_46426	46727	N	N	N	1	CUSTOMER ISSUE	-
DMS_46427	46728	N	N	N	1	CUSTOMER ISSUE	-
DMS_46428	46729	N	N	N	1	CUSTOMER ISSUE	-
DMS_46429	46730	N	N	N	1	CUSTOMER ISSUE	-
DMS_46430	46731	N	N	N	1	CUSTOMER ISSUE	-
DMS_46431	46732	N	N	N	1	CUSTOMER ISSUE	-
DMS_46432	46733	N	N	N	1	CUSTOMER ISSUE	-
DMS_46433	46734	N	N	N	1	CUSTOMER ISSUE	-
DMS_46434	46735	N	N	N	1	CUSTOMER ISSUE	-
DMS_46435	46736	N	N	N	1	CUSTOMER ISSUE	-
DMS_46437	46737	N	N	N	1	CUSTOMER ISSUE	-
DMS_46438	46738	N	N	N	1	CUSTOMER ISSUE	-
DMS_46440	46739	N	N	N	1	CUSTOMER ISSUE	-
DMS_46441	46740	N	N	N	1	CUSTOMER ISSUE	-
DMS_46442	46741	N	N	N	1	CUSTOMER ISSUE	-
DMS_46443	46742	N	N	N	1	CUSTOMER ISSUE	-
DMS_46444	46743	N	N	N	1	CUSTOMER ISSUE	-
DMS_46445	46744	N	N	N	1	CUSTOMER ISSUE	-
DMS_46446	46745	N	N	N	1	CUSTOMER ISSUE	-
DMS_46447	46746	N	N	N	1	CUSTOMER ISSUE	-
DMS_46448	46747	N	N	N	1	CUSTOMER ISSUE	-
DMS_46449	46748	N	N	N	1	CUSTOMER ISSUE	-
DMS_46450	46749	N	N	N	1	CUSTOMER ISSUE	-
DMS_46452	46750	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46453	46751	N	N	N	1	CUSTOMER ISSUE	-
DMS_46454	46752	N	N	N	1	CUSTOMER ISSUE	-
DMS_46455	46753	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46456	46754	N	N	N	1	CUSTOMER ISSUE	-
DMS_46457	46755	N	N	N	1	CUSTOMER ISSUE	-
DMS_46458	46756	N	N	N	1	CUSTOMER ISSUE	-
DMS_46459	46757	N	N	N	1	CUSTOMER ISSUE	-
DMS_46460	46758	N	N	N	1	CUSTOMER ISSUE	-
DMS_46461	46759	N	N	N	1	CUSTOMER ISSUE	-
DMS_46462	46760	N	N	N	1	CUSTOMER ISSUE	-
DMS_46464	46761	N	N	N	1	CUSTOMER ISSUE	-
DMS_46465	46762	N	N	N	1	CUSTOMER ISSUE	-
DMS_46466	46763	N	N	N	1	CUSTOMER ISSUE	-
DMS_46467	46764	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46468	46765	N	N	N	1	CUSTOMER ISSUE	-
DMS_46469	46766	N	N	N	1	CUSTOMER ISSUE	-
DMS_46470	46767	N	N	N	1	CUSTOMER ISSUE	-
DMS_46471	46768	N	N	N	1	CUSTOMER ISSUE	-
DMS_46473	46769	N	N	N	1	CUSTOMER ISSUE	-
DMS_46474	46770	N	N	N	1	CUSTOMER ISSUE	-
DMS_46475	46771	N	N	N	1	CUSTOMER ISSUE	-
DMS_46476	46772	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46477	46773	N	N	N	1	CUSTOMER ISSUE	-
DMS_46478	46774	N	N	N	1	CUSTOMER ISSUE	-
DMS_46479	46775	N	N	N	1	CUSTOMER ISSUE	-
DMS_46480	46776	N	N	N	1	CUSTOMER ISSUE	-

DMS_46481	46777	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46482	46778	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46483	46779	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46484	46780	N	N	N	1	CUSTOMER ISSUE	-
DMS_46485	46781	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46486	46782	N	N	N	1	CUSTOMER ISSUE	-
DMS_46487	46783	N	N	N	1	CUSTOMER ISSUE	-
DMS_46488	46784	N	N	N	1	CUSTOMER ISSUE	-
DMS_46489	46785	N	N	N	1	CUSTOMER ISSUE	-
DMS_46490	46786	N	N	N	1	CUSTOMER ISSUE	-
DMS_46491	46787	N	N	N	1	CUSTOMER ISSUE	-
DMS_46492	46788	N	N	N	1	CUSTOMER ISSUE	-
DMS_46493	46789	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46494	46790	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46495	46791	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46497	46792	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46498	46793	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46499	46794	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46500	46795	N	N	N	1	CUSTOMER ISSUE	-
DMS_46501	46796	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46502	46797	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46503	46798	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46505	46799	N	N	Y	2	SEC/SVC - REPLACE	708.75
DMS_46506	46800	N	N	N	1	CUSTOMER ISSUE	-
DMS_46507	46801	N	N	N	1	CUSTOMER ISSUE	-
DMS_46508	46802	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46509	46803	N	N	N	1	CUSTOMER ISSUE	-
DMS_46510	46804	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46511	46805	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46512	46806	N	N	N	1	CUSTOMER ISSUE	-
DMS_46513	46807	N	N	N	1	CUSTOMER ISSUE	-
DMS_46514	46808	N	N	N	1	CUSTOMER ISSUE	-
DMS_46515	46809	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46516	46810	N	N	N	1	CUSTOMER ISSUE	-
DMS_46517	46811	N	N	N	1	CUSTOMER ISSUE	-
DMS_46518	46812	N	N	N	1	CUSTOMER ISSUE	-
DMS_46519	46813	N	N	N	1	CUSTOMER ISSUE	-
DMS_46520	46814	N	N	N	1	CUSTOMER ISSUE	-
DMS_46521	46815	N	N	N	1	CUSTOMER ISSUE	-
DMS_46522	46816	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
DMS_46523	46817	N	N	N	1	CUSTOMER ISSUE	-
DMS_46524	46818	N	N	N	1	CUSTOMER ISSUE	-
DMS_46525	46819	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46526	46820	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46527	46821	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46528	46822	N	N	N	1	CUSTOMER ISSUE	-
DMS_46529	46823	N	N	N	1	CUSTOMER ISSUE	-
DMS_46530	46824	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46531	46825	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46532	46826	N	N	N	1	CUSTOMER ISSUE	-
DMS_46533	46827	N	N	N	1	CUSTOMER ISSUE	-
DMS_46534	46828	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46535	46829	N	N	N	1	CUSTOMER ISSUE	-
DMS_46537	46830	N	N	N	1	CUSTOMER ISSUE	-
DMS_46538	46831	N	N	N	1	CUSTOMER ISSUE	-
DMS_46539	46832	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46540	46833	N	N	N	1	CUSTOMER ISSUE	-
DMS_46541	46834	N	N	N	1	CUSTOMER ISSUE	-
DMS_46542	46835	N	N	N	1	CUSTOMER ISSUE	-
DMS_46543	46836	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46544	46837	N	N	N	1	CUSTOMER ISSUE	-
DMS_46545	46838	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46546	46839	N	N	N	1	CUSTOMER ISSUE	-
DMS_46548	46840	N	N	N	1	CUSTOMER ISSUE	-
DMS_46549	46841	N	N	N	1	CUSTOMER ISSUE	-
DMS_46550	46842	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46551	46843	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46552	46844	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46553	46845	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46554	46846	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46555	46847	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46559	46848	N	N	N	1	CUSTOMER ISSUE	-
DMS_46560	46849	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_46562	46850	N	N	N	1	CUSTOMER ISSUE	-
DMS_46564	46851	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46565	46852	N	N	N	1	CUSTOMER ISSUE	-
DMS_46566	46853	N	N	N	1	CUSTOMER ISSUE	-
DMS_46569	46854	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46570	46855	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46571	46856	N	N	N	1	CUSTOMER ISSUE	-

DMS_46573	46857	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_46574	46858	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46575	46859	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46576	46860	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46577	46861	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46578	46862	N	N	N	1	CUSTOMER ISSUE	-
DMS_46579	46863	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46583	46864	N	N	N	1	CUSTOMER ISSUE	-
DMS_46589	46865	N	N	N	1	CUSTOMER ISSUE	-
DMS_46590	46866	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_46591	46867	N	N	N	1	CUSTOMER ISSUE	-
DMS_46595	46868	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46596	46869	N	N	N	1	CUSTOMER ISSUE	-
DMS_46597	46870	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_46598	46871	N	N	Y	2	SEC/SVC - REPAIR	472.5
DMS_46599	46872	N	N	N	1	CUSTOMER ISSUE	-
DMS_46601	46873	N	N	N	1	CUSTOMER ISSUE	-
DMS_46602	46874	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46603	46875	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46604	46876	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46605	46877	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46606	46878	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46607	46879	N	N	N	1	CUSTOMER ISSUE	-
DMS_46608	46880	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46609	46881	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46610	46882	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46611	46883	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46612	46884	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46613	46885	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46614	46886	N	N	N	1	CUSTOMER ISSUE	-
DMS_46615	46887	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46616	46888	N	N	N	1	CUSTOMER ISSUE	-
DMS_46617	46889	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46618	46890	N	N	N	1	CUSTOMER ISSUE	-
DMS_46619	46891	N	N	N	1	CUSTOMER ISSUE	-
DMS_46621	46892	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46622	46893	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46623	46894	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46624	46895	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46625	46896	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46626	46897	N	N	N	1	CUSTOMER ISSUE	-
DMS_46627	46898	N	N	N	1	CUSTOMER ISSUE	-
DMS_46628	46899	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46629	46900	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46630	46901	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46632	46902	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46633	46903	N	N	N	1	CUSTOMER ISSUE	-
DMS_46635	46904	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46636	46905	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46637	46906	N	N	N	1	CUSTOMER ISSUE	-
DMS_46638	46907	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46639	46908	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46640	46909	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46641	46910	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46642	46911	N	N	N	1	CUSTOMER ISSUE	-
DMS_46643	46912	N	N	N	1	CUSTOMER ISSUE	-
DMS_46644	46913	N	N	N	1	CUSTOMER ISSUE	-
DMS_46645	46914	N	N	N	1	CUSTOMER ISSUE	-
DMS_46646	46915	N	N	N	1	CUSTOMER ISSUE	-
DMS_46647	46916	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46649	46917	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46650	46918	N	N	N	1	CUSTOMER ISSUE	-
DMS_46651	46919	N	N	N	1	CUSTOMER ISSUE	-
DMS_46652	46920	N	N	N	1	CUSTOMER ISSUE	-
DMS_46653	46921	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46654	46922	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46655	46923	N	N	N	1	CUSTOMER ISSUE	-
DMS_46656	46924	N	N	N	1	CUSTOMER ISSUE	-
DMS_46657	46925	N	N	N	1	CUSTOMER ISSUE	-
DMS_46658	46926	N	N	N	1	CUSTOMER ISSUE	-
DMS_46659	46927	N	N	N	1	CUSTOMER ISSUE	-
DMS_46661	46928	N	N	N	1	CUSTOMER ISSUE	-
DMS_46662	46929	N	N	N	1	CUSTOMER ISSUE	-
DMS_46664	46930	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46665	46931	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46666	46932	N	N	N	1	CUSTOMER ISSUE	-
DMS_46667	46933	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46668	46934	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46669	46935	N	N	N	1	CUSTOMER ISSUE	-
DMS_46670	46936	N	N	N	1	CUSTOMER ISSUE	-

DMS_46671	46937	N	N	N	1	CUSTOMER ISSUE	-
DMS_46672	46938	N	N	N	1	CUSTOMER ISSUE	-
DMS_46673	46939	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_46675	46940	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46676	46941	N	N	N	1	CUSTOMER ISSUE	-
DMS_46682	46942	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46683	46943	N	N	N	1	CUSTOMER ISSUE	-
DMS_46684	46944	N	N	N	1	CUSTOMER ISSUE	-
DMS_46685	46945	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46686	46946	N	N	N	2	CUSTOMER ISSUE	-
DMS_46688	46947	N	N	N	1	CUSTOMER ISSUE	-
DMS_46689	46948	N	N	N	1	CUSTOMER ISSUE	-
DMS_46690	46949	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46692	46950	N	N	N	1	CUSTOMER ISSUE	-
DMS_46693	46951	N	N	N	1	CUSTOMER ISSUE	-
DMS_46695	46952	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_46696	46953	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
DMS_46697	46954	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_46700	46955	N	N	N	1	CUSTOMER ISSUE	-
DMS_46701	46956	N	N	Y	1	DIST - CHANGE SETTINGS	708.75
DMS_46702	46957	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_46704	46958	N	N	N	1	CUSTOMER ISSUE	-
DMS_46705	46959	N	N	N	1	CUSTOMER ISSUE	-
DMS_46708	46960	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46709	46961	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46716	46962	N	N	N	1	CUSTOMER ISSUE	-
DMS_46719	46963	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46721	46964	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46723	46965	N	N	Y	1	TX - REPLACE	2500
DMS_46724	46966	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46725	46967	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46727	46968	N	N	Y	1	DIST - TREE TRIMMING	945
DMS_46735	46969	N	N	Y	1	SEC/SVC - REPLACE	708.75
DMS_46738	46970	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_46739	46971	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_46740	46972	N	N	Y	1	TX - REPLACE	2500
DMS_46741	46973	N	N	Y	1	SEC/SVC - REPAIR	472.5
DMS_46744	46974	N	N	Y	1	DIST - REPLACE FUSE	708.75
DMS_46747	46975	N	N	N	1	CUSTOMER ISSUE	-
DMS_46749	46976	N	N	N	1	CUSTOMER ISSUE	-
DMS_46750	46977	N	N	N	1	CUSTOMER ISSUE	-
DMS_46751	46978	N	N	N	1	CUSTOMER ISSUE	-
DMS_46752	46979	N	N	N	1	CUSTOMER ISSUE	-
DMS_46753	46980	N	N	N	1	CUSTOMER ISSUE	-
DMS_46754	46981	N	N	N	1	CUSTOMER ISSUE	-
DMS_46755	46982	N	N	N	1	CUSTOMER ISSUE	-
DMS_46756	46983	N	N	N	1	CUSTOMER ISSUE	-
DMS_46757	46984	N	N	N	1	CUSTOMER ISSUE	-
DMS_46758	46985	N	N	N	1	CUSTOMER ISSUE	-
DMS_46759	46986	N	N	N	1	CUSTOMER ISSUE	-
DMS_46760	46987	N	N	N	1	CUSTOMER ISSUE	-
DMS_46761	46988	N	N	N	1	CUSTOMER ISSUE	-
DMS_46762	46989	N	N	N	1	CUSTOMER ISSUE	-
PQ_001	46990	N	N	Y	2	DIST - REPAIR EQUIPMENT	2500
PQ_002	46991	N	N	N	3	CUSTOMER ISSUE	-
PQ_003	46992	Y	N	Y	2	DIST - CIRCUIT RETURN TO NORMAL CONFIG	472.5
PQ_004	46993	Y	N	N	14	CUSTOMER ISSUE	-
PQ_005	46994	N	N	Y	1	DIST - CIRCUIT RETURN TO NORMAL CONFIG	472.5
PQ_006	46995	N	N	Y	4	DIST - REPLACE EQUIPMENT	5500
PQ_007	46996	N	N	N	3	CUSTOMER ISSUE	-
PQ_008	46997	Y	N	N	1	CUSTOMER ISSUE	-
PQ_009	46998	Y	N	Y	5	SEC/SVC - REPLACE	708.75
PQ_010	46999	Y	N	N	41	CUSTOMER ISSUE	-
PQ_011	47000	N	N	Y	1	SUB/TRANS - REPAIR	5000
PQ_012	47001	N	N	N	1	CUSTOMER ISSUE	-
PQ_013	47002	Y	N	N	1	CUSTOMER ISSUE	-
PQ_014	47003	N	N	N	1	CUSTOMER ISSUE	-
PQ_015	47004	N	N	N	1	CUSTOMER ISSUE	-
PQ_016	47005	N	N	Y	3	SUB/TRANS - REPAIR	5000
PQ_017	47006	Y	N	N	40	CUSTOMER ISSUE	-
PQ_018	47007	N	N	N	42	CUSTOMER ISSUE	-
PQ_019	47008	N	N	N	3	CUSTOMER ISSUE	-
PQ_020	47009	N	N	N	3	CUSTOMER ISSUE	-
PQ_021	47010	N	N	N	3	CUSTOMER ISSUE	-
PQ_022	47011	N	N	N	12	CUSTOMER ISSUE	-
PQ_023	47012	Y	N	N	5	CUSTOMER ISSUE	-
PQ_024	47013	Y	N	N	34	CUSTOMER ISSUE	-
PQ_025	47014	N	N	N	0	CUSTOMER ISSUE	-
PQ_026	47015	N	N	N	36	CUSTOMER ISSUE	-
PQ_027	47016	N	N	N	50	CUSTOMER ISSUE	-

PQ_028	47017	N	N	Y	3	SUB/TRANS - REPAIR	5000
PQ_029	47018	N	N	N	12	CUSTOMER ISSUE	-
PQ_030	47019	N	N	N	33	CUSTOMER ISSUE	-
PQ_031	47020	Y	N	N	5	CUSTOMER ISSUE	-
PQ_032	47021	N	N	N	5	CUSTOMER ISSUE	-
PQ_033	47022	Y	Y	N	5	CUSTOMER ISSUE	-
PQ_034	47023	N	N	N	3	CUSTOMER ISSUE	-
PQ_035	47024	N	N	N	5	CUSTOMER ISSUE	-
PQ_036	47025	N	N	N	23	CUSTOMER ISSUE	-
PQ_037	47026	N	N	N	1	CUSTOMER ISSUE	-
PQ_038	47027	Y	Y	Y	35	DIST - CHANGE SETTINGS	708.75
PQ_039	47028	Y	N	N	6	CUSTOMER ISSUE	-
PQ_040	47029	Y	N	Y	8	DIST - CHANGE SETTINGS	708.75
PQ_041	47030	N	N	N	0	CUSTOMER ISSUE	-
PQ_042	47031	Y	Y	Y	7	DIST - CHANGE SETTINGS	708.75
PQ_043	47032	N	N	N	1	CUSTOMER ISSUE	-
PQ_044	47033	Y	Y	Y	43	DIST - CHANGE SETTINGS	708.75
PQ_045	47034	N	N	N	14	CUSTOMER ISSUE	-
PQ_046	47035	Y	Y	N	36	CUSTOMER ISSUE	-
PQ_047	47036	N	N	Y	43	DIST - CHANGE SETTINGS	708.75
PQ_048	47037	N	N	N	2	CUSTOMER ISSUE	-
PQ_049	47038	Y	Y	Y	19	DIST - CHANGE SETTINGS	708.75
PQ_050	47039	N	N	Y	5	DIST - CHANGE SETTINGS	708.75
PQ_051	47040	Y	N	Y	27	DIST - CHANGE SETTINGS	708.75
PQ_052	47041	N	N	N	5	CUSTOMER ISSUE	-
PQ_053	47042	N	N	N	12	CUSTOMER ISSUE	-
PQ_054	47043	N	N	N	55	CUSTOMER ISSUE	-
PQ_055	47044	N	N	N	33	CUSTOMER ISSUE	-
PQ_056	47045	Y	Y	Y	27	DIST - CHANGE SETTINGS	708.75
PQ_057	47046	N	N	N	1	CUSTOMER ISSUE	-
PQ_058	47047	Y	Y	Y	34	DIST - REPLACE EQUIPMENT	5500
PQ_059	47048	N	N	Y	34	DIST - REPLACE EQUIPMENT	5500
PQ_060	47049	N	N	N	4	CUSTOMER ISSUE	-
PQ_061	47050	Y	Y	Y	27	DIST - CHANGE SETTINGS	708.75
PQ_062	47051	N	N	Y	2	DIST - REPAIR EQUIPMENT	2500
PQ_063	47052	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
PQ_064	47053	Y	Y	Y	31	DIST - CHANGE SETTINGS	708.75
PQ_065	47054	N	N	Y	28	DIST - CHANGE SETTINGS	708.75
PQ_066	47055	N	N	Y	28	DIST - CHANGE SETTINGS	708.75
PQ_067	47056	N	N	Y	3	DIST - CHANGE SETTINGS	708.75
PQ_068	47057	N	N	Y	0	DIST - CHANGE SETTINGS	708.75
PQ_069	47058	N	N	N	22	CUSTOMER ISSUE	-
PQ_070	47059	N	N	Y	6	SUB/TRANS - CHANGE SETTINGS	708.75
PQ_071	47060	Y	N	N	7	CUSTOMER ISSUE	-
PQ_072	47061	N	N	N	111	CUSTOMER ISSUE	-
PQ_073	47062	Y	N	N	13	CUSTOMER ISSUE	-
PQ_074	47063	N	N	N	8	CUSTOMER ISSUE	-
PQ_075	47064	N	N	Y	2	DIST - CHANGE SETTINGS	708.75
PQ_076	47065	Y	N	N	3	CUSTOMER ISSUE	-
PQ_077	47066	N	N	N	21	CUSTOMER ISSUE	-
PQ_078	47067	Y	N	N	5	CUSTOMER ISSUE	-
PQ_079	47068	N	N	N	142	CUSTOMER ISSUE	-
PQ_080	47069	N	N	Y	8	DIST - REPAIR EQUIPMENT	2500
PQ_081	47070	Y	N	Y	12	DIST - REPAIR EQUIPMENT	2500
PQ_082	47071	Y	N	N	13	CUSTOMER ISSUE	-
PQ_083	47072	N	N	N	47	CUSTOMER ISSUE	-
PQ_084	47073	Y	N	Y	0	DIST - CIRCUIT RETURN TO NORMAL CONFIG	472.5
PQ_085	47074	Y	N	Y	6	DIST - CIRCUIT RETURN TO NORMAL CONFIG	472.5
PQ_086	47075	N	N	N	4	CUSTOMER ISSUE	-
PQ_087	47076	N	N	Y	2	DIST - CHANGE SETTINGS	708.75
PQ_088	47077	Y	N	Y	2	TX - REPLACE	2500
PQ_089	47078	Y	N	N	24	CUSTOMER ISSUE	-
PQ_090	47079	Y	N	Y	1	DIST - REPAIR EQUIPMENT	2500
PQ_091	47080	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
PQ_092	47081	Y	N	Y	1	DIST - REPAIR EQUIPMENT	2500
PQ_093	47082	Y	N	N	0	CUSTOMER ISSUE	-
PQ_094	47083	N	N	N	3	CUSTOMER ISSUE	-
PQ_095	47084	N	N	Y	8	DIST - REPAIR EQUIPMENT	2500
PQ_096	47085	N	N	Y	0	TX - REPLACE	2500
PQ_097	47086	Y	N	N	92	CUSTOMER ISSUE	-
PQ_098	47087	N	N	N	6	CUSTOMER ISSUE	-
PQ_099	47088	N	N	Y	0	DIST - CIRCUIT RETURN TO NORMAL CONFIG	472.5
PQ_100	47089	N	Y	Y	4	SUB/TRANS - REPAIR	5000
PQ_101	47090	N	N	N	216	CUSTOMER ISSUE	-
PQ_102	47091	N	N	N	13	CUSTOMER ISSUE	-
PQ_103	47092	Y	N	Y	13	DIST - REPAIR EQUIPMENT	2500
PQ_104	47093	N	N	Y	7	DIST - REPAIR EQUIPMENT	2500
PQ_105	47094	N	N	Y	7	SEC/SVC - REPLACE	708.75
PQ_106	47095	N	N	Y	8	SEC/SVC - REPAIR	472.5
PQ_107	47096	N	N	Y	1	DIST - REPLACE EQUIPMENT	5500

PQ_108	47097	Y	N	Y	14	DIST - CHANGE SETTINGS	708.75
PQ_109	47098	N	N	Y	0	DIST - REPLACE EQUIPMENT	5500
PQ_110	47099	Y	N	N	59	CUSTOMER ISSUE	-
PQ_111	47100	Y	N	Y	14	DIST - CIRCUIT RETURN TO NORMAL CONFIG	472.5
PQ_112	47101	Y	N	Y	61	DIST - REPAIR EQUIPMENT	2500
PQ_113	47102	N	N	Y	0	SEC/SVC - REPLACE	708.75
PQ_114	47103	N	N	Y	63	SUB/TRANS - CHANGE SETTINGS	708.75
PQ_115	47104	N	N	Y	2	TX - REPLACE	2500
PQ_116	47105	N	N	Y	2	DIST - REPAIR EQUIPMENT	2500
PQ_117	47106	N	N	N	6	CUSTOMER ISSUE	-
PQ_118	47107	N	N	N	4	CUSTOMER ISSUE	-
PQ_119	47108	Y	N	N	0	CUSTOMER ISSUE	-
PQ_120	47109	Y	N	Y	1	DIST - CIRCUIT RETURN TO NORMAL CONFIG	472.5
PQ_121	47110	N	N	N	5	CUSTOMER ISSUE	-
PQ_122	47111	Y	N	N	1	CUSTOMER ISSUE	-
PQ_123	47112	N	N	N	2	CUSTOMER ISSUE	-
PQ_124	47113	N	N	Y	16	DIST - REPAIR EQUIPMENT	2500
PQ_125	47114	N	N	Y	0	DIST - REPLACE FUSE	708.75
PQ_126	47115	N	N	N	0	CUSTOMER ISSUE	-
PQ_127	47116	N	N	Y	1	SUB/TRANS - REPAIR	5000
PQ_128	47117	N	N	Y	5	SUB/TRANS - REPAIR	5000
PQ_129	47118	N	N	Y	2	DIST - CHANGE SETTINGS	708.75
PQ_130	47119	N	N	Y	0	DIST - REPAIR EQUIPMENT	2500
PQ_131	47120	N	N	Y	0	DIST - REPAIR EQUIPMENT	2500
PQ_132	47121	N	N	N	0	CUSTOMER ISSUE	-
PQ_133	47122	N	N	Y	4	DIST - REPLACE FUSE	708.75
PQ_134	47123	N	N	N	1	CUSTOMER ISSUE	-
PQ_135	47124	N	Y	Y	0	DIST - REPLACE EQUIPMENT	5500
PQ_136	47125	N	N	N	0	CUSTOMER ISSUE	-
PQ_137	47126	Y	N	N	21	CUSTOMER ISSUE	-
PQ_138	47127	N	N	Y	0	DIST - REPLACE FUSE	708.75
PQ_139	47128	N	N	Y	0	DIST - REPAIR EQUIPMENT	2500
PQ_140	47129	Y	N	Y	8	DIST - REPAIR EQUIPMENT	2500
PQ_141	47130	N	N	N	5	CUSTOMER ISSUE	-
PQ_142	47131	N	N	Y	6	DIST - REPAIR EQUIPMENT	2500
PQ_143	47132	Y	N	Y	7	DIST - REPLACE FUSE	708.75
PQ_144	47133	N	N	Y	1	SEC/SVC - REPAIR	472.5
PQ_145	47134	N	N	N	6	CUSTOMER ISSUE	-
PQ_146	47135	N	N	Y	2	DIST - CHANGE SETTINGS	708.75
PQ_147	47136	N	N	N	1	CUSTOMER ISSUE	-
PQ_148	47137	Y	N	Y	1	SUB/TRANS - CHANGE SETTINGS	708.75
PQ_149	47138	N	N	N	2	CUSTOMER ISSUE	-
PQ_150	47139	N	N	Y	24	DIST - CHANGE SETTINGS	708.75
PQ_151	47140	N	N	Y	26	DIST - TREE TRIMMING	945
PQ_152	47141	N	N	N	6	CUSTOMER ISSUE	-
PQ_153	47142	N	N	N	1	CUSTOMER ISSUE	-
PQ_154	47143	N	N	Y	5	DIST - REPAIR EQUIPMENT	2500
PQ_155	47144	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
PQ_156	47145	N	N	N	3	CUSTOMER ISSUE	-
PQ_157	47146	N	N	N	0	CUSTOMER ISSUE	-
PQ_158	47147	Y	N	Y	1	DIST - REPAIR EQUIPMENT	2500
PQ_159	47148	Y	N	N	1	CUSTOMER ISSUE	-
PQ_160	47149	N	N	N	6	CUSTOMER ISSUE	-
PQ_161	47150	N	N	N	20	CUSTOMER ISSUE	-
PQ_162	47151	N	N	N	5	CUSTOMER ISSUE	-
PQ_163	47152	Y	N	N	18	CUSTOMER ISSUE	-
PQ_164	47153	N	N	N	6	CUSTOMER ISSUE	-
PQ_165	47154	Y	N	Y	12	SUB/TRANS - REPAIR	5000
PQ_166	47155	Y	N	Y	0	SUB/TRANS - REPAIR	5000
PQ_167	47156	N	N	Y	1	DIST - REPAIR EQUIPMENT	2500
PQ_168	47157	N	N	Y	2	SUB/TRANS - REPAIR	5000
PQ_169	47158	Y	N	Y	15	DIST - CHANGE SETTINGS	708.75
PQ_170	47159	N	N	N	84	CUSTOMER ISSUE	-
PQ_171	47160	Y	N	N	5	CUSTOMER ISSUE	-
PQ_172	47161	N	N	Y	56	TX - REPLACE	2500
PQ_173	47162	N	N	N	25	CUSTOMER ISSUE	-
PQ_174	47163	N	N	Y	84	TX - REPLACE	2500
PQ_175	47164	N	N	N	9	CUSTOMER ISSUE	-
PQ_176	47165	N	N	Y	23	DIST - CHANGE SETTINGS	708.75
PQ_177	47166	N	N	N	1	CUSTOMER ISSUE	-
VRT_001	47167	N	N	N	39	CUSTOMER ISSUE	-
VRT_002	47168	N	N	N	39	CUSTOMER ISSUE	-
VRT_003	47169	N	N	N	39	CUSTOMER ISSUE	-
VRT_004	47170	N	N	N	39	CUSTOMER ISSUE	-
VRT_005	47171	N	N	N	39	CUSTOMER ISSUE	-
VRT_006	47172	N	N	N	39	CUSTOMER ISSUE	-
VRT_007	47173	N	N	N	39	CUSTOMER ISSUE	-
VRT_008	47174	N	N	N	39	CUSTOMER ISSUE	-
VRT_009	47175	N	N	N	39	CUSTOMER ISSUE	-
VRT_010	47176	N	N	N	39	CUSTOMER ISSUE	-

VRT_011	47177	N	N	N	39	CUSTOMER ISSUE	-
VRT_012	47178	N	N	N	39	CUSTOMER ISSUE	-
VRT_013	47179	N	N	N	39	CUSTOMER ISSUE	-
VRT_014	47180	N	N	N	39	CUSTOMER ISSUE	-
VRT_015	47181	N	N	N	39	CUSTOMER ISSUE	-
VRT_016	47182	N	N	N	39	CUSTOMER ISSUE	-
VRT_017	47183	N	N	N	39	CUSTOMER ISSUE	-
VRT_018	47184	N	N	N	39	CUSTOMER ISSUE	-
VRT_019	47185	N	N	N	39	CUSTOMER ISSUE	-
VRT_020	47186	N	N	N	39	CUSTOMER ISSUE	-
VRT_021	47187	N	N	N	39	CUSTOMER ISSUE	-
VRT_022	47188	N	N	N	39	CUSTOMER ISSUE	-
VRT_023	47189	N	N	N	39	CUSTOMER ISSUE	-
VRT_024	47190	N	N	N	39	CUSTOMER ISSUE	-
VRT_025	47191	N	N	N	39	CUSTOMER ISSUE	-
VRT_026	47192	N	N	N	39	CUSTOMER ISSUE	-
VRT_027	47193	N	N	N	39	CUSTOMER ISSUE	-
VRT_028	47194	N	N	N	39	CUSTOMER ISSUE	-
VRT_029	47195	N	N	N	39	CUSTOMER ISSUE	-
VRT_030	47196	N	N	N	39	CUSTOMER ISSUE	-
VRT_031	47197	N	N	N	39	CUSTOMER ISSUE	-
VRT_032	47198	N	N	N	39	CUSTOMER ISSUE	-
VRT_033	47199	N	N	N	39	CUSTOMER ISSUE	-
VRT_034	47200	N	N	N	39	CUSTOMER ISSUE	-
VRT_035	47201	N	N	N	39	CUSTOMER ISSUE	-
VRT_036	47202	N	N	N	39	CUSTOMER ISSUE	-
VRT_037	47203	N	N	N	39	CUSTOMER ISSUE	-
VRT_038	47204	N	N	N	39	CUSTOMER ISSUE	-
VRT_039	47205	N	N	N	39	CUSTOMER ISSUE	-
VRT_040	47206	N	N	N	39	CUSTOMER ISSUE	-
VRT_041	47207	N	N	N	39	CUSTOMER ISSUE	-
VRT_042	47208	N	N	N	39	CUSTOMER ISSUE	-
VRT_043	47209	N	N	N	39	CUSTOMER ISSUE	-
VRT_044	47210	N	N	N	39	CUSTOMER ISSUE	-
VRT_045	47211	N	N	N	39	CUSTOMER ISSUE	-
VRT_046	47212	N	N	N	39	CUSTOMER ISSUE	-
VRT_047	47213	N	N	N	39	CUSTOMER ISSUE	-
VRT_048	47214	N	N	N	39	CUSTOMER ISSUE	-
VRT_049	47215	N	N	N	39	CUSTOMER ISSUE	-
VRT_050	47216	N	N	N	39	CUSTOMER ISSUE	-
VRT_051	47217	N	N	N	39	CUSTOMER ISSUE	-
VRT_052	47218	N	N	N	39	CUSTOMER ISSUE	-
VRT_053	47219	N	N	N	39	CUSTOMER ISSUE	-
VRT_054	47220	N	N	N	39	CUSTOMER ISSUE	-
VRT_055	47221	N	N	N	39	CUSTOMER ISSUE	-
VRT_056	47222	N	N	N	39	CUSTOMER ISSUE	-
VRT_057	47223	N	N	N	39	CUSTOMER ISSUE	-
VRT_058	47224	N	N	N	39	CUSTOMER ISSUE	-
VRT_059	47225	N	N	N	39	CUSTOMER ISSUE	-
VRT_060	47226	N	N	N	39	CUSTOMER ISSUE	-
VRT_061	47227	N	N	N	39	CUSTOMER ISSUE	-
VRT_062	47228	N	N	N	39	CUSTOMER ISSUE	-
VRT_063	47229	N	N	N	39	CUSTOMER ISSUE	-
VRT_064	47230	N	N	N	39	CUSTOMER ISSUE	-
VRT_065	47231	N	N	N	39	CUSTOMER ISSUE	-
VRT_066	47232	N	N	N	39	CUSTOMER ISSUE	-
VRT_067	47233	N	N	N	39	CUSTOMER ISSUE	-
VRT_068	47234	N	N	N	39	CUSTOMER ISSUE	-
VRT_069	47235	N	N	N	39	CUSTOMER ISSUE	-
VRT_070	47236	N	N	N	39	CUSTOMER ISSUE	-
VRT_071	47237	N	N	N	39	CUSTOMER ISSUE	-
VRT_072	47238	N	N	N	39	CUSTOMER ISSUE	-
VRT_073	47239	N	N	N	39	CUSTOMER ISSUE	-
VRT_074	47240	N	N	N	39	CUSTOMER ISSUE	-
VRT_075	47241	N	N	N	39	CUSTOMER ISSUE	-
VRT_076	47242	N	N	N	39	CUSTOMER ISSUE	-
VRT_077	47243	N	N	N	39	CUSTOMER ISSUE	-
VRT_078	47244	N	N	N	39	CUSTOMER ISSUE	-
VRT_079	47245	N	N	N	39	CUSTOMER ISSUE	-
VRT_080	47246	N	N	N	39	CUSTOMER ISSUE	-
VRT_081	47247	N	N	N	39	CUSTOMER ISSUE	-
VRT_082	47248	N	N	N	39	CUSTOMER ISSUE	-
VRT_083	47249	N	N	N	39	CUSTOMER ISSUE	-
VRT_084	47250	N	N	N	39	CUSTOMER ISSUE	-
VRT_085	47251	N	N	N	39	CUSTOMER ISSUE	-
VRT_086	47252	N	N	N	39	CUSTOMER ISSUE	-
VRT_087	47253	N	N	N	39	CUSTOMER ISSUE	-
VRT_088	47254	N	N	N	39	CUSTOMER ISSUE	-
VRT_089	47255	N	N	N	39	CUSTOMER ISSUE	-
VRT_090	47256	N	N	N	39	CUSTOMER ISSUE	-

VRT_091	47257	N	N	N	39	CUSTOMER ISSUE	-
VRT_092	47258	N	N	N	39	CUSTOMER ISSUE	-
VRT_093	47259	N	N	N	39	CUSTOMER ISSUE	-
VRT_094	47260	N	N	N	39	CUSTOMER ISSUE	-
VRT_095	47261	N	N	N	39	CUSTOMER ISSUE	-
VRT_096	47262	N	N	N	39	CUSTOMER ISSUE	-
VRT_097	47263	N	N	N	39	CUSTOMER ISSUE	-
VRT_098	47264	N	N	N	39	CUSTOMER ISSUE	-
VRT_099	47265	N	N	N	39	CUSTOMER ISSUE	-
VRT_100	47266	N	N	N	39	CUSTOMER ISSUE	-
VRT_101	47267	N	N	N	39	CUSTOMER ISSUE	-
VRT_102	47268	N	N	N	39	CUSTOMER ISSUE	-
VRT_103	47269	N	N	N	39	CUSTOMER ISSUE	-
VRT_104	47270	N	N	N	39	CUSTOMER ISSUE	-
VRT_105	47271	N	N	N	39	CUSTOMER ISSUE	-
VRT_106	47272	N	N	N	39	CUSTOMER ISSUE	-
VRT_107	47273	N	N	N	39	CUSTOMER ISSUE	-
VRT_108	47274	N	N	N	39	CUSTOMER ISSUE	-
VRT_109	47275	N	N	N	39	CUSTOMER ISSUE	-
VRT_110	47276	N	N	N	39	CUSTOMER ISSUE	-
VRT_111	47277	N	N	N	39	CUSTOMER ISSUE	-
VRT_112	47278	N	N	N	39	CUSTOMER ISSUE	-
VRT_113	47279	N	N	N	39	CUSTOMER ISSUE	-
VRT_114	47280	N	N	N	39	CUSTOMER ISSUE	-
VRT_115	47281	N	N	N	39	CUSTOMER ISSUE	-
VRT_116	47282	N	N	N	39	CUSTOMER ISSUE	-
VRT_117	47283	N	N	N	39	CUSTOMER ISSUE	-
VRT_118	47284	N	N	N	39	CUSTOMER ISSUE	-
VRT_119	47285	N	N	N	39	CUSTOMER ISSUE	-
VRT_120	47286	N	N	N	39	CUSTOMER ISSUE	-
VRT_121	47287	N	N	N	39	CUSTOMER ISSUE	-
VRT_122	47288	N	N	N	39	CUSTOMER ISSUE	-
VRT_123	47289	N	N	N	39	CUSTOMER ISSUE	-
VRT_124	47290	N	N	N	39	CUSTOMER ISSUE	-
VRT_125	47291	N	N	N	39	CUSTOMER ISSUE	-
VRT_126	47292	N	N	N	39	CUSTOMER ISSUE	-
VRT_127	47293	N	N	N	39	CUSTOMER ISSUE	-
VRT_128	47294	N	N	N	39	CUSTOMER ISSUE	-
VRT_129	47295	N	N	N	39	CUSTOMER ISSUE	-
VRT_130	47296	N	N	N	39	CUSTOMER ISSUE	-
VRT_131	47297	N	N	N	39	CUSTOMER ISSUE	-
VRT_132	47298	N	N	N	39	CUSTOMER ISSUE	-
VRT_133	47299	N	N	N	39	CUSTOMER ISSUE	-
VRT_134	47300	N	N	N	39	CUSTOMER ISSUE	-
VRT_135	47301	N	N	N	39	CUSTOMER ISSUE	-
VRT_136	47302	N	N	N	39	CUSTOMER ISSUE	-
VRT_137	47303	N	N	N	39	CUSTOMER ISSUE	-
VRT_138	47304	N	N	N	39	CUSTOMER ISSUE	-
VRT_139	47305	N	N	N	39	CUSTOMER ISSUE	-
VRT_140	47306	N	N	N	39	CUSTOMER ISSUE	-
VRT_141	47307	N	N	N	39	CUSTOMER ISSUE	-
VRT_142	47308	N	N	N	39	CUSTOMER ISSUE	-
VRT_143	47309	N	N	N	39	CUSTOMER ISSUE	-
VRT_144	47310	N	N	N	39	CUSTOMER ISSUE	-
VRT_145	47311	N	N	N	39	CUSTOMER ISSUE	-
VRT_146	47312	N	N	N	39	CUSTOMER ISSUE	-
VRT_147	47313	N	N	N	39	CUSTOMER ISSUE	-
VRT_148	47314	N	N	N	39	CUSTOMER ISSUE	-
VRT_149	47315	N	N	N	39	CUSTOMER ISSUE	-
VRT_150	47316	N	N	N	39	CUSTOMER ISSUE	-
VRT_151	47317	N	N	N	39	CUSTOMER ISSUE	-
VRT_152	47318	N	N	N	39	CUSTOMER ISSUE	-
VRT_153	47319	N	N	N	39	CUSTOMER ISSUE	-
VRT_154	47320	N	N	N	39	CUSTOMER ISSUE	-
VRT_155	47321	N	N	N	39	CUSTOMER ISSUE	-
VRT_156	47322	N	N	N	39	CUSTOMER ISSUE	-
VRT_157	47323	N	N	N	39	CUSTOMER ISSUE	-
VRT_158	47324	N	N	N	39	CUSTOMER ISSUE	-
VRT_159	47325	N	N	N	39	CUSTOMER ISSUE	-
VRT_160	47326	N	N	N	39	CUSTOMER ISSUE	-
VRT_161	47327	N	N	N	39	CUSTOMER ISSUE	-
VRT_162	47328	N	N	N	39	CUSTOMER ISSUE	-
VRT_163	47329	N	N	N	39	CUSTOMER ISSUE	-
VRT_164	47330	N	N	N	39	CUSTOMER ISSUE	-
VRT_165	47331	N	N	N	39	CUSTOMER ISSUE	-
VRT_166	47332	N	N	N	39	CUSTOMER ISSUE	-
VRT_167	47333	N	N	N	39	CUSTOMER ISSUE	-
VRT_168	47334	N	N	N	39	CUSTOMER ISSUE	-
VRT_169	47335	N	N	N	39	CUSTOMER ISSUE	-
VRT_170	47336	N	N	N	39	CUSTOMER ISSUE	-

VRT_171	47337	N	N	N	39	CUSTOMER ISSUE	-
VRT_172	47338	N	N	N	39	CUSTOMER ISSUE	-
VRT_173	47339	N	N	N	39	CUSTOMER ISSUE	-
VRT_174	47340	N	N	N	39	CUSTOMER ISSUE	-
VRT_175	47341	N	N	N	39	CUSTOMER ISSUE	-
VRT_176	47342	N	N	N	39	CUSTOMER ISSUE	-
VRT_177	47343	N	N	N	39	CUSTOMER ISSUE	-
VRT_178	47344	N	N	N	39	CUSTOMER ISSUE	-
VRT_179	47345	N	N	N	39	CUSTOMER ISSUE	-
VRT_180	47346	N	N	N	39	CUSTOMER ISSUE	-
VRT_181	47347	N	N	N	39	CUSTOMER ISSUE	-
VRT_182	47348	N	N	N	39	CUSTOMER ISSUE	-
VRT_183	47349	N	N	N	39	CUSTOMER ISSUE	-
VRT_184	47350	N	N	N	39	CUSTOMER ISSUE	-
VRT_185	47351	N	N	N	39	CUSTOMER ISSUE	-
VRT_186	47352	N	N	N	39	CUSTOMER ISSUE	-
VRT_187	47353	N	N	N	39	CUSTOMER ISSUE	-
VRT_188	47354	N	N	N	39	CUSTOMER ISSUE	-
VRT_189	47355	N	N	N	39	CUSTOMER ISSUE	-
VRT_190	47356	N	N	N	39	CUSTOMER ISSUE	-
VRT_191	47357	N	N	N	39	CUSTOMER ISSUE	-
VRT_192	47358	N	N	N	39	CUSTOMER ISSUE	-
VRT_193	47359	N	N	N	39	CUSTOMER ISSUE	-
VRT_194	47360	N	N	N	39	CUSTOMER ISSUE	-
VRT_195	47361	N	N	N	39	CUSTOMER ISSUE	-
VRT_196	47362	N	N	N	39	CUSTOMER ISSUE	-
VRT_197	47363	N	N	N	39	CUSTOMER ISSUE	-
VRT_198	47364	N	N	N	39	CUSTOMER ISSUE	-
VRT_199	47365	N	N	N	39	CUSTOMER ISSUE	-
VRT_200	47366	N	N	N	39	CUSTOMER ISSUE	-
VRT_201	47367	N	N	N	39	CUSTOMER ISSUE	-
VRT_202	47368	N	N	N	39	CUSTOMER ISSUE	-
VRT_203	47369	N	N	N	39	CUSTOMER ISSUE	-
VRT_204	47370	N	N	N	39	CUSTOMER ISSUE	-
VRT_205	47371	N	N	N	39	CUSTOMER ISSUE	-
VRT_206	47372	N	N	N	39	CUSTOMER ISSUE	-
VRT_207	47373	N	N	N	39	CUSTOMER ISSUE	-
VRT_208	47374	N	N	N	39	CUSTOMER ISSUE	-
VRT_209	47375	N	N	N	39	CUSTOMER ISSUE	-
VRT_210	47376	N	N	N	39	CUSTOMER ISSUE	-
VRT_211	47377	N	N	N	39	CUSTOMER ISSUE	-
VRT_212	47378	N	N	N	39	CUSTOMER ISSUE	-
VRT_213	47379	N	N	N	39	CUSTOMER ISSUE	-
VRT_214	47380	N	N	N	39	CUSTOMER ISSUE	-
VRT_215	47381	N	N	N	39	CUSTOMER ISSUE	-
VRT_216	47382	N	N	N	39	CUSTOMER ISSUE	-
VRT_217	47383	N	N	N	39	CUSTOMER ISSUE	-
VRT_218	47384	N	N	N	39	CUSTOMER ISSUE	-
VRT_219	47385	N	N	N	39	CUSTOMER ISSUE	-
VRT_220	47386	N	N	N	39	CUSTOMER ISSUE	-
VRT_221	47387	N	N	N	39	CUSTOMER ISSUE	-
VRT_222	47388	N	N	N	39	CUSTOMER ISSUE	-
VRT_223	47389	N	N	N	39	CUSTOMER ISSUE	-
VRT_224	47390	N	N	N	39	CUSTOMER ISSUE	-
VRT_225	47391	N	N	N	39	CUSTOMER ISSUE	-
VRT_226	47392	N	N	N	39	CUSTOMER ISSUE	-
VRT_227	47393	N	N	N	39	CUSTOMER ISSUE	-
VRT_228	47394	N	N	N	39	CUSTOMER ISSUE	-
VRT_229	47395	N	N	N	39	CUSTOMER ISSUE	-
VRT_230	47396	N	N	N	39	CUSTOMER ISSUE	-
VRT_231	47397	N	N	N	39	CUSTOMER ISSUE	-
VRT_232	47398	N	N	N	39	CUSTOMER ISSUE	-
VRT_233	47399	N	N	N	39	CUSTOMER ISSUE	-
VRT_234	47400	N	N	N	39	CUSTOMER ISSUE	-
VRT_235	47401	N	N	N	39	CUSTOMER ISSUE	-
VRT_236	47402	N	N	N	39	CUSTOMER ISSUE	-
VRT_237	47403	N	N	N	39	CUSTOMER ISSUE	-
VRT_238	47404	N	N	N	39	CUSTOMER ISSUE	-
VRT_239	47405	N	N	N	39	CUSTOMER ISSUE	-
VRT_240	47406	N	N	N	39	CUSTOMER ISSUE	-
VRT_241	47407	N	N	N	39	CUSTOMER ISSUE	-
VRT_242	47408	N	N	N	39	CUSTOMER ISSUE	-
VRT_243	47409	N	N	N	39	CUSTOMER ISSUE	-
VRT_244	47410	N	N	N	39	CUSTOMER ISSUE	-
VRT_245	47411	N	N	N	39	CUSTOMER ISSUE	-
VRT_246	47412	N	N	N	39	CUSTOMER ISSUE	-
VRT_247	47413	N	N	N	39	CUSTOMER ISSUE	-
VRT_248	47414	N	N	N	39	CUSTOMER ISSUE	-
VRT_249	47415	N	N	N	39	CUSTOMER ISSUE	-
VRT_250	47416	N	N	N	39	CUSTOMER ISSUE	-

VRT_251	47417	N	N	N	39	CUSTOMER ISSUE	-
VRT_252	47418	N	N	N	39	CUSTOMER ISSUE	-
VRT_253	47419	N	N	N	39	CUSTOMER ISSUE	-
VRT_254	47420	N	N	N	39	CUSTOMER ISSUE	-
VRT_255	47421	N	N	N	39	CUSTOMER ISSUE	-
VRT_256	47422	N	N	N	39	CUSTOMER ISSUE	-
VRT_257	47423	N	N	N	39	CUSTOMER ISSUE	-
VRT_258	47424	N	N	N	39	CUSTOMER ISSUE	-
VRT_259	47425	N	N	N	39	CUSTOMER ISSUE	-
VRT_260	47426	N	N	N	39	CUSTOMER ISSUE	-
VRT_261	47427	N	N	N	39	CUSTOMER ISSUE	-
VRT_262	47428	N	N	N	39	CUSTOMER ISSUE	-
VRT_263	47429	N	N	N	39	CUSTOMER ISSUE	-
VRT_264	47430	N	N	N	39	CUSTOMER ISSUE	-
VRT_265	47431	N	N	N	39	CUSTOMER ISSUE	-
VRT_266	47432	N	N	N	39	CUSTOMER ISSUE	-
VRT_267	47433	N	N	N	39	CUSTOMER ISSUE	-
VRT_268	47434	N	N	N	39	CUSTOMER ISSUE	-
VRT_269	47435	N	N	N	39	CUSTOMER ISSUE	-
VRT_270	47436	N	N	N	39	CUSTOMER ISSUE	-
VRT_271	47437	N	N	N	39	CUSTOMER ISSUE	-
VRT_272	47438	N	N	N	39	CUSTOMER ISSUE	-
VRT_273	47439	N	N	N	39	CUSTOMER ISSUE	-
VRT_274	47440	N	N	N	39	CUSTOMER ISSUE	-
VRT_275	47441	N	N	N	39	CUSTOMER ISSUE	-
VRT_276	47442	N	N	N	39	CUSTOMER ISSUE	-
VRT_277	47443	N	N	N	39	CUSTOMER ISSUE	-
VRT_278	47444	N	N	N	39	CUSTOMER ISSUE	-
VRT_279	47445	N	N	N	39	CUSTOMER ISSUE	-
VRT_280	47446	N	N	N	39	CUSTOMER ISSUE	-
VRT_281	47447	N	N	N	39	CUSTOMER ISSUE	-
VRT_282	47448	N	N	N	39	CUSTOMER ISSUE	-
VRT_283	47449	N	N	N	39	CUSTOMER ISSUE	-
VRT_284	47450	N	N	N	39	CUSTOMER ISSUE	-
VRT_285	47451	N	N	N	39	CUSTOMER ISSUE	-
VRT_286	47452	N	N	N	39	CUSTOMER ISSUE	-
VRT_287	47453	N	N	N	39	CUSTOMER ISSUE	-
VRT_288	47454	N	N	N	39	CUSTOMER ISSUE	-
VRT_289	47455	N	N	N	39	CUSTOMER ISSUE	-
VRT_290	47456	N	N	N	39	CUSTOMER ISSUE	-
VRT_291	47457	N	N	N	39	CUSTOMER ISSUE	-
VRT_292	47458	N	N	N	39	CUSTOMER ISSUE	-
VRT_293	47459	N	N	N	39	CUSTOMER ISSUE	-
VRT_294	47460	N	N	N	39	CUSTOMER ISSUE	-
VRT_295	47461	N	N	N	39	CUSTOMER ISSUE	-
VRT_296	47462	N	N	N	39	CUSTOMER ISSUE	-
VRT_297	47463	N	N	N	39	CUSTOMER ISSUE	-
VRT_298	47464	N	N	N	39	CUSTOMER ISSUE	-
VRT_299	47465	N	N	N	39	CUSTOMER ISSUE	-
VRT_300	47466	N	N	N	39	CUSTOMER ISSUE	-
VRT_301	47467	N	N	N	39	CUSTOMER ISSUE	-
VRT_302	47468	N	N	N	39	CUSTOMER ISSUE	-
VRT_303	47469	N	N	N	39	CUSTOMER ISSUE	-
VRT_304	47470	N	N	N	39	CUSTOMER ISSUE	-
VRT_305	47471	N	N	N	39	CUSTOMER ISSUE	-
VRT_306	47472	N	N	N	39	CUSTOMER ISSUE	-
VRT_307	47473	N	N	N	39	CUSTOMER ISSUE	-
VRT_308	47474	N	N	N	39	CUSTOMER ISSUE	-
VRT_309	47475	N	N	N	39	CUSTOMER ISSUE	-
VRT_310	47476	N	N	N	39	CUSTOMER ISSUE	-
VRT_311	47477	N	N	N	39	CUSTOMER ISSUE	-
VRT_312	47478	N	N	N	39	CUSTOMER ISSUE	-
VRT_313	47479	N	N	N	39	CUSTOMER ISSUE	-
VRT_314	47480	N	N	N	39	CUSTOMER ISSUE	-
VRT_315	47481	N	N	N	39	CUSTOMER ISSUE	-
VRT_316	47482	N	N	N	39	CUSTOMER ISSUE	-
VRT_317	47483	N	N	N	39	CUSTOMER ISSUE	-
VRT_318	47484	N	N	N	39	CUSTOMER ISSUE	-
VRT_319	47485	N	N	N	39	CUSTOMER ISSUE	-
VRT_320	47486	N	N	N	39	CUSTOMER ISSUE	-
VRT_321	47487	N	N	N	39	CUSTOMER ISSUE	-
VRT_322	47488	N	N	N	39	CUSTOMER ISSUE	-
VRT_323	47489	N	N	N	39	CUSTOMER ISSUE	-
VRT_324	47490	N	N	N	39	CUSTOMER ISSUE	-
VRT_325	47491	N	N	N	39	CUSTOMER ISSUE	-
VRT_326	47492	N	N	N	39	CUSTOMER ISSUE	-
VRT_327	47493	N	N	N	39	CUSTOMER ISSUE	-
VRT_328	47494	N	N	N	39	CUSTOMER ISSUE	-
VRT_329	47495	N	N	N	39	CUSTOMER ISSUE	-
VRT_330	47496	N	N	N	39	CUSTOMER ISSUE	-

VRT_331	47497	N	N	N	39	CUSTOMER ISSUE	-
VRT_332	47498	N	N	N	39	CUSTOMER ISSUE	-
VRT_333	47499	N	N	N	39	CUSTOMER ISSUE	-
VRT_334	47500	N	N	N	39	CUSTOMER ISSUE	-
VRT_335	47501	N	N	N	39	CUSTOMER ISSUE	-
VRT_336	47502	N	N	N	39	CUSTOMER ISSUE	-
VRT_337	47503	N	N	N	39	CUSTOMER ISSUE	-
VRT_338	47504	N	N	N	39	CUSTOMER ISSUE	-
VRT_339	47505	N	N	N	39	CUSTOMER ISSUE	-
VRT_340	47506	N	N	N	39	CUSTOMER ISSUE	-
VRT_341	47507	N	N	N	39	CUSTOMER ISSUE	-
VRT_342	47508	N	N	N	39	CUSTOMER ISSUE	-
VRT_343	47509	N	N	N	39	CUSTOMER ISSUE	-
VRT_344	47510	N	N	N	39	CUSTOMER ISSUE	-
VRT_345	47511	N	N	N	39	CUSTOMER ISSUE	-
VRT_346	47512	N	N	N	39	CUSTOMER ISSUE	-
VRT_347	47513	N	N	N	39	CUSTOMER ISSUE	-
VRT_348	47514	N	N	N	39	CUSTOMER ISSUE	-
VRT_349	47515	N	N	N	39	CUSTOMER ISSUE	-
VRT_350	47516	N	N	N	39	CUSTOMER ISSUE	-
VRT_351	47517	N	N	N	39	CUSTOMER ISSUE	-
VRT_352	47518	N	N	N	39	CUSTOMER ISSUE	-
VRT_353	47519	N	N	N	39	CUSTOMER ISSUE	-
VRT_354	47520	N	N	N	39	CUSTOMER ISSUE	-
VRT_355	47521	N	N	N	39	CUSTOMER ISSUE	-
VRT_356	47522	N	N	N	39	CUSTOMER ISSUE	-
VRT_357	47523	N	N	N	39	CUSTOMER ISSUE	-
VRT_358	47524	N	N	N	39	CUSTOMER ISSUE	-
VRT_359	47525	N	N	N	39	CUSTOMER ISSUE	-
VRT_360	47526	N	N	N	39	CUSTOMER ISSUE	-
VRT_361	47527	N	N	N	39	CUSTOMER ISSUE	-
VRT_362	47528	N	N	N	39	CUSTOMER ISSUE	-
VRT_363	47529	N	N	N	39	CUSTOMER ISSUE	-
VRT_364	47530	N	N	N	39	CUSTOMER ISSUE	-
VRT_365	47531	N	N	N	39	CUSTOMER ISSUE	-
VRT_366	47532	N	N	N	39	CUSTOMER ISSUE	-
VRT_367	47533	N	N	N	39	CUSTOMER ISSUE	-
VRT_368	47534	N	N	N	39	CUSTOMER ISSUE	-
VRT_369	47535	N	N	N	39	CUSTOMER ISSUE	-
VRT_370	47536	N	N	N	39	CUSTOMER ISSUE	-
VRT_371	47537	N	N	N	39	CUSTOMER ISSUE	-
VRT_372	47538	N	N	N	39	CUSTOMER ISSUE	-
VRT_373	47539	N	N	N	39	CUSTOMER ISSUE	-
VRT_374	47540	N	N	N	39	CUSTOMER ISSUE	-
VRT_375	47541	N	N	N	39	CUSTOMER ISSUE	-
VRT_376	47542	N	N	N	39	CUSTOMER ISSUE	-
VRT_377	47543	N	N	N	39	CUSTOMER ISSUE	-
VRT_378	47544	N	N	N	39	CUSTOMER ISSUE	-
VRT_379	47545	N	N	N	39	CUSTOMER ISSUE	-
VRT_380	47546	N	N	N	39	CUSTOMER ISSUE	-
VRT_381	47547	N	N	N	39	CUSTOMER ISSUE	-
VRT_382	47548	N	N	N	39	CUSTOMER ISSUE	-
VRT_383	47549	N	N	N	39	CUSTOMER ISSUE	-
VRT_384	47550	N	N	N	39	CUSTOMER ISSUE	-
VRT_385	47551	N	N	N	39	CUSTOMER ISSUE	-
VRT_386	47552	N	N	N	39	CUSTOMER ISSUE	-
VRT_387	47553	N	N	N	39	CUSTOMER ISSUE	-
VRT_388	47554	N	N	N	39	CUSTOMER ISSUE	-
VRT_389	47555	N	N	N	39	CUSTOMER ISSUE	-
VRT_390	47556	N	N	N	39	CUSTOMER ISSUE	-
VRT_391	47557	N	N	N	39	CUSTOMER ISSUE	-
VRT_392	47558	N	N	N	39	CUSTOMER ISSUE	-
VRT_393	47559	N	N	N	39	CUSTOMER ISSUE	-
VRT_394	47560	N	N	N	39	CUSTOMER ISSUE	-
VRT_395	47561	N	N	N	39	CUSTOMER ISSUE	-
VRT_396	47562	N	N	N	39	CUSTOMER ISSUE	-
VRT_397	47563	N	N	N	39	CUSTOMER ISSUE	-
VRT_398	47564	N	N	N	39	CUSTOMER ISSUE	-
VRT_399	47565	N	N	N	39	CUSTOMER ISSUE	-
VRT_400	47566	N	N	N	39	CUSTOMER ISSUE	-
VRT_401	47567	N	N	N	39	CUSTOMER ISSUE	-
VRT_402	47568	N	N	N	39	CUSTOMER ISSUE	-
VRT_403	47569	N	N	N	39	CUSTOMER ISSUE	-
VRT_404	47570	N	N	N	39	CUSTOMER ISSUE	-
VRT_405	47571	N	N	N	39	CUSTOMER ISSUE	-
VRT_406	47572	N	N	N	39	CUSTOMER ISSUE	-
VRT_407	47573	N	N	N	39	CUSTOMER ISSUE	-
VRT_408	47574	N	N	N	39	CUSTOMER ISSUE	-
VRT_409	47575	N	N	N	39	CUSTOMER ISSUE	-
VRT_410	47576	N	N	N	39	CUSTOMER ISSUE	-

PG&E Gas and Electric
Advice Submittal List
General Order 96-B, Section IV

AT&T
Albion Power Company

Alta Power Group, LLC
Anderson & Poole

Atlas ReFuel
BART

Barkovich & Yap, Inc.
Braun Blaising Smith Wynne, P.C.
California Cotton Ginners & Growers Assn
California Energy Commission

California Hub for Energy Efficiency Financing

California Alternative Energy and Advanced Transportation Financing Authority
California Public Utilities Commission
Calpine

Cameron-Daniel, P.C.
Casner, Steve
Center for Biological Diversity

Chevron Pipeline and Power
City of Palo Alto

City of San Jose
Clean Power Research
Coast Economic Consulting
Commercial Energy
Crossborder Energy
Crown Road Energy, LLC
Davis Wright Tremaine LLP
Day Carter Murphy

Dept of General Services
Don Pickett & Associates, Inc.
Douglass & Liddell
Downey Brand LLP
Dish Wireless L.L.C.

East Bay Community Energy Ellison Schneider & Harris LLP
Engineers and Scientists of California

GenOn Energy, Inc.
Green Power Institute
Hanna & Morton
ICF
iCommLaw
International Power Technology
Intertie

Intestate Gas Services, Inc.

Johnston, Kevin
Kelly Group
Ken Bohn Consulting
Keyes & Fox LLP
Leviton Manufacturing Co., Inc.

Los Angeles County Integrated Waste Management Task Force
MRW & Associates
Manatt Phelps Phillips
Marin Energy Authority
McClintock IP
McKenzie & Associates

Modesto Irrigation District
NLine Energy, Inc.
NRG Solar

OnGrid Solar
Pacific Gas and Electric Company
Peninsula Clean Energy

Pioneer Community Energy

Public Advocates Office

Redwood Coast Energy Authority
Regulatory & Cogeneration Service, Inc.

Resource Innovations

SCD Energy Solutions
San Diego Gas & Electric Company

SPURR
San Francisco Water Power and Sewer
Sempra Utilities

Sierra Telephone Company, Inc.
Southern California Edison Company
Southern California Gas Company
Spark Energy
Sun Light & Power
Sunshine Design
Stoel Rives LLP

Tecogen, Inc.
TerraVerde Renewable Partners
Tiger Natural Gas, Inc.

TransCanada
Utility Cost Management
Utility Power Solutions
Water and Energy Consulting Wellhead Electric Company
Western Manufactured Housing Communities Association (WMA)
Yep Energy